Control Number: 29165

Item Number: 24

Addendum StartPage: 0

CENTERPOINT ENERGY HOUSTON ELECTRIC LLC
Project 29165

RECEIVED
2004 JUN -4 PM 12: 09
PUBLIC UTILITY COMMISSION
FILING CLERK

Contact: Andy Machtemes
Phone: (713) 207-5372

Table of Contents
June 04, 2004

DESCRIPTION **PAGE**

CNP Service Quality Information Request.....125

ELECTRONIC FILES:
CNP Service Quality Information Request –Questions 1-3.xls
CNP Service Quality Information Request – Questions 4-9.doc

24

1. Provide complete records of all sustained interruptions, by interruption class, for the months of April and October, 2003. [Subst. R. §26.52(d)]

SUSTAINED INTERRUPTIONS
April and October, 2003

Forced Interruptions

PUC CATEGORY	SERVICE AREA	CKT	SECTION	FUSE	TRANSFORMER	CASE NUM	OUTAGE DATE	OUTAGE TIME	DURATION	SUSTAINED CUSTOMER AFFECTED	CUSTOMER MINS	CAUSE	CAUSE 2	TROUBLE LOC	SERVICE CD	OUTAGE TYPE	OUTAGE EQP 1	OUTAGE EQP 2	OUTAGE EQP 3	OUTAGE EQP 4	OUTAGE EQP 5	OUTAGE EQP 6	REMARKS	NUM SUSTAINED CASES	NUM LOCKOUTS
FORCED INTERR	GP	HV 03	22206	C92R	52636477	22003091000	T	4/1/2003	0418	49	3	147	TREE CLEARANC	TREE CLEAR	926	BLUE BELL	1	TF	526364723				TRIM TREES AN DREFUSED LIF, REF TR;	1	0
FORCED INTERR.	SH	WE 02	31250	C62E	56550180	22003091000	T	4/1/2003	0654	77	10	770	SQUIRREL	SQUIRREL	902	WILLOW	1	TF	565501808				REFUSE 50 CONV IN THE REAR OF 905 LIVE OAK LIGHTS CAME BACK ON 908 LIVE OAK "CC" NO ONE ANSWER THE DOOR. REF TR; MEK	1	0
FORCED INTERR	GP	TWG4	14RK8	81EJ	53682542	22003091001	T	4/1/2003	0716	81	14	854	VINES	VINES	2218	MILLSTONI	2	TF	536825432				CUT VINES FROM POLE, REF TR;	1	0
FORCED INTERR	SH	SO 42	31425	39MR	54466541	22003091000	F	4/1/2003	0725	154	1	154	LIGHTNING	LIGHTNING	2402	COUNTY R	1	LF	39MR	TF	544665416	PR	REPLACED THE K-MATE AND REFUSED THE LIGHTER TRANSFORMER ALSO RE-FUSED A-PHASE OF THE LINE FUSE. REF LF .RPLD LIMITER @ TR; REF TR RGR	1	0
FORCED INTERR	SH	SO 42	31425	39MR	54486543	22003091000	F	4/1/2003	0725	154	1	154	LIGHTNING	LIGHTNING	2402	COUNTY R	1	LF					REFUSED LF 418 - SQUIRREL, REF LF;	1	0
FORCED INTERR	BZ	VL 02	31124	4TS	54248455	22003091000	F	4/1/2003	0726	74	10	740	SQUIRREL	SQUIRREL	1802	N AVENUE	1	TF	4TS				REFUSED EAST POWER TRANS/ LEFT SERV ON / NOTIFIED. REF TR;	1	0
FORCED INTERR	SH	GG 04	30542	63M	55544235	22003091001	T	4/1/2003	0736	41	1	41	BIRD	BIRD	5726	NUNN	1	TF	555442321				REF TR.	1	0
FORCED INTERR	GP	AD 04	40298	F2M	53632210	22003091001	T	4/1/2003	0736	45	8	360	SQUIRREL	SQUIRREL	313	E LORINO	1	TF	536322167				B PHASE OFF INSULATOR WOOD ARM CONSTRUCTION ON CIRCUIT NOT TRUCK ACCESSABLE IN EASEMENT FLOATING ABOUT 8 INCHES OFF X-ARM; RPRD BUSS WORK @ TR, MEK	1	0
FORCED INTERR	SB	SR 13	21681	76AI	49585211	22003091000	T	4/1/2003	0801	97	3	291	OH SEC/DR CL H	OH SC CL-H	10333	KATY FW	1	SC	495852131				REPAIRED NEUTRAL AND ONE HOT LEG., RPRD BEC CONN @ PL-1 CUST.	1	0
FORCED INTERR.	CH	SW 05	41681		54629055	22003091000	E	4/1/2003	0801	144	1	144	TREE CLEARANC	TREE CLEAR	4406	LANGLEY		SC					REPLACED BURN UP FUSE BARREL ON A 7.9KVA POWER TFMR IN A CLOSED DELTA BANK. RPLD BIJ BARREL ON TR.	1	0
FORCED INTERR	BL	HT 03	12135	W82A	50558346	22003091001	E	4/1/2003	0843	37	12	444	BU DISC OR BARI	DISC/BARRL	6644	SOUTHWE	3	TF	505583408				CUT VINES ON TRF POLE REAR 12448 KATHRYN REFUSE LF; REF LF.	1	0
FORCED INTERR	CH	NM 04	41526	Y90H	57576568	22003091001	F	4/1/2003	0857	31	36	1116	VINES	VINES	12443	YANCY DI	1	LF	Y90H				CUT OUT, LOOP DAMAGE. NEED TO NOTIFY CUST METER INFO. A9167622S, 001 74630 LEFT XFMR OPEN. REPAIRED DAMAGED BUSSWORK. RPRD BUSS WORK @ TR	1	0
FORCED INTERR	SH	TE 05	31087	77PT	56504551	22003091002	T	4/1/2003	0941	7	1	7	COLLISION	COLLISION	8503	1/2 S SAM	1	SC	565045518				RPLD BIJ DISC-TF BLOWN.	1	0
FORCED INTERR	GP	BA 46	20867		50663268	22003091002	E	4/1/2003	0945	97	8	776	SQUIRREL	SQUIRREL	5818	PINE ARBO		TF	506832691	DB			RPLD BIJ BARREL ON TR.	1	0
FORCED INTERR	GP	RU 03	41661	K65C	53628137	22003091002	T	4/1/2003	0950	38	2	76	BU DISC OR BARI	DISC/BARRL	703	LITTLE YOR	1	TF	536281377				REFUSED TRNS / LEFT SERV ON / NOTIFIED LIA NEEDS TO BE REPLACED @ S/C CONV. – IN EASEMENT CAN NOT GET TRK TO IT, REF TR. RGR	1	0
FORCED INTERR	MP	HG 04	41063	F59G	56550420	22003091003	T	4/1/2003	1000	25	19	475	SQUIRREL	SQUIRREL	7406	FIR	1	TF	565504202				MADE REPAIRS ON UDR DROPS HIT BY COUST 8807 FERN CIR. RESET RR; REF TR.	1	0
FORCED INTERR	BA	HN 04	41021	S24H	62602356	22003091002	T	4/1/2003	1000	87	6	522	CUST EQP RELA	CUST RLTD	8807	HONEYSUK	2	TF	626023596				LIMB BROKE 1/0 ALUM LEAD OUT OF 25 KVA 277/480 TRAN IN BANK. BROKE OFF LIMBS AROUND TRAN AND PUT LEAD BACK IN; RPRD BUSS WORK @ TR;	1	0
FORCED INTERR	SB	DH 04	10423	E92Z	51604556	22003091003	T	4/1/2003	1027	58	1	58	TREE CLEARANC	TREE CLEAR	5540	BROOM	1	SC	518045587				RESET 75 CBP---REMOVED MTR # 801524604--X1--Rdg 81452--Int. Rdg 7.0-X1 FED 1100 SPRING CYPRESS--BUILDING BEING DEMOLISHED--CREW SHORTED MTR BANK--TRIPPED CBP---, RESE	1	0
FORCED INTERR	GP	RA 43	20439	3MD	52702556	22003091003	T	4/1/2003	1056	41	4	164	CONTRACTOR-N	CON-NT HLF	1111	SPRING C'	1	TF	527025504				TRIMMED TREE REPL BAD N CONN A1 POLE NEED STRAIGHTEN 35' POLE AN AT THIS ADDRESS AN NEXT DOOR TR ACCESS IF GRD DRT CORROSION COPPER OVER N. RPLD BEC CONN @ PL-	1	0
FORCED INTERR					54548200	22003091004	L	4/1/2003	1111	69	1	69	TREE CLEARANC	TREE CLEAR	6670	CRESTRID		DR					NEED TO REPLACE 1/0 4 WIRE DROP, AFTER 1800 TONIGHT, MMHPAND TAP CREWS REPLACED DROPS AND RECONNECTED LEFT MAIN SWITCH OFF TRX# 3417 AND 3584 PEK RGR	1	0
FORCED INTERR	SH	PJ 02	31332	B14C	58484444	22003091004	L	4/1/2003	1150	262	1	262	CUST EQP RELA	CUST RLTD	5111	FM 2351	1	DR					REFUSED TR ----SQUIRREL, REF TR; LF WAS NOT OUT	1	0
FORCED INTERR	FB	RS 04	12725	12KT		22003091005	F	4/1/2003	1151	64	9	576	SQUIRREL	SQUIRREL	BROOKS & FOU		1	LF	12KT	TF	434880331		REF LF	1	0
FORCED INTERR	BL	DN 12	10580	31ACN	53573228	22003091005	F	4/1/2003	1152	34	25	850	STRONG WIND	WIND	W DALLAS @ PI		1	LF	31ACN				REPLACED BAD RUBBER COATED DROPS FOR BETTERMENT.. RPLD DR.	1	0
FORCED INTERR	MP	WO 14	41806	1PB	51609425	22003091005	L	4/1/2003	1217	119	1	119	OH SEC/DR CL NI	OH SC CL-N	2206	DE MILO	1	DR					REPL KING PIN & V-30---ROTTED OFF---REFUSED 15KK 10T. PIU PR-FUSE BLOWN. REF LF	1	0
FORCED INTERR	FB	WR 08	1553A	M553	36379017	22003091006	F	4/1/2003	1230	101	1	101	INSULATOR	INSULATOR	1811	FM 1299	1	LF	15KK	PR			REF TR.	1	0
FORCED INTERR	SH	TE 03	31306	6D9	55503565	22003091004	T	4/1/2003	1248	49	1	49	LIGHTNING	LIGHTNING	5959	S SAM HOU	1	TF	555035536				REF TR.	1	0
FORCED INTERR	BL	HP 02	40878	22SW	53574267	22003091006	T	4/1/2003	1312	32	1	32	UNKNOWN	UNKNOWN	2221	W DALLAS 1	1	TF	535742678				HAS WILDLIFE GUARD, BUT SQUIRREL SOMEHOW GOT ACROSS SOMETHING TO BLOW FUSE. REF TR;	1	0
FORCED INTERR	MP	AN 08	40048	A19	53607296	22003091006	T	4/1/2003	1325	21	8	168	SQUIRREL	SQUIRREL	112	WEISENBEI	1	TF	536072986				PICKED BUP BONE SPAN OF 1/0 PRIMARY AND REPLACED BELL. PIU PR-FUSE BLOWN.	1	0
FORCED INTERR	BL	GT 03	40848	C43H	53586370	22003091007	F	4/1/2003	1357	87	20	1740	CUST EQP RELA	CUST RLTD	4200	MAIN ST	1	LF	C43H	PR			PIU DR. RPLD CONN @ WH.	1	0
FORCED INTERR	GP	WF 43	20542	A57W	52689355	22003091071	L	4/1/2003	1414	130	1	130	FIRE	FIRE	21119	HARDY R	1	DR					FOUND TREE ON PRI AT 11014 STROUD. NON PUC SECT 11748 TWB	1	1
FORCED INTERR	SU	AF 01				22003091008	C	4/1/2003	1441	0	0	0	FLLNG TREE IN E	TREE FL/IE	AF01	CKT LOCI		CL	AF01					0	0
FORCED INTERR	SU	AF 01	11752			22003091008	C	4/1/2003	1441	35	2502	87570	FLLNG TREE IN E					CL	AF01					0	0
FORCED INTERR	SU	AF 01	11749			22003091008	C	4/1/2003	1441	39	893	34827	FLLNG TREE IN E					CL	AF01					0	0
FORCED INTERR	SU	AF 01	1G282			22003091008	C	4/1/2003	1441	64	41	2624	FLLNG TREE IN E					CL	AF01					0	0
FORCED INTERR	SB	WT 03	21822	SB4	51582133	22003091008	T	4/1/2003	1511	33	3	99	BU DISC OR BARI	DISC/BARRL	211	CHIMNEY R	1	TF	515821331				REFUSED 25 KVA POWER POT IN OPEN DELTA BANK. REF TR;	1	0
FORCED INTERR	CH	PW 05	40942	N95E	57598083	22003091008	T	4/1/2003	1521	282	2	524	UNKNOWN	UNKNOWN	405	SPANIEL	1	BU	575980836				CHANGED OUT 26KVA CBP WITH 28KVA CON. IN REAR OF 405 SPANIEL. RPLD BIJ TR.	1	0
FORCED INTERR	BL	HE 06	41132		53584230	22003091009	T	4/1/2003	1536	76	11	836	LIGHTNING ARRE	LTNG ARRS	400	OXFORD #9		TF	535842361				CERAMIC ARRESTOR BLOWN IN CLEAR. REF TR.	1	0
FORCED INTERR	SB	CB 05	21441		50604200	22003091009	T	4/1/2003	1541	121	14	1694	BU DISC OR BARI	DISC/BARRL	9028	SPRINGVIE		TF	506042006				REF TR.	1	0
FORCED INTERR	BL	ST 02	11664	Y19N	51553185	22003091010	F	4/1/2003	1611	65	1	65	SQUIRREL	SQUIRREL	5607	DASHWOC	1	LF	Y19N	TF	515531854		REFUSED 75 KVA LIGHTER POT AND ALSO MIDDLE PHASE OF LF Y19N OUT BY SQUIRREL. REF LF; REF TR.	1	0
FORCED INTERR	SH	AI 05	40924	JM7	61564377	22003091007	T	4/1/2003	1620	36	1	36	UNKNOWN	UNKNOWN	2012	MILLER CL	1	TF	615643772				REF TR.	1	0
FORCED INTERR	FB	RS 02	11388	SJL	43486469	22003091010	F	4/1/2003	1621	48	33	1584	SQUIRREL	SQUIRREL	AVE G, E OF 7TH		1	LF	SJL	TF	434864672		REFUSED LINE FUSE SJL 46/ ALSO REFUSED 75 KVA TRANSFORMER AT 815 7TH ST CAUSED BY SQUIRREL TRANSFORMER ALREADY HAD WILD LIFE PROTECTION REF LF; REF TR.	1	0
FORCED INTERR	HC	MV 02	14215	36KR	54433469	22003091010	T	4/1/2003	1648	75	2	150	BU DISC OR BARI	DISC/BARRL	9301	ACORN DF	1	TF	544334645				REFUSED TRANS ALSO LIA BLOWN NEED TO REPLACE AT LATER DATE. REF TR;	1	0
FORCED INTERR.	SU	CE 09	12993	H4SY	48533350	22003091010	F	4/1/2003	1652	99	85	8415	UNKNOWN	UNKNOWN	10419	HUNTING	2	LF	H4SY				REF TR; CORRECTED 2HRCRH-3-3	1	0
FORCED INTERR	HM	AT 42	2314C	S277R	60684418	22003091009	L	4/1/2003	1700	199	1	199	FLLNG TREE OUT	TREE FL/OE	1419	GUM TREE 1		SC					PIU SEC-1 CUST.	1	0
FORCED INTERR	SB	CB 11	21465	X5AX		22003091009	E	4/1/2003	1700	76	1	76	ROTTEN POLE	ROTTEN PLI	EMNORA @ HO		1	LF	X5AX	PD			ROTTEN 30FT CL 6 SERVICE POLE @ 9426 KENRWOOD NEED REPL ABAP OK @ THIS TIME	1	0
FORCED INTERR	GP	LU 44	2E139	X43J	50692098	22003091009	T	4/1/2003	1723	433	4	1732	UNKNOWN	UNKNOWN	17206	WINDY PI	2	BU	509920996				WE HAVE A OIL SPILL ON THIS TRANS AT 17206 WINDY PINES NEED CLEAN UP RPLD BIJ TR	1	0
FORCED INTERR	HC	AM 06	10753	88H	52529158	22003091010	E	4/1/2003	1752	83	78	6474	FLLNG TREE IN E	TREE FL/IE	2818	WUTHERII	1	LF	88H	PR			PIU PR-FUSE BLOWN.	1	0
FORCED INTERR	BL	JN 09	10036	9GW	50540513	22003091011	T	4/1/2003	1800	18	10	180	FOREIGN MATER	FRGN MATR	8522	MOBUD DF	1	TF	505405179				REFUSED 75 KVA LIGHTER DUE TO BROKEN FUSE. REF TR;	1	0
FORCED INTERR	BA	NP 41	3766K	94HL	59652407	22003091007	T	4/1/2003	1814	83	2	166	UNKNOWN	UNKNOWN	3735	SHORE SH	1	SC	596524077				RPLD CONN @ TR.	1	0
FORCED INTERR	GP	LK 03	40923	BU8	52617488	22003091010	T	4/1/2003	1825	177	9	1593	UNKNOWN	UNKNOWN	752	ROSIE	1	SC	526174893				RPRD SEC-1 CUST.	1	0
FORCED INTERR	BZ	LJ 03	30289	69GJ	53263359	22003091008	T	4/1/2003	1928	62	1	62	UNKNOWN	UNKNOWN	250	N DIXIE	1	TF	532633582				REFUSED POWER POT--MELTED OUT. REF TR	1	0
FORCED INTERR	KY	FM 03	27387	39AAL		22003091012	E	4/1/2003	2111	115	3	345	UNKNOWN	UNKNOWN	32610	MALLARD	1	LF	43AHH	PR			PICKED UP ONE SPAN OF PRIMARY BEHIND CHILD FUSE V43 A H 20T AND GOT BERV ON. PIU PR-FUSE BLOWN. REF LF (PER CREW ONLY CHILD FUSE WAS OUT - BEV QA)	1	0
FORCED INTERR	SH	CC 04	30173	U17	54528264	22003091008	L	4/1/2003	2130	75	1	75	TREE CLEARANC	TREE CLEAR	5619	GRACE PC	1	SC					MADE REPAIRS TO DROP @ POLE. RPLD BEC CONN @ PL-1 CUST	1	0
FORCED INTERR	GP	FR 44	21407	M35Z	50626516	22003091010	F	4/1/2003	2144	0	0	0	UNKNOWN	UNKNOWN	10106	HANNON	2	LF	M35Z	BU	506265067		REPLACED BAD TF #13 @ 7510 LOG VIEW DR. B/O 7828	1	0
FORCED INTERR	GP	FR 44				22003091010	F	4/1/2003	2144	201	74	14874	UNKNOWN				2	LF	M35Z					0	0
FORCED INTERR	GP	FR 44				22003091010	F	4/1/2003	2144	476	6	2858	UNKNOWN				2	LF	M35Z					0	0
FORCED INTERR	SH	SH 01	30892	KK3	57525339	22003091008	T	4/1/2003	2244	34	8	272	UNKNOWN	UNKNOWN	10605	CHAMBER	1	TF	575253954				BAD FUSE. REF TR;	1	0
FORCED INTERR	MP	HR 01	41028	N36N	53599267	22003092000	T	4/2/2003	0556	31	2	62	BU DISC OR BARI	DISC/BARRL	228	CAVALCADE	1	TF	535992675				REPLACED FUSE BARREL ON 25 KVA POWER XFMR RPLD BIJ BARREL ON TR. REF TR. MEK	1	0
FORCED INTERR	SB	BM 03	21485	Y63W	48589521	22003092000	A	4/2/2003	0600	99	31	3089	SPLICE	SPLICE	1701	UPLAND BI	2	LF	Y63W	PR			RESTORED SERVICE ON # 0 87827 ... BAD SPAN OF PRIMARY 180L URD PR BENT M&G TO T&D B/48	1	0
FORCED INTERR	SH	PA 03	30764	S95	57542123	22003092000	F	4/2/2003	0640	56	15	840	UNKNOWN	UNKNOWN	5435	WILLOW C	1	LF	S95				REFUSED MIDDLE & E PHASE OF LF S 95. REF LF;	1	0
FORCED INTERR	MP	WV 02	41806	E92C	55586455	22003092000	T	4/2/2003	0736	31	14	434	SQUIRREL	SQUIRREL	6819	EAGLE PAS	1	TF	555864501				REFUSED TRNS @ 6819 EAGLE PASS / LEFT SERV ON / NOTIFIED. REF TR	1	0
FORCED INTERR	BA	CD 07	40386	85DN	63579198	22003092000	F	4/2/2003	0742	152	14	2128	STRONG WIND	WIND	1400	N 7TH ST	1	PR	85DN				REF LF RPLD B/O PR JUMPER-FUSE HOT BLOWN.	1	0
FORCED INTERR	SH	SH 03	30904	59ED	57524455	22003092000	T	4/2/2003	0751	43	8	344	SQUIRREL	SQUIRREL	10322	NEY	1	TF	575244533				REFUSE 50 CONV IN THE REAR OF 10318 NEY OUT BY BCI. REF TR.	1	0
FORCED INTERR	GP	AD 11	40071	C71Z	53627561	22003092000	T	4/2/2003	0800	35	1	35	BU DISC OR BARI	DISC/BARRL	1014	GULF BANI	1	TF	536275615				100 TR. REF TR.	1	0
FORCED INTERR	BL	HE 07	41136		53583329	22003092001	T	4/2/2003	0858	117	5	585	BU DISC OR BARI	DISC/BARRL	3219	WHITE OA		TF	535832909				REFUSED 25 KVA POWER TRANSFORMER PULLED FUSE. REF TR.	1	0
FORCED INTERR	MP	CL 05	40490	A32F	56572477	22003092001	T	4/2/2003	0900	35	6	210	SQUIRREL	SQUIRREL	1728	SILVERDAI	1	TF	565724733				REFUSED 75 CONV ... NO WILDLIFE PROTECTION NEEDED. REF TR;	1	0
FORCED INTERR	MP	HM 03	11016	J37Y	54541417	22003092002	L	4/2/2003	0907	53	1	53	TREE CLEARANC	TREE CLEAR	3635	IDAHO ST	1	SC					TRIMED TREES REPAIRED OPEN L LEG AT POLE. RPLD BEC CONN @ PL-1 CUST.	1	0
FORCED INTERR	MP	WV 02	41806	71AAS	47517092	22003092001	E	4/2/2003	0914	42	7	294	SQUIRREL	SQUIRREL	710	VENICE ST	1	TF	475170924				REFUSED LIGHTER XFMR SQUIRREL HAS WILD LEFT ON AND WORKI NG CUST NOTIFIED. REF TR;	1	0
FORCED INTERR	MP	CL 09	40510		56570536	22003092002	T	4/2/2003	0911	52	1	52	BU DISC OR BARI	DISC/BARRL	8006	TILGHAM		TF	565705397				25 CBP REF TR;	1	0
FORCED INTERR	SU	IM 48	12059	71AAS	47517092	22003092001	E	4/2/2003	0914	42	7	294	SQUIRREL	SQUIRREL	710	VENICE ST	1	TF					REPL. IM RUBBER COATED DROPS W/ IM AL. 3W DROPS. RPLD DR. MEK	1	0
FORCED INTERR	MP	CL 09	40510		56570536	22003092002	T	4/2/2003	0911	52	1	52	BU DISC OR BARI	DISC/BARRL	8006	TILGHAM		TF					REF LF OUT BY SQUIRREL 5118 MYRTLEWOOD NEED DISC & VALP REF LF MEK	1	0
FORCED INTERR	BA	CD 05	40370	RE3	63576415	22003092003	L	4/2/2003	1018	80	1	80	OH SEC/DR CL NI	OH SC CL-N	507	HAROLD LN	1	DR					BD TR. REF TR.	1	0
FORCED INTERR	HC	HM 09	11049	JM1	54536468	22003092003	F	4/2/2003	1030	26	72	1872	SQUIRREL	SQUIRREL	5118	MYRTLEW	1	LF	JM1				REFUSED LINE FUSE, TR FUSE ACTUALLY MEK	1	0
FORCED INTERR	GP	LK 06	21880	M25R	52622238	22003092004	T	4/2/2003	1030	36	5	180	SQUIRREL	SQUIRREL	9315	WILLOW	1	TF	526223843				REPLACED 38 KV DICONNECT, RPLD BIJ DISC-TF BLOWN. REF TR.	1	0
FORCED INTERR	BA	BT 06	40142		62572264	22003092003	T	4/2/2003	1055	46	7	322	BU DISC OR BARI	DISC/BARRL	5105	BAYWAY C	1	TF	625722680				MADE REPLACED BAD ELBOW AND BUSHING NO X-PRIMARY ELBOW 3128 ROYAL CRESCENT REF TF RPLD TR BUSH. RPLD ELBOW @ TR NO NEED TO BUSCABE B/O 7832 CAC	1	0
FORCED INTERR	GP	FR 46	21288	S266S	50613136	22003092005	T	4/2/2003	1101	186	3	558	BU DISC OR BARI	DISC/BARRL	8202	ELLINGER	1	TF	506131095	DB			REPL. BURNT UP KEARNY FUSE BARREL ON 99 LL LPOT RPLD BIJ BARREL ON TR.	1	0
FORCED INTERR	HM	KW 41	2483D	M82E		22003092005	F	4/2/2003	1111	194	45	8730	URD ELBOW	URD ELBOW	3118	ROYAL CR	1	LF	M34E			PR	REF TR.	1	0
FORCED INTERR	HC	AR 42	1583A	Y80C	52474317	22003092006	T	4/2/2003	1144	44	6	264	BU DISC OR BARI	DISC/BARRL	4115	LILLY	1	TF	524743179				Replaced broken meter and moved back. RPLD MTR.	1	0
FORCED INTERR	FB	DA 06	11328	X17P	45373106	22003092006	T	4/2/2003	1200	52	2	104	SQUIRREL	SQUIRREL	1322	WOODWA	1	TF	453731087				repaired drop damaged by the trimmers, neit company tree trimmers. PIU DR.	1	0
FORCED INTERR	MP	HM 02	11014	HM9	54544376	22003092005	E	4/2/2003	1220	30	1	30	VANDALISM	VANDALISM	6715	NEW YORI	1	MT					TRIMMED TREE LIMBS OFF 60 CBP XFMER--CLEANED UP LOOSE REC. FLAG AND CT ON XFMER--TIGHTENED UP REC. FLAG AND LEFT OK---CUST. NOT RPRD BEC CONN @ PL-1 CUST	1	0
FORCED INTERR	BA	CD 07	40388	A46S	63569300	22003092004	L	4/2/2003	1234	57	1	57	CONTRACTOR-N	CON-NT HLF	510	S CIRCLE D	1	DR					HOME TO RIDE OUT CKT - WORKING B/O CLOSE TO HV-05 (CONSTRUCTION (WATC HING) ***CREW LATER FOUND TREE ON PRIMARY @ 11808 ROCKY KNOLL *HV-12 LIO ***SEE SO#175 & 8	1	1
FORCED INTERR	BA	CD 11	40390	HZ9	63577384	22003092004	T	4/2/2003	1241	80	6	480	TREE CLEARANC	TREE CLEAR	102	MORRELL S	1	SC	635773845				HOME TO RIDE OUT CKT - WORKING B/O CLOSE TO HV-05 (CONSTRUCTION (WATC HING) ***CREW LATER FOUND TREE ON PRIMARY @ 11808 ROCKY KNOLL *HV-12 LIO ***SEE SO#175 & 8	0	0
FORCED INTERR	SU	HY 05	11711			22003092006	C	4/2/2003	1250	4	2767	11068	TREE CLEARANC	TREE CLEAR	11906	ROCKY R		CL	HY05				SEE TBL SO#174 - HOME REMOVED TREE LIMB OFF PRIMARY @ 11808 ROCKY KNOLL TW	1	1
FORCED INTERR	SU	HY 12	11711			22003092006	C	4/2/2003	1250	4	601	2404	TREE CLEARANC	TREE CLEAR	11906	ROCKY R		CL	HY05					0	0
FORCED INTERR	SU	HY 12				22003092011	C	4/2/2003	1330	0	0	0	TREE CLEARANC	TREE CLEAR	11906	ROCKY K		CL	HY12					0	0
FORCED INTERR	SU	HY 12	1G495			22003092011	C	4/2/2003	1330	17	355	6035	TREE CLEARANC					CL	HY12					0	0
FORCED INTERR	SU	HY 12	11711			22003092011	C	4/2/2003	1330	33	601	19833	TREE CLEARANC					CL	HY12					0	0
FORCED INTERR	GP	HV 07	20532		53640116	22003092007	L	4/2/2003	1430	185	1	185	FLLNG TREE OUT	TREE FL/OE	14915	WELLMAN		DR					PICKED UP # 4 3 C TWIST PIU DR	1	0
FORCED INTERR	HM	KW 41	2483D	M34E	57697462	22003092007	T	4/2/2003	1437	40	6	240	UNKNOWN	UNKNOWN	3170	E LAKE CR	2	TF	576974628				REPLACED BAYONET FUSE ON URD TRANS . REF TR.	1	0
FORCED INTERR	SB	WT 06	21832	81GE	51582200	22003092010	T	4/2/2003	1438	44	2	88	UNKNOWN	UNKNOWN	72	SADDLEBRO	1	TF	515822033				REF TR.	1	0
FORCED INTERR	BZ	VL 04	3526D	E84F	56239401	22003092005	T	4/2/2003	1500	111	3	333	OH SEC/DR CL HI	OH SC CL-H	610	WAVE CT	1	SC	562394015				RPLD BUSS WORK @ TR.	1	0
FORCED INTERR	SH	CG 04	30223	P97D	57531528	22003092005	L	4/2/2003	1500	39	1	39	COLLISION	COLLISION	512	LOUISIANA	1	SC					PIU BEC-1 CUST	1	0
FORCED INTERR	HC	BR 10	11160	RA5	51537314	22003092011	T	4/2/2003	1500	50	9	450	BU DISC OR BARI	DISC/BARRL	5102	WAYCROS	1	TF	515373142				REPLACED BURN UP FUSE BARREL B/O CLOSE TO HV-05 (CONSTRUCTION (WATC HING) RPLD BIJ BARREL ON TR.	1	0
FORCED INTERR	MP	WO 02	41834		52607326	22003092006	E	4/2/2003	1511	187	1	187	OH SEC/DR CL NI	OH SC CL-N	1003	CHESHIRE		DR			SC		CHG OUT A SET OF # 4 DROPS WITH A SET OF 1/0 DROPS. RPLD DR. RPLD CONN @ WH. RPLD CONN @ PL	1	0
FORCED INTERR	SH	CG 06	30203	I50C	57532273	22003092006	F	4/2/2003	1516	42	66	2772	UNKNOWN	UNKNOWN	801	IOWA	1	LF	I50C				UNPROTECTED CSP_8 _REF LF	1	0
FORCED INTERR	SL	SE 41	10162	60AAY	36558494	22003092011	T	4/2/2003	1516	269	1	269	COLLISION	COLLISION	8542	MORAVIAN	1	BU	365584944	SC			REPL 7200/120/240 - 25 KVA TRANS WITH THE SAME REP BUSS WORK, LIGHTNING ARRESTOR & REPL ONE SPAN OF 1/0 3- CON TWIST DUMP TRUCK TORE DOWN DROPS & PULLED BUSS	1	0
FORCED INTERR	SH	DR 06	30285	6SH	56530416	22003092006	F

FORCED INTERR	SH	DR 06	30288		5553555	220030920093	T	4/2/2003	1645	508	10	5080	UNKNOWN	UNKNOWN	6730	RIDGEWA		BU	555355582									1	0
FORCED INTERR	CH	SW 06	41685	DN4	5561840	320030920071	L	4/2/2003	1645	95	1	95	TREE CLEARANC	TREE CLEAF	7619	STERLING	1	DR										1	0
FORCED INTERR	GP	WF 41	2430C		5169807	220030920094	T	4/2/2003	1707	314	1	314	UNKNOWN	UNKNOWN	18001	CYPRESS		BU	516980752									1	0
FORCED INTERR	SB	ME 06	21604	C95T	4858106	120030922015	L	4/2/2003	1727	81	1	81	OH SEC/DR CL H	OH SC CL-H	818	THICKET LN	1	DR										1	0
FORCED INTERR.	BL	SF 42	10453		5157430	120030920151	T	4/2/2003	1736	74	1	74	UNKNOWN	UNKNOWN	5539	CRANBRO		TF	515743063									1	0
FORCED INTERR	CH	PW 02	40931		5761035	320030920071	L	4/2/2003	1859	62	1	62	OH SEC/DR CL NI	OH SC CL-N	10027	VALLEY S		DR										1	0
FORCED INTERR	CH	GP 05	40798	D4N	5757148	320030920081	T	4/2/2003	2130	386	6	2316	UNKNOWN	UNKNOWN	10823	LANE #6	1	BU	575714809									1	0
FORCED INTERR	MP	NS 04	41554	NA6	5458418	220030930001	T	4/3/2003	0037	38	5	190	BU DISC OR BARI	DISC/BARRL	2019	BROOKS	1	LF	545841847									1	0
FORCED INTERR	SH	SP 09	30989	M92S	5853900	320030930003	F	4/3/2003	0040	0	0	0	SPLICE	SPLICE	4211	FAIRWOOI	2	LF	M92S	PR								1	0
FORCED INTERR.	SH	SP 09				320030930003	F	4/3/2003	0040	241	14	3374	SPLICE				2	LF	M92S									0	0
FORCED INTERR	*SH*	*SP 09*				*320030930003*	*F*	*4/3/2003*	*0040*	*242*	*23*	*5568*	*SPLICE*				*2*	*LF*	*M92S*									0	0
FORCED INTERR	MP	HM 10	10955		5455416	220030930003	T	4/3/2003	0224	45	2	90	COLLISION	COLLISION	4300	GRIGGS		TF	545541620									1	0
FORCED INTERR	SL	SE 41	22492		3556053	120030930001	T	4/3/2003	0533	96	2	192	BIRD	BIRD	2013	MEYER		TF	355605366									1	0
FORCED INTERR	GP	BA 46	20619	H7SW	5066317	220030930006	T	4/3/2003	0638	94	3	282	VINES	VINES	5919	SPANISH (	1	PR	506631734									1	0
FORCED INTERR	BL	CR 08	40544		5357452	120030930006	L	4/3/2003	0738	145	1	145	OH SEC/DR CL H	OH SC CL-H	1003	STUDEMO		SC										1	0
FORCED INTERR	GA	AL 08	30052	Y55F	6240411	320030930010	T	4/3/2003	0830	83	1	83	CUST EQP RELAT	CUST RLTD	8925	DELESANE	1	TF	624041146									1	0
FORCED INTERR	FB	CRB4(	13005	86QE	4648657	120030930010	F	4/3/2003	0838	70	76	5320	LIGHTNING ARRE	LTNG ARRS	7502	GUINEVER	2	LF	86QE									1	0
FORCED INTERR.	SB	CB 06	21441	K90S	5080319	120030930013	T	4/3/2003	0838	29	7	203	CONTRACTOR (H	CON-HLP	3703	VALLEYFIE	1	TF	508031955									1	0
FORCED INTERR	SH	SH 04	30910	15JM	5751434	320030930013	T	4/3/2003	0852	31	12	372	SQUIRREL	SQUIRREL	10330	BUENA P	1	TF	575143466									1	0
FORCED INTERR	BZ	BZ 06	30148		5226850	320030930014	L	4/3/2003	0855	72	1	72	OH SEC/DR CL H	OH SC CL-H	103	CHERRY		SC										1	0
FORCED INTERR	FB	WR 12	11282	73AP	3638828	120030930015	L	4/3/2003	0901	91	1	91	VANDALISM	VANDALISM	722	OLD BOLINI	1	MT										1	0
FORCED INTERR.	*BL*	*DN 07*	*10578*	*13JJ*	*5356043*	*120030930016*	*L*	*4/3/2003*	*0914*	*122*	*1*	*122*	*FLLNG TREE OUT*	*TREE FL/DE*	*2035*	*KIPLING S*	*1*	*SC*										1	0
FORCED INTERR	FB	EB 05	11290	A8C	3644116	120030930025	T	4/3/2003	0951	83	1	83	O/H PRIMARY CU	OH PR CLMF	19926	COUNTY	1	TF	364411653									1	0
FORCED INTERR	HM	AT 42	2314C	S277G	6069345	220030930018	F	4/3/2003	0955	37	26	962	UNKNOWN	UNKNOWN	25418	VANYA	1	LF	S2779									1	0
FORCED INTERR	KY	WA 42	2161A	S7N	3854822	120030930027	L	4/3/2003	1000	66	1	66	OH SEC/DR CL H	OH SC CL-H	38630	CHEYENN	1	DR										1	0
FORCED INTERR	MP	HE 02	41108	PE3	3359108	220030930024	L	4/3/2003	1017	122	1	122	TREE CLEARANC	TREE CLEAF	1400	TULANE	1	SC		DR								1	0
FORCED INTERR	MP	NS 06	41575	F50	5459921	220030930025	L	4/3/2003	1017	112	1	112	TREE CLEARANC	TREE CLEAF	4603	LEFFINGW	1	SC										1	0
FORCED INTERR	SH	PA 04	30776	75R4	5755806	320030930027	T	4/3/2003	1030	114	2	228	OH SEC/DR CL H	OH SC CL-H	909	SHAVER ST	1	TF	575580687	SC								1	0
FORCED INTERR	BA	LP 05	41846	R24	6154713	320030930027	L	4/3/2003	1034	54	1	54	OH SEC/DR CL NI	OH SC CL-N	11515	N D ST	1	DR										1	0
FORCED INTERR	CH	SW 05	41954	F53L	5562725	320030930028	T	4/3/2003	1038	63	4	252	O/H PRIMARY CU	OH PR CLMF	10818	CHEEVES	1	PR	556272525									1	0
FORCED INTERR	BZ	VL 02	31125	37DV	5424532	320030930029	T	4/3/2003	1046	155	2	310	BU DISC OR BARI	DISC/BARRL	1501	YELLOWS	1	BU	542453281									1	0
FORCED INTERR	MP	WO 02	41837	J15	5260245	220030930026	L	4/3/2003	1050	113	1	113	OH SEC/DR CL H	OH SC CL-H	1511	RICHELIEI	1	SC										1	0
FORCED INTERR.	FB	EB 05	11291	84KK	3548636	120030930044	T	4/3/2003	1120	*180*	1	*180*	*BU DISC OR BARI*	*DISC/BARRL*	19005	COUNTY	1	TF	354863648	DB								1	0
FORCED INTERR	GP	LK 05	21885	51E	5280151	320030930036	T	4/3/2003	1239	81	1	81	BU DISC OR BARI	DISC/BARRL	4000	PINEMONT	1	TF	528015157									1	0
FORCED INTERR	MP	WO 12	41878		5280618	320030930038	T	4/3/2003	1238	200	1	200	UNKNOWN	UNKNOWN	909	SUE BARNE		BU	528061851									1	0
FORCED INTERR	GA	GA 09	31226	M8W	6738908	320030930043	L	4/3/2003	1258	63	1	63	TREE CLEARANC	TREE CLEAF	2513	43RD ST	1	DR										1	0
FORCED INTERR	BL	SF 13	10526	B53	5256347	120030930061	L	4/3/2003	1317	68	1	68	OH SEC/DR CL NI	OH SC CL-N	2401	MACONDA	1	SC										1	0
FORCED INTERR	SB	DV 03	10592	X87H	5056325	120030930064	T	4/3/2003	1335	24	1	24	UNKNOWN	UNKNOWN	2724	CROSSVIE	1	TF	505632574									1	0
FORCED INTERR	BL	GT 08	41692	BR2	5356553	120030930065	T	4/3/2003	1337	77	6	462	OH SEC/DR CL H	OH SC CL-H	3321	STANFORI	1	SC	535655341									1	0
FORCED INTERR	HM	LA 02	41220	B50Z	5563049	220030930047	L	4/3/2003	1340	348	1	348	ROTTEN POLE	ROTTEN PLI	4834	DEBENEY	1	PD										1	0
FORCED INTERR	BA	CD 11	40372	WY3	6357728	320030930048	T	4/3/2003	1415	137	9	1233	OH SEC/DR CL H	OH SC CL-H	1604	WILBURN I	1	SC	635772649									1	0
FORCED INTERR	HC	HOCG	11157	A56G	5253001	120030930074	L	4/3/2003	1431	38	1	38	OH SEC/DR CL H	OH SC CL-H	4554	WARM SPI	1	SC										1	0
FORCED INTERR	GP	WF 42	20351	54DL	5267326	220030930051	T	4/3/2003	1519	64	19	1216	TRANSFORMER	TRANSFRMI	5135	BLUE ASI	2	BU	526732636									1	0
FORCED INTERR	CY	PI 44	20123	438U	4774355	220030930052	L	4/3/2003	1521	83	1	83	OH SEC/DR CL H	OH SC CL-H	29622	MIDLAND	1	SC										1	0
FORCED INTERR	GP	DH 10	22184	K60L	5160658	220030930054	T	4/3/2003	1529	74	5	370	TREE CLEARANC	TREE CLEAF	2302	DEL NORT	1	TF	518085853	SC								1	0
FORCED INTERR	FB	EB 05	11291	84KK	3548636	120030930091	T	4/3/2003	1539	259	1	259	INSULATOR	INSULATOR	19005	COUNTY	1	BU	354863648									1	0
FORCED INTERR	CH	GW 02	40897	833B	5661704	320030930056	L	4/3/2003	1615	86	1	86	OH SEC/DR CL H	OH SC CL-H	8707	SULTAN	1	DR										1	0
FORCED INTERR.	SH	PA 07	30791	C85D	5754620	320030930061	L	4/3/2003	1628	25	1	25	OTHER	AGE	2010	HELEN	1	DR										1	0
FORCED INTERR	*MP*	*NS 01*	*40947*	*ND6*	*5459235*	*220030930058*	*T*	*4/3/2003*	*1651*	*22*	*9*	*198*	*BU DISC OR BARI*	*DISC/BARRL*	*5110*	*COCHRAN*	*1*	*TF*	*545923593*									1	0
FORCED INTERR	HC	HM 04	14311	K19H	5353908	120030930102	L	4/3/2003	1655	59	1	59	OH SEC/DR CL NI	OH SC CL-N	9437	FAIRLAND	1	DR										1	0
FORCED INTERR	CH	GP 04	40798	17ES	5758403	320030930064	T	4/3/2003	1658	34	8	204	SQUIRREL	SQUIRREL	1405	BELIN DR	1	TF	575840341									1	0
FORCED INTERR	SU	JN 01	10001		4955499	120030930104	T	4/3/2003	1700	72	50	3600	CUST EQP RELAT	CUST RLTD	8005	S GESSNE		TF	495499925									1	0
FORCED INTERR.	BL	DV 02	10589	DT4	5056302	120030930105	T	4/3/2003	1705	82	10	820	SQUIRREL	SQUIRREL	8922	BELLFLOW	1	TF	505630293									1	0
FORCED INTERR.	BL	BL 09	10089	3QL	5255254	120030930106	T	4/3/2003	1711	64	12	768	BU DISC OR BARI	DISC/BARRL	5534	WESLAYAI	1	TF	525525496									1	0
FORCED INTERR	GP	RU 05	41674	GJ8	5362444	220030930067	T	4/3/2003	1730	53	3	159	BU DISC OR BARI	DISC/BARRL	152	MAPLE LN	1	TF	536244421									1	0
FORCED INTERR	FB	RE 01	14275	Y74B		120030930106	F	4/3/2003	1731	200	2	400	OH SEC/DR CL H	OH SC CL-H	2707	FM 2218	1	LF	Y74B	SC	44471309							1	0
FORCED INTERR	SH	FT 02	30398	B64L	5954917	320030930068	L	4/3/2003	1735	83	1	83	TREE CLEARANC	TREE CLEAF	2722	COY	1	SC										1	0
FORCED INTERR.	SB	CB 04	21430	33ADB	4959959	120030930113	T	4/3/2003	1800	57	1	57	METER EQUIPME	MTR EQUIP	9721	KEMPWOC	1	LF	33ADB									1	0
FORCED INTERR	CH	SW 09	41897	B65C	5562638	320030930070	L	4/3/2003	1805	37	1	37	CONTRACTOR-N	CON-NT HLF	6318	ROSEMAR	1	DR										1	0
FORCED INTERR	GP	LU 42	20591	75ACH	5170425	220030930068	T	4/3/2003	1820	111	5	555	INSULATOR	INSULATOR	3103	ENCHANTI	2	BU	517042552									1	0
FORCED INTERR	SH	TE 02	31452	66M	5649220	320030930072	T	4/3/2003	1833	77	25	1925	SQUIRREL	SQUIRREL	TELEPHONE	@	1	LF	66M									1	0
FORCED INTERR	SU	RO 08	12248		4953635	120030930125	T	4/3/2003	1851	115	1	115	TRANSFORMER	TRANSFRMI	10420	1/2 SOUTI		BU	495363560									1	0
FORCED INTERR	BA	AT 41	41924	T42H	6186128	320030930074	T	4/3/2003	1913	70	1	70	UNKNOWN	UNKNOWN	19407	MILLER W	1	TF	618612803									1	0
FORCED INTERR	SB	CB 04	21430	J27N	4959956	120030930125	T	4/3/2003	1917	42	1	42	METER EQUIPME	MTR EQUIP	9721	KEMPWOC	1	DB	495995645									1	0
FORCED INTERR	GA	AL 10	30043	165A	6141327	320030930075	T	4/3/2003	1928	49	8	392	UNKNOWN	UNKNOWN	11855	ZIND	1	TF	614132780									1	0
FORCED INTERR	SH	DR 03	30272		5653546	320030930076	T	4/3/2003	2000	43	9	387	TRANSFORMER	TRANSFRMI	8603	HINMAN		BU	565354601									1	0
FORCED INTERR	BL	ST 05	10214		5154355	120030930131	L	4/3/2003	2014	48	1	48	OH SEC/DR CL NI	OH SC CL-N	5544	ASPEN ST		DR										1	0
FORCED INTERR	GP	LU 44	22399	S208B	5069727	220030930075	L	4/3/2003	2011	46	1	46	OVERLOAD	OVERLOAD	18714	TOMATO	1	SC										1	0
FORCED INTERR	HC	FD 11	10711	A33B	5154004	120030930133	T	4/3/2003	2031	66	1	66	SQUIRREL	SQUIRREL	9106	HILLCROF	1	TF	515400453									1	0
FORCED INTERR	SB	GE 43	22161	R31Z	4661353	320030930136	F	4/3/2003	2111	163	48	7824	URD ELBOW	URD ELBOW	17823	GLENMOI	2	LF	R31Z			PR						1	0
FORCED INTERR.	GA	STWG	31020	87BA	6636634	320030930082	T	4/3/2003	2317	*59*	*18*	*1062*	*UNKNOWN*	*UNKNOWN*	3428	COVE VIEV	2	BU	663663415									1	0
FORCED INTERR	SH	SH 08	30928	M77T	5753713	320030930085	F	4/3/2003	2346	119	1	119	BU DISC OR BARI	DISC/BARRL	101	EDGEBROC	1	DB	M77T									1	0
FORCED INTERR	FB	BC 09	11313	Y89B	4443220	120030940004	T	4/4/2003	0625	204	1	204	UNKNOWN	UNKNOWN	9850	FM 361	1	DB	444322033									1	0
FORCED INTERR	CY	TB 45	21046	131P	4670452	220030940005	T	4/4/2003	0722	84	2	168	SQUIRREL	SQUIRREL	22033	LUTHERA	1	PR	467045227									1	0
FORCED INTERR	HC	GV 02	10909	FD6	5453841	120030940007	L	4/4/2003	0748	47	1	47	FLLNG TREE OUT	TREE FL/DE	5628	WILLOW C	1	DR										1	0
FORCED INTERR.	*FB*	*NV 02*	*11220*	*G43Z*	*4241639*	*120030940010*	*L*	*4/4/2003*	*0810*	*135*	*1*	*135*	*OH SEC/DR CL NI*	*OH SC CL-N*	*8911*	*HEARD LN*	*1*	*SC*										1	0
FORCED INTERR	BA	BT 07	31518	C44S	6258635	320030940006	F	4/4/2003	0844	0	0	0	CONTRACTOR (H	CON-HLP	4501	COACHMA	2	LF	C44S	PR								1	0
FORCED INTERR	BA	BT 07				320030940006	F	4/4/2003	0844	118	34	4012	CONTRACTOR (H				2	LF	C44S									1	0
FORCED INTERR	BA	BT 07				320030940006	F	4/4/2003	0844	118	13	1534	CONTRACTOR (H				2	LF	C44S									1	0
FORCED INTERR.	SH	PJ 02	31678		5848539	320030940006	T	4/4/2003	0900	150	1	150	STRONG WIND	WIND	5008	PENNYSTC		SC	584853933	DR								1	0
FORCED INTERR	MP	UN 09	41728	2S8	5456910	220030940012	L	4/4/2003	0920	33	1	33	CONTRACTOR-N	CON-NT HLF	1326	MUNGER	1	DR										1	0
FORCED INTERR	BA	LP 05	41846	52AAC	6154721	320030940013	L	4/4/2003	0920	215	1	215	COLLISION	COLLISION	11501	N AVENUI	1	SC										1	0
FORCED INTERR	SH	SB 04	31044		5855519	320030940014	T	4/4/2003	0935	25	2	50	O/H PRIMARY CU	OH PR CLMF	2204	RED BLUFI	1	TF	585551908									1	0
FORCED INTERR.	CY	TB 44	21021	J94G	4672915	220030940014	F	4/4/2003	0941	72	6	432	TREE CLEARANC	TREE CLEAF	KING BIRD	@ St	1	LF	J94G	PR	467291084	TF	467:					1	0
FORCED INTERR	HM	HB 46	21019	96AEG		220030940022	F	4/4/2003	0945	257	0	0	PRIMARY CONDU	PRIMARY	12314	BEACON	2	LF	96AEG	PR								1	0
FORCED INTERR	BZ	LJ 08	31312	RD3	5227734	320030940020	T	4/4/2003	1000	25	13	325	BU DISC OR BARI	DISC/BARRL	165	OAK	1	TF	522773491									1	0
FORCED INTERR	*GP*	*RU 02*	*41655*	*3HR*	*5362020*	*220030940022*	*F*	*4/4/2003*	*1007*	*89*	*3*	*267*	*BU DISC OR BARI*	*DISC/BARRL*	*CANINO AT CUS*		*1*	*LF*	*3HR*									1	0
FORCED INTERR	KY	FZ 43	24792		4458607	120030940028	T	4/4/2003	1051	57	1	57	UNKNOWN	UNKNOWN	21941	KATY FW		TF	445860765									1	0
FORCED INTERR.	GP	BA 42	2C149		5067838	220030940025	T	4/4/2003	1054	60	9	540	UNKNOWN	UNKNOWN	14907	PEBBLE E		PR	506783813									1	0
FORCED INTERR	GA	AL 10	30043	93HT	6141904	320030940027	T	4/4/2003	1054	43	1	43	LIGHTNING	LIGHTNING	6002	AVENUE A	1	TF	614190480									1	0
FORCED INTERR.	SU	STF08	12267		4851402	120030940034	T	4/4/2003	1100	89	1	89	SQUIRREL	SQUIRREL	14151	SOUTHW		TF	485140207									1	0
FORCED INTERR	RS	AE 06	35360	A10C	5633038	320030940025	T	4/4/2003	1111	164	2	328	LIGHTNING	LIGHTNING	6118	DANBURY	1	BU	563303889									1	0
FORCED INTERR	MP	CR 01	40931		5358585	220030940041	L	4/4/2003	1121	68	1	68	OH SEC/DR CL H	OH SC CL-H	114	PECORE ST		DR		SC								1	0
FORCED INTERR	SB	EC 12	21751	F21K	4958913	120030940036	F	4/4/2003	1128	25	18	450	TREE CLEARANC	TREE CLEAF	11918	QUEENSI	1	LF	F21K									1	0
FORCED INTERR	GP	FR 41	22835	A49K	4962849	220030940040	T	4/4/2003	1210	106	3	318	TREE CLEARANC	TREE CLEAF	7714	ROLLING F	1	PR	496284973									1	0
FORCED INTERR	BL	BR 07	10511	R6P	5154859	120030940042	L	4/4/2003	1228	68	1	68	CONTRACTOR-N	CON-NT HLF	4620	EVERGREI	1	DR										1	0
FORCED INTERR	SB	SR 12	21679	M20W		120030940046	F	4/4/2003	1301	12	4	48	UNKNOWN	UNKNOWN	1868	STEBBINS	1	LF	M20W									1	0
FORCED INTERR	SH	PE 04	30815	E38B	5546016	320030940046	F	4/4/2003	1337	50	10	500	*UNKNOWN*	*UNKNOWN*	5115	*COUNTY R*	1	LF	*E38B*									1	0
FORCED INTERR	HC	BL 03	10769	51MF	5052309	120030940052	F	4/4/2003	1340	67	11	737	COLLISION	COLLISION	11919	N GARDE	1	LF	51MF	PR								1	0
FORCED INTERR	SH	CC 01	30169	C31Z	5452613	320030940050	F	4/4/2003	1359	129	45	5805	BU DISC OR BARI	DISC/BARRL	5122	BUNGALO	1	DB	C31Z									1	0
FORCED INTERR	HM	SW 08	41692		5563633	220030940046	T	4/4/2003	1415	33	6	198	UNKNOWN	UNKNOWN	11923	SUBURB		TF	556363370									1	0
FORCED INTERR	HC	SO 41				120030940061	C	4/4/2003	1435	0	0	0	COLLISION	COLLISION	N OF FM 518 E (			CL	SO41	PR								1	0
FORCED INTERR	HC	SO 41	10831			120030940061	C	4/4/2003	1435	36	2285	82260	COLLISION					CL	SO41									1	0
FORCED INTERR	HC	SO 41	11590			120030940061	C	4/4/2003	1435	37	661	25197	COLLISION					CL	SO41									1	0
FORCED INTERR	HC	SO 41	10963			120030940061	C	4/4/2003	1435	43	426	18318	COLLISION					CL	SO41									1	0
FORCED INTERR	HC	SO 41	1G010			120030940061	C	4/4/2003	1435	66	203	13398	COLLISION					CL	SO41									1	0
FORCED INTERR	SB	SR 12	21679	M20W	4959317	120030940078	F	4/4/2003	1455	46	4	184	UNKNOWN	UNKNOWN	10600	SHADOW	1	LF	M20W									1	0
FORCED INTERR	SH	PO 09	41183	27EL	6249051	320030940085	T	4/4/2003	1511	58	3	174	VINES	VINES	334	BISCAYNE E	1	TF	624005180									1	0
FORCED INTERR.	CY	CYF42	21212	68GC	4662849	220030940054	F	4/4/2003	1529	*0*	*0*	*0*	*TERMINATOR*	*TERMINATO*	*18408*	*RAINBOW*	*2*	*LF*	*68GC*	*PR*		*TF*	*466*					1	0
FORCED INTERR.	CY	CYF42				220030940054	F	4/4/2003	1529	183	75	13725	TERMINATOR				2	LF	68GC									1	0
FORCED INTERR	CY	CYF42				220030940054	F	4/4/2003	1529	277	6	1662	TERMINATOR				2	LF	68GC									1	0
FORCED INTERR	BA	NP 44	41490	73AM	6183349	320030940090	L	4/4/2003	1530	68	1	68	HUMAN ERROR	HUMN ERRC	2929	HIGHWAY	1	DR										1	0
FORCED INTERR	SB	SR 10	21668	C60D	4958419	120030940097	T	4/4/2003	1552	68	10	680	UNKNOWN	UNKNOWN	12607	KINGSRIE	1	TF	495841941									1	0
FORCED INTERR	SB	TO 05	22164	1N9	5160515	120030940098	L	4/4/2003	1552	164	1	164	OTHER	AGE	5214	LAMONTE	1	DR										1	0
FORCED INTERR	SB	GE 46	21232	W26L	4760256	120030940101	F	4/4/2003	1552	0	0	0	URD BUSHING	URD BSHING	18067	RUSTIC S	2	LF	W26L	PR								1	0
FORCED INTERR.	SB	GE 46				120030940101	F	4/4/2003	1552	159	8	1272	URD BUSHING				2	LF	W26L									1	0

RPLD BU TR; REF TR; NEED TO STRAIGHTEN BANK POLE AT SERVICE CENTER'S CONVIENCE SRs 1 0
TREE LIMB FELL ON DROPS BREAKING NEUTRAL WIRE AND ONE HOT LEG MADE REPAIRS AND RESACKED DROPS RPRD DR, RESACKED DR. 1 0
RPLD BU TR. 1 0
RPLD CONN @ WH. 1 0
REF TR. 1 0
capl change all posts upon neutral. RPRD DR. 1 0
RPLD BU TR. 1 0
RPLD BU BARREL ON TR; 1 0
ISOLATED BAD URD PRI ON URD 90 7934; BAD PR BTwin TRNG & TR84. REF TP. 90L URD Primary ... SENT MSG TO T&D ... SRB "SUSCASING NECESSARY" MPO 1 0
0 0
0 0
39FT POLE Was BRACED WITH CROSSBARM BEFORE BFI TRUCK HANG LOW TELEPHONE CABLE. SEND MESSAGE TO CENTER, POLE NEEDS TO BE REBRACE OR REPLACE. BFI COMES BY HE 1 0
REF TR. 1 0
CLAER VINES AND REPLACED LIMITER ON 75 KVA. RPLD LIMITER @ TR. REF TR. MEK 1 0
REPLACED BURNED UP 336 TR LEAD ON A OPEN DELTA BANK. MEK 1 0
REFUSED POWER POT IN OPEN DELTA BANK. REF TR; 1 0
REFUSED TF BADE ---BLOWN ARRESTOR. REF TP. 1 0
REFUSED OPEN DELTA BANK OUT BY TREE TRIMMERS. REF TR; MEK 1 0
REF TR. 1 0
CREW REPLACED CONNECTIONS @ POLE NO MORE. JETE 1 0
Replaced 2 broken meters on temp pole. Meter W5T067231 kwh = 04858 x 1. New meter C8133046 kwh = 00000 x 1. Also replaced destroyed meter (37483230 with meter 0596335137 kwh = 00000 x 1. RPLD 1 0
PICKED UP ONE SPAN OF #4 3W BEC. FEEDING A CELL TOWER. PAU BEC-1 CUST. 1 0
REF 30VA PULLED FUSE, REF TR; 1 0
REF LF. 1 0
RPLD CONN @ WH. 1 0
REPLACED TWO SPANS OF #4 RECONDARY AND SERVICE DROPS WITH TWO SPANS OF 1/0 THREE CONDUCTOR TWIST. LEFT SERVICE WORKING RPLD DR. RPLD CONN @ WH. RPLD BEC 1 0
REPLACE BROKEN AT POLE, RPLD BEC CONN @ PL-1 CUST. MEK 1 0
REFUSED TRANS & REPAIRED BURNED UP BUSHINGS, REF TR; RPRD BUSS WORK @ TR. 1 0
replaced all open s @ with messgers drop. RPLD CONN @ WH. 1 0
REPLACED A HOT LINE CLAMP ON A 50 CBP TRANS. RPRD B/O PRI JUMP-TF NOT BLOWN; 1 0
CHGED OUT 75 CONV TRANS. LIGHTER POT, IN CLOSED DELTA BANK TAKEN OUT BY OLD AGE RPLD BU TR LATER. 1 0
REPLACED CLAMP @ POLE TRIMMED TREES. RPLD BEC CONN @ PL-1 CUST 1 0
RPLD BAU DISC-TF BLOWN REF TR. MEK 1 0
REF TR; 1 0
REPLACED A 100 KV

FORCED INTERR.	SB	GE 46			120030940101	F	4/4/2003	155	159	36	5724	URD BUSHING			2	LF	W26L												0
FORCED INTERR	SH	PE 03	31590	36DM	55501205	320030940092	T	4/4/2003	160	166	2	332	BU DISC OR BARI	DISC/BARRL	5522	BROOKSIE	1	TF	555012093										0
FORCED INTERR	BL	HE 09	10533	9EX	52578281	120030940103	F	4/4/2003	162	270	6	1620	TREE CLEARANC	TREE CLEAR	1059	KIRBY DR	1	LF	9EX										0
FORCED INTERR.	BA	BT 01	40098	TD7	63565325	320030940097	T	4/4/2003	162	20	8	160	CUST EQP RELA	CUST RLTD	600	MIRIAM ST	1	TF	635653254										0
FORCED INTERR	BL	SF 14	10442		52560428	120030940106	T	4/4/2003	162	82	8	656	BU DISC OR BARI	DISC/BARRL	2500	MID LN #6	1	TF	525604288										0
FORCED INTERR.	SH	TE 05	31087	77PT	56504551	320030940096	T	4/4/2003	162	36	1	36	COLLISION	COLLISION	8503	1/2 S SAM	1	TF	585045518										0
FORCED INTERR	MP	WV 03	41813		55586225	220030940056	T	4/4/2003	162	38	2	76	UNKNOWN	UNKNOWN	8903	LYONS AVI	1	TF	555862253										0
FORCED INTERR.	FB	WR 14	11285	CF9	36373537	120030940106	F	4/4/2003	164	109	4	436	VINES	VINES	SHEPPARD @ C		1	LF	CF9										0
FORCED INTERR	CH	JP 05	40618	70JN	60570234	320030940102	T	4/4/2003	164	38	2	76	BU DISC OR BARI	DISC/BARRL	15919	JACINTOI	1	TF	605702348										0
FORCED INTERR	SH	CK 03	31525		59506367	320030940103	T	4/4/2003	165	32	2	64	BU DISC OR BARI	DISC/BARRL	1518	MABRY MIL	1	TF	595063871										0
FORCED INTERR	SH	TE 07	31075	22E	56497594	320030940104	F	4/4/2003	165	50	1	50	CONTRACTOR-N	CON-NT HLF	PLUM @ BARRY		1	LF	22E										0
FORCED INTERR	BL	KB 05	10155	CK5	52567533	120030940114	T	4/4/2003	172	116	8	928	TREE CLEARANC	TREE CLEAR	3031	ELLA LEE	1	DB	525675333										0
FORCED INTERR	BA	HL 06	41186	B14D	61609165	320030940105	T	4/4/2003	172	253	2	506	UNKNOWN	UNKNOWN	1301	BATTLEBE	1	BU	616091631										0
FORCED INTERR	GP	THW4	20678	P78N	49650081	220030940082	T	4/4/2003	172	368	8	2944	URD XFMR SEC B	URD TR BUS	11635	HENLEY	2	BU	496500613										0
FORCED INTERR	BZ	VL 04	35268		56233533	320030940107	T	4/4/2003	172	163	1	163	UNKNOWN	UNKNOWN	1801	HIGHWAY		BU	562335328										0
FORCED INTERR	KY	GE 42	25638	24BH	45625256	220030940064	F	4/4/2003	173	0	0	0	TRANSFORMER	TRANSFRMF	7113	HAVEN CR	2	LF	24BH	BU	456252683								0
FORCED INTERR	KY	GE 42				220030940064	F	4/4/2003	173	215	72	15480	TRANSFORMER				2	LF	24BH										0
FORCED INTERR	KY	GE 42				220030940064	F	4/4/2003	173	215	23	4945	TRANSFORMER				2	LF	24BH										0
FORCED INTERR	KY	GE 42				220030940064	F	4/4/2003	173	473	9	4257	TRANSFORMER				2	LF	24BH										0
FORCED INTERR.	SB	EC 08	21740	E42S	50581465	120030940116	F	4/4/2003	175	140	1	140	UNKNOWN	UNKNOWN	1230	OAK TREE	1	LF	E42S										0
FORCED INTERR.	BL	ST 05	10218	8TB	51547574	320030940120	T	4/4/2003	181	175	7	1225	O/H PRIMARY CU	OH PR CLMF	4807	FERN	1	BU	515475749										0
FORCED INTERR	GA	KM 01	31476	K11	61458571	320030940110	L	4/4/2003	182	201	1	201	FLLNG TREE OUT	TREE FL/OE	618	SEMINOLE 1	1	DR											0
FORCED INTERR.	KY	MAR4	24812		45584277	120030940121	T	4/4/2003	182	111	1	111	UNKNOWN	UNKNOWN	19910	PARK RO		TF	455842739										0
FORCED INTERR.	BA	CD 04	40353	TB5H	64587575	320030940113	T	4/4/2003	185	98	4	384	BIRD	BIRD	3801	SUMMER L	1	TF	645875790										0
FORCED INTERR	BL	DV 01	10612	G7H	50566088	120030940124	T	4/4/2003	185	72	9	648	SQUIRREL	SQUIRREL	7814	WINDSWE 1		TF	505680862										0
FORCED INTERR	FB	BV 42	12925	S61O	42517578	120030940125	F	4/4/2003	190	86	31	2666	UNKNOWN	UNKNOWN	7319	FOSTER IS	1	LF	561O										0
FORCED INTERR	GP	HV 01	20494		52849228	220030940066	T	4/4/2003	190	43	1	43	BIRD	BIRD	11381	AIRLINE C		TF	528492263										0
FORCED INTERR.	FB	RS 05	1555F	X36E	43463014	120030940126	T	4/4/2003	192	63	4	252	HUMAN ERROR	HUMN ERRC	2711	ASPEN DR	1	TF	434630149										0
FORCED INTERR	HC	FD 06	10663	R73W	50536177	320030940133	F	4/4/2003	194	119	59	7021	URD BUSHING	URD BSHINC	10800	FONDREI	2	LF	R73W	PR									0
FORCED INTERR.	SB	EC 13	21715	P1C	50573255	120030940134	T	4/4/2003	194	81	2	162	SQUIRREL	SQUIRREL	29	S CHESKA U	1	TF	505732534										0
FORCED INTERR.	GA	GA 05	31199	L42	67386211	320030940111	T	4/4/2003	200	157	13	2041	OVERLOAD	OVERLOAD	1202	53RD ST	1	BU	673862121										0
FORCED INTERR.	CH	NM 03	41523	S85J	57585251	320030940115	T	4/4/2003	200	116	17	2006	UNKNOWN	UNKNOWN	12200	FLEMING	2	TF	575852514										0
FORCED INTERR	BL	BR 01	10799	P3B	52542069	120030940136	L	4/4/2003	204	152	1	152	OH SEC/DR CL HI	OH SC CL-H	4117	LEMAC	1	DR											0
FORCED INTERR	BL	HE 05	10679	W85A	52578475	120030940137	F	4/4/2003	204	170	45	7650	VINES	VINES	5292	MEMORIAL	2	LF	W85A										0
FORCED INTERR	SB	EC 11	21758	N61	49579171	120030940138	T	4/4/2003	204	171	5	855	OH SEC/DR CL HI	OH SC CL-H	10	HIBURY	1	SC	495791710										0
FORCED INTERR	CH	GW 02	40896	B92P	56613195	320030940122	L	4/4/2003	204	149	1	149	OH SEC/DR CL NI	OH SC CL-N	8536	KELLETT S	1	DR		SC									0
FORCED INTERR	SH	CG 06	30221	62B	57534411	320030940127	T	4/4/2003	212	68	5	340	BU DISC OR BARI	DISC/BARRL	102	YORK ST	1	TF	575344157										0
FORCED INTERR	KY	WA 42	12088	54GA	39542498	120030940141	T	4/4/2003	212	148	1	148	SNAKE	SNAKE	35802	VERNON	1	TF	365424982										0
FORCED INTERR	SU	DL 44	12271		48528609	120030940142	T	4/4/2003	212	75	3	225	UNKNOWN	UNKNOWN	12711	SOUTHW		TF	485280904										0
FORCED INTERR	SH	PE 04	30815	E39B	55481138	320030940124	T	4/4/2003	213	232	1	232	UNKNOWN	UNKNOWN	3846	SKYLARK	1	BU	554811380										0
FORCED INTERR	BL	BR 05	10495	6Z3	52553000	120030940143	F	4/4/2003	214	37	22	814	BU DISC OR BARI	DISC/BARRL	STELLA LINK	N	1	DB	6Z3										0
FORCED INTERR	CH	BE 01	40216	L6T	55605555	320030940125	T	4/4/2003	222	85	2	170	UNKNOWN	UNKNOWN	8112	HOMESTE	1	TF	558055585										0
FORCED INTERR	HC	FD 08	10663	R73W	50536194	120030940146	T	4/4/2003	223	210	12	2520	URD BUSHING	URD BSHINC	10800	FONDREI	2	BU	505361949										0
FORCED INTERR	SU	HY 08	11717	J78C	48576165	120030940147	F	4/4/2003	231	0	0	0	SPLICE	SPLICE	11910	ASHMEAI	2	LF	J78C	PR									0
FORCED INTERR	SU	HY 08				120030940148	F	4/4/2003	231	181	5	905	SPLICE				2	LF	J78C										0
FORCED INTERR	SU	HY 08				120030940149	F	4/4/2003	231	193	14	2702	SPLICE				2	LF	J78C										0
FORCED INTERR	CH	NM 03	41523	S85J	57585251	320030940126	T	4/4/2003	232	303	17	5151	URD XFMR SEC B	URD TR BUS	12200	FLEMING	2	BU	575852514										0
FORCED INTERR	GA	STWO	3535A	Y97F	64330445	320030950003	T	4/5/2003	013	142	14	1988	BU DISC OR BARI	DISC/BARRL	16705	EDWARD	1	TF	643304431										0
FORCED INTERR	MP	BH 04	40285		54578259	220030950001	L	4/5/2003	025	87	1	87	FIRE	FIRE	438	N EVERTON		DR											0
FORCED INTERR	CH	CV 02	40428		60582424	320030950002	T	4/5/2003	030	440	1	440	UNKNOWN	UNKNOWN	16318	MARKET		BU	605824241										0
FORCED INTERR	MP	GG 01	40952	3RI	55546557	220030950002	F	4/5/2003	030	66	24	1584	OTHER WILDLIFE	OTHER WLD	6926	GOLFWAY	1	LF	3RI										0
FORCED INTERR	FB	WR 10	11259	Z2PN	36387471	120030950001	T	4/5/2003	030	201	9	1809	COLLISION	COLLISION	118	W DAHLGRI	1	TF	363874787										0
FORCED INTERR	FB	OR 03	11307	B20F	38479536	120030950004	T	4/5/2003	045	169	1	169	SQUIRREL	SQUIRREL	11346	HERMAN	1	TF	384795391										0
FORCED INTERR	FB	NV 01	11205		42429354	120030950007	T	4/5/2003	054	140	2	280	UNKNOWN	UNKNOWN	8007	BAKER RD		TF	424293548										0
FORCED INTERR	SH	SP 05	30974	SR6	58542161	320030950006	F	4/5/2003	061	83	25	2075	BU DISC OR BARI	DISC/BARRL	1207	FRESA	1	LF	SR6										0
FORCED INTERR.	CY	SA 42	22679	86DP	48624477	120030950010	F	4/5/2003	073	75	1	75	UNKNOWN	UNKNOWN	7534	FAIRVIEW	1	LF	86DP										0
FORCED INTERR.	MP	CR 01	40516	S81D	53585856	220030950008	T	4/5/2003	081	52	1	52	LIGHTNING ARRE	LTNG ARRS	3611	N MAIN ST	1	TF	535858502										0
FORCED INTERR	SH	EL 08	30370	S66B	57509483	320030950014	F	4/5/2003	085	99	25	2475	LIGHTNING ARRE	LTNG ARRS	11202	OLIVEWC	2	LF	S66B										0
FORCED INTERR	GA	PHRG	31303	5Z2	63473077	320030950016	F	4/5/2003	090	75	52	3900	UNKNOWN	UNKNOWN	1021	GRAND AV	1	LF	5Z2										0
FORCED INTERR	SU	VM 42	12520		47564177	120030950017	T	4/5/2003	092	52	3	156	SQUIRREL	SQUIRREL	14144	WESTHEI		TF	475641729										0
FORCED INTERR	KY	KT 41	22595	66DW	43592422	120030950018	F	4/5/2003	092	208	29	6032	UNKNOWN	UNKNOWN	3259	JAN CT	(E 2	LF	66DW	BU	435924220								0
FORCED INTERR	SU	CE 06	12010		48541222	120030950019	T	4/5/2003	093	65	6	390	LIGHTNING ARRE	LTNG ARRS	13123	WILDE GI		TF	485412228										0
FORCED INTERR	CY	PI 43	2H118	S1960	44719156	220030950013	T	4/5/2003	100	60	3	180	COLLISION	COLLISION	22606	MAIN BLV	1	TF	447191502										0
FORCED INTERR	SH	PE 04	30810		55491173	320030950015	T	4/5/2003	102	74	2	148	LIGHTNING ARRE	LTNG ARRS	7008	BROADWA		TF	554911700										0
FORCED INTERR.	MP	CR 03	40529		53594107	220030950014	T	4/5/2003	102	44	4	176	SQUIRREL	SQUIRREL	1502	OXFORD		TF	535941071										0
FORCED INTERR	GA	GL 01	30500	TE3	68382116	320030950020	T	4/5/2003	102	126	15	1890	OH SEC/DR CL HI	OH SC CL-H	3411	AVENUE R	1	SC	683821161	SC									0
FORCED INTERR	SB	SR 15	21678	19S	49595055	120030950021	F	4/5/2003	111	41	18	738	UNKNOWN	UNKNOWN	10222	CHATTEF	1	LF	19S										0
FORCED INTERR	HC	BL 01	10761	C48L	51508655	120030950022	L	4/5/2003	112	52	1	52	FALLING DEAD TI	TR FL/DEAD	5814	ARTHINGT	1	DR											0
FORCED INTERR	SB	SR 10	21858	C60D	49654194	120030950023	F	4/5/2003	113	55	17	935	UNKNOWN	UNKNOWN	ATTINGHAM, S		1	LF	C60D										0
FORCED INTERR	BL	KB 01	10136	U14H	52568034	120030950030	T	4/5/2003	113	94	2	188	BU DISC OR BARI	DISC/BARRL	5211	KIRBY DR	1	TF	525680366										0
FORCED INTERR	SU	QV 07	12597	R26W	50505115	120030950032	T	4/5/2003	114	72	9	648	UNKNOWN	UNKNOWN	16315	COVEY R	2	TF	505051157										0
FORCED INTERR	GP	LU 45	20603	10BB	51896592	220030950015	T	4/5/2003	120	91	6	546	VINES	VINES	20403	POST OA	1	TF	519895929	PR									0
FORCED INTERR	GP	AD 05	40077		53632375	220030950020	T	4/5/2003	120	127	12	1524	OH SEC/DR CL HI	OH SC CL-H	506	ALDINE MAI		SC	536323756										0
FORCED INTERR	CY	SA 42	22679	86DP	48624447	120030950034	T	4/5/2003	121	70	1	70	UNKNOWN	UNKNOWN	7534	FAIRVIEW	1	TF	486244777										0
FORCED INTERR.	MP	CL 03	40473	G2S	55588126	220030950022	T	4/5/2003	122	197	8	1576	LIGHTNING	LIGHTNING	7506	DENISON	1	BU	555881209										0
FORCED INTERR	GA	STWO	31643	5DG	66364561	320030950025	T	4/5/2003	123	106	2	212	UNKNOWN	UNKNOWN	2801	105TH ST	1	BU	663645613										0
FORCED INTERR.	FB	RE 03	11437	B59N	44495077	120030950036	T	4/5/2003	124	48	2	96	SQUIRREL	SQUIRREL	1703	LAUREL OA	1	TF	444950770										0
FORCED INTERR	GP	RU 05	41674	LO8	53622418	220030950024	T	4/5/2003	125	238	5	1190	UNKNOWN	UNKNOWN	8417	KAREN ST	1	BU	536224184										0
FORCED INTERR	KY	KT 04	22578	3KF	40568355	120030950040	T	4/5/2003	125	58	1	58	BIRD	BIRD	2875	WOODS	1	TF	405863551										0
FORCED INTERR.	BL	EU 09	40746	NS4	52596076	120030950041	T	4/5/2003	125	96	12	1176	UNKNOWN	UNKNOWN	6019	TYNE	1	DB	525680789										0
FORCED INTERR.	BL	GT 12	10658	83JJ	52575584	120030950043	T	4/5/2003	125	83	3	249	UNKNOWN	UNKNOWN	530	CRESTWOC	1	TF	525755847										0
FORCED INTERR	BL	EU 05	40723	26TB	52585017	120030950044	T	4/5/2003	130	52	13	676	UNKNOWN	UNKNOWN	8626	RODRIGO	1	TF	525850178										0
FORCED INTERR	SB	SR 12	21679	M20W		120030950046	F	4/5/2003	130	37	4	148	UNKNOWN	UNKNOWN	1868	STEBBINS	1	LF	M20W										0
FORCED INTERR	SB	SA 48	12471	P70N	47614415	120030950046	F	4/5/2003	131	0	0	0	URD BUSHING	URD BSHINC	15027	TILLEY Y	2	LF	P70N	BU	476143326								0
FORCED INTERR.	SB	SA 48				120030950046	F	4/5/2003	131	142	44	6248	URD BUSHING				2	LF	P70N										0
FORCED INTERR	SB	SA 48				120030950046	F	4/5/2003	131	142	37	5254	URD BUSHING				2	LF	P70N										0
FORCED INTERR	SB	SA 48				120030950046	F	4/5/2003	131	379	5	1895	URD BUSHING				2	LF	P70N										0
FORCED INTERR.	SH	HA 01	31638	95AAN	57514106	320030950025	T	4/5/2003	132	38	8	228	VINES	VINES	11311	CARIBBE	1	TF	575141096										0
FORCED INTERR.	SH	PE 05	30811	69PC		320030950026	L	4/5/2003	132	49	66	3234	OVERLOAD	OVERLOAD	3111	WEST OAK	1	LF	69PC										0
FORCED INTERR.	GA	LM 02	30658	H92F	62419477	320030950033	L	4/5/2003	134	90	1	90	OH SEC/DR CL NI	OH SC CL-N	4813	LAWNDALI	1	DR											0
FORCED INTERR	HM	KW 45	20843	N24S	57729097	220030950027	T	4/5/2003	134	97	4	388	CONTRACTOR-N	CON-NT HLF	3327	RICEWOOI	2	TF	577290793	DR									0
FORCED INTERR	MP	HG 02	41061	H3K	56553088	320030950034	T	4/5/2003	135	91	3	273	UNKNOWN	UNKNOWN	8260	DETROIT	1	TF	565530890										0
FORCED INTERR	SU	CE 06	12010		48541222	120030950052	T	4/5/2003	135	268	6	1608	UNKNOWN	UNKNOWN	13123	WILDE GI		BU	485412228										0
FORCED INTERR	GP	NB 43	20281	Y18I	52659376	220030950025	F	4/5/2003	140	103	52	5356	UNKNOWN	UNKNOWN	407	GREENS RI	2	LF	Y18I										0
FORCED INTERR.	SU	DL 42	12639	56HC	49502365	120030950055	F	4/5/2003	143	113	27	3051	TERMINATOR	TERMINATO	1314	VILLAGE G	2	LF	56HC	PR									0
FORCED INTERR	GP	KI 45	21915	24VJ	48691188	220030950031	F	4/5/2003	144	46	171	7866	O/H PRIMARY CU	OH PR CLMF	12018	N BRENT	2	LF	24VJ										0
FORCED INTERR	KY	KT 41	22590	R92E	43591006	120030950061	F	4/5/2003	145	119	62	7378	UNKNOWN	UNKNOWN	5414	PRINCETO	2	LF	R92E	PR		BU	435						0
FORCED INTERR	SB	WD 45	21570	61LE	46589301	120030950062	F	4/5/2003	145	114	0	0	SQUIRREL	SQUIRREL	REAR	15950,PAI	3	LF	61LE										0
FORCED INTERR	FB	WR 13	11285	51NV	37371585	120030950063	F	4/5/2003	145	42	1	42	SQUIRREL	SQUIRREL	830	LILY	1	LF	51NV	BU	373715855								0
FORCED INTERR	MP	BG 09	40273	D1D	54551551	320030950038	F	4/5/2003	150	254	29	7366	UNKNOWN	UNKNOWN	SCOTT ST BET		1	LF	D1D	BU	545515512								0
FORCED INTERR	BZ	LJ 01	30611	R53T	52277578	320030950039	F	4/5/2003	150	0	0	0	URD BUSHING	URD BSHINC	129	CROCUS (E 2		LF	R53T	BU	522775997								0
FORCED INTERR	BZ	LJ 01				320030950039	F	4/5/2003	150	94	22	2068	URD BUSHING				2	LF	R53T										0
FORCED INTERR	BL	UL 03	10372		50579016	120030950064	T	4/5/2003	150	49	3	147	BU DISC OR BARI	DISC/BARRL	6333	SAN FELIP		TF	505790102										0
FORCED INTERR.	GP	AD 04	40079		53630117	220030950038	L	4/5/2003	150	100	1	100	FLLNG TREE OUT	TREE FL/OE	9263	COLENDAI		DR											0
FORCED INTERR	SB	WO 06	21617	R72L	51598541	120030950066	F	4/5/2003	152	47	14	658	TREE CLEARANC	TREE CLEAR	3002	MAPLE GR	1	LF	R72L										0
FORCED INTERR	HC	FAN47	10632	K52J	52547577	120030950067	F	4/5/2003	152	136	38	5168	UNKNOWN	UNKNOWN	7547	BROMPTO	2	LF	K52J										0
FORCED INTERR	HC	HM 09	11048	86EB	54532474	120030950072	T	4/5/2003	154	51	14	714	HUMAN ERROR	HUMN ERRC	4421	DAVENPOI	1	TF	545324740										0
FORCED INTERR.	GP	BA 42	20149		51670284	220030950047	T	4/5/2003	151	118	10	1180	UNKNOWN	UNKNOWN	3403	FM 1960 W		PR	518702867										0
FORCED INTERR	HC	BL 02	12432	80L	50529388	120030950075	T	4/5/2003	161	38	9	342	VINES	VINES	6027	W AIRPOR	1	TF	505293883										0
FORCED INTERR	SB	WO 06	21617	R72L	51598541	120030950077	T	4/5/2003	162	52	6	312	LIGHTNING ARRE	LTNG ARRS	3018	MAPLE GR	1	PR	515985414										0
FORCED INTERR	SB	BM 04	21491	A89J	49571457	120030950078	T	4/5/2003	162	132	10	1320	UNKNOWN	UNKNOWN	355	CINNAMON	1	SC	495714574										0
FORCED INTERR	SU	BAR4	11903	S23U	46558059	120030950081	F	4/5/2003	163	0	0	0	URD ELBOW	URD ELBOW	15718	ALTA MES	2	LF	S23U	PR		BU	465	SC					0
FORCED INTERR	SU	BAR4				120030950081	F	4/5/2003	163	241	29	6989	URD ELBOW				2	LF	S23U										0
FORCED INTERR	SU	BAR4				120030950081	F	4/5/2003	163	241	45	10845	URD ELBOW				2	LF	S23U										0
FORCED INTERR	SU	BAR4				120030950081	F	4/5/2003	163	736	4	2944	URD ELBOW				2	LF	S23U										0
FORCED INTERR	CY	KDL44	20465	11ADD	49709270	220030950059	T	4/5/2003	164	148	40	5920	URD BUSHING	URD BSHINC	6530	ROSE WILI	2	LF	11ADD	PR	497092702								0

REF TR
REF LF
hoisted 504 inches, REF TR.
RPLD BAJ BARREL ON TR.
REFUSED TRANHE REF TR.
refused a 25 lock fuseer kf, REF TR.
REMOVED VINES AND TRIMMED TREE LIMBS OFF 25 CBP TRANSFORMER REPAIRED BROKEN GUY WIRES ON DEAD END TRANSFORMER POLE AT SAME ADDRESS INSTALLED W L P ON
REPLACED BURNED UP 12KV KERNERY BARREL, RPLD BAJ BARREL ON TR.
REPLACED 12 KV BARREL_____ALSO SEND MESSAGE TO BOH__BAD ARRESTER ON TRANSL ....TRUCK ACCESSIBLE IF ITS DRY RPLD BAJ BARREL ON TR. MSG SENT TO MC TLA
REFUSED MIDDLE PHASE NO HERE TO NOTIFY PLACE LOCK UP, REF LF
auto reset o to disc. RPLD BAJ DISC-TF NOT BLOWN.
RPLD BAJ TR.
RPLD BAJ TR.
REPLACED 75 CONV 120/240-7200 IN CLOSED DELTA BANK, RPLD BAJ TR.
REPLACED 50 KVA 19 8, 120/240 URD WITH SAME - BUSHING BLOWN OUT ON X SIDE - LOCATED AT 19923 FALLS DRIVE - NEED CLEANUP ASAP - CUST HAS DOGS IN YARD - RPLD BAJ TR. "SU

REF 'X' PHS OF LIF E42S FEEDS POWER TRANS FOR 1 CUST 3 PHS A/C UNIT COULD NOT LOC CAUSE MAY HAVE BEEN FROM PREV WEATHER. REF LF
REPLACED BAD 25 KVA WITH 50 KVA 7200 120/240, RPLD BAJ TR.
IN AL 3CTW DR REP AT B/C CONV NTA, RPRD DR. MSG SENT TO B/C TLA
REPL. LIMITER AT POWER POT & REFUSED TRANS RPLD LIMITER @ TR. REF TR.
REFUSED 50 KVA TRAN. REF TR.
REF TR.
FOUND LINE FUSE BLOWN WE RODE THE O H PART OF THE LINE OUT CONDUCTORS WERE ALL UP REFUSED LINE FUSE CAUSE WAS POSSIBLY A SQUIRREL , UNABLE TO LOCATE THE
REF TR.
REFUSED TRIE FUSE WAS BROKE EVERYTHING BACK ON FUSE WAS STRETCHED WHEN INSTALLED PREVIOUSLY REF TR
RPLCD TF BUSHING & ELBOW CORRECTED 2HNVCRH
REFUSED A 25KVA TRAN LIGHTER IN OPEN DELTA BANK OUT BY SQUIRRAL, REF TR.
RPLD BAJ TR.
REPL A BAD BANNER FUSE ON A 75 KVA URD TF REF TR.
RPLD CONN @ WH.
REF TR.
MADE REPAIRS INTERNALLY TO SEC BUSHING CONN ON 25KVA POWER POT X1 TIE BUSHING - TRIMMED TREES AROUND TRANSF BANK RPLD CONN @ TR.
REPLACED CLAMPS AT WH AND AT POLE, RPLD CONN @ WH. RPLD CONN @ PL.
REPLACED BURNED FUSE BARREL, RPLD BAJ BARREL ON TR.
refused a 25kva a h trans. cover smoke, REF TR.
REFUSED 167 KVA TRAN CUST CK, BAD GOOD VOLTAGE, REF TR.
REPLACED A BAD 25 KVA 7200-120-240 WITH A 15 KVA ON TRANS SHOW BACK ON @ 0115. RPLD BAJ TR.
RPLD BAJ DISC-LF NOT BLOWN.
REFUSED TRAN. REF TR.
tank at s o 7868. RPLD BAJ TR.
FOUND BAD URD PRIMARY ISOLATED URD PRIMARY TRF # 13 & 914 CLSD TP AND PRI IN SW TRF URD SO 7868. REF TP BOL URD PR "BUSCASING NECESSARY"SENT MSG

0 RPLD BAJ TR.
REPLACED A BURNED UP FUSE BARREL, REF TR. RPLD BAJ BARREL ON TR. NO BUSCASING NEEDED... CEW
Fire Cut Out-Rmvd Mtr & Drops PICKUP SPAN OF SEC DROPS MTR ABB 8518678A READING 16388. RPLD DR, FIRE-RMVD MTR & DR.
REPLACED 200 KVA 277/480 7200 TRANS WITH THE SAME, RPLD BAJ TR.
REFUSED WEAT PHASE OF 3RT VARMIT, REF LF
FOUND 1 SPAN OF #4 OPEN WIRE SEC DOWN CAR HIT POLE MOVE 4 BET OF DROP TO ANOTHER TRANS NEED TO

FORCED INTERR.	BL	JN 07	10022	50551105	120030950083	L	4/5/2003	1640	70	1	70	FLLNG TREE OUT	TREE FL/OE	8122	LEADER		DR											1	0
FORCED INTERR	SH	CA 06	31462	68CW	59536173	120030950043	F	4/5/2003	1650	92	1	92	ANTS	ANTS	RHODES, S OF	2	LF	68CW										1	0
FORCED INTERR	SH	PA 01	30746	MD5	57545566	120030950044	T	4/5/2003	1722	105	6	630	UNKNOWN	UNKNOWN	1106	MOBILE DR	1	TF	575455689									1	0
FORCED INTERR	SB	TO 05	21805		51606273	120030950085	T	4/5/2003	1740	190	4	760	UNKNOWN	UNKNOWN	4901	LIBBEY LN		TF	516062738									1	0
FORCED INTERR	SH	MY 05	31738	33ED	57481310	120030950046	F	4/5/2003	1757	76	92	6992	UNKNOWN	UNKNOWN	3417	LONGHERI	1	LF	33ED									1	0
FORCED INTERR.	SH	GV 05	30531	7P8	55525418	120030950046	F	4/5/2003	1816	119	18	2142	UNKNOWN	UNKNOWN	MYKAWA @ GA	1	LF	7P8	PR									1	0
FORCED INTERR	GA	STW02	30696	A53M	63349045	120030950051	T	4/5/2003	1820	46	8	368	FOREIGN MATER	FRGN MATR	16518	BAHAMA	1	SC	633490456									1	0
FORCED INTERR	SH	PE 05	30199	48LE	55479434	120030950052	F	4/5/2003	1833	76	4	304	SLACK SPANS	SLACK SPAN	17123	COUNTY	1	LF	48LE									1	0
FORCED INTERR	SH	SP 02	30969	15KH	58531553	120030950053	T	4/5/2003	1840	52	4	208	UNKNOWN	UNKNOWN	2919	VILLAGE W	1	TF	585315524									1	0
FORCED INTERR.	HM	SW 08	41694	2GC	56639524	120030950054	T	4/5/2003	1840	44	3	132	UNKNOWN	UNKNOWN	13805	FOREST	1	TF	566395243									1	0
FORCED INTERR	BL	UL 16	10380		51563385	120030950056	T	4/5/2003	1855	39	3	117	UNKNOWN	UNKNOWN	5702	WESTHEIM		TF	515633834									1	0
FORCED INTERR	SH	UW 02	31896	3NZ	60542034	120030950054	L	4/5/2003	1900	130	1	130	FLLNG TREE OUT	TREE FL/OE	733	RUTGERS L	1	DR										1	0
FORCED INTERR	HC	MV 02	14215	H40F		120030950101	F	4/5/2003	1900	142	103	14626	SNAKE	SNAKE	9910	TWIN OAK	1	LF	38KR	TF	544333537							1	0
FORCED INTERR	GA	LM 04	31486	8NM	64397584	120030950057	T	4/5/2003	1924	96	8	576	FOREIGN MATER	FRGN MATR	310	LING	1	SC	843975840									1	0
FORCED INTERR	GP	THW4	23611		49643405	120030950062	T	4/5/2003	1931	149	2	298	UNKNOWN	UNKNOWN	11929	WINDFER	PR	PR	496434051									1	0
FORCED INTERR	FB	RE 09	16002	79PN	44484076	120030950103	T	4/5/2003	1938	145	3	435	UNKNOWN	UNKNOWN	2415	B F TERRY	1	BU	444840769									1	0
FORCED INTERR.	SB	CB 12	21473	K22S	50596165	120030950106	L	4/5/2003	2011	146	1	146	OH SEC/DR CL H	OH SC CL-H	1717	LONGACRI	1	SC										1	0
FORCED INTERR	CH	LY 44	41344	J81A	59625078	120030950062	T	4/5/2003	2038	88	8	704	UNKNOWN	UNKNOWN	16915	WOODAC	1	TF	596250797									1	0
FORCED INTERR	GP	FR 46	21365	W18W	50623033	120030950063	T	4/5/2003	2102	121	5	605	VINES	VINES	6931	GUHN #27	1	PR	508230334									1	0
FORCED INTERR	CH	LB 01	41253	L8U	55606139	120030950064	L	4/5/2003	2130	82	1	82	UNKNOWN	UNKNOWN	7201	PHILIBERT	1	SC										1	0
FORCED INTERR	FB	BV 41	1151A	28GB	42526264	120030950115	T	4/5/2003	2251	53	1	53	BU DISC OR BARI	DISC/BARRL	327	CALETA CIR	1	TF	425262680									1	0
FORCED INTERR	SH	SH 11	31404	A21S	58520135	120030950066	L	4/5/2003	2254	50	1	50	TREE CLEARANC	TREE CLEAR	12229	DUMAS	1	SC										1	0
FORCED INTERR	GP	THW4	20578		49650141	120030950072	T	4/5/2003	2321	63	5	315	UNKNOWN	UNKNOWN	9915	WINDRIVE		TF	496501415									1	0
FORCED INTERR	GP	GZ 46	22990		52650504	120030960001	T	4/6/2003	0040	78	4	312	TREE CLEARANC	TREE CLEAR	1417	HUGH RD		TF	526505047	PR								1	0
FORCED INTERR	HC	BL 03	10771	S93S	50522397	120030960004	F	4/6/2003	0443	79	41	3239	HUMAN ERROR	HUMN ERRC	12235	RIPPLE G	2	LF	S93S									1	0
FORCED INTERR	GP	BY 06	40186	7C7	54610261	120030960004	T	4/6/2003	0450	63	8	504	UNKNOWN	UNKNOWN	9701	LANGDALE	1	TF	546102613									1	0
FORCED INTERR	BL	SF 42	10453	KM8	51574471	120030960012	T	4/6/2003	0507	254	3	762	VINES	VINES	21	E BROAD OA	1	PR	515744710									1	0
FORCED INTERR	HM	HB 43	20832	63FD		120030960007	F	4/6/2003	0538	119	108	12852	VINES	VINES	5734	UPPER LAU	1	LF	63FD									1	0
FORCED INTERR	HC	HOC0	11179	C16F	51529104	120030960014	F	4/6/2003	0545	53	3	159	HUMAN ERROR	HUMN ERRC	LOTUS @	NITID	1	LF	C16F									1	0
FORCED INTERR	MP	WO 14	41866	8PA	51609463	120030960006	T	4/6/2003	0546	59	10	590	UNKNOWN	UNKNOWN	2119	BETHLEHE	1	TF	516094635									1	0
FORCED INTERR	SU	WI 43	12618	74NC	48554544	120030960018	F	4/6/2003	0611	0	0	0	STRONG WIND	WIND	3422	SHADOWE	2	LF	74NC									1	0
FORCED INTERR	SU	WI 43				120030960018	F	4/6/2003	0611	46	117	5382	STRONG WIND				2	LF	74NC									1	0
FORCED INTERR	SU	BAR47	13215		47533200	120030960019	T	4/6/2003	0634	140	3	420	LIGHTNING ARRE	LTNG ARRS	14906	OLD RICH		TF	475332035									1	0
FORCED INTERR	GP	KI 43	22077	S2530	49680157	120030960011	F	4/6/2003	0646	267	12	3204	LIGHTNING	LIGHTNING	9603	BALLIN DA	2	LF	S2530									1	0
FORCED INTERR	GP	BA 43	22074	P68P	50652224	120030960012	F	4/6/2003	0650	0	0	0	UNKNOWN	UNKNOWN	11543	CANYON	2	LF	P68P	BU	506522548							1	0
FORCED INTERR	GP	BA 43				120030960013	F	4/6/2003	0650	159	14	2226	UNKNOWN				2	LF	P68P									0	0
FORCED INTERR	GP	BA 43				120030960013	F	4/6/2003	0650	384	6	2304	UNKNOWN				2	LF	P68P									0	0
FORCED INTERR	SB	ADK42	22559		48601522	120030960020	T	4/6/2003	0659	88	3	267	LIGHTNING ARRE	LTNG ARRS	5319	SUMMER E		TF	488015224									1	0
FORCED INTERR	GP	NB 45	20219		54650322	120030960014	T	4/6/2003	0651	130	3	390	BU DISC OR BARI	DISC/BARRL	2101	GRAB		TF	546503276									1	0
FORCED INTERR	GP	RU 01	41645	30G	53612597	120030960015	T	4/6/2003	0659	157	3	471	VINES	VINES	6922	WERNER	1	TF	536125974									1	0
FORCED INTERR	CY	CYF42	20676	T91Y	46629316	120030960017	F	4/6/2003	0722	76	53	4028	LIGHTNING	LIGHTNING	7435	DEW MIST	2	LF	T91Y									1	0
FORCED INTERR	BL	ST 16	10231	CN7	50548207	120030960022	T	4/6/2003	0728	86	9	774	BU DISC OR BARI	DISC/BARRL	8411	MC AVOY	1	TF	505482073									1	0
FORCED INTERR	SB	SR 15	21421	8MB	49596286	120030960024	F	4/6/2003	0759	79	7	553	TREE CLEARANC	TREE CLEAR	2021	GESSNER	1	LF	8MB	TF	495962808							1	0
FORCED INTERR	HM	AT 42	2386E		59698028	120030960020	T	4/6/2003	0801	120	5	600	VINES	VINES	24319	SUNNY G		TF	596960293									1	1
FORCED INTERR	SH	SB 01				120030960013	C	4/6/2003	0811	0	0	0	PRIMARY CONDU	PRIMARY	802	PRESTON		CL	SB01	PR								0	0
FORCED INTERR	SH	SB 01	31030			120030960013	C	4/6/2003	0811	32	1742	55744	PRIMARY CONDU					CL	SB01									0	0
FORCED INTERR	SH	SB 01	3G180			120030960013	C	4/6/2003	0811	97	4	388	PRIMARY CONDU					CL	SB01									0	0
FORCED INTERR	HC	MV 01	13138	H27F	53459047	120030960026	F	4/6/2003	0825	87	82	5494	FOREIGN MATER	FRGN MATR	IOWA	SOUTH S	1	LF	72AEA									1	0
FORCED INTERR	FB	OR 03	11308	N9J	40460016	120030960027	F	4/6/2003	0831	83	2	166	INSULATOR	INSULATOR	8622	BOHACEK	1	PR	N9J									1	0
FORCED INTERR	SB	EC 06	21711	94J	50583074	120030960026	F	4/6/2003	0830	72	4	288	UNKNOWN	UNKNOWN	PINEY POINT	@	1	LF	94J									1	0
FORCED INTERR	CH	NM 04				120030960015	C	4/6/2003	0830	0	0	0	PRIMARY CONDU	PRIMARY	1314	FEDERAL		CL	NM04									0	0
FORCED INTERR	CH	NM 04	3G291			120030960015	C	4/6/2003	0830	44	1112	48928	PRIMARY CONDU					CL	NM04									0	0
FORCED INTERR	GA	LM 03	30063	I67G	63405294	120030960016	T	4/6/2003	0830	331	6	1986	UNKNOWN	UNKNOWN	6520	WASHING	1	BU	634052947									1	0
FORCED INTERR	CY	PI 41	21059	S45P	45749294	120030960023	F	4/6/2003	0830	68	32	2176	VINES	VINES	35218	PINE FOR	1	LF	S45P	TF	457491866							1	0
FORCED INTERR	CY	PI 42	21070	T79Z	45769353	120030960024	T	4/6/2003	0844	139	3	417	VINES	VINES	14102	PINEHUR	1	TF	457893531									1	0
FORCED INTERR	CY	HK 06	21114	28LB	43674034	120030960025	T	4/6/2003	0844	53	1	53	O/H PRIMARY CU	OH PR CLM	15837	HOUSE	1	TF	436740366									1	0
FORCED INTERR	GP	GZ 44	20686	Y81I	51651239	120030960027	T	4/6/2003	0855	87	5	435	LIGHTNING ARRE	LTNG ARRS	3627	CLAVERTC	2	TF	516512388									1	0
FORCED INTERR	BL	GN 10	10625	U91	52558636	120030960031	L	4/6/2003	0911	105	1	105	OH SEC/DR CL H	OH SC CL-H	2508	DRYDEN	1	DR										1	0
FORCED INTERR	HC	BR 09	10613	81FC	51539456	120030960034	T	4/6/2003	0922	203	8	1624	OH SEC/DR CL H	OH SC CL-H	10218	WILLOWC	1	BU	515394604									1	0
FORCED INTERR	BL	ST 08	10232	R34R	51550088	120030960036	F	4/6/2003	0931	67	100	6700	TREE CLEARANC	TREE CLEAR	7111	HILLCROF	1	LF	R34R									1	0
FORCED INTERR	HM	RA 44	20429	U74C	51739115	120030960031	F	4/6/2003	0933	50	153	7650	VINES	VINES	25510	BROOKHA	2	LF	U74C									1	0
FORCED INTERR.	FB	CRB4	12478	64NA	46484510	120030960037	F	4/6/2003	0940	107	16	1712	INSULATOR	INSULATOR	20017	SOUTHW	1	LF	64NA	PR								1	0
FORCED INTERR.	CH	GP 06	40814	B68Z	56568504	120030960031	T	4/6/2003	1010	45	7	315	UNKNOWN	UNKNOWN	707	BANK DR	1	TF	565685040									1	0
FORCED INTERR	BA	AT 41	41478		60666452	120030960033	T	4/6/2003	1021	36	1	36	UNKNOWN	UNKNOWN	20005	FM 2100	F	TF	606654522									1	0
FORCED INTERR	SH	SO 42	10959		54490154	120030960036	T	4/6/2003	1045	86	2	172	OTHER WILDLIFE	OTHER WLD	2645	MILLER RA		PR	544801542									1	0
FORCED INTERR	GP	BA 46	2D141			120030960045	C	4/6/2003	1051	0	0	0	PRIMARY CONDU	PRIMARY	CHAMPIONS DR			PC	BA46									0	0
FORCED INTERR	GP	BA 46	2C141			120030960045	C	4/6/2003	1051	36	855	30780	PRIMARY CONDU					PC	BA46									0	0
FORCED INTERR	GP	BA 46	2B141			120030960045	C	4/6/2003	1051	56	708	39646	PRIMARY CONDU					PC	BA46									0	0
FORCED INTERR	GP	BA 46	2A141			120030960045	C	4/6/2003	1051	151	719	108569	PRIMARY CONDU					PC	BA46									0	0
FORCED INTERR	CY	KL 45	2B129	79BB	48650143	120030960054	L	4/6/2003	1118	74	1	74	OH SEC/DR CL H	OH SC CL-H	11907	W MORG	1	DR										1	0
FORCED INTERR	BL	ST 08	10232	R34R	51550054	120030960044	F	4/6/2003	1125	51	100	5100	TREE CLEARANC	TREE CLEAR	7111	HILLCROF	1	LF	R34R									1	0
FORCED INTERR	CH	NM 04	41526	3K9	57577528	120030960033	T	4/6/2003	1125	49	9	441	UNKNOWN	UNKNOWN	1335	FALCON S	1	TF	575775209									1	0
FORCED INTERR	HC	ST 10	10244		51545325	120030960045	T	4/6/2003	1133	54	4	216	BU DISC OR BARI	DISC/BARRL	5215	MAPLE		TF	515453253									1	0
FORCED INTERR	CY	PI 41	20152	T56K	44756525	120030960062	T	4/6/2003	1135	57	2	114	LIGHTNING ARRE	LTNG ARRS	31911	REDWOC	1	PR	447565295									1	0
FORCED INTERR	SH	PA 01	30747	PO6	57546571	120030960036	L	4/6/2003	1141	61	1	61	OH SEC/DR CL N	OH SC CL-N	807	MIMOSA AV	1	DR										1	0
FORCED INTERR	CH	NM 03	41521	M59N	57587101	120030960047	L	4/6/2003	1141	38	2	76	UNKNOWN	UNKNOWN	1020	FEDERAL	1	TF	575871015									1	0
FORCED INTERR	SB	TO 10	21769	M27A	50598233	120030960047	T	4/6/2003	1151	70	7	490	OH SEC/DR CL H	OH SC CL-H	1902	COULORE	1	SC	505982322									1	0
FORCED INTERR	SL	SE 02	24288	95FK	36571361	120030960046	L	4/6/2003	1152	70	1	70	LIGHTNING	LIGHTNING	138	FM 1458N	TI	1	SC									1	0
FORCED INTERR	BL	UL 09	10318	30MD	51561487	120030960052	F	4/6/2003	1200	234	47	10998	TRANSFORMER	TRANSFRM	2400	FOUNTAIN	2	LF	30MD									1	0
FORCED INTERR	HC	HM 09	11048	W28	54532364	120030960054	T	4/6/2003	1213	60	7	420	UNKNOWN	UNKNOWN	4410	ALVIN ST	1	TF	545323684									1	0
FORCED INTERR	CY	KL 43	21983		46657546	120030960065	T	4/6/2003	1224	57	3	171	VINES	VINES	15737	JARVIS		PR	466575435									1	0
FORCED INTERR	FB	WA 43	12843	87GB	39491474	120030960056	F	4/6/2003	1228	52	55	2860	INSULATOR	INSULATOR	HWY 36W	@ MA	1	LF	S3810	PR								1	0
FORCED INTERR	SH	WE 02	31246	1GP	58551246	120030960041	T	4/6/2003	1230	54	7	378	UNKNOWN	UNKNOWN	506	SCOTT	1	TF	585512408									1	0
FORCED INTERR	HC	QV 08	12185	49BP	49509175	120030960056	F	4/6/2003	1238	54	3	162	SQUIRREL	SQUIRREL	COURT, E OF V	1	LF	49BP	TF	495091758								1	0
FORCED INTERR	SB	BM 05	21497	7ER	46585046	120030960061	L	4/6/2003	1240	59	1	59	OH SEC/DR CL H	OH SC CL-H	14130	PINEROC	1	DR										1	0
FORCED INTERR	HM	RA 42	22081	S2921	52715100	120030960077	L	4/6/2003	1300	88	1	88	OH SEC/DR CL H	OH SC CL-H	119	CAROLINE	1	DR										1	0
FORCED INTERR	SH	TE 01	31596	8LT	56514443	120030960042	L	4/6/2003	1313	78	1	78	OH SEC/DR CL H	OH SC CL-H	8133	SAYLYNN	1	DR										1	0
FORCED INTERR	HC	GV 03	10912	J13Y	54538334	120030960065	T	4/6/2003	1318	40	7	280	SQUIRREL	SQUIRREL	5887	BELNEATH	1	TF	545363382									1	0
FORCED INTERR	FB	WA 43	12843	87GB	39498205	120030960064	T	4/6/2003	1320	135	1	135	O/H PRIMARY CU	OH PR CLM	2915	MACHA	1	BU	384982020									1	0
FORCED INTERR	SH	CG 02	30208	JR7	57532165	120030960044	T	4/6/2003	1358	34	6	204	SQUIRREL	SQUIRREL	1007	MARLEEN	1	TF	575321652									1	0
FORCED INTERR	BL	ST 07	10228	K28U	50549290	120030960066	T	4/6/2003	1400	46	9	414	LIGHTNING ARRE	LTNG ARRS	1	CARLOTA CT	1	TF	505492927									1	0
FORCED INTERR	GP	BA 01	20614	C88A	50662438	120030960081	F	4/6/2003	1414	52	65	3380	VINES	VINES	13110	LOOKOUT	1	LF	C88A									1	0
FORCED INTERR	CY	TB 45	22980	43EJ	46718040	120030960085	T	4/6/2003	1455	27	6	162	BU DISC OR BARI	DISC/BARRL	15222	FM 2920	F	TF	467180407									1	0
FORCED INTERR	SU	HY 11	11591	40H	49566355	120030960071	F	4/6/2003	1523	83	9	747	UNKNOWN	UNKNOWN	2111	BRIARPAR	1	LF	40H									1	0
FORCED INTERR	BL	ST 08	10232	R34R	51550054	120030960072	F	4/6/2003	1547	87	33	2871	TREE CLEARANC	TREE CLEAR	7111	HILLCROF	1	LF	R34R									1	0
FORCED INTERR	CY	KL 45	2473E		48650355	120030960086	T	4/6/2003	1610	104	3	312	OH SEC/DR CL H	OH SC CL-H	12422	E SHADO		PR	486503555	SC								1	0
FORCED INTERR	HC	AM 03	10724	122X	52519285	120030960075	F	4/6/2003	1614	57	1	57	SQUIRREL	SQUIRREL	305	ALMEDA GE	3	LF	122X	BU	525192837							1	0
FORCED INTERR	KY	KT 04	22578	3KF	40566444	120030960081	T	4/6/2003	1711	56	1	56	UNKNOWN	UNKNOWN	2445	WOODS	1	TF	405664493									1	0
FORCED INTERR	BL	BR 01	12727	FF5	52532597	120030960082	T	4/6/2003	1740	41	9	369	BU DISC OR BARI	DISC/BARRL	4045	OSBY	1	TF	525325977									1	0
FORCED INTERR	FB	WR 12	11282		36388264	120030960083	T	4/6/2003	1754	81	1	81	SQUIRREL	SQUIRREL	515	E BOLING		TF	363882647									1	0
FORCED INTERR	SB	EC 02	21690		50572388	120030960085	T	4/6/2003	1822	35	1	35	VINES	VINES	11535	QUAIL HC		TF	505723852									1	0
FORCED INTERR	SH	TE 01	31064	H59P	56512311	120030960056	F	4/6/2003	1822	100	8	800	UNKNOWN	UNKNOWN	7735	GREENSW	1	LF	H59P									1	0
FORCED INTERR	CH	NM 03	41520	B10A	58580003	120030960057	T	4/6/2003	1828	65	1	65	UNKNOWN	UNKNOWN	12872	MARKET	1	TF	585800037									1	0
FORCED INTERR	FB	WR 10	11108	74AP	34419310	120030960086	T	4/6/2003	1833	155	1	155	LIGHTNING	LIGHTNING	707	USTYNIK	1	BU	344193109									1	0
FORCED INTERR	HM	HB 43	20078	P19M	58687091	120030960095	F	4/6/2003	1922	80	54	3240	VINES	VINES	20007	PINEHUR	2	LF	P19M									1	0
FORCED INTERR	SH	CG 02	30210	JE8	57533043	120030960056	L	4/6/2003	1954	85	1	85	UNKNOWN	UNKNOWN	839	GLOBE	1	SC	CONN									1	0
FORCED INTERR	SB	WT 02	10433	UR1	51584502	120030960102	T	4/6/2003	2330	36	5	180	BU DISC OR BARI	DISC/BARRL	1417	CAYWOOD	1	TF	515845029									1	0
FORCED INTERR	FB	NV 02	11220	94S	42418289	120030970001	T	4/7/2003	0052	30	1	30	HUMAN ERROR	HUMN ERRC	8407	HIGHLAND	1	TF	424182938									1	0
FORCED INTERR.	CH	LB 01	41288	B76P	55592242	120030970001	T	4/7/2003	0108	63	5	315	BU DISC OR BARI	DISC/BARRL	5414	BUNTE	1	TF	555922437									1	0
FORCED INTERR	SH	TE 07	31100	I72C	56495023	120030970007	F	4/7/2003	0321	102	35	3570	UNKNOWN	UNKNOWN	3202	WESTMINI	1	LF	I72C									1	0
FORCED INTERR	SU	SIE41	12601	A38K	50480466	120030970003	F	4/7/2003	0328	72	55	3960	LIGHTNING ARRE	LTNG ARRS	126	PALM BLVD	2	LF	A38K									1	0
FORCED INTERR	HM	RA 44	21211	70PL	52730286	120030970002	F	4/7/2003	0330	76	35	2660	LIGHTNING ARRE	LTNG ARRS	502	HEARTHST	2	LF	70PL									1	0
FORCED INTERR.	SU	BAR42	11865	15RV	47551311	120030970006	F	4/7/2003	0417	113	30	3390	LIGHTNING ARRE	LTNG ARRS	3318	CHERRYBI	2	LF	15RV									1	0
FORCED INTERR	MP	AN 02	40009	MA7	53595177	120030970006	F	4/7/2003	0422	80	4	320	COLLISION	COLLISION	WINSTON @ MI	1	LF	MA7										1	0
FORCED INTERR	HM	RA 44	21285	92PL	52735424	120030970007	F	4/7/2003	0440	66	47	3102	LIGHTNING ARRE	LTNG ARRS	1702	ASHTON V	2	LF	92PL	TF	527354244							1	0
FORCED INTERR	SB	CB 05	21435	HW9	50601248	120030970007	T	4/7/2003	0640	69	1	69	UNKNOWN	UNKNOWN	4106	CAMPBELL	1	TF	506012455									1	0

RPRD DR. RESAGGED DR.
75 PMT NTA D F B/C CONV . REF TP; NO SUB CABING --ABK
BAD FUSE. REF TR.
REFUSE POWER POT TR REF TR.
REF LF
REF LF: RPLD B/O PR JUMPER-FUSE BLOWN; CORRECTED 2HMCRH
REPAIRED TRANS BUSS ON THE HOT LEG DUE TO SALT CORORION; RPRD BUSS WORK @ TR.
ADJUSTED SLACK SPAN. REF LF
BAD FUSE. REF TR.
REF TR:
REFUSED 75 KVA LIGHTER POT IN CLOBED DELTA BANK. REF TR.
RPLD DR.
REFUSE X-FORMER AT 8415 TWIN OAKS AND REFUSE LF AT HANNELMAN @ TWIN OAK 38 KR. REF LF, REF TR.
REPAIRED BUSS WORK ON HOT LEG DUE TO SALT CORROSION. FOUND ALL 3 PHASES OF LINE FUSE 8HM ON. JUST THIS 1 TRANS INVOLVED. RPRD BUSS WORK @ TR.
REPL LIMITER. COULD NOT LOC CAUSE NEED TO REPL 35KV LIA B/C CONV. RPLD LIMITER @ TR.
REPLACED BAD 15 KVA CSP TRS 7200-120-240 WITH A 25 KVA TRS 7200-120-240 AND INSTALLED 7200 KERNEY DISBCONNECT SWITCH AND 11 INCH SWITCH ARM. LOOKED LIKE OLI
NEED TO REPLACE 88 DROPS WITH 84. RPLD BEC CONN @ PL-1 CUST
REFUSED TRAN. REF TR.
CLEARED VINES. RPLD LIMITER @ TR. REF TR
Found Cut Out-RCANC. RPLD CONN @ PL.
REFUSED 50 KVA TRANSFORMER CAUSED BY BROKEN FUSE REMOVED THE SPRING FROM THE FUSE BARREL TO PREVENT FUTHER OUTAGES DUE TO PULLED FUSES REF TR.
REAR 12228 NTA. RPLD BEC CONN @ PL-1 CUST
RPLD LIMITER @ TR. REF TR.
REPLACED LIGHTING ARESTOR AND LIMITER TRIM TREES. RPLD LIMITER @ TR. REF TR.
REPLACE BAD 80-AMP FUSE. REF TP 2419 OPT VAN ENROUTE 2008. ONBITE 0802
REF TR.
REPLACED 12K MATE ON TRANSFORMER AND REMOVED VINE FROM TRABNFORMER AND POLE. RPLD LIMITER @ TR. REF TR. MEK
REMOVED VINES OFF POLE @ 5734 UPPER LAKE / REFUSED LF LEFT BERV ON; REF LF. RMVD TREE/IMB OFF PR. CORRECTED 2HMCRH
PULLED 65-AMP-FUSE-NO-FUSE-CAP-ON-IT-REPLACE-FUSE. REF LF.
REFUSED TRAN. REF TR.
REFUSED T P WEATHER. REF TP

TRUCK ACCESSABLE. REF TR. MEK
REPLACED LIMITERS ON 8TEP DOWN BANK AND CLEARED VINES. REF TP REF TR RGR
RPLD B/U TR.

REPLACED LIGHTING ARESTOR. REF TR. RPLD LIGHTNING ARRESTOR.
refused 50 kva banked with a 25kva pulled fuse. REF TR.
CLEARED VINES FROM TRX & OPEN WIRE 45FT POLE NEEDS TO BE REPLACED @ LATER DATE. ROTTEN AT GROUND REF TR. MEK
REFUSE TP T91Y REF TP.
RPLD

FORCED INTERR	HM	TWG4	22234	A85D	5566335	220030970011	F	4/7/2003 064	77	2	154	FLLNG TREE OUT	TREE FL/OE	LEE N OF HONI	1	LF	A85D		REF LF;	MEK	1	0
FORCED INTERR	BZ	FP 02	30415	X70K	5622147	320030970009	T	4/7/2003 064	122	3	366	BU DISC OR BARI	DISC/BARRL	814 LAMAR	1	TF	562214726		REPLACED BURNED UP FUSE BARREL ., RPLD B/U BARREL ON TR.		1	0
FORCED INTERR	GP	WF 42	20562	72MW	5167953	220030970012	F	4/7/2003 064	68	1	68	UNKNOWN	UNKNOWN	16713,ELLA	3	LF	94JS	LF 72MW	NEED TO GET AN OUTAGE TO REPLACE 2 BLOWN LA'S ON TP 72MW; REF LF REF TP;	MEK	1	0
FORCED INTERR	CH	OA 05	41615		5758641	320030970010	T	4/7/2003 065	49	1	49	BU DISC OR BARI	DISC/BARRL	820 MAXEY RD		TF	575864123		REPLACED FUSE BARREL ON LIGHTER TRNS / LEFT SERV ON / NOTIFIED; RPLD B/U BARREL ON TR;		1	0
FORCED INTERR	SU	AF 10	11823	D81B	4854728	120030970006	T	4/7/2003 070	27	1	27	BU DISC OR BARI	DISC/BARRL	7979 S KIRKWO	1	TF	485472879		rep burned up fuse barrel on 480 bank service ok by cust; RPLD B/U BARREL ON TR.		1	0
FORCED INTERR	KY	MAR4	20800	S80M	4457514	120030970010	F	4/7/2003 0711	69	52	3588	BU DISC OR BARI	DISC/BARRL	1210 SILVER MC	2	LF	S80M		REFUSED TERMINAL POLE BLOWN FROM A BAD DISCONNECT ON SAME POLE BACK ON., REF TP		1	0
FORCED INTERR	KY	MAR4	20800	P85K	4457528	120030970016	F	4/7/2003 073	40	37	1480	BU DISC OR BARI	DISC/BARRL	955 THREE FOR	2	LF	P85K	DB	REFUSED BLOWN FROM ANOTHER TERMINAL POLE ON SAME POLE. BAD DISCONNECT BACK ON., REF TP		1	0
FORCED INTERR	SB	ME 11	21582		4857459	120030970017	T	4/7/2003 073	60	1	60	BU DISC OR BARI	DISC/BARRL	14240 MEMORIA		TF	485745914	DB	RPLD B/U DISC-TF BLOWN; REF TR;		1	0
FORCED INTERR	FB	NEW0	11245	C7K	4037132	120030970018	L	4/7/2003 0741	226	1	226	CONTRACTOR-N	CON-NT HLF	1606 BARKER R	1	DR		SC	REPLACE CLAMP MID SPAN HIT BY HI LOAD & REPL BAD CLAMPS @ WH NOTIFIED; RPRD CONN @ WH, RPLD SEC CONN @ PL-1 CUST RPLD POA		1	0
FORCED INTERR	HC	ST 09	11661	K91T	5154027	120030970019	F	4/7/2003 075	66	2	132	BU DISC OR BARI	DISC/BARRL	HILLCROFT, S C	1	LF	K91T		REPLACED BARREL ON LINE FUSE; RPLD B/U BARREL ON LF;		1	0
FORCED INTERR	GP	THW4	28153	K22M	4864649	220030970018	T	4/7/2003 075	143	11	1573	VINES	VINES	10750 FM 1960 V	1	TF	486464969	PR	REPLACED 25 K-MAT LIMITER & 36 KV LA; RPLD LIMITER @ TR; REF TR, RPLD LIGHTNING ARRESTOR;	ROR	1	0
FORCED INTERR	BL	EU 09	40744	33JW	5258449	220030970020	T	4/7/2003 0801	34	2	68	UNKNOWN	UNKNOWN	2821 W 11TH	1	TF	525844945		REPLACED BROKEN FUSE ON MIDDLE TRNS / LEFT SERV ON / NOTIFIED; REF TR.		1	0
FORCED INTERR	SB	TO 11	11294	JT5	5060929	120030970021	T	4/7/2003 080	128	11	1408	UNKNOWN	UNKNOWN	8625 CLEMSON	1	TF	506092964		REFUSED 50 KVA TRANS., REF TR;		1	0
FORCED INTERR	BZ	VL 03	3511D	15ABG	5629713	320030970013	F	4/7/2003 080	140	33	4620	LIGHTNING	LIGHTNING	119 REDFISH	1	LF	15ABG	BU 562971352	REPL 25 KVA CONV TR WITH THE SAME & INSTALLED W/LP. REF LF RPLD B/U TR.	ROR	1	0
FORCED INTERR.	HC	ST 09	11661		5154025	120030970022	T	4/7/2003 080	41	5	205	BU DISC OR BARI	DISC/BARRL	8302 HILLCROF		TF	515402557		MEK		1	0
FORCED INTERR	BL	ES 07	40685	39TP	5457003	120030970024	T	4/7/2003 082	65	1	65	HUMAN ERROR	HUMN ERRC	1221 PIERCE	1	TF	545700307		REFUSED 50 KVA TRANSFORMER. PULLED FUSE; REF TR; MEK		1	0
FORCED INTERR	HC	FD 12	10667	37FP	5052552	120030970027	T	4/7/2003 083	38	1	38	BU DISC OR BARI	DISC/BARRL	7823 LUDINGTO	1	TF	505255270		FUSE TORE AT THE BOTTOM OF THE FUSE BARREL ON THE POWER POT REPLACED THE FUSE. RPLD B/U BARREL ON TR;		1	0
FORCED INTERR	SU	RO 43	11531	96HC	4953108	120030970031	F	4/7/2003 084	13	1	13	BIRD	BIRD	11330 WILCRES	1	LF	96HC		REFUSED TR LF; REF LF;		1	0
FORCED INTERR	MP	LB 04	41270	72AAE	5659505	220030970026	T	4/7/2003 085	52	1	52	UNKNOWN	UNKNOWN	9505 WALLISVIL	1	TF	565950597		REPLACED FUSE THAT BROKE AT END OF BARREL / CNAS; REF TR,		1	0
FORCED INTERR	SU	HY 03	11695		4956228	120030970035	T	4/7/2003 090	34	8	272	SQUIRREL	SQUIRREL	10642 WESTHEI		TF	495622897		REF TR,		1	0
FORCED INTERR	BZ	BZ 06	30651	U75	5226959	320030970015	T	4/7/2003 0911	81	9	729	TREE CLEARANC	TREE CLEAI	517 CENTER W	1	SC	522695913		MADE TEMP REPAIRS TO 1/0 SECONDARIES FEEDING THIS ADDRESS - NEED TO REPLACE SPAN OF SEC FROM SVC POLE FEEDING THIS ADDRESS TO NEXT SVC POLE APPROX 100FT - LOC		1	0
FORCED INTERR	SB	SR 15	21421	8M8	4959628	120030970040	T	4/7/2003 091	80	1	80	VINES	VINES	2021 GESSNER	1	TF	495962808		REF TR;		1	0
FORCED INTERR	GP	AD 05	2C112	23EW	5364108	220030970030	T	4/7/2003 093	65	5	325	VINES	VINES	14723 DOGWOC	1	TF	536410875		REF TR.		1	0
FORCED INTERR	RS	RZ 03	30906	25PT	5441603	320030970024	T	4/7/2003 093	124	1	124	LIGHTNING	LIGHTNING	6715 ROSS	1	BU	544160322		replaced 10 conn w/hams, RPLD B/U TR,		1	0
FORCED INTERR	SB	BM 04	21489	83R	4958025	120030970046	T	4/7/2003 093	29	2	58	UNKNOWN	UNKNOWN	10940 OLD KAT	1	TF	495802579		REF TR.		1	0
FORCED INTERR	BA	CD 07	40394	193N	6356858	320030970026	T	4/7/2003 0941	108	12	1296	OH SEC/DR CL H	OH SC CL-H	504 E STERLINC	1	SC	635685874		FOUND #4 SS NEUTRAL AT X2 BUSHING ON XFMER CORRODDED AND ALSO 1 HOT LEG ON 4/0 SEC BURNED INTO 4/0 NEUTRAL—CLEANED UP 4-SS AND CT ON XFME AND MADE REPAIRS T		1	0
FORCED INTERR	BL	GT 05	40840	N68R	5356719	220030970034	T	4/7/2003 095	25	16	400	UNKNOWN	UNKNOWN	4810 CHENEVEI	1	TF	535671972		REFUSED POWER POT IN OPEN DELTA BANK / CNAS; REF TR,		1	0
FORCED INTERR	SH	PA 06	30785	D2W	5754839	320030970032	T	4/7/2003 1001	42	4	168	BIRD	BIRD	603 AUSTIN AVE	1	TF	575483999		REF TR, MEK		1	0
FORCED INTERR	GA	HX 02	31355	H7H	6340300	320030970033	F	4/7/2003 100	137	23	3151	UNKNOWN	UNKNOWN	7519 BERING AV	1	LF	H7H		REFUSE LINE FUSE TURN STREET LIGHT #480342 TO GET FIX. BEEN OUT FOR 4 MONTH, REF LF MEK		1	0
FORCED INTERR	HC	ST 09	11661	K91T	5154027	120030970057	T	4/7/2003 100	250	4	1000	OVERLOAD	OVERLOAD	5699 BEECHNU	1	BU	515402755	SC	REPL 50/100 7200-120/240 INSTL W/LPI RECTRO BUSS-WRK, RPLD B/U TR, RPRD BUSS WORK @ TR.		1	0
FORCED INTERR	MP	GG 01	40950	C51S	5554244	220030970037	L	4/7/2003 1011	39	1	39	OH SEC/DR CL H	OH SC CL-H	6125 CHERRYHI	1	DR			REPAIRED DROP AND CLAMPS AT WH; RPLD CONN @ WH, RPRD DR;	MEK	1	0
FORCED INTERR.	BZ	LJ 02	31785	SWE	5426243	320030970036	T	4/7/2003 1011	113	1	113	BU DISC OR BARI	DISC/BARRL	814 STRATTON	1	TF	542624324		REPLACED BAD FUSE BARREL ON LIGHTER POT ., RPLD B/U BARREL ON TR.		1	0
FORCED INTERR	SH	ED 04	30328	S51W	5949529	320030970041	F	4/7/2003 102	48	60	2880	SQUIRREL	SQUIRREL	503 EL DORADC	2	LF	S51W		REFUSED TERMINAL POLE TAKEN OUT BY A SQUIRREL / CNLS, REF TP		1	0
FORCED INTERR	SL	SE 41	1D162	X72E	3655347	120030970067	T	4/7/2003 104	289	1	289	COLLISION	COLLISION	4771 MORNING	1	BU	365534740	SC	RPLC CSP WITH CONVENTIONAL 25/7.2 INSTALL SWITCH, RPLD B/U TR; REF TR, RPRD SEC-1 CUST P/U SEC-1 CUST,		1	0
FORCED INTERR.	GA	GL 05	30483		6838428	320030970047	T	4/7/2003 104	22	3	66	LIGHTNING	LIGHTNING	2402 AVENUE Q		TF	683842886		REFUSED MID TRX (FUSE MELTED); REF TR,		1	0
FORCED INTERR	SH	HG 06	30264	I39K	5654837	320030970048	L	4/7/2003 105	35	1	35	OH SEC/DR CL H	OH SC CL-H	2010 AHRENS S	1	DR			REPLACED 1 HOT LEG & NEUTRAL AT WH; RPLD CONN @ WH;		1	0
FORCED INTERR	CY	PI 44	21031	C92W		220030970049	F	4/7/2003 105	35	83	2905	CONTRACTOR (H	CON-HLP	12107 SAMANTH	1	LF	C92W		HIGH LINE CREW & NHPL CREW WORKING ON HIGH LINE STREET CROSSING, GRIP GAVE UP AND WIRE GOT INTO LF, REF LF		1	0
FORCED INTERR	MP	AN 01	40003	7H6	5360434	220030970050	T	4/7/2003 105	22	3	66	SQUIRREL	SQUIRREL	4426 BUSIEK	1	TF	536043461		NO 3 PHASE REFUSED 10-15 KVA POWER OUT BY SQUIRREL, REF TR,		1	0
FORCED INTERR	BL	GT 13	10638		5356214	120030970074	T	4/7/2003 110	114	8	912	VINES	VINES	1644 NORTH BL		TF	535621464	PR	REPLACED 2 LIGHTNING ARRESTER 12FEET OF SQUIRAL WIRE 2 SQUIRAL GUARDS ON A OPEN DELTA BANK, RPLD B/O PR JUMP-TF BLOWN, RPLD LIGHTNING ARRESTOR,		1	0
FORCED INTERR	GA	SCW0	30887		6839844	320030970055	T	4/7/2003 111	19	4	76	LIGHTNING	LIGHTNING	1013 HARBOR V		TF	683984436		REFUSED LTR TRX (LTNG) TRK 6484 — NEED ARSTR REPL. —TRK ACCESS; REF TR; MEK		1	0
FORCED INTERR	BA	KM 04	41461	A88U	6249646	320030970056	F	4/7/2003 111	46	19	874	LIGHTNING	LIGHTNING	1406 CEDARBR	1	LF	A88U		REF LF		1	0
FORCED INTERR	GA	KM 06	30602	H99A	6248920	320030970058	F	4/7/2003 112	97	2	194	LIGHTNING	LIGHTNING	1800 KIPP	1	LF	H99A		REF LF;		1	0
FORCED INTERR	GA	GL 01	30459	HT2	6838224	320030970061	T	4/7/2003 112	201	10	2010	UNKNOWN	UNKNOWN	3114 AVENUE O	1	TF	683822489	DB	REPL 50 KVA CONV TRANS W SAME ALSO REPL JOSLYN FUSE BARRELL RPLD B/U DISC-TF BLOWN, RPLD B/U BARREL ON TR; MEK		1	0
FORCED INTERR	GP	KDL41	2433		5072235	220030970058	T	4/7/2003 114	72	1	72	BIRD	BIRD	24800 DOVERSI		PR	507223508		RPLD LIMITER @ TR, REF TR, MEK		1	0
FORCED INTERR	GA	PHR01	30633	18SW	6446922	320030970065	T	4/7/2003 114	65	2	130	SQUIRREL	SQUIRREL	1032 14TH	1	TF	644692242		REFUSED TRX (SQUIRREL) TRK 8464 —— NEED W.L.P & NEXT TRX (ARSTR) ——TRK ACCESS; REF TR,	ROR	1	0
FORCED INTERR	SH	PO 09	41398	C48	6149845	320030970066	T	4/7/2003 1151	86	4	344	LIGHTNING	LIGHTNING	114 CEDAR LN	1	PR	614984539		also had to remove vines off pole, RPLD B/O PRI JUMP-TF NOT BLOWN;		1	0
FORCED INTERR	HC	CC 02	13009	B73	5452341	120030970097	F	4/7/2003 1221	73	62	4526	O/H PRIMARY CL	OH PR CLMF	10607 LEITRIM	1	LF	B73	PR	FOUND # 4ACSR PRI DOWN AT 10607 LEITRIM CUT DOWN AT 10611 LEITRIM REF LF NEED SEND TICKET TO SC TO REPL ONE SPAN PRIMARY OR MAKE POLE IN REAR 10611 LEITRIM A DE PO		1	0
FORCED INTERR	BL	ST 15	10274	K81T	5155216	120030970098	T	4/7/2003 122	224	1	224	LIGHTNING	LIGHTNING	5800 DASHWOC	1	BU	515521667		RPLD B/U TR;		1	0
FORCED INTERR	CH	HR 03	41043	MU9	5460624	320030970077	L	4/7/2003 122	43	1	43	CONTRACTOR-N	CON-NT HLF	3103 MADELEY	1	DR			P/U DR.		1	0
FORCED INTERR	SH	SH 08	30928	A61H	5752857	320030970078	T	4/7/2003 122	193	8	1544	LIGHTNING	LIGHTNING	4302 BALCONES	1	BU	575285704		REPLACE A BAD 50 WITH A 25 KVA, RPLD B/U TR.		1	0
FORCED INTERR	BL	BR 12				120030970102	C	4/7/2003 122	0	0	0	OTHER EQUIPME	X-ARM	N OF 3440 S LO		CL	BR12	PR	CREWS IN ROUTE TO TROUBLE LOCATION @ 3440 SOUTH LOOP WEST REPORT OF WIRE DOWN CREW MADE REPAIR TO X-ARM AND TIED PRIMARY BACK IN ALL SEVCIE RESTORED NO		1	1
FORCED INTERR	BL	BR 12	1G067			120030970102	C	4/7/2003 122	29	684	19836	OTHER EQUIPME				CL	BR12				0	0
FORCED INTERR	BL	BR 12	10620			120030970102	C	4/7/2003 122	38	848	32224	OTHER EQUIPME				CL	BR12				0	0
FORCED INTERR	BL	BR 12	12729			120030970102	C	4/7/2003 122	184	143	26312	OTHER EQUIPME				CL	BR12				0	0
FORCED INTERR.	SH	CG 02	30212	P58U		320030970079	F	4/7/2003 1231	51	112	5712	LIGHTNING	LIGHTNING	77 E EDGEBRO	1	LF	P58U		REFUSE E PH P 58 U 100T, REF LF,		1	0
FORCED INTERR	SH	DR 07	30290	BG4		320030970081	F	4/7/2003 123	75	26	1950	LIGHTNING	LIGHTNING	7474 SANTA FE	1	LF	BG4		REFUSED 2 OF 3 PHASES OF LF REF LF		1	0
FORCED INTERR	SU	CE 05	11968	T79M	48532521	120030970104	T	4/7/2003 123	153	16	2448	OH SEC/DR CL N	OH SC CL-N	12941 SHANNO	1	SC	485325219		REPLACED NEUTRAL LUG AT THE TRANSFORMER AND REPLAED NEUTRA CLAMPS AT THE POLE		1	0
FORCED INTERR	SH	GG 04	30540	14H	55546171	220030970065	F	4/7/2003 123	57	85	4845	LIGHTNING	LIGHTNING	5912 BERNICE S	1	LF	14H		REF LF,		1	0
FORCED INTERR	SH	SB 03	31038	81A	5855949	320030970084	F	4/7/2003 124	53	80	4240	LIGHTNING	LIGHTNING	204 SHERMAN	1	LF	81A		REFUSED LF 81A--65T--W1, REF LF		1	0
FORCED INTERR	SH	DR 09	30300		5853033	320030970094	T	4/7/2003 124	95	1	95	OH SEC/DR CL H	OH SC CL-H	6817 TELEPHON		SC	565303371		REPLACED BAD XSMER LUG ON LIGHTER LEG, RPRD BUSS WORK @ TR;		1	0
FORCED INTERR	SH	SB 03	31037	I55U	5855934	320030970101	F	4/7/2003 125	58	40	2320	SQUIRREL	SQUIRREL	3201 ALBEMARL	1	LF	I55U		REFUSED L.F (SQUIRREL) TRK 6484 —— C.S.P @ REAR 3205 ALBEMARLE (NO SWITCH OR W.L.P), REF LF		1	0
FORCED INTERR	SH	DE 01	31368	54ED	5955741	320030970102	F	4/7/2003 125	137	5	685	BU DISC OR BARI	DISC/BARRL	5006 RAILROAD	1	LF	54ED	DB	REPLC BURNED UP 12KV DISC ,DUE TO LIGHTNING, RPLD B/U DISC-LF BLOWN,		1	0
FORCED INTERR	SH	GG 04	30542	S9P	5554426	220030970066	T	4/7/2003 125	197	1	197	LIGHTNING	LIGHTNING	5710 RANSOM S	1	BU	555442683		REPL 167 7200/277/480 VOLT TR WITH THE SAME, RPLD B/U TR,		1	0
FORCED INTERR	HC	HM 05	11031	K40H	5452045	120030970110	T	4/7/2003 125	58	4	232	LIGHTNING	LIGHTNING	3533 AIRPORT E	1	TF	545204554		REF TR.		1	0
FORCED INTERR	SH	DE 04	31375	PD3	5955936	320030970105	F	4/7/2003 125	43	24	1032	LIGHTNING	LIGHTNING	109 W 7TH #12	1	LF	PD3		REFUSED OUTSIDE PHASES OF LINE FUSE TAKEN OUT BY LIGHTNING, REF LF		1	0
FORCED INTERR	SH	WE 07	31369	NN1	5955230	320030970107	F	4/7/2003 125	81	99	8019	LIGHTNING	LIGHTNING	3604 WASHING	1	LF	NN1		REFUSED LF (LEFT SERV ON), REF LF		1	0
FORCED INTERR	HC	HM 06	11034	3AB	5454315	220030970069	F	4/7/2003 125	31	1	31	LIGHTNING	LIGHTNING	S.LOOP E @ CU	1	LF	3AB		REF LF		1	0
FORCED INTERR	HC	IR 04	11898	Y76L	5250828	120030970114	F	4/7/2003 130	40	1	40	UNKNOWN	UNKNOWN	96 RILEY (BEHI	1	LF	Y76L		REF LF		1	0
FORCED INTERR	SH	HA 05	30568	37EE	5750729	320030970106	F	4/7/2003 130	49	54	2646	LIGHTNING	LIGHTNING	11518 SAGEVAL	2	LF	37EE		REF TP,		1	0
FORCED INTERR.	SH	WE 08	31318	20PT	5855322	320030970110	F	4/7/2003 130	26	47	1222	LIGHTNING	LIGHTNING	1508 POLK	1	LF	20PT		REF LF		1	0
FORCED INTERR	BA	HL 06	41187	D39	6160305	320030970115	F	4/7/2003 130	8	57	456	VINES	VINES	504 HARRIS ST	1	LF	D39		REMOVE VINES OFF TRANSF AT 510 HARRIS AND REFUSE LF REF LF		1	0
FORCED INTERR	SH	SB 06	31049	FB8	5954057	320030970117	T	4/7/2003 130	70	5	350	BU DISC OR BARI	DISC/BARRL	1307 GLENMOR	1	TF	595405796		REPLACED FUSE BARREL ON A 50KVA LIGHTER TFMR; RPLD B/U BARREL ON TR. MEK		1	0
FORCED INTERR	BA	BT 02	40108	G19E		320030970123	F	4/7/2003 131	56	183	10248	LIGHTNING	LIGHTNING	3400 SHADY HIL	1	LF	G19E		REF LF,		1	0
FORCED INTERR	BA	MB 08	41421	P84X	6560450	320030970124	F	4/7/2003 131	82	97	7954	LIGHTNING	LIGHTNING	10601 LANGSTC	1	LF	P84X	LF 66GL	REF TP 66GL HAS BLOWN LA 7.2 TRUCK ACCESSABLE, REF LF, REF TP	ROR	1	0
FORCED INTERR	BA	CD 05	41965	37CG	6358415	320030970125	F	4/7/2003 131	71	1	71	LIGHTNING	LIGHTNING	1300 ROLLINGB	1	LF	37CG		VOLTAGE GOOD AT CUST INSIDE SERVICE OK BY CUST R/F SOUTH AND MIDDLE PH OF 3 PH LF ., REF LF		1	0
FORCED INTERR	GA	PHR02	31303	5Z2	6347305	320030970126	F	4/7/2003 131	59	52	3068	UNKNOWN	UNKNOWN	4450 17TH A	1	LF	5Z2		5 UNPROTECTED CAP'S ON THIS LINE FUSE. CUSTOMERS CONCERNED ABOUT NUMEROUS OUTAGES OVER THE LAST WEEK. NEEDS W/O TO FIND AND FIX PROBLEM. REF LF		1	0
FORCED INTERR	BA	MB 08	30527	26ND		320030970128	F	4/7/2003 131	119	1	119	LIGHTNING	LIGHTNING	19530 NEEDLEP	1	LF	26ND		REF LF CORRECTED 2HR/CRH		1	0
FORCED INTERR	SH	DE 01	30236	56PC	5955621	320030970129	F	4/7/2003 131	46	1	46	LIGHTNING	LIGHTNING	1718 W 13TH	1	LF	56PC		REF LF		1	0
FORCED INTERR	SU	AF 03	11825	X24M	4854616	120030970118	F	4/7/2003 131	59	18	1062	LIGHTNING	LIGHTNING	12042 TANAGEF	1	LF	X24M		REF LF		1	0
FORCED INTERR.	BL	CR 06	40537	JSS	5357747	120030970120	T	4/7/2003 131	216	1	216	BU DISC OR BARI	DISC/BARRL	1912 LUBBOCK	1	TF	535774789	DB	RPLD B/U DISC-TF NOT BLOWN; RPLD B/U DISC-TF BLOWN; RPLD LIGHTNING ARRESTOR,		1	0
FORCED INTERR.	SH	WE 02	31246	P9D	5855132	320030970134	F	4/7/2003 131	46	11	506	STRONG WIND	WIND	311 PASADENA	1	LF	P9D		REFUSE MIDDLE AND SOUTH PH'S P9D 50T WEATHER, REF LF		1	0
FORCED INTERR	SB	CB 06	21440	SWS	5060207	120030970121	F	4/7/2003 132	70	36	2520	LIGHTNING	LIGHTNING	9253 THEYSEN	1	LF	SWS		REF LF LEFT WORKING NO 1 HOME, REF LF		1	0
FORCED INTERR	SU	STF08	12266		48502441	120030970122	T	4/7/2003 132	38	4	152	LIGHTNING	LIGHTNING	1503 COUNTRY		TF	485024418		REF TR.		1	0
FORCED INTERR	BA	TRM02	4316A			320030970156	C	4/7/2003 132	0	0	0	LIGHTNING	LIGHTNING	TRM02 PART CI		PC	TRM02		BAD# 388 LGTN HIT PR M316 LOCKED OUT M316 TRIED M316 WOULD NOT HOLD UN ABLE TO OPEN SOURCE DISC ON M316 OPEN & TAGED LOAD SIDE DISC CLOSED M316 BY PASS ...		1	0
FORCED INTERR	BA	TRM02	4316A			320030970156	C	4/7/2003 132	74	314	23236	LIGHTNING				PC	TRM02				0	0
FORCED INTERR	BA	TRM02	4316B			320030970156	C	4/7/2003 132	89	220	19580	LIGHTNING				PC	TRM02				0	0
FORCED INTERR	CH	GW 02	40897	B33B	5661704	320030970136	T	4/7/2003 132	255	10	2550	OH SEC/DR CL H	OH SC CL-H	8719 SULTAN	1	TF	566170439	SC	REPAIRED 4/0 COPPER BUSS WORK AND # 2 SYSTEM NEURTAL, RESET TR, RPRD BUSS WORK @ TR, RPRD SEC CONN @ PL--1 CUST MEK		1	0
FORCED INTERR	SH	SB 04	31044	93UR	5855529	320030970140	F	4/7/2003 132	109	52	5668	LIGHTNING	LIGHTNING	801 JAMES ST	1	LF	93UR		REF LF;		1	0
FORCED INTERR	BA	MB 08	37138	P12X	6760544	320030970141	F	4/7/2003 132	77	12	924	LIGHTNING	LIGHTNING	GOU HOLE @ B	1	LF	P12X		REF LF		1	0
FORCED INTERR.	SU	AF 03	11825		4854614	120030970123	T	4/7/2003 132	54	12	648	LIGHTNING	LIGHTNING	12119 TROULON		TF	485461458		REFUSED TRANS BACK ON WEATHER RAIN LIGHTNING, REF TR,		1	0
FORCED INTERR	KY	FZ 42	2562G	55HG	4659112	120030970124	F	4/7/2003 132	86	13	1118	UNKNOWN	UNKNOWN	2910 DULANEY	1	LF	55HG		REF LF,		1	0
FORCED INTERR	SH	SB 06	31649	G51D	5955206	320030970145	F	4/7/2003 132	56	1	56	LIGHTNING	LIGHTNING	1202 S EAST BE	1	LF	G51D		REFUSED 2 LF'S --LIGHTING; REF LF		1	0
FORCED INTERR	SH	AI 08	31376		6055131	320030970147	T	4/7/2003 132	42	2	84	LIGHTNING	LIGHTNING	440 E 8TH		TF	605513185		LIFT STATION SEWER, REF TR,		1	0
FORCED INTERR	BA	CD 03	30579		6458054	320030970146	T	4/7/2003 1331	32	1	32	LIGHTNING	LIGHTNING	1012 E CEDAR E		TF	645805427		REF 25 KVA XFMER OUT BY LIGHTENING—LEFT OK, REF TR,		1	0
FORCED INTERR	BL	BR 05	10495	DD9	5254254	120030970127	F	4/7/2003 133	49	51	2499	LIGHTNING	LIGHTNING	4103 UNDERWC	1	LF	DD9		REFUSED LF DD9 50 T TAKEN OUT BY LIGHTING, REF LF		1	0
FORCED INTERR	BL	UL 46	10334	63DU	5157013	120030970128	F	4/7/2003 133	210	16	3360	LIGHTNING	LIGHTNING	6150 VALLEY FC	1	LF	63DU	SC	PICKED UP ONE SPAN OF PRI NEUTRAL REPLACED ONE 35KV BARREL IN THE REAR OF #134 VALLEY FORGE DR. REF LF P/U PR NEUT		1	0
FORCED INTERR	CH	GP 05	40809	82U	5657713	220030970075	T	4/7/2003 133	34	5	170	SQUIRREL	SQUIRREL	9707 RACINE ST	1	TF	565771395		SQ, REF TR	ROR	1	0
FORCED INTERR	BA	HNY02	40308	68CG	6358255	320030970158	F	4/7/2003 133	42	11	462	LIGHTNING	LIGHTNING	1511 W CEDAR	1	LF	68CG		REFUSE LF REF LF		1	0
FORCED INTERR	SH	SB 03	31038	81A	5855848	320030970160	T	4/7/2003 133	55	8	440	LIGHTNING	LIGHTNING	3102 CARTER	1	TF	585584843		REF 50 L POT, REF TR,		1	0
FORCED INTERR	HM	AD 03	20401	R50	5364859	220030970078	F	4/7/2003 134	84	24	2016	SLACK SPANS	SLACK SPAI	RALPHCREST	1	LF	R50	SC	WE STRAIGHTENED 40 FOOT DEAD END POLE , REPULLED GUYS AND PICKED UP # 2 PRIMARY NEUTRAL .HIGH LOAD HUNG THE SLACK SPAN NEUTRAL AND PULLED POLE OVER REF LF		1	0
FORCED INTERR	HC	FD 08	10863	I95X	5053614	120030970132	F	4/7/2003 134	0	0	0	LIGHTNING ARRE	LTNG ARRS	7618 CLARIDGE	2	LF	I95X	PR	ISOLATED THE T.P. ON URD ORDER # 7982 BAD LIGHTNING ARRESTOR ON A DOUBLE T.P. COVERED WITH VINES MIGHT BE TRUCK ACCESSIBLE WITH A SMALL SINGLE BUCKET (CUT THE		1	0
FORCED INTERR	HC	FD 08				120030970132	F	4/7/2003 134	98	17	1666	LIGHTNING ARRE			2	LF	I95X				0	0
FORCED INTERR	HC	BL 06	12681	40AR	5152451	120030970133	T	4/7/2003 134	155	1	155	HUMAN ERROR	HUMN ERRC	11677 1/2 CHIMI	1	SC	515245187		REPLACED BURNED UP 2 BOLT CLAMP AT TRANS, RPLD CONN @ TR.		1	0
FORCED INTERR	SH	DE 04	31375	4PS	5955933	320030970167	F	4/7/2003 135	27	22	594	LIGHTNING	LIGHTNING	132 W 8TH	1	LF	4PS	DB	RPLD B/U DISC-LF BLOWN,		1	0
FORCED INTERR	BL	DN 04	10553	E95L	53564411	120030970134	F	4/7/2003 140	42	3	126	LIGHTNING	LIGHTNING	MT VERNON @	1	LF	E95L	TF 535644116	REFUSED MIDDLE TRAN OF BANK, LOOKS LIKE 100 KVA, ALSO REFUSED MIDDLE PHASE OF LF REF LF REF TR.		1	0
FORCED INTERR	HM	SW 06	41694	82AH	5663613	220030970080	F	4/7/2003 140	119	36	4284	LIGHTNING	LIGHTNING	9110 BLK MT HC	1	LF	82AH	DB 566361350	REPLACED BURNED-UP DISCONNECT CORRECTED 2HR/CRH		1	0
FORCED INTERR	SH	SB 05	31046	E65B	5855314	320030970170	F	4/7/2003 140	70	22	1540	LIGHTNING	LIGHTNING	1418 HARRIS	1	LF	E65B	TF 565531471	REF LF REF TR		1	0
FORCED INTERR.	BL	ST 07	10228	K28U	5054929	120030970137	F	4/7/2003 140	29	11	319	LIGHTNING	LIGHTNING	2 CARLOTA CT	1	LF	K28U		REF LF		1	0
FORCED INTERR	SH	DR 03	30271	15X	5653532	320030970172	F	4/7/2003 140	61	28	1708	LIGHTNING	LIGHTNING	8302 DILLON	1	LF	15X		REFUSE 2 PH'S 15 X 65 T WEATHER LIGHTING. REF LF		1	0
FORCED INTERR.	BA	BT 02	40108	K81Z	6258903	320030970177	F	4/7/2003 141	41	11	451	LIGHTNING	LIGHTNING	4810 OAK HOLL	2	LF	K81Z		REFUSED T/P K812, REF TP		1	0
FORCED INTERR	SL	SE 02	2428B	95EG	3658229	120030970142	F	4/7/2003 142	61	11	671	LIGHTNING	LIGHTNING	FM 1458 NORTH	1	LF	95EG		REFUSED L F LEFT 120 120 240 WEATHER, REF LF,		1	0
FORCED INTERR	MP	OA 07	41606	12HR	5759244	320030970181	F	4/7/2003 142	54	2	108	FLLNG TREE OUT	TREE FL/OE	GLORIA @ WYN	1	LF	12HR		REF LF		1	0
FORCED INTERR	FB	EB 06	11295	R95T		120030970145	F	4/7/2003 1431	67	118	7906	LIGHTNING	LIGHTNING	1905 LEVERIDG	1	LF	R95T	LF G48I LF F74 LF 12L TF 384	REF----F74T----REF B & C OF 12L8----REF G48I----REF TR @ 3236 FM 1266----WEATHER, REF LF REF TR		1	0
FORCED INTERR	FB	OR 02	11301	L25	40469191	120030970147	T	4/7/2003 143	171	2	342	LIGHTNING	LIGHTNING	6626 1/2 ROSE	1	BU	404691916		REPLACED BAD 15 KV 7200 TRANS W/SAME GLN 40469191 W/O BUTTON WAS HIT RPLD B/U TR.		1	0
FORCED INTERR	BA	CD 03	40339	E29K	6458117	320030970183	T	4/7/2003 143	197	6	1182	LIGHTNING	LIGHTNING	3925 TUMBLEW	1	BU	645811799		REPLACED 50 KVA CSP WITH 50 KVA CONV / TR WAS PICKED UP & RETURNED TO BAYTOWN S/C RPLD B/U TR		1	0
FORCED INTERR	FB	RE 05	11436	D49		120030970148	F	4/7/2003 143	73	9	657	LIGHTNING	LIGHTNING	602 HILLCREST	1	LF	D49		REF LF		1	0

FORCED INTERR	FB	OR 03	11307	F38T		12003097014E	F	4/7/2003	144(	100	3	300	LIGHTNING	LIGHTNING	FM 1675, S OF H	1	LF	F38T	LF	53AAK	LF	B23	FOUND PARENT LINE FUSE F38T WORKING RIF CHILD LINE FUSE 53AAK-86T @ HWY 90 AND ENGEL AND ALSO CHILD FUSE B23F-25T ON ENGEL, SOUTH OF BUILS BOTH ARE WHOLE PHASE	1	0
FORCED INTERR	BZ	VL 03	35118	H2R	552563613	12003097018A	T	4/7/2003	144(	25	2	50	BU DISC OR BARI	DISC/BARRL	2902 FM 523 #1	1	TF	552563611					REF TR, RPLD BAJ BARREL ON TR, RGR	1	0
FORCED INTERR	SB	SR 15	21678	NP5	49586565	12003097015 T		4/7/2003	144!	76	14	1064	VINES	VINES	10123 HAZELHU	1	TF	495865659					RMID WHAT VINES I COULD TO GET LIGHTS BACK ON BUT NEED TO RM THE REAT & INSTALL WILD LIFE PROT, REF TR MBG TO BC TO MAKE REPAIRS WHEN MGU	1	0
FORCED INTERR	FB	OR 01	11299	68LS	41470545	12003097015 F		4/7/2003	144!	109	28	3052	LIGHTNING	LIGHTNING	2515 SPENCER	1	LF	68LS					OPENED AND CLOSED LINE DISCONNECT FEEDING LINE FUSE / REPICKE BACK ON IF LINE FUSE GOES OUT AGAIN, CREW MAY WANT TO CHECK DISCONNECT & HIGH AND LOW BIDES AS W	1	0
FORCED INTERR	FB	EB 05	11290	G11J		12003097054 F		4/7/2003	145(	139	1	139	LIGHTNING	LIGHTNING	CO 207 @ CO 2	1	LF	A9C	TF	36443295C			FOUND LINE FUSE IN / REFUSED LIGHTER AT THE ADDRESS, REF TR, CORRECTD OUTAGE TYPE AND ADJ EAT CUST AFFECTED QAMX	1	0
FORCED INTERR	SH	HG 06	31326	86UR	56557351	32003097018E	F	4/7/2003	145!	42	1	42	LIGHTNING	LIGHTNING	9850 GOODYEA	1	LF	86UR	TF	565573510			REPLACED MIDDLE TRIAS FUSE BARREL / REFUSED LF / LEFT BERV ON NOTIFIED, REF LF, RPLD BAJ BARREL ON TR,	1	0
FORCED INTERR	FB	OR 01	11299	DJ9	39488377	12003097015E	F	4/7/2003	145!	100	2	200	LIGHTNING	LIGHTNING	HWY 90A W @ I	1	LF	DJ9					REFUSED MIDDLE AND SOUTH PHASE OF LINE FUSE DJ9 #6 T WEATHER, REF LF,	1	0
FORCED INTERR	FB	NV 01	11206	D79	42447114	12003097015E	F	4/7/2003	145!	79	36	2844	LIGHTNING	LIGHTNING	6141 FENSKE LI	1	LF	D79	PR				TRK 6484 ---- REFUSED LF JPR DOWNN NEED PRI RETIED @ 6164 FENSKE ---- ARISTR REPL @5710 FENSKE & DBLD E LOWERED @ 5230 FENSKE BALL TRK ACCESABIE, REF LF,	1	0
FORCED INTERR	KY	FZ 42	2562G	55HG	46591125	12003097057 T		4/7/2003	145!	88	3	264	SQUIRREL	SQUIRREL	2819 DEEDS RD	1	TF	465911296					CLEARED UP BAD ARRESTOR & REP LIMITER FUSE ON TR OUT BY SQUIRREL NEED TO REP ARRESTOR & INSTALL BETTER WIL PROT ON TR, RPLD LIMITER @ TR, REF TR, MBG TO BC TO M	1	0
FORCED INTERR	SH	DR 09	30302	LL6	58530045	32003097018E	F	4/7/2003	145!	41	2	82	LIGHTNING	LIGHTNING	TELEPHONE @	1	LF	LL6					REF LF;	1	0
FORCED INTERR	BL	BI 04	10060		52561337	12003097015E	L	4/7/2003	150!	172	1	172	TREE CLEARANC	TREE CLEAR	4018 BETSY LN		DR						TRIMMED OUT TREE AND BRUSHED OUT DROPS LEFT ON AN WORKING, RPRD DR,	1	0
FORCED INTERR.	SH	SB 03	31038	81A	58558496	32003097018 T		4/7/2003	150!	151	8	1208	LIGHTNING	LIGHTNING	3110 CARTER	1	BU	585584993					REPLACE A 50CBP WITH A 50 COW , RPLD BAJ TR,	1	0
FORCED INTERR	SU	BAR42	11855	X33H	47542339	12003097016C	F	4/7/2003	150!	106	50	5300	LIGHTNING ARRE	LTNG ARRS	7427 ALCOMITA 2		LF	X33H					CLEARED UP BAD LIGHTNING ARRESTOR AND REFUSED TP X33H NEED TO REPLACE L A. AND REWIRE LOWBIDE OF DISCCONNECT ABAP IN EASMENT , REF TP	1	0
FORCED INTERR	HM	LA 04	41251			22003097009E	C	4/7/2003	150!	120	245	29400	LIGHTNING	LIGHTNING	12606 LADBROI		PC	LA04					CREWE IN ROUTE TO POSSIBLE BURNED OFF JUMPER FD 2 BU JUMP 1 6P E OF LF G485 @ JUNCTION POLE - CREW TO MAKE REPAIRS RJS SWITCH WOULD NOT OPEN	1	0
FORCED INTERR	BL	KB 04	10150	G38		12003097016E	F	4/7/2003	151(	47	81	3807	LIGHTNING	LIGHTNING	1840 NORFOLK	1	LF	G38					REF LF	1	0
FORCED INTERR	FB	RS 04	11401	64G	43474447	12003097064 F		4/7/2003	151!	52	17	884	LIGHTNING	LIGHTNING	1621 WALENTA	1	LF	64G					REF LF,	1	0
FORCED INTERR	GA	MDY01	31028	E6SD	66369584	32003097018E	L	4/7/2003	151!	304	1	304	OH SEC/DR CL H	OH SC CL-H	8817 STEWART 2		SC						FOUND PED 1/2 WAY UNDER MOBILE HOME, MADE TEMP REPAIRS TO HOT LEGS, WILL NEED A WKO TO HAVE PED MOVED AND UPGRADED, RPLD BEC CONN @ PED-1 CUST	1	0
FORCED INTERR	SU	IM 43	12071	60BK	47511454	12003097016E	F	4/7/2003	151!	82	11	902	LIGHTNING	LIGHTNING	12800 DIAMONC	1	LF	60BK					REF LF	1	0
FORCED INTERR	FB	RS 01	11384		42489165	12003097016E	T	4/7/2003	151!	39	2	78	LIGHTNING	LIGHTNING	118 PRAIRIE LN		TF	424891655					REF TRANS LIGHTNING / RVC ON, REF TR,	1	0
FORCED INTERR	SB	GE 41	21192	N42U	47610210	12003097017E	F	4/7/2003	151!	54	132	7128	LIGHTNING	LIGHTNING	5323 GIRNIGOE 2		LF	N42U					REPL. FUSE BARREL, RPLD BAJ BARREL ON TP,	1	0
FORCED INTERR	BL	SF 15	10436		51576101	12003097017E	T	4/7/2003	152(	324	7	2268	LIGHTNING	LIGHTNING	5302 FIELDWOC		BU	515761011					BAD 37 5 PWR AND 50 LIGHTER 120 240 7 2 KV ALL THAT RVC BACK ON , RPLD BAJ TR, RPLD LIGHTNING ARRESTOR.	1	0
FORCED INTERR.	SH	PJ 04	30449	G82N		32003097019D	F	4/7/2003	152!	110	152	16720	TREE CLEARANC	TREE CLEAR	5111 ROYAL PK	1	LF	G82N					NEED TO TRIM TREES FROM PRI. @ 5316 ROYAL PKY, & @ LF G82N, REF LF;	1	0
FORCED INTERR	BL	UL 46	13069	16JJ	51571022	12003097017E	T	4/7/2003	152!	349	10	3490	LIGHTNING	LIGHTNING	1613 POTOMAC	1	BU	515761224	SC				REPLACED 75KVA 18.8 120240 PICKED UP MO BEC, RPLD BAJ TR, RPRD CONN @ TR, RPLD LIGHTNING ARRESTOR.	1	0
FORCED INTERR.	BL	GN 06	10619		52559054	12003097018C	T	4/7/2003	152!	226	5	1130	LIGHTNING	LIGHTNING	2348 MARONEA		BU	525590569	SC			DB	REPLACED CONNECTIONS ON TOP LIGHTER BUSS WORK, RPLD BAJ TR, RPLD BAJ DISC-TF BLOWN, RPLD BUSS WORK @ TR,	1	0
FORCED INTERR	BL	SF 46				12003097083 C		4/7/2003	152!	7	1205	8435	LIGHTNING	LIGHTNING	SF 46 CKT LOCI		CL	SF46					WEATHER IN AREA LOCKED OUT ON TWO TRIPS, WP8,	1	1
FORCED INTERR	FB	OB 42	12826		45512548	12003097018A	T	4/7/2003	153!	61	5	305	LIGHTNING	LIGHTNING	2614 OLD SOUT		TF	455125461					REFUSED TRANSFORMER----ALLEN TR 3232, REF TR.	1	0
FORCED INTERR	SU	RO 04	12220	H85Z	49528204	12003097018E	F	4/7/2003	153!	34	44	1496	LIGHTNING	LIGHTNING	9563 RAVENSW 2		LF	H85Z					REF TP;	1	0
FORCED INTERR	SU	WI 43	12618	74NC	48554585	12003097018E	F	4/7/2003	153!	78	117	9128	INSULATOR	INSULATOR	3306 SHADOWC 2		LF	74NC					TERMINATOR CAME LOOSE FROM THE BRACKET AND FELL AGAINST THE POLE , I MADE REPAIRS AND RE-FUSED THE T.P., REF TP	1	0
FORCED INTERR	SU	AF 01				12003097087 C		4/7/2003	153!	14	3436	48104	LIGHTNING	LIGHTNING	AF01 CKT LOCI		CL	AF01					ALIEF 81 LOCKED OUT WEATHER IN AREA FULL CYCLE, TRIED ALL BACK HOT WP8,	1	1
FORCED INTERR	CH	BY 10	40208		54611285	32003097097 T		4/7/2003	153!	53	2	106	LIGHTNING	LIGHTNING	9502 E HARDY S		TF	546112870					REF TR,	1	0
FORCED INTERR	FB	CRB45	11461		46483146	12003097098 T		4/7/2003	153!	80	7	560	LIGHTNING	LIGHTNING	826 KNOLL FOR		PR	464831492					REPL BAD LIMITER & REFUSED TRANS - LIGHTNING - RVC REETORED; RPLD LIMITER @ TR, REF TR,	1	0
FORCED INTERR	SB	ADK42	21308	M60H	50605504	22003097009E	T	4/7/2003	153!	50	1	50	LIGHTNING	LIGHTNING	7821 PINEMONT	1	TF	506065041					REF TR,	1	0
FORCED INTERR	GP	BY 06	47037	B70F		22003097010C	F	4/7/2003	153!	61	71	4331	LIGHTNING	LIGHTNING	O'DONNELL S E	1	LF	B70F	TF	53817418C			CLEARED UP TRMB LIN @ 148 TREASURE I NEEDS TO BE REPLACED @ B/C CONV CAN NOT GET TRK TO IT / REPLACED LF BARREL O'DONNELL S. OF E RUNNYSIDE LEFT BERV ON, REF LF	1	0
FORCED INTERR	CH	BY 04	40173	R8N	54615153	32003097019E	F	4/7/2003	154(	17	19	2223	LIGHTNING	LIGHTNING	9417 JENSEN	1	LF	R8N					REFUSED 2 PHASE OF 3 PHASE LF, REF LF,	1	0
FORCED INTERR	MP	EU 12	41969	R80A	52581568	22003097010 T		4/7/2003	154(	267	1	267	LIGHTNING	LIGHTNING	3901 W 12TH	1	BU	525815650					REPLACED BAD 75KVA LIGHTER TRANS IN CLOSED DELTA BANK WITH THE SAME RPLD BAJ TR,	1	0
FORCED INTERR.	SH	PE 04	31599	148F		32003097020I	F	4/7/2003	154(	85	34	2890	LIGHTNING	LIGHTNING	4803 ARNOLD D	1	LF	148F					REF LF,	1	0
FORCED INTERR	HC	QV 08	12434	R50F	50504386	12003097019E	F	4/7/2003	154(	42	46	1932	LIGHTNING	LIGHTNING	1207 PECAN GL	2	LF	R50F					REF TP, REF TP,	1	0
FORCED INTERR	SB	WT 08	22393		50578475	12003097020S	T	4/7/2003	154(	124	3	372	VINES	VINES	501 RIPPLE CRE		TF	505784757					VINES ENGULFING OPENDELTA BANK CAUSED WL GUARD TO BURN UP AND HIBIDE TRB DO PH TO PH -- CLEARED VINES - REFUSED RO AND 25 BUT POWER POT BLEW BACK DUE TO BAD L	1	0
FORCED INTERR.	BA	BT 05	40137	AS2T	62569321	32003097020S	F	4/7/2003	154(	37	1	37	LIGHTNING	LIGHTNING	1905 CAROLINA	1	LF	AS2T					REF LF	1	0
FORCED INTERR	MP	UN 08	10970	W9M	54548555	22003097010S	F	4/7/2003	154(	84	64	5376	LIGHTNING	LIGHTNING	5238 KINGSBUR	1	LF	W9M	PR	545485551			FOUND LF OUT RODE OUT AND FOUND LIGHTNING ARRESTOR AND HIGH SIDE BLOWN OFF 50 KVA TRAN REAR OF 5242 KINGSBURY, REPAIRED HIGH SIDE AND THEN RE FUSED LF TRAN F	1	0
FORCED INTERR	SH	PE 01	31299	I91C	56473444	32003097020E	F	4/7/2003	154(	109	61	6649	LIGHTNING	LIGHTNING	17301 COUNTY	1	LF	I91C					REF LF,	1	0
FORCED INTERR	KY	KT 41	22599	B9CA	43583384	12003097021S	T	4/7/2003	155!	189	4	756	LIGHTNING	LIGHTNING	5118 MOCKINGI	1	BU	435833900					REPLD 50 KVA OH RPLD BAJ TR, RPLD LIGHTNING ARRESTOR,	1	0
FORCED INTERR	BA	TRM0(	4316B		66594125	32003097020K	T	4/7/2003	155!	37	2	74	LIGHTNING	LIGHTNING	6219 FM 3180 RI		TF	665941209					REF TR;	1	0
FORCED INTERR	BL	DN 02	13122	UG7	53574108	12003097021S	T	4/7/2003	155!	49	14	686	TREE CLEARANC	TREE CLEAR	1126 W GRAY S	1	TF	535741088					TRIMMED TREE FROM TRANSFORMER REFUSE A 50 KVA T/F, REF TR,	1	0
FORCED INTERR	BA	CD 08	40396	PT5	64562465	32003097020S	T	4/7/2003	155!	54	2	108	TREE CLEARANC	TREE CLEAR	2102 E TEXAS A	1	TF	645624631					TRIMMED TREE LIMBS OFF OF TRANS AND DISCONNECT AND REFUSED TRANS, REF TR,	1	0
FORCED INTERR	SH	AI 08	31376	18H	60551330	32003097021C	F	4/7/2003	155!	62	2	124	LIGHTNING	LIGHTNING	601 E 8TH	1	LF	18H					REFUSED LINE FUSE, REF LF;	1	0
FORCED INTERR.	SH	HG 06	30264	32D		32003097021S	F	4/7/2003	155!	77	138	10626	STRONG WIND	WIND	8348 BAKER DR	1	LF	32D					REFUSED LINE FUSE, REF LF,	1	0
FORCED INTERR	SH	CA 03	30113	U24O	59536022	32003097021A	F	4/7/2003	160(	0	0	0	LIGHTNING	LIGHTNING	4102 WOODHAA	2	LF	U24O	BU	595360068			REPLACE A 25 DEADFRONT WITH THE SAME, RPLD BAJ TR,	1	0
FORCED INTERR	SH	CA 03				32003097021A	F	4/7/2003	160(	106	27	2862	LIGHTNING			2	LF	U24O						0	0
FORCED INTERR	SH	CA 03				32003097021A	F	4/7/2003	160(	315	2	630	LIGHTNING			2	LF	U24O						0	0
FORCED INTERR	HC	HM 05	11032	40LH	54534225	12003097022S	T	4/7/2003	160(	71	5	355	LIGHTNING	LIGHTNING	4714 LARKSPUF	1	TF	545342296					REF TR,	1	0
FORCED INTERR	CH	GP 06	40810	61GU	56579045	32003097021S	F	4/7/2003	160(	189	15	2835	LIGHTNING	LIGHTNING	1810 LEGGETT	1	LF	61GU	PR			DB	PICKED UP ONE SPAN OF 6 4 PRI AND REPLACED ONE SWITCH, PAI PR FUSE BLOWN, RPLD BAJ DISC-LF NOT BLOWN	1	0
FORCED INTERR	MP	HM 02	11014	J46Y		22003097010E	F	4/7/2003	160(	187	2	374	LIGHTNING	LIGHTNING	NEW YORK @ Y	1	LF	J46Y	TF	545444893			CHG OUT A 15 KVA 7200 120 240 V TRANSFORMER WITH A 25 KVA 7200 120 240 V TRANSFORMER OLD SERIAL # 3048423; RPLD BAJ TR, EADDED TF TO OUTAGE TYPE - REDUCED E91 CUST AF	1	0
FORCED INTERR	CH	GP 06	40810	7KX		32003097021E	F	4/7/2003	160(	47	111	5217	LIGHTNING	LIGHTNING	1407 CRAIG	1	LF	7KX					REF LF RPLD BAJ BARREL ON LF	1	0
FORCED INTERR	HC	GV 02	10909	FD7	54538524	12003097022S	T	4/7/2003	160!	78	9	702	TREE CLEARANC	TREE CLEAR	5631 KENILWOC	1	TF	545385241					NEED TO TRIM TREE AROUND THIS TRANS REF TR	1	0
FORCED INTERR	BA	TRM0(	4316A	P11G	66576319	32003097021E	T	4/7/2003	160!	46	2	92	LIGHTNING	LIGHTNING	8705 LENNIE LN	1	TF	865763195					REF TR	1	0
FORCED INTERR	FB	EB 06	11295	85AP	38451346	12003097022E	F	4/7/2003	161(	46	3	138	LIGHTNING	LIGHTNING	13500 BATTLE	1	LF	85AP					REF LF	1	0
FORCED INTERR	BA	MB 08	3D163	52AAB	66608054	32003097022 T		4/7/2003	161(	46	2	92	LIGHTNING	LIGHTNING	1411 MAGNOLIA	1	TF	668080598					REF TR,	1	0
FORCED INTERR	GA	GA 04	31195	A16M	67372566	32003097022S	L	4/7/2003	161!	167	1	167	UNKNOWN	UNKNOWN	1724 68TH ST	1	DR						REPLACED BAD 65 CU DROPS WITH 140 AL 3 W TW, RPLD DR	1	0
FORCED INTERR	SH	CA 03	30165	S58W	59535203	32003097022E	F	4/7/2003	161!	151	37	5567	LIGHTNING	LIGHTNING	3726 SUNSHINE 2		LF	S58W					REFUSED TERMINAL POLE TAKEN OUT BY LIGHTNING / CN&B REF TP	1	0
FORCED INTERR	SB	ADK42	20891		48617054	12003097023 T		4/7/2003	162(	82	2	164	LIGHTNING	LIGHTNING	11640 BRITTMO		TF	486170543					refused lighter b k open delta bank out by another REF TR,	1	0
FORCED INTERR	HC	CC 02	10830	B19S	54522322	12003097023E	T	4/7/2003	162!	14	5	70	LIGHTNING	LIGHTNING	10807 SEGRES 1		TF	545223226					REFUSED TRANS BACK ON WEATHER, REF TR,	1	0
FORCED INTERR	CH	LB 02	41257	K45E		32003097022E	F	4/7/2003	162!	92	11	1012	LIGHTNING	LIGHTNING	7959 CHATEAU	1	LF	K45E					REF LF	1	0
FORCED INTERR	SU	IM 47	12107	S3901	48512166	12003097023S	T	4/7/2003	162!	216	2	432	LIGHTNING	LIGHTNING	518 W ALKIRE L	1	BU	485121802					REPL. 25 KVA TRANS 7200 120/240 WITH SAME, RPLD BAJ TR	1	0
FORCED INTERR	SH	SP 03	30996	98T	58537547	32003097023 F		4/7/2003	162!	40	51	2040	LIGHTNING	LIGHTNING	2510 GRAPE LN	1	LF	98T					REF LF,	1	0
FORCED INTERR	RS	AV 02	30057	79HJ		32003097023A	F	4/7/2003	162!	146	96	14308	LIGHTNING ARRE	LTNG ARRS	916 RYMAL	2	LF	79HJ					REPLACED BAD LARRESTOR DUE TO WEATHER, REF LF,	1	0
FORCED INTERR	FB	OR 01	11299	88ADA	39479501	12003097023A	F	4/7/2003	162!	15	5	75	LIGHTNING	LIGHTNING	8715 HIGHWAY	1	LF	88ADA					REFURBED LINE FUSE WEATHER, REF LF	1	0
FORCED INTERR	FB	OR 01	11299	87ADA	40472576	12003097023E	F	4/7/2003	162!	20	18	320	LIGHTNING	LIGHTNING	633 LAKE	1	LF	87ADA					REFURBED LINE FUSE, REF LF	1	0
FORCED INTERR	BA	BT 02	40108	K81Z	62589033	32003097023S	T	4/7/2003	162!	381	2	762	LIGHTNING	LIGHTNING	4800 OAK HOLL	2	BU	625890337					REPLACED 50KVA URD TR, TR WAS PICKED UP & RETURNED TO BAYTOWN B/C RPLD BAJ TR,	1	0
FORCED INTERR.	SH	TE 04	31594	75T	56490163	32003097023E	T	4/7/2003	163(	76	12	912	LIGHTNING	LIGHTNING	2537 S PEARLAI	1	TF	564001826					REFURBED TRX 4,TNGH TRK 6484 ---- NEED ARTSTR REPL @ EASEMENT ---REAR2529 REF TR, MEK	1	0
FORCED INTERR	MP	UN 08	10971	39HU	54558126	22003097011 F		4/7/2003	163!	55	18	990	LIGHTNING	LIGHTNING	5507 TALLOW L	1	LF	39HU					REF LF	1	0
FORCED INTERR	GA	PHR01	30869	95HN	65463557	32003097024C	T	4/7/2003	164(	104	8	832	TREE CLEARANC	TREE CLEAR	213 2ND	1	TF	654635073					TRIMMED TREES AND REFUSED TRANS REF TR,	1	0
FORCED INTERR	SU	BAR45	11895		47549568	12003097024C	T	4/7/2003	165(	218	2	436	LIGHTNING	LIGHTNING	13402 BELLAIRE		BU	475495609					RPLD BAJ TR,	1	0
FORCED INTERR	SH	UW 02	31696	N10F	60531561	32003097024C	T	4/7/2003	165!	164	6	984	OH SEC/DR CL H	OH SC CL-H	510 N CROCKET	2	SC	605315619					REPLACED 4 TRANSFORMER LUGS FOR 2 HOUSES IN THE URD TRANSFORMER THEY WERE HEATING UP CAUSING THE LIGHTS TO BLINK, RPLD CONN @ TR	1	0
FORCED INTERR	CH	GP 06	40810	7KX	56579065	32003097024S	F	4/7/2003	165!	43	36	1548	LIGHTNING	LIGHTNING	2227 15TH	1	LF	H89E					TLA	1	0
FORCED INTERR	SU	CE 10	11945	F29T	47529221	12003097024E	F	4/7/2003	165!	119	28	3332	RISING WATER	RISING H20	1415 BRAMBLEI	2	LF	F29T	PR				URD ORDER 7867 REPAIRED LIVEFRONT BUSHING IN TRAN #22, REF TP, RPLD CONN @ TR	1	0
FORCED INTERR	SB	GE 41	21192	N42U	46619194	12003097024E	F	4/7/2003	165!	46	132	6072	TREE CLEARANC	TREE CLEAR	5119 CAIRNLEIC	2	LF	N42U					REMOVED SMALL TREE BRANCH AND REFUSED TERMINAL POLE, REF TP	1	0
FORCED INTERR	BA	MB 08	3D163	52AAB	66609028	32003097024E	T	4/7/2003	170(	200	2	400	LIGHTNING	LIGHTNING	1519 MAGNOLIA	1	BU	666090289					REPLACED 75 KVA T/R T/R WAS PICKED UP & RETURNED TO BAYTOWN B/C , RPLD BAJ TR,	1	0
FORCED INTERR	CY	PI 42	2454A	F73F	49762572	22003097011S	F	4/7/2003	170(	100	24	2400	LIGHTNING	LIGHTNING	33308 SWEETGI	1	LF	F73F					REF LF,	1	0
FORCED INTERR	SH	CK 02	31713	18MR	59518116	32003097024F	F	4/7/2003	171(	49	14	686	LIGHTNING	LIGHTNING	3014 PRAIRIE KI	2	LF	18MR					RPLD BAJ BARREL ON LF	1	0
FORCED INTERR	BL	KB 09	14177	T4Z	52566020	12003097025C	T	4/7/2003	171!	83	9	747	VINES	VINES	3121 WROXTON	1	TF	525660201					REFURBED 50 KVA CBP CLEARED VINES ENGULFING POLE VINES TOOK OUT REF TR,	1	0
FORCED INTERR	SH	PE 04	31599	148F	54488020	32003097024E	T	4/7/2003	171!	113	1	113	LIGHTNING	LIGHTNING	4719 ARNOLD D	1	BU	544880207					replaced 25 cop with conv RPLD BAJ TR,	1	0
FORCED INTERR	HC	BL 06	10907		51533094	12003097025I	T	4/7/2003	171!	91	1	91	LIGHTNING	LIGHTNING	11578 I/S CHIMB		BU	515330980					RPLD BAJ TR;	1	0
FORCED INTERR	HC	HOC0(	11154	B22B	52523006	12003097025A	T	4/7/2003	171!	54	10	540	UNKNOWN	UNKNOWN	4314 TRAIL LAKI	1	SC	525230098	DR				REPLACE ALL CLAMP AT WH, RPLD CONN @ PL, MEK	1	0
FORCED INTERR	SH	FT 05	30401	45LJ	60538513	32003097025C	F	4/7/2003	172(	47	15	705	LIGHTNING	LIGHTNING	9403 MONTGOM	1	LF	45LJ					REF LF,	1	0
FORCED INTERR	FB	EB 05	11290	A9L	36459584	12003097025E	F	4/7/2003	172!	25	1	25	LIGHTNING	LIGHTNING	7615 HWY 60	1	LF	A9L					WEATHER, REF LF	1	0
FORCED INTERR	MP	HM 02	11014	8G7	54545334	22003097011E	T	4/7/2003	173!	202	19	3838	LIGHTNING	LIGHTNING	6815 DUMBLE R	1	BU	545453364					REPLACE 75 KVA 120/240/7200 WITH THE SAME, RPLD BAJ TR,	1	0
FORCED INTERR	KY	KT 41	22589		42599355	12003097025J	T	4/7/2003	173!	204	1	204	LIGHTNING	LIGHTNING	3158 KATY HOC		BU	425993526					REPLD LA && 50KVA TRF RPLD BAJ TR, RPLD LIGHTNING ARRESTOR,	1	0
FORCED INTERR	BL	SF 15	10436	U4E	51576130	12003097025E	F	4/7/2003	173!	79	12	948	LIGHTNING	LIGHTNING	5095 CEDAR CR	1	LF	U4E					REF LF	1	0
FORCED INTERR	CH	GP 06	40810	H89E		32003097025E	F	4/7/2003	174(	164	36	5904	LIGHTNING	LIGHTNING	2227 15TH	1	LF	H89E	BU	565790531			REPLACED 50 KVA CONV WITH SAME--REPLACED LIL--NVA ON XFMR--CONTENTS OF XFMR ON GROUND AND BUSH--NOTIFIED BOARD--UNLOADED AT CHV RPLD BAJ TR, REF TR RPLD LIGH	1	0
FORCED INTERR	SB	GE 41	21192	N42U	46619286	12003097026J	F	4/7/2003	174(	0	0	0	TRANSFORMER	TRANSFRMI	16731 GREAT G	2	LF	N42U	BU	466192262	PR		REPL 50 KVA URD DEAD FRONT W/ 50 KVA URD DEAD FRONT ALSO SPLICE PRIMARY AND SECONDARIES AND REPL ELBOWS BKX URD PR RPRD URD PR, RPLD BAJ TR (SEE CREW C	1	0
FORCED INTERR	SB	GE 41				12003097026J	F	4/7/2003	174(	259	50	12950	TRANSFORMER			2	LF	N42U						0	0
FORCED INTERR	SB	GE 41				12003097026J	F	4/7/2003	174(	259	78	20202	TRANSFORMER			2	LF	N42U						0	0
FORCED INTERR	SB	GE 41				12003097026J	F	4/7/2003	174(	410	4	1640	TRANSFORMER			2	LF	N42U						0	0
FORCED INTERR	SB	SA 48	11638	S2874	48622076	12003097026A	L	4/7/2003	175!	45	1	45	OH SEC/DR CL NI	OH SC CL-N	12702 1/2 EMME	1	DR						MADE REPAIRS TO BROKEN NEUT MID SPAN in 6 4 RUBBER COATED DROP DUE TO OLD AGE NEED TO REPLACE B/C CONN TRUCK ACCESSABLE NOTE CUST BAID HAD DAMAGE TO EQUIPME	1	0
FORCED INTERR	BL	ST 07	10230		50549204	12003097026S	T	4/7/2003	175!	202	10	2020	LIGHTNING ARRE	LTNG ARRS	6132 BEECHNU	1	SC	505492067					REPL. BUSS WORK ARRESTOR BOURREL WHILE TRIM TREES PICKED UP PRIMARY NE NEUTRAL RPLD BUSS WORK @ TR,	1	0
FORCED INTERR	BL	FD 09	10703	W7U	50545198	12003097028E	T	4/7/2003	175!	44	8	352	LIGHTNING	LIGHTNING	8810 CADAWAC	1	TF	505451981					REFURBED 25 KVA POWER T/F TAKEN OUT BY WEATHER, REF TR MEK	1	0
FORCED INTERR	BZ	FP 06	4534E	C6J	53247198	32003097026C	T	4/7/2003	181(	58	1	58	LIGHTNING	LIGHTNING	614 SOUTHFOR	1	TF	532471988					REF TR,	1	0
FORCED INTERR	BL	HT 09	10310	B55R	50559330	12003097026E	F	4/7/2003	181!	38	2	76	LIGHTNING	LIGHTNING	8535 SOUTHWE	1	LF	B55R					REFURED L F REF LF,	1	0
FORCED INTERR	SH	SP 06	30690	S15N	56534054	32003097028S	F	4/7/2003	182(	60

FORCED INTERR	MP	UN 08	10971	13AAJ	54556158	220030970142	L	4/7/2003	1941	193	1	193	FLLNG TREE IN E	TREE FLAE	4723 ARVILLA LI	1	DR					REPAIRED MID SPAN TAP RPRD DR.	1	0
FORCED INTERR	BA	TRMC	43168		66594120	320030970281	T	4/7/2003	1944	287	2	574	LIGHTNING	LIGHTNING	6219 FM 3180 RI		BU	665941209				CHANGED OUT 25CBP WITH 25CONV RPLD B4J TR.	1	0
FORCED INTERR	BL	BI 06	10084	A99A	52550091	120030970284	L	4/7/2003	1958	46	1	46	OH SEC/DR CL HI	OH SC CL-H	4403 PHIL	1	DR					RPLD CONN @ WH.	1	0
FORCED INTERR	GA	GA 03	31230	2B1	66381352	320030970285	F	4/7/2003	2012	94	1	94	BIRD	BIRD	8600 OLD CAUS	1	LF	2B1				REFUSED EAST PHASE. REF LF	1	0
FORCED INTERR	SH	EL 07	30744	W68X	57508284	320030970288	F	4/7/2003	2033	32	52	1664	LIGHTNING	LIGHTNING	11538 GANDERI	2	LF	W68X				REFUSED TP. REF TP	1	0
FORCED INTERR	HC	HOCO	11154	B22B	52523005	120030970289	T	4/7/2003	2104	285	10	2850	LIGHTNING	LIGHTNING	4322 TRAIL LAKI	1	BU	525230098	DB			REPLACED BAD TRANSFORMER INSTALLED CUT OUT RPLD B4J TR. RPLD B4J DISC-TF HOT BLOWN. RPLD LIGHTNING ARRESTOR.	1	0
FORCED INTERR	SH	CK 04	31630	45GS	59508351	320030970290	T	4/7/2003	2111	62	8	372	BU DISC OR BARI	DISC/BARRL	14906 1/2 SPACI	2	TF	595083513				REFUSED TRANSFORMER. RPLD B4J BARREL ON TR.	1	0
FORCED INTERR	GA	STWD	31025	A19M	65961811	320030970291	T	4/7/2003	2122	37	3	111	BU DISC OR BARI	DISC/BARRL	11660 COUNTY	1	TF	653681156				REF TR.	1	0
FORCED INTERR	FB	EB 05	11290	K74	37461034	120030970288	T	4/7/2003	2137	188	1	188	LIGHTNING	LIGHTNING	6730 FM 2919	1	BU	374610306				REPLACED 15 @ 25 KVA 7200/120/240 TRANS INST WLP LIGHTNING. RPLD B4J TR.	1	0
FORCED INTERR	BA	CD 04	30675		64586248	320030970296	T	4/7/2003	2230	131	1	131	LIGHTNING	LIGHTNING	3023 1/2 MASSE		DB	645862457				REPL DISC 2 LIAE. REF TR. RPLD B4J DISC-TF BLOWN. RPLD LIGHTNING ARRESTOR.	1	0
FORCED INTERR	SH	AI 08	31109	79N	60551397	320030970300	T	4/7/2003	2245	64	6	384	BU DISC OR BARI	DISC/BARRL	901 MARTHA	1	TF	605513971				REPLACED FUSE BARREL. RPLD B4J BARREL ON TR.	1	0
FORCED INTERR	SH	PA 02	30757	C92E	57540515	320030970301	T	4/7/2003	2311	37	12	444	LIGHTNING	LIGHTNING	1011 MAROBY	1	TF	575405155				REFUSED TRANSY. REF TR.	1	0
FORCED INTERR	GP	RA 41				220030980002	C	4/8/2003	0057	0	0	0	FLLNG TREE IN E	TREE FLAE	RA41 CKT LOCI		CL	RA41				NON 10% CKT IEEE TBL 8WG #213 "OHH" FOUND PINE TREE DOWN ACROSS ALL 3 PHASES AT 2108 BANQUET RD CREWS TO TEAM UP TOREMOVE TREE "OHH" ALRD 10C	1	1
FORCED INTERR	GP	RA 41	2G234			220030980002	C	4/8/2003	0057	54	1463	79002	FLLNG TREE IN E				CL	RA41					0	0
FORCED INTERR	GP	RA 41	2465A			220030980002	C	4/8/2003	0057	97	1175	113975	FLLNG TREE IN E				CL	RA41					0	0
FORCED INTERR	GP	RA 41	2041B			220030980002	C	4/8/2003	0057	108	29	3132	FLLNG TREE IN E				CL	RA41					0	0
FORCED INTERR	SH	FW 03	30436	M69I	58476585	320030980004	F	4/8/2003	0224	138	19	2622	LIGHTNING	LIGHTNING	16422 PAINT RC	2	LF	M69I	DB	584765858		REPLACED A BURN UP LIGHTNG ARRESTOR & SWITCH ON TP M 69 I - REF TP RPLD B4J DISC-TF BLOWN. RPLD LIGHTNING ARRESTOR	1	0
FORCED INTERR	HM	LW 42	20135		54657296	220030980006	T	4/8/2003	0330	88	1	88	BIRD	BIRD	15600 JOHN F K		PR	546572906				RPLD LIMITER @ TR.	1	0
FORCED INTERR	CY	KL 41	21977	11BW	47664596	220030980010	T	4/8/2003	0344	62	4	248	VINES	VINES	13715 CASABA	1	TF	476645906	PR			RM VINES. REPLACED LIMITER AND REFUSED A 50 KVA. RPLD LIMITER @ TR. REF TR. RMVD TREE&IMB OFF PR.	1	0
FORCED INTERR.	BL	UL 46	13069	16JJ	51571124	120030980003	T	4/8/2003	0433	66	10	660	VINES	VINES	8007 VALLEY FC	1	TF	515711241				REMVD VINES OFF POLE. REF TR	1	0
FORCED INTERR	SU	IM 45	12070	Y29M	47517567	120030980004	F	4/8/2003	0442	76	39	2964	TREE CLEARANC	TREE CLEAI	13931 WILDE FF	2	LF	Y29M				TRIMMED TREES OUT OF Y END OF T P. REFUSED. REF TP.	1	0
FORCED INTERR	SH	PO 05	30847	W98J	60494468	320030980006	F	4/8/2003	0500	53	46	2438	LIGHTNING ARRE	LTNG ARRS	16818 CLEAR CI	2	LF	W98J	PD			REFUSED TP W 98 J. THE TP IS A 40' ROTTEN POLE. RPL ARRESTOR WHEN REPLACE POLE. REF TP	1	0
FORCED INTERR	BL	DN 04	10553	E95L	53564411	120030980004	T	4/8/2003	0529	279	10	2790	LIGHTNING	LIGHTNING	3510 MT VERNC	1	BU	535644116				spit 100fys with 75kvs 2700/120/240 (900 ires at 30percent 75 should limit) RPLD B4J TR.	1	0
FORCED INTERR	SH	EL 09	30361	T29A	58506368	320030980020	L	4/8/2003	0541	385	1	385	STRONG WIND	WIND	950 FM 1959 #41	2	PD					CHG OUT 40 FT. T P TAKEN OUT BY STORM. RPLD PL.	1	0
FORCED INTERR	HM	AD 10	41977	C14F	54643168	220030980015	T	4/8/2003	0615	76	5	380	FLLNG TREE OUT	TREE FLOE	13914 RUSS	1	TF	546431868				CUTOUT @ WH LEFT METER #63673436 MULT 001 READING L TO R 58860 REFUSED TRANS @ 13836 GREEN RANCH DR. REF TR. TEMP DISC-LEFT MTR & DR.	1	0
FORCED INTERR	SH	EL 09				320030980022	C	4/8/2003	0630	0	0	0	ROTTEN POLE	ROTTEN PLI	EL09 CKT LOCI		CL	EL09				CREW REQUESTED POLE DOWN IN PRIMARY AT 850 FM 1958,8418 REMOVED POLE & MADE BACK HOT ~ NOTE CKT FEEDS ELMGTON FIELD AND EDC BUILDING NON 10% CKT IEEE TBL 8WG	1	1
FORCED INTERR	SH	EL 09	30151			320030980022	C	4/8/2003	0630	6	606	3636	ROTTEN POLE				CL	EL09					0	0
FORCED INTERR	RS	LV 01	30080	ZO2	57372220	320030980026	F	4/8/2003	0711	57	28	1482	UNKNOWN	UNKNOWN	532 SNUG HARE	1	LF	ZO2				FOUND 8 8 AMPS @ LF ZO2. REF LF	1	0
FORCED INTERR	HC	FD 14	10861	3KL		120030980007	F	4/8/2003	0714	168	64	10624	TREE CLEARANC	TREE CLEAI	11419 HILLCRO	1	LF	3KL	DB			TRIMMED TREES AWAY FROM SECONDARIES REPLACED 120V DISCONNECT AND REPLACED BURN OFF LOW SIDE. RPLD B4J DISC-TF BLOWN. MEK (PER NOTES - CREW OPE	1	0
FORCED INTERR	BA	MB 08	30183	52AAB	66608077	320030980025	T	4/8/2003	0715	112	2	224	LIGHTNING	LIGHTNING	1422 MAGNOLIA	1	TF	666080755				REF TR.	1	0
FORCED INTERR	SH	CG 05	30920		56538095	320030980030	T	4/8/2003	0728	185	1	185	LIGHTNING	LIGHTNING	8350 MOSLEY		TF	565380922	DB			REPLACED 3 SWITCHES AN LIGHTING ARRESTERS -- LIGHTING. RPLD B4J DISC-TF BLOWN. MEK	1	0
FORCED INTERR	SU	ME 04	20159	A19U	48573231	120030980006	L	4/8/2003	0723	81	1	81	OH SEC/DR CL HI	OH SC CL-H	802 HARVEST M	1	DR					CHANGED BURNT UP CLAMP AT WEATHERHEAD . RPLD CONN @ WH.	1	0
FORCED INTERR	BL	BR 03	14268	R6K	52545571	120030980011	L	4/8/2003	0751	68	1	68	OH SEC/DR CL HI	OH SC CL-H	3514 GRENNOC	1	DR					REPLACED BOTH LIGHTER CLAMPS AT WH FOR ST 89 CU 3W DROP NEEDS CHANGING OUT IN THE EASEMENT RPLD CONN @ WH. MEK	1	0
FORCED INTERR	BL	BR 11	12483		52540269	120030980012	T	4/8/2003	0753	90	1	90	BU DISC OR BARI	DISC/BARRL	8430 NEWCAST		TF	525402668				REPLACED A FUSE BARREL ON A POWER TRANSFORMER IN A CLOSED DELTA BANK. RPLD B4J BARREL ON TR.	1	0
FORCED INTERR	SH	DR 09	30300		56530258	320030980034	T	4/8/2003	0754	80	1	80	BU DISC OR BARI	DISC/BARRL	7509 WYNLEA		TF	565302587				REPLACED BURNED UP FUSE BARREL ON POWER POT FEEDING CLOSED DELTA BANK / NEED LIGHNING ARRESTOR REPLACED ON POWER POT FACING ROAD! TRUCK ACCESIBLE/ MAY NI	1	0
FORCED INTERR	CY	TB 04	21095	525Y	48709591	220030980020	F	4/8/2003	0759	90	5	450	VINES	VINES	FM 2920, WEST	1	LF	39LB				REFUSED TP 39LB. THE TP IS FED BY OH LF 8287 @ B E CORNER OF DONDELL & 2920. TP IS ON S W CORNER AND FEEDS CU TP 8297 8297 NOT IN FIELD. COULD NOT FIND REF TP BA	1	0
FORCED INTERR	SB	SA 48	11539	39HK	48627121	120030980016	F	4/8/2003	0811	114	2	228	STRONG WIND	WIND	6707 NORTHWI	1	LF	39HK				TOOK BLACK OUT # 2 PRIMARY AT 6707 NORTHWIND AND REFUSED MIDDLE AND BOTTOM PHASES. P4J PR-FUSE BLOWN. REF LF. MEK	1	0
FORCED INTERR	FB	BV 42				120030980022	C	4/8/2003	0827	0	0	0	FLLNG TREE IN E	TREE FLAE	2714 MILLERS F		CL	BV42				FAULT BEHIND R/C PT8 10884 OPEN & CLOSED BRKR- CREW FOUND TREE IN PRI @ 2714 MILLERS FALLS CT - ISOLATING DOWN TO 1 SECTION - CREW & TREE CREW CLEARED UP TREE	1	1
FORCED INTERR	FB	BV 42	1G459			120030980022	C	4/8/2003	0827	5	581	2905	FLLNG TREE IN E				CL	BV42					0	0
FORCED INTERR	FB	BV 42	10481			120030980022	C	4/8/2003	0827	32	1587	50784	FLLNG TREE IN E				CL	BV42					0	0
FORCED INTERR	FB	BV 42	11364			120030980022	C	4/8/2003	0827	59	435	25665	FLLNG TREE IN E				CL	BV42					0	0
FORCED INTERR	FB	BV 42	10505			120030980022	C	4/8/2003	0827	152	195	29640	FLLNG TREE IN E				CL	BV42					0	0
FORCED INTERR	FB	WR 11	1269C	B5H	31428518	120030980016	F	4/8/2003	0828	191	8	1528	LIGHTNING	LIGHTNING	FM 2614 @ CO	1	LF	B5H				LINE FUSE WENT OUT YESTERDAY DURING BAD WEATHER . REF LF	1	0
FORCED INTERR	BL	EU 09	40743	K22	52585533	220030980027	F	4/8/2003	0830	53	20	1060	BU DISC OR BARI	DISC/BARRL	MANVILLE, S OF	1	LF	K22				REMOVED VINES OFF LF DISC/ REPLACED FUSE BARREL / LEFT SERV ON NOTIFIED. RPLD B4J BARREL ON LF	1	0
FORCED INTERR	HM	RA 44	20161		52737168	320030980028	T	4/8/2003	0830	71	4	284	VINES	VINES	2215 WICKBURI		PR	527371693				RMVD VINES--RPLCD B4J LIMITER FUSE ON 50 LIGNTER-- RPLD LIMITER @ TR.	1	0
FORCED INTERR	HC	HOCO	11169	15R	51535011	120030980031	T	4/8/2003	0845	77	8	616	TREE CLEARANC	TREE CLEAI	11515 GAYMOO	1	TF	515350162				NEED TO TRIM TREES FROM OPEN WIRE SEC @ TR POLE LOC NEAR 13616 GAYMOOR ALSO NEED TO STRAIGHTEN 45 FT TR POLE NEAR THIS ADDRESS HAS BEEN QUYED OFF TO TREE BOL	1	0
FORCED INTERR	SB	SA 44	21314	X13X	48617367	120030980032	F	4/8/2003	0845	53	2	106	STRONG WIND	WIND	6400 CUNNINGH	1	LF	X13X				REF LF	1	0
FORCED INTERR	BL	SF 48	12514		51576094	120030980036	T	4/8/2003	0844	88	4	352	LIGHTNING	LIGHTNING	5035 FIELDWOC		TF	515780949				REF TR	1	0
FORCED INTERR	MP	WO 03	41837	H6F	52602317	220030980025	L	4/8/2003	0855	87	1	87	UNKNOWN	UNKNOWN	1563 HEWITT	1	DR					RPLD CONN @ WH. REBADGED DR. MEK	1	0
FORCED INTERR	HM	TWG4	20256	N36S	54696311	220030980037	F	4/8/2003	0911	119	70	8330	URD ELBOW	URD ELBOW	8307 BROOKGA	2	LF	N36S	PR			URD 8W08 8004 SERVICE ON @ 1125. REF TP MOL URD PR CORRECTED 2HUCRH	1	0
FORCED INTERR	SB	CB 01	21415	K62A	50590018	120030980052	T	4/8/2003	0911	64	5	320	SQUIRREL	SQUIRREL	9713 WARWANI	1	TF	505900189				WOLF IN PLACE. REF TR.	1	0
FORCED INTERR	GA	TIK01	30102		65386422	320030980040	T	4/8/2003	0922	173	1	173	UNKNOWN	UNKNOWN	747 TIKI DR #1		BU	653864222				REPLACED BAD 25 KVA 7200 120/240 TRANS IN OPEN DELTA BANK WITH SAME. RPLD B4J TR	1	0
FORCED INTERR	SH	AI 06	31376	18H	60551330	320030980041	F	4/8/2003	0927	43	2	86	CUST EQP RELAT	CUST RLTD	601 E 8TH	1	LF	18H				I BELIEVE CUST EQUIPMENT TRYING TO GO BAD BECAUSE OF THE WAY THIS FUSE IS BLOWING. REF LF.	1	0
FORCED INTERR	HC	IR 04	11898		53500277	120030980058	T	4/8/2003	0930	157	1	157	OH SEC/DR CL HI	OH SC CL-H	324 RILEY		BU	535002727	SC			REPLACED BAD 50 CONVENTIONAL TRANSFORMER AND BAD LIGHTNING ARRESTOR MADE REPAIRS TO BUSS WORK. RPLD B4J TR. RPRD BUSS WORK @ TR. RPLD LIGHTNING ARRESTOR.	1	0
FORCED INTERR	BL	ST 16	10231	CN7	50548296	120030980064	T	4/8/2003	0944	48	11	528	BU DISC OR BARI	DISC/BARRL	8510 ROBINDEL	1	TF	505482992				FOUND FUSE BARREL BURNT UP. REPLACED. RPLD B4J BARREL ON TR.	1	0
FORCED INTERR	SU	HY 12				120030980065	C	4/8/2003	0944	0	0	0	FLLNG TREE IN E	TREE FLAE	HY12 CKT LOCI		CL	HY12				TREE LIMB ON PRI AT 12118NALDEMAR PUC CIRCUIT SECTION 11711 TWB	1	1
FORCED INTERR	SU	HY 12	1G495			120030980065	C	4/8/2003	0944	17	355	6035	FLLNG TREE IN E				CL	HY12					0	0
FORCED INTERR	SU	HY 12	11711			120030980065	C	4/8/2003	0944	32	601	19232	FLLNG TREE IN E				CL	HY12					0	0
FORCED INTERR	BL	DN 02	10566	UG8	53574113	120030980073	F	4/8/2003	0950	42	60	2520	SQUIRREL	SQUIRREL	1110 PEDEN ST	1	LF	UG8				REFUSED NORTH PHASE OF LF UG8 NEED WILDLIFE PROTECTION & SWATCH ON 75 CBP REAR OF 1112 PEDEN EASEMENT REF LF MEK	1	0
FORCED INTERR	BA	BT 05	40137	A48T	62569228	320030980047	F	4/8/2003	1000	169	39	6591	FLLNG TREE IN E	TREE FLAE	2112 UTAH ST	1	LF	A48T	PR			PICKED UP TWO SPANS # 4 CU PRI P4J PR-FUSE BLOWN.	1	0
FORCED INTERR	SH	TE 07	31289	26PT	56505310	320030980048	T	4/8/2003	1000	82	4	248	OH SEC/DR CL HI	OH SC CL-H	3207 GLASTONI	1	SC	565053107				MADE REPAIRS TO BUSSWORK AT TRANS ON HOT LEG ROR	1	0
FORCED INTERR	FB	WR 10	11260	90W	36397325	120030980075	L	4/8/2003	1015	102	1	102	TREE CLEARANC	TREE CLEAI	4123 HIGHWAY	1	SC					CUT TREES --REPAIRED SEC NEUTRAL. RPRD SEC-1 CUST	1	0
FORCED INTERR	FB	BC 08	12887	90DB	44456475	120030980081	F	4/8/2003	1025	425	11	4675	ROTTEN POLE	ROTTEN PLI	5021 MOURNINI	1	PR	90DB	SC		PD	REPLACED 2 -35CL4 POLES W/BAME PICKED UP 2 SPANS #2 PRIMARY AND NEU WO BUTTON WAS HIT . P4J PR-FUSE NOT BLOWN B4J PR NEUT RPLD PL. RPLD GUY WIRE NO BUSCABIN	1	0
FORCED INTERR	MP	WO 03	41837	H6F	52603316	220030980046	T	4/8/2003	1022	8	8	64	SQUIRREL	SQUIRREL	1407 MARTIN	1	TF	526033169				REF TR.	1	0
FORCED INTERR	FB	CRB4E	11444	W18F	44499342	120030980106	F	4/8/2003	1022	39	44	1716	LIGHTNING	LIGHTNING	RIVEREDGE @	1	LF	W18F				MEK	1	0
FORCED INTERR	BA	HNY04	41021	X91F	62616000	320030980060	T	4/8/2003	1100	74	1	74	LIGHTNING ARRE	LTNG ARRS	3315 FIG ORCH	1	TF	626180005				REFUSED TR FUSE FEEDING BARN CAN GET LA. W TK. IF GATE IS OPEN ACROSS THE ST FROM 3320 FIG ORCHARD RD REF TR. MEK	1	0
FORCED INTERR	SH	SH 11	31404	A21S	58520139	320030980061	F	4/8/2003	1100	97	56	5432	ROTTEN POLE	ROTTEN PLI	12230 PALMCRE	1	LF	A21S	PR		PD	REFUSED LF AFTER REFRAMMING TOP OF DEADEND-BLACK SPAN POLE NEED TO REPLACE DEDEND POLE AT 12005 DUMAS--TOP OF POLE IS ROTTEN ITS A 45-2 POLE IN THE EASEMENT, R	1	0
FORCED INTERR	CY	TB 45	21044	B43C	47700401	220030980056	F	4/8/2003	1100	240	9	2160	LIGHTNING	LIGHTNING	27600 CALVERT	1	LF	B43C				REPLACED A 250 STEP DOWN WITH THE SAME. RPLD B4J TR. ROR	1	0
FORCED INTERR	SH	WE 08	30168	64EH	58551486	320030980062	F	4/8/2003	1100	38	3	114	UNKNOWN	UNKNOWN	1238 RED BLUFI	1	LF	64EH				REFUSED LF. REF LF.	1	0
FORCED INTERR	CH	PW 02	40934	H14T	57614125	320030980063	T	4/8/2003	1100	53	7	371	TREE CLEARANC	TREE CLEAI	11910 ROBERT	1	TF	578141255				REFUSE 50 CONV FT OF ABV ADDRESS TRIMMED TREE LIMBS AWAY FROM TRF REF TR	1	0
FORCED INTERR	FB	BC 09	11306	35KT	45442541	120030980102	T	4/8/2003	1100	82	3	246	LIGHTNING	LIGHTNING	5557 FM 2977	1	TF	454425414				REF B PHASE TR IN 480 V BANK---MAY HAVE TO RESTART WELLS---NO ONE AROUND. REF TR	1	0
FORCED INTERR	GA	GL 05	30483	AM1	68384257	320030980065	F	4/8/2003	1120	115	4	460	O/H PRIMARY CL	OH PR CLMF	2502 SEAWALL	1	LF	AM1	PR			REPLACED BAD DEAD END SHOE P4J PR-FUSE BLOWN.	1	0
FORCED INTERR	SH	AI 06	31376	18H	60551330	320030980067	F	4/8/2003	1122	38	2	76	CUST EQP RELAT	CUST RLTD	601 E.8TH	1	LF	18H				REFUSED MIDDLE PHASE OF THREE DIFFERENT LINE FUSES ON CUST SIDE OF PRIMARY METERING. 2 WITH 80TS. 1 WITH 80T IN EFFORT TO SEE IF PROBLEM IS CUSTOMER'S OR OURS. RE	1	0
FORCED INTERR	BA	MB 09	41439		65628094	320030980070	T	4/8/2003	1130	209	3	627	COLLISION	COLLISION	2100 N FM 585 R		BU	656280465				REPLACED 25 KVA TR. RPLD B4J TR.	1	0
FORCED INTERR	CH	UV 03	41756	JZ2	58604171	320030980071	F	4/8/2003	1131	63	1	63	CUST EQP RELAT	CUST RLTD	HL&P ROW E OF	1	LF	JZ2				REF LF	1	0
FORCED INTERR	SH	PA 03	30764	26FF	57543243	320030980072	T	4/8/2003	1133	33	8	264	SQUIRREL	SQUIRREL	2110 SPRING CI	1	TF	575432430				REFUSE TRANSF REF TR, MEK	1	0
FORCED INTERR	HC	GV 02	10825	FB4	54539341	320030980010	L	4/8/2003	1138	32	1	32	FLLNG TREE OUT	TREE FLOE	5774 BELCREST	1	SC					TRIMMED TREES / REPAIRED BROKEN NEUTRAL @ POLE / LEFT SERV ON NOTIFIED RPLD CONN @ PL. RMVD TREE,IMBS FROM DR.	1	0
FORCED INTERR	SU	STF02	12721		48514285	120030980108	T	4/8/2003	1142	44	4	176	BU DISC OR BARI	DISC/BARRL	14015 SOUTHW		TF	485142825				REPLACED FUSE BARREL CUST NOTIFIED. REF TR. RPLD B4J BARREL ON TR. MEK	1	0
FORCED INTERR	BA	CD 05	40370	RE3	63577446	320030980074	L	4/8/2003	1142	74	1	74	UNKNOWN	UNKNOWN	112 GRANTHAM	1	DR					FOUND BURNED UP HOT LEG CLAMP AT WH #40--ALL CONDUCTORS AND CLAMPS GOING BAD---REPL ALL 3 CLAMPS AT WH#40 AND LEFT OK---CUST HOT RPLD CONN @ WH.	1	0
FORCED INTERR	BL	HE 03	10670		52576594	120030980112	L	4/8/2003	1152	50	1	50	TREE CLEARANC	TREE CLEAI	6019 FLOYD		SC					MADE REPAIRS TO DROPS AT POLE/CUT TREE LIMB AWAY RPLD CONN @ PL.	1	0
FORCED INTERR	CH	CV 03	40432	W60K	59586521	320030980075	T	4/8/2003	1152	126	7	882	COLLISION	COLLISION	15522 N BRENTI	1	SC	595865214	SC			REPAIRED BUSS WORK ON 50 KVA AND CUT-OUT METER 67831528 READING 84318 CENTERPOINT POLE TRUCK HIT WIRES ELECTRICIAN ON SITE TO FIX WEATHERHEAD LEFT CUT OUT AT	1	0
FORCED INTERR.	BL	HE 09	11556	2EZ	52579271	120030980115	F	4/8/2003	1200	82	9	738	TREE CLEARANC	TREE CLEAI	2156 TROON	1	LF	2EZ				REFUSED MIDDLE AND NORTH PHASE OF THE LINE FUSE TAKE OUT BY TREES @ 2132 TROON NEED TO TRIM A LARGE OAK TREE OUT OF THE PRIMARY REF LF MEK	1	0
FORCED INTERR	MP	GG 09	40984	C44Z	55556000	320030980062	F	4/8/2003	1200	61	69	4209	TREE CLEARANC	TREE CLEAI	3034 ROE	1	LF	C44Z				2 OUT SIDE PHASES BLOWN, FOUND TREES IN REAR OF 3048 ROE THAT WIND BLEW LIMBS ACROSS PHASES AND BLEW FUSES WAS BURNT IN CLEAR. REFUSED BUT NEED TRIMMING ASAP	1	0
FORCED INTERR	CY	TB 45	21046	43GQ		220030980063	F	4/8/2003	1211	229	3	687	FALLING DEAD TI	TR FL/DEAD	23303 HOLLY CF	1	LF	43GQ	PR		SC	REPLACE 60KD PIN AND 16" ARM. PICKED TWO SPANS OF #2 PRIMARY AND STATIC ROTTEN TREE FELL. P4J PR-FUSE BLOWN. REF LF	1	0
FORCED INTERR	SH	CC 03	30182	176F	54512111	320030980116	L	4/8/2003	1222	95	1	95	TREE CLEARANC	TREE CLEAI	3630 VAN METE	1	DR					REPLACED BAD RUBBER COATED DROPS WITH #4 TW AL NEO DROPS. RPLD DR.	1	0
FORCED INTERR	BL	UL 48	10378		51563327	120030980120	T	4/8/2003	1233	73	14	1022	TREE CLEARANC	TREE CLEAI	5722 VAL VERDI		SC	515633270				MADE REPAIRS TO A 40 TFMR LEAD ON A 75KVA TFMR AND TRIMMED TREE OUT OF POLE TFMR AN SEC RPRD BUSS WORK @ TR. RMVD TREE,IMBS OFF PL. RMVD TREE,IMBS FROM DR.	1	0
FORCED INTERR	GP	AD 04	40079	25FN	52639290	220030980068	T	4/8/2003	1240	61	7	427	TREE CLEARANC	TREE CLEAI	423 FRAZER LN	1	TF	525302047				TRIMMED TREES OUT OF OPEN WIRE SEC. REF TR.	1	0
FORCED INTERR	CY	WL 41	21160	41AB	40892518	220030980071	T	4/8/2003	1257	98	1	98	TREE CLEARANC	TREE CLEAI	2708 BRAZEAL S	1	TF	408925187	PR			TRIMMED TREE. RPLD LIMITER @ TR. REF TR. ROR	1	0
FORCED INTERR	CH	NM 03	41521	M59N	57586252	320030980086	F	4/8/2003	1254	41	10	410	BU DISC OR BARI	DISC/BARRL	1008 FEDERAL	1	LF	M59N				BARRELL FELL OPEN. REF LF	1	0
FORCED INTERR	SH	TE 05	31087	77PT	56504551	320030980088	T	4/8/2003	1311	47	1	47	LIGHTNING	LIGHTNING	8503 1/2 S SAM	1	TF	565045518				referred this -- replacedburned up fuse burnt RPLD B4J BARREL ON TR.	1	0
FORCED INTERR	CY	PI 44	20110	78LV	46735484	220030980074	F	4/8/2003	1316	156	14	2184	VINES	VINES	12527 PATRIDG	1	LF	78LV	TF	467364332		CLEARED VINES REFUSED LF 78LV, REFUSED TRANSFORMER@ 12807 WOODLAKE IN CYPRESS # C. REF LF REF TR.	1	0
FORCED INTERR	MP	MP 07	41387	E42C	55565437	320030980076	T	4/8/2003	1325	36	15	540	UNKNOWN	UNKNOWN	206 WAYSIDE	1	TF	555654376				NO 3 PHASE, CUST NOT HERE. TALKED TO BY PHONE. REFUSED 25 KVA POWER AND HE WILL COME BY LATER TO SEE IF BACK ON. SWITCH BOX INSIDE AND GATE LOCKED REF TR	1	0
FORCED INTERR	HC	FD 12	10867	R19F	50525472	120030980127	T	4/8/2003	1341	301	6	1806	UNKNOWN	UNKNOWN	7715 MOONDAN	2	SC	505254726				RUN 200' SEC BYPASS SEC DIRECT BURIED INST SEC BYPASS MBO TO B/C TO MAKE REPAIRS NO BUSCABING NEEDED MGU	1	0
FORCED INTERR	GP	THW4	20147		48648906	220030980096	T	4/8/2003	1343	222	6	1332	TREE CLEARANC	TREE CLEAI	10308 SADDLEH		PR	486490064	DB			CLEARED TREE FROM TRANSFORMER REPL LIMITER & DISCONNECT RPLD LIMITER @ TR REF TR. RPLD B4J DISC-TF BLOWN.	1	0
FORCED INTERR	FB	RS 04	11401	W98T	43475525	120030980132	T	4/8/2003	1354	31	3	93	O/H PRIMARY CL	OH PR CLMF	2623 1ST	1	TF	434755290				REF E PHASE OF LF---FEEDS POWER POT IN OPEN DELTA BANK

FORCED INTERR	GP	AD 04	40069		53635151	220030980104	T	4/8/2003	1641	137	8	1096	OH SEC/DR CL HI	OH SC CL-H	811 HILL RD A		SC	536351579											
FORCED INTERR	HC	HM 06	11037	WF9	54547159	120030980182	T	4/8/2003	1701	83	11	913	SQUIRREL	SQUIRREL	5309 BURMA	1	TF	545471993											
FORCED INTERR	CH	GP 07	40820	RA8	57561561	320030980110	T	4/8/2003	1712	60	9	540	TREE CLEARANC	TREE CLEAR	1710 10TH	1	TF	575615613											
FORCED INTERR	FB	OR 02	11228	A4M	38454223	120030980173	T	4/8/2003	1801	49	1	49	BU DISC OR BARI	DISC/BARRL	13025 BATTLE F	1	TF	384542239											
FORCED INTERR	MP	GG 07	40978	P8D	55548269	220030980116	T	4/8/2003	1818	46	3	138	UNKNOWN	UNKNOWN	5738 TELEPHONE	1	TF	555482653											
FORCED INTERR	CY	TB 45	21044	B43C	46709559	220030980117	T	4/8/2003	1822	64	1	64	BU DISC OR BARI	DISC/BARRL	15141 TREICHEL	1	TF	467095984											
FORCED INTERR	SB	ME 03	21591	N18M	47575591	120030980177	F	4/8/2003	1848	113	19	2147	VINES	VINES	803 WALKWOOD	2	LF	N18M	PR										
FORCED INTERR	MP	BH 04	40285	U81U	54578313	220030980125	F	4/8/2003	1904	46	8	276	UNKNOWN	UNKNOWN	3403 NAVIGATIO	1	LF	U81U											
FORCED INTERR	GP	KL 42	21935	PS2L	48670155	220030980124	T	4/8/2003	1903	41	5	205	VINES	VINES	12202 CHRISTY	1	TF	486701531											
FORCED INTERR	GP	AD 04	40069		53635151	220030980127	T	4/8/2003	1918	50	8	400	OH SEC/DR CL HI	OH SC CL-H	811 HILL RD A		SC	536351579											
FORCED INTERR	GA	GA 09	31226	M9L	68370525	320030980120	L	4/8/2003	2000	60	1	60	TREE CLEARANC	TREE CLEAR	2714 43RD ST G	1	DR												
FORCED INTERR	SH	CC 04	30173	T94	54529259	320030980122	F	4/8/2003	2050	42	3	126	BU DISC OR BARI	DISC/BARRL	5610 DENORON	1	LF	T94											
FORCED INTERR	BL	KB 20	10139	7PP	52558466	120030980183	T	4/8/2003	2120	51	10	510	LIGHTNING ARRE	LTNG ARRS	2518 RICE B	1	TF	525584605											
FORCED INTERR	BA	MB 08	41421	58MM	65604573	320030980123	F	4/8/2003	2148	57	1	57	UNKNOWN	UNKNOWN	10600 BLK OF L	1	LF	58MM											
FORCED INTERR	SH	DE 02	30030	K97G	59548403	320030980124	F	4/8/2003	2220	46	58	2668	LIGHTNING	LIGHTNING	1010 MARSHALL	2	LF	K97G											
FORCED INTERR	SH	DE 02	30030	K97G	59547459	320030980125	F	4/8/2003	2301	48	56	2784	ANTS	ANTS	2513 HENDERSO	2	LF	K97G	PR										
FORCED INTERR	MP	BH 04	40285	U81U	54578313	220030980141	T	4/8/2003	2351	117	4	468	STRONG WIND	WIND	3401 NAVIGATIO	1	PR	545783131											
FORCED INTERR	SH	HG 06	41055		58544414	320030980127	T	4/8/2003	2354	68	21	1386	UNKNOWN	UNKNOWN	8250 PARK PL#	1	TF	585444144											
FORCED INTERR	CH	AD 02	22889	56U	54624573	320030990000	F	4/9/2003	0030	255	63	16065	FLLNG TREE IN E	TREE FLIE	2707 BREA CRE	1	LF	56U				PR							
FORCED INTERR	CH	NM 05	41510	26ES	57589414	320030990000	F	4/9/2003	0157	194	36	6984	URD ELBOW	URD ELBOW	794 NORMANDY	2	LF	26ES	PR										
FORCED INTERR.	GP	WF 05				220030990001	C	4/9/2003	0320	0	0	0	FLLNG TREE IN E	TREE FLIE	903 OLD MILL		CL	WF05											
FORCED INTERR	GP	WF 05	2G292			220030990001	C	4/9/2003	0320	65	979	63635	FLLNG TREE IN E				CL	WF05											
FORCED INTERR	FB	WR 10	11180	ROS	38415466	120030990005	T	4/9/2003	0422	131	1	131	O/H PRIMARY CL	OH PR CLMB	6816 COUNTY R	1	PR	384154698											
FORCED INTERR	BL	ST 03	13519	1K7	50547511	120030990007	T	4/9/2003	0505	114	9	1026	OH SEC/DR CL HI	OH SC CL-H	7019 NEFF	1	SC	505475115											
FORCED INTERR	GP	WF 02	20376	S83E	52706168	320030990007	F	4/9/2003	0505	78	9	684	STRONG WIND	WIND	24500 HARDY R	1	LF	S83E											
FORCED INTERR	MP	GG 06	10951	G90W	55540222	120030990010	L	4/9/2003	0544	86	1	86	TREE CLEARANC	TREE CLEAR	6851 CRESTMO	1	SC												
FORCED INTERR	SB	ADK 43	22145	86JQ	49613065	120030990011	F	4/9/2003	0600	71	1	71	OTHER	PULLD FUSE	TANNER & CRA	1	LF	86JQ											
FORCED INTERR	RS	RZ 01	14197	49GK	52424321	320030990012	T	4/9/2003	0611	229	1	229	LIGHTNING	LIGHTNING	1938 COUNTY R	1	BU	524243210											
FORCED INTERR	CY	PI 41	2436A	S22Y		220030990006	F	4/9/2003	0641	117	21	2457	FLLNG TREE OUT	TREE FL/OE	30859 CHEROKI	1	LF	S22Y											
FORCED INTERR	GP	FR 42	2B138	61AEH	50643252	220030990010	F	4/9/2003	0642	48	14	672	COLLISION	COLLISION	TAYLAR AT MILL	1	LF	61AEH											
FORCED INTERR	FB	BC 08	12880	D91	43469246	120030990017	T	4/9/2003	0701	68	1	68	TREE CLEARANC	TREE CLEAR	4842 FM 2218	1	SC	434692409											
FORCED INTERR	BL	UL 49	10343	75U	51563254	120030990020	T	4/9/2003	0722	232	4	928	TREE CLEARANC	TREE CLEAR	5710 FAIRDALE	1	PR	515632542											
FORCED INTERR	HC	HOCO	11163		51537181	120030990021	L	4/9/2003	0724	86	1	86	TREE CLEARANC	TREE CLEAR	11046 WAXWIN		SC												
FORCED INTERR	HC	FD 03	10846		51532400	120030990022	L	4/9/2003	0746	89	1	89	OH SEC/DR CL HI	OH SC CL-H	5711 BRAESHEA		SC												
FORCED INTERR.	HC	HM 05	11032	40LH	54534225	120030990023	T	4/9/2003	0800	180	5	900	LIGHTNING ARRE	LTNG ARRS	4730 LARKSPUR	1	BU	545342296											
FORCED INTERR	BA	LP 01	41651	Y10G	62544444	320030990020	T	4/9/2003	0821	109	1	109	OH SEC/DR CL HI	OH SC CL-H	400 N L ST	1	SC	625444441											
FORCED INTERR	SH	SP 02	30969	15KH	58530654	320030990021	T	4/9/2003	0841	54	1	54	LIGHTNING ARRE	LTNG ARRS	2859 WESTSIDE	1	TF	585315045											
FORCED INTERR	MP	BY 09	40199		54600599	220030990015	T	4/9/2003	0844	49	3	147	TREE CLEARANC	TREE CLEAR	8615 IRVINGTON	1	TF	546005249											
FORCED INTERR	GP	AD 01	22872	Y73Z	53464645	220030990016	T	4/9/2003	0848	36	2	78	BU DISC OR BARI	DISC/BARRL	14802 WILLIS	1	TF	536454628											
FORCED INTERR	KY	WA 42	1206J	62AAC		120030990022	F	4/9/2003	0850	102	19	1938	UNKNOWN	UNKNOWN	7021 FM 1489	1	LF	62AAC											
FORCED INTERR	GP	NB 45	20219	62AK	53659277	220030990015	F	4/9/2003	0900	0	0	0	UNKNOWN	UNKNOWN	1906 JEFFERS	2	LF	62AK	BU	536592787									
FORCED INTERR	GP	NB 45				220030990016	F	4/9/2003	0900	226	10	2260	UNKNOWN			2	LF	62AK											
FORCED INTERR	GP	NB 45				220030990015	F	4/9/2003	0900	454	15	6810	UNKNOWN			2	LF	62AK											
FORCED INTERR	BL	DV 01	10612	G2H	50566034	120030990033	T	4/9/2003	0918	47	8	376	SQUIRREL	SQUIRREL	7918 SKYLINE	1	TF	505660345											
FORCED INTERR	GA	GA 02	31184	51SC	67387398	320030990032	T	4/9/2003	0925	116	7	812	UNKNOWN	UNKNOWN	4527 BROADWA	1	TF	673873862											
FORCED INTERR	CH	BY 05	40180	E3D	54614577	320030990035	F	4/9/2003	0925	232	84	19488	O/H PRIMARY CL	OH PR CLMB	10409 RAYMONI	1	LF	E3D	PR				SC						
FORCED INTERR	BZ	BZ 05	35178	HW2	50242166	320030990036	T	4/9/2003	0940	103	2	206	STRONG WIND	WIND	2314 HINKLE FE	1	PR	502421603											
FORCED INTERR.	GP	LK 03	41292		52619500	320030990020	T	4/9/2003	0944	44	11	484	BIRD	BIRD	617 W RITTENH	1	TF	526195098											
FORCED INTERR	MP	AN 04	40022	M5N	53596411	220030990027	T	4/9/2003	0944	58	3	174	OH SEC/DR CL HI	OH SC CL-H	2709 AIRLINE DI	1	SC	535964199											
FORCED INTERR	SH	SP 01	30951	2LZ	58543073	320030990038	T	4/9/2003	0952	41	8	246	UNKNOWN	UNKNOWN	2708 DEWBERR	1	TF	585430735											
FORCED INTERR	HC	IR 04	11898		53500277	120030990046	T	4/9/2003	1010	75	1	75	OVERLOAD	OVERLOAD	324 RILEY		TF	535002727											
FORCED INTERR	HC	BR 09	10811	5F5	52541020	120030990047	T	4/9/2003	1016	39	6	234	SQUIRREL	SQUIRREL	4303 LEMAC	1	TF	525410202											
FORCED INTERR	MP	GG 07	40977	S3D	55547494	220030990033	F	4/9/2003	1022	39	56	2184	SQUIRREL	SQUIRREL	4917 PLUM	1	LF	S3D											
FORCED INTERR	BL	GT 08	41892	ATB	53565415	120030990055	L	4/9/2003	1042	53	1	53	SQUIRREL	SQUIRREL	815 HAWTHORN	1	DR												
FORCED INTERR.	MP	UN 01	30544	76DU	55541210	120030990056	T	4/9/2003	1044	36	1	36	BU DISC OR BARI	DISC/BARRL	8603 KIRBYVILLE	1	TF	555412104											
FORCED INTERR	GA	KM 07	30605	B33	63471334	320030990047	T	4/9/2003	1055	67	2	134	VINES	VINES	3230 CHARLES	1	TF	634713347											
FORCED INTERR.	BL	SF 42	12449	E78S	51574384	120030990061	T	4/9/2003	1100	181	8	1448	TREE CLEARANC	TREE CLEAR	5441 TUPPER L	1	TF	515743842											
FORCED INTERR	GP	BA 43	22073		50655304	220030990036	T	4/9/2003	1117	100	1	100	BIRD	BIRD	11103 CANYON		PR	506553041											
FORCED INTERR	SH	TE 06	3577C		56491148	320030990051	L	4/9/2003	1123	45	1	45	OH SEC/DR CL HI	OH SC CL-H	2518 S SACRAM		DR												
FORCED INTERR	SH	CC 01	30176	65JM	54525456	320030990056	L	4/9/2003	1138	77	1	77	OH SEC/DR CL HI	OH SC CL-H	5026 PARADISE	1	MT												
FORCED INTERR.	HC	MV 02	14215	W533	53436188	320030990056	T	4/9/2003	1140	42	1	42	OH SEC/DR CL HI	OH SC CL-H	11221 COUNTY	1	SC	534361805											
FORCED INTERR.	GA	KM 05	41211	3NA	63513134	320030990065	F	4/9/2003	1151	39	25	975	UNKNOWN	UNKNOWN	4727 BLAND ST	1	LF	3NA											
FORCED INTERR	GA	GA 09	31189	B3K	67387198	320030990062	L	4/9/2003	1152	274	1	274	OH SEC/DR CL HI	OH SC CL-H	4817 AVENUE P	1	DR		SC										
FORCED INTERR	BA	AT 41	41478	K43Z	60667127	320030990065	L	4/9/2003	1152	62	1	62	CONTRACTOR-IN	CON-NT HLP	102 ROSE ELFE	1	DR												
FORCED INTERR	CH	CV 01	40422	47GU	58595553	320030990066	L	4/9/2003	1211	215	1	215	COLLISION	COLLISION	13733 EAGLE PI	1	SC		PD										
FORCED INTERR	GA	AL 06	30035	6Z2	60424023	320030990071	F	4/9/2003	1221	32	14	448	UNKNOWN	UNKNOWN	3806 PEACK	1	LF	6Z2											
FORCED INTERR	CY	CYF 42	22025	71FE	46638015	220030990044	F	4/9/2003	1231	83	60	4980	LIGHTNING ARRE	LTNG ARRS	7618 FIELDSTOI	2	LF	71FE											
FORCED INTERR	FB	OR 02	11301	DK1	40468015	120030990072	T	4/9/2003	1258	30	6	180	BU DISC OR BARI	DISC/BARRL	7414 AVENUE A	1	TF	404680153											
FORCED INTERR.	BA	TRMG	4101C		66540259	320030990080	T	4/9/2003	1311	81	2	162	UNKNOWN	UNKNOWN	8822 OCEAN DR		TF	665402597											
FORCED INTERR	BL	SF 47	14124	J47C	51576394	120030990075	T	4/9/2003	1322	69	2	138	COLLISION	COLLISION	516 S POST OAI	2	TF	515763947											
FORCED INTERR	GA	AL 10	30043	S5J	61404307	320030990085	F	4/9/2003	1322	47	12	564	UNKNOWN	UNKNOWN	29TH @ FM 646	1	LF	S5J											
FORCED INTERR	BL	ST 08	10223	A26B	51542099	120030990075	T	4/9/2003	1331	51	6	306	SQUIRREL	SQUIRREL	5471 KULDELL	1	TF	515420907											
FORCED INTERR	SB	DH 04				120030990083	C	4/9/2003	1339	9	2092	18828	CONTRACTOR (H	CON-HLP	DH04 CKT LOC		CL	DH04											
FORCED INTERR	GA	KM 07	30605	B33	63471334	320030990085	T	4/9/2003	1339	53	2	126	TREE CLEARANC	TREE CLEAR	3228 CHARLES	1	TF	634713347											
FORCED INTERR	BA	LP 05	41835	8QLT	62532534	320030990081	L	4/9/2003	1341	37	1	37	FLLNG TREE IN E	TREE FLIE	112 12TH ST	1	DR												
FORCED INTERR.	FB	BC 09	11306	35KT	45442541	120030990086	T	4/9/2003	1342	82	3	246	O/H PRIMARY CL	OH PR CLMB	5557 FM 2077	1	TF	454425414											
FORCED INTERR	CH	LY 42	4706C	37JN	60592566	320030990087	T	4/9/2003	1348	55	6	330	UNKNOWN	UNKNOWN	16404 WOOD #1	1	SC	605925682											
FORCED INTERR	HC	MV 01	14208	86B		120030990096	F	4/9/2003	1400	52	74	3848	SQUIRREL	SQUIRREL	8919 ALABAMA	1	LF	H30F											
FORCED INTERR	GP	RU 01	41645	LE3	53621093	220030990054	L	4/9/2003	1421	140	1	140	FLLNG TREE OUT	TREE FL/OE	114 W RITTENH	1	DR												
FORCED INTERR	SB	DH 05	21532	F83	51610191	120030990105	L	4/9/2003	1431	83	1	83	SEC COND OR DI	SECONDARY	6518 CASTLEBA	1	SC												
FORCED INTERR	SU	CE 06	11977	48BD	48531510	120030990107	F	4/9/2003	1435	75	61	4575	TREE CLEARANC	TREE CLEAR	9330 SYNOTT #-	2	LF	48BD											
FORCED INTERR.	GP	AD 04	40069	NO8	53633188	220030990057	L	4/9/2003	1437	53	1	53	OH SEC/DR CL HI	OH SC CL-H	13610 COURRE	1	DR												
FORCED INTERR	CH	NM 01	41504	7KZ	58582381	320030990092	T	4/9/2003	1437	37	4	148	SQUIRREL	SQUIRREL	13222 BERWICK	1	TF	585823810											
FORCED INTERR	FB	DA 04	1186G	40JC	48418081	120030990110	T	4/9/2003	1446	91	1	91	O/H PRIMARY CL	OH PR CLMB	21901 FM 762	1	TF	484180815											
FORCED INTERR	SH	CC 04	30525	40PC	55521270	320030990093	T	4/9/2003	1446	172	1	172	UNKNOWN	UNKNOWN	5950 SELINSKY	1	BU	555212707											
FORCED INTERR	SU	CE 07	12009	S14V	48530553	120030990111	T	4/9/2003	1445	80	8	640	TREE CLEARANC	TREE CLEAR	8314 BARONSM	2	TF	485305534											
FORCED INTERR	GP	BA 03	21289	17CN	50663320	220030990054	F	4/9/2003	1459	178	1	178	SQUIRREL	SQUIRREL	5835 FM 1960W	1	LF	17CN	TF	506633208									
FORCED INTERR	HC	KN 04	14074		53530315	120030990116	T	4/9/2003	1459	67	3	201	CUST EQP RELA	CUST RLTD	1550 HOLMES #		TF	535303153	DR										
FORCED INTERR	CY	WL 42	21182		39699376	220030990065	T	4/9/2003	1459	71	3	213	TREE CLEARANC	TREE CLEAR	41207 OLD HEM		TF	396993788											
FORCED INTERR	HM	LW 44	20853	93HA	56666117	220030990067	L	4/9/2003	1516	41	1	41	OTHER	OTHER	1003 ATASCOCI	1	PD												
FORCED INTERR.	SU	CE 06	11977	S13V	48530576	120030990121	F	4/9/2003	1511	50	26	1300	TREE CLEARANC	TREE CLEAR	9239 BOLLINGB	2	LF	S13V											
FORCED INTERR	SB	BM 05	21497	A76N	48586146	120030990123	F	4/9/2003	1518	80	70	4200	FLLNG TREE OUT	TREE FL/OE	13935 BRITOAK	1	PR	A76N											
FORCED INTERR	BZ	VL 01	31119	96L	54246466	320030990102	L	4/9/2003	1533	86	1	86	OH SEC/DR CL HI	OH SC CL-H	1811 N AVENUE	1	DR		SC										
FORCED INTERR	SU	IM 48	12120	U26L	47519428	120030990127	F	4/9/2003	1555	88	57	5016	TREE CLEARANC	TREE CLEAR	614 ROZELLE	2	LF	U26L											
FORCED INTERR	BL	GN 10	10630	1J	52557235	120030990132	T	4/9/2003	1605	52	5	260	UNKNOWN	UNKNOWN	8443 BROMPTO	1	TF	525572339											
FORCED INTERR	CH	BY 04	40181	E50M	54626041	320030990117	L	4/9/2003	1605	150	1	150	OH SEC/DR CL NI	OH SC CL-N	10601 FOY	1	SC												
FORCED INTERR	HC	ST 10	10248	KC2	51546399	120030990138	T	4/9/2003	1621	177	9	1593	UNKNOWN	UNKNOWN	5003 MIMOSA D	1	TF	515463902											
FORCED INTERR	CH	UV 08	41777	Y67S	58614285	320030990113	L	4/9/2003	1640	55	1	55	OTHER	OTHER	14001 FOREST	1	PD												
FORCED INTERR	SH	HA 03	30558	F77Y	57505452	320030990114	L	4/9/2003	1647	41	1	41	TREE CLEARANC	TREE CLEAR	10915 SAGEMEA	1	SC												
FORCED INTERR	SU	BAR 42	11855	43MQ	47542388	120030990138	T	4/9/2003	1651	120	8	960	UNKNOWN	UNKNOWN	7627 LAS FLORE	2	TF	475423850											
FORCED INTERR	GP	RU 05	41672	R5A	53624334	220030990077	T	4/9/2003	1655	63	3	189	BU DISC OR BARI	DISC/BARRL	8009 AIRLINE DI	1	TF	536243343											
FORCED INTERR	GP	LK 07	41298		52625043	220030990086	L	4/9/2003	1716	176	1	176	OH SEC/DR CL HI	OH SC CL-H	897 W LITTLE Y		SC		DR										
FORCED INTERR	GP	GZ 44	2H145	W57G	51653033	220030990081	F	4/9/2003	1726	0	0	0	UNKNOWN	UNKNOWN	3451 FOUNTAIN	2	LF	W57G	BU	516530845	PR								
FORCED INTERR	GP	GZ 44				220030990081	F	4/9/2003	1726	167	36	6012	UNKNOWN			2	LF	W57G											
FORCED INTERR	GP	GZ 44				220030990081	F	4/9/2003	1726	167	25	4175	UNKNOWN			2	LF	W57G											
FORCED INTERR	GP	GZ 44				220030990081	F	4/9/2003	1726	327	7	2289	UNKNOWN			2	LF	W57G											
FORCED INTERR	CH	GW 06	40903	J78S	56611591	320030990121	F	4/9/2003	1728	119	24	2856	UNKNOWN	UNKNOWN	8229 CADDO RE	1	LF	J78S	PR										
FORCED INTERR	HC	AR 41				120030990170	C	4/9/2003	1730	0	0	0	COLLISION	COLLISION	FM 521 - 10 SP S		CL	AR41	PD										
FORCED INTERR	HC	AR 41	10923			120030990170	C	4/9/2003	1730	8	744	5952	COLLISION				CL	AR41											
FORCED INTERR.	RS	RZ 01	10923			120030990170	C	4/9/2003	1730	8	3	24	COLLISION				CL	AR41											
FORCED INTERR	HC	AR 41	11609			120030990170	C	4/9/2003	1730	48	14	672	COLLISION				CL	AR41											
FORCED INTERR	HC	AR 41	10007			120030990170	C	4/9/2003	1730	109	89	9701	COLLISION				CL	AR41											
FORCED INTERR	KY	GE 42	22532	53CA	46610599	120030990146	L	4/9/2003	1741	177	1	177	URD DROPS (HL8	URD DR-HLF	6511 AMBERFIE	2	SC												
FORCED INTERR	HC	AM 03	10720	DW1	53512428	120030990154	L	4/9/2003	1755	206	1	206	HUMAN ERROR	HUMN ERR	12642 CHISWICI	1	SC												
FORCED INTERR	BL	BR 03	10462	WA9	52542377	120030990155	T	4/9/2003	1755	80	12	960	SQUIRREL	SQUIRREL	4035 FALKIRK LI	1	TF	525423739											
FORCED INTERR	SH	SP 08	30990	31EH	58537052	320030990138	F	4/9/2003	1911	109	58	6322	UNKNOWN	UNKNOWN	4007 KARANKA	2	LF	31EH											

REPAIRED CLAMPS AT POLE 818 HILL RD., RPRD SEC CONN @ PL-1 CUST																													
REF TR.																													
NEED TREETRIM IN REAR GETTING INTO PRIMARY AND TRANSFORMER REPL BURNED UP BARREL TRIM SOME OF TREE ASAP!! PRIMARY ALSO FEEDS SCHOOL. REF TR, RPLD BU BARREL C																													
REFUSED 16 KVA TRANSFORMER DUE TO BROKEN FUSE AT THE FUSE BARREL REMOVED THE TIE BRING ON THE FUSE BARREL TO PREVENT FUTHER OUTAGES DUE TO BROKEN FUSE																													
REF TR, NO SUBCASING NEEDED ... MOJ																													
RPLD BU BARREL ON TR.																													
REF TR; RPRD URD PR.																													
REFUSED MIDDLE LF; REF LF;																													
REF TR.																													
REWORKED SECONDARIES ON SECOND POLE FROM TRANSFORMER; RPRD CONN @ TR.																													
REPLACED ALL CONN. AND REPAIRED DROPS AT WH DUE TO TREE, RPRD DR.																													
REPLACED FUSE BARRLE. RPLD BU BARREL ON LF.																													
NORTH POWER POT WILL NEED LIGHTING ARRESTOR REPLACED AT BERV CENER CONN WILL NEED PLANED OUTAGE, REF TR; MSG SENT TO B/C TLA																													
RPLD BU BARREL ON LF, REF LF BRB																													
PREVIOUS WEATHER, REF TP;																													
REP ELBOW PNT #32 1014 MARSHALL, REF TP; BRB																													
REPLACED BURNT OFF HIGHSIDE ON XFMR BANK. RPLD B/O PRI JUMP-TF NOT BLOWN.																													
REFUSED A 200/200/200/240 TRANS, REF TR.																													
REF LF, PAJ PR-FUSE BLOWN RPRD TREE&WIR OFF PR; BAB																													
CLEANED ELBOW & CHANGED PROBE IN TRANS # 2 ON URD B/O 8008, REF TP; RPRD URD PR.																													
CREW REMOVED TREE OFF PRIMARY IN REAR OF 803 OLD MILL. B/O 231 10% CIRCUIT SECTION 20633 978 CUSTOMERS ELN/OHH																													
REPLACED PRIMARY HOT LINE CLAMP ON ON TRANSFORMER BRE																													
MADE REPAIRS TO LIGHTER LEG CT ON TRANS. RPRD BUSS WORK @ TR.																													
REF LF;																													
REPL CONN @ POLE NEED TO STRAIGHTEN 40FT POLE, RPLD SEC CONN @ PL-1 CUST BJH																													
REPLACED PULLED FUSE IN LF 86JQ ON A PHASE BRB																													
REPLACED 35C2P WIZECONN, RPLD BU TR.																													
WALKED OUT AND REFUSED LF - S22Y LOOKED LIKE TREE FELL ON MEADOW EDGE, REF LF																													
RE

FORCED INTERR	CH	LY 41	41994	T27X	5962623	320030990141	F	4/9/2003	194	69	2	138	UNKNOWN	UNKNOWN	10521 SHELDON	1	LF	T27X						REPL BARREL ON LF AND RESET M750, REF LF: RPLD BAJ BARREL ON LF;	1	0
FORCED INTERR	BL	FD 09	10704	B48A	5054631	120030990172	L	4/9/2003	201	155	1	155	TREE CLEARANC	TREE CLEAR	7122 TROULON	1	SC							MADEREPAIRS TO HOTLEG AT POLE DUE TO TREE LIMB ALSO TRIMMED TREE: RPRD CONN @ PL.	1	0
FORCED INTERR	BL	ST 13	10203	PB4	5054958	120030990173	L	4/9/2003	202	67	1	67	TREE CLEARANC	TREE CLEAR	6414 ROWAN LN	1	SC							REPAIRED CONNECTION AT POLE DUE TO TREE RUBBING IT LOSE WILL TURN IN FOR TREE TRIMMING: RPLD CONN @ PL.	1	0
FORCED INTERR	GA	GL 06	30491	S9G	6838752	320030990144	T	4/9/2003	205	48	15	720	FOREIGN MATER	FRGN MATR	1216 AVENUE M	1	SC	683875296						repaired #2cu 3/w secondary RPRD SEC->1 CUST	1	0
FORCED INTERR	SH	HG 06	41055		5654441	320030990145	T	4/9/2003	205	35	21	735	UNKNOWN	UNKNOWN	8250 PARK PL #		TF	565444144						REFUSED TRANNY, REF TR;	1	0
FORCED INTERR.	SU	BAR46	11902	S70Q	4755120	120030990175	T	4/9/2003	210	76	11	836	HUMAN ERROR	HUMN ERRO	3806 GREEN CR	2	TF	475512062	MT					REST 50KVA 18.9 120/240 URD TRANS RESET TR, RPLD MTR,	1	0
FORCED INTERR.	GP	DH 09	40594	X16G	5160756	220030990096	F	4/9/2003	210	94	4	376	COLLISION	COLLISION	PINEMONT, E O	1	LF	X16G						REFUSED 2 PHASES OF 3 PHASE LF X-16-G 65T POLE BUMPED BY VEHICLE-POLE OKAY_ REF LF;	1	0
FORCED INTERR.	MP	AN 05	40030	A65U	5361205	220030990097	T	4/9/2003	214	57	7	399	BIRD	BIRD	213 1/2 E BURR	1	TF	536120531						REFUSED A 25 KVA 7200 120 240 V POWER TRANSFORMER; REF TR;	1	0
FORCED INTERR	CH	LY 41	41321	S1704	5961508	320030990146	T	4/9/2003	215	57	2	114	OH SEC/DR CL H	OH SC CL-H	18026 1/2 MILLE	1	SC	596150858						repaired burned up sec lead at trans: RPRD SEC CONN @ PL->1 CUST	1	0
FORCED INTERR	GA	STW0	31424	8CD	6433044	320030990149	T	4/9/2003	221	14	8	112	UNKNOWN	UNKNOWN	18619 HENRY M	1	TF	643304478						refused 25kva trans. REF TR.	1	0
FORCED INTERR.	MP	BG 02	40248	WH1	5355849	220030990100	L	4/9/2003	221	70	1	70	OH SEC/DR CL H	OH SC CL-H	2531 BINZ	1	DR							CHG OUT BURN UP CLAMP AT THE WH., RPLD CONN @ WH; RETAGGED DR.	1	0
FORCED INTERR	CY	CYF45	21199	91TN	4662223	220030990101	F	4/9/2003	222	185	52	9620	URD ELBOW	U3	18131 IVORY CR	2	LF	91TN	PR					WE FOUND Y ELBOW BLOWN OFF OF TF # 4 AND WE REPLACED ELBOW AND BUSHING AND GOT LOOP BACK ON: REF TF: RPLD TR BUSH, RPLD ELBOW @ TR "URD S/O#6024 "NO 6	1	0
FORCED INTERR	FB	NV 02	11202	79HH	4241751	120031000001	T	4/10/2003	000	30	10	300	BU DISC OR BARI	DISC/BARRL	3434 BEASLEY	1	TF	424175176						REPLACED BURNED UP KEARNEY FUSE BARREL ON A 50 KVA TRANS: RPLD BAJ BARREL ON TR. BRS	1	0
FORCED INTERR	FB	WR 14	11265	3C7		120031000002	F	4/10/2003	011	65	8	520	BU DISC OR BARI	DISC/BARRL	1014 DAMON	1	LF	3C7						REFUSED FIELD PHASE OF 3C7 HAD 7.3 AMPS PULLED FUSE. REF LF	1	0
FORCED INTERR	GP	GZ 44	2C145	52BW	5164741	220031000001	F	4/10/2003	023	119	6	714	UNKNOWN	UNKNOWN	10815 VETERAN	1	LF	52BW	TF	516474167				REF LF, RPLD LIMITER @ TR, BRS CORRECTED 2HR/CRH	1	0
FORCED INTERR	GA	GA 03	31230	118Z	6638135	320031000001	F	4/10/2003	025	52	1	52	UNKNOWN	UNKNOWN	8600 OLD CAUS	1	LF	118Z						REF LF	1	0
FORCED INTERR	SH	GG 04	40971	TL8	5554728	220031000003	T	4/10/2003	051	41	6	246	UNKNOWN	UNKNOWN	7310 1/2 EDNA	1	TF	555472897						REFUSED A 75 KVA LIGHTEN IN OPEN DELTA / REAR OF 7318 EDNA, REF TR.	1	0
FORCED INTERR	SH	SO 42	12853	15GR	5450547	320031000004	T	4/10/2003	055	53	2	106	UNKNOWN	UNKNOWN	14535 OLD CHO	1	TF	545054704						REFUSE 25 KVA TF; REF TR;	1	0
FORCED INTERR.	SH	TE 03	31306	9SC	5551422	320031000008	L	4/10/2003	073	75	1	75	TREE CLEARANC	TREE CLEAR	8022 HERTFORD	1	SC							beat ... neutral in two at pole; RPLD CONN @ PL	1	0
FORCED INTERR.	SH	PA 03	30761	68FF	5754341	320031000010	T	4/10/2003	080	74	6	444	UNKNOWN	UNKNOWN	1314 ALLEN GE	1	TF	575434147						REF TR;	1	0
FORCED INTERR	CH	JP 02	41193		5957437	320031000011	T	4/10/2003	080	89	1	89	UNKNOWN	UNKNOWN	15135 JACINTO		TF	595743739						REFUSE 250 KVA TRF FUSE HAD MELTED INTO. REF TR.	1	0
FORCED INTERR	MP	MP 05	41379	4CH	5556953	220031000008	L	4/10/2003	083	35	1	35	VANDALISM	VANDALISM	7417 1/2 NAVIGA	1	MT							REPLACED STOLEN METER, RPLD MTR;	1	0
FORCED INTERR.	BL	GT 04	10652	X72M	5356413	120031000011	F	4/10/2003	084	31	73	2263	SQUIRREL	SQUIRREL	1117 MILFORD	1	LF	X72M						SQUIRREL ON CSP REAR OF 1210 BERTHEA. REF LF,	1	0
FORCED INTERR	HC	AR 43	10944		5047946	120031000014	T	4/10/2003	085	93	1	93	SQUIRREL	SQUIRREL	10710 1/2 HIGHW		PR	504794641						replaced limiter fuse. RPLD LIMITER @ TR,	1	0
FORCED INTERR	FB	TM 04	10808	M29Y	4847313	120031000017	F	4/10/2003	085	41	21	861	SQUIRREL	SQUIRREL	710 PITTMAN	1	LF	M29Y						REF LF	1	0
FORCED INTERR	SH	UW 02	31696	1JZ	6053250	320031000017	F	4/10/2003	090	64	25	1600	SQUIRREL	SQUIRREL	709 PRINCETON	1	LF	1JZ						REFUSED L.F. 3 UNPROTECTED CSP TRANS BEHIND L.F., REF LF; BJH	1	0
FORCED INTERR	CH	NM 01	41501	T15	58581241	320031000018	T	4/10/2003	091	20	2	40	SQUIRREL	SQUIRREL	930 LEAR	1	TF	585812414						REF TR.	1	0
FORCED INTERR	SU	CE 11	11978		48541071	120031000023	T	4/10/2003	091	61	6	366	VINES	VINES	13047 BACARD		TF	485410714						REF TR,	1	0
FORCED INTERR	BZ	LJ 07	30646	70KL	5428238	320031000020	T	4/10/2003	093	71	1	71	OH SEC/DR CL H	OH SC CL-H	1011 COUNTY R	1	SC	542823859						REPLACED BAD CONN AT TRANSF., RPLD CONN @ TR;	1	0
FORCED INTERR	SB	GE 46	21182	T85Y	4760250	120031000026	L	4/10/2003	093	84	1	84	OH SEC/DR CL H	OH SC CL-H	16209 LOCH KA	1	DR							REPL. CLAMPS AT WEATHERHEAD: RPLD CONN @ WH;	1	0
FORCED INTERR	SB	SA 43	21295	E38N	4861938	120031000027	F	4/10/2003	093	28	17	476	SQUIRREL	SQUIRREL	SKYVIEW N OF	1	LF	E38N						REF LF	1	0
FORCED INTERR	HC	HM 06	11037	WF9	5454515	120031000031	L	4/10/2003	100	89	1	89	OH SEC/DR CL H	OH SC CL-H	4610 BURMA	1	DR		SC					MADE REPAIRS TO DROPS @ WH --REPLACED CLAMPS @ POLE/ LEFT SERV ON NOTIFIED: RPLD CONN @ WH, RPLD CONN @ PL.	1	0
FORCED INTERR	GP	HV 01	20486		5264920	220031000025	T	4/10/2003	100	30	1	30	UNKNOWN	UNKNOWN	11025 AIRLINE D		TF	526492094						REF TR.	1	0
FORCED INTERR	SH	UW 03	31105	U83D	6054243	320031000024	F	4/10/2003	101	109	1	109	BU DISC OR BARI	DISC/BARRL	2920 LUELLA	3	LF	U83D	DB					REPLACE BAD SWITCH ON LF# U83D; REF LF	1	0
FORCED INTERR	SH	UW 02	31696	1JZ	6053250	320031000025	L	4/10/2003	101	21	1	21	OH SEC/DR CL N	OH SC CL-N	709 PRINCETON	1	SC							REPLACED NEUTRAL AT POLE, RPLD SEC CONN @ PL-1 CUST.	1	0
FORCED INTERR	SU	WI 05	12389	R58R	4855141	120031000041	T	4/10/2003	102	114	9	1026	TERMINATOR	TERMINATO	3517 DENIO	2	SC	485514163						RPRD SEC->1 CUST	1	0
FORCED INTERR	FB	WR 09	1553A	G13F	37352201	120031000043	T	4/10/2003	103	63	1	63	O/H PRIMARY CL	OH PR CLMP	5631 FM 1299	1	TF	373522015						REF TR.	1	0
FORCED INTERR	MP	HG 04	41083	EP1	5655039	220031000040	T	4/10/2003	104	36	16	576	BU DISC OR BARI	DISC/BARRL	7606 ILEX ST	1	TF	565503927						RPLD BAJ BARREL ON TR.	1	0
FORCED INTERR	KY	WA 42	2161A	55AAM	3854950	120031000055	F	4/10/2003	111	114	1	114	LIGHTNING	LIGHTNING	6650 FM 1489 (E	1	LF	55AAM						DUE TO PAST WEATHER.; REF LF.	1	0
FORCED INTERR	HC	HM 09	11048	W6H	5453422	120031000059	F	4/10/2003	112	25	60	1500	UNKNOWN	UNKNOWN	8904 CULLEN	1	LF	W6H						REFUSED LINE FUSE / CN&S. REF LF.	1	0
FORCED INTERR	CH	GP 04	42046	5N6	5757651	320031000038	T	4/10/2003	112	44	13	572	SQUIRREL	SQUIRREL	12323 COULSON	1	TF	575765154						REFUSE 50 CONV REAR OF 12331 COULSON OUT BY SQ., REF TR.	1	0
FORCED INTERR	BL	BI 02	10053		5256023	120031000061	T	4/10/2003	112	33	13	429	UNKNOWN	UNKNOWN	3303 BANBURY		TF	525602308						NO 3 PHASE, FUSE BROKE AT END OF BARREL ON 25KVA POWER TRAN IN OPEN DELTA, REF TR.	1	0
FORCED INTERR	HC	CC 02	10827	77EG	5452203	120031000062	F	4/10/2003	112	50	26	1300	UNKNOWN	UNKNOWN	12015 SEGREST	1	LF	77EG						REFUSED L.F. FEEDS ALONG WAY MANY CSP TRANS ON (UNPROTECTED) COULD ALSO PUT SOME SWITCHES ON LATERALS, REF LF BJH	1	0
FORCED INTERR	FB	NV 03	11236	W240	44402201	120031000063	T	4/10/2003	113	60	3	180	TREE CLEARANC	TREE CLEAR	12714 DANNHAUS	1	TF	444022012						Trimmed trees from around transformer., REF TR;	1	0
FORCED INTERR	HC	HM 05	11032	40LH		120031000066	F	4/10/2003	113	29	65	1885	VINES	VINES	9021 CULLEN	1	LF	40LH						REMOVED VINES OFF POLE @ 4730 LARKSPUR /REFUSED LF --LEFT SERV ON, REF LF. RMVD TREE/LMB OFF PR.	1	0
FORCED INTERR	HC	AM 05	10747	H59H	5251638	120031000067	T	4/10/2003	113	33	6	198	CONTRACTOR-N	CON-NT HLP	14422 ALROVER	1	TF	525163832						CLOSE TRANSF., REF TR. CABLE CONTRACTOR PULLING IN CABLE-DROPPED ACROSS TRANSFORMER HIGH SIDE MTE	1	0
FORCED INTERR	SB	SA 46	22177	24FM	4862029	120031000070	F	4/10/2003	114	41	22	902	COLLISION	COLLISION	13150 FM 529 R	1	PR	24FM						PICKED UP 1-SPAN #2 PRI CAR HIT POLE. PAIP PR-FUSE NOT BLOWN. BJH	1	0
FORCED INTERR	GA	AL 07	30033	85GK	6042701	320031000042	F	4/10/2003	115	64	1	64	LIGHTNING	LIGHTNING	13302 6TH	1	LF	85GK						REFUSED WEST L.F. (LTNG). REF LF	1	0
FORCED INTERR	CH	GP 08	40823	J34	5756254	320031000043	T	4/10/2003	115	185	11	2035	UNKNOWN	UNKNOWN	1442 12TH	1	BU	575625447						CHANGED OUT 75KVA CSP WITH A 75 KVA CONV ADDED SWITCH_ RPLD BAJ TR.	1	0
FORCED INTERR	GA	HX 01	30053	9JW	62407291	320031000046	F	4/10/2003	121	34	18	612	LIGHTNING ARRE	LTNG ARRST	8009 WHITES	1	LF	9JW						LIGHTING ARRESTOR ON TRN AT 8009 WENT BAD AND BLOW THE LINE FUSE REFUSED LF # 9JW 40 T WILL NEED TO REPLACE LIGHTING ARRESTOR AND WILD LIFE THE TRN AT 8009 WHITE	1	0
FORCED INTERR	GP	LU 03				220031000058	C	4/10/2003	122	0	0	0	UNKNOWN	UNKNOWN	LU03 CKT LOC		CL	LU03						FULL CYCLE - NO CALLS - CREWS IN ROUTE TO RIDE OUT RJB / CREWS ROA CIRCUIT - FOK - NO CUST CALLS - BTN RJB	1	1
FORCED INTERR	GP	LU 03	2G195			220031000058	C	4/10/2003	122	31	730	22630	UNKNOWN				CL	LU03							0	0
FORCED INTERR	GP	LU 03	20557			220031000058	C	4/10/2003	122	63	37	2331	UNKNOWN				CL	LU03							0	0
FORCED INTERR	GP	LU 03	20559			220031000058	C	4/10/2003	122	76	210	15960	UNKNOWN				CL	LU03							0	0
FORCED INTERR.	MP	BH 07	40300	4RS	5559206	220031000056	L	4/10/2003	122	102	1	102	CONTRACTOR-N	CON-NT HLP	3601 E LOCKWO	1	DR							CHANGED OUT BURNED UP RUBBER COATED DROPS WITH NEW CHECKED VOLTAGE. RPLD DR.	1	0
FORCED INTERR	CH	NM 04	41526	4D1	5757757	320031000051	F	4/10/2003	124	28	73	2044	SQUIRREL	SQUIRREL	1403 FEDERAL	1	LF	4D1						SQ. ALL CSP'S UNCOVERED ON THIS LATERAL. REF LF. BJH	1	0
FORCED INTERR	SU	RO 04	12220	H85Z	4952726	120031000077	F	4/10/2003	125	94	44	4136	ANTS	ANTS	12323 CHESTER	2	LF	H85Z						CLEARED ANTS OUT ANTS OUT OF LIVE FRONT XFMR AT 8642 RAVENSWORTH REFUSED T P H85Z 40T LEFT ON AND WORKING. REF TP	1	0
FORCED INTERR	CY	CYF41	22902	73LB	4763148	220031000066	T	4/10/2003	130	313	6	1878	ANTS	ANTS	9026 BONNYVIE	2	BU	476314877						RPLD BAJ TR.	1	0
FORCED INTERR	MP	ES 08	40691		5457219	220031000070	T	4/10/2003	131	25	29	725	SQUIRREL	SQUIRREL	1203 CHARTRES		TF	545721933						REFUSED POWER POT IN CLOSED DELTA BANK TAKEN OUT BY A SQUIRREL. REF TR.	1	0
FORCED INTERR	SH	TE 01	31067	K86G	5652340	320031000060	T	4/10/2003	132	16	3	48	CUST EQP RELAT	CUST RLTD	8800 PAUL B KC	3	TF	565234050						replace burn up fuse barrel. RPLD BAJ BARREL ON TR.	1	0
FORCED INTERR	GP	LU 03	20559	F82B		220031000077	F	4/10/2003	134	194	13	2522	BU DISC OR BARI	DISC/BARRL	17289 BEAVER	1	LF	F82B	DB					NOTE TREE TREE NEEDED 17331 B LF LOCATION FOR F82B B PHASE LOW SIDE WAS AGAINST ARM B PHASE WAS BLOWN MAY HAVE TOOK OUT A. RPLD BAJ DISC-LF BLOWN. MSG SENT TO	1	0
FORCED INTERR	GA	AL 09	30107	I32A	6142411	320031000062	T	4/10/2003	134	67	3	201	FOREIGN MATER	FRGN MATR	3818 AVENUE G	1	SC	614241181						RPLCD CONN @ TF	1	0
FORCED INTERR	GA	AL 09	30107	52FJ	6142618	320031000063	T	4/10/2003	135	14	6	84	SQUIRREL	SQUIRREL	11014 GILES	1	TF	614261889						REFUSED TRX -SQUIRREL) TRX 8484 ---- NEED W.L.P. ---- TRX ACCESS ---- NO A FRIBEE WON'T GE T IT @: REF TR. BJH	1	0
FORCED INTERR	SH	CC 01	30174	M72I	5452844	320031000072	T	4/10/2003	142	245	8	1960	OH SEC/DR CL H	OH SC CL-H	5427 OSPREY	1	BU	545284403						replaces 50 csp with 50 conv RPLD BAJ TR.	1	0
FORCED INTERR	KY	KT 41	22595	66DW	4359244	120031000087	F	4/10/2003	144	119	29	3451	HUMAN ERROR	HUMN ERRO	3259 JAN CT (E	2	LF	66DW	PR					RPLD ELBOW @ TR.	1	0
FORCED INTERR	MP	MP 01	41362	RR6	5556728	220031000084	L	4/10/2003	145	70	1	70	OH SEC/DR CL N	OH SC CL-N	7357 WALKER S	1	DR							MADE REPAIRS TO NEUTRAL AT WH, RPLD CONN @ WH.	1	0
FORCED INTERR	RS	MU 01	30737	A79R	57429131	320031000076	T	4/10/2003	145	82	2	164	SQUIRREL	SQUIRREL	609 RIVERSIDE	1	TF	574291315						refused tr already has wl prot. REF TR.	1	0
FORCED INTERR	GA	STW0	31024		6535559	320031000078	L	4/10/2003	150	45	1	45	OH SEC/DR CL H	OH SC CL-H	12133 COUNTY		DR							REPL. CLAMPS AT THE WH; RPLD CONN @ WH	1	0
FORCED INTERR	CH	AD 08	40086	G32B	5463604	320031000079	L	4/10/2003	151	71	1	71	OH SEC/DR CL H	OH SC CL-H	3005 BERTRAND	1	DR							REPLACED #4 RUBBER COATED DROPS W/ #4 AL 3C TW / CN&S: RPLD DR.	1	0
FORCED INTERR	HC	ST 10	10248	KC2	5154639	120031000094	T	4/10/2003	151	74	9	666	TREE CLEARANC	TREE CLEAR	5011 MIMOSA D	1	TF	515463902						TRIMMED TREES OUT OF OPEN WIRE SECONDARIES @ 5001 MIMOSA THE WIRES WOULD TOUCH WHEN THE WIND BLEW RIGHT THEN RE-SET A CSP LIGHTER IN AN OPEN DELTA BANK. RE	1	0
FORCED INTERR	CH	GW 02	40896		5661520	320031000088	L	4/10/2003	154	64	1	64	ROTTEN POLE	ROTTEN PLE	9245 MESA DR		PD							25 FT SERVICE POLE ROTTEN AT THE BUTT OF POLE. CUST PIPED UP POLE AND PIPE IS WHAT'S HOLDING POLE UP FOR NOW NEED TO CHANGE POLE OUT AT SERV CENTER CONV MSC	1	0
FORCED INTERR	GA	PHR01	30832	9NL	6447505	320031000089	F	4/10/2003	154	52	39	2028	LIGHTNING ARRE	LTNG ARRST	327 TENNYSON	1	LF	9NL						REFUSED LF # 9NL 40T LIGHTING ARRT BLOW AND TOOK OUT LF NEED TO REPLACE DEADEND BELLS AT AVE D AND BUTTON ASAP AND NEED TO WILD LIFE AND ADD SWITCHS TO AB	1	0
FORCED INTERR	FB	WR 10	11259	G55I	3638852	120031000101	F	4/10/2003	155	114	1	114	SQUIRREL	SQUIRREL	RICHMOND @ C	1	LF	G55I	SC	363885206				REMOVED SQUIRREL OFF THE TRANSFORMER AND REFUSED LINE FUSE INSTALLED WILD LIFE PROTECTION ON TRANSFORMER REPLACED CLAMPS AT THE TRANSFORMER FOR BETTE	1	0
FORCED INTERR	HM	AD 10	22931	79UH	5464142	220031000091	F	4/10/2003	155	118	3	354	UNKNOWN	UNKNOWN	1911BUSHONG	1	LF	79UH	PR	546414262				REPAIRED LOAD SIDE OF TRASFROMER REFUSED 79UH; RPLD S/O PR JUMP-TF BLOWN; REF TR.	1	0
FORCED INTERR	FB	RS 02	11395	M7E	4348820	120031000105	F	4/10/2003	163	90	64	5760	O/H PRIMARY CL	OH PR CLMP	AVE J, W OF AU	1	LF	M7E	PR					SPLICED 2 PHASES OF 3 PHASE M7E GETTING INTO ST LITE STADARD AND 30 FT INTERMEDIATE POLE REPL EYE AND 150 HPS BULB ON ST LITE STRD # 327636 HAD 3 PHASES OF M7E OUT F	1	0
FORCED INTERR	SU	BAR46	11903	S23U	4654859	120031000107	L	4/10/2003	164	166	1	166	URD DROPS (CUS	URD DR-C/O	6810 LOS TIOS	2	DR							CUST CUT HIS OWN DROPS SPLICED OUT CUST DROPS. RPRD DR;	1	0
FORCED INTERR	CY	TB 47	2427C	42FU	4874822	220031000096	L	4/10/2003	165	61	1	61	OTHER	OTHER	27506 BENT OAK	1	PD							NEED TO REPLACE 25 FT CL 7 SERV POLE IN EASEMENT TREE HOLDING UP WIRE. MSG SENT TO S/C TLA	1	0
FORCED INTERR	GA	HX 01	30053	8JW	6240729	320031000097	L	4/10/2003	165	111	1	111	OH SEC/DR CL H	OH SC CL-H	8005 MILLER	1	DR		SC					ACTUAL TBL ADDRESS IS 8623 TEXAS (THIS CUST'S RENTAL PROPERTY). RPLD CONN @ WH. RPLD SEC CONN @ PL-1 CUST	1	0
FORCED INTERR	FB	CRB45	14884	99RR	4647123	120031000112	F	4/10/2003	172	79	1	79	BIRD	BIRD	7211 SAVANNAH	1	LF	99RR	TF	464712346				REFUSED LINE FUSE # 99 RR 10 T AND REFUSED TRS 37.5 KVA -BIRD; REF LF REF TR; TLA	1	0
FORCED INTERR	SH	CK 06	31694		6051615	320031000099	T	4/10/2003	173	59	4	236	BU DISC OR BARI	DISC/BARRL	4222 VILLAGE C		TF	605161573						REPLACED FUSE BARREL, RPLD BAJ BARREL ON TR.	1	0
FORCED INTERR	FB	NEW0	10931	EL7	4138503	120031000117	T	4/10/2003	175	53	3	159	SQUIRREL	SQUIRREL	12239 FM 442 R	1	TF	413850309						REFUSED 25 KVA TRANSFORMER , FUSE BLOWN BY SQUIRREL TRANSFORMER HAD WILD LIFE PROTECTION REF TR.	1	0
FORCED INTERR	GA	KM 05	41191		6249611	320031000101	L	4/10/2003	175	101	1	101	HUMAN ERROR	HUMN ERRO	416 WATERFRO		SC							CREW THAT HOOKED UP 414 @ 2 BURNED HIGH LEG INTO JUST TAPED IT, RPLD SEC CONN @ PL->1 CUST TLA	1	0
FORCED INTERR	HC	AM 05	10746	F96A	5251640	120031000118	L	4/10/2003	180	229	1	229	FLLNG TREE OUT	TREE FL/OE	14146 BUFFALO	1	DR							REPAIRED DROPS NEED TO NEED TO REPLACE S/C CON TREE TRIMMING NEED. PAJ DR MSG SENT TO S/C TLA	1	0
FORCED INTERR	CH	NM 04	41526	4D1	5757859	320031000102	L	4/10/2003	180	74	1	74	CONTRACTOR-N	CON-NT HLP	12723 CELIA	1	DR							REPLACED ELECTRIAN CLAMPS AT WH. RPLD CONN @ WH.	1	0
FORCED INTERR	GP	BY 06	40186	28TJ	5361947	220031000111	L	4/10/2003	182	82	1	82	OH SEC/DR CL H	OH SC CL-H	805 ROXELLA	1	DR							RPLD CONN @ WH.	1	0
FORCED INTERR	HC	HOCO	11186	JG9	5253122	120031000127	T	4/10/2003	184	51	9	459	SQUIRREL	SQUIRREL	4321 CREEKBEN	1	TF	525312235						refused trans. REF TR.	1	0
FORCED INTERR	GP	KI 43	21923		4967152	220031000112	T	4/10/2003	184	192	1	192	LIGHTNING ARRE	LTNG ARRST	16525 OLD LOUI		PR	496715271						REPRD LOW SIDE JUMPER. REPL LA. INSTALL WL PROT REF TRANS REF TR. RPRD S/O PRI JUMP-TF BLOWN. RPLD LIGHTNING ARRESTOR.	1	0
FORCED INTERR	BA	CD 09	40138	115N	6457301	320031000106	T	4/10/2003	190	31	8	248	UNKNOWN	UNKNOWN	1209 DWINNELL	1	TF	645730182						REF TR.	1	0
FORCED INTERR	SH	FT 05				320031000106	C	4/10/2003	190	0	0	0	CONTRACTOR-N	PLUMBING	FT05 CKT LOC		CL	FT05						NON 10%--NO R/C EQUIP ---CREW CUT JUMPERS ON SPENCER, E OF PTS 11732 ON PRI BREAKING H. DE PL DOWN BY PLUMBING CONTRS DIGGING ON SECTION#30401---SENT MESS TO S/C	1	1
FORCED INTERR	SH	FT 05	40741			320031000106	C	4/10/2003	190	21	986	20706	CONTRACTOR-N				CL	FT05							0	0
FORCED INTERR	SH	FT 05	3G068			320031000106	C	4/10/2003	190	54	280	15120	CONTRACTOR-N				CL	FT05							0	0
FORCED INTERR	MP	BY 08	40198	LB8	5460037	220031000114	L	4/10/2003	191	64	1	64	FLLNG TREE OUT	TREE FL/OE	633 CAPERTON	1	DR							PICKED UP # 4 DROPS REPLACED PT OF ATTACHMENT AND RECONNECTED WHO. PAJ DR. RPLD CONN @ WH. RPLD POA. RESAGGED DR TLA	1	0
FORCED INTERR.	BL	UL 02	10324	14CT	5156111	120031000129	T	4/10/2003	192	190	4	760	O/H PRIMARY CL	OH PR CLMP	6116 SKYLINE #	1	BU	515611170						REPLACED BAD 167 KVA 13.2 277/480 WITH SAME PLEASE NOTE NO SUCH POTS LISTED ON LIST TO CHOOSE FROM BAD 167 13.2 277/480 SMALL WA ON ASPHALT 5X5 AREA, RPLD BAJ TR.	1	0
FORCED INTERR	MP	MP 08	41391	E55C	55563501	220031000116	F	4/10/2003	193	0	0	0	UNKNOWN	UNKNOWN	116 LINWOOD #	1	LF	E55C	BU	555635016	DB			PICKED UP/DROPPED OFF MAG PARK ON TRANSF. REPL. 7200 50KVA CSP WITH 50KVA CONV 120/240. AND ADDED SWITCH/ WILDLIFE WA SPILL 20 GALS 400 SQ FT ON STREET AND DRIVI	1	0
FORCED INTERR	MP	MP 08				220031000116	F	4/10/2003	193	26	46	1196	UNKNOWN			1	LF	E55C							0	0
FORCED INTERR	MP	MP 08				220031000116	F	4/10/2003	193	136	10	1360	UNKNOWN			1	LF	E55C							0	0
FORCED INTERR	BL	KB 12	10183	L5P	5255359	120031000135	T	4/10/2003	210	51	8	408	UNKNOWN	UNKNOWN	3764 ROBINHOO	1	TF	525535994						REF TR.	1	0
FORCED INTERR	KY	FM 01	22450	37MS	4161913	120031000139	T	4/10/2003	215	114	4	456	UNKNOWN	UNKNOWN	28200 BECKEND	1	BU	416191309						CHANGED OUT A 50 KVA 7200 120/240 O.H. TRANS WITH THE SAME & ADDED WLP & REPLACED FUSE BARREL CAUSE OLD AGE RPLD BAJ TR, RPLD BAJ BARREL ON TR. REF TR. BRS	1	0
FORCED INTERR	SH	SB 02	31650		5854855	320031000121	T	4/10/2003	224	34	4	136	OTHER	BROKE FUSE	2905 SOUTHMO		TF	585485568						REFUSE POWER POT WITH BROKE FUSE BRS	1	0
FORCED INTERR	SH	WEB0	31160	31EF	6048748	320031000122	T	4/10/2003	225	65	9	585	SPLICE	SPLICE	18318 CAPE BAI	2	SC	604874842						REPAIRE SECONDARY BELOW PEDESTAL. RPRD SEC->1 CUST	1	0
FORCED INTERR	GP	LK 03	40923	H13G	5261835	220031000126	F	4/10/2003	232	72	33	2376	UNKNOWN	UNKNOWN	6217 1/2 N SHEP	1	LF	H13G						REFUSED 2 PHASES OF LF REF LF	1	0
FORCED INTERR	GA	PHR01				320031010001	C	4/11/2003	000	0	0	0	COLLISION	COLLISION	TRUCK HIT POL		CL	PHR01						10% CKT SEE TBL SWO R363 TBL IN SECTION "30832" MADE HOT ON 8 SKR	1	1
FORCED INTERR	GA	PHR01	3G343			320031010001	C	4/11/2003	000	54	2372	128088	COLLISION				CL	PHR01							0	0
FORCED INTERR	GA	PHR01				320031010011	C	4/11/2003	005	336	6	2016	COLLISION	COLLISION	PHR01 PART CII		PC	PHR01	LF	20SC	SC	DR	PD	HIGH LOAD DAMAGED VARIOUS EQUIPMENT ON FM 517 BTWN 24TH & 25TH ST CREW REPLACED 2-BROKEN 30FT POLES. PICKED UP 4-SPANS OF SECONDARY & NEUTRAL & 3SETS OF D	1	0
FORCED INTERR	CH	PW 04	41637	B48T	5860049	320031010013	T	4/11/2003	040	67	8	536	BU DISC OR BARI	DISC/BARRL	13105 VERDUN	1	TF	586004991						REFUSED A 50 KVA TRANS, REF TR RPLD BAJ BARREL ON TR. BRS	1	0
FORCED INTERR	BZ	VL 03	31130		5524450	320031010015	T	4/11/2003	050	148	3	444	O/H PRIMARY CL	OH PR CLMP	1811 FM 523		TF	552445095						REFUSED 100KVA TRANS 277/480 7200 - PULLED FUSE. REF TR.	1	0
FORCED INTERR	GA	PHR02	31303	RC9	6347319	320031010016	F	4/11/2003	050	100	26	2600	BIRD	BIRD	GRAND @ 13TH	1	LF	RC9						BIRD ON CSP REF LF	1	0
FORCED INTERR	BL	DN 12	10579	PH8	5357237	120031010009	T	4/11/2003	064	73	2	146	BU DISC OR BARI	DISC/BARRL	3107 1/2 D'AMIC	1	TF	535723721						rep burnt up fuse barrel on lighter tr in closed delta bank. RPLD BAJ BARREL ON TR	1	0
FORCED INTERR	GA	STW0	31424	1CE	6433047	320031010020	T	4/11/2003	070	237	5	1185	FOREIGN MATER	FRGN MATR	16610 LEWIS SC	1	SC	643304787	SC					REPL CT'S AT TRANS AND NEED TO REPL TRANS PADDLES ARE BURN-UP 25 CONV RPRD BUSS WORK @ TR. RPLD CONN @ PL.	1	0
FORCED INTERR	BL	BI 05	10073	F7C	5155631	120031010010	T	4/11/2003	070	50	2	100	SQUIRREL	SQUIRREL	5106 ELM	1	TF	515563172						REFUSED TRNS LEFT SERV ON / NOTIFIED: REF TR.	1	0
FORCED INTERR	CY	WL 41	21160	41AB	4069258	220031010003	T	4/11/2003	071	78	3	234	LIGHTNING ARRE	LTNG ARRST	2211 SMITH	1	PR	406925847						TRUCK ACCESSABLE TANK MOUNTED 18 9. RPLD LIMITER @ TR REF TR. MEK	1	0
FORCED INTERR	RS	LV 01	30080	ZO2	5737220	320031010021	T	4/11/2003	074	38	6	228	SQUIRREL	SQUIRREL	532 SNUG HARB	1	TF	573722050						ctrr has wlp REF TR	1	0
FORCED INTERR	KY	WA 42	2161A	W73F	3854840	120031010011	L	4/11/2003	074	88	1	88	OH SEC/DR CL H	OH SC CL-H	8630 FM 1489	1	DR							Made repairs to drops at pole RPRD DR	1	0
FORCED INTERR	CH	GP 04	42046		5758701	320031010022	T	4/11/2003	080	64	5	320	UNKNOWN	UNKNOWN	12501 KATHRYN		TF	575870122						refused 50 kva tran REF TR.	1	0
FORCED INTERR	BL	ST 07	10230	B40P	5054926	120031010014	T	4/11/2003	081	40	9	360	SQUIRREL	SQUIRREL	5921 DARNELL	1	TF	505492601						REFUSED TR OUT BY SQUIRREL ON LOAD BREAK LEVER OF DISC REF TR. MEK	1	0
FORCED INTERR.	SH	AI 08	31376	18H	6055133	320031010023	F	4/11/2003	081	182	2	364	BU DISC OR BARI	DISC/BARRL	801 E 8TH	1	LF	18H	DB					RPLD BAJ DISC-LF BLOWN.	1	0

FORCED INTERR	SH	GG 04	40971	TL8	55547286	22003101000E	T	4/11/2003	0830	51	6	366	SQUIRREL	SQUIRREL	7314	EDNA	1	TF	555472897								ROTTEN 40 FT POLE CL 4 NEEDS TO BE CHANGED ASAP BEFORE 3 PHASE PRIMARY AND BANK HIT THE GROUND EASEMENT REF TR; MEK	1	0
FORCED INTERR	MP	NS 06	41575	E28V	55591322	22003101000T	U	4/11/2003	0833	26	8	208	BU DISC OR BARI	DISC/BARRL	4815	LAVENDEF	1	TF	555913253								25 TR, REF TR;	1	0
FORCED INTERR	BA	CD 08	40405	PU3	64571172	32003101002E	T	4/11/2003	0840	63	11	693	SQUIRREL	SQUIRREL	1307	MONROE S	1	TF	645711730								REFUSE 50 OP DELTA BANKOUT BY 3Q; REF TR;	1	0
FORCED INTERR	SU	SIE41	10945	A80A	50477385	12003101002E	F	4/11/2003	0844	63	31	1953	UNKNOWN	UNKNOWN	3508	WATTS PL	1	LF	A80A								RE-FUSED LINE FUSE LINE GOES OFF INTO THE WOODS ... MAY HAVE BEEN AN ANIMAL, REF LF	1	0
FORCED INTERR	SH	PE 03	31590	75KA	55490614	32003101003T	T	4/11/2003	0852	71	3	213	SQUIRREL	SQUIRREL	1749	MAX RD #3	1	LF	554905168								REF TR;	1	0
FORCED INTERR					53566620	22003101001C	L	4/11/2003	0854	64	1	614	COLLISION	COLLISION	4704	1/2 FANNIA		SC		DR							REPLACED DROPS DOWNED BY CAR ACCIDENT/LEFT SERV ON / NOTIFIED SWALID OLH, RPLD DR RPLD CONN @ WH, RPLD CONN @ PL,	1	0
FORCED INTERR	SH	SB 06	31649	48GD		32003101003H	F	4/11/2003	0857	39	112	4368	UNKNOWN	UNKNOWN	3717	MALONE	1	LF	48GD								REFUSED LINE FUSE / CHAIR, REF LF,	1	0
FORCED INTERR	HC	AM 06	10749	69H	52529125	12003101002E	T	4/11/2003	0854	48	12	576	SQUIRREL	SQUIRREL	2850	DRAGONA	1	TF	525291257								INSTALLED WILDLIFE PROTECTION AND REFUSED TRANS; REF TR	1	0
FORCED INTERR	SH	SH 09	30934	B28B	57539025	32003101003S	T	4/11/2003	0914	98	4	384	SQUIRREL	SQUIRREL	302	EMPRESS	1	TF	575390298								TRIMMED TREES NEED TO RPL, ROTTEN 40' CL, 4 POLE (@ 3 10); REF TR	1	0
FORCED INTERR	CH	SW 09	41697	J59S	55627410	32003101003E	T	4/11/2003	0916	37	14	518	SQUIRREL	SQUIRREL	6415	HANLEY LI	1	TF	556274103								REFUSED 75 KVA, REF TR;	1	0
FORCED INTERR	GA	STW0	31005	E88D	62313491	32003101003T	L	4/11/2003	0917	172	1	172	OH SEC/DR CL HI	OH SC CL-H	4226	HARDIN	1	DR									REPL 84 ALL DROPS WITH COPPER DROPS RPLD DR,	1	0
FORCED INTERR	MP	HR 01	41029	M1W	53599444	22003101011L	L	4/11/2003	0918	54	1	54	OH SEC/DR CL HI	OH SC CL-H	202	AVENUE OF	1	DR									FOUND HIGH LEG CONNECTION AT WEATHER BURNED INTOV MADE REPAIRS NO LOAD ON AT THIS TIME RPLD CONN @ WHC	1	0
FORCED INTERR	GA	AL 05	30027		61410510	32003101003E	T	4/11/2003	0924	41	1	41	SQUIRREL	SQUIRREL	12626	C BAR CII		TF	614105100								REFUSED TRANS DOES NEED WLP REF TR	1	0
FORCED INTERR	MP	UN 03	41714	D9F	55550049	22003101001Z	T	4/11/2003	0939	37	7	259	UNKNOWN	UNKNOWN	2511	MUNGER	1	TF	555504925								RUFIRD TRNS, REF TR,	1	0
FORCED INTERR	BA	NP 41	3765J	S219B	80662151	32003101004E	T	4/11/2003	0946	307	2	614	UNKNOWN	UNKNOWN	19414	HANNA N	1	BU	606621514	SC			SC				RPLD BAJ TR, RPLD CONN @ TR, RPLD BUSS WORK @ TR,	1	0
FORCED INTERR	SB	WD 43	21594	S56T	47573465	12003101003F	T	4/11/2003	0947	57	26	1482	COLLISION	COLLISION	910	RIVERLACE	2	LF	556T								REFUSED STEP BANK MONERS MAY HAVE HIT POLE BACK ON, REF TR,	1	0
FORCED INTERR	SU	VM 01	12366	37EG	48571044	22003101003T	F	4/11/2003	0955	36	27	972	SQUIRREL	SQUIRREL	1621	BEACONSI	2	LF	37EG								REFUSED T P 37EG 90T SQUIRREL ALL BACK ON, REF TP; VAN CALLED OFF, CREW GOT TP REFUSED...ARK	1	0
FORCED INTERR	CH	LB 01	41254	C30T	55803213	32003101004L	T	4/11/2003	0957	39	7	273	SQUIRREL	SQUIRREL	7216	SHOTWEL	1	TF	558032135								TR HAS WLP ALREADY, REF TR,	1	0
FORCED INTERR	SH	SP 05	31612	1GT	58542291	32003101004E	T	4/11/2003	1011	36	8	288	SQUIRREL	SQUIRREL	1303	TRIMM	1	TF	585422916								REFUSE TRANSF, REF TR,	1	0
FORCED INTERR	SH	SB 06	31649	47GD	58542504	32003101005C	T	4/11/2003	1028	54	18	972	SQUIRREL	SQUIRREL	3804	MALONE	1	TF	585425045								REFUSED TRANS NEEDS WLP, REF TR,	1	0
FORCED INTERR	MP	ES 08	40691		54572195	22003101001E	T	4/11/2003	1030	67	29	1943	SQUIRREL	SQUIRREL	1203	CHARTRE!		TF	545721933								REF TR	1	0
FORCED INTERR	BL	ST 07	10229	38G	50549394	12003101044T	T	4/11/2003	1038	63	13	819	SQUIRREL	SQUIRREL	8208	DUNLAP	1	TF	505493991								WOLF IN PLACE, REF TR	1	0
FORCED INTERR	SH	PE 04	30815	E44B	55463111	32003101005Z	F	4/11/2003	1040	180	14	2520	O/H PRIMARY CL	OH PR CLM#	3709	BLUEBIRD	1	LF	E44B	PR							PAJ PR-FUSE BLOWN;	1	0
FORCED INTERR	MP	UN 03	41712	73X	55554576	22003101002Z	T	4/11/2003	1101	88	17	1462	VINES	VINES	1720	IDYLWOOD	1	TF	555545706								40' PL IN EASEMENT NEEDS VINES REMOVED 30 & 15 TRA F 10 TR + 800H + REF TR, MEK	1	0
FORCED INTERR	GA	STW0	35358	H96X	63336168	32003101004L	L	4/11/2003	1110	96	1	96	OH SEC/DR CL NI	OH SC CL-H	18100	SAN LUIS	1	DR									REPAIR NEUTRAL AT THE WHY, RPLD CONN @ WH,	1	0
FORCED INTERR	BA	CD 07	40388	A50S	63569400	32003101005E	F	4/11/2003	1110	45	35	1575	UNKNOWN	UNKNOWN	5 5TH, N OF E C		1	LF	A50S								REFUSE LINE FUSE, REF LF	1	0
FORCED INTERR	BL	HT 04	10296		50556491	12003101002T	T	4/11/2003	1131	45	1	45	LIGHTNING ARRE	LTNG ARRS	5810	SAVOY DR		TF	505564917								ALL 3 COMB. TYPE LIA AND BLOWN TRUCK ACCESSABLE DOUBLE BUCKET ONLY REF TR; MEK	1	0
FORCED INTERR	BZ	VL 03	3511B	HH7	55254285	32003101005T	F	4/11/2003	1140	57	15	855	BIRD	BIRD	2739	DUTCH LK	1	LF	HH7								REFUSED L F H H - 7 28-T , REF LF	1	0
FORCED INTERR	BL	KB 07	10154	X24C	52566475	12003101005E	F	4/11/2003	1152	23	1	23	SQUIRREL	SQUIRREL	3131	BAMMEL	3	LF	X24C								NEED WOLF REINSTALLED AND TREE CUT AWAY/ GET TRUCK TO IT/NEED PIC IN AREA BET UP OUTAGE OR POSSIBLE OR POSSIBLE HOT STICK IT ON FEEDB 10 STORY CONDO, REF TP MEI	1	0
FORCED INTERR	SH	UW 03	31107	B80J	60552254	32003101001T	T	4/11/2003	1201	51	6	306	SQUIRREL	SQUIRREL	1125	PEARL	1	TF	605522597								REFUSED TRANS NEEDS WLP REF TR, MEK	1	0
FORCED INTERR	CH	BY 10	40208	H1B		32003101004F	T	4/11/2003	1216	180	74	11840	FLLNG TREE OUT	TREE FL/OE	1534	SKINNER	9	LF	H1B	PR							SOMEBODY AT 1534 SKINNER CUT DOWN TREE ON 3 PHASE #2 PRIMARY PICKED UP ALL PHASE TREE IN CLEAR, REF LF PAJ PR-FUSE BLOWN,	1	0
FORCED INTERR	FB	RS 07	11414	85RB	43485500	12003101005S	T	4/11/2003	1238	36	18	648	SQUIRREL	SQUIRREL	305	1ST	1	TF	434855063								LINE FUSE WAS HOT BLOWN ONLY 1 TRANSFORMER WAS OUT NEEDS WILDLIFE PROTECTION TRUCK ACCESSIBLE, REF TR, MEK	1	0
FORCED INTERR	RS	MU 01	30737	A79R	57429135	32003101007Z	F	4/11/2003	1310	70	17	1190	SQUIRREL	SQUIRREL	701	RIVERSIDE	1	LF	A79R								SQUIRREL ON OP DELTA BANK @ 606 RIVERSIDE, REF LF	1	0
FORCED INTERR	SH	CG 02	30212	W50C	57536138	32003101007H	F	4/11/2003	1313	33	5	165	UNKNOWN	UNKNOWN	7311	GALVESTO	1	LF	W50C								REFUSED L F REF LF	1	0
FORCED INTERR	GP	RU 01	41644	3B2	53613571	22003101003K	T	4/11/2003	1325	105	2	210	OH SEC/DR CL HI	OH SC CL-H	522	DUNKLEY	1	SC	536135716				DR				REMOVRED CONNECTIONS @ Trans LEADS--RPLCD CLMPS @ WH--RPLCD BAD FUSE BARREL ON 50 LIGHTER--NOTIFIED; RPLD BAJ BARREL ON TR, RPLD CONN @ TR, RPLD CONN @ WH,	1	0
FORCED INTERR	GA	AL 06	30031	71HT	61420394	32003101007E	F	4/11/2003	1322	27	6	162	SQUIRREL	SQUIRREL	FM 645 @ 4 1/2		1	LF	71HT								REFUSED L F 48QUIRREL REF LF	1	0
FORCED INTERR	SB	EU 06	40728	99RT	52583454	22003101004T	T	4/11/2003	1350	51	1	51	BU DISC OR BARI	DISC/BARRL	3325	W 11TH	1	TF	525834545								REF TR,	1	0
FORCED INTERR	HM	RA 03	20412	F44B	52740011	22003101004T	T	4/11/2003	1359	62	3	186	CONTRACTOR-N	CON-NT HLF	512	ALANA LN	1	TF	527400109								REINET TR, C/O DUE TO LOOP DAMAGE, MTR 54460254, ROG 24615, X1, ELDERLY CUSTOMER..... 88T	1	0
FORCED INTERR	HM	RA 44	2A181	S62U	52725401	22003101004S	T	4/11/2003	1400	140	3	420	LIGHTNING	LIGHTNING	29518	GENEVA I	1	BU	527254013	SC							RPLD BAJ TR, RPLD LIMITER @ TR, RPLD BUSS WORK @ TR, RPLD LIGHTNING ARRESTOR;	1	0
FORCED INTERR	BA	MB 08	41421	P84X		32003101008Z	F	4/11/2003	1420	29	32	928	ANTS	ANTS	10527	LANGSTC	1	LF	P84X	LF	66GL						LF CLOSED BACK IN AT 14 50 CLEANED ANTS OUT OF URD TRANS 60 RLDD 40 REFUSED TP 86GL, REF LF, REF TP	1	0
FORCED INTERR	MP	WO 06	41861	A47L	52589330	12003101005T	T	4/11/2003	1444	135	15	2025	ROTTEN POLE	ROTTEN PLI	1601	W 24TH	1	BU	525953303								REPL 60 CONV 7200/120/240 WITH THE SAME , TR WAS LEAKING OIL AL/BQ REPL LIGHTING ARRESTER BER # 675872	1	0
FORCED INTERR	HC	BR 10	11160	82A	51537368	12003101007S	T	4/11/2003	1522	35	1	35	BIRD	BIRD	10532	S POST C	1	TF	515373683								REF TR,	1	0
FORCED INTERR	CY	PI 42	2444B	91JA	48771241	22003101005E	T	4/11/2003	1529	304	2	608	TRANSFORMER	TRANSFRMF	40318	THREE FI	1	BU	487712418								RPLD BAJ TR,	1	0
FORCED INTERR	GP	LK 03	40923	H13G	52618455	22003101005T	T	4/11/2003	1531	26	1	26	UNKNOWN	UNKNOWN	6401	N SHEPHE	1	TF	526184560								REFUSED 50 LIGHTER--BROKE FUSE--ADE, REF TR	1	0
FORCED INTERR	FB	RE 04	11446	M72Y		12003101007E	F	4/11/2003	1600	146	67	9916	SPLICE	SPLICE	1216	WESTWOX	2	LF	M72Y	PR							REPAIRED URD PRIMARY IN TRANSFORMER #11 BUILDING 1100 CLOSED URD T P M72Y Y FEED SWITCHING ORDER # 6036 REF TP RPRD URD PR	1	0
FORCED INTERR	BA	NP 44	42055	AN50F	61647400	32003101009Z	F	4/11/2003	1622	48	33	1584	UNKNOWN	UNKNOWN	1402	CHATEAU	1	LF	AN50F								REF LF	1	0
FORCED INTERR	SU	AF 08	11811		49540468	12003101008T	U	4/11/2003	1642	170	1	170	UNKNOWN	UNKNOWN	7503	BOONE		BU	495404691								RPLD BAD 50 CBPV 60 CONV 7200/120/240, RPLD BAJ TR;	1	0
FORCED INTERR	GP	GZ 41	22188	50DL	52661324	22003101006H	F	4/11/2003	1654	109	182	19838	UNKNOWN	UNKNOWN	14335	ELLA #71:	2	LF	50DL								URD BAD 8037, FIND OK WITH VAN REF TP, REF TP;	1	0
FORCED INTERR	FB	NV 02	11223	J59	41401531	12003101008H	T	4/11/2003	1727	35	2	70	LIGHTNING	LIGHTNING	7521	DALE DOD	1	TF	414015314								REFUSED POWER TRS IN OPEN DELTA BANK #PASSED LIGHTINGH FROM THE OTHER DAY REF TR	1	0
FORCED INTERR	HM	RA 03	20412	F44B	52740011	22003101007C	L	4/11/2003	1750	98	1	98	COLLISION	COLLISION	512	ALANA LN	1	DR									PAJ DR,	1	0
FORCED INTERR	SB	TO 08	21775		51597584	12003101008E	T	4/11/2003	1800	92	1	92	BU DISC OR BARI	DISC/BARRL	3020	MANGUM	1	TF	515975841	DB							REPLACED BAD 12 KVA SWITCH IN A CLOSED DELTA BANK, RPLD BAJ DISC-TF BLOWN,	1	0
FORCED INTERR	SH	CC 01	30176	L40	54532105	12003101006E	T	4/11/2003	1814	33	1	33	BU DISC OR BARI	DISC/BARRL	4332	WILMINGT	1	TF	545321601								RPLD BAJ BARREL ON TR,	1	0
FORCED INTERR	SH	SH 09	31015	H91P	58521465	32003101010T	T	4/11/2003	1830	43	1	43	BIRD	BIRD	717	CRENSHAW	1	TF	585214632								SECOND TIME OUT CLOSE DELTA BANK NEED W L P REF TR, NO BUSCASING--ABK	1	0
FORCED INTERR	GA	PHR01	30832		64465375	32003101010E	L	4/11/2003	1940	174	1	174	COLLISION	COLLISION	2379	FM 517		DR		SC							REPL 84 DROP AND SECONDARIES TAKEN DOWN BY A HIGH LOAD, RPLD DR, RPLD SEC-1 CUST,	1	0
FORCED INTERR	GA	AL 05	30028	W78O	61410370	32003101011C	F	4/11/2003	2015	158	8	948	FOREIGN MATER	FRGN MATR	12430	HWY 6	1	LF	W78O								FUSE BROKE AND BARREL BURNED UP ON NORTH PHARE W780 RPLD BAJ BARREL ON LF	1	0
FORCED INTERR	MP	ES 02	40647		54577056	22003101007S	T	4/11/2003	2022	52	2	104	BU DISC OR BARI	DISC/BARRL	3801	HARRISBU		TF	545770565								FOUND BAD 200 AMP FUSE CUST BREAKER BOX INSIDE TBL INT-CUST NOTIFIED, REF TR NO BUSCASING--ABK	1	0
FORCED INTERR	KY	GE 44	22507		46610244	22003101009E	T	4/11/2003	2031	384	8	2304	HUMAN ERROR	HUMAN ERRC	18627	SANDELF		SC	468102467								REPAIRED BURS WORK ON OVERHEAD TRANS RPRD BUSS WORK @ TR, BRS	1	0
FORCED INTERR	GP	FR 43	21395	S139B	51630201	22003101008C	F	4/11/2003	2240	208	64	13312	UNKNOWN	UNKNOWN	N.HOUSTON RC		1	LF	S139B	SC			PR				REPLACED 250 KVA STEP POT AND PICKED UP 1 SPAN OF #2 NEUTRAL, SPLICED ON PR, RPLD BAJ TR RPLD LIMITER @ TR, REF TR, BRS	1	0
FORCED INTERR	BL	SF 03	10418	J1R	52563536	12003101010E	F	4/11/2003	2325	58	13	754	O/H PRIMARY CL	OH PR CLM#	3717	ELLA LEE L	1	LF	J1R	PR							REPLACED BURNED STIRRUP , HOT LINE CLAMP, REF LF NO BUSCASING--ABK	1	0
FORCED INTERR	GA	SCW0	30880		66398584	32003101011E	T	4/11/2003	2330	44	2	88	BU DISC OR BARI	DISC/BARRL	928	FERRY #1		TF	663985869	DB							REPLACED BURN UP DISC ON TRANSFORMER BRS	1	0
FORCED INTERR	RS	LV 01	3A115	B33P	57355455	32003120001T	F	4/12/2003	0152	277	2	554	O/H PRIMARY CL	OH PR CLM#	7403	CO 203	1	LF	B33P	PR							PICKED UP 1 SP 6 4 AL PRI PAJ PR-FUSE BLOWN REF LF ROR	1	0
FORCED INTERR	MP	HG 04	41061	F6G	56561004	22003120002E	F	4/12/2003	0532	66	14	924	LIGHTNING ARRE	LTNG ARRS	7714	E MAGNOL	1	LF	F6G								9LWIN LITE ARRESTR ON TRANS AT END OF LINE- REPL AT SERV CENT CONV REF LF /PER CREW - ONLY ONE PHASE WAS REFUSED - CORRECTED CUSTOMER COUNT -BEV QA)	1	0
FORCED INTERR	BA	CD 08	40405	PU3	64571172	32003120004T	T	4/12/2003	0706	78	11	858	UNKNOWN	UNKNOWN	1304	MADISON	1	TF	645711730								REF TR,	1	0
FORCED INTERR	SH	SH 05	30913		57520228	32003120006T	T	4/12/2003	0731	100	4	400	BU DISC OR BARI	DISC/BARRL	9415	MELDRUM		TF	575202267								RPLD BAJ BARREL ON TR,	1	0
FORCED INTERR	MP	MP 05	41376		55567544	22003120006L	L	4/12/2003	0800	115	1	115	OH SEC/DR CL HI	OH SC CL-H	7047	AVENUE J		SC									replaced 8 4 rubber coated drops, RPRD BEC-1 CUST	1	0
FORCED INTERR	SU	SIE41	10947	Y34C	50470111	12003120006T	T	4/12/2003	0800	98	5	490	OH SEC/DR CL HI	OH SC CL-H	5410	RAINTREE	1	TF	504701120								NEED TO REPLACE 50 KVA TRANS 10 8 120/240 JUNEWORK TRANS LEADS GET WITH TRUCK WHEN DRY DRY NOW REF TR, ROR	1	0
FORCED INTERR	FB	OB 44	11918		46544114	12003120007T	T	4/12/2003	0814	64	4	256	BIRD	BIRD	7703	LORO LINE		PR	465441145								REPLACED 12 K-MATE ON 50 KVA LIGHTER XFMR BIRD LEFT ON AND WORKING CUST NOTIFIED, RPLD LIMITER @ TR	1	0
FORCED INTERR	BZ	BZ 01	30180	86J	53265082	32003120009E	F	4/12/2003	0822	20	20	400	FLLNG TREE IN E	TREE FL/E	812	PLANTATIO	1	LF	86J								CUST TRIMMING TREE DROPPED LINE IN PRI REF LF	1	0
FORCED INTERR	GP	LK 06	22554	S01		22003120001Z	F	4/12/2003	0833	100	63	6300	SQUIRREL	SQUIRREL	9922	GLOYNA	1	LF	K27L	TF	516275911						REFUSE 25KVA 7200 CONV 9922 GLOYNA CAUSE OF TRL, REF LF, REF TR ROR R/USE 15ACO SHOWN ON CABE 220031040380 - BEV QA)	1	0
FORCED INTERR	GP	LK 06	22554	25ACQ		22003104003E	F	4/12/2003	0833	100	14	1400	SQUIRREL	SQUIRREL	2718	STALLINGS	1	LF	25ACQ								INFORMATION FROM CASE 220031020120	1	0
FORCED INTERR	MP	AN 02	40027	L8K	53593428	22003120001S	F	4/12/2003	0838	72	17	1224	SQUIRREL	SQUIRREL	309	E 27TH	1	LF	L8K								REF LF,	1	0
FORCED INTERR	SB	SA 44	21314	X13X	48617367	12003120002F	F	4/12/2003	0844	40	2	80	UNKNOWN	UNKNOWN	8400	CUNNINGH	1	LF	X13X								REFUSED SOUTH PHASE OF LINE X13X, REF LF	1	0
FORCED INTERR	HC	AM 08	10749	71H	53520231	12003120001S	T	4/12/2003	0900	33	8	196	BU DISC OR BARI	DISC/BARRL	12139	OUT	1	TF	535202320								REPLACED BURNED UP FUSE BARREL ON TRANS REF TR,	1	0
FORCED INTERR	FB	NV 03	11232	31ADK	44413315	12003120017F	T	4/12/2003	0914	99	15	1485	INSULATOR	INSULATOR	11522	JESKE	1	LF	31ADK	PR							PICKED UP 2 SPANS OF PRIMARY AND REPL INSULATOR, PAJ PR-FUSE BLOWN, REF LF	1	0
FORCED INTERR	HM	SW 08	41694	3GC	56637561	22003120017F	T	4/12/2003	1020	119	40	4760	BU DISC OR BARI	DISC/BARRL	13721	NIGHTINC	1	DB	3GC								RPLD BAJ BARREL ON LF, RPLD BAJ DISC-LF NOT BLOWN, CORRECTED 2HRCRH	1	0
FORCED INTERR	SH	PA 02	30755	H36P	57550141	32003120017T	T	4/12/2003	1033	59	11	649	SQUIRREL	SQUIRREL	506	GOBER	1	TF	575501411								refused trans --1 three a neutral-- does have arrester, REF TR,	1	0
FORCED INTERR	MP	UN 01	41710	JJ5	55552159	32003120015T	T	4/12/2003	1040	35	7	245	SQUIRREL	SQUIRREL	3803	LAZYWOO	1	TF	555521553								REF TR	1	0
FORCED INTERR	SH	SH 11	31404	A21S	57529140	32003120015L	L	4/12/2003	1050	50	1	50	TREE CLEARANC	TREE CLEAI	12018	PALMCRE	1	SC									RPLD SEC CONN @ PL-1 CUST	1	0
FORCED INTERR	RS	LV 03	30078	K60F	56363511	32003120002F	F	4/12/2003	1059	41	2	82	COLLISION	COLLISION	708	CO 192	1	LF	K60F								CUST HIT GUY WIRE WITH TRACTOR, REF LF	1	0
FORCED INTERR	SB	SA 44	21314	X13X	48618301	12003120003T	T	4/12/2003	1114	65	2	130	UNKNOWN	UNKNOWN	8464	CUNNINGH	1	PR	486183019								REPL LIMITER INFUSED TR, RPLD LIMITER @ TR, REF TR	1	0
FORCED INTERR	GP	KG 44	20546	B33B	49699736	22003120022T	F	4/12/2003	1115	114	3	342	SLACK SPANS	SLACK SPAI	6700	SPRING C	1	LF	B33B	PR						SC	REASODED #4 PRIMARY NUETRAL & #2 PRIMARY @ POLE CLEARANCE, REF LF SPLICED OH PR RPRD PRI NEUT,	1	0
FORCED INTERR	RS	LV 01	3A115	B33P	57355455	32003120022T	F	4/12/2003	1118	60	2	120	O/H PRIMARY CL	OH PR CLM#	7403	CO 203	1	LF	B33P								CA 2 SP OF ABANDED WIRE @ DE OF LINE TOP OF POLE SPLIT KINGPIN FLOAT INCL REF LF	1	0
FORCED INTERR	HC	PZ 41	12845	40BR	53547277	12003120003C	F	4/12/2003	1148	119	83	9877	URD ELBOW	URD ELBOW	3232	HOLLY HAI	2	LF	40BR	PR	535472847						REPLACED BAD ELBOW IN TRANS FORMER #8 ON X PRIMARY REFUSED TERMINAL POLE, REF TP RPLD ELBOW @ TR CORRECTED 2HRCRH	1	0
FORCED INTERR	GP	DH 10	40599	E96Y		22003120024F	F	4/12/2003	1200	74	89	6586	FLLNG TREE OUT	TREE FL/OE	4218	FALLEN OH	1	LF	E96Y								REF LF	1	0
FORCED INTERR	SH	SP 04	31363	18EH	58535560	32003120002E	L	4/12/2003	1218	85	1	85	OH SEC/DR CL HI	OH SC CL-H	3933	SPENCER	1	DR									RPLD CONN @ WH,	1	0
FORCED INTERR	HC	HM 06	11035	R7D	54546195	12003120003A	T	4/12/2003	1224	108	9	972	SQUIRREL	SQUIRREL	7307	HURTGEN	1	TF	545461552								TRANS HAS WILDLIFE PROTECTION, REF TR,	1	0
FORCED INTERR	GP	BA 43	2F144		50658561	22003120025T	T	4/12/2003	1234	160	6	960	TREE CLEARANC	TREE CLEAI	4810	TRACEME/		PR	508565699								REPLACED 12 K-MAT LIMITER & 36 KV LIGHTING ARRESTOR, RPLD LIMITER @ TR, REF TR, RPLD LIGHTNING ARRESTOR	1	0
FORCED INTERR	BL	ST 15				12003120003T	C	4/12/2003	1250	26	943	24518	COLLISION	COLLISION	5771	CLAREWO		CL	ST15	PR							CAR HIT A POLE AT LF 80M 5711 CLAREWOOD - CREWS OPENED LF 8-OM TO CLEAR FAULT - WILL REPAIR HIGH SIDE JUMPER ON LF 8-OM ALL SVC RESTORED @ 1316 ~SEC78 10275	1	1
FORCED INTERR	SU	WW 0	12417	M34	49549474	12003120004T	T	4/12/2003	1322	81	12	972	SQUIRREL	SQUIRREL	7411	S GESSNE	1	TF	495494746								A VARMIT WENT TO GROUND ON TOP OF THE XFMR TRIMMED TREES AND INSTALLED A SQUIRREL GUARD REFUSED A 75 KVA 7200 120/240 XF MR LOCATED IN THE REAR OF 7407 8 QESBNE	1	0
FORCED INTERR	MP	CL 05	40468		56570284	22003120022F	T	4/12/2003	1400	33	4	132	LIGHTNING	LIGHTNING	2337	MC CARTY		TF	565702840								RPLD BAJ BARREL ON TR,	1	0
FORCED INTERR	BL	KB 12	10186	R8S	52555374	12003120005Z	T	4/12/2003	1411	68	10	680	FLLNG TREE IN E	TREE FL/E	3301	UNIVERSITI		TF	525553745								NEED MAJOR TREE TRIMMING IN REAR OF 8328 RUTGERS LARGE PALM TREE HAS GROWN ALL OVER OPEN DELTA BANK, REF TR	1	0
FORCED INTERR	HM	KW 41	2463C	H95M	57704054	22003120003C	F	4/12/2003	1414	0	0	0	URD ELBOW	URD ELBOW	2302	KINGS FOI	2	LF	H95M	PR							REPLACED ELBOW IN TRANS #8 ISOLATED SPAN OF PRI BETWEENTRANS # 4 & #5 BAD PRI BUSHING IN TRANS BANKED TRANS REPLACED PRI SPLICED 50KVA DEAD FRONT ANSI 2 SWITCHI	1	0
FORCED INTERR	HM	KW 41				22003120003C	F	4/12/2003	1414	211	13	2743	URD ELBOW	URD ELBOW			2	LF	H95M									0	0
FORCED INTERR	HM	KW 41				22003120003C	F	4/12/2003	1414	211	11	2321	URD ELBOW	URD ELBOW			2	LF	H95M									0	0
FORCED INTERR	HM	AT 42	2386C	E27K	58698095	22003120003T	T	4/12/2003	1444	46	8	368	VINES	VINES	200	SWIFT CUR	1	TF

FORCED INTERR.	SB	WT 07	21837		51581427	120031020086	T	4/12/2003	2144	65	5	330	TRANSFORMER	TRANSFRME	14	HILSHIRE GR		BU	515814279									1	0
FORCED INTERR.	SH	DR 06				320031030001	C	4/13/2003	0200	0	0	0	OTHER EQUIPME	OTHR EQUIP	7146	BELLFORT		CL	DR06	PR			PD					0	0
FORCED INTERR.	SH	DR 06	3G052			320031030001	C	4/13/2003	0200	80	1235	98800	OTHER EQUIPME					CL	DR06									0	0
FORCED INTERR.	SH	DR 06	30288			320031030001	C	4/13/2003	0200	122	190	23180	OTHER EQUIPME					CL	DR06									0	0
FORCED INTERR.	HC	TV 03	11139	P55R	51508046	120031030002	F	4/13/2003	0400	93	11	1023	UNKNOWN	UNKNOWN	5035	RIDGECRE	2	LF	P55R									1	0
FORCED INTERR	GP	KL 48	21908	R30P	48672111	220031030014	F	4/13/2003	0500	0	0	0	UNKNOWN	UNKNOWN	11902	HILL BRO	2	LF	R30P	BU	486722601							0	0
FORCED INTERR	GP	KL 48				220031030014	F	4/13/2003	0500	110	55	6050	UNKNOWN				2	LF	R30P									0	0
FORCED INTERR	GP	KL 48				220031030014	F	4/13/2003	0500	291	6	1746	UNKNOWN				2	LF	R30P									0	0
FORCED INTERR	GA	MDY01	31515		67372257	320031030002	T	4/13/2003	0516	34	7	238	BU DISC OR BARI	DISC/BARRL	7217	YOUPON		TF	673722577									1	0
FORCED INTERR	SH	SH 04	30909	WE3	57515436	320031030003	F	4/13/2003	0700	74	10	740	SQUIRREL	SQUIRREL	10707	RAMBLIN	1	LF	WE3									1	0
FORCED INTERR	HM	LW 43	23017	74ABP		220031030017	F	4/13/2003	0711	189	104	19656	UNKNOWN	UNKNOWN	5533	SEYMOUR	1	LF	74ABP	PR								1	0
FORCED INTERR	HM	HB 49	20037	S2891	56673434	220031030018	T	4/13/2003	0751	61	8	488	FIRE	FIRE	402	S AVENUE	1	TF	566734360									1	0
FORCED INTERR	HC	SO 41	12620	H32H	52478586	120031030011	T	4/13/2003	0800	118	1	118	SQUIRREL	SQUIRREL	1902	MUSTANG	1	TF	524785862	PR								1	0
FORCED INTERR	BL	ST 01	10194	F48C	51543246	120031030012	T	4/13/2003	0815	87	10	870	TREE CLEARANC	TREE CLEAR	5435	DARNELL	1	TF	515432453									1	0
FORCED INTERR	HC	GV 02	10825	FB4	55530314	120031030014	T	4/13/2003	0828	128	8	1024	SQUIRREL	SQUIRREL	5850	BELCREST	1	TF	555303146									1	0
FORCED INTERR	HM	HB 04	20103	H68M	56698282	220031030021	T	4/13/2003	0835	74	2	148	BU DISC OR BARI	DISC/BARRL	1410	BROOKTR	1	TF	566982847									1	0
FORCED INTERR	BL	WW 0	10692	M12P	50542065	120031030022	F	4/13/2003	0955	74	19	1406	BIRD	BIRD	8345	NAIRN ST	2	LF	M12P									1	0
FORCED INTERR	CH	AD 06	40087	68P	54626544	320031030012	T	4/13/2003	1025	56	13	728	UNKNOWN	UNKNOWN	3214	HARTWICH	1	TF	546265444									1	0
FORCED INTERR	SU	CE 02	11935	72FS	47526222	120031030022	F	4/13/2003	1025	185	19	3515	UNKNOWN	UNKNOWN	13803	GREENW	2	LF	72FS	BU	475272818	PR						1	0
FORCED INTERR.	BA	CD 09	40380	I20N	64573181	320031030013	T	4/13/2003	1020	25	4	100	SQUIRREL	SQUIRREL	1507	NARCILLE	1	TF	645731810									1	0
FORCED INTERR	GP	GZ 41	2H169	P19A	51856596	220031030025	F	4/13/2003	1040	150	42	6300	URD ELBOW	URD ELBOW	11911	YEATMAN	2	LF	P19A	PR								1	0
FORCED INTERR	GP	GZ 41	2H169	P18A	51857524	220031030026	F	4/13/2003	1040	157	34	5338	URD ELBOW	URD ELBOW	11938	ARROYO	2	LF	P18A									1	0
FORCED INTERR	SB	SA 47	21222	24AI	47634242	220031030027	T	4/13/2003	1055	89	12	1068	BU DISC OR BARI	DISC/BARRL	15218	WEST RE	1	TF	476342422									1	0
FORCED INTERR	GP	THW4	21165		48851127	220031030030	T	4/13/2003	1100	91	10	910	UNKNOWN	UNKNOWN	11950	PERRY B	1	TF	488511272									1	0
FORCED INTERR	RS	LV 02	30077	57QK	55357527	320031030014	F	4/13/2003	1122	56	3	168	BU DISC OR BARI	DISC/BARRL	2100	COUNTY R	1	LF	57QK									1	0
FORCED INTERR	SB	CB 02	21419	K70A	49599331	320031030022	T	4/13/2003	1200	28	8	224	OTHER WILDLIFE	OTHER WLIF	2215	ELMGATE	1	TF	495993353									1	0
FORCED INTERR	BA	CD 09	40378	C35W	64573178	320031030017	T	4/13/2003	1240	50	8	400	SQUIRREL	SQUIRREL	2207	CEDAR CR	1	TF	645731788									1	0
FORCED INTERR	GP	KL 42	21893	S1908	48671011	220031030031	T	4/13/2003	1310	140	3	420	UNKNOWN	UNKNOWN	15006	LONG OA	1	BU	486710119									1	0
FORCED INTERR	BL	UL 47	13011	K80U	51571092	120031030032	T	4/13/2003	1330	85	5	425	TRANSFORMER	TRANSFRME	5869	DOLIVER	2	BU	515710927									1	0
FORCED INTERR	CH	GP 07	40820	5EK	57560582	320031030022	T	4/13/2003	1330	78	8	608	UNKNOWN	UNKNOWN	2009	9TH	1	TF	575605831									1	0
FORCED INTERR	MP	NS 06	41573	7LN	54585492	220031030036	L	4/13/2003	1330	89	1	89	COLLISION	COLLISION	2729	JONES	1	PD										1	0
FORCED INTERR	GP	THW4	20901		48654028	220031030036	L	4/13/2003	1330	78	1	78	FLLNG TREE OUT	TREE FL/OE	8807	SWEETBR		SC										1	0
FORCED INTERR	HC	BL 05	10797	N85L	50528291	120031030042	T	4/13/2003	1417	226	8	1356	UNKNOWN	UNKNOWN	12327	BRAESRII	2	SC	505282919									1	0
FORCED INTERR	BL	DN 07	13151	84ABL	52569351	120031030044	F	4/13/2003	1430	86	37	3182	LIGHTNING ARRE	LTNG ARRS	2207	DEVONSHI	2	LF	84ABL									1	0
FORCED INTERR.	CY	KL 43	21890		47663244	220031030047	L	4/13/2003	1430	66	1	66	OH SEC/DR CL H	OH SC CL-H	13610	KLUGE RI		DR										1	0
FORCED INTERR.	CY	WL 02	2370A	L34	40692138	220031030046	T	4/13/2003	1440	84	14	1176	OH SEC/DR CL H	OH SC CL-H	2711	MYRTLE	1	SC	406921358									1	0
FORCED INTERR	SU	AF 07	11800	N62N	49550056	220031030046	T	4/13/2003	1450	63	10	630	COLLISION	COLLISION	11108	HOLWOR	2	TF	495500568									1	0
FORCED INTERR	SB	DH 04	21529	56KQ	51604371	120031030047	F	4/13/2003	1455	54	16	864	FLLNG TREE IN E	TREE FL/E	5313	DE MILO	1	LF	56KQ									1	0
FORCED INTERR	CY	SA 42	22045	63SD	47636362	220031030050	F	4/13/2003	1510	37	2	74	GUY/ANCHOR	GUY/ANCHO	8902	POINT SIX	3	LF	63SD	SC								1	0
FORCED INTERR	BL	JN 09	10035		50540536	120031030050	L	4/13/2003	1535	55	1	55	OH SEC/DR CL NI	OH SC CL-N	8422	NEFF		DR										1	0
FORCED INTERR	GP	TWG4	2368M	26AAS	54670416	220031030053	F	4/13/2003	1540	114	2	228	BU DISC OR BARI	DISC/BARRL	ALDINE WESTF		1	LF	26AAS									1	0
FORCED INTERR	BL	HE 03	10670		52577527	120031030056	L	4/13/2003	1610	54	1	54	OH SEC/DR CL H	OH SC CL-H	5815	ROSE		DR										1	0
FORCED INTERR	HM	AD 03	20402		53648573	220031030057	T	4/13/2003	1710	56	3	168	BU DISC OR BARI	DISC/BARRL	1208	ALDINE BE		TF	536485775									1	0
FORCED INTERR	SL	SE 41	1A162	X36P	35578296	120031030058	F	4/13/2003	1720	58	1	58	SQUIRREL	SQUIRREL	2114	HWY 90E	1	LF	X36P									1	0
FORCED INTERR	CY	PI 41	21060	K50N	45754014	220031030058	F	4/13/2003	1722	107	26	2782	UNKNOWN	UNKNOWN	30210	MISTY ME	1	LF	K80N									1	0
FORCED INTERR	CH	OA 04	41365	4BES	57571526	320031030028	T	4/13/2003	1805	34	11	374	UNKNOWN	UNKNOWN	10721	BURMAN	1	TF	575715268									1	0
FORCED INTERR	SH	MY 08	31297	33FJ		320031030028	F	4/13/2003	1814	58	107	6206	CONTRACTOR-N	CON-NT HLF	3819	LOCHMOO	1	LF	33FJ									1	0
FORCED INTERR	CH	GW 02	40897	H9Z	56616288	320031030030	T	4/13/2003	1830	175	15	2625	UNKNOWN	UNKNOWN	9210	FOREST V	1	BU	566162892									1	0
FORCED INTERR.	SU	CE 01	11933		47535080	120031030056	T	4/13/2003	1840	33	3	99	BIRD	BIRD	14223	BAY GARI		TF	475350866									1	0
FORCED INTERR	SU	FD 15	10686		50520446	120031030070	T	4/13/2003	1840	72	4	288	LIGHTNING ARRE	LTNG ARRS	11630	RICEVILLI		TF	505204402									1	0
FORCED INTERR	BL	ST 01	10246	UR6	51544181	120031030077	T	4/13/2003	1855	44	10	440	BU DISC OR BARI	DISC/BARRL	5230	IMOGENE	1	TF	515441815									1	0
FORCED INTERR	BZ	LJ 02	30819	N25Y	53269368	320031030038	T	4/13/2003	1938	73	2	146	UNKNOWN	UNKNOWN	301	N BRAZOSP	1	BU	532693689									1	0
FORCED INTERR	SH	EL 08	30357		58507234	320031030036	T	4/13/2003	2031	299	1	299	COLLISION	COLLISION	15711	GULF FW		BU	585072301									1	0
FORCED INTERR	HC	SO 41	12620	H32H	53470505	120031030080	F	4/13/2003	2122	114	9	1026	BU DISC OR BARI	DISC/BARRL	2319	MUSTANG	1	LF	H32H									1	0
FORCED INTERR.	SU	AF 08	11798	I54M	48544256	120031040001	F	4/14/2003	0024	75	22	1650	UNKNOWN	UNKNOWN	7828	FAIR ACRE	2	LF	I54M									1	0
FORCED INTERR	SH	SP 03	30996	R70K	58538554	320031040006	F	4/14/2003	0433	61	1	61	UNKNOWN	UNKNOWN	2835	PRESTON	1	LF	R70K	TF	585385596							1	0
FORCED INTERR	CH	CV 06	40452	Y22S	59590033	320031040011	F	4/14/2003	0500	78	1	78	BU DISC OR BARI	DISC/BARRL	E.BELT, S OF W		1	LF	Y22S									1	0
FORCED INTERR	BA	BT 07	30925	M91M	62588262	320031040012	T	4/14/2003	0620	44	8	352	VINES	VINES	5009	FAIRWAY	1	TF	625882688									1	0
FORCED INTERR	CH	AD 02	40064	H6C	53639275	320031040002	F	4/14/2003	0700	72	31	2232	BIRD	BIRD	1533	HILL RD	1	LF	H6C	TF	536392791							1	0
FORCED INTERR	SB	SA 46	22883	Y12W	48620468	120031040000	F	4/14/2003	0715	287	56	16072	TERMINATOR	TERMINATO	7407	BROOKLEA	2	LF	Y12W	PR								1	0
FORCED INTERR	MP	BY 08	40198	W12E	54600282	220031040002	T	4/14/2003	0720	14	2	28	BU DISC OR BARI	DISC/BARRL	701	WAINWRIGI	1	TF	546002852									1	0
FORCED INTERR	MP	MP 05	41374	E87C	55566570	220031040000	T	4/14/2003	0735	57	2	114	UNKNOWN	UNKNOWN	704 70TH		1	TF	555665740									1	0
FORCED INTERR	MP	OA 07	41608	G47	57590339	320031040015	T	4/14/2003	0740	147	1	147	UNKNOWN	UNKNOWN	4310	1/2 OATES	1	TF	575903904									1	0
FORCED INTERR	HC	FD 10	10874	S3AA	50529400	120031040012	T	4/14/2003	0740	180	4	720	ANTS	ANTS	6287	LUDINGTO	2	SC	505294087									1	0
FORCED INTERR	BZ	BZ 02	30135	C10F	53259498	320031040016	T	4/14/2003	0751	84	1	84	OTHER EQUIPME	PULLED FUS	222	HIGHWAY 3	1	TF	532594985									1	0
FORCED INTERR	FB	OB 42	11370	50DB	45522004	220031040013	F	4/14/2003	0815	119	70	8330	TERMINATOR	TERMINATO	3006	JANE LONI	2	LF	50DB									1	0
FORCED INTERR	HM	KW 43	20173	U84W	57708301	220031040012	L	4/14/2003	0830	87	1	87	URD SEC PDSTL	URD SC PEC	3811	GARDEN L	2	SC										1	0
FORCED INTERR	SU	HY 11	11692		49566575	120031040015	T	4/14/2003	0835	65	4	260	LIGHTNING	LIGHTNING	1303	BRIARPAR		TF	495665727									1	0
FORCED INTERR	MP	ES 05	40256	S8B	54563188	220031040014	L	4/14/2003	0841	82	1	82	OH SEC/DR CL H	OH SC CL-H	3336	FRANCIS	1	DR										1	0
FORCED INTERR	MP	MP 08	41391	E49C	55561555	220031040016	F	4/14/2003	0840	30	33	990	SQUIRREL	SQUIRREL	5302	SHERMAN	1	LF	E49C									1	0
FORCED INTERR	MP	HG 04	41062	M79K	56550440	220031040017	T	4/14/2003	0844	94	1	94	UNKNOWN	UNKNOWN	1201	KELLOGA	1	TF	565504496									1	0
FORCED INTERR	BZ	LJ 08	30612	E56F	52275287	320031040022	T	4/14/2003	0844	52	4	208	BU DISC OR BARI	DISC/BARRL	128	TAMARISK	1	TF	522752877									1	0
FORCED INTERR	RS	LV 03	30594	62QK	55389451	320031040023	T	4/14/2003	0844	52	1	52	UNKNOWN	UNKNOWN	9522	HIGHWAY	1	TF	553894515									1	0
FORCED INTERR	FB	LC 01	11249	30AP	38303351	120031040015	T	4/14/2003	0855	137	1	137	UNKNOWN	UNKNOWN	3215	COCKBUR	1	TF	383035177									1	0
FORCED INTERR	GA	STW0	31003	E31E	64349484	320031040025	T	4/14/2003	0854	134	3	402	FOREIGN MATER	FRGN MATR	13807	SAN DOM	1	TF	643494840									1	0
FORCED INTERR	GA	MDY0	31022		67371040	320031040026	L	4/14/2003	0855	210	1	210	OH SEC/DR CL NI	OH SC CL-N	3405	KLEIMANN		SC										1	0
FORCED INTERR	SB	SA 43	21298	85CD	49615423	120031040020	T	4/14/2003	0855	167	3	501	BU DISC OR BARI	DISC/BARRL	10410	PAPALOT	1	TF	496154272									1	0
FORCED INTERR.	BZ	BZ 02	30135	C10F	53259498	320031040025	T	4/14/2003	0922	91	1	91	LIGHTNING	LIGHTNING	222	HIGHWAY 3	1	BU	532594985									1	0
FORCED INTERR	FB	EB 06	11295	R72S	38452206	120031040026	F	4/14/2003	0920	192	1	192	VINES	VINES	13430	BATTLE	1	LF	R72S									1	0
FORCED INTERR.	SH	WE 07	31369	44DT	59552340	320031040031	T	4/14/2003	0940	47	12	564	SQUIRREL	SQUIRREL	3617	SHERBRO	1	TF	565523429									1	0
FORCED INTERR	SB	GE 46	10220		47600311	120031040036	T	4/14/2003	1000	268	5	1340	URD SEC PDSTL	URD SC PEC	4306	KINLOCH		SC	478031170									1	0
FORCED INTERR	GP	LK 05	41296	G1R	52611420	220031040036	T	4/14/2003	1000	108	5	530	UNKNOWN	UNKNOWN	6617	BETHUNE	1	TF	526114205									1	0
FORCED INTERR	MP	BU 01	41588	56AJ	56574352	220031040033	T	4/14/2003	1038	93	4	372	BU DISC OR BARI	DISC/BARRL	1905	TURNING I	1	TF	565743523									1	0
FORCED INTERR	GP	BY 06	40169	73AAX	53618298	220031040038	F	4/14/2003	1054	0	0	0	CONTRACTOR-N	CON-NT HLF	119	LUETTA	1	LF	73AAX	PR								1	0
FORCED INTERR.	GP	BY 06				220031040038	F	4/14/2003	1054	68	59	5192	CONTRACTOR-N				1	LF	73AAX									0	0
FORCED INTERR	GP	BY 06				220031040038	F	4/14/2003	1054	187	21	3927	CONTRACTOR-N				1	LF	73AAX									0	0
FORCED INTERR	MP	EU 03	40711	A57L	52595251	220031040042	F	4/14/2003	1100	90	12	1080	UNKNOWN	UNKNOWN	W.23RD @ COU		1	LF	A57L									1	0
FORCED INTERR	GP	WF 04	20368	G13M	52671418	220031040044	F	4/14/2003	1101	141	22	3102	CONTRACTOR-N	CON-NT HLF	16234	SUMMER	2	LF	G13M	PR								1	0
FORCED INTERR	GP	LK 09	41310		52617246	220031040046	T	4/14/2003	1100	66	1	66	BU DISC OR BARI	DISC/BARRL	5902	BEALL ST		TF	526172455									1	0
FORCED INTERR	BL	HE 09	11556	2EZ	53570203	120031040046	L	4/14/2003	1117	63	1	63	OH SEC/DR CL H	OH SC CL-H	2100	TROON	1	DR										1	0
FORCED INTERR	BL	BI 02	10054	HD5	51568282	120031040055	L	4/14/2003	1130	59	1	59	OH SEC/DR CL H	OH SC CL-H	4718	WARING	1	DR			SC							1	0
FORCED INTERR	SU	JM 45	12089	W40F	47527226	120031040054	T	4/14/2003	1135	202	6	1212	UNKNOWN	UNKNOWN	1522	JO ANN LN	2	SC	475272390									1	0
FORCED INTERR	SH	PE 01	31299	91C	56472477	320031040056	T	4/14/2003	1135	92	6	552	OH SEC/DR CL H	OH SC CL-H	7646	COUNTY R	1	SC	564724752									1	0
FORCED INTERR	KY	GE 44	22737	T69F	45625195	120031040055	L	4/14/2003	1140	161	1	161	CONTRACTOR-N	CON-NT HLF	6822	HAVEN CR	2	SC										1	0
FORCED INTERR	GA	STW0	31011		65351058	320031040058	T	4/14/2003	1145	55	2	110	BU DISC OR BARI	DISC/BARRL	13304	STEWAR		TF	653510588									1	0
FORCED INTERR	FB	WR 12	11748		38380074	120031040058	T	4/14/2003	1140	54	3	162	BU DISC OR BARI	DISC/BARRL	3820	FM 1301		TF	383800788									1	0
FORCED INTERR	RS	RZ 01	3573A	W75O	50402018	320031040068	T	4/14/2003	1241	43	2	86	SQUIRREL	SQUIRREL	18510	LOCHNES	1	TF	504020182									1	0
FORCED INTERR	BL	HE 09	11556		52579346	120031040064	T	4/14/2003	1245	43	3	129	VINES	VINES	60	TIEL WY		TF	525793463									1	0
FORCED INTERR	SU	JM 43	12073	40AS	47520455	120031040065	L	4/14/2003	1251	80	1	80	CONTRACTOR-N	CON-NT HLF	18619	OLD RICH	1	SC		SC								1	0
FORCED INTERR	CY	PI 41	2436A	H38B	45757248	220031040063	T	4/14/2003	1300	74	4	296	VINES	VINES	36619	BROWN C	1	SC	457572480									1	0
FORCED INTERR	GP	RU 03	41682		53628384	220031040070	L	4/14/2003	1324	51	1	51	CONTRACTOR-N	CON-NT HLF	1135	CARBY		DR		SC								1	0
FORCED INTERR	HC	HOC0	11149	M9H	52513595	120031040078	T	4/14/2003	1350	197	11	2167	UNKNOWN	UNKNOWN	4122	BOYNTON	1	BU	525135939									1	0
FORCED INTERR.	CH	JP 07	41207	C79H	60581261	320031040085	L	4/14/2003	1400	126	1	126	UNKNOWN	UNKNOWN	721 1/2	PEMBER	1	DR		SC								1	0
FORCED INTERR.	HC	MV 01	14212	N49G	55447377	320031040085	L	4/14/2003	1430	116	1	116	COLLISION	COLLISION	23101	HIGHWAY	1	PD										1	0
FORCED INTERR	SB	WT 05	21831		51588204	120031040087	L	4/14/2003	1454	138	1	138	HUMAN ERROR	HUMN ERRC	8838	CHATSWC		SC		DR								1	0
FORCED INTERR.	SH	CA 05	30153	12ADR	58528418	320031040091	F	4/14/2003	1458	87	1	87	BU DISC OR BARI	DISC/BARRL	4410	CRENSHAW	3	DB	12ADR									1	0
FORCED INTERR	SH	WE 01	31239		58555552	320031040092	T	4/14/2003	1501	30	1	30	LIGHTNING	LIGHTNING	130	JEFFERSOI		TF	585555523									1	0
FORCED INTERR	SH	SP 07	30957	23HW	57538467	320031040094	F	4/14/2003	1515	82	1	82	UNKNOWN	UNKNOWN	1413	SPENCER	1	LF	23HW									1	0
FORCED INTERR.	GA	AL 09	31731	N50G	60438362	320031040097	F	4/14/2003	1556	39	68	2652	SQUIRREL	SQUIRREL	1625	AVENUE Q	1	LF	N50G									1	0
FORCED INTERR.	MP	UN 10	41741		55550339	220031040098	T	4/14/2003	1601	39	3	117	UNKNOWN	UNKNOWN	2915	DELAFIELE		TF	555503962									1	0
FORCED INTERR.	CH	GW 07	40910		56612181	320031040099	T	4/14/2003	1604	50	8	400	BU DISC OR BARI	DISC/BARRL	8401	WOODLYN		TF	566121610									1	0
FORCED INTERR	SH	CG 05				320031040101	C	4/14/2003	1607	0	0	0	ROTTEN POLE	ROTTEN PLI	9902	GULF FWY		CL	CG05	PD			BU	565				1	1
FORCED INTERR	SH	CG 05	3G040			320031040101	C	4/14/2003	1607	24	1461	35064	ROTTEN POLE					CL	CG05									0	0
FORCED INTERR	SH	CG 05	30920			320031040101	C	4/14/2003	1607	37	309	11433	ROTTEN POLE					CL	CG05									0	0
FORCED INTERR	SH	CG 05	30920	97DT	58538084	320031040126	T	4/14/2003	1607	745	1	745	ROTTEN POLE	ROTTEN PLI	9902	GULF FWY	1	BU	585380968	PD								1	0
FORCED INTERR	FB	BC 08	12887	W112	44468311	120031040100	F	4/14/2003	1800	103	25	2575	COLLISION	COLLISION	3006	FM 2977	1	LF	W112	SC								1	0

75 KVA URD TR. NEEDED REPL. ON MONDAY AND CLEAN-UP CREW FOR WIN CLEAN TR. IS WORKING BUT WILL NEEDED REPLACING ASAP FIRST THING MONDAY 7200/120-240 1 0
RECEIVED REPORT OF PD @ 7146 BELLFORT CREWS FOUND 2 POLES BROKE ON TOP OF BUILDING AND CAUGHT FIRE, ISOLATED FAULT AND MADE REPAIRS ON OH TBL ORDER 384 IN 1 1
0 0
0 0
REFUSE TP P90R. REF TP 1 0
REPL 50KVA ANSI 1 PMT WITH SAME; RPLD BAU TR SUBCARED, SEE SO# 8042, JRK 1 0
0 0
0 0
REPLACED BAD FUSE BARREL ON TRANS RPLD BAU BARREL ON TR; 1 0
REFUSE 8 PHASE WE3. REF LF 1 0
REPLACED LIMITER ON 8 PHASE LOTS OF CBP TRANS BEHIND STEP BANK; REF LF RPLD LIMITER @ TR, REF TR. 1 0
REIRET 80 CBP OUT DUE TO FRE LAST NIGHT @ 216 FISHER REMOVED MTR AND DROPS MTR#84000651 GB1 READ 76237 REIRET TR. 1 0
REFURB TRANSFORMER AND REPLACE LIMITER ON TRANSFORMER ...RGR 1 0
TRIMMED TREES OUT OF OPEN DELTA BANK AND REFUSED POWER POT REF TR 1 0
EASEMENT NEEDS TREE TRIMMING. REFUSED TRANS HAS WILDLIFE PROTECTION; REF TR. RGR 1 0
RPLD BAU BARREL ON TR; 1 0
REFUSE 1 P (M12P- 50T) DUE TO BIRD , REF TP 1 0
REFUSED TRANS. REF TR; 1 0
REPLACED 37.5 MRB WITH THE SAME SPLICED OUT X PRI. REF TP; RPRD URD PR. RPLD BAU TR. ...S/O 8046, STN. SUBCABINO NOT NECESSARY CREW DID NOT ISOLATE. CAC 1 0
REF TR; 1 0
REPLACED BAD ELBOW AT 11818 ARROOYO VIETA, REF TP; 1 0
REPLACED ELBOW AT 11818 ARROYO VIETA REFUSED T P # P19A, REF TP; 1 0
REPLACED BAU FUSE BARREL, RPLD BAU BARREL ON TR MEK 1 0
REPLACED 25 KAMAT LIMITER & 35 KVA LIGHTING ARRESTER RPLD LIMITER @ TR, REF TR, RPLD LIGHTNING ARRESTOR. MEK 1 0
REFUSED LINE FUSE, REF LF MEK 1 0
NEED TO INSTALL WILD LIFE PROTECTION ON TR IN REAR OF2203 ELMGATE; REF TR; MEK 1 0
REF 75KVA XFMER OUT BY SQUIRREL—NEED WLIF INST —2ND TIME IN A FEW WEEKS- TRK ACCESS THRU STORAGE BLDG MON. - FRI., REF TR 1 0
REPLACED BAD 50 KVA 7200 120/240 OH POT W/BANE OPT TO OPT., RPLD BAU TR, REF TR. NO SUBCABE NEEDED PEK 1 0
POSSIBLE INTERNAL PROBLEM W/ 50KVA 7200/ 120/ 240 POWNT LIVE FRONT - BEST TR

FORCED INTERR	GP	RU 03	41659		53628074	220031040091	T	4/14/2003	1604	363	7	2541	UNKNOWN	UNKNOWN	505 RITTENHOL	BU	536280742			RPLD BAJ TR	1	0
FORCED INTERR	SH	SH 01	30894	PR5	57524570	320031040102	T	4/14/2003	1600	68	7	476	UNKNOWN	UNKNOWN	711 GILPIN 1	TF	575245700			REFUSED A 25 KVA LIGHTER---PULLED FUSE, REF TR.	1	0
FORCED INTERR	HC	BL 07	10793	B91J	50529084	220031040103	T	4/14/2003	1627	53	5	265	BU DISC OR BARI	DISC/BARRL	14217 MAIN ST 1	TF	505290847			FUSE BARREL FELL OPEN CLOSE IT BACK COULD NOT TELL WHAT MADE IT OPEN UP UNLESS IT HAS A WEAK DISCONNECT CUST NOTIFY REF TR	1	0
FORCED INTERR	MP	GG 06	40975	14SP	55543385	220031040094	T	4/14/2003	1628	39	3	117	BU DISC OR BARI	DISC/BARRL	6427 SPRINGER 1	TF	555433857			RPLD BAJ BARREL ON TR.	1	0
FORCED INTERR	MP	CR 01	40516		53589467	220031040096	T	4/14/2003	1657	47	3	141	BU DISC OR BARI	DISC/BARRL	3303 1/5 N MAIN	DB	535894677			REPLACED A 15 KV KEARNEY FUSE BARREL ON A 50 KVA 7200 120 240 V TRAN. RPLD BAJ BARREL ON TR, REF TR.	1	0
FORCED INTERR	GP	SA 01	21177	I59S	49623402	220031040096	F	4/14/2003	1722	91	10	910	UNKNOWN	UNKNOWN	15714 LAKEVIEV 2	LF	I59S			REF TP	1	0
FORCED INTERR	SU	BAR42	11857		47541376	120031040110	T	4/14/2003	1722	314	3	942	UNKNOWN	UNKNOWN	7226 WINKLEMA	BU	475413769			REPL 15KVA 15 8 120/240 OH SEC WITH 75KVA 120/240 OH TRF RPLD BAJ TR, REF TR.	1	0
FORCED INTERR	BL	HP 02	40606	2CB	53575234	120031040117	F	4/14/2003	1740	61	55	3355	UNKNOWN	UNKNOWN	606 W SAULNIE 1	LF	2CB			REF LF	1	0
FORCED INTERR	FB	DA 06				120031040120	C	4/14/2003	1800	0	0	0	COLLISION	CAR	1603 PIPELINE	CL	DA06	PD		NO AUTOMATION 18-WHEELER HIT POLE CREW CALLED OUT TO REPLACE POLE CREW RESTORING AB MUCH SERVICE AB POSSIBLE CREW ON SITE TC	1	1
FORCED INTERR	FB	DA 06	11326			120031040120	C	4/14/2003	1800	38	258	9804	COLLISION			CL	DA06				0	0
FORCED INTERR	FB	DA 06	11325			120031040120	C	4/14/2003	1800	140	67	9360	COLLISION			CL	DA06				0	0
FORCED INTERR	FB	DA 06	1191A			120031040120	C	4/14/2003	1800	313	71	22223	COLLISION			CL	DA06				0	0
FORCED INTERR	GP	RU 05	41675	6HR	53622267	220031040107	T	4/14/2003	1828	63	4	252	TREE CLEARANC	TREE CLEAI	314 E KOWIS 1	TF	536222671			REF TR	1	0
FORCED INTERR	MP	UN 11	41752	B8t	54554267	220031040118	F	4/14/2003	1828	54	24	1296	UNKNOWN	UNKNOWN	4101 ROSENEA 1	LF	B81			FOUND NORTH PHASE OF B81 100 T BLOWN, B AND C WERE IN RODE OUT LINE NO CAUSE FOUND BACK ON AT 1823 HRS REF LF	1	0
FORCED INTERR	CH	GP 08	40823	J34	57562544	320031040114	F	4/14/2003	1833	48	36	1728	UNKNOWN	UNKNOWN	1505 11TH 1	LF	J34			REF LF.	1	0
FORCED INTERR	GP	KI 44	20580	17KM	50694267	220031040112	F	4/14/2003	1837	0	0	0	TRANSFORMER	TRANSFRMI	5502 WESTBRO 2	LF	17KM	BU	506951287	RPLD BAJ TR.	1	0
FORCED INTERR	GP	KI 44				220031040112	F	4/14/2003	1837	151	6	906	TRANSFORMER		2	LF	17KM				0	0
FORCED INTERR	GP	KI 44				220031040112	F	4/14/2003	1837	151	34	5134	TRANSFORMER		2	LF	17KM				0	0
FORCED INTERR	GP	KI 44				220031040112	F	4/14/2003	1837	553	3	1659	TRANSFORMER		2	LF	17KM				0	0
FORCED INTERR	SB	EC 05	21704	8BN	50585331	120031040136	F	4/14/2003	1914	38	8	304	UNKNOWN	UNKNOWN	9014 BACE 1	LF	88N			REF LF	1	0
FORCED INTERR	GA	STW0	31003	A26M	64348334	320031040119	L	4/14/2003	1918	163	1	163	OH SEC/DR CL HI	OH SC CL-H	4110 SURF 1	SC				RPLD SEC CONN @ PL-1 CUST	1	0
FORCED INTERR	HM	LW 41	22066	G96R	56650181	220031040115	F	4/14/2003	1922	41	17	697	UNKNOWN	UNKNOWN	14918 HICKORY 1	LF	G96R			REFUSED LINE FUSE, REF LF	1	0
FORCED INTERR	GA	GA 09	31224	R3U	67377456	320031040120	F	4/14/2003	1932	95	28	2470	BU DISC OR BARI	DISC/BARRL	52ND @ AVE S 1	DB	R3U			REPLACED BAD DISC, RPLD BAJ DISC-LF NOT BLOWN.	1	0
FORCED INTERR	SH	PE 04	30815	E40B	55481276	320031040122	L	4/14/2003	2011	1	1	1	OH SEC/DR CL HI	OH SC CL-H	6929 MEADOW I 1	DR				REPLACED CLAMPS AT WHEAD WAS STOPPED BY CUSTOMER WHICH EXPLAINS THE TIMER, RPLD CONN @ WH.	1	0
FORCED INTERR.	MP	CR 01	40516		53589467	220031040117	T	4/14/2003	2011	146	3	438	UNKNOWN	UNKNOWN	3303 1/5 N MAIN	BU	535894677			REPLACED 7200 2KVA 120/240 WITH THE SAME PICKED UP/DROP OFF AT MAG PK, RPLD BAJ TR.	1	0
FORCED INTERR	BL	BR 04	10489	61G	52542476	120031040146	T	4/14/2003	2100	61	8	488	BU DISC OR BARI	DISC/BARRL	4043 DURNESS 1	TF	525424784			REPLACED BURNT UP KEARNY FUSE BARREL IN OPEN DELTA BANK 25 KVA POWER POT OLD AGE. REF TR.	1	0
FORCED INTERR	CH	NM 03	41521	82JN	57586115	320031040126	T	4/14/2003	2100	35	1	35	UNKNOWN	UNKNOWN	12333 EAST FW 1	TF	575861155			replaced a 120 frame beam and sensor NOR REF TR.	1	0
FORCED INTERR	CH	NM 01	41500		58580125	320031040125	L	4/14/2003	2128	85	1	85	OH SEC/DR CL HI	OH SC CL-H	12910 EAST FW	DR				repl clamps at wh on high leg, RPLD CONN @ WH	1	0
FORCED INTERR	GA	GL 06	30491	P2W	68387428	320031040130	T	4/14/2003	2132	92	7	644	BU DISC OR BARI	DISC/BARRL	1324 AVENUE N 1	DB	683874287			REPLACED BAD BARREL ON CLOSED DELTA BANK 1322 N V2. RPLD BAJ BARREL ON TR.	1	0
FORCED INTERR	BA	CO 11	41948		83577370	320031040131	T	4/14/2003	2138	37	11	407	TREE CLEARANC	TREE CLEAI	118 GRESHAM S	TF	635773707			XFMR LOCATED AT 110 GRESHAM LARGE TREE HAS GROWN UP AROUND POLE AND XFMR TREE NEEDS TO BE REMOVED CUST BAD IT WOULD BE OK TO REMOVE HE NEEDS 2 PEN DOGS	1	0
FORCED INTERR	KY	KT 41	22587	50HB	42599027	120031040146	T	4/14/2003	2216	30	2	60	FALLING DEAD TI	TR FL/DEAD	5814 DELFREN 1 1	TF	425990271			REF TR	1	0
FORCED INTERR	MP	NS 02				220031040122	C	4/14/2003	2311	0	0	0	COLLISION	COLLISION	4000,FULTON *4	CL	NS02	PD		NON 10% CKT SEE TBL RWO #210 REPORT OF POLE DOWN AT 4000 BLOCK OF FULTON DUE TO CAR ACCIDENT CREWS ENROUTE PEK	1	1
FORCED INTERR	MP	NS 02	2G221			220031040122	C	4/14/2003	2311	37	808	29896	COLLISION			CL	NS02				0	0
FORCED INTERR	MP	NS 02	41542			220031040122	C	4/14/2003	2311	50	801	30050	COLLISION			CL	NS02				0	0
FORCED INTERR	MP	NS 02	41541			220031040122	C	4/14/2003	2311	63	655	41265	COLLISION			CL	NS02				0	0
FORCED INTERR	SB	ME 05	21604		48570676	120031050001	T	4/15/2003	0004	35	4	140	UNKNOWN	UNKNOWN	778 THORNBRA	TF	485705796			REF TR.	1	0
FORCED INTERR	FB	WR 10	11188	J89F	37410280	120031050015	L	4/15/2003	0150	145	7	1015	OH SEC/DR CL HI	OH SC CL-H	7604 COLORADO 1	SC	374102808			NEED TO REPLACE POLE AND RUN 4/0 SECONDARY IN THE NEAR FUTURE I REPLACED 1 SPAN OF #2 COPPER SECONDARIES WITH 1/0 TWIST POLE IS LOCATED AT 7604 COLORADO RPLD	1	0
FORCED INTERR	GP	FR 44	21407	M33Z	50625477	220031050014	F	4/15/2003	0332	0	0	0	TERMINATOR	TERMINATO	7502 WOODSAW 2	LF	M33Z	PR		BAD TERMINATOR ON (R) TP 180L URD PR.	1	0
FORCED INTERR	GP	FR 44				220031050014	F	4/15/2003	0332	169	37	6253	TERMINATOR		2	LF	M33Z				0	0
FORCED INTERR	BZ	VL 04	3526D	N45Y	57241181	320031050002	T	4/15/2003	0420	154	2	308	BU DISC OR BARI	DISC/BARRL	1902 POINT LAF 1	TF	572411814			REPL FUSE BARRELL 15KVA TF RPLD BAJ BARREL ON TR.	1	0
FORCED INTERR	SU	BAR4E				120031050006	C	4/15/2003	0600	0	0	0	COLLISION	COLLISION	16400 ALIEF CLI	CL	BAR46	PR	PD	10% CKT CAR HIT POLE @ 16400 ALIEF CLOSINE, CREWS ISOLATED FAULT AND MADE REPAIRS On TBL ORDER #108 CEWOH4-MMC/TWS AUTOMATION SECTION 11804	1	1
FORCED INTERR	SU	BAR42	1G298			120031050006	C	4/15/2003	0601	45	470	21150	COLLISION			CL	BAR46				0	0
FORCED INTERR	SU	BAR46	1G298			120031050006	C	4/15/2003	0601	45	1406	63270	COLLISION			CL	BAR46				0	0
FORCED INTERR	SU	BAR46	11473			120031050006	C	4/15/2003	0601	92	2061	189612	COLLISION			CL	BAR46				0	0
FORCED INTERR	SU	BAR46	11908			120031050006	C	4/15/2003	0601	133	491	65303	COLLISION			CL	BAR46				0	0
FORCED INTERR	GP	BA 42	20698	U30Y	51673117	220031050006	T	4/15/2003	0701	141	8	1128	FOREIGN MATER	FRGN MATR	14022 WALTERS 1	TF	516731170	PR			1	0
FORCED INTERR	BL	UL 49	10343	75U	51563254	120031050025	F	4/15/2003	0711	72	21	1512	TREE CLEARANC	TREE CLEAI	5710 FAIRDALE 1	LF	75U			REFUSED BOTT CM PHASE OF L F 75U TREES HAVE GROWN UP INTO C PHASE EASEMENT IS IN NEED OF TRIMMING REF LF MEK	1	0
FORCED INTERR	GP	BA 43	22074		50853342	220031050021	T	4/15/2003	0711	56	3	168	VINES	VINES	11538 COLONIA	TF	508533428			REF TR	1	0
FORCED INTERR	HC	BL 04	10775	N75L	51510088	120031050033	F	4/15/2003	0733	150	31	4650	SPLICE	SPLICE	14903 FOUR WI 2	LF	N75L	PR		FOUND BAD PRIMARY IN FIRST POT FROM X TP MADE PERMANENT REPAIRS AND REFUSED TP REF TP RPRD URD PR.	1	0
FORCED INTERR	SU	RO 03	12236	F93	49531327	120031050036	T	4/15/2003	0745	56	2	112	SQUIRREL	SQUIRREL	9811 BOONE 1	TF	495313238			REF 50 L POT NEED TRIM TREE AN VINES AWAY FROM POLE. REF TR.	1	0
FORCED INTERR	SU	WZ 43	12346		49551348	120031050037	L	4/15/2003	0744	125	1	125	OH SEC/DR CL HI	OH SC CL-H	11398 HARWIN I	SC				RPRD SEC-1 CUST	1	0
FORCED INTERR	SU	CE 08	12025		47535440	120031050041	T	4/15/2003	0800	59	4	236	SQUIRREL	SQUIRREL	14423 SWANFIE	TF	475354032			REFUSE 50 BKL, REF TR;	1	0
FORCED INTERR	SU	WD 42	21554			120031050066	C	4/15/2003	0811	0	0	0	COLLISION	COLLISION	13405 1/2 KATY	PC	WD42			CREW FOUND CAR HIT PTS 4403 & KNOCKED "A" PHASE OPEN ON PTS 4403 - PICKED UP TAIL END & PTS 4403 OPEN FOR REPAIRS - SECTION #21564 - NON 10% CRH	1	0
FORCED INTERR	SU	WD 42	11598			120031050066	C	4/15/2003	0811	37	461	17057	COLLISION			PC	WD42				0	0
FORCED INTERR	MP	ES 02	40647		54577042	220031050025	L	4/15/2003	0820	66	1	66	OH SEC/DR CL HI	OH SC CL-H	516 MILBY	SC				RPLD SEC CONN @ PL-1 CUST	1	0
FORCED INTERR	HC	HOC0	11157		52530158	120031050065	T	4/15/2003	0834	71	10	710	SQUIRREL	SQUIRREL	4529 KINGFISHE	TF	525301583			REFUSED A 50 KVA LIGHTER. SQUIRREL REF TR.	1	0
FORCED INTERR	SB	ADK42	20959		49618145	120031050071	L	4/15/2003	0844	85	1	85	FLLNG TREE OUT	TREE FL/OE	5721 WINDFER	SC		DR		REPAIR NEUT IN IN DROPS MID-SPAN ALSO @ SERVPOLE & REPLACED CLAMPS @ THE WH, RPRD DR. RPLD CONN @ WH. RPLD SEC CONN @ PL-1 CUST MEK	1	0
FORCED INTERR	BL	UL 49	10343	75U	51563268	120031050086	T	4/15/2003	0910	65	7	455	SQUIRREL	SQUIRREL	5703 DOLORES 1	TF	515632602			TRIMMED TREE FROM & REFUSED TR OUT BY SQUIRREL TR ALREADY HAS WA, PROT NEED TO RELOCATE BOND WIRE AWAY FROM HIGH SIDE JUMPER S/C CONN REF TR MEK	1	0
FORCED INTERR	HM	SW 08	41694	3GC	56637555	220031050034	F	4/15/2003	0915	67	40	2680	TREE CLEARANC	TREE CLEAI	13907 NIGHTINC 1	LF	3GC			NEED TO HAVE TREE TRIMMING DONE IN SEVERAL LOCATION BEHIND THIS LINE FUSE REF LF MEK	1	0
FORCED INTERR	RS	LV 02	31555	PN7	55350010	320031050014	L	4/15/2003	0911	73	1	73	TREE CLEARANC	TREE CLEAI	1815 AVENUE F 1	DR				FOUND BROKEN NEUTRAL MID-SPAN AND HOT LEGS FRING UP---REPLACED #4 DROPS. RPLD DR.	1	0
FORCED INTERR	SH	HA 01	31636			320031050036	C	4/15/2003	0921	0	0	0	POLE TOP SWITC	JUMPER	PTS 9368 ON KU	PC	HA01	PR		NON 10% S/O # 367 B PHASE JUMPER BURNT OFF NORTH EAST SIDE OF PTS 9368 SECTION # 30547 TRB 3213 MADE REPAIRS TO PTS 9368 @ 1135 MKC	1	0
FORCED INTERR	SH	HA 01	30184			320031050036	C	4/15/2003	0921	59	271	15989	POLE TOP SWITC			PC	HA01				0	0
FORCED INTERR	GP	KI 43	21931	90ADF	49675217	220031050047	T	4/15/2003	1002	157	2	314	VINES	VINES	9406 FENCHURI 1	TF	496752128	PR		REPLACED LIMITER CLEARED VINES FROM TRX POLE, RPLD LIMITER @ TR REF TR RGR	1	0
FORCED INTERR	FB	WR 14	11265		36383011	120031050106	T	4/15/2003	1011	33	4	132	BU DISC OR BARI	DISC/BARRL	1125 W MILAM 1	TF	363830180			RPLD BAJ BARREL ON TR. RGR	1	0
FORCED INTERR	FB	DA 06	1191A		45354538	120031050106	T	4/15/2003	1011	84	2	168	SQUIRREL	SQUIRREL	3531 OLD DAMC	TF	453545388			REFUSED 25 KVA---- INSTALLED VKG. REF TR	1	0
FORCED INTERR	FB	EB 05	11291	K72	34447128	120031050111	L	4/15/2003	1031	63	1	63	TREE CLEARANC	TREE CLEAI	33307 TIDEWAT 1	SC				PICK UP 1 SPAN W/2 AL PRIMARY & SPANS 8 OF 33203 HOPE WE ARE IN THE R IGHT PLACE, PUP PR-FUSE NOT BLOWN RGR	1	0
FORCED INTERR	SU	BAR44	11877	N27U	47540545	120031050111	T	4/15/2003	1033	102	8	816	OTHER	HOUSE FIRE	15315 LA MANCI 2	TF	475405457			FIRE CUT OUT-RMVD MTR & DROPS, REMOVED METER AND DISCONNECTED DROPS IN XFMR PER FIRE CHIEF CUST NOTIFIED METER WB1830843 READING L TO R 78918 X 001 FIRE-RMVD &	1	0
FORCED INTERR	MP	WO 14	41888	24F	51607369	120031050115	L	4/15/2003	1037	50	1	50	OH SEC/DR CL NI	OH SC CL-N	4514 LIBBEY LN 1	DR				REPLACED NEUT CLAMP @ THE WH, RPLD CONN @ WH.	1	0
FORCED INTERR	SB	DH 04	21528		51603578	120031050114	T	4/15/2003	1040	94	7	658	OH SEC/DR CL HI	OH SC CL-H	5141 ANTOINE D	SC	518035780			HIGH LEG CONNECTION BURNT OFF @ PADDLE REPLACED WITH CT CLAMP RPRD BUSS WORK @ TR	1	0
FORCED INTERR	CY	KDL44				220031050046	C	4/15/2003	1042	125	126	1890	CONTRACTOR-N	CON-NT HLF	FM 2920 & KUYP	CL	KDL44			KDL 44 LOCKED OUT ON ONE TRIP CREW DRIVING BY SAW CUST CLEARING PROPE RTY @ FM 2920 & KUYKENDAHL DROP TREE INTO PRI CREW REMOVED TREE AND CKT WAS MADE BACK	1	1
FORCED INTERR	GP	KDL43	2439L			220031050055	C	4/15/2003	1042	15	3503	52545	CONTRACTOR-N	CON-NT HLF	FEEDING OF B I	CL	KDL43			KDL 43 WAS FEEDING OFF THE B BRKR OF KDL44 DUE TO TFR1 BEING BWITCHED OUT KDL44 LOCKED OUT ON ONE SHOT CREW DRIVING BY SAW CUST CLEARING PROPERTY AND DROPPED	1	1
FORCED INTERR	SH	HA 01	30547	I97U	57502576	320031050042	F	4/15/2003	1050	119	26	3094	UNKNOWN	UNKNOWN	10330 SAGETRA 2	PR	I97U			REPLACED END LUGS ON 3LY PRI IN TRAN #71 ON BO 8085. RPRD URD PR	1	0
FORCED INTERR	SH	SP 10	30674	63LG	58521409	320031050044	T	4/15/2003	1057	161	2	322	UNKNOWN	UNKNOWN	730 KEITH AVE 1	SC	585214989	SC		REPAIRED VCOPPER BUSS WORK, RPLD CONN @ TR, RPLD CONN @ PL.	1	0
FORCED INTERR	MP	AN 02	40012		53593246	220031050074	T	4/15/2003	1105	41	2	82	BU DISC OR BARI	DISC/BARRL	405 E 20TH 1	CL	535632466			REPLACED BURN UP FUSE BARREL ON A 25KVA POWER TRANS, RPLD BAJ BARREL ON TR.	1	0
FORCED INTERR	GP	LK 03	40923	H11G	52619351	220031050077	T	4/15/2003	1102	62	2	124	UNKNOWN	UNKNOWN	540 W OBION 1	TF	526193518			FOUND ALL 3-50 KVA TRANS BLOW IN CLOSED DELTA BANK, CUST JUST LIKES BURLD ING FOR STORAGE, BAYS IT COULD HAVE BEEN OFF A COUPLE OF WEEKS. REFUSED ALL 3 TRANS. REF	1	0
FORCED INTERR	GP	BA 41	20653	S96R	50675387	220031050082	T	4/15/2003	1111	57	5	285	SQUIRREL	SQUIRREL	15414 MISTY HC 1	TF	506753878			REFURB 100 KVA LIGHTER---A1---TRAE HAS WLP REF TR. RGR	1	0
FORCED INTERR	FB	RS 08	11411	W195	42483277	120031050125	T	4/15/2003	1121	72	1	72	O/H PRIMARY CU	OH PR CLMF	2460 1/2 HIGHW 1	TF	424832756			PULLED FUSE ON 100KVA TR, REF TR.	1	0
FORCED INTERR	HC	BL 04	10773	37AA	51510131	120031050126	T	4/15/2003	1128	87	10	870	ANTS	ANTS	14422 Lone Willo 2	SC	515101315			Made temp repairs to broil road bore bar in urd # 37 BC 14422 Lone Willow Court. Unable to get bolts home to replace neutral buss bar Hoping to replace bore bar b/c conn 75 KVA 7200-120-240 # RPLD CONN	1	0
FORCED INTERR	SL	RB 02	22449		35671166	120031050132	T	4/15/2003	1144	96	1	96	UNKNOWN	UNKNOWN	1380 WALTON	TF	356711608			RFZ LTRUPIN DLTA, REF TR.	1	0
FORCED INTERR	BL	KB 12	10182		52564018	120031050133	T	4/15/2003	1151	99	6	594	SQUIRREL	SQUIRREL	3743 PURDUE	TF	525640194			REF TR.	1	0
FORCED INTERR.	SB	EC 04	21700	FR6	50592098	120031050136	T	4/15/2003	1208	53	8	424	UNKNOWN	UNKNOWN	9301 LONG POII 1	TF	505920864			CUST WAS CALLING ABOUT SECONDARIES GETTING TOGETHER AT 1706 SPUR REFUSED 75 KVA TRANS REF TR MEK	1	0
FORCED INTERR	SB	EC 04	21701	CL2	50591047	120031050137	F	4/15/2003	1208	87	128	11136	UNKNOWN	UNKNOWN	9580 LONG POII 1	LF	CL2			REFUSED LINE FUSE CL2 REF LF.	1	0
FORCED INTERR	SH	WE80	31180	N116N	60468355	320031050057	F	4/15/2003	1230	56	14	784	VINES	VINES	522 BARBUDA 2	LF	N116N			REFURED T/P / CUT TREES AND VINES AWAY / LEFT DOOR HANGER, REF TP	1	0
FORCED INTERR	SB	ADK44	21307	35KQ	50602511	120031050138	T	4/15/2003	1240	49	1	49	UNKNOWN	UNKNOWN	9348 BAYTHORI 1	TF	506025134			FUSE BROKE REF TR.	1	0
FORCED INTERR	FB	RS 04	11400	N5H	43485377	120031050141	T	4/15/2003	1300	41	8	246	SQUIRREL	SQUIRREL	1215 3RD 1	TF	434853720			INSTALL WLP & REF 2NVA---TREE RAT, REF TR.	1	0
FORCED INTERR	RS	MU 01	31440	52DM	57413563	320031050066	T	4/15/2003	1333	171	7	1197	UNKNOWN	UNKNOWN	3503 LONGWOC 1	BU	574135635			REPLACED 25 KVA TRANS WITH THE SAME. RPLD BAJ TR.	1	0
FORCED INTERR	CH	LY 42	4707G	E46J	58639066	320031050067	T	4/15/2003	1333	37	5	185	SQUIRREL	SQUIRREL	11423 E JACINT 1	TF	586390832			RO, REF TR. MEK	1	0
FORCED INTERR	SH	TE 04	31085	4LU	56491399	320031050068	F	4/15/2003	1341	51	5	255	UNKNOWN	UNKNOWN	2110 N HOUSTC 1	LF	4LU			REFURED N PHASE OF LF --TREE'S OR A SQUIRREL ON A UNCOVERED CAP REF LF	1	0
FORCED INTERR	SB	ADK42	21319	A28K	49616273	120031050153	F	4/15/2003	1348	52	3	156	TREE CLEARANC	TREE CLEAI	10151 ALFRED L 1	LF	A28K	PR		REF LF RPLD LIMITER @ TR.	1	0
FORCED INTERR	GP	FR 46	21364		50622274	220031050094	T	4/15/2003	1348	144	4	576	URD SEC PDSTL	URD SC PEI	7307 WOOD BLI 1	SC	506222746			REPLACED PED A (1) HOT & POS MOLEHEAD, RPLD SEC CONN @ PED-A 1 CUST RPLD PED	1	0
FORCED INTERR	GA	STW0	31643	Y75F	66365598	320031050071	F	4/15/2003	1352	15	6	90	COLLISION	COLLISION	34 CAMPECHE C 1	LF	Y75F			TRK 9484 --- NEED METRAL RAISED A PIKO UP ON BCHAPER ----NEED PALMS TRIMMED @ 1418-1119-1220 103RD & 1208 BHPPERSM ALL TRK ACCESS ---TRAIBH TRK HITN L F WIRES @ BCHA	1	0
FORCED INTERR	MP	CR 01	40533		53588447	220031050097	T	4/15/2003	1411	37	15	555	UNKNOWN	UNKNOWN	303 BAYLAND A	TF	535884474			REF TR, RESET TR. RGR	1	0
FORCED INTERR	BL	HE 09	11556		52579348	120031050171	T	4/15/2003	1540	48	3	144	UNKNOWN	UNKNOWN	60 TIEL WY 1	TF	525793463			REF TR.	1	0
FORCED INTERR	SB	SR 15	21421		49596271	120031050176	T	4/15/2003	1610	62	4	248	O/H PRIMARY CU	OH PR CLMF	1815 GESSNER	PR	495962720			RPLD BAD PR JUMPER-FUSE NOT BLOWN.	1	0
FORCED INTERR	KY	FZ 44	13788	U73K	45586355	120031050186	F	4/15/2003	1628	189	27	5103	FLLNG TREE IN E	TREE FL/AE	1710 WESTMEA 2	LF	U73K			XM TREE LIMB FROM X TP U73K WILL NEED TREE CREW FOLLOW-UP ON TREE LIMBING, REF TP MSG SENT TO B/C TLA	1	0
FORCED INTERR	SH	SB 03	31037	I19F	58559345	320031050087	F	4/15/2003	1630	60	28	1680	SQUIRREL	SQUIRREL	3120 ALBEMARL 1	LF	I19F			REF LF.	1	0
FORCED INTERR	BL	GT 04	10651	2JF	53564255	120031050183	T	4/15/2003	1641	58	20	1160	HUMAN ERROR	HUMN ERRC	1118 BANKS ST 1	TF	535642550			FUSE PULLED OUT. REF TR.	1	0
FORCED INTERR	HC	AM 06	10753	F57Z	52528165	120031050184	T	4/15/2003	1642	67	10	670	TREE CLEARANC	TREE CLEAI	2914 TRAIL LAKI 1	TF	525281670			NEEDS TREE TRIMMING AT 2910TRAIL LAKE, REF TR, MSG SENT TO B/C TLA	1	0
FORCED INTERR	CH	SW 10	41980	DC5	55632048	320031050088	L	4/15/2003	1651	82	1	82	COLLISION	COLLISION	11605 WESTWA 1	DR				CUST SNATCH DROPS DOWN WHILE MOVING TRAILER PAJ DR REBAGGED DR.	1	0
FORCED INTERR	SH	PA 09	30767	UC1	57545354	320031050089	L	4/15/2003	1700	80	1	80	OTHER	OTHER	1202 CASCADE 1	PD				POLE IS STUBBED BUT NEEDS TO BE REPLACED MSG SENT TO B/C TLA	1	0
FORCED INTERR	BA	LP 07				320031050092	C	4/15/2003	1710	0	0	0	COLLISION	COLLISION	502 1/2 S HIGHV	CL	LP07	PR	PD	BU 625	1	0
FORCED INTERR	BA	LP 07	3G336			320031050092	C	4/15/2003	1710	41	318	13038	COLLISION			CL	LP07				0	0
FORCED INTERR	BA	LP 07	31023			320031050092	C	4/15/2003	1710	63	444	27972	COLLISION			CL	LP07				0	0
FORCED INTERR	BA	LP 07	41715			320031050092	C	4/15/2003	1710	103	364	37492	COLLISION			CL	LP07				0	0
FORCED INTERR	GP	BA 02	20623		50664394	220031050116	T	4/15/2003	1722	39	3	117	UNKNOWN	UNKNOWN	5503 BOYCE SP 1	TF	506843942			REF TR.	1	0
FORCED INTERR	SU	STF06	12292	36EU	48519468	120031050191	T	4/15/2003	1740	131	5	655	TREE CLEARANC	TREE CLEAI	118 OAK ST 1	BU	485194682			CHANGED OUT A 25 KVA C&P TRANS WITH A 50 KVA CONV ADDED A SWITCH A NEF ARM LIGHTING ARRESTOR BQU OR WIRE RPLD BAJ TR, REF TR. RMVD TREE,W/B OFF PR	1	0
FORCED INTERR

FORCED INTERR	MP	BH 08	40304	16AEK	55580118	220031050127	T	4/15/2003	1856	33	1	33	BU DISC OR BARI	DISC/BARRL	4403 EAST FWY	1	TF	555801184				REPLACED A BURN UP FUSE BARREL ON A 75 KVA 7200 120 240 V WEST POWER TRANSFORMER IN A CLOSED DELTA BANK, RPLD BAU BARREL ON TR, REF TR.		1	0
FORCED INTERR	BL	BR 04	10496	N58	52555161	120031050202	T	4/15/2003	1918	284	8	2272	OH SEC/DR CL H	OH SC CL-H	3514 GRAMERC	1	BU	525551610				REPLACED BAD TRANS., RPLD BAU TR.		1	0
FORCED INTERR	HC	AR 42	15838	75AA	52481264	120031050205	F	4/15/2003	1957	81	6	486	BU DISC OR BARI	DISC/BARRL	FM 521, N OF TF	1	LF	75AA				RPLD BAU BARREL ON LF;		1	0
FORCED INTERR	GA	GA 05	31077	74X	67376434	320031050131	T	4/15/2003	2057	66	6	396	FOREIGN MATER	FRGN MATR	2715 57TH ST	1	SC	673764345				REPLACED ALL 3 CONN. AT TRANS DUE TO SALT COROSION; RPLD CONN @ TR.		1	0
FORCED INTERR	BL	KB 09	10169		52557353	120031050206	T	4/15/2003	2317	34	8	272	BU DISC OR BARI	DISC/BARRL	6408 WAKEFOR		TF	525573532				RPLD BAU BARREL ON TR;		1	0
FORCED INTERR.	KY	FZ 46	12101		45602513	120031050210	T	4/15/2003	2320	126	11	1386	TREE CLEARANC	TREE CLEAF	5014 WESTFIEL		TF	456025131				FOUND TREES TOOK OUT 100KVA TF CHANGED OUT LIMITER AND GUARDED TF AND GOT SERVICE ON; RPLD LIMITER @ TR, REF TR	MOC	1	0
FORCED INTERR.	SB	SA 46	22883		47629448	120031050211	T	4/15/2003	2320	36	4	144	FLLNG TREE IN E	TREE FL/IE	7535 STAMEN		TF	476294487				AT 7535 STAMEN TREES NEED TO BE TRIMMED; REF TR;	SENT MSG TO T&D TO TRIM TREES BRS	1	0
FORCED INTERR	CY	TB 06	21018	M37B		220031060003	F	4/15/2003	2320	78	1	78	VINES	VINES	800 BLK BAKER	3	LF	M37B				REMOVED VINES OFF OF LF M37B. BUT IT NEEDS MORE TREE TRIMMING. SENT MSG TO T&D BRS.		1	0
FORCED INTERR	SB	ME 07	21607	F33K	48583138	120031050212	F	4/15/2003	2330	161	43	6923	TREE CLEARANC	TREE CLEAF	14546 MISTY ME	2	LF	F33K				REF TP.		1	0
FORCED INTERR.	HM	LW 43	20949	24HA		220031050136	F	4/15/2003	2345	111	101	11211	FLLNG TREE OUT	TREE FL/OE	13824 RAWLING	1	LF	24HA	SC			REMOVED TREE FROM PRIMARY AND PICKED UP ONE SPAN PRIMARY NEUTRA, REF LF; P/U PR NEUT		1	0
FORCED INTERR.	HM	LW 42	20199	S3140	55663160	220031050140	T	4/15/2003	2351	41	2	82	TREE CLEARANC	TREE CLEAF	5828 GLEN GRC	1	TF	556631804				TRIM TREES BEST I COULD NEED HAVE TREES TRIM HAVE OPEN SEC. RESET CSP RESET TR	SENT MSG TO TRIM TREES TO T&D. BRS	1	0
FORCED INTERR.	BL	DN 12	10580	31ACN	53573228	120031050217	F	4/15/2003	2355	119	37	4403	BU DISC OR BARI	DISC/BARRL	1108 JOE ANNIE	1	LF	31ACN	DB			RPLD BAU DISC-LF BLOWN;	BRS CORRECTED 3HR/CRH	1	0
FORCED INTERR	CH	BY 07	40188	CST	54605514	320031050133	L	4/15/2003	2358	133	1	133	TREE CLEARANC	TREE CLEAF	8701 HARRELL	1	SC					RPRD SEC-1 CUST		1	0
FORCED INTERR.	GP	LU 44	20574	U70B	50687528	220031060001	T	4/16/2003	0000	63	6	378	VINES	VINES	17926 TERRANC	1	TF	506875261				REFUSED TRAN, REF TR.		1	0
FORCED INTERR	SU	AF 02	11755	E66S		120031060002	F	4/16/2003	0128	0	0	0	SPLICE	SPLICE	8368 LEAMONT	2	LF	E66S	PR			FOUND BAD Y FEED AT 11340 (E67S) BAD BELLOW GROUND IN THIS TRANS X FEED IE E66S. REF TP		1	0
FORCED INTERR	SU	AF 02				120031060002	F	4/16/2003	0128	212	20	4240	SPLICE			2	LF	E66S						0	0
FORCED INTERR	SU	AF 02				120031060002	F	4/16/2003	0128	212	5	1060	SPLICE			2	LF	E66S						0	0
FORCED INTERR	CY	PI 42	2454A	T60K	48767438	220031060004	T	4/16/2003	0231	79	3	237	VINES	VINES	32914 OAK CRE	1	TF	487674386				RAM VINES, REPLACED LIMITER AND REFUSED A 50 KVA, RPLD LIMITER @ TR, REF TR; RMVD TREE/LIMB OFF PR.	BRS	1	0
FORCED INTERR	SH	MY 01	30720	I75C	56494288	320031060001	T	4/16/2003	0255	49	5	245	BU DISC OR BARI	DISC/BARRL	3219 JACQUELY	1	TF	564942886				REFUSED A 50 KVA., RPLD BAU BARREL ON TR; REF TR.	BRS	1	0
FORCED INTERR.	CY	PI 41	20152	S15Y	45756183	220031060005	T	4/16/2003	0401	55	3	165	VINES	VINES	30634 HAZY ME	1	TF	457561830				RAM VINES, REPLACED LIMITER AND REFUSED A 25 KVA; RPLD LIMITER @ TR; REF TR, RMVD TREE/LIMB OFF PR.	MOC	1	0
FORCED INTERR	SU	WI 42	11993	F47R	47564315	120031060003	F	4/16/2003	0517	343	21	7203	UNKNOWN	UNKNOWN	14318 BURGOYI	2	LF	F47R				REPLA 500 KVA STEPDOWN, URD ORDER8073, REF TP RPLD BAU TR. MEK		1	0
FORCED INTERR	GP	LU 44	20574	U70B	50687528	220031060006	T	4/16/2003	0546	83	6	498	UNKNOWN	UNKNOWN	5415 WOODVILL	1	PR	506875261				REPLACED LIMITER, RPLD LIMITER @ TR, REF TR. MEK		1	0
FORCED INTERR	SB	ADK43	13092	17FM	49619124	120031060005	T	4/16/2003	0634	42	5	210	STRONG WIND	WIND	9730 TANNER R	1	TF	496191245				REF TR, MEK		1	0
FORCED INTERR	HC	MV 02	14214	A1J	54447442	120031060006	T	4/16/2003	0634	216	3	648	INSULATOR	INSULATOR	8303 COOK	1	BU	544474429				RPLD BAU TR,		1	0
FORCED INTERR	SU	AF 02	11755	E67S	48549197	120031060010	T	4/16/2003	0643	166	2	332	UNKNOWN	UNKNOWN	8339 LEAWOOD	2	BU	485491979				REPL. 25 KVA TR WITH SAME., RPLD BAU TR;		1	0
FORCED INTERR	CY	PI 45	2445K		43728001	220031060009	T	4/16/2003	0725	67	1	67	VINES	VINES	23515 ROBERTS		PR	437280012				CLEARED VINES OFF TOP XSMER / REPLACED LIMITOR/INSTALLED WOLF; RPLD LIMITER @ TR, REF TR, MEK		1	0
FORCED INTERR	MP	BH 05	40289	58JE	54588108	220031060010	F	4/16/2003	0725	36	7	252	SQUIRREL	SQUIRREL	GREGG @ STOI	1	LF	58JE	TF	545881062		CALL SCREEN-REQUIRED TRIP REFUSED 50 KVA TRAN AND ALSO LF SQUIRREL GUARD MISSING, HAS THE SQUIRREL WIRE, REF LF REF TR.		1	0
FORCED INTERR	SH	CG 06	30206	U04	57536352	320031060005	L	4/16/2003	0726	56	1	56	CONTRACTOR-N	CON-NT HLF	716 AVENUE G	1	DR					REPL. ELEC. CONT @ WTHRHD; RPLD CONN @ WH;		1	0
FORCED INTERR	SB	EC 09	21747	4AM	50594131	120031060011	F	4/16/2003	0728	95	2	190	O/H PRIMARY CL	OH PR CLMF	1700 CAMPBELL	1	PR	4AM				REPLACED STIRRUP & HOT LINE CLAMP; RPLD BO PR JUMPER-FUSE NOT BLOWN.		1	0
FORCED INTERR	SB	BM 01	21474	70GE	49591346	120031060013	F	4/16/2003	0734	64	7	448	COLLISION	COLLISION	1812 BRITTMOC	1	LF	70GE				REFUSED B & C PHASE OF LF 70GE 50T BELIEVE TRK BUMPED POLE AN PHASES GOT TOGETHER REF LF		1	0
FORCED INTERR	HM	AT 42	2314C	S2781	60692590	220031060013	T	4/16/2003	0807	32	2	64	SQUIRREL	SQUIRREL	1115 LAKE GLEI	1	TF	606925906				REF TR.		1	0
FORCED INTERR	MP	AN 05	40029		53603343	220031060014	T	4/16/2003	0812	94	1	94	BU DISC OR BARI	DISC/BARRL	4404 HAYGOOD		TF	536033430				REF TR.		1	0
FORCED INTERR	HC	CC 02	30179	UT1	54523253	120031060016	T	4/16/2003	0819	26	9	234	SQUIRREL	SQUIRREL	4319 HOWCHEF	1	TF	545232536				REFUSE 50 KVA SQ., REF TR.		1	0
FORCED INTERR	SH	CK 04	31700	51GS	59507236	320031060011	T	4/16/2003	0821	77	5	385	ANTS	ANTS	14515 OAK CHA	2	SC	595072368				repaired sec neutral in tran --ants, RPRD SEC-> 1 CUST		1	0
FORCED INTERR	CY	PI 41	2436A	S23Y		220031060016	F	4/16/2003	0824	73	45	3285	UNKNOWN	UNKNOWN	31035 MISTLET(	1	LF	S23Y				REF LF;		1	0
FORCED INTERR	SU	WZ 44	12361	24EB	49567206	120031060018	F	4/16/2003	0825	138	1	138	3 PHASE UG CAB	POTHEAD	9999 WESTHEIN	3	LF	24EB	PR			3 PHASE UG CREW REPLACED POT HEAD AT WAC BRKR 8-3787 KEN		1	0
FORCED INTERR	MP	BG 01	40243	16GV	53557593	220031060017	F	4/16/2003	0826	379	1	379	3 PHASE UG CAB	3 P/UG CBL	5445 ALMEDA (I	3	LF	16GV	PR			3 PHASE UG REPLACE CABLE. KEN		1	0
FORCED INTERR.	CH	SW 05	41678	E88Y	55627351	320031060012	F	4/16/2003	0827	59	8	472	SQUIRREL	SQUIRREL	8514 LEEDALE	2	LF	E88Y				REFUSE TP REF TP CREW 3443 REF T/P DUE TO SQUIRREL DID NOT CALL WHEN LOOP BACK ON NEVER CALLED VAN OFF CAC		1	0
FORCED INTERR	SH	AI 08	31376		60551318	320031060014	T	4/16/2003	0834	99	2	198	OH SEC/DR CL H	OH SC CL-H	440 E 8TH		SC	605513185				RPLD CONN @ TR,		1	0
FORCED INTERR	MP	AN 05	40032	A31F	53611298	220031060018	T	4/16/2003	0837	20	8	160	SQUIRREL	SQUIRREL	150 E WITCHER	1	TF	536112981				CALL SCREEN-UNSUCCESSFUL, NO RESPONSE REFUSED 50 KVA TRAN. HAS GUARD AND WIRE. REF TR;		1	0
FORCED INTERR.	BZ	RT 02	31402	X56K	52270318	320031060018	T	4/16/2003	0848	64	2	128	BU DISC OR BARI	DISC/BARRL	1 BAYOU #1	1	TF	522703169				REFUSED 25 CONV POWER POT IN OPEN DELTA BANK. REF TR;		1	0
FORCED INTERR	CY	PI 42	2454A	S1787	49763521	220031060020	T	4/16/2003	0848	78	1	78	BIRD	BIRD	5119 APRIL VIST	1	TF	497635210				REFUSED 10 KVA TRANS @ 5119 APRIL VISTA, REF TR,		1	0
FORCED INTERR	CH	AD 02	40066	8M8		320031060018	F	4/16/2003	0858	105	79	8295	O/H PRIMARY CL	OH PR CLMF	2306 BREA CRE	1	LF	8M8	PR			PICK UP 1 SPAN #4 ACSR PRIMARY IN REAR OF 2104 WARDMONT, PK/ PR-FUSE BLOWN; REF LF		1	0
FORCED INTERR	SU	CE 09	11962	41EG	48534303	120031060029	F	4/16/2003	0904	55	1	55	HUMAN ERROR	HUMN ERRC	9515 S.DAIRY A	3	LF	41EG				REFUSED B PHASE OF 3 PHASE TP OUT DUE TO PULLED OR BROKEN FUSE SERVICE OK BY CUST ELECT., REF TP		1	0
FORCED INTERR	BL	EU 09	40743	2BE	52586458	220031060021	T	4/16/2003	0908	48	9	432	UNKNOWN	UNKNOWN	8203 HURST	1	TF	525864591				refused power pot in open delta bank / CN&E. REF TR.		1	0
FORCED INTERR	SH	PE 04	30815	E42B	55482252	320031060020	T	4/16/2003	0928	189	1	189	UNKNOWN	UNKNOWN	6805 MEADOW I	1	BU	554822523				REPLACED BAD 25CSP WITH 25 CONV., RPLD BAU TR.		1	0
FORCED INTERR	SH	TE 04	31082	B95T	55509310	320031060021	F	4/16/2003	0933	53	7	371	TREE CLEARANC	TREE CLEAF	12700 MYKAWA	1	LF	B95T				REF LF		1	0
FORCED INTERR	HM	HB 43	20065		57675558	220031060032	T	4/16/2003	1007	35	1	35	LIGHTNING	LIGHTNING	4015 1/2 FM 196		BU	576755584				trans has been out probably weather fed sighn board, RPLD BAU TR,		1	0
FORCED INTERR	BL	BR 11	10507	55QW	51547328	120031060038	L	4/16/2003	1008	72	1	72	OH SEC/DR CL H	OH SC CL-H	4913 HOLLY	1	DR					MADE REPAIRS TO #4.4W DROP AT WH. CHANGED ALL CLAMPS AT WH FOR ST AND RESAGGED DROP RPRD DR, RPLD CONN @ WH, RESAGGED DR. MEK		1	0
FORCED INTERR	SU	MC 02	12140	B63U	50510121	120031060039	L	4/16/2003	1011	270	1	270	OH SEC/DR CL H	OH SC CL-H	607 MARTIN LN	2	DR					RAN BYPASS HLP OWNED DROP(URD) LEFT ON AND WORKING REPLACED MOHEADS AND PEDESTAL CUST NOTIFIED, RAN BYPASS-HL&P OWNED DR.		1	0
FORCED INTERR	FB	BV 42	12865	71MA	43523418	120031060040	F	4/16/2003	1021	30	3	90	UNKNOWN	UNKNOWN	6465 FM 723	1	LF	71MA	TF	435234165		REFUSED TRANSFORMER @ 1848 LEEWAY & NORTH PHASE OF LINE FUSE 71MA NO CAUSE MISTING RAIN., REF LF. REF TR.	MEK	1	0
FORCED INTERR	SH	DR 03	30272		56535460	320031060028	T	4/16/2003	1022	271	9	2439	LIGHTNING ARRE	LTNG ARRS	8603 HINMAN		BU	565354601				REPLACED 25 CSP POWER WITH 25 CONV HUNG SWITCHES & W L IN EAIR.	TAKEN OUT BY PREVIOUS LIGHTNING	1	0
FORCED INTERR	FB	CRB45	13062		46462283	120031060041	T	4/16/2003	1024	110	4	440	TREE CLEARANC	TREE CLEAF	8618 FLOWERM		TF	464622831				INST WLP & TRIM PALM TREE---REF 50KVA--19 8 TR---CAUSE TREE----; REF TR.		1	0
FORCED INTERR	GP	KI 45				220031060039	C	4/16/2003	1051	7	2173	15211	WORK TAG	46ACU/CON	19407 VELVET S		CL	KI45				3 PH UG CREW HOLDING WORK TAG DID NOT SEE ANYTHING, MADE TONES & ANN OUNCEMENTS ALL BACK HOT SEE TBL S/O #252	MJW---LATER REC TBL CALL & FO TP 46ACU BLOWN DU	1	1
FORCED INTERR	BL	BI 04	10060	G59H	52560274	120031060042	T	4/16/2003	1054	280	16	4480	CONTRACTOR-N	CON-NT HLF	30 HACKBERRY	1	SC	525602746				RAN A TEMP SEC. BYPASS FOR CENTER POINT NEED TO HAVE SEM URD SEC REPLACED. INST SEC BYPASS.	MSG SENT TO S/C TLA	1	0
FORCED INTERR	SH	PA 01	30747	PO6	57546593	320031060031	F	4/16/2003	1100	50	7	350	UNKNOWN	UNKNOWN	802 CHEROKEE	1	LF	PO6	TF	575465935		XFMR WAS @ 712 CHEROKEE; REF LF, REF TR.	MEK	1	0
FORCED INTERR.	GP	KI 45	21915	46ACU	48691240	220031060047	F	4/16/2003	1108	169	9	1521	CONTRACTOR-N	CON-NT HLF	19407 VELVET S	2	LF	46ACU	PR			SPLICED URD 35KV PRIMARY ISOLATED DUE TO SEWER CREW WORKING IN HOLE ON SO# 8077 ISOL URD PR; RPRD URD PR;	NO SUBCASING NEEDED - JTF	1	0
FORCED INTERR	SH	PA 03	30761	68FF	57543414	320031060033	T	4/16/2003	1108	35	6	210	SQUIRREL	SQUIRREL	1302 ALLEN GEI	1	TF	575434147				REF TR.		1	0
FORCED INTERR.	SU	CE 04	11965		48537227	120031060053	T	4/16/2003	1214	172	6	1032	UNKNOWN	UNKNOWN	10722 SASHAY		SC	485372273				MADE REPAIRS TO 3 SECONDARY CLAMPS THAT FEED OFF 1 PADDLE OF TRANS THEY WERE BURNED UP THE LUGS, RPLD CONN @ TR.		1	0
FORCED INTERR	CY	PI 43	21118	S1993	44714221	220031060057	F	4/16/2003	1214	31	62	1922	CONTRACTOR (H	CON-HLP	2818 PINE OAK	1	LF	S1993				TREE CREW GOT TREE LIMB ON PRI; REF LF;		1	0
FORCED INTERR	MP	EU 07	40736	E80L	52591124	220031060060	T	4/16/2003	1238	107	8	856	OH SEC/DR CL H	OH SC CL-H	2531 WILLOWB	1	SC	525911245				REPLACED BOTH LIGHTER LEG CONNECTIONS ON OPEN WIRE SECONDARYS SERVICE NOT TAKEN OFF/TREES NEED CUT OUT OFF OPEN WIRE SEC AT 2531/2518 WILLOWBY POSSIBLE OE		1	0
FORCED INTERR	SU	CE 04	11964		48536198	120031060059	T	4/16/2003	1312	52	4	208	SQUIRREL	SQUIRREL	12322 JAGUAR		TF	485361987				REF TR;		1	0
FORCED INTERR.	SU	IM 44	12094		48496545	120031060060	T	4/16/2003	1314	94	6	564	BIRD	BIRD	3811 STOVE PIF		PR	484965457				REPLACED K-MATED AND RE-FUSED TRANSFORMER--- BIRD, RPLD LIMITER @ TR, REF TR.		1	0
FORCED INTERR	MP	AN 08	40048	A20	53606276	220031060072	L	4/16/2003	1358	111	1	111	FLLNG TREE OUT	TREE FL/OE	232 THERON	1	DR					RPLD DR.		1	0
FORCED INTERR.	HC	HM 05	11027	PL8	54531545	120031060062	T	4/16/2003	1400	56	1	56	TREE CLEARANC	TREE CLEAF	8310 SOUTHVIE	1	TF	545315450				CLEARED TREE LIMBS AWAY FROM OPEN DELTA BANK AND REPLACED FUSE BARREL FEEDING POWER POT / CN&E NEED TREE TRIMMERS TO TRIM MORE OF TREE AWAY FROM BANK AND		1	0
FORCED INTERR.	CY	KL 45	21962	C58K	48641505	220031060073	F	4/16/2003	1403	98	22	2156	UNKNOWN	UNKNOWN	12303 DAKAR DI	2	LF	C58K				REFUSED TPC58K IMPROPERLY FUSED, REF TP;		1	0
FORCED INTERR	CY	PI 41	20152	U40B	45750145	220031060077	F	4/16/2003	1414	36	17	612	UNKNOWN	UNKNOWN	38214 GREEN W	1	LF	U40B				REF LF.		1	0
FORCED INTERR	HM	HB 45				220031060079	C	4/16/2003	1418	0	0	0	CONTRACTOR-N	TREE CREW	18929 ATASCA (		CL	HB45				10% CIRCUIT---NO R/C EQUIP ---TREE CREW GOT TREE IN PRI @ 18929 ATASC A OAKS @ FM1960 (NEW WAL-MART)---PROBLEM RESTORED ON TBL S/O#253---NOT HL&P TREE CREW---TREE		1	1
FORCED INTERR	HM	HB 45	20071			220031060079	C	4/16/2003	1418	31	2330	72230	CONTRACTOR-N				CL	HB45						0	0
FORCED INTERR.	HM	HB 45	2G150			220031060079	C	4/16/2003	1418	35	931	32585	CONTRACTOR-N				CL	HB45						0	0
FORCED INTERR	HM	HB 45	20069			220031060079	C	4/16/2003	1418	44	192	8448	CONTRACTOR-N				CL	HB45						0	0
FORCED INTERR	BL	BR 04	10496	N58	52555161	120031060068	T	4/16/2003	1457	255	8	2040	UNKNOWN	UNKNOWN	3522 GRAMERC	1	BU	525551610				RPLD 25 KVA CSP POWER POT WITH 25 KVA CONV IN OPEN DELTA BANK, RPLD BAU TR;		1	0
FORCED INTERR					54570000	220031060112	L	4/16/2003	1506	233	1	233	SEC COND OR DI	SECONDAR	215 BAYOU ST		SC					RAN SEC BY - PASS CORD FROM PED AT 215 BAYOU TO TRAN AT 207 BAYOU INVALID GLN, RAN BYPASS-HL&P OWNED DR:	MSG SENT TO S/C TLA	1	0
FORCED INTERR	SH	DR 07	30293	F2K	56540281	220031060113	T	4/16/2003	1507	44	11	484	SQUIRREL	SQUIRREL	7714 MOLINE ST	1	TF	565402817				refuse trans., REF TR;		1	0
FORCED INTERR	SH	MY 08	30731	93KA	57496049	320031060053	T	4/16/2003	1530	40	3	120	TREE CLEARANC	TREE CLEAF	2410 DIXIE FARI	1	TF	574960495				CLEARED LIMBS AWAY FROM TRANSFORMER & REFUSED IT / NEED MORE TREE TRIM- MING AWAY FROM TRANSFORMER & PRIMARY REF TR.	MSG SENT TO S/C TLA	1	0
FORCED INTERR	GP	BY 06	40186	97PD	53619311	220031060116	T	4/16/2003	1541	204	12	2448	FALLING DEAD TI	TR FL/DEAD	517 ROBMORE	1	SC	536193118	DR		PD	NEED TO REPLACE A 25 FT CL 6 SERVICE POLE IN EASEMENT IN THE REAR OF 517 ROBMORE. RPRD SEC CONN @ PL-> 1 CUST RPRD DR.	MSG SENT TO S/C TLA	1	0
FORCED INTERR.	HM	AD 07	40081		53638369	220031060121	T	4/16/2003	1624	117	1	117	UNKNOWN	UNKNOWN	1205 ALDINE MA		TF	536383697				reset a 25kva csp istill working, RESET TR,		1	0
FORCED INTERR	HM	HB 49	22083		56673460	220031060122	T	4/16/2003	1627	176	2	352	UNKNOWN	UNKNOWN	503 MAIN		TF	566734605				REPLACE LIMITER ON 25 KVA POWER POT, RPLD LIMITER @ TR, REF TR.		1	0
FORCED INTERR	SU	IM 48	12118	U47L	47518369	120031060079	T	4/16/2003	1721	41	3	123	UNKNOWN	UNKNOWN	410 LAKEVIEW	1	TF	475183699				REFUSED 50 KVA TRANS PULLED FUSE, REF TR;		1	0
FORCED INTERR	SB	EC 04	21703	CL3	49589562	120031060082	L	4/16/2003	1735	120	1	120	CONTRACTOR-N	CON-NT HLF	10 ROLLINGWO	1	DR					PICKED UP A SET OF #4 DROPS CAUSED BY HIGH LOAD; PAU DR:		1	0
FORCED INTERR.	MP	WV 03	41814	94X	55586212	220031060132	T	4/16/2003	1822	47	8	376	UNKNOWN	UNKNOWN	729 MAJESTIC	1	TF	555862120				REF TR.		1	0
FORCED INTERR.	SB	CB 07	12604	K24X	50606135	120031060087	T	4/16/2003	1836	113	7	791	TREE CLEARANC	TREE CLEAF	8645 RANNIE RI	1	TF	506061355				CUST CUTTING TREE DOWN GOT ARROSS OPEN WIRE SEC. OPEN TRANS AND REMOVED TREE, REF TR.	TLA	1	0
FORCED INTERR	SB	CB 08	21452	K44X	50602267	120031060088	L	4/16/2003	1844	101	1	101	UNKNOWN	UNKNOWN	4114 PHILCO	1	DR					FOUND NUETRAL BROKEN AT WEATHERHEAD MADE REPAIRS AND GOT SERVICE on CUST STATING THAT SOME OF THEIR APPLIANCES ARE NOT WORKING, RPLD CONN @ WH;		1	0
FORCED INTERR	SB	WT 10	21848	K39M	51586206	120031060090	T	4/16/2003	1858	58	6	348	FLLNG TREE IN E	TREE FL/IE	9230 KENILWOF	1	TF	515862086				REF TR.		1	0
FORCED INTERR	BL	BR 04	14290	N7E	52542517	120031060094	T	4/16/2003	1942	101	10	1010	TRANSFORMER	TRANSFRMI	4102 ABERDEEI	1	BU	525425175				NEED TO REPLACE 25 KVA 7200 120 240 TRAN FIRST THING TOMORROW MORNING SMALL WA NO OIL ON GROUND	MSG SENT TO S/C TLA	1	0
FORCED INTERR	SH	CA 02	30158	27N	59541098	320031060078	T	4/16/2003	2012	28	7	196	UNKNOWN	UNKNOWN	2714 MORNING	1	TF	595410998				BAD FUSE, REF TR.		1	0
FORCED INTERR	GP	NB 43	22367		53656427	220031060136	T	4/16/2003	2022	98	5	490	VINES	VINES	1439 GREENS R		TF	536564272				REMOVED VINES TRIM TREE BUT NEED TO TURN OVER FOR TREE TRIM ALSO CHANGED OUT LIMITER AND REFUSED; RPLD LIMITER @ TR, REF TR.	MSG SENT TO S/C TLA	1	0
FORCED INTERR	SH	GG 04	40970	K4G	55546332	220031060141	L	4/16/2003	2112	83	1	83	FLLNG TREE IN E	TREE FL/IE	7003 KINNEY	1	SC					RPLD CONN @ PL, RMVD TREE/LIMBS FROM DR.		1	0
FORCED INTERR	FB	WR 12	11748	J99F	38370276	120031060103	T	4/16/2003	2120	97	1	97	VINES	VINES	1310 S CANEY T	1	TF	383702769				REMOVED VINES OFF OF A 50KVA TF & REFUSED TF @ SERVICE CENTER'S CONVIENCE NEED TO REPL TOP GUY WIRE, WITH GUY STRAIN INSULATOR TO PROVIDE CLEARANCE FOR TRANS		1	0
FORCED INTERR	BA	NP 44	42055	19JK	61644117	320031060063	T	4/16/2003	2135	75	1	75	UNKNOWN	UNKNOWN	5318 SIXTH ST	1	SC	616441173				XFMR HAS LOOSE BUSHING, X2 BUSHING MIDDLE XFMR 277/480/10 8 TK XCESS IF DRY RPLD BUSS WORK @ TR.	SENT MSG TO T&D TO REPLACE LATER BRS	1	0
FORCED INTERR	CY	CYF44	21253	Y77U	47841511	220031060142	F	4/16/2003	2151	90	1	90	HUMAN ERROR	HUMN ERRC	11208 TELGE	1	LF	Y77U				REMOVED BALLOONS OFF BOTH PHASES. REF LF		1	0
FORCED INTERR.	HC	MV 01	14212	48ABH	55441391	120031060104	T	4/16/2003	2214	154	4	616	OH SEC/DR CL H	OH SC CL-H	8919 CRESTMO	1	BU	554413915				RPLD BAU TR.		1	0
FORCED INTERR	BA	CD 02	40330	84SB	63583314	320031060085	T	4/16/2003	2225	208	21	4368	UNKNOWN	UNKNOWN	2100 W BAKER I	2	BU	635833143				RPLD BAU TR,		1	0
FORCED INTERR	CY	SA 42	22220	38GE	47637195	120031060106	F	4/16/2003	2329	68	1	68	SLACK SPANS	SLACK SPAI	14450 WEST RC	1	LF	38GE				NEED SLACK TAKEN OUT OF # 2 PRIM LINE FUSE 38 GE 1 SPAN CUST STATES FRIDAY BETWEEN 08 00--16 00 WILL REQUIRE OUTAGE CAN GET TO WITH TRUCK, REF LF	SENT MSG TO T&D	1	0
FORCED INTERR	SB	WO 07	21620	RS9		120031070001	F	4/17/2003	0335	48	51	2448	FLLNG TREE IN E	TREE FL/IE	5001 LAMONTE	1	LF	RS9				REF LF		1	0
FORCED INTERR	CH	GW 07	40909		56606475	320031070004	T	4/17/2003	0450	87	3	261	BU DISC OR BARI	DISC/BARRL	9103 LEY		TF	566064754				RPLD BAU BARREL ON TR.		1	0
FORCED INTERR	HC	GV 02	10910	EK1	55540026	120031070004	F	4/17/2003	0619	54	33	1782	UNKNOWN	UNKNOWN	5959 SOUTHSE	1	LF	EK1				REFUSE N PHASE EXT REF LF		1	0
FORCED INTERR	CY	PI 43	2A118		45722328	220031070004	T	4/17/2003	0644	85	2	170	SNAKE	SNAKE	16107 WALNUT		TF	457223295				RAM VINES, RAM SNAKE & REFUSED A 25 KVA, REF TR, RMVD TREE/LIMB OFF PR.		1	0
FORCED INTERR.	CY	SA 42	20951	42DP	48625356	120031070005	F	4/17/2003	0650	64	1	64	COLLISION	COLLISION	7227 WRIGHT R	1	LF	42DP				RF L.F.S ...TAKEN OUT BY HIGH LOAD HITTING PRIMARY REF LF		1	0
FORCED INTERR	CY	TB 44	22061		47713066	220031070006	T	4/17/2003	0701	56	2	112	BIRD	BIRD	28431 TOMBALL		TF	477130669				ALL READY HAS WILD LIFE PROT (BIRD GOT ON LOW SIDE PRI JUMPER & INTO BOND WIRE. GOT JUMPER AWAY FROM BOND WIRE., REF TR.		1	0
FORCED INTERR	BA	MB 03	41425	R74X	64589507	320031070007	F	4/17/2003	0714	41	22	902	UNKNOWN	UNKNOWN	9739 FOREST H	1	LF	R74X				REF LF.		1	0
FORCED INTERR	GP	LK 06	21880	1PR	52620306	220031070010	T	4/17/2003	0727	38	3	114	SQUIRREL	SQUIRREL	2414 FERGUSOI	1	TF	526203060				REFUSED 25 KVA TRAN, HAS GUARD AND WIRE, VERY HARD TO REFUSE BECAUSE OF TREE LIMBS, LIMBS NEED TO BE CUT AROUND TRAN AND POLE, REF TR.	BJH	1	0
FORCED INTERR.	SU	BAR42	13212	89ACD	46536258	120031070006	F	4/17/2003	0743	90	41	3690	COLLISION	COLLISION	18536 BOSS GA	1	LF	89ACD	LF	1BG		TRUCK HIT NEUTRAL CROSSING BOSS GASTON AND SWUNG IT UP INTO THE PRIMARY	THE CHILD FUSE BLEW AND IT ALSO BLEW THE MIDDLE PHASE OF THE STEP DOWN I TOOK SL	1	0
FORCED INTERR.	GP	LU 42	20589	R77P	50709394	220031070012	F	4/17/2003	0820	40	12	480	BIRD	BIRD	4120 FM 2920	1	LF	R77P	TF	507093946		REFUSED L.F R17P @ 0800 REFUSED TRANS @ LEAD ADDRESS @ 0815 TR HAS WILD LIFE PROT REF LF REF TR.	BJH	1	0
FORCED INTERR	GP	THW4	24907	31DL	50647327	220031070013	F	4/17/2003	0822	92	86	7912	URD ELBOW	URD ELBOW	10401 OLD BAM	2	LF	31DL				CREW REPAIRED THE Y PRI IN TF # 5 @ BLDG # 5. NO SUBCASING NEEDED. JRK		1	0
FORCED INTERR	SH	AI 08	31109	82N	60552361	320031070014	L	4/17/2003	0847	69	1	69	OH SEC/DR CL H	OH SC CL-H	901 MARK	1	DR					RPLD CONN @ WH.		1	0
FORCED INTERR	BL	GN 10	11588	R1T	52554298	120031070017	L	4/17/2003	0856	106	1	106	OH SEC/DR CL H	OH SC CL-H	3604 CARNEGIE	1	DR					REPLACED BAD TRANSFORMER LUGS		1	0
FORCED INTERR	BL	HE 07	41137	B29Z	53583427	120031070018	F	4/17/2003	0908	74	16	1184	SQUIRREL	SQUIRREL	829 1/2 CORTLA	1	LF	B29Z				REFUSED E PHASE OF LF OUT BY SQUIRREL ON HIGH SIDE JUMPER TR LOC 1SPAN S OF LF, REF LF		1	0
FORCED INTERR	SU	WZ 43	12339		49552036	120031070025	L	4/17/2003	0930	60	1	60	VANDALISM	VANDALISM	10600 BELLAIRE		MT					REPLACED 4 DAMAGED METERS 841464866 WITH Q67675011 801775674 WITH S24206605 W66192283 WITH S22477860 W69886325 WITH S25922824 ALL NEED BILLING ADJUSTMENT EXCE		1	0
FORCED INTERR	MP	BG 02	40248	88DH	53558547	220031070024	T	4/17/2003	0936	24	3	72	SQUIRREL	SQUIRREL	2323 PROSPEC	1	TF	535585475				REFUSED TRNS / LEFT SERV ON / NOTIFIED REF TR.		1	0
FORCED INTERR	MP	AN 09	40056		53614132	220031070031	T	4/17/2003	0946	19	1	19	SQUIRREL	SQUIRREL	614 E TIDWELL		TF	536141321				REFUSED 50 KVA LIGHTER IN OPEN DELTA, HAS GUARD AND WIRE SQUIRREL GOT ACROSS LOAD BREAK OF BARREL AND BOND WIRE. REF TR.		1	0
FORCED INTERR	BL	ST 13	10204	9P2	50546488	120031070034	T	4/17/2003	0953	46	9	414	TREE CLEARANC	TREE CLEAF	7055 SHARPCRI	1	TF	505464885				REF TR.		1	0
FORCED INTERR	FB	WR 13	11285	83EG	36388095	120031070037	F	4/17/2003	1000	55	1	55	CONTRACTOR (H	CON-HLP	1000 BREEZY **	1	LF	83EG				TREE TRIMMER GOT LIMB INTO LOAD SIDE OF DISCONNECT REF LF.		1	0
FORCED INTERR	SH	TE 01	31064	H59P	56511398	320031070020	F	4/17/2003	1003	78	15	1170	UNKNOWN	UNKNOWN	7735 GREENSW	1	LF	H59P				REFUSE LINE FUSE. REF LF	BJH	1	0
FORCED INTERR	CH	CV 10	40466	J72A	58585367	320031070021	F	4/17/2003	1008	14	37	518	SQUIRREL	SQUIRREL	NADOLNEY @ C	1	LF	J72A				SQ ON CSP 2 CSP'S ON THIS LATERAL NOT GUARDED REF LF.	BJH	1	0
FORCED INTERR	FB	DA 04	1186G	K25	48425060	120031070039	T	4/17/2003	1015	62	1	62	LIGHTNING	LIGHTNING	3730 SAWMILL	1	TF	484250602				REPL LA---INSTALL WLP---REF 10KVA TR REF TR.		1	0

FORCED INTERR	FB	DA 06	1191A	B49M	4433648	120031070041	T	4/17/2003	102	232	1	232	LIGHTNING	LIGHTNING	3636 ANDERSOI	1	TF	443364858					REF TR.	1	0
FORCED INTERR	BL	HE 03	10672	97ADX	5258808	120031070042	T	4/17/2003	104	177	11	1947	UNKNOWN	UNKNOWN	1009 MOY	1	BU	525880801					RPLD B/U TR.	1	0
FORCED INTERR	GP	TWG4	22373	S77R	5469035	220031070037	T	4/17/2003	104	59	1	59	UNKNOWN	UNKNOWN	22855 BANQUO	1	TF	546903580					REF TR. BJH	1	0
FORCED INTERR	SB	ADK41	21320	S2105	4960659	120031070043	T	4/17/2003	104	85	5	425	OH SEC/DR CL H	OH SC CL-H	10123 ALGIERS	1	SC	496065979					REPL. 1/0 TRAN. BUSS WORK WITH 4/0; RPLD BUSS WORK @ TR;	1	0
FORCED INTERR	SU	WZ 43	12341		4955103	120031070044	L	4/17/2003	104	26	1	26	VANDALISM	VANDALISM	10902 BELLAIRE		MT						REPLACED METER FOR UNIT # A SOMEONE SMASHED THE METER OLD # S36606684 (READING- 23156 x 1 ...READING MAY BE INCORRECT DUE TO DAMAGE) NEW # 10886456 (READING	1	0
FORCED INTERR	GA	GA 05	31199	L42	6738621	320031070027	L	4/17/2003	112	93	1	93	OH SEC/DR CL NI	OH SC CL-N	1223 53RD ST	1	SC						RPLD CONN @ PL.	1	0
FORCED INTERR	SB	SA 46	21328	Y99J	4761965	120031070051	T	4/17/2003	112	48	3	144	LIGHTNING	LIGHTNING	6415 CALLE LOZ	1	DB	476195507					HAD LOAD KILLED SERVICE WORKING ON ARRIVAL/TOOK CREW OUTAGE TO REPLACE FUSE BARREL. RPLD B/U DISC-TF NOT BLOWN. BJH	1	0
FORCED INTERR	MP	CR 03	40529	Y88K	5359326	220031070041	L	4/17/2003	1131	69	1	69	FOREIGN MATER	FRGN MATR	1641 COLUMBIA	1	DR		DR				ELECTRICIAN CLAMPS AT W/H CAUGHT ON FIRE AND BURNT DROPS DOWN. HAD TRAN OFF 5 MIN.'S TO SEPARATE WIRES, SPLICED AND PICKED UP #4 DROPS. P/U DR; RPRD DR BJH	1	0
FORCED INTERR	BA	TRM0	4101C		6654026	320031070030	T	4/17/2003	1131	83	3	249	OH SEC/DR CL H	OH SC CL-H	8637 OCEAN DR		SC	665402609					REPL. ENLUG @ TR.; RPLD CONN @ TR.	1	0
FORCED INTERR.	GA	STW0	31012		6434538	320031070031	T	4/17/2003	113	44	1	44	BU DISC OR BARI	DISC/BARRL	14528 STEWAR		DB	643453699					RPLD B/U DISC-TF NOT BLOWN;	1	0
FORCED INTERR	BL	SF 42	10390	K37T	5157403	120031070055	T	4/17/2003	114	157	12	1884	TREE CLEARANC	TREE CLEAR	5627 DOLIVER	1	PR	515740348					TRIMMED LG PALM BRANCH AWAY FROM TOP SIDE OF A 50 KVA 19.9 120/240 POWER XFMR AND REPLACED 12 K-MATE CURRENT LIMITER. RPLD LIMITER @ TR.	1	0
FORCED INTERR	SB	CB 06	21440	5WS	5060300	120031070056	T	4/17/2003	115	54	14	756	SQUIRREL	SQUIRREL	9234 ROCKHUR	1	TF	506030048					REFUSED TR OUT BY SQUIRREL NEEDS W/L PROT S/C CONN. REF TR. BJH	1	0
FORCED INTERR	CY	KL 45	21886	F29S	4766531	220031070045	F	4/17/2003	121	69	3	207	BIRD	BIRD	13023 KLUGE	1	LF	F29S					REFUSED L.F MARKED T29S (BIRD GOT INTO PRI ABOVE DISC ON TR)TR HAS WILD LIFE PROT(NEED TO CHECK L.F #'S. REF LF BJH	1	0
FORCED INTERR	SH	WEB0	31157	17DS	5948928	320031070042	F	4/17/2003	124	37	1	37	SQUIRREL	SQUIRREL	709 MEDICAL CI	3	LF	17DS					3 PHASE TP., REF LF	1	0
FORCED INTERR	BA	MB 03	41425	P19G	6559047	320031070043	T	4/17/2003	1301	35	9	315	O/H PRIMARY CL	OH PR CLMF	9942 BAYOU W	1	TF	655904768					FUSE PULLED INTOO ON 78 CONV REF TR.	1	0
FORCED INTERR	BL	ST 03	13519	1K9	5054651	120031070064	L	4/17/2003	130	166	1	166	OH SEC/DR CL H	OH SC CL-H	7134 MOBUD DI	1	DR						REPLACED # 4 RUBBER COATED 3C TWIST WITH # 4 NEOPRENE 3C TWIST 45 FT RPLD DR.	1	0
FORCED INTERR	MP	UN 05	41725	B57W	5456934	220031070051	F	4/17/2003	131	53	45	2385	COLLISION	COLLISION	4721 PEASE	1	LF	B57W					TRUCK HUNG PHONE CABLE BEHIND 709 TELEPHONE. REF LF.	1	0
FORCED INTERR.	HM	TWG4	2451K	21BL	5370237	220031070052	F	4/17/2003	133	138	55	7590	URD ELBOW	URD ELBOW	26524 CYPRESS	2	LF	21BL	PR				REF TP, RPLD ELBOW @ TR. TLA	1	0
FORCED INTERR	GP	LK 10	22122	FW2	5261040	220031070056	T	4/17/2003	1401	190	9	1710	UNKNOWN	UNKNOWN	2437 MAYVIEW	1	SC	526104078			SC		50KVA 7200/120/240 AT 2446 ARESA NEED TO BE RPL SVC FLUCATING VOLTAGE SAMMIT HAND JOB ON XFMR. RPLD CONN @ TR. RPRD SEC-+1 CUST. RPLD CONN @ PL. MSG SENT TO S/C	1	0
FORCED INTERR	SU	MC 04	12656	G55W	4952718	120031070070	L	4/17/2003	140	43	1	43	OH SEC/DR CL H	OH SC CL-H	9706 OLDCREST	1	DR						svc bad conn at w/h. RPLD CONN @ WH.	1	0
FORCED INTERR.	BL	SF 47	22331	45JQ	5158702	120031070071	T	4/17/2003	140	80	3	240	UNKNOWN	UNKNOWN	8750 CRESCENT	2	TF	515870201	DB		PR		BOTH DISCONNECTS WERE IN BAD SHAPE RPLD AND HIGHSIDE WAS BURNED IN TWO. RPLD B/U DISC-TF BLOWN.	1	0
FORCED INTERR	BL	GT 12	10657		5356134	120031070072	T	4/17/2003	140	62	26	1612	VINES	VINES	1818 COLQUITT		TF	535613412					REMOVED VINES FROM TRANSFORMER AND REFUSED IT / CHAS. REF TR.	1	0
FORCED INTERR.	HC	FD 11	10713	5KT	5054811	120031070073	T	4/17/2003	140	297	9	2673	OH SEC/DR CL NI	OH SC CL-N	6311 GRAPE	1	SC	505481115	DR				REPLACE X-FRM LEAD AND DROPS; RPLD BUSS WORK @ TR. RPLD DR;	1	0
FORCED INTERR.	SH	PO 08	30853	T29B	6049440	320031070054	F	4/17/2003	144	185	71	13135	HUMAN ERROR	HUMN ERRC	2001 GEMINI #1	2	LF	T29B	PR				REPLACED ELBOW FEEDING SWITCHING TRANS.....X-PRIMARY TOO SHARP OF A BEND BELOW ELBOW; RPLD ELBOW @ TR.	1	0
FORCED INTERR	SB	SA 43	21295	E34N	4961040	120031070077	T	4/17/2003	144	130	4	520	OH SEC/DR CL H	OH SC CL-H	11026 HANNING	1	SC	496104026					REPL. LIGHTING ARR. , CLAMPS AT TRAN. AND INSTALLED WILDLIFE PROT	1	0
FORCED INTERR	BA	TRM01	41949	67HL	6455522	320031070056	T	4/17/2003	145	79	2	158	SQUIRREL	SQUIRREL	118 N CANVASB	1	TF	645552225					w/L guards in place but he got in to 2 anyhow REF TR.	1	0
FORCED INTERR	KY	FZ 41	22772	U84K	4458321	120031070079	F	4/17/2003	145	46	59	2714	VANDALISM	VANDALISM	22802 POWELL	2	LF	U84K					KIDS THREW GREEN CANE POLE ON Y T/P REF TP;	1	0
FORCED INTERR.	GA	STW0	35498	2CF	6131812	320031070057	L	4/17/2003	150	106	1	106	OH SEC/DR CL H	OH SC CL-H	3923 4TH ST	1	DR						REPL. ALL DROPS WITH COPPER DROPS .... REPL. THE METER JAWS; RPLD DR. RPLD MTR JAWS/LUGS;	1	0
FORCED INTERR	GP	BA 46	2C141	N96W	5067010	220031070064	L	4/17/2003	1511	135	1	135	UNKNOWN	UNKNOWN	315 CHAMPIONS	2	SC		DR				RPRD CORRODED NETRAL LUG IN PED--ALSO RPLCD CORROED NEUTRAL LUG IN SAME PED -FOR 6619 GLEN MIST--BOTH CUST NOTIFIED---NEED TO RPLC OLD MOLE HEADS IN PED MIC	1	0
FORCED INTERR	GP	TWG4	20246	A37W	5369928	220031070066	T	4/17/2003	152	221	1	221	UNKNOWN	UNKNOWN	4713 TREASCH	1	TF	536992856					CHANGED OUT LIMITER AND REFUSED TRASF., RPLD LIMITER @ TR. REF TR.	1	0
FORCED INTERR	HM	KW 42	22384	N14S	5771904	220031070068	F	4/17/2003	152	0	0	0	UNKNOWN	UNKNOWN	3330 SYCAMOR	2	LF	N14S	BU	57719060E			REPLACED 75KVA 19.9 120/240 URD AND 1 WITH THE SAME. RPLD B/U TR.	1	0
FORCED INTERR	HM	KW 42				220031070068	F	4/17/2003	152	143	15	2145	UNKNOWN			2	LF	N14S						0	0
FORCED INTERR	HM	KW 42				220031070068	F	4/17/2003	152	147	59	8673	UNKNOWN			2	LF	N14S						0	0
FORCED INTERR	HM	KW 42				220031070068	F	4/17/2003	152	254	8	2032	UNKNOWN			2	LF	N14S						0	0
FORCED INTERR	HC	HOC0	11155	A17W	5251555	120031070083	T	4/17/2003	153	64	8	512	VINES	VINES	3806 PRUDENC	1	TF	525155550					REMOVE VINES AND REFUSE TRANSF.. REF TR. RPLD B/U BARREL ON TR;	1	0
FORCED INTERR.	SB	SA 47	21257	N26M	4762435	220031070070	F	4/17/2003	153	0	0	0	OVERLOAD	OVERLOAD	7503 BULL CRE	2	LF	N26M	DB		BU	476	RPLCD A BAD 25KVA 19.9 120/240 PMT TF#16. W/50KVA TF ALSO RPLCD BAD 19.9 DISC ON THE(Y)TP N26M URD BO#### *VAN ENROUTE 15:37 *SUBCASING NECESSARY	1	0
FORCED INTERR	SB	SA 47				220031070070	F	4/17/2003	153	340	33	11220	OVERLOAD			2	LF	N26M						0	0
FORCED INTERR	SB	SA 47				220031070070	F	4/17/2003	153	340	4	1360	OVERLOAD			2	LF	N26M						0	0
FORCED INTERR	SB	SA 47				220031070070	F	4/17/2003	153	543	4	2172	OVERLOAD			2	LF	N26M						0	0
FORCED INTERR	BL	ST 03	13519	1K9	5054651	120031070086	L	4/17/2003	155	25	1	25	OH SEC/DR CL H	OH SC CL-H	7134 MOBUD DI	1	DR						REPLACED 40 FT # 4 RUBBER COATED 3C TWIST HOUSE DROPS WITH # 4 NEOPRENE 3C TWIST HOUSE DROPS AT 7134 MOBUD. RPLD DR;	1	0
FORCED INTERR	MP	HG 02	41067	8FE	5655202	320031070066	F	4/17/2003	155	106	2	212	LIGHTNING ARRE	LTNG ARRS	BROADWAY @	1	LF	8FE					REFUSED LF REF LF	1	0
FORCED INTERR	SH	SB 07	31054	W79C	5855500	320031070066	F	4/17/2003	155	114	40	4560	BIRD	BIRD	2008 JENKINS #	2	LF	W79C	DB				RPLD B/U DISC-TF BLOWN.	1	0
FORCED INTERR	BL	ST 03	13519	62ABN	5054557	120031070091	T	4/17/2003	161	59	7	413	BIRD	BIRD	7206 ROOS	1	TF	505455735					REFUSED 50 KVA DUE TO BIRD ON TRANS. REF TR.	1	0
FORCED INTERR	CH	NM 04	41526	4D1	5757758	320031070072	L	4/17/2003	162	63	1	63	OH SEC/DR CL NI	OH SC CL-N	12610 YANCY DI	1	DR						REPLACED CLAMPS ON TWO WH. RPLD CONN @ WH.	1	0
FORCED INTERR	GP	LU 44	2H139	83BL	5069410	220031070081	F	4/17/2003	164	118	40	4720	LIGHTNING ARRE	LTNG ARRS	17202 OAK DALI	2	LF	83BL					REPL L/A, REF T/P REF TP RPLD LIGHTNING ARRESTOR.	1	0
FORCED INTERR	SH	SH 08	30926	A76P	5752644	320031070075	T	4/17/2003	164	124	8	992	UNKNOWN	UNKNOWN	8106 DELWIN	1	TF	575264405					REFUSED TRANSFORMER, REF TR.	1	0
FORCED INTERR	FB	OR 02	1122C	R58S	3743707	120031070100	T	4/17/2003	165	233	1	233	INSULATOR	INSULATOR	1507 COUNTY R	1	BU	374370739					REPLACED 10 KVA CSP 7200/120/240 TRANS @ 10 KVA 7200 /120/240 CONV TRANS INST LA W/LP & AB CHANCE SWITCH EQUIP FAILURE, RPLD B/U TR LATER. RPLD LIGHTNING ARRESTOR.	1	0
FORCED INTERR	GP	BA 41	2E154	Y55I	5067956	220031070083	T	4/17/2003	165	326	5	1630	GUY/ANCHOR	GUY/ANCHC	15223 LANTERN	2	BU	506795833					HAD TO REM FENCE TO REPL. TR., RPLD B/U TR.	1	0
FORCED INTERR	CH	OA 04	41365	P67	5857950	320031070077	L	4/17/2003	165	98	1	98	OH SEC/DR CL H	OH SC CL-H	10234 PILLOT	1	DR						REPLACED HEATED UP CLAMPS AT W/H. RPLD CONN @ WH;	1	0
FORCED INTERR	CH	CV 08	41802	X83R	5959315	320031070078	T	4/17/2003	170	328	4	1312	UNKNOWN	UNKNOWN	944 LEADENHAI	2	BU	595931552	PR				REPLACED 37.5 KVA LF URD XFMR WITH 25 KVA DF URD XFMR-7200-120/240 SPLICED OUT URD PRI AND INSTALLED LB ELBOWS. RPRD URD PR. RPLD B/U TR TLA	1	0
FORCED INTERR	MP	UN 05	41725	B57W	5456932	220031070088	T	4/17/2003	171	77	7	539	UNKNOWN	UNKNOWN	4701 PEASE	1	TF	545693243					REFUSED A 25 KVA 7200 120 240 V TRANSFORMER. REF TR.	1	0
FORCED INTERR	CY	PI 43	2J118	99GC	4470403	220031070090	T	4/17/2003	172	305	1	305	UNKNOWN	UNKNOWN	20202 HERITAG	1	BU	447040392					CHANGED OUT 15 KVA 19.9 OVERHEAD T/R WITH THE SAME. RPLD B/U TR. REF TR. TLA	1	0
FORCED INTERR	GA	STW0	35358	H96X	6333617	320031070079	L	4/17/2003	173	45	1	45	TREE CLEARANC	TREE CLEAR	18100 SAN LUIS	1	DR						replaced neutral conn at w/h broken by tree's. RPLD CONN @ WH;	1	0
FORCED INTERR	FB	EB 06	11295	F74T	3746907	120031070110	F	4/17/2003	173	57	6	342	COLLISION	COLLISION	2026 TWIN OAK	1	LF	F74T	SC				RAISED PRI 28 FT NEUTRAL 24 FT DUMP TRUCK GOT INTO IT REFUSED F74T P/U PR-FUSE BLOWN. REF LF. P/U PR NEUT;	1	0
FORCED INTERR	BA	BT 04	40116	HS2	6357602	320031070081	T	4/17/2003	175	59	6	354	UNKNOWN	UNKNOWN	506 N WHITING	1	TF	635760287					REF TR.	1	0
FORCED INTERR	GP	KI 46	20744	51LE	4968229	220031070093	T	4/17/2003	180	215	7	1505	URD SEC PDSTL	URD SC PEI	17811 SPLIT CR	2	SC	496822978					SPLICED URD SEC. AND REPL MOLDHEAD ON LITER LEG. PED IS 12" TO 14" BELOW GRADE. NEED TO RAISE PED AND MOLDHEADS. RPRD SEC-+1 CUST MSG SENT TO S/C TLA	1	0
FORCED INTERR.	MP	AN 01	40001	97AH	5360423	220031070094	T	4/17/2003	180	57	5	285	OVERLOAD	OVERLOAD	803 E 43RD	1	TF	536042321					refused a 25 kva. REF TR.	1	0
FORCED INTERR	GP	BA 01	20614	C88A	5066143	220031070095	T	4/17/2003	181	49	1	49	UNKNOWN	UNKNOWN	5916 CORAL RI	1	TF	506614336					REFUSED 75KVA TR. ON 480V BANK. REF TR.	1	0
FORCED INTERR	SH	SH 01	30895		5752448	320031070082	T	4/17/2003	181	49	4	196	UNKNOWN	UNKNOWN	650 GILPIN		TF	575244878					REFUSED TRANSFORMER. REF TR.	1	0
FORCED INTERR	RS	LV 01	3A115	18N	5736758	320031070083	T	4/17/2003	182	50	2	100	SQUIRREL	SQUIRREL	5726 FM 2917	1	TF	573675876					refused 10 kva has w/p. REF TR.	1	0
FORCED INTERR.	CH	SW 06	41685		5561641	320031070084	L	4/17/2003	182	92	1	92	OH SEC/DR CL H	OH SC CL-H	7208 PARKER R		DR						SPLICED OUT DROPS ABOUT MIDSPAN, DROPS ARE OLD AND HAS SEVERAL BAD SPOTS NEED TO BE REPLACED AT SERVICE CENTER CONV RPRD DR RPLD CONN @ WH. MSG SENT T(	1	0
FORCED INTERR	BL	DV 04	10594	I94B	5056329	120031070116	T	4/17/2003	182	138	1	138	FOREIGN MATER	FRGN MATR	8611 WESTHEII	1	BU	505632987					CHANGED OUT BAD 167KVA 7200 120/240 IN CLOSED DELTA BANK ASSISTED BY 3879 MARTINEZ 3222 MAXWELL. RPLD B/U TR.	1	0
FORCED INTERR	GP	RU 03	41659	K60C	5362814	220031070098	T	4/17/2003	183	122	10	1220	BU DISC OR BARI	DISC/BARRL	11509 CATAMOI	1	TF	536281430	DB				RPLD B/U DISC-TF BLOWN	1	0
FORCED INTERR	MP	NS 06	41578	N1D	5459729	220031070100	T	4/17/2003	184	37	10	370	OVERLOAD	OVERLOAD	3403 MEMEL #1	1	TF	545972985					refused a 50 kva. REF TR.	1	0
FORCED INTERR.	CH	LB 01	41253	N19N	5560415	320031070093	T	4/17/2003	185	234	4	936	UNKNOWN	UNKNOWN	6934 PEYTON	1	BU	556041521					REPL. A B/U 25 KVA WITH NEW 25 KVA ADDED SQUIREL WIRE AND GUARD ALSO LIGHTING ARRESTOR. RPLD B/U TR.	1	0
FORCED INTERR	CY	HK 06	21114		4366127	220031070102	T	4/17/2003	190	92	1	92	FOREIGN MATER	FRGN MATR	14711 KATY HO		TF	436612769					REFUSED 5KVA POWER TRANF 7200; REF TR.	1	0
FORCED INTERR	HC	FD 05	10859	9AJ	5053919	120031070125	T	4/17/2003	191	152	8	1216	SQUIRREL	SQUIRREL	6026 BENNING	1	TF	505391972					REFUSED TRANSFORMER, REF TR;	1	0
FORCED INTERR	HC	BL 02	10766	74EG	5152049	120031070127	T	4/17/2003	192	49	7	343	SQUIRREL	SQUIRREL	11931 HILLCRO	1	TF	515204975					REFUSED TRANSFORMER, REF TR.	1	0
FORCED INTERR	BL	SF 46	11485		5157230	120031070128	T	4/17/2003	192	219	3	657	VINES	VINES	6003 DEERWOC		TF	515723063					REPLACED 2 K MATES ON 19.9 TRANS IN OPEN DELTA DUE TO VINES. REF TR;	1	0
FORCED INTERR	SH	CA 02	30160	S34B	5953530	320031070096	T	4/17/2003	1931	270	11	2970	HUMAN ERROR	HUMN ERRC	3310 JANA LN #	2	SC	595353075					ENTEX CUT SEC BAD SET PMT AND #273 INSTALLED SEC BYPASS, INST SEC BYPASS. SENT MSG TO T&D BRS	1	0
FORCED INTERR	BL	BI 05	10073	K45T	5155730	120031070129	T	4/17/2003	1941	102	11	1122	BU DISC OR BARI	DISC/BARRL	800 HOLTON	1	TF	515573011					RPLD B/U BARREL ON TR.	1	0
FORCED INTERR	CH	UV 03	41762	R51C	5859317	320031070100	T	4/17/2003	195	95	25	2375	UNKNOWN	UNKNOWN	280 UVALDE RD	2	TF	585931769					reset 100kva of trans. RESET TR.	1	0
FORCED INTERR	HM	GR 01	20187	U58W	5466610	220031070107	F	4/17/2003	195	41	1	41	BIRD	BIRD	16901 JOHN F.K	3	LF	U58W					REFUSED B PHASE OF U58W 1ST THIS THREE PHASE URD. REF LF;	1	0
FORCED INTERR	SH	DR 03	31393	P49D	5653434	320031070101	T	4/17/2003	201	440	43	18920	UNKNOWN	UNKNOWN	8801 GLENCRE	2	BU	565343430					REPLACED 100 KVA DF XFMR WITH SAME--7200-120/240 FOUND WORKING P/B. RPLD B/U TR;	1	0
FORCED INTERR	SH	CG 02	30209	30D	5753322	320031070102	F	4/17/2003	201	28	26	728	UNKNOWN	UNKNOWN	711 MISSISSIPP	1	LF	30D					REFUSED LINE FUSE.....SEND MESSAGE TO SCH.....SEVERAL CSP TRANS NEED WILDLIFE PROTECTION. REF LF. MSG SENT TO S/C TLA	1	0
FORCED INTERR	SH	CG 04	30223		5753136	320031070103	T	4/17/2003	203	33	7	231	UNKNOWN	UNKNOWN	809 INDIANA ST		TF	575313636					REFUSED A 25 KVA LIGHTER. PULLED FUSE. REF TR.	1	0
FORCED INTERR	CH	NM 01	41267	67GU	5858232	320031070104	T	4/17/2003	204	56	8	448	UNKNOWN	UNKNOWN	13110 EMPORIA	1	TF	585823278					REF TR.	1	0
FORCED INTERR	SU	IM 47	12106	69PE	4751820	120031070136	F	4/17/2003	210	107	66	7062	LIGHTNING ARRE	LTNG ARRS	231 RIVER GRO	2	LF	69PE					REF TP RPLD LIGHTNING ARRESTOR.	1	0
FORCED INTERR.	GP	KI 46	22312	M54B	4968545	220031070111	L	4/17/2003	210	139	1	139	CONTRACTOR-N	CON-NT HLF	17807 THEISS M	1	DR						Rpld/Rprd Point of Attachment. REPL. ELECTRICIAN CONN's @ WH; RPLD CONN @ WH.	1	0
FORCED INTERR	SH	DR 07	30293	F2K	5654028	120031070113	F	4/17/2003	210	59	93	5487	SQUIRREL	SQUIRREL	7733 BUENA VIS	1	LF	F2K					REFUSED LF REF LF	1	0
FORCED INTERR	GA	AL 10	30045		6140334	320031070106	T	4/17/2003	211	119	2	238	UNKNOWN	UNKNOWN	6602 FM 646		BU	614033485					RPLD B/U TR;	1	0
FORCED INTERR.	HC	BR 10	10513	A68B	5253242	120031070160	T	4/17/2003	211	53	11	583	HUMAN ERROR	HUMN ERRC	10210 OBOE	1	TF	525324243					FUSE PULLED OUT REF TR.	1	0
FORCED INTERR	SU	IM 47	12106	95NR	4751912	120031070164	F	4/17/2003	213	110	17	1870	LIGHTNING ARRE	LTNG ARRS	427 DOCKSIDE	2	LF	95NR					REF TP; RPLD LIGHTNING ARRESTOR.	1	0
FORCED INTERR	KY	MAR41	22682	48JG	4556259	120031070165	F	4/17/2003	214	174	49	8526	URD BUSHING	URD BSHING	20502 CHADBUF	2	LF	48JG					RPL. TRANS BUSHING AND REFUSED TERMINAL POLE ALL SERVICE RESTORED. REF TP RPLD TR BUSH.	1	0
FORCED INTERR.	CY	PI 42	2320A	44ACC	4977124	220031070120	F	4/17/2003	223	364	44	16016	FLLNG TREE OUT	TREE FL/OE	807 FAIRBANKS	1	LF	44ACC	SC				IN THE REAR OF 808 WESTWOOD NORTH DR. REPL. KING PIN & V - 20 INSULATOR. ALSO TIED #2 STATIC BACK IN. ALSO PICKED UP 3 SPANS #2 STATIC. REFUSED L F 44ACC AT 04 36 TRK 2	1	0
FORCED INTERR	KY	GE 42	2563K		4561138	120031070170	T	4/17/2003	223	111	3	333	LIGHTNING ARRE	LTNG ARRS	21006 CLAREMC		TF	456113815					REF TR. RPLD LIGHTNING ARRESTOR.	1	0
FORCED INTERR	HC	BL 02	10766		5152046	120031070172	T	4/17/2003	225	58	6	348	SQUIRREL	SQUIRREL	12111 DUNLAP		TF	515204670					REFUSED TRANSFORMER. REF TR.	1	0
FORCED INTERR	FB	WA 43	14060	80GB	3950215	120031070173	T	4/17/2003	231	55	1	55	BIRD	BIRD	14818 FM 1489	1	TF	395021516					REPLACED 12 K MATE LIMITER FUSE FOUND OWL IN GARDEN; REF TR;	1	0
FORCED INTERR	GA	AL 10	30045	39AAJ	6140438	320031070112	T	4/17/2003	235	85	4	340	BU DISC OR BARI	DISC/BARRL	6631 AVENUE F	1	TF	614043885					REF TR.	1	0
FORCED INTERR	SU	WZ 44	12358	N55P	4956807	120031080001	T	4/18/2003	000	62	40	2480	CUST EQP RELAT	CUST RLTD	3230 S GESSNE	2	TF	495680738					REPLCD DMOD MTR WITH NEW MTR- OLD MTR INFO-GE6327 1842 RDNG-22211 TYPE- 1708 CL-200 NEW MTR INFO-SCH 18182174 120/240 3W TYPE-J5SR CL 200 LFFT NEW MTR BO'D DUE TO	1	0
FORCED INTERR	HC	QV 06	11120		5050621	120031080002	T	4/18/2003	001	70	2	140	BU DISC OR BARI	DISC/BARRL	2302 DOVERGL		TF	505062108					RPLD B/U BARREL ON TR.	1	0
FORCED INTERR	CY	TB 06	21016	AG9	4771536	220031080004	T	4/18/2003	014	245	4	980	TREE CLEARANC	TREE CLEAR	803 HICKS	1	BU	477153895	DB				RPLD B/U TR. RPLD B/U DISC-TF BLOWN. RPLD LIGHTNING ARRESTOR.	1	0
FORCED INTERR	CY	KL 45	21963	15LM	4764954	220031080005	F	4/18/2003	042	0	0	0	URD ELBOW	URD ELBOW	12714 DAKER Y	2	LF	15LM	BU	47649552C			REPLACED A BAD 25KVA 19.9 120/240 PADMOUNT WITH THE SAME IN THE FRONT OF 12714 MAXIM. RPLD B/U TR. URD B/O#0108 RADAR VAN ENROUTE-PULLED OF	1	0
FORCED INTERR	CY	KL 45				220031080005	F	4/18/2003	042	140	43	6020	URD ELBOW			2	LF	15LM						0	0
FORCED INTERR	CY	KL 45				220031080005	F	4/18/2003	042	222	2	444	URD ELBOW			2	LF	15LM						0	0
FORCED INTERR	KY	GE 44	22740	65DJ	4561848	120031080011	F	4/18/2003	051	0	0	0	UNKNOWN	UNKNOWN	19102 REBEL YE	2	LF	65DJ	BU	45618444E			REPLACED 50 KVA PADMOUNT WITH SAME. REF TP RPLD B/U TR.	1	0
FORCED INTERR	KY	GE 44				120031080011	F	4/18/2003	051	231	54	12474	UNKNOWN			2	LF	65DJ						0	0
FORCED INTERR	KY	GE 44				120031080011	F	4/18/2003	051	355	5	1775	UNKNOWN			2	LF	65DJ						0	0
FORCED INTERR	MP	OA 07	41609	75JV	5659604	220031080007	F	4/18/2003	063	63	1	63	BIRD	BIRD	9711 WALLISVIL	1	LF	75JV					REF LF	1	0
FORCED INTERR	MP	BH 07	40299	AT7	5458841	220031080008	T	4/18/2003	070	67	15	1005	HUMAN ERROR	HUMN ERRC	2511 BRINGHUF	1	TF	545884172					RESET 50 CSP DUED TOO FIRE AT VAC HOUSE 2506 BRINGHURST RM MTR DROPS 2506 MTR BN UP DUED TOO HOUSE FIRE UNABLE TOO GET A READING. RESET TR.	1	0
FORCED INTERR	FB	OB 44	14096		4652829	120031080014	T	4/18/2003	070	188	4	752	VINES	VINES	2502 COBBLE R		TF	465282990					REF TR.	1	0
FORCED INTERR	FB	WA 43	14060	44UE	3950720	120031080015	F	4/18/2003	071	97	1	97	UNKNOWN	UNKNOWN	ON MAGNOLIA	1	LF	44UE					REFUSED LF 44UE---CAUSE UNK.. REF LF	1	0
FORCED INTERR	CH	SW 09	41698	32QS	5562031	320031080006	T	4/18/2003	073	168	1	168	COLLISION	COLLISION	4403 MOHAWK	1	TF	556203148					CAR BUMPED POLE. REF TR.	1	0
FORCED INTERR	SU	WZ 41	12308	Y22M	4956203	120031080017	F	4/18/2003	073	99	1	99	LIGHTNING ARRE	LTNG ARRS	10850 RICHMON	3	LF	Y22M					RPLD BAD LTNG ARR & REF TP - JTF	1	0
FORCED INTERR	FB	WR 11	1158D	64F	3439402	120031080019	T	4/18/2003	083	116	1	116	LIGHTNING	LIGHTNING	427 BOATWRIG	1	BU	343940285					REPL BAD 15 CSP TAN 7200 120 240 WITH 10 CONV TRAN AND INSTALLED 10; RPLD B/U TR. RPLD LIGHTNING ARRESTOR.	1	0
FORCED INTERR	SB	WD 45	22159		4658922	120031080020	T	4/18/2003	090	80	1	80	UNKNOWN	UNKNOWN	15810 PARK TE		PR	465892207					RPLD LIMITER ON 250 KVA 19.9 277/480 TRANS ALL SERV. BACK ON. RPLD LIMITER @ TR	1	0
FORCED INTERR	SB	SR 12	21679		4959422	120031080021	T	4/18/2003	090	42	7	294	UNKNOWN	UNKNOWN	10522 BARWOO		TF	495942241					REFUSED 25 KVA POWER POT -- CAUSE UNK - PROBABLY BIRD. REF TR	1	0
FORCED INTERR.	SH	DR 09	30300		5653049	320031080011	T	4/18/2003	090	31	4	124	VINES	VINES	6742 HOLLYGR		TF	565304991					REFUSED A 25 KVA., REF TR. BJH	1	0
FORCED INTERR	FB	RS 01	11384	X95E	4248809	120031080026	T	4/18/2003	093	52	1	52	BU DISC OR BARI	DISC/BARRL	1207 SPUR 529	1	TF	424880907					REPL BURNED UP FUSE BARREL. RPLD B/U BARREL ON TR.	1	0
FORCED INTERR	CH	CV 10	40466	J34A	5858528	320031080014	F	4/18/2003	095	35	12	420	SQUIRREL	SQUIRREL	1040 FREEPOR	1	LF	J34A					SQUIRREL WAS ON XFMR @ 13757 DUNCUM ST (25 KVA CSP NO DISCONNECT) REF LF	1	0
FORCED INTERR	BL	SF 46	12514	X48H	5157605	120031080032	F	4/18/2003	1001	173	2	346	UNKNOWN	UNKNOWN	SAN FELIPE, BT	1	LF	X48H					REPLACED 25K LIMITER ON STEP DOWN AND REFUSED NORTH PHASE OF LINE FUSE. REF LF BJH	1	0
FORCED INTERR	SU	CE 01	11933		4753508	120031080034	T	4/18/2003	102	42	3	126	SQUIRREL	SQUIRREL	14223 BAY GAR		TF	475350866					REF TR.	1	0
FORCED INTERR	CH	UV 02	31309	E80J	5859629	320031080016	F	4/18/2003	102	71	43	3053	SQUIRREL	SQUIRREL	13919 LANTERN	2	LF	14GU					REFUSE LF 14GU 1ST REF LF BJH	1	0
FORCED INTERR	SB	ME 06	21604	M87Z	4857251	120031080035	L	4/18/2003	102	99	1	99	URD SEC PDSTL	URD SC PEI	14662 PERTHS	2	SC						replaced sec mold head in urd ped. RPRD SEC-1 CUST	1	0
FORCED INTERR	GP	LK 02	21873	B40Z	5263401	220031080026	F	4/18/2003	102	38	63	2394	BU DISC OR BARI	DISC/BARRL	1727 TWINBRO	2	LF	B40Z					REPLACED BURNED UP FUSE BARREL ON TERMINAL POLE. RPLD B/U BARREL ON TP.	1	0
FORCED INTERR	SB	TO 06	21785	I99H	5159431	120031080037	F	4/18/2003	102	49	1	49	LIGHTNING	LIGHTNING	TODD, S OF HAI	1	LF	I99H	TF	51594315E			RE-FUSED POWER POT AND ALSO THE MIDDLE PHASE OF THE LINE FUSE NEED TO REPLACE THE LIGHTNING ARRESTOR ON THE SOUTH POWER POT TRUCK ACCESSIBLE. NO RUSH (PAS	1	0

FORCED INTERR	SB	GE 41	21191	27DP	4661700	120031080041 T	4/18/2003	105	43	5	215	UNKNOWN	UNKNOWN	17560 KIETH HA	1	PR	466170093			REFUSED TRAN REPL LIMITER FUSE, RPLD LIMITER @ TR, REF TR.		1	0
FORCED INTERR	MP	EU 03	40709	F82	5259823	220031080029 F	4/18/2003	105	43	24	1032	LIGHTNING ARRE	LTNG ARRS	BEALL @ W.22N	1	LF	F82			2- 8- KV ARM ON TEE BKT ON ST REF LF LOCATED 912 W.22ND	BJH	1	0
FORCED INTERR	MP	BU 01	41588	B30N	56574541	220031080031 L	4/18/2003	111	73	1	73	FLLNG TREE OUT	TREE FL/OE	1310 LAURENTI	1	DR				tree trimmers dropped limb on drop [illegible] span, spliced drop & restored service., RPRD DR.		1	0
FORCED INTERR	RS	RZ 01	35738	20KA	4938359	320031080031 T	4/18/2003	112	130	1	130	COLLISION	COLLISION	18310 REDWOC	1	SC	493835936	DR		PICKED UP 1 SP 1/0 SECONDARIES HOUSE DROPS..		1	0
FORCED INTERR	GA	STW0	31004	99BA	6333605	320031080021 T	4/18/2003	113	97	4	388	BU DISC OR BARI	DISC/BARRL	18228 E DE VAC	2	TF	633360506	DB		REPL. BAD DISC BAD TERMINATOR @ 18308 E. DE VACA LN., RPLD BU DISC-TF BLOWN;	BJH	1	0
FORCED INTERR	SB	TO 10	21769	M28A	50598251	120031080045 L	4/18/2003	114	58	1	58	OH SEC/DR CL H	OH SC CL-H	1909 NORCRES	1	SC				REPL CLAMP AT POLE; RPLD SEC CONN @ PL-1 CUST;		1	0
FORCED INTERR	SB	EC 09	21744	C55S	50584461	120031080046 F	4/18/2003	114	71	14	994	SLACK SPANS	SLACK SPA	1313 CAMPBELL	1	LF	C55S			TOOK SLACK OUT OF SLACK SPAN ALL SERV BACK ON AT 13:00, REF LF;		1	0
FORCED INTERR	GP	KI 43	21931	N71X	49674381	220031080036 T	4/18/2003	115	73	6	438	SQUIRREL	SQUIRREL	18154 HEXHAM	1	TF	496743814			REF TR;		1	0
FORCED INTERR	SH	CA 01	30154	I47K	5853935	320031080023 F	4/18/2003	115	37	37	1369	TREE CLEARANC	TREE CLEA	4908 IVY	1	LF	I47K			REFUSED L.F. TREES THICK @ 4713 & 4711 CREPE MYRTLE, REF LF;	BJH	1	0
FORCED INTERR	SU	QV 04	12175	M45U	4949527	120031080046 F	4/18/2003	120	51	9	459	TREE CLEARANC	TREE CLEA	3335 OYSTER C	2	LF	M45U			REF TP		1	0
FORCED INTERR	GA	STW0	3535D	8CE	6231453	320031080024 L	4/18/2003	122	73	1	73	OH SEC/DR CL H	OH SC CL-H	4038 PANOLA D	1	DR				RPLD CONN @ WH;		1	0
FORCED INTERR	GP	LK 07	41298	LH4	5262607	220031080042 T	4/18/2003	123	57	2	114	SQUIRREL	SQUIRREL	7429 DE PRIEST	1	TF	526260747			REFUSED 7200 KV 25 KVA TRANS. TAKEN OUT BY SQUIRREL NEED WILD LIFE PROTECTION; REF TR,	BJH	1	0
FORCED INTERR	HM	AD 03	20893	Y81Z	5363859	220031080044 T	4/18/2003	130	42	7	294	BU DISC OR BARI	DISC/BARRL	13317 REEVEST	1	TF	536385981			50 CONV REF TR,		1	0
FORCED INTERR	FB	RE 05	11353	K44Y	4450401	120031080056 L	4/18/2003	132	55	1	55	OH SEC/DR CL H	OH SC CL-H	1102 ALAMO AV	1	DR				REPL. BAD CLAMP AT WEATHERHEAD; RPLD CONN @ WH;		1	0
FORCED INTERR	SB	TO 02	21765	36L	5159049	120031080060 T	4/18/2003	133	193	2	386	BIRD	BIRD	2323 WIRT RD	1	BU	515904989			REPLACE BAD 500 XFMR 277/480 7.2 KV W/ SAME RPLD BU TR.		1	0
FORCED INTERR	GP	BA 02	20620		5066139	220031080049 L	4/18/2003	151	80	1	80	FLLNG TREE OUT	TREE FL/OE	6010 FM 1960 W		DR				RPRD DR, RMVD TREE LIMBS FROM DR.		1	0
FORCED INTERR	GP	LK 06	22554		51628511	220031080051 T	4/18/2003	151	226	2	452	OH SEC/DR CL H	OH SC CL-H	10401 W MONT		BU	516285117			REPL 10 KVA POWER POT WITH 25 CONV RPLD BU TR.		1	0
FORCED INTERR	MP	EU 07	82006		5259510	220031080052 T	4/18/2003	151	252	10	2520	OH SEC/DR CL H	OH SC CL-H	1614 TANNEHIL		BU	525951061	DB		TRANSFORMER WAS LEAKING FROM SEC. & URD[illegible]. NEED CLEAN UP CREW TO CLEAN FENCE + ABOUT 6' B Y 6' AREA OF GRD , RPLD BU TR; RPLD BU DISC-TF NOT BLOWN, RPLD LIGHT		1	0
FORCED INTERR	SB	TO 04	21778	C15U	5159531	120031080068 T	4/18/2003	152	45	3	135	BU DISC OR BARI	DISC/BARRL	10612 HEMPSTE	1	TF	515953135			REFUSED 25KVA POWER POT FUSE MELTED OUT; REF TR.		1	0
FORCED INTERR	BZ	VL 03	35110	67B	5528510	320031080037 F	4/18/2003	153	59	2	118	BU DISC OR BARI	DISC/BARRL	1100 CO 227	1	LF	67B			REFUSED MIDDLE PHASE ON L.F. 67-B 25-T,BURNED UP FUSE BARRLE, REF LF		1	0
FORCED INTERR	FB	RS 01	11384	X95E	4248809	120031080077 F	4/18/2003	162	32	1	32	SQUIRREL	SQUIRREL	1221 HWY 59	1	LF	X95E	TF	424880907	REPL FUSE BARRELL & REF 50KVA---B PHASE REPL FUSE BARRELL & REF B PHASE OF X95E, REF LF REF TR, RPLD BU BARREL ON TR,	BRS	1	0
FORCED INTERR	HM	LA 04	41247	E57M	5463854	220031080057 F	4/18/2003	164	0	0	0	UNKNOWN	UNKNOWN	4434 CICADA LN	2	LF	E57M	PR		BAD SPAN BETWEEN 4834 SANDYDALE Y SIDE AND 4848 SANDYDALE X SIDE CLOSE X AT 4848 CICADA AND CLOSE T.P E-57M 65T DIRECT BURY SWITCHING ORDER 8111. REF TP SENT MSG		1	0
FORCED INTERR	HM	LA 04				220031080057 F	4/18/2003	164	144	50	7200	UNKNOWN			2	LF	E57M					0	0
FORCED INTERR	HM	LA 04				220031080057 F	4/18/2003	164	144	4	576	UNKNOWN			2	LF	E57M					0	0
FORCED INTERR	CH	NM 04	41525	4C9		320031080045 F	4/18/2003	170	52	68	3536	UNKNOWN	UNKNOWN	12813 COULSO	1	LF	4C9			REFUSED NORTH PHASE OF 3 PHASE LF 4C9---LEFT OK. REF LF;		1	0
FORCED INTERR	BA	LP 02	41687	8NP	6252524	320031080051 F	4/18/2003	174	0	0	0	UNKNOWN	UNKNOWN	3215 BAYOU (8	2	LF	8NP	BU	625252466	CHANGED OUT A BAD 75 KVA 7200/120-240 WITH THE SAME. RPLD BU TR.		1	0
FORCED INTERR	BA	LP 02				320031080051 F	4/18/2003	174	98	7	686	UNKNOWN			2	LF	8NP					0	0
FORCED INTERR	BA	LP 02				320031080051 F	4/18/2003	174	98	5	490	UNKNOWN			2	LF	8NP					0	0
FORCED INTERR	BA	LP 02				320031080051 F	4/18/2003	174	249	6	1494	UNKNOWN			2	LF	8NP					0	0
FORCED INTERR	CH	AD 08	40085	X67G	5463021	220031080064 F	4/18/2003	174	137	1	137	UNKNOWN	UNKNOWN	CHRISMAN, N O	1	LF	X67G			REFUSED TWO PHASE OF LINE FUSE, REF LF		1	0
FORCED INTERR	KY	KT 43	20082	10SU	3958604	120031080080 L	4/18/2003	174	70	1	70	OH SEC/DR CL H	OH SC CL-H	4427 GASSNER	1	DR				RPLD CONN @ WH;		1	0
FORCED INTERR	BL	UL 02	10325		51562001	120031080081 T	4/18/2003	1751	42	1	42	UNKNOWN	UNKNOWN	8015 SKYLINE		TF	515620015			REFUSED 50 KVA 277/480 POT PULLED FUSE, REF TR.		1	0
FORCED INTERR	FB	RE 03	10954		4449213	120031080082 T	4/18/2003	180	22	5	110	BU DISC OR BARI	DISC/BARRL	5101 AVENUE H		TF	444921372			REF TR, RPLD BU BARREL ON TR.	BRS	1	0
FORCED INTERR	BL	WW 0	10661	S96U	5054227	120031080084 F	4/18/2003	182	0	0	0	TERMINATOR	TERMINATO	8431 WEDNESB	2	LF	S96U	BU	505422591	REPLACED BAD 50 KVA URD POT TRANSFORMER [illegible], RPLD BU TR;		1	0
FORCED INTERR	BL	WW 0				120031080084 F	4/18/2003	182	81	7	567	TERMINATOR			2	LF	S96U					0	0
FORCED INTERR	BL	WW 0				120031080084 F	4/18/2003	182	105	16	1680	TERMINATOR			2	LF	S96U					0	0
FORCED INTERR	BL	WW 0				120031080084 F	4/18/2003	182	149	3	447	TERMINATOR			2	LF	S96U					0	0
FORCED INTERR	SH	WEB0	31163	N145N	6148037	320031080056 F	4/18/2003	183	67	32	2144	UNKNOWN	UNKNOWN	2006 BACK BAY	2	LF	N145N			REFUSED TP N 145 N., REF TP	BRS	1	0
FORCED INTERR	SB	SR 12	21677	8N6	4959401	120031080085 T	4/18/2003	184	50	7	350	BU DISC OR BARI	DISC/BARRL	1603 SHADOW	1	TF	495940181			REPL KEARNEY FUSE BARREL ON 50 KVA POWER POT IN CLOSED DELTA, REF TR.	BRS	1	0
FORCED INTERR	GP	THW4	20729	88AW	4964122	220031080068 L	4/18/2003	191	94	1	94	OH SEC/DR CL N	OH SC CL-N	9423 WAVING F	2	SC				BU NEU LUG IN PED-REPL, RPLD SEC CONN @ PED-1 CUST		1	0
FORCED INTERR	SH	WEB0	31163	N145N	6148037	320031080063 F	4/18/2003	201	180	32	5760	URD XFMR SEC E	URD TR BUS	2010 BACK BAY	2	LF	N145N	BU	614803775	REPLACED A BAD 100 KVA URD TRTANS., REF TP, RPLD BU TR.		1	0
FORCED INTERR	HC	HOC0	11184	7W5	5253448	120031080086 T	4/18/2003	202	70	3	210	TREE CLEARANC	TREE CLEA	10711 1/5 MAIN	1	TF	525344890			FOUND ON-CUST NOTIFIED; REFUSED TRANS ADJACENT CABLE EQUIP REF TR.	BRS	1	0
FORCED INTERR	MP	GG 01	40950		5554245	220031080070 T	4/18/2003	202	24	2	48	UNKNOWN	UNKNOWN	8142 LONG		TF	555424577			REF TR.		1	0
FORCED INTERR	KY	FL 44	12497	B68D	4555014	120031080092 F	4/18/2003	204	114	11	1254	LIGHTNING ARRE	LTNG ARRS	6207 CANYON T	2	LF	B68D	TF	455500475	REPLACED A BAD LIGHTNING ARRESTER ON T/P B68D @ 6203 CANYON TOP CT & REPLACED A BAD BAYENETT FUSE IN URD TRANS #3 @6214 CANYON TOP CT & REFUSED T/P B68D X FEED		1	0
FORCED INTERR	HC	AR 41	12734	47RE	5344956	120031080093 T	4/18/2003	205	52	1	52	O/H PRIMARY CL	OH PR CLMF	8515 KIRCHNER	1	PR	534495609			RPLD B/O PRI JUMP-TF NOT BLOWN;		1	0
FORCED INTERR	CY	TB 44	21021	J93G	4672914	220031080073 F	4/18/2003	210	70	18	1260	VINES	VINES	14702 ROCK EL	1	LF	J93G	TF	467291422	REF LF, REF TR.	BRS	1	0
FORCED INTERR	CH	CV 08	40459	E91J	5958451	320031080064 T	4/18/2003	215	91	4	364	BU DISC OR BARI	DISC/BARRL	707 DEERPASS	1	TF	595845159			REPLACED BURNT UP KEARNEY FUSE BARRELL ON 75 KVA CONV XFMR--, RPLD BU BARREL ON TR.		1	0
FORCED INTERR	GA	KM 05	41211	2D4	6351300	320031080065 T	4/18/2003	220	149	2	298	LIGHTNING ARRE	LTNG ARRS	409 BAYWOOD	1	TF	635130073			REF TR.		1	0
FORCED INTERR	GA	GA 05	31077	74X	6737645	320031080068 L	4/18/2003	2251	65	1	65	FOREIGN MATER	FRGN MATR	5621 TEAKWOO	1	DR				replaced sec clamps at wh bad hot leg. RPLD CONN @ WH.		1	0
FORCED INTERR	CH	GP 08	40827		5756130	320031080070 T	4/18/2003	235	65	2	130	TREE CLEARANC	TREE CLEA	206 EASTWAY		TF	575613079			NEED TREE TRIM AROUND TRANS; REF TR. *SENT MSSG TO SC FOR TREE TRIMMING. . . *MPO		1	0
FORCED INTERR	BL	FD 01	10689	W86		120031090001 F	4/19/2003	000	64	135	8640	TREE CLEARANC	TREE CLEA	7003 BISSONNE	1	LF	W86			REFUSED WEST PHASE OF L/F W86 DUE TO TREES AND A BALLOON IN PRIMARY WILL TURN IN TO TREE TRIMMERS FOR TRIMMING, REF LF		1	0
FORCED INTERR	GA	PHR01	30831	34CS	6446139	320031090001 T	4/19/2003	003	166	7	1162	FIRE	FIRE	1103 27TH #1	1	SC	644613935			SPLICED #2ALUM TO 4/0 SEC TO KEEP SYSTEM NEUTRAL CLOSE, CHANGED 4/0 DROP TO NEXT TRANF UNTIL SOME ONE CAN COME AND REPLACE SEC ASAP 4/0 TWIST DIDNT HAVE ANY ON		1	0
FORCED INTERR	MP	AN 04	40024	8K8	5359745	220031090002 F	4/19/2003	004	79	16	1264	TREE CLEARANC	TREE CLEA	LINK @ TABOR	1	LF	8K8			FALLEN TREE BRANCH., REF LF		1	0
FORCED INTERR	MP	HM 03	11016	2AW	5454058	220031090004 T	4/19/2003	010	89	1	89	UNKNOWN	UNKNOWN	6804 WINTON	1	TF	545405885			REFUSED 50 KVA LIGHTER IN OPEN DELTA UNKNOWN, REF TR.		1	0
FORCED INTERR	GP	AD 04	40079		5363027	220031090005 T	4/19/2003	0201	34	6	204	UNKNOWN	UNKNOWN	203 W HELMS #		TF	536302744			REF TR.		1	0
FORCED INTERR	BA	CD 09	40138	9ER	6456357	320031090002 L	4/19/2003	020	153	1	153	TREE CLEARANC	TREE CLEA	2302 CAMELIA C	1	SC				RPLD SEC CONN @ PL-1 CUST;		1	0
FORCED INTERR	SB	CB 08	21451	D68C	5059259	120031090004 T	4/19/2003	030	125	11	1375	TREE CLEARANC	TREE CLEA	9254 NORTON	1	PR	505925937			RESET TR; RPLD B/O PR JUMP-TF BLOWN.	BRS	1	0
FORCED INTERR	CH	BE 04	40233	I62W	5561319	320031090006 T	4/19/2003	032	64	2	128	BU DISC OR BARI	DISC/BARRL	9010 SHADY	1	TF	556131961			RPLD BU BARREL ON TR.		1	0
FORCED INTERR	SU	RO 02	12235	F99C	4953033	120031090005 F	4/19/2003	032	0	0	0	SPLICE	SPLICE	11302 LARKDAL	2	LF	F99C	PR		FOUND BAD SPAN OF PRI BETWEEN TRANS 10 AND 11 7200 CABLE ISOLATED GOT ALL SERVICE BACK ON ASSISTED BY 2571 BLANKENSHIP ISOL URD PR. SENT MSG TO TAD*BRS*W		1	0
FORCED INTERR	SU	RO 02				120031090005 F	4/19/2003	032	289	15	4335	SPLICE			2	LF	F99C					0	0
FORCED INTERR	SU	RO 02				120031090005 F	4/19/2003	032	289	22	6358	SPLICE			2	LF	F99C					0	0
FORCED INTERR	FB	OB 42	11376	69EB	4550357	120031090006 T	4/19/2003	034	129	2	258	BIRD	BIRD	1515 SAVANNA	1	TF	455035732			TRIMMED TREES REPLACED LIMITER. REFUSED A 50 KVA. OUT BY BIRD DOES HAVE WILDLIFE PROTECTION INSTALLED. RPLD LIMITER @ TR REF TR.	BRS	1	0
FORCED INTERR	SU	STF02	14279	308Z	48515071	120031090007 F	4/19/2003	053	80	6	480	BU DISC OR BARI	DISC/BARRL	4 REGENT CT	2	LF	308Z			REPLACED BURNED UP BARREL AND CLOSED T.P.308Z. RPLD BU BARREL ON TP *ALSO 1-SP FROM HERE IS A 3-PH DIP POLE#5862 (WEST) HAS VINES SOO HEAVY.CAN ONLY SEE TOP TH		1	0
FORCED INTERR	SU	WI 42	11993	F43R	4756328	120031090010 F	4/19/2003	072	0	0	0	SPLICE	SPLICE	2227 BRIARVIEV	2	LF	F43R	PR		REPLACED BAD 500 KV 16 8/7200 W/SAME *NO BUTTON WAS HIT*NEW TF PAPS OLD DROPPED OFF @ FT8*ALSO,LEFT BAD SP PRI ISOL BTWN TFS'@ 14207 & 14215,ELLA LEE LN(DIRECT BU		1	0
FORCED INTERR	SU	WI 42				120031090010 F	4/19/2003	072	190	2	380	SPLICE			2	LF	F43R					0	0
FORCED INTERR	SU	WI 42				120031090010 F	4/19/2003	072	448	15	6720	SPLICE			2	LF	F43R					0	0
FORCED INTERR	GA	GA 05	31077	74X	6737645	320031090006 T	4/19/2003	072	172	5	860	OH SEC/DR CL H	OH SC CL-H	5621 TEAKWOO	1	SC	673764555			REPL CLAMPS AT THE TRANS FEEDING SEC AND REPL METER JAWS. RPLD SEC CONN @ PL-1 CUST RPLD MTR JAWS/LUGS.		1	0
FORCED INTERR	GP	LK 07	20070	K90L	5262725	220031090006 T	4/19/2003	075	84	13	1092	SQUIRREL	SQUIRREL	770 ENTERPRIS	1	TF	526272593			REFUSED TRANSFORMER TOOK OUT BY SQUIRREL, REF TR, RESET TR;		1	0
FORCED INTERR	SU	WI 41	12380		4756821	120031090012 T	4/19/2003	075	64	13	832	BIRD	BIRD	13318 WESTHEI		TF	475682162			REFUSED 2 167 TRANS OUT BY BIRD ALREADY WLP; REF TR.		1	0
FORCED INTERR	MP	CR 01	41063	LW7	5359605	220031090013 T	4/19/2003	080	63	5	315	UNKNOWN	UNKNOWN	815 FUGATE	1	TF	535960595			REFUSED 25 KVA XFMR # HAS WILDLIFE PROTECTION; REF TR.		1	0
FORCED INTERR	SB	GE 46	21189	N35M	4760042	120031090013 F	4/19/2003	081	57	121	6897	TREE CLEARANC	TREE CLEA	4507 JURA	2	LF	N35M			TRIMMED TREES FROM Y-T.P. N-35-M, REF TP		1	0
FORCED INTERR	GP	LK 02	21868	E35V	5262645	220031090015 F	4/19/2003	082	46	37	1702	SQUIRREL	SQUIRREL	8355 PONNEL L	2	LF	E35V			REF TP		1	0
FORCED INTERR	SH	CC 04	30173	U15	5452828	320031090011 F	4/19/2003	084	48	36	1728	UNKNOWN	UNKNOWN	5615 GREYLOG	1	LF	U15			REFUSED LF -- SQUIRREL ON UNCOVERED CIP ??? REF LF		1	0
FORCED INTERR	SU	CE 11	11978	10CJ	4854104	120031090015 F	4/19/2003	092	31	7	217	BIRD	BIRD	13150 BISSONN	2	LF	10CJ			REFUSED T/P 10CJ 50 T BIRD HUNG IN DISCONNECT REF TP,		1	0
FORCED INTERR	BZ	FP 06	30419	A78T	5523017	320031090016 F	4/19/2003	094	79	14	1106	BU DISC OR BARI	DISC/BARRL	410 W 9TH	1	LF	A78T			REFUSED LF A-78-T 65-T REF LF		1	0
FORCED INTERR	BZ	BZ 08	30636	A98Z	5326139	320031090017 L	4/19/2003	095	46	1	46	TREE CLEARANC	TREE CLEA	543 SYCAMORE	1	SC				RPLD SEC CONN @ PL-1 CUST		1	0
FORCED INTERR	MP	EU 07	40736		5259105	220031090021 T	4/19/2003	100	76	14	1064	SQUIRREL	SQUIRREL	2431 DROXFOR		TF	525910589			TRIMMED TREES OFF OF 75 KVA XFMR AND PRIMARY # HAS WILDLIFE PROTECTION SQUIRREL GOT INTO HORSESHOE BRACKET HUNG DISCONNECT IN REAR OF 2431 DROXFORD. STILL HA		1	0
FORCED INTERR	BA	MB 03	41425	R75X	6459940	320031090018 T	4/19/2003	1011	43	10	430	SQUIRREL	SQUIRREL	9738 PINEHURS	1	TF	645994087			REFUSED 100KV TR. DUE TO SQUIRREL, REF TR.		1	0
FORCED INTERR	GA	GA 07	31211	T9B	6738511	320031090021 T	4/19/2003	102	119	13	1547	TREE CLEARANC	TREE CLEA	1514 CAMPBELL	1	TF	673851182			NEED TO HAVE THIS TREE CUT DOWN IT IS REALLY BAD COVERING THE WHOLE TRANS REF TR	RGR	1	0
FORCED INTERR	BZ	VL 04	3526D	E92F	5724113	320031090022 T	4/19/2003	102	66	2	132	STRONG WIND	WIND	123 SANDPIPER	1	SC	572411340			RPLD CONN @ TR.		1	0
FORCED INTERR	GA	GL 05	30481	P5W	6838238	320031090025 L	4/19/2003	104	130	1	130	OH SEC/DR CL H	OH SC CL-H	2915 AVENUE M	1	SC				REPL. CLAMP AT THE POLE, RPLD CONN @ PL.		1	0
FORCED INTERR	SH	FW 01	30434	E51A	5847952	320031090026 T	4/19/2003	105	152	8	1216	UNKNOWN	UNKNOWN	17022 FOREST	2	SC	584795261			BAD SEC BETWEEN 17018 & 17022, INST SEC BYPASS;		1	0
FORCED INTERR	FB	CRB4	11461	R43Y	4648318	120031090026 L	4/19/2003	110	142	1	142	CONTRACTOR-N	CON-NT HLF	623 TARA PLAN	2	DR				installed temp bypass at 628 JEFF DAVIS, RAN BYPASS-HL&P OWNED DR,		1	0
FORCED INTERR	GA	STW0	31424	4DS	64331441	320031090028 L	4/19/2003	1151	117	1	117	OH SEC/DR CL H	OH SC CL-H	18527 EDWARD	1	SC				REPL CLAMP AT THE POLE ALSO REPL CLAMP FEEDING 18531 EDWARD TEACH, RPLD CONN @ PL.		1	0
FORCED INTERR	GA	STW0	3535D	8CE	6232306	320031090030 L	4/19/2003	121	130	1	130	OH SEC/DR CL H	OH SC CL-H	3603 ANTASCO	1	SC				REPL CLAMPS AT THE POLE RPLD CONN @ PL.		1	0
FORCED INTERR	BL	UL 45	13083	G88H	5056855	120031090035 T	4/19/2003	1231	132	5	660	VINES	VINES	6435 SAN FELIP	1	PR	505685509			RM VINES AND MADE REPAIRS TO LOW SIDE JUMPER FEEDING A 50 KVA 7200 277/480 XFMR. RPRD B/O PRI JUMP-TF NOT BLOWN.		1	0
FORCED INTERR	HC	PZ 42	13003	Y65L	5354541	120031090036 F	4/19/2003	123	78	82	6396	BIRD	BIRD	7575 CAMBRID	2	LF	Y65L			REFUSED TERMINAL POLE, REF TP.		1	0
FORCED INTERR	SB	SR 10	22361		4957456	120031090037 T	4/19/2003	123	83	4	332	VINES	VINES	530 HALLIE DR		TF	495745660			RF PWR TR, REF TR.		1	0
FORCED INTERR	BZ	VL 04	3526D	84GJ	5724228	320031090032 F	4/19/2003	123	16	1	16	BU DISC OR BARI	DISC/BARRL	2211 BLUEWAT	1	LF	84GJ			REFUSED L.F. 84-GJ 25-T .. REF LF		1	0
FORCED INTERR	BL	DN 01	10539	W67V	5257816	120031090039 F	4/19/2003	1241	357	20	7140	TRANSFORMER	TRANSFRM	2219 PINE VLY	1	LF	E36L	PR		CREW PICKED UP 2 SPANS OF PRIMARY AND REFUSED LFE36L NO SUBCASING 0---ABK		1	0
FORCED INTERR	FB	RE 04	11447		4449314	120031090041 T	4/19/2003	124	104	7	728	OH SEC/DR CL H	OH SC CL-H	5192 AVENUE H		SC	444931424			REPL BAD TR. LUG. RPLD CONN @ TR.		1	0
FORCED INTERR	GP	LK 09	41128	K92L	5261928	220031090027 L	4/19/2003	125	79	1	79	TREE CLEARANC	TREE CLEA	5711 YALE ST #	1	DR				RPRD CONN @ WH.		1	0
FORCED INTERR	GA	GL 08	30488	E42E	6838545	320031090033 L	4/19/2003	125	157	1	157	OH SEC/DR CL N	OH SC CL-N	1910 AVENUE M	1	SC		DR		REPL. CLAMPS @ THE POLE AND WH .... REP NEUTRAL ON DROPS NO ONE HOME, RPLD CONN @ WH, RPRD DR, RPLD CONN @ PL.	RGR	1	0
FORCED INTERR	HC	HM 05	11032	W19Y	5453329	120031090046 L	4/19/2003	132	56	1	56	OH SEC/DR CL H	OH SC CL-H	8932 CULLEN B	1	DR				FOUND BAD CLAMP AT WHEAD REPLACED ALL CLAMPS AT WHEAD. RPLD CONN @ WH.		1	0
FORCED INTERR	CH	OA 04	41365	GU10	5658809	320031090037 T	4/19/2003	1341	85	22	1870	SQUIRREL	SQUIRREL	10206 PALESTI	1	TF	565880970			TRANSFORMER FUSE BLOWN DUE TO ROCKY THE FLYING SQUIRREL REFUSED TRAN- FORMER TRIMMED TREE ALL AROUND TRANSFORMER AND SEC REF TR.		1	0
FORCED INTERR	SH	SO 43	12793		5448930	320031090038 T	4/19/2003	134	76	4	304	TREE CLEARANC	TREE CLEA	2734 ASH RD		TF	544893028			trimmed trees on refused tran, REF TR.		1	0
FORCED INTERR	MP	EU 07	82006		5259510	220031090031 T	4/19/2003	134	79	10	790	BU DISC OR BARI	DISC/BARRL	1614 TANNEHIL		TF	525951061			REPLACED FUSE BARREL ON CHANCE DISCONNECT ON POWER XFMR IN CLOSED DELTA. RPLD BU BARREL ON TR, REF TR	RGR	1	0
FORCED INTERR	MP	WO 14	41886	49F	5160920	220031090032 T	4/19/2003	134	36	7	252	LIGHTNING ARRE	LTNG ARRS	2310 CHANTILL	1	TF	516092055			REFUSED 50 KVA XFMR # HAS WILDLIFE # ARRESTOR WENT BAD; REF TR	RGR	1	0
FORCED INTERR	HC	PZ 42	13003	Y65L	5354541	120031090048 T	4/19/2003	135	144	20	2880	FOREIGN MATER	FRGN MATR	7575 CAMBRID	2	BU	535454148			REPLACE 167 19.9 URD TRAN, RPLD BU TR.		1	0
FORCED INTERR	BL	BR 01	10801		5254403	120031090050 T	4/19/2003	143	159	6	954	BU DISC OR BARI	DISC/BARRL	3631 WOODVAL		TF	525440308			REPL BURNED UP FUSE BARREL ON 50 KVA CONV OPEN DELTA.., REF TR.		1	0
FORCED INTERR	BA	TRM0	4316A		6657459	320031090041 T	4/19/2003	145	182	1	182	O/H PRIMARY CL	OH PR CLMF	14830 FM 2354 F		SC	665745923	SC		PICKED UP 2- SPANS OF PRI NEUTRAL WIRE REFUSED LF M81F 25T EAST PHASE ALSO REPL 1-12KV L.A. P/U PR NEUT RPLD LIGHTNING ARRESTOR		1	0
FORCED INTERR	GP	LK 10	22122	FW2	5261040	220031090036 F	4/19/2003	145	119	9	1071	UNKNOWN	UNKNOWN	W LITTLE YORK	1	LF	FW2	BU	526104078	RPLD BU TR; (PARENT FUSE - UNABLE TO LOWER CASE LEVEL - SEV OA) CORRECTED 2HR/CRH		1	0
FORCED INTERR	SH	CG 04	30217	C818	57541031	320031090042 L	4/19/2003	152	97	1	97	OH SEC/DR CL N	OH SC CL-N	2707 FOREST O	1	DR				AGE, RPLD CONN @ WH;		1	0
FORCED INTERR	GA	AL 07	30036	45HT	6041546	320031090044 F	4/19/2003	153	104	4	416	VINES	VINES	13715 8TH	1	LF	45HT			REFUSED SINGLE PHASE LINE FUSE 45HT POSSIBLY TAKEN OUT BY VINE. REF LF		1	0
FORCED INTERR	SB	CB 09	21460	J55R	4959340	120031090055 F	4/19/2003	163	83	1	83	UNKNOWN	UNKNOWN	10660 HAMMERI	3	LF	J55R			REF TP		1	0
FORCED INTERR	CH	PW 05	40944	S74J	5859144	320031090048 T	4/19/2003	181	40	6	240	UNKNOWN	UNKNOWN	14245 WALLISV	1	TF	585914446			REFUSED SOUTH POWER POT IN CLOSED DELTA BANK REF TR.		1	0
FORCED INTERR	BA	TRM0	4316A		6657459	320031090050 T	4/19/2003	183	91	1	91	UNKNOWN	UNKNOWN	14830 FM 2354 F		TF	665745923			RFUSED 25KV TR REF TR.		1	0
FORCED INTERR	GP	SA 50	20863	W59H	4962816	220031090049 F	4/19/2003	184	3	5	15	UNKNOWN	UNKNOWN	WINDFERN @ K	1	LF	W59H			REFUSED LF REF LF		1	0
FORCED INTERR	GA	AL 08	30526	1J8	6141504	320031090052 F	4/19/2003	184	40	15	600	UNKNOWN	UNKNOWN	5908 AVENUE F	1	LF	1J8			THERE'S 4 CSP THAT NEEDS SWITCHES ADDRESSES 5641 5711 5722 & 5610 AV F ALSO @ 5711 NEED TREE TRIMMED. REF LF NO SUBCASING---ABK		1	0
FORCED INTERR	SH	SB 04	31043	G58D	5855734	320031090060 T	4/19/2003	231	46	12	552	BU DISC OR BARI	DISC/BARRL	2716 NORMAN	1	TF	585573405			replaced bu kearney barrel. RPLD BU BARREL ON TR.		1	0
FORCED INTERR	HM	LA 03	41241	A94C	5463639	220031100002 T	4/20/2003	021	47	7	329	UNKNOWN	UNKNOWN	3719 BLUE MEA	1	TF	546363901			REFUSED 50 KVA, REF TR.		1	0
FORCED INTERR	KY	MAR4	24818	A41A	45579581	120031100003 T	4/20/2003	031	61	4	244	OTHER WILDLIFE	OTHER WLI	811 KINGSFOR	1	TF	455795811			REFUSED XFMR # VARMIT ON SECONDARIES # HAS WILDLIFE. REF TR		1	0
FORCED INTERR	BA	CD 06	40375		6457253	320031100001 T	4/20/2003	035	277	4	1108	UNKNOWN	UNKNOWN	1402 BOB SMIT		BU	645725337			REPLACED 75 KVA 7200/120/240 9KV LA 12KV SWITCH SEARIAL # ON OLD TRANSFORMER D667809-58Y RPLD BU TR.		1	0
FORCED INTERR	BL	ST 16				120031100005 C	4/20/2003	040	0	0	0	COLLISION	GUYWIRE	7525,HILLCROF		CL	ST16	PR		SO#115 CAR HIT GUY WIRE,2 BROKEN XARMS,2PH PRI DWN(BROKE-2-PLACES) BIG CREW CALLED OUT CUT 3-PH JUMPERS @ 7525 HILLCROFT(EAST SIDE HILLCROFT) EL NAMPO		1	1
FORCED INTERR	BL	ST 16	10231			120031100005 C	4/20/2003	040	37	756	27972	COLLISION				CL	ST16					0	0
FORCED INTERR	BL	ST 16	1G477			120031100005 C	4/20/2003	040	84	621	52164	COLLISION				CL	ST16					0	0

FORCED INTERR	KY	KT 41	22770		4358949E	120031100011	T	4/20/2003	0705	137	4	548	UNKNOWN	UNKNOWN	23839	SILVERSA	TF	435894963	PR								RFZ TR NO CALIBRANST KMA1E AND WLP REF TR, RPLD BIO PR JUMP-TF BLOWN, ROR	1	0
FORCED INTERR	CH	GP 06	40815	N23K	56565558	120031100006	T	4/20/2003	0711	38	16	608	SQUIRREL	SQUIRREL	114	GEORGIA 1	TF	565655874									REF TR.	1	0
FORCED INTERR	BL	JN 11	10039	D58	50551556	120031100012	L	4/20/2003	0731	173	1	173	VANDALISM	VANDALISM	3901	OCEE 1											REPLACE CLAMPS @ POLE AND MID SPAN DUE TO GUN SHOTS , RPRD SEC CONN @ PL-1 CUST.	1	0
FORCED INTERR	CH	UV 08	41777	PW4	58616316	120031100008	T	4/20/2003	0750	70	7	490	SQUIRREL	SQUIRREL	14325	FOREST I 1	TF	586163190									REFUSED 37.8 KVA CONV XFMR--NEED TO STRAIGHTEN 40' CLA POLE ~33ft FROM 14308 BEAUMONT HWY -(GRANGER ELECT.)--CUST STATES HAS CALLED SEVERAL TIMES-TR ALREADY HA	1	0
FORCED INTERR	SL	PT 07	22493	Z45	34606614	120031100014	F	4/20/2003	0805	156	1	156	COLLISION	COLLISION	FM 331	@ PETE 1	LF	Z45	PD								NEED TO REPLACE 50 FT CLASS 3 ASAP HIT BY CAR BROKEN 1/2 WAY UP 3 PHASE DELTA CONSTRUCTION 1 PHASE LATERAL BREAKING OFF WIE SPLICED WITH 3 ARM TRUCK ACESSABLE IF	1	0
FORCED INTERR.	CH	GP 08	40823	AB3	57562495	120031100007	T	4/20/2003	0805	63	7	441	SQUIRREL	SQUIRREL	1311	STH 1	TF	575624907									REF TR.	1	0
FORCED INTERR	SB	GE 47	22162	T28L	46605221	120031100016	F	4/20/2003	0815	60	19	1140	TREE CLEARANC	TREE CLEAR	3907	HEATHERS 2	LF	T28L									REFUSED T/P T-28-L TRIMMED TREES FOLLOW UP NEEDED, REF TP ROR	1	0
FORCED INTERR	CH	SW 09	41697	J59S	55627410	120031100008	T	4/20/2003	0817	105	14	1470	VINES	VINES	6415	HANLEY LI 1	TF	558274103									RM VINES OFF TRANS & POLE, REF TR.	1	0
FORCED INTERR	BL	ST 15	10278	TL2	51553415	120031100017	T	4/20/2003	0852	62	3	186	UNKNOWN	UNKNOWN	5705	GREEN AS 1	TF	515534194									REFUSED LIGHTER-100KVA X-FMER,DUE TO A BROKE FUSE,ALSO MADE REPAIRS TO LIGHTER- LEG ON A 40 4w DROP X-FMER LOC @ 6705 GREEN ASH DR, REF TR	1	0
FORCED INTERR.	HC	AR 42	13162		52468316	120031100016	T	4/20/2003	0914	138	1	138	BIRD	BIRD	5830	COUNTY R	TF	524683190	PR								REPLACED LIGHTER FUSE TAKEN OUT BY BIRD NEED TO INSTALL WILD LIFE PROTECT RPLD LIMITER @ TR, REF TR, ROR	1	0
FORCED INTERR	CH	LY 42	47060	4KS		320031100012	F	4/20/2003	0937	26	2	52	SQUIRREL	SQUIRREL	BEAR BAYOU	E 1	LF	4KS	TF	605955025							REFUSED 25 KVA CONV, REF TR. FUSE 4KS WAS NOT BLOWN WENT TO PARENT LINE FUSE, COULD NOT DOWN GRADE TO TRANSFORMI	1	0
FORCED INTERR	BZ	BZ 01	31166	N89Y	53263020	120031100013	T	4/20/2003	0940	28	1	28	BU DISC OR BARI	DISC/BARRL	128	FLAG LAKE 1	TF	532630267									50 KVA 277/480, REF TR.	1	0
FORCED INTERR	CH	SW 06	41684	2GE	55615534	120031100015	T	4/20/2003	0945	61	14	854	SQUIRREL	SQUIRREL	10121	ROCKAW 1	TF	556155341									REF TR.	1	0
FORCED INTERR	GP	BA 43	22073		50655304	120031100015	T	4/20/2003	0944	183	1	183	LIGHTNING	LIGHTNING	11103	CANYON	BU	506553041	PR								NO LOAD TO GET A LOAD CHECK REPLACED A BAD 277/480 - 167.5 -100 KVA OH TRANSFORMER, LIGHTNING ARRESTER, & K-MATE 12 LIMITER ---TRANS. FROM & TO GREENPOINT RPLD BAU	1	0
FORCED INTERR.	SH	PA 03	30764	C40B	57543205	120031100017	L	4/20/2003	1014	38	1	38	OH SEC/DR CL H	OH SC CL-H	5618	WINDING (1	SC										RPLD SEC CONN @ PL-1 CUST	1	0
FORCED INTERR	SH	SP 04	31363	96JM	58535558	120031100015	T	4/20/2003	1059	39	1	39	UNKNOWN	UNKNOWN	4021	SPENCER 1	TF	585355880									REF TR.	1	0
FORCED INTERR	BA	UW 05	40922	26HN	61541353	120031100020	F	4/20/2003	1100	94	5	470	LIGHTNING ARRE	LTNG ARRS	N L, W OF COU	1	LF	26HN	TF	615413522	DB						REF LF RPLD BAU DISC-TF NOT BLOWN, REF TR, RPLD LIGHTNING ARRESTOR;	1	0
FORCED INTERR	GA	AL 06	30032		60429375	120031100021	T	4/20/2003	1100	49	3	147	BU DISC OR BARI	DISC/BARRL	12725	4 1/2	TF	604293758	DB								HAD TO REPLACE SWITCH AND LOAD WIRE IN POT AND REMOVED VINES FOR AROUND AND ON POLE ..... , RPLD BAU DISC-TF BLOWN;	1	0
FORCED INTERR	CY	TB 45	21030	U74Z	45712074	120031100018	T	4/20/2003	1100	49	2	98	LIGHTNING	LIGHTNING	18926	MISTY LN 1	TF	457120742									REFUSE 25/16.8 TRANSFORMER, REF TR.	1	0
FORCED INTERR	CH	SW 07	41689	4C3	55623047	120031100022	T	4/20/2003	1110	23	6	138	SQUIRREL	SQUIRREL	10430	WICKLOW 1	TF	556230467									REF TR.	1	0
FORCED INTERR	CY	CYF41				220031100016	C	4/20/2003	1133	0	0	0	LIGHTNING	LIGHTNING	CYF41	CKT LOC	CL	CYF41									NON 10%---R/C EQUIP SHOWED FAULT BEHIND R/C P18 17217---OPENED R/C P 18 17217---CLOSED BRKR---CREWS IN ROUTE---TRIED R/C P18 17217 AND HELD---CREW STATED LIGHTNING	1	1
FORCED INTERR	CY	CYF41	2G068			220031100016	C	4/20/2003	1133	9	1364	12546	LIGHTNING				CL	CYF41										0	0
FORCED INTERR	CY	CYF43	2G068			220031100016	C	4/20/2003	1133	9	700	6300	LIGHTNING				CL	CYF41										0	0
FORCED INTERR	SB	SA 47	2G068			220031100016	C	4/20/2003	1133	9	685	6185	LIGHTNING				CL	CYF41										0	0
FORCED INTERR.	CY	CYF41	20902			220031100016	C	4/20/2003	1133	25	2064	51800	LIGHTNING				CL	CYF41										0	0
FORCED INTERR	SU	AF 01	11750	C21P	49541475	120031100022	F	4/20/2003	1138	39	19	741	SQUIRREL	SQUIRREL	10826	SELA LN 2	LF	C21P									REF TP	1	0
FORCED INTERR	KY	KT 41	22589		42609041	120031100024	T	4/20/2003	1140	45	2	90	LIGHTNING ARRE	LTNG ARRS	3746	KATY HOC	TF	426090400									NEED TO RPLC 10.8 ARRESTOR & INSTALL WLP; REF TR; BRB	1	0
FORCED INTERR.	GP	SA 49	2D152	47CC	48645124	120031100027	F	4/20/2003	1148	208	18	3744	LIGHTNING	LIGHTNING	10254	CROOKS 2	LF	47CC									REPLACE LIGHTNING ARRESTOR ON ON TP 47CC; REF TP;	1	0
FORCED INTERR	GP	BA 45	21148	99FV	50665566	220031100034	F	4/20/2003	1152	74	1	74	LIGHTNING	LIGHTNING	13800	BRECK 1	LF	99FV	TF	506655662							REFUSE LIGHTER TRANS AND TOP PHASE OF LINE FUSE, REF LF REF TR; BRB	1	0
FORCED INTERR	GP	LU 41	20148	S3062	51686320	120031100046	T	4/20/2003	1200	86	9	774	LIGHTNING	LIGHTNING	1419	TUCUMCA 1	PR	516863204									RPLD LIMITER @ TR, REF TR, RPLD LIGHTNING ARRESTOR, BRB	1	0
FORCED INTERR	SB	SA 47	21219	81AI	47634351	220031100046	F	4/20/2003	1200	111	111	12321	LIGHTNING	LIGHTNING	8750	POINT PAF 2	LF	81AI									REF TP	1	0
FORCED INTERR	CY	CYF42	22025	73FE	46637081	220031100050	F	4/20/2003	1200	58	12	696	LIGHTNING	LIGHTNING	7814	MCCORMIC 1	LF	73FE									REFUSED LF 73FE 80T @ 16607 MCCORMICK, REF LF	1	0
FORCED INTERR	CY	CYF42	22087	89UN	46637015	220031100051	F	4/20/2003	1200	95	40	3800	LIGHTNING	LIGHTNING	16646	MILLRIDG 2	LF	89UN									RPL FZ BARREL, REF TP; RPLD BAU BARREL ON TP; BRB	1	0
FORCED INTERR	CY	KL 47	2463G	37LM	45678336	220031100052	F	4/20/2003	1200	37	7	259	LIGHTNING	LIGHTNING	17926	EMRDSE 1	LF	37LM									REFUSED LF 37LM, REF LF;	1	0
FORCED INTERR	CY	KL 46	2C157	10NP	48666166	220031100052	F	4/20/2003	1200	291	41	11931	TREE CLEARANC	TREE CLEAR	10807	CREEKTR 1	LF	10NP	PR								PICKED UP 1 SPAN OF 1/0 PRIMARY TRIMMED1 SPAN OF TREES. PAU PR-FUSE BLOWN, REF LF BRB	1	0
FORCED INTERR	CY	KL 47	2463G	S3440	45678435	220031100054	T	4/20/2003	1200	72	1	72	LIGHTNING	LIGHTNING	18526	FENSKE 1	TF	456764359									REFUSED 25 KVA 7.2 120/240; REF TR,	1	0
FORCED INTERR	GP	THW4	2P147	S45K	48648445	120031100055	T	4/20/2003	1211	68	6	510	LIGHTNING	LIGHTNING	13003	WINDFER 1	TF	486484431									REF TR.	1	0
FORCED INTERR	GP	THW4	2H147		48648421	220031100056	T	4/20/2003	1211	314	8	2512	LIGHTNING	LIGHTNING	10911	SPRING I	BU	486482173									REPLACED 50 KVA 16.8 120 / 240 TRANS 10911 SPRING HARVEST OH PICKED UP TRANS AT BELLAIRE. RETURENED BAD TRANS BELLAIRE, RPLD BAU TR,	1	0
FORCED INTERR	HM	HB 47	22252		56672568	220031100057	T	4/20/2003	1211	111	1	111	LIGHTNING	LIGHTNING	268	W 1ST	TF	566725653	DB			PR					RPLD BAU DISC-TF BLOWN, RPLD BIO PR JUMP-TF BLOWN; REF TR;	1	0
FORCED INTERR	GP	KDL41	2433C		50725120	220031100080	T	4/20/2003	1222	228	2	456	LIGHTNING	LIGHTNING	5228	CARIBOU	PR	507251201									REPLACED LIMITER FUSE, DID NOT HAVE A LIGHTING ARRESTER TO REPLACE THE ONE BLOWN ON TRF CAN CHANGE LATER B/C CONV; RPLD LIMITER @ TR; REF TR. BRB--BENT MESSA	1	0
FORCED INTERR	CY	TB 46	21041	P5K	47704986	220031100061	F	4/20/2003	1224	282	5	1410	LIGHTNING	LIGHTNING	12900	HOLDERF 1	LF	P5K	PR								RF22 80 KVA 19-7.2/REPLC 1 LIMITIRARF LF PMK RF5 50/1MBT480 AT 28484 HWY 148 (BAME SPOT WE WERE WORKING). REF LF; RPLD LIMITER @ TR; REF TR, RPLD BAU BARREL ON TR.	1	0
FORCED INTERR	GP	LU 42	20087	W93P	51703540	220031100087	F	4/20/2003	1233	0	0	0	SPLICE	SPLICE	21415	GOLDEN 2	LF	W93P	PR								INSULATED BAD TERMINATOR ON X TP WEDP STOCDED OFF X PR @ 21423 GOLDEN DOVE BO # 8124, INSL URD PR	1	0
FORCED INTERR	GP	LU 42				220031100088	F	4/20/2003	1233	202	33	6666	SPLICE				LF	W93P										0	0
FORCED INTERR	CY	SA 45	20997	93SF	47639599	220031100071	F	4/20/2003	1238	86	1	86	LIGHTNING	LIGHTNING	13125	FM1980 W 1	LF	93SF									REFUSED 2 PHASES LF 93-SF LIGHTNING, REF LF	1	0
FORCED INTERR	GP	WF 03	20371	87MH		220031130085	F	4/20/2003	1238	102	1	102	LIGHTNING	LIGHTNING	1950W, E OF CY	1	LF	87MH									REFUSED LF [CORRECTING CASE 220031100730 - BEV QA]	1	0
FORCED INTERR	GP	LU 03	20558	N63H	51684331	120031100073	F	4/20/2003	1237	113	21	2373	LIGHTNING	LIGHTNING	1810	CASTLERC 1	LF	N63H									REF LF	1	0
FORCED INTERR	GP	LU 03	20558	N64H	51684211	220031100076	F	4/20/2003	1240	116	25	2900	TREE CLEARANC	TREE CLEAR	1910	BIG HORN 1	LF	N64H									REF LF.	1	0
FORCED INTERR	GP	LU 04	20547	G24M	51696003	220031100081	F	4/20/2003	1240	94	20	1880	LIGHTNING	LIGHTNING	1103	TERRANO 1	LF	G24M									REF LF	1	0
FORCED INTERR	SB	EC 08	21740	E44S	50581463	120031100025	L	4/20/2003	1245	106	1	106	OH SEC/DR CL H	OH SC CL-H	9618	LONG BRA 1	SC										REPLACED 84CROPS, RPLD SEC CONN @ PL-1 CUST,	1	0
FORCED INTERR	GP	GZ 42				220031100084	C	4/20/2003	1250	0	0	0	FLLNG TREE IN E	TREE FLAE	S OF PTS 12515		CL	GZ42									NON 10%---NO R/C EQUIP ---TRIED BRKR, DID NOT HOLD---ALL BACK HOT ON T&L 8KDR256. NO FAULT FOUND POSIBBLE WEATHER: MAMBRB REFER T&L 8/O 256 CREWS FOUND TREE IN P	1	1
FORCED INTERR	GP	GZ 42	2G098			220031100084	C	4/20/2003	1250	38	799	28784	FLLNG TREE IN E				CL	GZ42										0	0
FORCED INTERR	GP	GZ 42	20464			220031100084	C	4/20/2003	1250	42	470	19740	FLLNG TREE IN E				CL	GZ42										0	0
FORCED INTERR	GP	GZ 42	23001			220031100084	C	4/20/2003	1250	52	15	780	FLLNG TREE IN E				CL	GZ42										0	0
FORCED INTERR	GP	GZ 42	22280			220031100084	C	4/20/2003	1250	54	16	864	FLLNG TREE IN E				CL	GZ42										0	0
FORCED INTERR	HM	RA 42	20438		52714158	220031100085	T	4/20/2003	1254	185	6	990	LIGHTNING	LIGHTNING	314	SPRING STI	TF	527141585									REF TR.	1	0
FORCED INTERR	SB	SA 48	21263	Y47W		120031120075	F	4/20/2003	1254	99	11	1089	LIGHTNING	LIGHTNING	11850	F.M 529 1	LF	Y47W									(ISSUED TO CORRECT CASE 120031100610 - BEV QA)	1	0
FORCED INTERR.	GP	NB 45	20219		54650323	220031100090	T	4/20/2003	1302	67	3	201	LIGHTNING	LIGHTNING	2101	GRAB	TF	546503276									REFUSED XFMR--LIGHTNING, REF TR;	1	0
FORCED INTERR	SB	ADK42	20959	S2136	49616173	120031100033	F	4/20/2003	1300	237	14	3318	TREE CLEARANC	TREE CLEAR	10142	HARDISO 1	LF	S2136									TRIMMED TREE OUT OF PRIMARY NEED TO HAVE WHOLE EASEMENT TRIMMED , REF LF; ELN	1	0
FORCED INTERR	CY	TB 06	23015	S2933	47729067	220031100092	T	4/20/2003	1300	67	12	804	TREE CLEARANC	TREE CLEAR	820	E CARRELL 1	TF	477290671									REFUSED 50 KVA 18.8 NEED TO TRIM TREES ASAP AT THIS LOCATION, REF TR.	1	0
FORCED INTERR	HM	HB 46	20045	20KF	56675420	220031100093	F	4/20/2003	1300	119	54	8426	VINES	VINES	19115	TIMBER V 2	LF	20KF									REMOVED VINES OFF T.P 20KF REF TP CORRECTED 2HUCRH	1	0
FORCED INTERR	CY	KL 45	2473C		47666006	220031100094	T	4/20/2003	1307	97	1	97	VINES	VINES	12446	TEXAS AF	TF	476660092									RMV VINES, REF TR.	1	0
FORCED INTERR	GP	GZ 43	2J168		52656333	220031100095	T	4/20/2003	1307	161	1	161	BU DISC OR BARI	DISC/BARRL	12701	NORTH F	PR	526563379									REPLACED BURNED UP LIMITER ON 250 KVA, RPLD LIMITER @ TR,	1	0
FORCED INTERR	GP	NB 45	20219	220G	54650316	220031100097	T	4/20/2003	1308	55	4	220	LIGHTNING	LIGHTNING	2043	GRAB 1	TF	546503106									REFUSED XFMR--LIGHTNING REF TR;	1	0
FORCED INTERR	RS	RZ 01	3573A	82TC	49417230	320031100027	T	4/20/2003	1308	116	1	116	LIGHTNING	LIGHTNING	14138	COUNTY 1	TF	494172301									REFUSED 15 KVA TRANS, REF TR,	1	0
FORCED INTERR	KY	GE 44	22498	T18L		120031100034	F	4/20/2003	1308	104	4	416	LIGHTNING	LIGHTNING	5801	OLD GREE 1	LF	T18L	TF	466111494	LF	B97.					REFUSE LIF (T18L-40T 867A-25T AND REFUSE X-FRM @ 5618 OLD GREENHOUSE RD, REF LF REF TR, BRB	1	0
FORCED INTERR	GP	NB 43	22370	S1376	53658214	220031100096	T	4/20/2003	1310	159	7	1113	TREE CLEARANC	TREE CLEAR	15842	MAGEE S 1	TF	536582147									NEED TO TRIM TREE AROUND TRANS POLE (IF IT DOES BACK OUT BEFORE THE TREE ARE TRIMMED REND A 2 MAN TRUCK, REF TR. BRB	1	0
FORCED INTERR	SB	ADK42	21306		50610196	220031100102	T	4/20/2003	1310	77	3	231	LIGHTNING	LIGHTNING	13902	HEMPSTE	TF	506101903									ON XFMR REF TR	1	0
FORCED INTERR	HM	LA 03	41241	A93C		220031100104	F	4/20/2003	1312	119	71	8449	LIGHTNING	LIGHTNING	3527	PINE MEAL 1	LF	A93C									REFUSED LINE FUSE BACK ON WEATHER, REF LF CORRECTED 2HUCRH	1	0
FORCED INTERR	HM	AT 42	23146	62PL		220031100110	F	4/20/2003	1322	118	59	6962	LIGHTNING	LIGHTNING	3503	HUFFMAN 1	LF	62PL									REF LF	1	0
FORCED INTERR	CY	KL 45	21950		47854273	120031100113	T	4/20/2003	1325	49	2	98	LIGHTNING	LIGHTNING	12227	OLD HUFI	TF	478542705									refused trans. REF TR;	1	0
FORCED INTERR	GP	LK 08	20149	BK3	52614444	220031100115	T	4/20/2003	1331	168	6	1008	TREE CLEARANC	TREE CLEAR	6701	WHEATLE 1	TF	526144467									REF TR	1	0
FORCED INTERR	GP	LU 43	24640	37KU	50705286	220031100116	F	4/20/2003	1332	220	3	660	TREE CLEARANC	TREE CLEAR	RHODES RD, B11	1	LF	37KU	PR								TRIM TREES AND PICKED 1 SPAN OF 40 PRIMARY EASEMENT NEEDS MORE TRIMMING; PAU PR-FUSE BLOWN, BRB	1	0
FORCED INTERR	GA	AL 06	30060	12NE	59437067	320031100031	T	4/20/2003	1333	230	2	460	LIGHTNING	LIGHTNING	16245	COWAN F 1	BU	594370670									RPL. 15KVA CONV TRANSFORMER WITH SAME, RPLD BAU TR.	1	0
FORCED INTERR	SU	WI 42	11993		47563274	120031100036	T	4/20/2003	1337	63	10	630	LIGHTNING	LIGHTNING	2305	HIGHWAY	TF	475632746									REF TR;	1	0
FORCED INTERR.	HM	HB 49	22086	L2J	56875352	220031100117	F	4/20/2003	1337	58	49	2842	LIGHTNING	LIGHTNING	181	WILLOW 1	LF	L2J	TF	566753156							REFUSED TRANS @ 133WILLOW LF ON @ 142Z; REF LF; REF TR,	1	0
FORCED INTERR.	SB	ADK41	21320	S2107	49616094	120031100037	T	4/20/2003	1341	99	13	1287	LIGHTNING	LIGHTNING	10138	TANGIER 1	TF	496150944									REF TR.	1	0
FORCED INTERR.	GP	LU 44	2446A	M94B	50696093	220031100120	T	4/20/2003	1348	144	11	1584	LIGHTNING	LIGHTNING	5302	BRYANHUI 1	TF	506960932									REPLACED LIMITER & REFUSED 75 KVA LIGHTER REF TR.	1	0
FORCED INTERR	GA	HX 02	30662	3JW		320031100035	F	4/20/2003	1348	119	34	4046	LIGHTNING	LIGHTNING	7216	SPEAKER 1	LF	3JW	PR								PICKED UP ONE SPAN OF #4 ALU PRI. ONE SPAN EAST OF LF# 3JW ON SANTA FE, PAU PR-FUSE BLOWN, REF LF BRB	1	0
FORCED INTERR	MP	BH 05	40269	E7S	54577541	220031100124	L	4/20/2003	1350	90	1	90	OH SEC/DR CL H	OH SC CL-H	3102	NANCE ST 1	DR										RPLD CONN @ WK	1	0
FORCED INTERR	CY	TB 46	21039	U47S	47695524	220031100125	T	4/20/2003	1355	83	2	166	LIGHTNING	LIGHTNING	25416	LA FOUCI 1	TF	476955249									REF TR.	1	0
FORCED INTERR	KY	KT 43	11577	6HU	38603064	120031100036	T	4/20/2003	1400	210	1	210	LIGHTNING	LIGHTNING	37945	FM 1458 1	BU	386030641									RPLD BAU TR;	1	0
FORCED INTERR	GP	RA 41	20414		51734017	220031100127	T	4/20/2003	1400	115	5	575	LIGHTNING	LIGHTNING	1314	SAWDUST	TF	517340173									REFUSED TRANS REF TR.	1	0
FORCED INTERR.	SU	CE 03	12984	96CM	48522458	120031100039	F	4/20/2003	1400	194	35	6790	URD ELBOW	URD ELBOW	12831	WAYBRIC 2	LF	96CM									REF TR.	1	0
FORCED INTERR	SB	TO 03	20625	75CD	51594440	120031100040	T	4/20/2003	1410	133	12	1596	TREE CLEARANC	TREE CLEAR	2872	ANTOINE L 1	TF	515944402									REFUSE 50 kva AND TRIM TREES , REF TR.	1	0
FORCED INTERR.	GA	AL 05	30513	78KA	60393498	320031100039	T	4/20/2003	1420	134	1	134	LIGHTNING	LIGHTNING	12831	GIBBS 1	TF	603934867									REPLACED BRUNED UP FUSE BARREL, RPLD BAU BARREL ON TR,	1	0
FORCED INTERR	GP	SA 50	21278		49628030	220031100126	T	4/20/2003	1422	34	1	34	LIGHTNING	LIGHTNING	6942	WINDFER 1	TF	496280369									REF TR,	1	0
FORCED INTERR	SL	SE 01	2429E	A21C	35596134	120031100041	F	4/20/2003	1425	105	4	420	LIGHTNING	LIGHTNING	PETERS-SAN FI 1		LF	A21C									REFUSED LF A21C 25T - WEATHER ALL #VC RESTORED, REF LF	1	0
FORCED INTERR	GP	LU 44	22080	S1555	50689531	220031100132	T	4/20/2003	1430	15	6	90	SQUIRREL	SQUIRREL	1453	1	TF	506895313									REFUSE 50 CONV OUT BY BQ TAF LOC FT SAME ADD; REF TR,	1	0
FORCED INTERR	CH	CV 01	40421	22T	58587326	320031100041	T	4/20/2003	1445	69	14	966	OH SEC/DR CL H	OH SC CL-H	14114	GREENVI 1	SC	585873205									REPLACE BUSS WORK ON TRANS, RPLD BUSS WORK @ TR,	1	0
FORCED INTERR	HC	AR 43	10942	84KP	51474101	220031100042	F	4/20/2003	1444	48	12	576	LIGHTNING	LIGHTNING	1810	DARBY LN 1	LF	84KP									REF LF,	1	0
FORCED INTERR	SH	WEB0	31669	15KS		320031100042	F	4/20/2003	1510	54	14	714	LIGHTNING	LIGHTNING	21820	GULF FW 1	LF	15KS									REF LF,	1	0
FORCED INTERR	SU	CRB4	14881	84TG	46494233	120031100045	F	4/20/2003	1511	80	26	2080	VINES	VINES	2502	SPARROW 2	LF	84TG									CLEARED VINES OFF T/P -REF-LEFT ON REF TP.	1	0
FORCED INTERR	GA	GA 03	31232	J43L		320031100044	F	4/20/2003	1520	195	11	2145	LIGHTNING	LIGHTNING	9710	TEICHMAN 1	LF	J43L									REFUSED LF J43L 25T TAKEN OUT BY LIGHTING REF LF	1	0
FORCED INTERR	HM	HB 47	20240		56682257	220031100140	T	4/20/2003	1522	58	1	58	LIGHTNING	LIGHTNING	20407	HIGHWAY	TF	566822573									REFUSE 50 KVA 19.9 277/480 WILL NEED TO REPLACE LIMITR AT B/C CONV TRUCK ACC. STREET SIDE TRAN , REF TR. BRB	1	0
FORCED INTERR	HM	AT 42	2314C	E66K	60692455	220031100141	F	4/20/2003	1524	42	10	420	LIGHTNING	LIGHTNING	25411	HELMS DI 1	LF	E66K									REF LF,	1	0
FORCED INTERR	GA	GA 09	31226	M8W	68380005	320031100045	T	4/20/2003	1526	180	10	1800	LIGHTNING	LIGHTNING	4228	AVENUE S 1	BU	683800092									REPLACED BAD 25 CBP WITH 25 CONV ADDED DISC., RPLD BAU TR.	1	0
FORCED INTERR	GA	GA 10	30024	2WE	67372255	320031100046	T	4/20/2003	1527	348	9	3132	LIGHTNING	LIGHTNING	7217	POPLAR 1	BU	673722559									REPL. BAD 75 KVA TRANS WITH 75 KVA TRANS.SERVICE CAME BACK ON AT 21:15 RPLD BAU TR	1	0
FORCED INTERR	HM	LA 03	41241	A93C	54636256	220031100144	T	4/20/2003	1533	14	13	182	VINES	VINES	11907	HAY MEAI 1	TF	546362505									TRANS OUT VINES BACK ON TRANS/ POLE COVERED IN VINES NEEDS TO BE CLEARED OHTRUE CONV REF TR. BRB.	1	0
FORCED INTERR	SB	WO 07	21620	RS9	51604156	120031100046	T	4/20/2003	1540	80	19	1520	LIGHTNING	LIGHTNING	5407	LAMONTE 1	TF	516041501									REFUSED 75 KVA 7200 120/240 T/P TREES NEED TREE TRIMMIND REF TR,	1	0
FORCED INTERR	RS	RZ 02	3516A	28RN	51377516	320031100046	T	4/20/2003	1540	68	4	272	LIGHTNING	LIGHTNING	1801	FM 855 T16 1	TF	513775183									REF TR,	1	0
FORCED INTERR	BL	UL 18	10391		51574050	120031100051	T	4/20/2003	1540	85	1	85	UNKNOWN	UN

FORCED INTERR	GP	LK 02				22003110015	F	4/20/2003	161	274	13	3562	UNKNOWN			2	LF	E36V					0	0
FORCED INTERR	GP	LK 02				22003110015	F	4/20/2003	161	330	14	4620	UNKNOWN			2	LF	E36V					0	0
FORCED INTERR	GP	LK 02				22003110015	F	4/20/2003	161	440	16	7040	UNKNOWN			2	LF	E36V					0	0
FORCED INTERR	SB	EC 04	21698	6SGE	5058350	12003110006	T	4/20/2003	162	28	8	224	LIGHTNING	LIGHTNING	1304 BLALOCK	1	TF	505835020				REFUSED LIGHTER POT REF TR;	1	0
FORCED INTERR	GA	STW0	31009	A22M	6535552	32003110006	T	4/20/2003	162	314	1	314	LIGHTNING	LIGHTNING	12240 JENKINS	1	BU	653555239				REPLACED BAD 25 CONV WITH SAME ALSO REPLACED BAD DISC AND INSTALLED W/LP RPLD B/U TR;	1	0
FORCED INTERR	SU	CE 11				12003110006	C	4/20/2003	162	0	0	0	TREE CLEARANC	TREE CLEA	8618 BROOKW		CL	CE11				NEED TREE TRIM AT 8618 BROOKWOLF ON SECT 10534...MSG TO S/C...WPS	1	1
FORCED INTERR	SU	CE 11	1G488			12003110006	C	4/20/2003	162	31	961	29791	TREE CLEARANC				CL	CE11					0	0
FORCED INTERR	SU	CE 11	11980			12003110006	C	4/20/2003	162	40	1440	57600	TREE CLEARANC				CL	CE11					0	0
FORCED INTERR	SH	PA 03	30762	1GS	5754344	32003110006	T	4/20/2003	162	37	13	481	UNKNOWN	UNKNOWN	5731 SWEETBR	1	TF	575434480				REFUSED A 50 KVA LIGHTER......PULLED FUSE. REF TR.	1	0
FORCED INTERR	CH	LY 42	4707E	SAL	5962659	32003110006	T	4/20/2003	162	58	5	290	VINES	VINES	16214 DUNMAN	1	TF	596265964				CLEARED VINES OFF 50 CONV; REF TR.	1	0
FORCED INTERR	SB	WT 01	12672	7CX	5159004	12003110006	T	4/20/2003	162	107	4	428	TREE CLEARANC	TREE CLEA	1513 PINE CHAS	1	TF	515900493				[illegible] refused. REF TR;	1	0
FORCED INTERR	SB	CB 03	21425	F91K	4959847	12003110006	F	4/20/2003	162	139	26	3614	BU DISC OR BAR	DISC/BARRL	2323 ROSEFIEL	1	LF	F91K				RPLD B/U BARREL ON LF	1	0
FORCED INTERR	CY	WL 42	24870	E7E	3971144	22003110015	F	4/20/2003	162	75	19	1425	LIGHTNING	LIGHTNING	34916 FLUKING	1	LF	E7E				RODE OUT LF E7E 50T LIGHTNING IN AREA PER CUST TREE TRIMMING NEEDED AT FIRST BREAK OFF TO DEADEND ON ROBERTSON PROPERTY REF LF BRB	1	0
FORCED INTERR	BZ	LJ 07	30643	K41W	5328312	32003110006	T	4/20/2003	163	81	2	162	OH SEC/DR CL H	OH SC CL-H	56 CANDLEWO	1	SC	532831205				RPLD CONN @ TR.	1	0
FORCED INTERR	GP	SA 41	12443	S2150	4961630	12003110006	T	4/20/2003	163	59	3	177	LIGHTNING	LIGHTNING	8208 NYOKA	1	TF	496163055				Replaced burned up fuse barrel RPLD B/U BARREL ON TR	1	0
FORCED INTERR	GP	LK 05	41305	BJ6	5261015	22003110015	T	4/20/2003	163	69	4	276	LIGHTNING	LIGHTNING	2513 PAUL QUI	1	TF	526101534				REF TR.	1	0
FORCED INTERR	GP	AD 09	20387	T33V	5363357	22003110015	F	4/20/2003	163	38	47	1786	TERMINATOR	TERMINATO	551 WALSTON	2	LF	T33V	PR			MADE REPAIRS TO Y PRI TRANS #7 SW#6128, REF TP RPLD URD PR.	1	0
FORCED INTERR	GA	HX 01	30053	BC3	6240824	32003110006	T	4/20/2003	163	72	1	72	LIGHTNING	LIGHTNING	7020 OLEANDE	1	TF	624082499				REPLACED BURED UP FUSE BARREL, RPLD B/U BARREL ON TR.	1	0
FORCED INTERR	CH	LY 41	3762E	49ACL	5862246	32003110006	F	4/20/2003	163	79	12	948	LIGHTNING	LIGHTNING	11023 SUNTUR	1	LF	49ACL				REFUSE 50 PH 49ACL, REF LF	1	0
FORCED INTERR	SB	WO 0	21618	E19W	5159941	12003110006	F	4/20/2003	164	119	27	3213	TREE CLEARANC	TREE CLEA	4205 BROOK W	1	LF	E19W				TRIM TREES ONE SPAN EAST OF LF E19W 65T REF LF. CORRECTED 2HR/CRH	1	0
FORCED INTERR	CH	BY 04	40173	R8N	5461512	32003110006	F	4/20/2003	164	73	19	1387	TREE CLEARANC	TREE CLEA	9231 JENSEN	1	LF	R8N				REF LF RMVD TREE/LIMB OFF PR.	1	0
FORCED INTERR	BL	WW 0	12410	81S	5054101	12003110007	T	4/20/2003	164	211	9	1899	LIGHTNING	LIGHTNING	8815 SHADOW	1	BU	505410137				RPLD B/U TR.	1	0
FORCED INTERR	HM	HB 04				22003110016	C	4/20/2003	164	0	0	0	FLLNG TREE IN E	TREE FL/IE	21826B WALNU		CL	HB04				10/4CKT CREW FD & REMOVED LIMB OFF THE PRI @ 21826 WALNUT , SECTION 2 [illegible], SENT MSG TO S/C FOR TREE TRIMMING ASAP ... MJW B/O 257	1	1
FORCED INTERR	HM	HB 04	2G232			22003110016	C	4/20/2003	164	18	106	1908	FLLNG TREE IN E				CL	HB04					0	0
FORCED INTERR	HM	HB 04	20096			22003110016	C	4/20/2003	164	45	541	24345	FLLNG TREE IN E				CL	HB04					0	0
FORCED INTERR	HM	LW 44	20117	P21Z	5665354	22003110016	F	4/20/2003	164	0	0	0	LIGHTNING	LIGHTNING	16110 CATBIRD	2	LF	P21Z	DB		PR	REPLACE DISCONNECT AND FOUND BAD TERMINATOR, REF LF RPLD B/U DISC-LF BLOWN. BRB	1	0
FORCED INTERR	HM	LW 44				22003110016	F	4/20/2003	164	197	21	4137	LIGHTNING			2	LF	P21Z					0	0
FORCED INTERR	HM	RA 42	20438		5271353	22003110016	T	4/20/2003	165	307	1	307	LIGHTNING	LIGHTNING	23123 PILGRIMS		BU	527135301				RPLD B/U TR REF TR; RPLD LIGHTNING ARRESTOR. BRB	1	0
FORCED INTERR	CH	GW 0	40899	CU9	5660557	32003110006	F	4/20/2003	165	62	24	1488	UNKNOWN	UNKNOWN	8909 CRESTVIE	1	LF	CU9				REF LF	1	0
FORCED INTERR	GP	LK 02	21869	16EJ	52627311	22003110017	F	4/20/2003	170	103	37	3811	LIGHTNING	LIGHTNING	839 MARCOLIN	2	LF	16EJ				REF TP;	1	0
FORCED INTERR	GP	WF 41	20568	U43N	5168832	22003110017	T	4/20/2003	170	102	2	204	LIGHTNING	LIGHTNING	17323 RED OAK	1	TF	516883277				REFUSED TRANSFORMER, REF TR;	1	0
FORCED INTERR	SH	WE 02	31247	LSF	5855125	32003110006	L	4/20/2003	171	81	1	81	OH SEC/DR CL H	OH SC CL-H	1037 THOMAS	1	DR					replaced bad lighter lug clamp at weatherhead, RPLD CONN @ WH;	1	0
FORCED INTERR	FB	WA 43	11332	49UL	3751327	12003110009	T	4/20/2003	173	205	7	1435	VINES	VINES	6116 RAILROAD	1	TF	375132794				REF T/F.	1	0
FORCED INTERR	GP	AD 11	40065	42HE	5462151	32003110007	F	4/20/2003	173	59	2	118	TREE CLEARANC	TREE CLEA	1712 HARTWIC	1	LF	42HE	TF	546215143		REFUSED TR FUSE AND LINE FUSE-OUT BY TREE LIMB--TRIMMED LIMBS AWAY FROM TR --OK BY CUST REF LF REF TR BRB	1	0
FORCED INTERR	MP	AN 07	40044	76G	5359149	22003110018	T	4/20/2003	174	70	15	1050	LIGHTNING	LIGHTNING	212 W 27TH	1	TF	535914922				REFUSED A 75 KVA 7200 120 240 V LIGHTER TRANSFOMER AND A 25 KVA POWER TRANSFORMER, REF TR. BRB	1	0
FORCED INTERR	BL	DV 08	10610	G90X	5056419	12003110008	F	4/20/2003	174	53	17	901	UNKNOWN	UNKNOWN	3122 DUNVALE	1	LF	G90X				REFUSED SOUTH PHASE OF LF PULLED FUSE; REF LF	1	0
FORCED INTERR	GP	LK 02	21869	E40V	5262733	22003110018	F	4/20/2003	174	37	9	333	LIGHTNING	LIGHTNING	8202 LAWN Y(E	2	LF	E40V				REF TP.	1	0
FORCED INTERR	SB	ADK4	21319	S2135	4961618	12003110008	F	4/20/2003	175	68	17	1156	FLLNG TREE OUT	TREE FL/OE	10122 CHICKAS	1	LF	S2135				TRIMMED TREE LIMBS OUT OF PRIMARY FROM FALLEN TREE OUT OF EASEMENT NEED TO HAVE TREE REMOVED OR TRIMMED BACK SOME MORE REFUSED NORTH AND MIDDLE PHASES (	1	0
FORCED INTERR	MP	BY 03	22992	M68R	5461019	22003110018	F	4/20/2003	175	50	31	1550	LIGHTNING	LIGHTNING	1104 TIDWELL	1	LF	M68R				REF LF.	1	0
FORCED INTERR	HC	AR 42	10926	19AAX	5146937	12003110008	F	4/20/2003	180	92	1	92	LIGHTNING	LIGHTNING	5735 COUNTY	1	LF	19AAX				REF LF	1	0
FORCED INTERR	MP	AN 05	40060	C5A	5361006	22003110019	T	4/20/2003	180	76	5	380	LIGHTNING	LIGHTNING	410 HOHLDALE	1	TF	536100641				REF TR.	1	0
FORCED INTERR	KY	KT 43	11577	76SU	3860309	12003110008	T	4/20/2003	181	49	1	49	LIGHTNING	LIGHTNING	37642 FM 1458	1	TF	386030952				REFUSED TF AND GOT LIGHTS ON, REF TR.	1	0
FORCED INTERR	GP	AD 11	40065	59HE	54621581	32003110007	T	4/20/2003	183	26	5	130	LIGHTNING	LIGHTNING	1902 ALDINE PA	1	TF	546215814				REFUSED 50 KVA CONV--OK BY CUST REF TR.	1	0
FORCED INTERR	HC	HOC0	11186	JG9	5253027	12003110008	T	4/20/2003	184	33	10	330	BU DISC OR BAR	DISC/BARRL	4429 CREEKBE	1	TF	525302755				REPLACED FUSE BARREL, RPLD B/U BARREL ON TR	1	0
FORCED INTERR	SH	HG 06	41054	M7B	5854754	32003110008	L	4/20/2003	184	74	1	74	FLLNG TREE OUT	TREE FL/OE	153 ROCKLEIG	1	SC					RESAGGED DROPS. RPLD SEC CONN @ PL-1 CUST RESAGGED DR. BRB	1	0
FORCED INTERR	SB	SA 48	21263	A94G	4862617	12003110009	T	4/20/2003	185	46	2	92	LIGHTNING	LIGHTNING	11913 FM 529 R	1	TF	486261700				REF TR. BRB	1	0
FORCED INTERR	MP	AN 05	40060	C5A	5361007	22003110021	T	4/20/2003	185	318	4	1272	LIGHTNING	LIGHTNING	319 HOHLDALE	1	BU	536100791				RPLD B/U TR. RPLD LIGHTNING ARRESTOR.	1	0
FORCED INTERR	MP	OA 02				22003110019	C	4/20/2003	190	0	0	0	OTHER	SWITCHING	OA02 CKT LOC		CL	OA02				B/O 325 WHILE SWITCHING OA04 TO ISOLATE DAMAGED POLE AND XARM @ OATS & RUMAR,POLE FIRED UP & OA02 & OA04 LOCKED OUT WPS NON 10%_	1	1
FORCED INTERR	CH	OA 01	2G226			22003110019	C	4/20/2003	190	2	528	1056	OTHER				CL	OA02					0	0
FORCED INTERR	CH	OA 04	2G226			22003110019	C	4/20/2003	190	2	1645	3290	OTHER				CL	OA02					0	0
FORCED INTERR	MP	OA 02	2G226			22003110019	C	4/20/2003	190	2	79	158	OTHER				CL	OA02					0	0
FORCED INTERR	GP	RU 05	41671	T20W	5362627	22003110019	F	4/20/2003	192	110	39	4290	TREE CLEARANC	TREE CLEA	11911 AGGIE LN	1	LF	T20W				NEED TO TRIMM TREES AT 402 ROSE, REF LF RMVD TREE/LIMB OFF PL. BRB	1	0
FORCED INTERR	SL	SE 41	1H162	72AAP	3757445	12003110009	F	4/20/2003	203	68	21	1428	LIGHTNING	LIGHTNING	HWY 90 EAST	1	LF	72AAP				REFUSED B PHASE OF BANK OF STEP DOWNS #72AAP AND GOT SERVICE ON, REF TR. BRB	1	0
FORCED INTERR	CY	KL 45	21962	C58K	4864150	22003110021	F	4/20/2003	2051	0	0	0	LIGHTNING	LIGHTNING	12303 DAKAR Y	2	LF	C58K	BU	486415054	PR	REPLACED BAD 50 7200 120/240 URD TRAN IN EASMENT ,SPLICED 6 FT URD PRI [illegible] BAD 167 STEP POT AND BURNED UP PRI FROM TRAN [illegible] TO BAD STEP POT STEP IN EASMENT POS	1	0
FORCED INTERR	CY	KL 45				22003110021	F	4/20/2003	2051	204	16	3264	LIGHTNING			2	LF	C58K					0	0
FORCED INTERR	CY	KL 45				22003110021	F	4/20/2003	2051	444	6	2664	LIGHTNING			2	LF	C58K					0	0
FORCED INTERR	GP	LU 42	2A131	68CK	5170259	22003110021	F	4/20/2003	205	0	0	0	LIGHTNING	LIGHTNING	21523 NOTTING	2	LF	68CK	PR			BAD TERMINATOR ON 68CH AT 21523 NOTTINGHILL ON SWITCHING 6311 ON 68CK 30T REF TP	1	0
FORCED INTERR	GP	LU 42				22003110021	F	4/20/2003	205	156	36	5616	LIGHTNING			2	LF	68CK					0	0
FORCED INTERR	HC	AR 42	10926	19AAX	5146937	12003110009	T	4/20/2003	210	50	1	50	LIGHTNING	LIGHTNING	5735 COUNTY	1	TF	514693781				REF TR.	1	0
FORCED INTERR	SU	CE 03	12998	M34G	4853412	12003110009	F	4/20/2003	211	100	25	2500	UNKNOWN	UNKNOWN	10607 COOK	2	LF	M34G				PUT THE VAN ON IT COULDN'T FIND ANYTHING REFUSE TP M34G. REF TP	1	0
FORCED INTERR	BA	UW 05	40922	26HN	6154135	32003110009	T	4/20/2003	212	61	2	122	LIGHTNING	LIGHTNING	10200 N L ST A	1	TF	615413522				REF TR.	1	0
FORCED INTERR	SB	TO 04	21776	U91I	5159745	12003110009	F	4/20/2003	213	45	3	135	O/H PRIMARY CL	OH PR CLM	2855 MANGUM	3	LF	U91I				NEED TO TURN OVER TO UNDERGROUND DEPT TO REPLACE BAKER BOARD ON TERMINAL POLE MIDDLE PHASE, REF TP	1	0
FORCED INTERR	CY	TB 46	21039	U47S	4769552	22003110021	T	4/20/2003	213	125	2	250	LIGHTNING	LIGHTNING	26418 LA FOUC	1	TF	476955249				REPLACED BAD 19.9 LIGHTNING ARRESTER RPLD LIGHTNING ARRESTOR	1	0
FORCED INTERR	CY	PI 42	2320A		4876851	22003110022	T	4/20/2003	215	180	1	180	HUMAN ERROR	HUMN ERR	256 1/2 OLD EG		TF	487685179	PR			REROUTED LOAD SIDE OF DISCONNECT WAS LAYING ON TOP OF 25 KVA 19.9 120 240 V TRANS. RPRD B/O PRI JUMP-TF BLOWN. REF TR.	1	0
FORCED INTERR	HM	LW 42	22977	19G	5565342	22003110022	T	4/20/2003	215	34	8	272	UNKNOWN	UNKNOWN	5658 APGAR ST	1	TF	556534272				REFUSED A 50 KVA 7200 120 240 V TRAN, REF TR;	1	0
FORCED INTERR	GP	DH 06	20962	G74G	5162421	22003110022	F	4/20/2003	220	58	15	870	UNKNOWN	UNKNOWN	5634 COUNCIL	2	LF	G74G				REFUSED TP G-74-G, REF TP.	1	0
FORCED INTERR	SH	SB 04	31044	35QN	5855449	32003110010	F	4/20/2003	222	119	1	119	COLLISION	COLLISION	BEARLE S OF H	1	LF	35QN	PD			STUB 45' LF POLE # 35QN NEED TO BE REPLACE, REF LF STUBBED UP PL. CORRECTED 2HR/CRH	1	0
FORCED INTERR	SU	CE 10	11951	12SN	47539091	12003110010	F	4/20/2003	225	60	47	2820	LIGHTNING ARRE	LTNG ARRS	13423 SARENT	2	LF	12SN				REPLACED L/A, REF TP	1	0
FORCED INTERR	SU	IM 45	14281	S3478	4751609	12003110010	T	4/20/2003	230	62	11	682	LIGHTNING	LIGHTNING	154 CAMELLIA	1	TF	475160960				REF TR.	1	0
FORCED INTERR.	GA	SCW0	30885	95FH	6839922	32003111000	F	4/21/2003	002	87	25	2175	BU DISC OR BAR	DISC/BARRL	315 POST OFFI	1	LF	95FH				REPL FUSE BARREL ON LINE FUSE NORTH PHASE, RPLD B/U BARREL ON LF	1	0
FORCED INTERR	GA	AL 10	30041	E20G	6141046	32003111000	T	4/21/2003	003	108	1	108	LIGHTNING	LIGHTNING	4411 B BAR DR	1	TF	614104682				REF TR.	1	0
FORCED INTERR	GP	HV 04	20513	J12I	5264019	22003111000	F	4/21/2003	024	57	12	684	UNKNOWN	UNKNOWN	1215 DELLBRO	2	LF	J12I				REFUSED T/P REF TP	1	0
FORCED INTERR	GP	WF 43	20333	73BB	5367432	22003111000	F	4/21/2003	043	79	1	79	LIGHTNING	LIGHTNING	1531 EAST RIC	1	LF	73BB				REFUSED L/F REF LF	1	0
FORCED INTERR	CH	BE 02	40220	U42	5560159	32003111000	T	4/21/2003	043	72	6	432	UNKNOWN	UNKNOWN	8607 WILEYVAL	1	TF	556015928				REF TR.	1	0
FORCED INTERR	CY	SA 42	20951	U35V	4862551	12003111000	F	4/21/2003	044	125	1	125	LIGHTNING	LIGHTNING	7723 WRIGHT	1	LF	U35V	TF	486255161		WEATHER TOOK OUT LINE FUSE AND TRANS FUSE, REF LF REF TR. MEK	1	0
FORCED INTERR	GA	HX 01	30053	E18G	6240822	32003111000	T	4/21/2003	051	42	1	42	BU DISC OR BAR	DISC/BARRL	7217 2ND ST #2	1	TF	624082284				REPLACED FUSE BARREL ON TRANS RPLD B/U BARREL ON TR.	1	0
FORCED INTERR.	GA	HX 02	30662	3JW	63401241	32003111000	T	4/21/2003	053	40	2	80	BU DISC OR BAR	DISC/BARRL	6907 FRAZIER A	1	TF	634012415				REPLACED BAD FUSE BARREL ON TRANS RPLD B/U BARREL ON TR.	1	0
FORCED INTERR.	SU	RO 44	11540		4852314	12003111000	T	4/21/2003	0641	62	2	124	LIGHTNING	LIGHTNING	810 INDUSTRIA		TF	485231402				refused it out by weather over weekend. REF TR;	1	0
FORCED INTERR	SB	GE 43	20836	71QM	4762321	12003111000	T	4/21/2003	065	82	8	656	LIGHTNING	LIGHTNING	15444 FM 529 R	1	TF	476232133				REPLACED A BAD FUSE BARREL WEATHER OVER THE WEEKEND; REF TR.	1	0
FORCED INTERR	SH	EL 04	30362	R42K	5850759	32003111000	F	4/21/2003	065	144	3	432	O/H PRIMARY CL	OH PR CLM	401 FM 1959	1	LF	R42K				REF LF	1	0
FORCED INTERR	GP	AD 09	20387	T33V	5363359	22003111000	F	4/21/2003	070	38	47	1786	BIRD	BIRD	606 CORVETTE	2	LF	T33V				REF TP	1	0
FORCED INTERR	GP	BA 46	20871		5066028	22003111000	T	4/21/2003	0711	271	2	542	LIGHTNING ARRE	LTNG ARRS	6215 FM 1960 W		BU	506602868				REPL. 50 & 25 19.9 120/240 OH. RPLD B/U TR. MEK	1	0
FORCED INTERR	SH	PA 03	30763	7GR	5754232	32003111001	T	4/21/2003	0711	47	10	470	SQUIRREL	SQUIRREL	5506 STARLING	1	TF	575423276				REFUSE 50 REAR OF 5506 STARLING SQ REF TR.	1	0
FORCED INTERR	SH	CG 04	30218	4DU	5354851	12003111000	F	4/21/2003	072	70	1	70	UNKNOWN	UNKNOWN	5118 LAUREL C	1	LF	4DU				REFUSE LF 4DT 125T REF LF MEK	1	0
FORCED INTERR	CY	KL 45	21950	67TU	4765510	22003111000	T	4/21/2003	073	170	2	340	LIGHTNING	LIGHTNING	12121 OLD HUF	1	PR	476551038				REPLACE LIMITER ON SOUTH PHASE TRANSFORMER IN 277/480V BANK. RPLD LIMITER @ TR.	1	0
FORCED INTERR	FB	RE 04	11447		4449439	12003111000	T	4/21/2003	074	36	9	324	BU DISC OR BAR	DISC/BARRL	1106 MORTON		TF	444943976				REF 1-POWER POT IN CLOSED DELTA BANK--BROKE FUSE, REF TR.	1	0
FORCED INTERR	BL	DV 08	10610	G90X	5056405	12003111001	T	4/21/2003	0751	93	4	372	VINES	VINES	8640 RICHMON	1	TF	505640569				REFUSED POWER TRANS REF TR. MEK	1	0
FORCED INTERR	GP	GZ 46	20982	69ABJ	5266003	22003111001	T	4/21/2003	075	112	1	112	TREE CLEARANC	TREE CLEA	1360 HUGH RD	1	PR	526600341				TRIMMED TREES REPLACED 12 K-MAT LIMITER, RPLD LIMITER @ TR, REF TR. MEK	1	0
FORCED INTERR	BA	AT 41	20007	S1605	6067429	32003111001	T	4/21/2003	0801	51	6	306	TREE CLEARANC	TREE CLEA	115 ANTELOPE	1	TF	606742993				120V DISCONNECT & L/A. NEEDS TO BE REPLACED ALSO TREES NEED TO BE TRIMMED AWAY FROM TRANSFORMER REF TR MEK	1	0
FORCED INTERR	GP	GZ 43	20450		5266514	22003111001	T	4/21/2003	080	40	2	80	BU DISC OR BAR	DISC/BARRL	222 W RANKIN		TF	526651427				CHANGED BURNT UP FUSE BARREL ON 167 KVA LIGHTER IN OPEN DELTA. RPLD B/U BARREL ON TR	1	0
FORCED INTERR	BL	UL 49	14063	49X	5156401	12003111001	T	4/21/2003	082	101	3	303	LIGHTNING	LIGHTNING	3402 CHIMNEY	1	TF	515640128				REFUSED 25 KVA 120/240/19.9 POWER, REF TR. MEK	1	0
FORCED INTERR	SH	DE 02	30250	8FN	5954725	32003111002	L	4/21/2003	082	84	1	84	FLLNG TREE OUT	TREE FL/OE	2218 ESTATE S	1	DR					PICKED UP HOUSE DROP DOWN/DUE TO CUST TREE FALLING. RPLD CONN @ WH. P/U DR. MEK	1	0
FORCED INTERR	RS	MU 02	354SB	6E4	5639803	32003111002	F	4/21/2003	082	38	2	76	UNKNOWN	UNKNOWN	FM 2917 @ CO 1	1	LF	6E4				NEED TO CHG. LF LOCATION TO FM 2917 @ FM 2403. REF LF.	1	0
FORCED INTERR	GA	STW0	31427	90FH	6534251	32003111002	T	4/21/2003	082	59	1	59	BU DISC OR BAR	DISC/BARRL	4128 SEA EAGL	1	TF	653425101				TRK 6464 ---- NEED SWITCH BRACKET @ TRX REPL REAR OF ADDRESS EASEMENT ---- GONE & LOW-SIDE HITN BOND WIRE &POLE WHEN WIND BLOWS RIGHT[illegible] REF TR. MEK	1	0
FORCED INTERR	CH	GP 07	40813		5757109	32003111002	T	4/21/2003	083	44	4	176	UNKNOWN	UNKNOWN	1500 16TH		TF	575710905				REPLACED FUSE BARREL. FOUND MISSING. RPLD B/U BARREL ON TR.	1	0
FORCED INTERR	MP	EU 03	40711	A57L	5259620	22003111002	T	4/21/2003	083	162	2	324	COLLISION	COLLISION	1431 W 20TH	1	TF	525962025	PD			45 POLE WITH 3 PHASE TR FUSES FEEDING ADDRESS. REF TR; STUBBED UP PL. MEK	1	0
FORCED INTERR	BL	SF 14	10441		5258051	12003111002	T	4/21/2003	084	32	2	64	SQUIRREL	SQUIRREL	4298 1/2 SAN FE		TF	525805196				refused it out by [illegible] REF TR.	1	0
FORCED INTERR	SB	EU 10	21864	B7P	5158757	12003111002	T	4/21/2003	084	46	2	92	LIGHTNING	LIGHTNING	6048 WESTVIE	1	TF	515875706				REFUSED POWER POT IN CLOSED/DELTA BANK BACK ON LIGHTING STORM FROM 4/20 REF TR	1	0
FORCED INTERR.	HM	HB 49	22086	H12M	5667438	22003111002	T	4/21/2003	084	56	2	112	LIGHTNING	LIGHTNING	140 S HOUSTO	1	TF	566743847				REFUSED 25 KVA TRAN, PROBABLY OUT FROM LIGHTNING YESTERDAY REF TR.	1	0
FORCED INTERR	SH	DE 06	30086	94CF	5954826	32003111002	F	4/21/2003	085	54	82	4428	UNKNOWN	UNKNOWN	2508 HILLSHIRE	1	LF	94CF				REFUSE LINE FUSE; REF LF.	1	0
FORCED INTERR	SH	WE 04	31263	R9C	5755958	32003111002	T	4/21/2003	090	53	1	53	BU DISC OR BAR	DISC/BARRL	621 BELMONT	1	TF	575595897				RPLD B/U BARREL ON TR. MEK	1	0
FORCED INTERR	FB	RE 08	11443	M32Y	44495361	12003111002	T	4/21/2003	090	34	1	34	BU DISC OR BAR	DISC/BARRL	700 JACKSON S	1	TF	444953618				REF TR.	1	0
FORCED INTERR	SB	CB 11	21466	K15M	5059334	12003111002	F	4/21/2003	090	43	18	774	SQUIRREL	SQUIRREL	2015 BARR ST	1	LF	K15M				TRANS HAS WILD LIFE PROT REF LF;	1	0
FORCED INTERR	GP	LK 06	21880	K81L	5262321	22003111002	F	4/21/2003	090	57	1	57	SQUIRREL	SQUIRREL	ESTHER E OF V	1	LF	K81L				REFUSED LF K81L--40T--A1- SQUIRREL ON 25 CSP IN LOT NEXT DOOR TO THIS ADDRESS--NEED W/LP & C/C. REF LF MEK	1	0
FORCED INTERR	HM	RA 44	2A161		5272550	22003111002	T	4/21/2003	091	88	2	176	VINES	VINES	1602 RAYFORD		PR	527255036				TOOK CREW OUTAGE ON LIGHTER LONG ENOUGH TO REPLACE LIMITOR ON POWER / ALSO RM VINES OFF TOP BANK AND POLE/ ALSO VRM VINES OFF POLE B/ACK TO EAST OF BANK. RR	1	0
FORCED INTERR	GA	HX 02	30662	I59G	6340237	32003111003	L	4/21/2003	091	200	1	200	FALLING DEAD T	TR FL/DEAD	8606 MIKE AVE	1	DR					TEMP DISCONNECT AND RECONNECT_ RPRD DR, RPLD CONN @ WH. MEK	1	0
FORCED INTERR	RS	MU 01	30737	A79R	5742815	32003111003	F	4/21/2003	091	42	17	714	SQUIRREL	SQUIRREL	109 E LARKSPU	1	LF	A79R				SQUIRREL ON XFMR @ 102 E. SHERWOOD. REF LF	1	0
FORCED INTERR	BL	HE 07	41138	B68G	5358459	22003111003	T	4/21/2003	091	93	10	930	SQUIRREL	SQUIRREL	728 E 11 1/2	1	TF	535845924				CROSS ARM IN BAD SHAPE TX ACCESSABLE FROM 721 E 11 TH. REF TR RQR	1	0
FORCED INTERR	RS	MU 02	30740	50NE	5839517	32003111003	T	4/21/2003	092	306	1	306	LIGHTNING	LIGHTNING	7501 CHO BYO	1	BU	583951701				REPLACED 50 CONV W/SAME--480--ALSO REFUSE WEST PHASE OF LINE FUSE GET TO ADDRESS OFF CR 170 -USE GATE OFF CR170--STAY TO THE RIGHT 2MILES. RPLD B/U TR	1	0
FORCED INTERR	BA	HNY0	41018		6360201	32003111003	T	4/21/2003	092	164	1	164	OH SEC/DR CL H	OH SC CL-H	4815 EAST FWY		BU	636020120				RPLD B/U TR:	1	0
FORCED INTERR	CY	TB 46	21035		4869248	22003111003	T	4/21/2003	092	84	2	168	LIGHTNING	LIGHTNING	11715 BOUDRE		TF	486924868				REFUSED TWO FUSE ON STAB. LEFT WORKING CAUSE WEATHER. RQR	1	0
FORCED INTERR	HM	LA 04	41247	E56M	5463842	22003111003	F	4/21/2003	093	27	13	351	LIGHTNING ARRE	LTNG ARRS	4434 SANDYDA	2	LF	E56M				REFUSED TER POLE OUT BY BAD LIGHTNING ARRESTOR. REF TP MEK	1	0
FORCED INTERR	SB	SR 15	21678	7M5	4958657	12003111003	T	4/21/2003	094	238	9	2142	UNKNOWN	UNKNOWN	10135 HANKA D	1	BU	495865704	PD			stubbed up pole & replaced 25 kva 7200 120/240 tf with 15 kva need to replace 40 ft pole with open delta on it. RPLD B/U TR. STUBBED UP PL	1	0
FORCED INTERR	BZ	LJ 01	31331	C97G	5227547	32003111004	L	4/21/2003	094	206	1	206	VINES	VINES	215 ANY WAY	1	SC					REPL SEC CONN. MEK	1	0
FORCED INTERR	SB	SR 05	21646	K74T	4959305	12003111003	F	4/21/2003	094	186	1	186	LIGHTNING	LIGHTNING	1730 STEBBINS	1	LF	K74T				PAST WEATHER OVER WEEKEND REF LF MEK	1	0
FORCED INTERR	SH	DR 02	30267	16CW	5653553	32003111004	T	4/21/2003	0951	46	11	506	SQUIRREL	SQUIRREL	8319 WYNBROC	1	TF	565355359				REFUSED TRANS HAS W/LP BUT SWITCH IS ON HORSESHOE BRACKET REF TR.	1	0

FORCED INTERR	HC	BL 02	10764	18LH	5152122	12003111004E	L	4/21/2003	100(	76	1	76	TREE CLEARANC	TREE CLEAI	5854 SOUTHMIN	1	SC						REPLACED BAD HOT LEG CLAMP AT TRANS POLE: RPLD SEC CONN @ PL-1 CUST	1	0
FORCED INTERR.	SH	CG 06	30221	64B	5753343	32003111004	F	4/21/2003	100(	23	29	667	SQUIRREL	SQUIRREL	316 INDIANA	1	LF	64B					REF LF:	1	0
FORCED INTERR	SH	CG 05	30226	88EH	5753016	32003111004E	F	4/21/2003	101:	59	4	238	SQUIRREL	SQUIRREL	1410 COLLEGE	1	LF	88EH	TF	57530168E			REFUSED (W) PHASE OF 88EH 30T AT 10.45, REF LF: REF TR. MEK	1	0
FORCED INTERR.	BZ	LJ 09	3521E	4FP	5530012	320031110047	F	4/21/2003	101	0	0	0	LIGHTNING	LIGHTNING	1535 FAIRWAY (	1	LF	4FP	BU	54309198			REPL 25 KVA CONV TR WITH THE SAME. RPLD B/U TR. MEK	1	0
FORCED INTERR.	BZ	LJ 09				320031110047	F	4/21/2003	101	66	110	7480	LIGHTNING			1	LF	4FP						0	0
FORCED INTERR	BZ	LJ 09				320031110047	F	4/21/2003	101	243	1	243	LIGHTNING			1	LF	4FP						0	0
FORCED INTERR	FB	EB 05	1557A		3448835	12003111005(	T	4/21/2003	102(	343	1	343	UNKNOWN	UNKNOWN	2010 COUNTY R		BU	344883515	MT				OLN 3448835152. REPLACED BAD 50 KV 7200 240/480 V TRANS W/ SAME ALL THREE OF THE CUSTOMERS FUSES ARE BAD. REPLACED METER OLD 818 X1 37568 NEW METER W87081543 O48-	1	0
FORCED INTERR	HM	SW 08	41691	C32W	5663200	32003111004E	T	4/21/2003	102	256	4	1024	OH SEC/DR CL H	OH SC CL-H	7910 FURAY RD	1	SC	566320091	SC				REPLACED HOT LEG CLAMPS AT POLE AND XFMR--	1	0
FORCED INTERR.	BA	KM 02	41189	5C7		320031110051	F	4/21/2003	104(	67	414	27738	COLLISION	COLLISION	3010 E NASA RD	1	LF	5C7					REFUSE LINE FUSE. TRUCK HIT TELPHONE CABLE; REF LF;	1	0
FORCED INTERR	GP	FR 41	21389	18CN	5063020	22003111004	F	4/21/2003	104	62	1	62	BU DISC OR BARI	DISC/BARRL	8205 FAIRBANK	1	LF	18CN	TF	50630204			REFUSED-B- PH LF 18CN--80T--RPLCD BAD FUSE BARREL ON "TR" FUSE FEEDING 480V BANK--. REF LF; RPLD B/U BARREL ON TR; MEK	1	0
FORCED INTERR	BL	HE 07	41136		5358329	12003111005E	T	4/21/2003	105	27	5	135	UNKNOWN	UNKNOWN	3219 WHITE OA		TF	535832909					PULLED FUSE; REF TR, MEK	1	0
FORCED INTERR.	BA	AT 41	20013	8SW	5968915	22003111004E	T	4/21/2003	111	162	1	162	OH SEC/DR CL H	OH SC CL-H	22627 1/2 W SH	1	SC	596891590	SC				REPL BAD C T TRAN LUGS WITH 1/0 TRAN LUGS ALUM WIRE IN COPPER TRAN C T RPLD CONN @ TR, RPRD BUSS WORK @ TR,	1	0
FORCED INTERR.	CY	PI 44	2A123	A84E	4774819	22003111005(	F	4/21/2003	1121	46	1	46	COLLISION	COLLISION	27706 DOBBIN H	1	LF	A84E					POLE HIT BY CAR KNOCKED SWITCH OPEN/CLOSED LEFT ON. REF LF	1	0
FORCED INTERR	SB	SR 15	21678	20S	4959500	12003111006E	T	4/21/2003	112	40	10	400	LIGHTNING	LIGHTNING	1711 SPRINGWI	1	TF	495950089					PAST LIGHTNING, REF TR,	1	0
FORCED INTERR	SH	TE 01	31089	7LT	5651430	32003111005E	T	4/21/2003	1141	126	3	378	SQUIRREL	SQUIRREL	8107 ARROWHE	1	BU	565143094					RPLD B/U TR, MEK	1	0
FORCED INTERR	CY	TB 45	21046	25ABF	4671106	22003111005E	T	4/21/2003	1151	39	1	39	SQUIRREL	SQUIRREL	22235 KOBS	1	TF	467110674					REFUSED 25/19.9 TRANSFORMER. REF TR.	1	0
FORCED INTERR	BL	BI 46	14235	G20P	5155914	12003111007E	T	4/21/2003	115	118	6	708	TREE CLEARANC	TREE CLEAI	4602 CEDAR	1	PR	515591439					RPLD LIMITER @ TR;	1	0
FORCED INTERR	GP	THW4	20724	N34M	4964040	22003111006(	F	4/21/2003	122	63	1	63	CUST EQP RELAT	CUST RLTD	11355,FALCON	3	LF	N34M					REF LF;	1	0
FORCED INTERR	SB	WT 04	21826		5058625	12003111008(	L	4/21/2003	123	172	1	172	OVERLOAD	OVERLOAD	8793 GAYLORD		DR						REPL 1/0 4 WIRE DROPS WITH 4/0 4 WIRE.ALSO INSTALLED DISC ON OPEN DELTA BANK; RPLD DR.	1	0
FORCED INTERR.	GP	BA 45	2E137		5068309	220031110061	T	4/21/2003	123	134	1	134	OH SEC/DR CL NI	OH SC CL-N	15705 N GREEN		TF	506830957	SC				MADE REPAIRES TO NUETRAL TIE REPLACED 2 BOLT CLAMP EASEMENT. REF TR, RPRD BUSS WORK @ TR.	1	0
FORCED INTERR.	BA	FT 01	31036	FM5	6153342	320031110071	T	4/21/2003	123	40	7	280	SQUIRREL	SQUIRREL	10419 COLLING	1	TF	615334210					REFUSED 50KVA XFMER OUT BY A SQUIRREL—NEED WLP INSTALLED AT SC CONV., REF TR; MEK	1	0
FORCED INTERR	BA	CS 03	40581	61EN	6161505	32003111007	F	4/21/2003	1251	23	26	598	BU DISC OR BARI	DISC/BARRL	321 RED HAVEN	1	LF	61EN					RPLD B/U BARREL ON LF;	1	0
FORCED INTERR	HC	AM 05	10745	K71R	5251758	12003111008	T	4/21/2003	125	20	5	100	SQUIRREL	SQUIRREL	13903 WATERL	1	TF	525175801					REFUSED TRANS L/A BLOWN AND NEEDS WLP; REF TR; MEK	1	0
FORCED INTERR	SH	TE 05	31090	D16B	5651536	32003111007	F	4/21/2003	130	42	23	966	UNKNOWN	UNKNOWN	10401 MONROE	1	LF	D16B					CREW HAD BAD TRANS @ 8107 ARROW HEAD TOOK OUT LF REF LF	1	0
FORCED INTERR	BL	KB 03	10146	90P	5255548	120031110084	T	4/21/2003	131	45	5	225	FIRE	FIRE	3223 GEORGET	1	TF	525554864					CUT OUT-MTR LOOP DAMAGE-RMVD MTR. ..C/O WH. ...FIRE IN METER CAN REFUSED 2 TRANS. REF TR. MEK	1	0
FORCED INTERR	GP	FR 44	21409	14LP	5062511	220031110064	F	4/21/2003	131	143	39	5577	PRIMARY CONDU	PRI	9202 LONG BAR	2	LF	14LP	PR				REPLACED BAD ELBOW AT 9211 LOREN AND REFUSED T.P. 14LP. REF TP, RPLD ELBOW @ TR. MAM NO SUBCASING NEEDED	1	0
FORCED INTERR	HM	IT 02	20194	WG2	5465244	22003111006E	F	4/21/2003	134	121	8	968	TREE CLEARANC	TREE CLEAI	16106 GREEN T	1	LF	WG2	PR		SC		PICKED UP 1-SPAN #4 PRI & NEUTRAL, REF LF P/U PR-FUSE BLOWN; RPRD PRI NEUT	1	0
FORCED INTERR	FB	NSH03	30866	107W	5136001	32003111008(	T	4/21/2003	134	140	1	140	FOREIGN MATER	FRGN MATR	3202 COUNTY R	1	SC	513600153	DR				REPLACED CONNECTIONS AT WEATHERHEAD AND AT TRANSF NEED TO REPLACE BAD L.A. AT SVC CONV., RPLD CONN @ TR, RPLD CONN @ WH;	1	0
FORCED INTERR.	BL	HE 08	41118	NU8	5258853	22003111007	T	4/21/2003	135	68	3	204	VINES	VINES	1126 TIMBERGR	1	TF	525885346					RMVD VINES & CLEARED UP BAD L/A ON 37.5KVA LIGHTER TRNS--REFUSED LTRNS --LEFT ON--NEED TO RPLC BAD L/A & RE-SQUIRREL WIRE -- TRNS--S/C/C--LOC'D REAR SAME. REF TR. M	1	0
FORCED INTERR	HC	IR 02	11061	A56S	5251207	12003111009(	L	4/21/2003	135	57	1	57	OH SEC/DR CL H	OH SC CL-H	4418 BROWNST	1	SC						MADE REPAIRS TO DROP AT POLE; RPLD SEC CONN @ PL-1 CUST	1	0
FORCED INTERR					5370000	22003111007E	L	4/21/2003	135	105	1	105	URD SEC PDSTL	URD SC PEC	2102 SHORT PA		SC						NEED TO REPLACE PEDESTAL AND MOLD HEADS SET UP BARRIER FOR NOW INVALID OLN. MSG SENT TO SC TLA	1	0
FORCED INTERR.	CH	BY 10	40205		5461221	32003111008	T	4/21/2003	135	45	10	450	LIGHTNING	LIGHTNING	1717 TIDWELL F		TF	546122160					yesterday's lightning. REF TR;	1	0
FORCED INTERR.	FB	WR 10	1118A	F45	3740019	120031110091	T	4/21/2003	1401	51	1	51	LIGHTNING	LIGHTNING	411 MELTON	1	TF	374001991					Feeds ... REF TR,	1	0
FORCED INTERR	BL	HE 09	11558	3EZ	5257939	12003111009	T	4/21/2003	1401	209	1	209	SQUIRREL	SQUIRREL	1 TIEL WY	1	TF	525793923					REPLACED BAD SOUTHEREN STATES FUSE BARREL ON OPEN DELTA BANK TAKEN OUT BY SQUIRREL, REF TR;	1	0
FORCED INTERR	MP	ES 01	21269	26AAG	5457410	220031110077	T	4/21/2003	141	42	2	84	HUMAN ERROR	HUMN ERRC	704 BASTROP S	1	TF	545741078					100 KVA TRF WAS FUSED WITH 10 AMP FUSE INSTALLED PROPER FUSE. REF TR,	1	0
FORCED INTERR.	CH	BY 04	40177	B38H	5461527	32003111009	T	4/21/2003	150(	48	2	96	UNKNOWN	UNKNOWN	9701 JENSEN	1	SC	546152759					MADE TEMPORARY REPAIRS TO HIGH LEG BUSS WORK / NEED CREW TO REPLACE X-1 BUSHING OR WHOLE POWER POT TRANSFORMER IN NEXT DAY OR TWO/ TRUCK ACCESSIBLE/	1	0
FORCED INTERR	SH	TE 06	30191		5550822	32003111009	L	4/21/2003	1501	40	1	40	FLLNG TREE OUT	TREE FL/OE	6822 BROOKSIC		DR						TREE FELL & PULLED DROP OFF HOUSE REATTACHED AND LEFT ON; RPLD CONN @ WH;	1	0
FORCED INTERR	BL	KB 05	10155		5256745	12003111010	T	4/21/2003	151	252	4	1008	VINES	VINES	3039 LOCKE LN		TF	525674579					REF TR,	1	0
FORCED INTERR	HC	BR 09	10812	A59B	5253055	12003111010E	T	4/21/2003	1521	37	8	296	UNKNOWN	UNKNOWN	4414 CHEENA	1	TF	525305595					REF TR,	1	0
FORCED INTERR.	FB	RS 05	1555E	A96Z	4346223	12003111010E	T	4/21/2003	152	26	6	156	SQUIRREL	SQUIRREL	3313 PECHA LN	1	TF	434622364					REF TR;	1	0
FORCED INTERR	CY	KL 46	2D157		4866709	220031110101	T	4/21/2003	160(	239	1	239	FLLNG TREE OUT	TREE FL/OE	10511 GRANT		BU	486670968	SC				REPL BAD 50KVA 19.9/120/240 TRAN WITH THE SAME. ALSO REPL 1 SPAN 1/0 SEC. ALSO REPL 4/0 BUSS WORK. RPLD B/U TR, RPLD BUSS WORK @ TR RPLD SEC-1 CUST	1	0
FORCED INTERR	SH	SP 07	30982	I79R	5753736	320031110107	F	4/21/2003	160	26	34	884	UNKNOWN	UNKNOWN	1106 AVENUE F	1	LF	I79R					REFUSED LINE FUSE, REF LF,	1	0
FORCED INTERR	RS	MU 01	30737	A79R	5742911	32003111010E	F	4/21/2003	161	69	17	1173	TREE CLEARANC	TREE CLEAI	201 E TIMBERL	1	LF	A79R					REF LF,	1	0
FORCED INTERR	MP	CR 03	41095	41N	5359601	220031110091	F	4/21/2003	162	90	90	8100	SQUIRREL	SQUIRREL	944 W GARDNE	1	LF	41N					REFUSED LF, REF LF	1	0
FORCED INTERR	CH	SW 06	41683	G88S	5662031	32003111010	F	4/21/2003	163	114	18	2052	CONTRACTOR-N	CON-NT HLF	7238 HEATH	2	LF	G88S	PR				RESTORED SERVICE ON URD SWITCHING #6144 / BAD SPAN OF PRIMARY IN REAR OF 7238 HEATH / CITY OF HOUSTON WILL HAVE HOLE STILL EXPOSED UNTILL AFTER- NOON ON 04/22/03 #	1	0
FORCED INTERR	SH	PA 09	30766	1D2	5754531	32003111011	T	4/21/2003	165(	127	3	381	UNKNOWN	UNKNOWN	2020 RICHEY ST	1	BU	575453141					RPLD B/U TR,	1	0
FORCED INTERR	FB	EB 05	11290	K74	3745350	12003111012E	T	4/21/2003	165	85	1	85	BIRD	BIRD	8523 FM 2919	1	TF	374535056					REFUSED 15 BIRD ON TRANS DISCONNECT, REF TR;	1	0
FORCED INTERR	FB	NV 02	11222	5DZ	4139251	12003111013(	T	4/21/2003	170	49	1	49	LIGHTNING	LIGHTNING	14336 MOODY	1	TF	413925102					REFUSED TRS -PAST LIGHTNIGH NOTIFED, REF TR,	1	0
FORCED INTERR	BL	GN 10	10626	C1F	5255922	120031110134	L	4/21/2003	172(	52	1	52	FOREIGN MATER	FRGN MATR	2405 WORDSW	1	DR						REPLACED BAD CLAMP AT WEATHERHEAD DUE TO CORROSION; RPLD CONN @ WH	1	0
FORCED INTERR	HC	IR 01	11056	B13C	5250153	12003111013E	T	4/21/2003	172	44	10	440	BIRD	BIRD	4819 MACRIDGE	1	TF	525015301					REFUSED TRANSF REF TR,	1	0
FORCED INTERR.	BA	MB 08	37138	I25N	6760346	32003111011E	T	4/21/2003	1741	140	4	560	UNKNOWN	UNKNOWN	7119 WILLIAMS	1	TF	676034630					REF TR,	1	0
FORCED INTERR	SB	SR 12	21677	UK4	4958557	12003111014E	L	4/21/2003	181	94	1	94	OTHER	OTHER	1422 SHADELAN	1	PD						IN REAR OF 1400 MURRYHILL JOINT-USE POLE WITH LIGHTER POT NEEDS REPL - ROTTEN., MSG SENT TO SC TLA	1	0
FORCED INTERR	SH	CG 05	30228	T74A	5752155	320031110121	F	4/21/2003	182	0	0	0	SPLICE	SPLICE	1401 REDFORD	2	PR	T74A					ISOLATED 1ST SPAN OF PRI___BAD @ BOTTOM OF POLE..SPLICE WENT BAD WE HAVE 3 INCH PVC @ BOTTOM OF POLE,,,,DUE TO BEING HIT BEFORE PRI IS IN PIPE. ISOL URD PR	1	0
FORCED INTERR	SH	CG 05				320031110121	F	4/21/2003	182	53	61	3233	SPLICE			2	PR	T74A						0	0
FORCED INTERR.	GP	FR 45	21369	S45T	5062432	22003111010E	F	4/21/2003	183	137	34	4658	URD ELBOW	URD ELBOW	7930 SALGE DR	2	LF	S45T	PR				FOUND BAD ELBOW AT 5867 BATTLE CREEK, REPLACED ELBOW; REF TP	1	0
FORCED INTERR	SH	SP 05	30974	SR6	5854216	320031110124	F	4/21/2003	183	73	25	1825	UNKNOWN	UNKNOWN	1210 BELSHIRE	1	LF	SR6					REFUSED L-F SR6-50 T REF LF;	1	0
FORCED INTERR	HM	SW 08	41691	J28S	5663105	32003111012E	T	4/21/2003	1851	67	5	335	TREE CLEARANC	TREE CLEAI	7725 SHERWAY	1	TF	566310575					TRIMED TREES /REFUSED 50 KVA, REF TR,	1	0
FORCED INTERR	SH	SP 07	30957		5753749	32003111012E	T	4/21/2003	185	240	3	720	SQUIRREL	SQUIRREL	1202 SPENCER		BU	575374904					40 FT DEADEND POLE ROTTEN IN FEEDER CIRCUIT- ALSO NEEDS NEW HELIX ANCHOR IN EASMENT BEHIND 1202 SPENCER- NEEDS TO BE REPLACED SOON; RPLD B/U TR,	1	0
FORCED INTERR	SH	ED 02	30316	S55G	5949635	32003111012E	F	4/21/2003	190	53	26	1378	SQUIRREL	SQUIRREL	15418 TADWOR	2	LF	S55G					REFUSED T/P S55G, REF TP	1	0
FORCED INTERR	SB	EC 06	21697	B92N	5057641	120031110157	F	4/21/2003	200	30	5	150	BU DISC OR BARI	DISC/BARRL	11010 HUNTWY	1	LF	B92N					REPLACED FUSE BARREL FUSE WAS NOT BLOWN, RPLD B/U BARREL ON LF	1	0
FORCED INTERR	SH	SP 05	30974	SR6	5854214	32003111013E	T	4/21/2003	201	4	8	32	UNKNOWN	UNKNOWN	1113 FRESA	1	TF	585421422					REFUSED 50 KVA, REF TR,	1	0
FORCED INTERR	CY	PI 41	2459C	78GO	4476309	22003111010E	T	4/21/2003	201	79	1	79	SEC COND OR DI	SECONDAR'	411 HEFLIN	1	SC	447630974					REPLACED BAD LUG AT THE TRANSFORMER. MGJ	1	0
FORCED INTERR	BL	SF 02	10415	MT2	5257821	12003111016(	T	4/21/2003	210(	144	3	432	FOREIGN MATER	FRGN MATR	2945 LAZY LN	1	SC	525782130					REPAIRED 4/0 LEADS ON 50 KVA TRANS THAT FEEDS TWO LARGE HOMES ON KIRBY DUE TO CORROSION 3612 MR. LYNCH ASSISTED. RPRD BUSS WORK @ TR	1	0
FORCED INTERR	SH	DE 02	30250	96CF	5954729	32003111014(	L	4/21/2003	213(	65	1	65	OH SEC/DR CL H	OH SC CL-H	2317 PICKERTO	1	DR						MADE REPAIRS TO BROKEN HOT LEG @ WEATHERHEAD, ..HOUSEKNOB PULLED OUT OF FACIAL BOARD___ALSO SEND MESSAGE TO ST. LIGHT TO REPLACE BULB ON STANDARD#465568....	1	0
FORCED INTERR.	BA	NP 44	41300	W59D	6266513	320031110144	T	4/21/2003	222	77	2	154	TRANSFORMER	TRANSFRM	8315 HIGHWAY	1	TF	626651399					REF TR, RPLD B/U BARREL ON TR.	1	0
FORCED INTERR	CY	HK 04	2149B	83GC	3868510	22003111011	F	4/21/2003	223	117	2	234	BU DISC OR BARI	DISC/BARRL	BETKA, W OF C	1	LF	83GC					REF LF REPLACED A PHASE	1	0
FORCED INTERR	BL	ST 13	10203	PF7	5054950	12003111016E	T	4/21/2003	2241	65	7	455	OTHER WILDLIFE	OTHER WLE	6605 ROWAN LI	1	TF	505495065					REFUSED TRANSF REF TR,	1	0
FORCED INTERR	BL	BR 03	10488	Z83	5254645	12003111016E	T	4/21/2003	224	51	5	255	UNKNOWN	UNKNOWN	3203 S BRAESW	1	TF	525464515					REF TR,	1	0
FORCED INTERR	SH	EL 07	30744	Y53E	5750922	32003111014E	T	4/21/2003	2251	18	13	234	BU DISC OR BARI	DISC/BARRL	10901 SCARSD	1	TF	575092289					REPLACED BAD FUSE BARREL, RPLD B/U BARREL ON TR;	1	0
FORCED INTERR	BL	DN 01	10539	W67V	5257816	12003112000	T	4/22/2003	001	336	3	1008	UNKNOWN	UNKNOWN	2428 BRENTWO	1	BU	525781618					REPACED 50 KVA 7200 120/240 O H TRANS WITH THE SAME, RPLD B/U TR;	1	0
FORCED INTERR	KY	FZ 42	2562C		4559945	12003112000	T	4/22/2003	054	119	4	476	UNKNOWN	UNKNOWN	3343 EAGLE RIC		TF	455994564	PR				RPLD LIMITER @ TR, REF TR, ROR	1	0
FORCED INTERR.	CY	TB 44	22019	R26P	4771512	22003112000	F	4/22/2003	064	119	37	4403	URD ELBOW	URD ELBOW	1014 GRAHAM [	2	LF	R26P	BU	47715123	PR		URD SW# 8144, REPAIRED Y - ELBOW IN TRNS @ 8LDNA, REFUSED & CLOSED X-TP ***** NEED TO REPLACE TR# 8 @ 1014 GRAHAM DR. BLD # A, 75 KVA - 19.9 240/120 ANSI-2-NLB,CAN GET TO 1	1	0
FORCED INTERR.	MP	HG 04	41081	F6G	5656100	22003112000	L	4/22/2003	065	136	1	136	COLLISION	COLLISION	7714 E MAGNOL	1	SC						REPLACED 2# SECONDARIES WITH 1/0 (80 FT); RPLD SEC CONN @ PL-1 CUST. RPLD SEC-1 CUST REBAGGED DR. ROR	1	0
FORCED INTERR	BL	KB 05	10155		5256745	12003112000E	T	4/22/2003	070	204	4	816	VINES	VINES	3039 LOCKE LN		SC	525674579					RAN VINES REPLACED BURNED XFMR LUGS ON 1 HOT LEG ON A 50 KVA 7200 120/240 LIGHTER XFMR IN AN OPEN DELTA BANK. RE-BONDED POLE RPLD CONN @ TR.	1	0
FORCED INTERR	BA	CD 03	40340	P65X	6458134	32003112000E	F	4/22/2003	073	57	43	2451	BU DISC OR BARI	DISC/BARRL	1405 PACKSAD	2	LF	P65X					REPL. BURNED UP FUSE BARREL ON TP #P65X-80T--SVC REST., REF TP, RPLD B/U BARREL ON TP	1	0
FORCED INTERR	MP	GG 10	40992	E22	5555738	22003112000	F	4/22/2003	074	36	27	972	SQUIRREL	SQUIRREL	REDWOOD N. C	1	LF	E22					REMOVED TREE RAT OFF CSP TRNS LOC @ 6422 HEMLOCK / REFUSED LF LEFT SERV ON, REF LF	1	0
FORCED INTERR	RS	MU 01	30737	A79R	5742818	32003112000E	F	4/22/2003	075	27	17	459	SQUIRREL	SQUIRREL	121 E LARKSPU	1	LF	A79R					TRK 8484 ---- TREES-TREES & TREES ---- SQUIRREL @ REAR 101 E. LARKSPUR ON UNPROTECTED C S P ""IN EASEMENT"", REF LF MSG SENT TO SVC CENTER CEW	1	0
FORCED INTERR	CY	TB 06	21016	I44L	4771630	22003112001	F	4/22/2003	081	49	39	1911	UNKNOWN	UNKNOWN	703 MASON	1	LF	I44L					REF LF,	1	0
FORCED INTERR	SH	ED 04	30328	T11A	5949524	320031120011	F	4/22/2003	082	53	55	2915	SQUIRREL	SQUIRREL	15534 ZABOLIO	2	LF	T11A					REFUSED TP--SQUIRREL, REF TP	1	0
FORCED INTERR.	GA	STW0	31009	A22M	6535552	32003112001	L	4/22/2003	082	130	1	130	OH SEC/DR CL H	OH SC CL-H	12240 JENKINS	1	DR		DR		MT		REPAIRED DROPS REPL. CLAMPS AT THE WH. REPL. BAD METER, RPRD DR. RPLD CONN @ WH; RPLD MTR	1	0
FORCED INTERR.	CH	BY 04	20163	R2K	5461424	32003112001	F	4/22/2003	083	49	41	2009	SQUIRREL	SQUIRREL	9603 EDGEWOF	1	LF	R2K					THERE ARE 6 OR 7 CSP TRS ON THIS LF THAT NEED VARMENT PROTECTION INSTALL ED NO RUSH IS TRUCK ACCESSABLE, REF LF ROR	1	0
FORCED INTERR	HC	MC 03	11101	X49L	5050354	12003112001E	L	4/22/2003	0841	167	1	167	ANTS	ANTS	1439 MIMOSA R	2	DR						REPAIRED SECONDARY MEK CREW TO REPLACE TRANSFORMER. MATERIAL TRACKING DONE BY ROR	1	0
FORCED INTERR	CH	LY 44	30427	52ACL	5862336	320031120014	T	4/22/2003	084	55	2	110	TREE CLEARANC	TREE CLEAI	10227 SUNTURF	1	TF	586233680					TRIMMED TREE LIMBS REFUSED TRANS; REF TR,	1	0
FORCED INTERR	BL	BI 09	11546	9BU	5255355	12003112001	T	4/22/2003	085	41	11	451	VINES	VINES	3826 NORTHWE	1	TF	525535555					REFUSED A 75 NEED VINES REMOVED FROM BANK POLE, REF TR, ROR	1	0
FORCED INTERR.	CH	OA 04	41365	528	5758005	32003112001E	T	4/22/2003	085	53	14	742	SQUIRREL	SQUIRREL	10509 WIGGINS	1	TF	575800521					REFUSED TRANS WLP ALREADY INSTALLED, REF TR,	1	0
FORCED INTERR	CY	TB 44	22392		4872122	22003112001E	T	4/22/2003	085	119	1	119	SQUIRREL	SQUIRREL	11918 ZION RD		TF	487212284	PR				REPLACED 12 KV LIMITER This TRANSFORMER ALREADY HAS WILD LIFE. RPLD LIMITER @ TR REF TR;	1	0
FORCED INTERR	SH	PA 05	30781	M3M	5854024	32003112001E	F	4/22/2003	0911	173	58	10034	TREE CLEARANC	TREE CLEAI	2151 SHAVER S	1	LF	M3M	PR				PICKED UP 1 SPAN OF 2 PHASE #2 PRI., P/U PR-FUSE BLOWN,	1	0
FORCED INTERR	SH	TE 01	31596	77AF	5652109	32003112001	F	4/22/2003	091	27	3	81	UNKNOWN	UNKNOWN	7801 ALMEDA G	1	LF	77AF					REFUSED LINE FUSE / CAUSE UNKNOWN; REF LF;	1	0
FORCED INTERR.	SH	TE 03	31306	6D9	5550355	32003112002(	T	4/22/2003	092	71	1	71	CUST EQP RELAT	CUST RLTD	5959 S SAM HO	1	TF	555035536					CUST HAS 100 HP MTR STARTING COMP OF MOTOR 850 AMPS ON TRF THAT MELTED OUT THEN LEVELS OFF WHEN MOTORS RUNNING NTFD TOO HAVE ELEC TOO CK OUT REF TR;	1	0
FORCED INTERR.	KY	FL 42	22755	31TW	4054251	12003112003(	F	4/22/2003	095(	65	2	130	BIRD	BIRD	8515 POOL HILL	1	LF	31TW					RFZ LF SOUPDUCK ON INLINE POLE TOOK IT OUT REF LF, [J.JAMES WILL HAVE THE FUSE RESTENCILED FROM SOUP TO 31TW - SEV OA]	1	0
FORCED INTERR	MP	HR 01	41028		5359917	22003112002	T	4/22/2003	095	31	1	31	BIRD	BIRD	113 CORONADC		TF	535991737					REFUSED LIGHTER TRNS / LEFT SERV ON / NOTIFIED, REF TR,	1	0
FORCED INTERR	BA	AI 06	30009	P50U	6057734	32003112002	T	4/22/2003	100	254	2	508	SQUIRREL	SQUIRREL	3523 BATTLEGR	1	BU	605773404					REPLACED 50 CSP WITH 10 CONV RPLD B/U TR,	1	0
FORCED INTERR	SH	AI 05	30003	J33K	6057914	320031120031	T	4/22/2003	101	90	1	90	UNKNOWN	UNKNOWN	3810 BATTLEGR	1	TF	605791489					RESET CSP TRANS RESET TR,	1	0
FORCED INTERR	CH	LB 02	41257	K41E	5660023	32003112003	L	4/22/2003	1021	100	1	100	OH SEC/DR CL H	OH SC CL-H	7958 EARHART	1	DR		SC				RPLD CONN @ WH, RPLD SEC CONN @ PL-1 CUST	1	0
FORCED INTERR	FB	RS 07	14170	58GT	4348242	12003112003E	T	4/22/2003	103	67	1	67	CONTRACTOR-N	CON-NT HLF	208 HIGHWAY 3	1	TF	434824263					CRANE BURNED DOWN 1 PHASE PRI. NO ONE HURT --WARNING ISSUED; P/UP PR-FUSE NOT BLOWN.	1	0
FORCED INTERR	HC	AR 44	12555	14NM	5046846	12003112003E	T	4/22/2003	103	85	1	85	VINES	VINES	2711 MC KEEVE	1	TF	504684653	PR				REMOVED VINES REPLACED LIMITER, AND REFUSED XFMR, RPLD LIMITER @ TR, REF TR.	1	0
FORCED INTERR	BA	CD 09	40380	4W2	6457226	32003112003	T	4/22/2003	104	81	10	810	OH SEC/DR CL H	OH SC CL-H	1903 AMY DR	1	SC	645722682					replaced burned up buss ON TRANS, RPRD BUSS WORK @ TR,	1	0
FORCED INTERR	SB	TO 04	21780	A40F	5159833	12003112004E	F	4/22/2003	110	250	8	2000	COLLISION	COLLISION	4602 DACOMA S	1	LF	A40F	PR		SC	PD	REPLACED 45' CLASS 2 POLE WITH THE SAME PICKED UP 4 SPANS OF PRI AND NEUTRAL REPLACED LATERAL POLE H31C. POLE HAULED FROM CYPRESS P/U PR-FUSE BLOWN REF LF 1	1	0
FORCED INTERR	HC	AM 06	10753	PW9	5252814	120031120047	T	4/22/2003	110	49	12	588	SQUIRREL	SQUIRREL	2934 KNOTTY O	1	TF	525281463					REFUSE TRANSF., REF TR.	1	0
FORCED INTERR	MP	BU 01	40618	15DH	5656332	22003112003E	T	4/22/2003	111(	34	2	68	UNKNOWN	UNKNOWN	24 WHARF RR	1	TF	565633248					REPLACED FUSE BARREL FEEDING POWER POT IN OPEN DELTA BANK / CHLS RPLD B/U BARREL ON TR.	1	0
FORCED INTERR	KY	KT 43	11577	40SJ		12003112004E	F	4/22/2003	111	43	11	473	UNKNOWN	UNKNOWN	2323 HARTWEL	1	LF	40SJ					RFZ LF2, REF LF	1	0
FORCED INTERR	BA	AI 06	30009	73GD	6057738	32003112003E	T	4/22/2003	112	2	1	2	BU DISC OR BARI	DISC/BARRL	3655 BATTLEGR	1	TF	605773866					RPLD B/U BARREL ON TR,	1	0
FORCED INTERR	BA	CD 08	40396	PT5	6456249	32003112004	F	4/22/2003	1131	65	32	2080	UNKNOWN	UNKNOWN	DANUBINA, S O	1	LF	PT5					REFUSED SOUTH PHASE ROR	1	0
FORCED INTERR	SB	GE 41	21196	N39M	4761007	12003112005	F	4/22/2003	113	135	35	4725	URD ELBOW	URD ELBOW	5026 TAIN DR	2	LF	N39M	PR				ON URD SW # 8152 RPLD Y ELBOW @ TRANS # 5 ALL SERV BACK ON. REF TP RPRD URD PR.	1	0
FORCED INTERR.	FB	BV 42	12761		4550047	12003112005E	T	4/22/2003	114(	152	3	456	UNKNOWN	UNKNOWN	900 FM 359		BU	455004725					REPL 50/50 KVA 19.9 TR. RPLD B/U TR.	1	0
FORCED INTERR	MP	BG 09	40275	F8U	5455117	22003112004	F	4/22/2003	114	63	25	1575	COLLISION	COLLISION	3547 CHARLEST	1	LF	F8U					REFUSE LINE FUSE POLE LEANING DUE TO CABLE TV CAUSING PRIMARY TO RAP TOGETHER AT 3423 CHARLESTON POLE AT 3423 CHARLESTON REF LF ROR	1	0
FORCED INTERR	HC	AR 42	10927	49AEK	5146937	12003112005E	T	4/22/2003	114	132	5	660	TRANSFORMER	TRANSFRM	120 DISNEY	1	BU	514693799					REPLACED 25KVA 7200KV 120/240 TRANSFORMER ROR	1	0
FORCED INTERR	SH	WE 07	31272		5856732	32003112004E	T	4/22/2003	114	132	1	132	UNKNOWN	UNKNOWN	1400 N JEFFER		BU	585673212					REPLACED BAD 25CONV WITH THE SAME RPLD B/U TR.	1	0
FORCED INTERR	HC	AM 06	10753	PW9	5252816	12003112006(	T	4/22/2003	115	2	6	12	SQUIRREL	SQUIRREL	2914 KNOTTY O	1	TF	525281683					refuse transf REF TR,	1	0
FORCED INTERR	FB	RE 04	11445		4448550	120031120061	T	4/22/2003	115	23	5	115	SQUIRREL	SQUIRREL	1704 CYPRESS		TF	444855053					50 KVA 7200 CSP TR NEEDS TO BE REPL. PRI BUSHING DAMAGED BY SQUIRREL EASEMENT --HAND JOB NEEDS SWITCH INSTALLED RESET TR ROR	1	0
FORCED INTERR	SH	TE 01	31089	7LT	5651430	320031120047	T	4/22/2003	120	39	3	117	UNKNOWN	UNKNOWN	8107 ARROWHE	1	TF	565143094					REFUSED TRANS REF TR,	1	0
FORCED INTERR	MP	EU 03	40710	N29C	5259905	220031120044	F	4/22/2003	122(	40	18	720	SQUIRREL	SQUIRREL	W 15TH @ LAIR	1	LF	N29C					REF LF	1	0
FORCED INTERR	GA	GA 10	31827	X13I	6738518	320031120051	L	4/22/2003	122	45	1	45	OH SEC/DR CL NI	OH SC CL-N	5428 BORDEN A	1	SC						REPAIRED NUETRAL AT THE POLE, RPLD CONN @ PL	1	0
FORCED INTERR	RS	AE 06	3537A	11PH	5731137	32003112005E	F	4/22/2003	1251	110	1	110	LIGHTNING	LIGHTNING	10404 DANBUR	1	LF	11PH	PD				I FOUND A 40' CL 4 POLE THAT HAD BEEN STRUCK BY LIGHTNING I TOPPED OFF THE POLE AND RE-ATTACHED THE KINGPIN AND PRIMARY TEMPORARILY POLE NEEDS TO BE REPLACED S/	1	0
FORCED INTERR	FB	EB 05	1557B	W130	3349009	120031120067	T	4/22/2003	125	149	1	149	UNKNOWN	UNKNOWN	1407 FM 2764	1	BU	334900902					repl 15kva 7200 120/240 lt power pot. RPLD B/U TR.	1	0
FORCED INTERR	GA	GA 07	31211	T9B	6738512	32003112008(	F	4/22/2003	131	50	24	1200	TREE CLEARANC	TREE CLEAI	5718 STEWART	1	LF	T9B	TF	67385118			TREE IN THE REAR OF 1523 & 1527 ARE IN THE TRANS AND OPEN WIRE SEC WE TRIMMED AROUND THE POT BUT THE TREE NEEDS TO COME DOWN WE ALSO REFUSED THE LINE FUSE	1	0

FORCED INTERR	GP	RU 02	41655	H99G	5362101	220031120057	L	4/22/2003	1314	62	1	62	UNKNOWN	UNKNOWN	7313 DOMINO LI	1	SC						RPLCD CORRODED HI-LEG CLAMP @ TRNS POLE; RPLD CONN @ PL.	1	0
FORCED INTERR	GP	BA 04	20626	18BW	5066550	220031120056	F	4/22/2003	1318	27	8	216	LIGHTNING ARRE	LTNG ARRS'	4950 FM 1960 W	1	LF	18BW					REF LF	1	0
FORCED INTERR	MP	BG 07	10956	8C2	5355918	220031120060	L	4/22/2003	1321	53	1	53	CUST EQP RELAT	CUST RLTD	3336 TAMPA ST	1	DR						replace clamps at wh, RPLD CONN @ WH;	1	0
FORCED INTERR	KY	FZ 41	22766		44583471	120031120072	T	4/22/2003	1320	146	5	730	BU DISC OR BARI	DISC/BARRL	22619 BUCKTRC		DB	445834712					RPLCD BOND WIRE AND REPLACED DISCONNECT ON TF... TLA	1	0
FORCED INTERR.	KY	FL 42	22750	77GN	41547135	120031120080	T	4/22/2003	1408	139	1	139	UNKNOWN	UNKNOWN	28938 FM 1093	1	BU	415471353					REPL. 50/50 10 W7.2 STEP DOWN TR. ... RPLD B/U TR;	1	0
FORCED INTERR	BL	UL 46	10334	63N	50579171	120031120081	F	4/22/2003	1409	36	7	252	TREE CLEARANC	TREE CLEAF	6202 VALLEY FC	1	LF	63N					NEED TO TRIM TREES BEHIND THIS LF; REF LF; RGR	1	0
FORCED INTERR	CY	HK 05	2A110	C60U	4071526	220031120066	F	4/22/2003	1420	65	10	650	LIGHTNING	LIGHTNING	22307 STOKES L	1	LF	C60U	PR				PICKED UP 2 SPANS OF #2 PRIMARY 3 SPANS SOUTH OF LINE FUSE; P/U PR-FUSE BLOWN; REF LF;	1	0
FORCED INTERR	FB	TM 04	10808	M29Y	4847302	120031120084	F	4/22/2003	1422	68	21	1428	SQUIRREL	SQUIRREL	525 PITTMAN	1	LF	M29Y					@ 525 PITTMAN A SQUIRREL CLIMBED A POLE WITH HARDWARE CLOTH THAT GOES ALL THE WAY TO THE TOP. HE STOOD ON TOP OF THE POLE AND HIS HEAD HIT THE PRIMARY BLOWING	1	0
FORCED INTERR	GP	SA 41	21274		4962304	220031120071	T	4/22/2003	1435	312	2	624	COLLISION	COLLISION	15535 HEMPSTE		BU	496230465	SC			PD	replaced meter [illegible]; RPLD B/U TR; RPRD CONN @ TR; RPLD PL; RPLD LIGHTNING ARRESTOR;	1	0
FORCED INTERR	HM	AT 42	2314E	K91Z	5970438	220031120077	T	4/22/2003	1453	41	1	41	FLLNG TREE OUT	TREE FL/OE	28004 CALVIN	1	TF	597043803					RESET CBP ... TREE LIMB ON OPEN-WIRE SECONDARIES; RESET TR.	1	0
FORCED INTERR	MP	BG 03	40252		5456106	220031120078	L	4/22/2003	1501	36	1	36	OH SEC/DR CL NI	OH SC CL-N	3022 ISABELLA		DR						REPAIRED NEUTRAL @ WH; RPLD CONN @ WH;	1	0
FORCED INTERR	MP	MP 08	41391	E49C	5556155	220031120080	L	4/22/2003	1503	49	1	49	UNKNOWN	UNKNOWN	217 LENOX	1	DR						REPLACED NEUTRAL CLAMP @ WEATHERHEAD / NO ONE HOME TO NOTIFY / LEFT DOOR HANGER AT BACK DOOR; RPLD CONN @ WH;	1	0
FORCED INTERR	BA	MB 05	3C164	31RM	6763148	320031120066	F	4/22/2003	1518	144	3	432	FLLNG TREE OUT	TREE FL/OE	15406 WOODCF	1	LF	31RM					P/U PR-FUSE BLOWN; REF LF; RPLD LIGHTNING ARRESTOR; TLA	1	0
FORCED INTERR	CH	HR 03	41037	K13C	5460418	320031120070	L	4/22/2003	1528	79	1	79	UNKNOWN	UNKNOWN	2406 LYNNFIELD	1	DR						TEMP REATTACHED BRKR BOX BACK TO WALL—RPLCD P.O.A.—REBAGGED DROPS— RPLCD CONNECTIONS @ WH—RPLCD BROKEN MTR # D20280383—X1—RDG 11112 W/ NEW MTR # [illegible]	1	0
FORCED INTERR.	BL	EU 09	40743	NU3	5258659	220031120084	L	4/22/2003	1544	93	1	93	UNKNOWN	UNKNOWN	1136 SHELTERV	1	DR						REPLACED RUBBER COATED DROPS WITH #4 AL 3C TW / CNLS / NEED 2-MAN CREW TO REPLACE #4 RUBBER COATED 4 WIRE SECONDARIES (75 FEET) AT SERVICE CENTER CONVENIENCE	1	0
FORCED INTERR	CH	SW 10	41960	JO9	5562442	320031120072	L	4/22/2003	1547	122	1	122	OH SEC/DR CL NI	OH SC CL-N	5641 VAN ZAND	1	DR					PD	NEEDS TO REPLACE 35FT POLE HAS TWO DROPS TO HOUSE SERVICE DROPS HOLDING POLE UP — HAS 2 OLD RED TAGS THIS MAY BE TELEPHONE POLE - BUT NEEDS TO BE CHANGE OUT	1	0
FORCED INTERR.	SH	SB 04	31043	84PT	5855739	320031120073	T	4/22/2003	1608	89	6	534	FLLNG TREE OUT	TREE FL/OE	325 BROWN	1	SC	585573904					RPRD SEC CONN @ PL→1 CUST	1	0
FORCED INTERR	SB	DH 04	40598	3B7	5160643	120031120112	T	4/22/2003	1646	102	1	102	UNKNOWN	UNKNOWN	4613 MANGUM	1	TF	516064320					REF TR.	1	0
FORCED INTERR.	HM	IT 02	20208	48NN	5367729	220031120090	F	4/22/2003	1657	86	1	86	BU DISC OR BARI	DISC/BARRL	18933 ALDINE W	1	LF	48NN	PR				REF LF RPLD B/O PR JUMPER-FUSE NOT BLOWN; TLA	1	0
FORCED INTERR.	CH	OA 01	41580	B14U	56588281	320031120076	T	4/22/2003	1659	144	6	864	TREE CLEARANC	TREE CLEAF	10126 FLEMING	1	TF	565882816					REPL FUSE BARREL, L/A, SQUIRREL GUARDS, SQUIRREL GUARDS CUT TREES AWAY FROM TRANS. REF TR; RPLD B/U BARREL ON TR; RPLD LIGHTNING ARRESTOR.	1	0
FORCED INTERR.	BL	GT 09	10648	K8N	5356439	120031120115	F	4/22/2003	1705	67	53	3551	UNKNOWN	UNKNOWN	3939 MONTROS	1	LF	K8N					REF LF.	1	0
FORCED INTERR	BA	HL 04	40838		6258134	320031120075	T	4/22/2003	1718	81	2	162	UNKNOWN	UNKNOWN	7414 BAYWAY D		SC	625813491					RPLD BUSS WORK @ TR.	1	0
FORCED INTERR	BL	SF 02	10415	MT2	5257821	120031120120	T	4/22/2003	1728	373	3	1119	UNKNOWN	UNKNOWN	1516 KIRBY DR	1	BU	525782130					REPLACED 50 KVA 7200 120/240 O.H TRANS. WITH 100 KVA 7200 120/240 CAUSE UNKNOWN; RPLD B/U TR;	1	0
FORCED INTERR.	BL	ST 12	10256	C41F	5155111	120031120130	F	4/22/2003	1734	119	3	357	GUY/ANCHOR	GUY/ANCHC	6120 BELLAIRE	1	LF	C41F	PR			DB	PICKED UP 1 SPAN OF PRIMARY AND CHANGED A 19.9 DISCONNECT; P/U PR-FUSE BLOWN; RPLD B/U DISC-LF BLOWN. TLA CORRECTED 2HR/CRH 04-28-03	1	0
FORCED INTERR	MP	WO 01	41822	PF3	52598551	220031120092	T	4/22/2003	1738	71	8	568	OH SEC/DR CL HI	OH SC CL-H	3018 ATTRIDGE	1	SC	525985511					REPLACED BURN UP LUG ON 25 KVA 7200 120 240 V TRAN. JBB	1	0
FORCED INTERR	SU	STF05	12288	F57T	4852752	120031120126	F	4/22/2003	1746	135	21	2835	UNKNOWN	UNKNOWN	12114 MONTICE	2	LF	F57T	BU	485275737			RPL TR#75 S/N[illegible]164, REF TP; RPLD B/U TR.	1	0
FORCED INTERR	BZ	BZ 05	30629	K15W		320031120083	F	4/22/2003	1804	46	50	2300	TREE CLEARANC	TREE CLEAF	4600 COUNTY R	1	LF	K15W					NEED TO TRIM—BAD. REF LF JBB	1	0
FORCED INTERR.	SH	DE 04	31375	4N5	59559421	320031120086	T	4/22/2003	1811	35	4	140	SQUIRREL	SQUIRREL	202 MAXIE	1	TF	595594214					REF TR.	1	0
FORCED INTERR	SU	AF 06	11795	K96J	4854495	120031120128	F	4/22/2003	1814	36	167	6012	FOREIGN MATER	FRGN MATR	7520 COOK	1	LF	K96J					REF LF	1	0
FORCED INTERR	CY	PI 41	2A120	S1793	44760501	220031120096	T	4/22/2003	1820	77	2	154	SQUIRREL	SQUIRREL	809 W BRENDA	1	TF	447605011					INSTALLED W/P REF TR.	1	0
FORCED INTERR	GP	RA 41	22978	99SR	5173618	220031120100	T	4/22/2003	1836	78	1	78	VINES	VINES	25439 BUDDE R	1	TF	517361804					REF TR.	1	0
FORCED INTERR	BL	UL 45	13083		5057498	120031120133	T	4/22/2003	1913	74	50	3700	TRANSFORMER	TRANSFRMI	1416 WOOD HO		TF	505749804					FUSE BLOWN ON CUST OWNED URD- MGR. NOTIFIED;	1	0
FORCED INTERR.	MP	WO 04	41303		5261805	220031120104	T	4/22/2003	1937	153	2	306	HUMAN ERROR	HUMN ERRC	811 W DONOVA		SC	526180556					MADE REPAIRS TO GROUND BUSS ON INSIDE OF TRANS. CT LUGS NOT TIGHTENED PROPERLY. RPLD CONN @ TR;	1	0
FORCED INTERR.	FB	RS 03	11415	A71J	4449149	120031120135	T	4/22/2003	1942	69	4	276	LIGHTNING ARRE	LTNG ARRS'	2107 FM 3155	1	TF	444914944	DR				REPLACED BLOWN LA REPAIRED SET OF #4 DROPS INST W/LP REFUSED 75 KVA TRANS. REF TR; RPRD DR; RPLD LIGHTNING ARRESTOR.	1	0
FORCED INTERR	BL	ST 06	10221	S82A	5154244	120031120140	T	4/22/2003	2021	134	19	2546	HUMAN ERROR	HUMN ERRC	7714 RENWICK	1	SC	515424435					REPLACED BAD TRANS LEAD ON LIGHTER TRANS. DUE TO BAD CONNECTION; RPLD BUSS WORK @ TR;	1	0
FORCED INTERR	FB	OB 42	11376		4550455	120031120141	T	4/22/2003	2027	120	2	240	TREE CLEARANC	TREE CLEAF	2302 FAIRDALE		TF	455045509					CUT TREE OFF OF 10 8 25VA TRANS REPLACED 12 K MATE LIMITER FUSE INSTALLED SQUIRREL WIRE AND GUTHRIE GUARDS. RPLD LIMITER @ TR.	1	0
FORCED INTERR	MP	EU 03	40711	A57L	52595251	220031120113	T	4/22/2003	2153	72	8	576	OTHER WILDLIFE	OTHER WLD	2044 E T C JEST	1	TF	525952515					REFUSED A 100 KVA AND TWO 75 KVA 7200 120 240 V TRANSFORMER; REF TR. BRS	1	0
FORCED INTERR	FB	RE 01	22295	61SE	4447734	120031120147	T	4/22/2003	2256	40	1	40	TREE CLEARANC	TREE CLEAF	2303 SHANE	1	TF	444773480					CUT TREE OFF OF TRANS AND POLE REFUSED 25 CUST STATED TREES WOULD NOT TRIM BECAUSE WAS NOT OVER PRI?; REF TR. BRS	1	0
FORCED INTERR	GA	GA 10	30024	Y49	6737217	320031130001	T	4/23/2003	0105	46	11	506	BU DISC OR BARI	DISC/BARRL	3102 BELUCHE	1	TF	673721747					REPLACED BAD FUSE BARREL ON TRANS. RPLD B/U BARREL ON TR.	1	0
FORCED INTERR	HM	GR 01	20187	S85E	54665211	220031130001	F	4/23/2003	0240	44	1	44	SQUIRREL	SQUIRREL	17281 JOHN F.K	3	LF	S85E					REF TP.	1	0
FORCED INTERR	GA	GA 09	31226	H59X	6737957	320031130003	T	4/23/2003	0300	28	1	28	BU DISC OR BARI	DISC/BARRL	4502 SEAWALL	1	TF	673795700					REPLACED BAD FUSE BARREL ON TRANS FOR STREET LIGHTS. RPLD B/U BARREL ON TR.	1	0
FORCED INTERR	CH	SW 05	41678	E88Y	55627351	320031130002	F	4/23/2003	0305	61	8	488	UNKNOWN	UNKNOWN	8514 LEEDALE	2	LF	E88Y					REF TP.	1	0
FORCED INTERR	SH	EL 05	30349	F18Y	5850230	320031130004	F	4/23/2003	0404	62	32	1984	OTHER WILDLIFE	OTHER WLD	12406 CORNING	2	LF	F18Y					REFUSED TP F 18 Y., REF TP. SENT MSG TO T&D TO TRIM TREES IN ESMT BRS	1	0
FORCED INTERR	CY	WL 42	21162	J28X	39700171	220031130005	T	4/23/2003	0700	65	1	65	BIRD	BIRD	20910 EMERALD	1	TF	397001713					REFUSED 25KVA TF OUT BY BIRD BRS	1	0
FORCED INTERR	HC	ST 09	10238	KE3	5154138	120031130004	T	4/23/2003	0718	41	7	287	SQUIRREL	SQUIRREL	8011 RAMPART	1	TF	515413804					refused power tr in open delta bank tr already has sql prot. service ok by cust. REF TR;	1	0
FORCED INTERR	SB	CB 11	21466		5059345	120031130006	T	4/23/2003	0803	117	9	1053	OH SEC/DR CL NI	OH SC CL-N	9207 VOGUE LN		SC	505934523					REPAIRED BROKEN NEUT AT SERV POLE, RPLD SEC CONN @ PL→1 CUST	1	0
FORCED INTERR	GP	LU 42	2C131	S2278	5071948	220031130014	T	4/23/2003	0850	63	2	126	SQUIRREL	SQUIRREL	22831 FRITZ LN	1	TF	507194802					REFUSED 25 KVA 7200 120/240 OH POT REF TR,	1	0
FORCED INTERR	SB	EC 03	21695	K69M	50586141	120031130017	F	4/23/2003	0936	35	8	280	UNKNOWN	UNKNOWN	809 BROGDEN	1	LF	K69M					REF LF.	1	0
FORCED INTERR	KY	KT 43	22623	W29U	39586051	120031130020	F	4/23/2003	0941	72	7	504	FOREIGN MATER	FRGN MATR	4500 5TH	1	LF	W29U	LF	M67L			ARRANGED OUT AGE FOR 4 27 03 AT 0900 TO REPLACE A AND B PHASE SWITCHES AND AT LF W29U AND LF M67U C PHASE SWITCH TK 3000 AND 3003 REFUSED BOTH C PHASE & REF LF.	1	0
FORCED INTERR	SH	SP 05	30974	SR6	5854214	320031130016	T	4/23/2003	0951	19	8	152	SQUIRREL	SQUIRREL	1110 BELSHIRE	1	TF	585421422					REFUSED TRX -SQUIRREL- REF TR.	1	0
FORCED INTERR	HM	AT 42	20016	S3128	6169223	220031130022	T	4/23/2003	1007	75	1	75	UNKNOWN	UNKNOWN	14240 FM 1960 E	1	TF	616922397					REF TR.	1	0
FORCED INTERR	SH	MY 03	31543		5749536	320031130019	L	4/23/2003	1006	40	1	40	HUMAN ERROR	HUMN ERRC	1406 SAN MARI		SC						MADE UP DROPS @ PED. RPRD SEC-1 CUST;	1	0
FORCED INTERR	SH	WEB0	31669	15KS	6047625	320031130026	T	4/23/2003	1043	36	1	36	BIRD	BIRD	807 HIGHWAY 3	1	TF	604762587					TRK 6464— TRX NEEDS W.L.P —NORTH OF BOAT RAMP—TRK ACCESS. REF TR MEK	1	0
FORCED INTERR	SH	PA 03	30760	KL7	57543471	320031130025	T	4/23/2003	1047	55	7	385	UNKNOWN	UNKNOWN	1304 HEMLOCK	1	TF	575434718					refused trx —does have w/lp. REF TR.	1	0
FORCED INTERR	GP	LK 07	41298	LH4	5262634	220031130031	T	4/23/2003	1048	199	1	199	UNKNOWN	UNKNOWN	8414 DE PRIEST	1	BU	526263471					RPLD B/U TR.	1	0
FORCED INTERR	FB	WR 09	11255		3737332	120031130036	L	4/23/2003	1050	38	1	38	VANDALISM	VANDALISM	2910 OLD LANE		SC						MADE REPAIRS TO PRI THAT HAD BEEN SHOT MEK	1	0
FORCED INTERR	HM	AD 10	41977	C14F	5464314	220031130033	L	4/23/2003	1053	57	1	57	OH SEC/DR CL HI	OH SC CL-H	13911 RUSS	1	DR						Found Cut Out-RCNC, MTR #135 RDG 31026 X1 RPLD CONN @ WH.	1	0
FORCED INTERR	SH	SH 03	30905	Y89E	5752138	320031130033	T	4/23/2003	1117	28	1	28	UNKNOWN	UNKNOWN	10600 GULF FW	1	TF	575213837					REFUSED LIGHTER POT IN OPEN DELTA BANK / CNLS / CAUSE UNKNOWN, RESET TR.	1	0
FORCED INTERR	CH	SW 10	41960	J45S	5563524	220031130036	T	4/23/2003	1125	205	5	1025	COLLISION	COLLISION	6034 HERMANN	1	SC	556352444	DR			PD	REPL. 25' AND 30' POLES WITH 30' POLE. REPL. 1SPAN 1/0 SEC., TWO SPANS OF #4 DROPS LEFT BOTH METERS DISC ELECT IS REBUILDING WEATHERHEADS ALSO STRAIGHTEN 45' POLE O	1	0
FORCED INTERR	CH	LB 01	41288	B75P	5559237	220031130036	T	4/23/2003	1137	42	1	42	SQUIRREL	SQUIRREL	5518 RAND ST	1	TF	555923790					187 TR IN EASEMENT NEED BW ON 12' F= SKT; REF TR. MEK	1	0
FORCED INTERR	HM	RA 42	22250		5272301	220031130046	T	4/23/2003	1250	117	1	117	LIGHTNING	LIGHTNING	23802 1/2 NORT		TF	527230198					REF TR.	1	0
FORCED INTERR	CY	HK 42	22257	86VJ	4466551	220031130047	F	4/23/2003	1251	108	1	108	LIGHTNING	LIGHTNING	29101 HWY 290	1	LF	86VJ					REF LF.	1	0
FORCED INTERR	GP	LK 06	22554	A2W	5162943	220031130049	L	4/23/2003	1258	51	1	51	OH SEC/DR CL HI	OH SC CL-H	9802 W MONTG	1	DR						REPLACED BAD LIGHTER LEG AT WEATHERHEAD/REWORKED NEUTRAL, RPLD CONN @ WH;	1	0
FORCED INTERR	BA	AT 41	20013			320031130055	C	4/23/2003	1301	0	0	0	TRANSFORMER	PRIMARY	FAIRLAKE BW S		PC	AT41					CREW FD A PHASE OF STEP DOWN 83125 BLOWN CREW RODE OUT CIRCUIT FOUND PRIMARY DOWN BEHIND LF E41K FUSE DID NOT BLOW SECTION 20013 CREW WILL MAKE REPAIRS TC	1	0
FORCED INTERR	BA	AT 41	20006			320031130055	C	4/23/2003	1301	56	89	4984	TRANSFORMER				PC	AT41						0	0
FORCED INTERR	FB	BV 42	11363	W17T	4351855	120031130065	T	4/23/2003	1320	41	2	82	OH SEC/DR CL HI	OH SC CL-H	5308 MIMOSA LI	1	SC	435185556					REPL.BAD LUG AT TR. RPLD CONN @ TR.	1	0
FORCED INTERR	SH	SO 42	10958	W93S	54494191	320031130050	T	4/23/2003	1337	61	2	122	OH SEC/DR CL HI	OH SC CL-H	2557 HILLHOUSE	1	SC	544941917					REPAIRED HOT LEG AT TRANS, RPRD BUSS WORK @ TR;	1	0
FORCED INTERR	BA	AT 41				220031130062	C	4/23/2003	1357	95	89	8455	PRIMARY CONDU	PRIMARY	FAIR LK BTW SI		PC	AT42					CREW TRIED TO PICK UP THE SERVICE DUE TO PREVIOUS OUTAGE AND STEP DOWN 83134 (A PHASE) BLEW CREW FOUND PRIMARY DOWN BEHIND LF E41K SECTION 20013 LF DID NOT	0	0
FORCED INTERR	HM	AT 42				220031130062	C	4/23/2003	1357	95	57	5415	PRIMARY CONDU	PRIMARY	FAIR LK BTW SI		PC	AT42					CREW TRIED TO PICK UP THE SERVICE DUE TO PREVIOUS OUTAGE AND STEP DOWN 83134 (A PHASE) BLEW CREW FOUND PRIMARY DOWN BEHIND LF E41K SECTION 20013 LF DID NOT	1	0
FORCED INTERR	SH	SH 11	31404	UA1	5752906	320031130057	F	4/23/2003	1414	115	92	10580	UNKNOWN	UNKNOWN	12113 PALMSPR	1	PR	UA1					P/U/P PR-FUSE NOT BLOWN;	1	0
FORCED INTERR	GP	AD 06	20394	G6B	5364541	220031130065	L	4/23/2003	1440	49	1	49	TREE CLEARANC	TREE CLEAF	15501 HENRY	1	SC						KILLED LOAD ON ARRIVAL / FOUND NEUTRAL BROKE AT POLE CUT TREE LIMBS MADE REPAIRS, RPLD SEC CONN @ PL-1 CUST.	1	0
FORCED INTERR	SU	IM 44	12081	Y75O	4850413	120031130078	T	4/23/2003	1444	58	5	290	OH SEC/DR CL HI	OH SC CL-H	2507 WILLIAMS	1	SC	485041330					MADE TEMP REPR TO BUSS TIE ON LITER POT- NEED TO REWORK ALL CONNECTIONS ON THIS OPEN DELTA BANK-BANK LOC EAST OF BLDG-1 SPAN SOUTH OF 480 V BANK-THEY CLOSE @5	1	0
FORCED INTERR	SB	CB 11	21466		5059345	120031130080	L	4/23/2003	1453	50	1	50	OH SEC/DR CL HI	OH SC CL-H	9207 VOGUE LN		SC						REPL. CLAMP AT SERV POLE, RPLD SEC CONN @ PL-1 CUST.	1	0
FORCED INTERR	SU	IM 44	12094	W24F	4850601	120031130081	T	4/23/2003	1457	129	9	1161	OH SEC/DR CL HI	OH SC CL-H	3650 HIGHWAY	2	SC	485060155					DUG DOWN AND REPAIRED 1 LEG OF THE 350 SECONDARIES BELOW THE PEDISTAL @ 2402 OLD FORT NEED TO REPLACE DIRECT BURIED SECONDARIES FROM THE PED @ 2408 TO 2402 C	1	0
FORCED INTERR	BL	JN 03	10011	G71X		120031130082	F	4/23/2003	1503	267	8	2136	FOREIGN MATER	FRGN MATR	MARINETTE, BT	1	LF	N86Z	BU	505541031			REPLACED BAD 100 KVA LIGHTER IN CLOSED DELTA ALSO REPLACED BAD LIGHTNING ARRESTOR ADDED SQUIRREL PROTECTION ASSISTED BY 3676 MARTINEZ. RPLD B/U TR, LF NOT BLOW	1	0
FORCED INTERR	BA	CS 02	40563	46SM	6263500	320031130061	T	4/23/2003	1508	257	1	257	UNKNOWN	UNKNOWN	3014 WOLCIK R	1	BU	626350051					REPLACED 15 KVA T/R, RPLD B/U TR.	1	0
FORCED INTERR	GP	RU 01	41644	1S6	5362502	220031130076	T	4/23/2003	1514	38	5	190	UNKNOWN	UNKNOWN	7220 AIRLINE DI	1	TF	536250297					RIBBON GOT ACROSS TOP SIDE OF XFMR BANK. RM RIBBON, REF TR.	1	0
FORCED INTERR.	MP	CL 03	40470	N51R	5558611	220031130077	T	4/23/2003	1514	49	8	392	SQUIRREL	SQUIRREL	827 MAJESTIC	1	TF	555861135					REF TR.	1	0
FORCED INTERR	HM	AT 42				220031130090	C	4/23/2003	1531	0	0	0	PRIMARY CONDU	PRIMARY	FAIR LK BTW SI		PC	AT42					CREWS STILL HAVE SERVICE OFF ON A PHASE. CREWS FOUND PRIMARY DOWN BEHIND LF E41K FUSE DID NOT BLOW ALL SERVICE BACK ON SECTION 20013 SO 281 10 % CIRCUIT —ABK	1	0
FORCED INTERR	HM	AT 42	2386J			220031130090	C	4/23/2003	1531	118	57	6726	PRIMARY CONDU				PC	AT42						0	0
FORCED INTERR	BA	AT 41	20006			220031130090	C	4/23/2003	1531	159	89	14151	PRIMARY CONDU				PC	AT42						0	0
FORCED INTERR	HM	AT 42				220031130098	C	4/23/2003	1532	105	154	16170	PRIMARY CONDU	PRIMARY	FAIR LK BTW SI		PC	AT42					CREWS FOUND A PHASE BLOWN ON 83125 CREWS FOUND PRIMARY DOWN BEHIND E41K FUSE DID NOT BLOW SECTION 20013 CREWS MAKING REPAIRS SO 182 10% CIRCUIT —ABK TR	1	0
FORCED INTERR	BL	KB 11	10176	D7L	5256803	120031130086	T	4/23/2003	1557	49	2	98	BU DISC OR BARI	DISC/BARRL	5115 KIRBY DR	1	TF	525680399					RPLD B/U BARREL ON TR;	1	0
FORCED INTERR	HC	BL 03	10769	S1MF	5052309	120031130090	T	4/23/2003	1600	46	1	46	BU DISC OR BARI	DISC/BARRL	11907 N GARDE	1	TF	505230973					REFUSED POWER TRANSF , REF TR;	1	0
FORCED INTERR.	SH	TE 01	31067	80AF	5652308	320031130065	T	4/23/2003	1610	46	10	460	UNKNOWN	UNKNOWN	8118 WINTHROI	1	TF	565230887					REFUSED TRANSFORMER. REF TR.	1	0
FORCED INTERR	GP	TWG4	2388K	S3203	53681231	220031130093	T	4/23/2003	1656	49	2	98	SQUIRREL	SQUIRREL	20922 H AND R	1	TF	536812319					REF TR;	1	0
FORCED INTERR.	CY	TB 45	21046	75CP	4571834	220031130098	F	4/23/2003	1711	116	4	464	VINES	VINES	23402 HOLLY HC	1	LF	75CP	TF	457183601			REFUSED LF 75CP — ALSO CLEANED VINES & REFUSED 25 KVA 19.9 KV TR AT 23320 HOLLY HOLLOW. REF LF REF TR.	1	0
FORCED INTERR.	SH	SH 05	30914	29A	5652945	320031130073	L	4/23/2003	1725	52	1	52	COLLISION	COLLISION	9235 EDGEBRO	1	SC						P/U SEC-1 CUST;	1	0
FORCED INTERR.	GP	THW4	2E153	57PR	4865647	220031130102	F	4/23/2003	1758	87	68	5916	TREE CLEARANC	TREE CLEAF	12743 JUSTIN T	2	LF	57PR					TRIMMED PALM TREE AWAY FROM 'Y' T/P 58PR NEED TREE CREW TO TRIM MORE OR HAVE CUST REM TREE URD SWO # 182 REF TP MSG SENT TO S/C TLA	1	0
FORCED INTERR	SH	PA 06	30783		5754849	320031130075	T	4/23/2003	1800	55	10	550	UNKNOWN	UNKNOWN	1404 SHAVER S		TF	575484908					REFUSED TRANNY, REF TR.	1	0
FORCED INTERR	SU	RO 43	12598	52EU	4852238	120031130109	F	4/23/2003	1818	119	1	119	UNKNOWN	UNKNOWN	12808 W AIRPO	3	LF	51EU					REFUSED A - PHASE ON LINE FUSE 51EU - 657 RESET THREE PHASE RECLOSER M-178 FEEDING THREE PHASE TRANSFORMER REF LF CORRECTED 2HR/CRH 04-28-	1	0
FORCED INTERR	HC	BL 04	10774	N72L	5150156	120031130110	F	4/23/2003	1818	58	35	2030	SQUIRREL	SQUIRREL	15163 FOUR WI	2	LF	N72L					W/LP-ALREADY-INSTALL REF TP	1	0
FORCED INTERR.	BL	ST 07	10230	B46P	5154010	120031130116	F	4/23/2003	1916	50	18	900	UNKNOWN	UNKNOWN	5833 ARTEL	1	LF	B46P					REF LF;	1	0
FORCED INTERR	GP	RU 02	41654	K61E	5362214	220031130106	F	4/23/2003	1920	97	22	2134	VINES	VINES	214 ARNETT LN	1	LF	K61E	TF	536221447			REF LF REF TR.	1	0
FORCED INTERR	SL	SE 01	2429F	94JG	3560035	120031130122	F	4/23/2003	1940	105	1	105	SQUIRREL	SQUIRREL	1919 GRUBBS	1	LF	94JG	TF	356003586			REFUSED L.F AND TF CAUSE SQUIRREL, REF LF REF TR.	1	0
FORCED INTERR	FB	WA 43	12843	87GB		120031130124	F	4/23/2003	2013	71	5	355	TREE CLEARANC	TREE CLEAF	13306 B J DUSE	1	LF	98H					REFUSED 98 H RM TREE LIMB BACK ON AT 2100 STARTING FROM 4 SPANS WEST TOO 8 SPANS NEEDS TREE TRIMMING PER JAMES FOJTIK FOREMAN. REF LF RMVD TREE/LIMB OFF PR MSI	1	0
FORCED INTERR	GP	THW4	2F153		4865731	220031130113	T	4/23/2003	2122	103	1	103	UNKNOWN	UNKNOWN	12571 MILLVAN		PR	486573178					REPL LIMITER EQUIPMENT FAILURE - FUSE NOT BLOWN. RPLD LIMITER @ TR.	1	0
FORCED INTERR	SU	HY 12	11710	J13M	4856641	120031130128	F	4/23/2003	2228	0	0	0	SPLICE	SPLICE	11854 WESTME	2	LF	J13M	PR				HAVE BAD PRI JUST BE LOW TERMINATOR OF T/P J13M Y FEED @ 11858 BRIAR FOREST AND Y PRI IS ON STAND OFF IN TRANS @ 11855 BRIAR FOREST SO# 8184 ISOL URD PR URD S/O#816	1	0
FORCED INTERR	SU	HY 12				120031130128	F	4/23/2003	2225	182	48	8736	SPLICE			2	LF	J13M						0	0
FORCED INTERR	FB	RE 05	11353	69DB	4449350	120031130129	F	4/23/2003	2320	48	16	768	TREE CLEARANC	TREE CLEAF	1809 GEORGE	1	LF	69DB	PR				CUT TREE PICKED UP #4 PRI AT 1809 GEORGE REFUSED 69 DB, REF LF, RMVD TREE/LIMB OFF PR. BRS	1	0
FORCED INTERR	GP	WF 42	20341	40QL	5267620	220031130117	T	4/23/2003	2334	236	7	1652	CUST EQP RELAT	CUST RLTD	433 NORTHPAR	1	TF	526762007					CUT OUT-MTR LOOP DAMAGE-LEFT MTR CUT OUT AT POLE PRI MTR MTR 815642736 LEFT ON MTR W71474627 LEFT OFF DROPS DAMAGED REF TR	1	0
FORCED INTERR	BL	UL 49	14063	49X	5156307	120031130130	T	4/23/2003	2336	85	16	1360	BU DISC OR BARI	DISC/BARRL	5701 SCHUMAC	1	TF	515630738					RPLD B/U BARREL ON TR.	1	0
FORCED INTERR	MP	WO 01	41822		52598431	220031140001	T	4/24/2003	0001	65	7	455	FLLNG TREE IN E	TREE FL/IE	907 W 30TH		TF	525984318					REF TR.	1	0
FORCED INTERR	CH	SW 05	41678	E83Y	5562637	320031140002	F	4/24/2003	0028	0	0	0	SPLICE	SPLICE	6303 LEEDALE	2	LF	E83Y	PR				SO # 5185 STOOD (Y) PRIMARY OFF IN XFMR #3 STOOD (X) PRIMARY OFF IN XFMR #4 HAVE A BAD SPAN OF DIRECT BURY URD PRIMARY BETWEEN #3 & #4 FAULT ABOUT 5-10 FT FROM X	1	0
FORCED INTERR	CH	SW 05				320031140002	F	4/24/2003	0028	187	12	2244	SPLICE			2	LF	E83Y						0	0
FORCED INTERR	CH	SW 05				320031140002	F	4/24/2003	0028	191	44	8404	SPLICE			2	LF	E83Y						0	0
FORCED INTERR	HC	AM 06	10753	67H	5252912	120031140001	T	4/24/2003	0330	84	10	840	OTHER WILDLIFE	OTHER WLD	2830 TIDEWATE	1	TF	525291292					REFUSE 50KVA TF NEED TREE TRIMMING ASAP ASAP ASAP REF TR. SENT MSG TO T&D BRS	1	0
FORCED INTERR	GP	SA 50	21278	E85Z	49628271	220031140002	F	4/24/2003	0627	299	16	4784	UNKNOWN	UNKNOWN	7163 WHITE OA	2	LF	E85Z	BU	496282711	PR		REPLACEDBAD 7200KV ,50 KVA URD TRANS/120/240 WITH SAME INSTALLED ELBOWS REF TP RPLD B/U TR, RPLD ELBOW @ TR.	1	0
FORCED INTERR	BZ	LJ 09	3521E	22PH	5429808	320031140004	F	4/24/2003	0734	119	1	119	STRONG WIND	WIND	10002 FM 523 (E	1	LF	22PH					REFUSED LF 22-PH 15-T., REF LF CORRECTED 2HR/CRH 04-28-03	1	0
FORCED INTERR.	CH	OA 05	41602	43SM	5758130	320031140005	L	4/24/2003	0736	74	1	74	TREE CLEARANC	TREE CLEAF	10726 DUNVEG	1	SC						CUT TREE FROM SECONDARYS. RPLD CONN @ PL.	1	0
FORCED INTERR	MP	CR 03	40529	Y89K	5359313	220031140007	T	4/24/2003	0742	40	11	440	SQUIRREL	SQUIRREL	1619 ARLINGTO	1	TF	535931377					REFUSED TRNS / LEFT SERV ON. REF TR.	1	0
FORCED INTERR	SH	SP 08	31000	P31U	5852227	320031140007	T	4/24/2003	0752	38	9	342	SQUIRREL	SQUIRREL	5000 ALLEN GE	1	TF	585222788					TRK #484 — NEED W.L.P @ REAR #44 —EASEMENT@ REFUSED TRX -SQUIRREL- REF TR (MSG SENT - BEV OA)	1	0
FORCED INTERR	MP	GG 06	30543	S40W	5554335	220031140006	T	4/24/2003	0800	162	1	162	UNKNOWN	UNKNOWN	5567 MAUDLIN	1	TF	555433580					NEED TO STRAIGHTEN POLE FEED 5567 MAUDLIN REF TR.	1	0
FORCED INTERR	SB	WT 06	21830	K79S	5158613	120031140006	T	4/24/2003	0813	63	2	126	VINES	VINES	9030 SANDRING	1	TF	515861376					REFUSED TRANS BACK ON VINES REF TR.	1	0
FORCED INTERR	BA	LP 03	41750	W12J	6153627	320031140006	T	4/24/2003	0816	61	1	61	BU DISC OR BARI	DISC/BARRL	11426 FAIRMON	1	TF	615362771					CUSTOMER WOULD LIKE TO SCHEDULE OUTAGE TO CHECK ALL CONN ON TRANS BANK. RPLD B/U BARREL ON TR	1	0
FORCED INTERR	MP	HE 02	41107	NP7	5359015	220031140010	T	4/24/2003	0822	22	13	286	SQUIRREL	SQUIRREL	518 W 17TH	1	TF	535901526					REFUSED TRNS LOC IN REAR OF 518 W 17TH / LEFT SERV ON. REF TR.	1	0

FORCED INTERR	KY	KT 43	22624	34GN		12003114002	F	4/24/2003	0846	36	1	36	LIGHTNING	LIGHTNING	35103	KATY FW	1	LF	34GN									1	0
FORCED INTERR	FB	WC 01	1290A	M290	48334000	12003114001	T	4/24/2003	0847	116	2	232	UNKNOWN	UNKNOWN	30236	PLANTAT	1	BU	483340067									1	0
FORCED INTERR	HC	FD 03	10845		51531451	12003114001	T	4/24/2003	0847	72	9	648	FLLNG TREE IN E	TREE FLIE	5815	QUEENSLE		TF	515314518									1	1
FORCED INTERR	SL	RB 02				12003114001	C	4/24/2003	0850	137	157	21509	STRONG WIND	WIND		FM 331,5 SPANS		CL	RB02	PR								1	0
FORCED INTERR	BA	HL 01	41152	WZ1D	62588597	32003114001	T	4/24/2003	0800	105	7	735	CONTRACTOR-N	CON-NT HLF	5130	PARSLEY I	2	TF	625885926									1	0
FORCED INTERR	BZ	LJ 07	30921	C54J	54271143	32003114001	T	4/24/2003	0925	45	4	180	BU DISC OR BARI	DISC/BARRL	1501	KYLE	1	TF	542711434									1	0
FORCED INTERR	CY	HK 04	21137	D9A		12003114001	E	4/24/2003	0925	183	73	13359	LIGHTNING	LIGHTNING	MOUND, W OF	1	1	LF	35KD	LF	D9A							1	0
FORCED INTERR	CY	WL 02	2C128			12003114007	C	4/24/2003	0927	0	0	0	BU DISC OR BARI	DISC/C93D	MULBERRY & P			PC	WL02	DB	C93D							1	0
FORCED INTERR	CY	WL 02	2C128			12003114007	C	4/24/2003	0927	80	271	21680	BU DISC OR BARI					PC	WL02									1	0
FORCED INTERR	SL	SE 01	28766	WI60	33588197	12003114002	T	4/24/2003	0937	81	2	162	LIGHTNING	LIGHTNING	3602	QUAIL CIR	1	TF	335881972									1	0
FORCED INTERR	SL	SE 04	22472	13ACY		12003114005	F	4/24/2003	0938	62	1	62	LIGHTNING	LIGHTNING	2391	PYKA	1	LF	13ACY	TF	325771966							1	0
FORCED INTERR	CY	TB 45	21046	36DF	46690534	12003114002	S	4/24/2003	0941	69	18	1242	LIGHTNING	LIGHTNING	19812	CYPRESS	1	LF	36DF									1	0
FORCED INTERR	SL	SE 01	22477	A57F	35583288	12003114002	F	4/24/2003	0944	88	15	1320	LIGHTNING	LIGHTNING	4431	KURTZ RD	1	LF	A57F									1	0
FORCED INTERR	CY	HK 06	21121	76PS	42700525	12003114002	E	4/24/2003	0944	79	8	474	LIGHTNING	LIGHTNING	27509	WALLER	1	LF	76PS									1	0
FORCED INTERR	CY	TB 44	22549	S2594	47724300	12003114002	T	4/24/2003	0947	24	2	48	LIGHTNING	LIGHTNING	31103	QUINN RI	1	TF	477243036									1	0
FORCED INTERR	CY	HK 05	2A110	C58V	41720061	12003114002	E	4/24/2003	0947	107	5	535	LIGHTNING	LIGHTNING	BINFORD @ CA	1		LF	C58V									1	0
FORCED INTERR	CY	HK 05	2329C	C50U	41716361	12003114003	C	4/24/2003	0948	80	2	160	LIGHTNING	LIGHTNING	28310	MARGER:	1	LF	C50U									1	0
FORCED INTERR	CY	KL 45	21950		47654270	12003114003	T	4/24/2003	0950	50	2	100	TREE CLEARANC	TREE CLEAI	12227	OLD HUFI	1	TF	478542705									1	0
FORCED INTERR	CY	WL 42	21162	S2482	39694587	12003114003	F	4/24/2003	0954	119	40	4760	LIGHTNING	LIGHTNING	42422	HEMPSTE	1	LF	S2482	PR			TF	3981				1	0
FORCED INTERR	CY	TB 02	20805	B10P	47715145	12003114003	E	4/24/2003	0957	53	21	1113	LIGHTNING	LIGHTNING	911	BARBARA S	1	LF	98DR	LF	B10P							1	0
FORCED INTERR	SL	SE 41	1D162	44ABS	37560381	12003114003	F	4/24/2003	1000	63	28	1764	LIGHTNING	LIGHTNING	1511	SAHA	1	LF	44ABS									1	0
FORCED INTERR.	BA	AT 41	20007	M21M	59678208	32003114002	F	4/24/2003	1000	88	21	1848	COLLISION	COLLISION	1919	BLACK BEA	1	LF	M21M	SC								1	0
FORCED INTERR.	SL	SE 41	1C162	62AAU	36577123	12003114003	T	4/24/2003	1010	94	1	94	LIGHTNING	LIGHTNING	11748	MLCAK RI	1	TF	365771291									1	0
FORCED INTERR	HM	RA 44	20429	63PL	51729958	22003114003	E	4/24/2003	1010	36	1	36	LIGHTNING	LIGHTNING	RAYFORD @ SF	1		LF	63PL									1	0
FORCED INTERR	HM	RA 42	28113	T73U	52718586	22003114004	F	4/24/2003	1015	69	10	690	LIGHTNING	LIGHTNING	1623	RILEY FUZ	1	LF	T73U									1	0
FORCED INTERR	SL	SE 04	22472	30CR	33561536	12003114003	T	4/24/2003	1018	63	1	63	LIGHTNING	LIGHTNING	1702	PYKA	1	TF	335615309									1	0
FORCED INTERR	SB	SA 47	21225	N92U	47627437	22003114004	T	4/24/2003	1011	133	7	931	TREE CLEARANC	TREE CLEAI	7723	VIRGINIA V	2	PR	476274306									1	0
FORCED INTERR	HM	LW 44	20853	13SK	56686155	22003114004	T	4/24/2003	1024	136	1	136	LIGHTNING	LIGHTNING	1029	ATASCOCI	1	TF	566661527									1	1
FORCED INTERR	CY	SA 45				22003114005	C	4/24/2003	1030	0	0	0	O/H PRIMARY CU	OH PR CLMF	12202	PADDOC		CL	SA45									0	0
FORCED INTERR	CY	SA 45	20997			22003114005	C	4/24/2003	1030	28	1275	35700	O/H PRIMARY CU					CL	SA45									0	0
FORCED INTERR	CY	SA 45	2G246			22003114005	C	4/24/2003	1030	41	2542	104222	O/H PRIMARY CU					CL	SA45									0	0
FORCED INTERR	CY	SA 45	21348			22003114005	C	4/24/2003	1030	111	467	51837	O/H PRIMARY CU					CL	SA45									0	0
FORCED INTERR.	SB	BM 03	21485	C40L	48599956	12003114004	F	4/24/2003	1031	29	77	2233	LIGHTNING	LIGHTNING	1726	WYCLIFFE	1	LF	C40L									1	0
FORCED INTERR	FB	RS 02	11386	SJL	43484646	12003114004	T	4/24/2003	1033	63	32	2016	SQUIRREL	SQUIRREL	816	8TH	1	TF	434884661									1	0
FORCED INTERR	FB	WR 11	12698	R45S	33380584	12003114004	T	4/24/2003	1034	100	1	100	UNKNOWN	UNKNOWN	11345	FM 102	1	TF	333805846									1	0
FORCED INTERR	CY	TB 45	21043	S31P	47703434	22003114005	T	4/24/2003	1034	51	8	408	LIGHTNING	LIGHTNING	ALICE BTWN	H	1	LF	S31P									1	0
FORCED INTERR	CY	PI 44	21031	99RD	47730288	22003114005	F	4/24/2003	1034	42	1	42	LIGHTNING	LIGHTNING	25432	HARDIN S	1	LF	99RD									1	0
FORCED INTERR	CY	TB 03	21004	ZC8	47728168	22003114005	A	4/24/2003	1034	70	1	70	LIGHTNING	LIGHTNING	615	E HUFSMITI	1	TF	477281601									1	0
FORCED INTERR	KY	KT 02	22566		43580211	12003114004	E	4/24/2003	1037	41	2	82	LIGHTNING	LIGHTNING	1113	AVENUE A		TF	435802102									1	0
FORCED INTERR	GP	DH 07	23978	D49B	50628016	22003114006	F	4/24/2003	1042	25	40	1000	LIGHTNING	LIGHTNING	8810	ARBOR WI	2	LF	D49B									1	0
FORCED INTERR	HM	LW 43	20405	S3286	55641277	22003114007	T	4/24/2003	1052	129	3	387	CONTRACTOR-N	CON-NT HLF	4930	MC DERMI	2	TF	556412725									1	0
FORCED INTERR	GP	NB 41	22366	52DR	53656271	22003114007	E	4/24/2003	1059	55	34	1870	LIGHTNING	LIGHTNING	15728	DOWLWI	1	LF	52DR									1	0
FORCED INTERR	SH	CC 01	30174		54525398	32003114002	T	4/24/2003	1100	40	1	40	UNKNOWN	UNKNOWN	5021	SOUTH AC		TF	545253609									1	0
FORCED INTERR	GP	AD 01	20388	B83A	53645014	22003114007	E	4/24/2003	1100	31	24	744	TREE CLEARANC	TREE CLEAI	14701	HENRY	1	LF	B83A									1	0
FORCED INTERR	BA	AT 41	20007	M10M	60673221	32003114002	E	4/24/2003	1100	221	4	884	UNKNOWN	UNKNOWN	514	ELK	1	BU	606732218									1	0
FORCED INTERR	CY	HK 04	21137	D8C	41668285	22003114008	F	4/24/2003	1100	85	13	1105	STRONG WIND	WIND	27949	MOUND	1	LF	D8C	PR								1	0
FORCED INTERR	CY	HK 06	21121	78PS	41709348	22003114008	F	4/24/2003	1100	12	2	24	LIGHTNING	LIGHTNING	27807	WALLER	1	LF	78PS									1	0
FORCED INTERR	SH	CA 02	30161	B90T	59544016	32003114002	S	4/24/2003	1100	0	0	0	SQUIRREL	SQUIRREL	2734	BEVERLY	2	LF	B90T	PR								1	0
FORCED INTERR	SH	CA 02				32003114002	F	4/24/2003	1100	81	20	1620	SQUIRREL				2	LF	B90T									1	0
FORCED INTERR	BL	UL 45	14001	84G	51560511	12003114005	T	4/24/2003	1110	40	4	160	LIGHTNING	LIGHTNING	6201	DEL MONT	1	TF	515605111									1	0
FORCED INTERR	SB	ADK42	21306		50611122	12003114008	T	4/24/2003	1111	42	2	84	LIGHTNING	LIGHTNING	13610	HEMPSTE		TF	508111231									1	0
FORCED INTERR	SH	DR 09	30304	71ACL	55539908	32003114003	T	4/24/2003	1111	59	1	59	UNKNOWN	UNKNOWN	7330	NEUHAUS	1	TF	555390600									1	0
FORCED INTERR	BA	HL 04	47600	B41D	62586533	32003114003	L	4/24/2003	1121	57	1	57	OH SEC/DR CL H	OH SC CL-H	5409	LILLIAN ST	1	SC										1	0
FORCED INTERR	SL	SE 41	1D162	32AAW	36579071	12003114006	F	4/24/2003	1123	18	6	108	LIGHTNING	LIGHTNING	1023	SAHA (167	1	LF	32AAW									1	0
FORCED INTERR	CY	PI 45	2A126	54ACP	44750085	22003114009	T	4/24/2003	1140	38	1	38	LIGHTNING	LIGHTNING	20802	TIMBER R	1	TF	447500858									1	0
FORCED INTERR	GP	LK 06	21880	K81L	52623216	22003114009	F	4/24/2003	1155	52	1	52	SQUIRREL	SQUIRREL	ESTHER E OF	V	1	LF	K81L									1	0
FORCED INTERR	GP	DH 07	23976	T95T	50628325	22003114009	E	4/24/2003	1158	53	7	371	LIGHTNING	LIGHTNING	9634	HEARTHW	1	LF	T95T									1	0
FORCED INTERR	GP	LK 07	41298	LH4	52626252	22003114009	T	4/24/2003	1200	45	1	45	LIGHTNING	LIGHTNING	8022	DE PRIEST	1	TF	526262524									1	0
FORCED INTERR	BA	BT 01	40098		63565332	32003114003	E	4/24/2003	1215	22	4	88	SQUIRREL	SQUIRREL	606	W NAZRO S		TF	635653222									1	0
FORCED INTERR	FB	BV 42	12781	12GB	45500559	12003114007	F	4/24/2003	1220	80	7	420	VINES	VINES	1121	FM 359	1	LF	12GB	PR								1	0
FORCED INTERR	CY	TB 44	22549	S2594	47724312	22003114010	E	4/24/2003	1220	144	1	144	LIGHTNING	LIGHTNING	31104	QUINN RI	1	BU	477243125									1	0
FORCED INTERR	HM	AD 07	40081		54631303	22003114010	T	4/24/2003	1230	43	1	43	SQUIRREL	SQUIRREL	1710	ALDINE MA		TF	546313025									1	0
FORCED INTERR	SH	SB 03	31038	R9Z	58559418	32003114003	E	4/24/2003	1230	59	6	354	BU DISC OR BARI	DISC/BARRL	3124	BOND	1	TF	585594164									1	0
FORCED INTERR	CY	PI 45	2445K	70FG	43716420	22003114010	T	4/24/2003	1241	53	1	53	LIGHTNING	LIGHTNING	23426	BRUSHY I	1	TF	437164206									1	0
FORCED INTERR	BL	UL 09	10318	P92T	51561385	12003114007	E	4/24/2003	1245	51	1	51	SQUIRREL	SQUIRREL	2620	FOUNTAIN	3	LF	P92T									1	0
FORCED INTERR	HM	AT 42	22323	G97E	60684472	22003114010	T	4/24/2003	1248	126	3	378	OH SEC/DR CL H	OH SC CL-H	23402	FM 2100 F	1	SC	606844773									1	0
FORCED INTERR	GP	LK 04	21674	M54T	52621584	22003114011	E	4/24/2003	1321	119	37	4403	SPLICE	SPLICE	2215	WINTER BL	2	LF	M54T	PR								1	0
FORCED INTERR	GP	KI 43	21925	S59Y	49684008	22003114011	F	4/24/2003	1322	119	40	4760	LIGHTNING	LIGHTNING	17110	PARK LOI	2	LF	S59Y									1	0
FORCED INTERR	BL	DV 11	21724	75KM	50565595	12003114008	E	4/24/2003	1323	45	1	45	HUMAN ERROR	HUMAN ERRC	201	KINKAID SC	3	LF	75KM									1	0
FORCED INTERR	SH	GV 04	30529		54529547	32003114008	T	4/24/2003	1330	92	7	644	O/H PRIMARY CU	OH PR CLMF	5765	PEACOCK		PR	545295471									1	0
FORCED INTERR	GP	KI 43	22077	S2528	48689198	22003114011	F	4/24/2003	1330	65	31	2015	LIGHTNING	LIGHTNING	9730	DALMALLY	2	LF	S2528									1	0
FORCED INTERR	CY	WL 42	24869	C84	39708591	22003114011	L	4/24/2003	1338	91	1	91	OH SEC/DR CL H	OH SC CL-H	33438	OWENS	1	DR										1	0
FORCED INTERR	BA	BT 01	40080	K9L	63562471	32003114004	E	4/24/2003	1351	49	1	49	OH SEC/DR CL N	OH SC CL-N	1517	LINDBERG	1	DR										1	0
FORCED INTERR	CY	KL 41	21977	65BB	47876020	22003114011	E	4/24/2003	1354	76	14	1064	TREE CLEARANC	TREE CLEAI	13107	LEMUR	1	LF	65BB	TF	476760262							1	0
FORCED INTERR	HM	TWG4	2451F	T60U	53701140	22003114011	E	4/24/2003	1400	194	57	11058	URD ELBOW	URD ELBOW	2022	AZURE CR	2	LF	T60U	PR	537011466							1	0
FORCED INTERR	SH	CG 02	30210	JE6	57533043	32003114004	E	4/24/2003	1415	38	1	38	TREE CLEARANC	TREE CLEAI	839	GLOBE	1	SC										1	0
FORCED INTERR	BL	SF 42	10390	K37T	51574085	12003114009	T	4/24/2003	1427	48	8	384	LIGHTNING	LIGHTNING	5566	CEDAR CR	1	TF	515740858									1	0
FORCED INTERR	MP	WO 03	41838	A91N	52603578	22003114012	F	4/24/2003	1427	48	23	1104	UNKNOWN	UNKNOWN	OAK FOREST,	N	1	LF	A91N									1	0
FORCED INTERR	SU	RO 42	12827		49536218	12003114009	E	4/24/2003	1437	66	1	66	UNKNOWN	UNKNOWN	10531	SOUTHW		DR										1	0
FORCED INTERR	CY	PI 41	2B120	S1866	43759346	22003114012	T	4/24/2003	1520	72	1	72	SQUIRREL	SQUIRREL	501	ABNEY LN	1	TF	437593468									1	0
FORCED INTERR	SL	SE 41	22732	47UP	35564098	12003114010	F	4/24/2003	1522	119	1	119	LIGHTNING	LIGHTNING	822	STOCKHOU	1	LF	47UP									1	0
FORCED INTERR	BL	JN 07	10022		50551030	12003114010	E	4/24/2003	1535	74	6	444	BU DISC OR BARI	DISC/BARRL	8250	BELLAIRE		TF	505510367									1	0
FORCED INTERR	BA	CS 03	40581	B81B	61605408	32003114005	T	4/24/2003	1530	23	10	230	UNKNOWN	UNKNOWN	708	OAK	1	TF	618054095									1	0
FORCED INTERR	SB	WT 07	21708	GH2	50587512	12003114010	E	4/24/2003	1540	78	6	468	LIGHTNING	LIGHTNING	8714	WESTVIEW	1	TF	505875124									1	0
FORCED INTERR	SL	SE 41	1C162	61AAU	36563516	12003114011	F	4/24/2003	1608	52	2	104	LIGHTNING	LIGHTNING	1500	FM 1458 (E	1	LF	61AAU									1	0
FORCED INTERR	MP	HG 04	41331	88QT	56551235	22003114013	C	4/24/2003	1613	111	1	111	OTHER	OTHER	7730	ARBERRY	1	DR										1	0
FORCED INTERR	GP	KDL41	20423	64LW	49719598	22003114013	T	4/24/2003	1635	91	9	819	TRANSFORMER	TRANSFRM	8611	BARRONT	2	BU	497195963									1	0
FORCED INTERR	CH	GP 06	40815	N23K	56566511	22003114013	T	4/24/2003	1640	209	13	2717	OH SEC/DR CL H	OH SC CL-H	141	OWENS	1	SC	565865174	SC			DR					1	0
FORCED INTERR	SB	GE 41	21191	27DP	46617006	12003114012	E	4/24/2003	1646	99	2	198	BU DISC OR BARI	DISC/BARRL	17560	KEITH HA	1	LF	27DP									1	0
FORCED INTERR	SL	SE 02	22481		35575268	12003114012	T	4/24/2003	1655	178	2	356	LIGHTNING	LIGHTNING	1313	HIGHWAY		PR	355752688	DB								1	0
FORCED INTERR	SB	SR 01	20745	42T	49577431	12003114012	F	4/24/2003	1655	137	25	3425	ROTTEN POLE	ROTTEN PLI	12307	HUNTING	1	LF	42T	PD								1	0
FORCED INTERR	HC	FD 03	10842	9HU	50539325	12003114012	T	4/24/2003	1654	68	15	1020	HUMAN ERROR	HUMN ERRC	6107	WIGTON	1	TF	505363207									1	0
FORCED INTERR	SH	DR 07	30293	P4R	56540224	22003114014	T	4/24/2003	1711	32	9	288	SQUIRREL	SQUIRREL	7654	EL RANCH	1	TF	565402450									1	0
FORCED INTERR	SB	BM 04	21493	B66P	48577570	12003114012	L	4/24/2003	1736	103	1	103	OH SEC/DR CL H	OH SC CL-H	13727	CAMARA	1	DR										1	0
FORCED INTERR	SL	SE 41	22763	55UP	34559315	12003114013	T	4/24/2003	1750	153	1	153	LIGHTNING	LIGHTNING	1386	HARRISON	1	TF	345593156									1	0
FORCED INTERR	CH	BE 01	40216	P3G	55604423	32003114006	E	4/24/2003	1750	63	1	63	UNKNOWN	UNKNOWN	6715	WEAVER	1	SC										1	0
FORCED INTERR	CY	TB 03	21004	ZC8	47728168	22003114014	E	4/24/2003	1815	230	1	230	LIGHTNING	LIGHTNING	615	E HUFSMITI	1	BU	477281601									1	0
FORCED INTERR	BL	BI 02	10053	5A5	51569356	12003114013	T	4/24/2003	1822	58	10	580	UNKNOWN	UNKNOWN	3100	KETTERIN	1	TF	515693564									1	0
FORCED INTERR	CY	CYF41	24963	Y98W	47630284	22003114014	F	4/24/2003	1825	213	115	24495	URD BUSHING	URD BSHING	8636	PLUM LAKI	2	LF	Y98W	PR								1	0
FORCED INTERR	FB	OR 03	11307	4NN	39480523	12003114013	F	4/24/2003	1830	1	18	18	O/H PRIMARY CU	OH PR CLMF	2507	FM 1952	1	PR	A38									1	0
FORCED INTERR	SH	UW 03	31107	B87J	60552268	32003114006	T	4/24/2003	1841	69	8	552	SQUIRREL	SQUIRREL	1206	E 13TH	1	TF	605522603									1	0
FORCED INTERR	CY	KL 43	21983	27DR	46658584	22003114015	F	4/24/2003	1854	255	21	5355	LIGHTNING	LIGHTNING	12806	W CYPRE	1	LF	27DR	TF	466585641	PR						1	0
FORCED INTERR	CH	CV 06	40456	59GU	58582556	32003114007	T	4/24/2003	1900	77	7	539	OH SEC/DR CL H	OH SC CL-H	13210	HALIFAX	1	SC	585825564									1	0
FORCED INTERR	HM	KW 42	22384	91JB	58710088	22003114015	F	4/24/2003	1915	137	84	11508	URD BUSHING	URD BSHING	3634	MILL BRIDG	2	LF	91JB	PR	587110066							1	0
FORCED INTERR	SU	CE 04	11964		48536195	12003114014	T	4/24/2003	1938	54	4	216	UNKNOWN	UNKNOWN	12322	JAGUAR	1	TF	485361987									1	0
FORCED INTERR	FB	RE 08	12774	37HH	44498059	12003114014	F	4/24/2003	1940	60	13	780	UNKNOWN	UNKNOWN	GOLFVIEW,	BTV	1	LF	37HH									1	0
FORCED INTERR	GP	LK 04	21675	J25Z	52632054	22003114015	F	4/24/2003	2011	0	0	0	UNKNOWN	UNKNOWN	2111	MOSHER L	2	LF	J25Z	PR								1	0
FORCED INTERR	GP	LK 04				22003114015	F	4/24/2003	2011	193	15	2895	UNKNOWN				2	LF	J25Z									1	0
FORCED INTERR	GP	LK 04				22003114015	F	4/24/2003	2011	193	8	1544	UNKNOWN				2	LF	J25Z									1	0
FORCED INTERR	GP	LU 45	20602	R96D	51695552	12003114015	T	4/24/2003	2011	80	1	80	CONTRACTOR-N	CON-NT HLF	3104	1/2 LOUET	1	SC										1	0
FORCED INTERR	GP	LK 04	21874	40DR	52631022	22003114016	T	4/24/2003	2035	395	11	4345	UNKNOWN	UNKNOWN	10706	CORA #1	1	BU	526310230									1	0
FORCED INTERR	HC	HM 05	11032	71HU	54532277	12003114015	T	4/24/2003	2045	37	12	444	BU DISC OR BARI	DISC/BARRL	4422	LARKSPUF	1	TF	545322725									1	0
FORCED INTERR	SB	SA 46	22883	Y12W	48621415	12003114015	F	4/24/2003	2048	77	56	4312	LIGHTNING ARRE	LTNG ARRS	13115	VISTA OR	2	LF	Y12W									1	0
FORCED INTERR	SB	SR 13	21682	J30N	49576307	12003114015	F	4/24/2003	2051	74	27	1998	URD ELBOW	URD ELBOW	308	LITCHFIELD	2	PR	J30N									1	0
FORCED INTERR	CH	GW 01	40689	H66W	56612478	32003114004	F	4/24/2003	2055	98	13	1274	INSULATOR	INSULATOR	8419	BIGWOOD	2	LF	H66W	BU	566124898	PR						1	0
FORCED INTERR	MP	NS 01	41532	S96Z	54594085	22003114016	F	4/24/2003	2144	117	2	234	LIGHTNING ARRE	LTNG ARRS	1921	COLLINGS	1	LF	S96Z									1	0

[OUT ISSUED TO CORRECT CABE 812003114001201 - BEV OAI
REPL 25/25 KVA 7200 120/240 INSTALLED WQ. RPLD BAJ TR.
REFUSE TRAN BANK DUE CUST TRIMMING TREES. REF TR.
4 SPANS PRIMARY DOWN. JUST NORTH OF CU SWITCH AIR ALL CUST BEHIND SWIT CREWS ON SITE TO MAKE REPAIRS. EOT 1115. CREWS PIU 4 SPANS OF 84 PRIMARY AND RESTORED ALL
CITY OF BAYTOWN DIGGING MADE REPAIRS TO CUST URD DROPS @ 6129 PEPPER MILL REMOVED ANT FROM URD TR. REFUSED 75KV URD TR. REF TR.
REFUSED 25 CONV TRANS REF TR.
REF LF
CREW FOUND BU 8 PHASE DISCONNECT ON C93D SECTION 2370C NON 10 % CIRCUIT TROUBLE SWO 286 - SWITCHED CKT AROUND AND GOT ALL SVC RESTORED. TURNED OVER
refuse transf. REF TR.
ISSUED TO CORRECT CABE 120031140027 9
REF LF
REF LF
REF LF
REF TR.
REF LF
REF LF.
trimmed trees & rem vines off pole. REF TR.
PICKED UP 1 SPAN OF 8 4 PRIMARY, AND REFUSED A 10 KVA 7200 120/240 CONV TR. PIU PR-FUSE BLOWN. REF TR. CORRECTED 2HRJCRH 04-28-03
REFUSED 1 PHASE OF 9 10 F & 1PHASE OF 98DR. REF LF.
REF LF.
PICKED UP 1 SPAN OF 84 AL NEUTRAL AND REBAGED OVERHEAD GUY WIRE HIGH LOAD CAME THROUGH AND SNAGGED TELEPHONE DROP ALSO RAISED IT COMPUTER CRASHED TIME W
REFUSED 25KVA ON TRANS LEFT 121 121 242. REF TR.
REF LF
RODE OUT LINE AND REFUSED LINE FUSE. REF LF.
RE-FUSED A LIGHTER POT ... LIGHTNING. REF TR.
REPLACED LIMITER ON 50 KVA. RPLD LIMITER @ TR.
REF TR.
WEATHER IN AREA - NO REPORTS OF TBL - CREWS IN ROUTE TO CK OUT - TRK 6741 ALSO HELPING W/SWITCHING - FD DE SHOE BU ON DE POLE - NEED CREW - REC721348 - HON 1015 - 1
REFUSED LINE FUSE BACK ON WEATHER SINGLE PH LINE FUSE. REF LF.
FOUND LF WORKING REFUSED TR 816 8TH OUT BY SQUIRREL ON LOAD BREAK ARM TR ALREADY HAS WL PROT RAM LOAD BREAK ARM FROM DISC. REF TR.
REPL LIA. REF TR
REF LF
REF LF
REF TR.
REFUSED TRANS. REF TR.
REFUSED T P 4.7KOL REF TP.
HOUSE BEING DEMOLISHED CUT OUT METER # 28900770 IN TRANS READING L-R 84223 & 001 HAD TO REFUSE URD TRANS TRACK HOE

FORCED INTERR.	BL	KB 09	14177	T5Z	52566091	12003114015	T	4/24/2003	220	64	10	640	BU DISC OR BARI	DISC/BARRL	2914 SUNSET	1	TF	525660910				RPLD B/U BARREL ON TR;	1	0
FORCED INTERR	SB	WD 45	22028	T72Y	4658433	120031140157	T	4/24/2003	220	68	2	136	UNKNOWN	UNKNOWN	17220 PARK RO	1	TF	465843302				CHANGED OUT LIMITER ON500 TF AND GOT SERVICE ON; RPLD LIMITER @ TR; REF TR; BRS	1	0
FORCED INTERR	FB	RE 08	12774	77FT	4449807	12003114016	L	4/24/2003	225	54	1	54	OH SEC/DR CL H	OH SC CL-H	2203 N BELMON	1	DR					REPLACED CLAMPS AT THE WEATHERHEAD .BRS .	1	0
FORCED INTERR.	KY	FZ 41	22610	28CA	4457228	12003115000	F	4/25/2003	014	154	82	12628	URD ELBOW	URD ELBOW	814 LONG PRAI	2	LF	28CA	PR			RPRD URD PR; BRS	1	0
FORCED INTERR	BZ	VL 03	3511B	HJ2	5525645	32003115000	F	4/25/2003	014	275	8	2200	COLLISION	COLLISION	FM 523, N OF H	1	LF	HJ2	PD			REPLACED 45 C4 W/60 C4 FOR CLEARANCE 18 WHEELER HUNG CABLE VISION AND SNAPPED POLE; REF LF RPLD PL.	1	0
FORCED INTERR.	SL	SE 01	22477	B96	3557548	12003115000	F	4/25/2003	015	182	5	910	LIGHTNING ARRE	LTNG ARRS	1219 OLD SEAL	1	LF	B96				REF LF;	1	0
FORCED INTERR	MP	NS 01				22003115000	C	4/25/2003	061	0	0	0	LIGHTNING ARRE	LTNG ARRS	TP 6215 BLWN		CL	NS01				CKT LOCKED OUT ON TWO TRIPS , TRIED BRKR AND IT HELD , S&O CREW WENT TO CHECK OUT BRKR AND FD 3 PH L/A BLOWN ON NS01 TP 6215 , L/A IN THE CLEAR , TURNED OVER TO 3 P	1	1
FORCED INTERR	MP	NS 01	2G220			22003115000	C	4/25/2003	061	4	1158	4632	LIGHTNING ARRE				CL	NS01					0	0
FORCED INTERR.	MP	NS 02	2G220			22003115000	C	4/25/2003	061	4	1256	5024	LIGHTNING ARRE				CL	NS01					0	0
FORCED INTERR	SU	SIE41	10947	80CE	5047204	12003115000	F	4/25/2003	061	150	3	450	O/H PRIMARY CL	OH PR CLMF	4600 MC KEEVE	1	LF	80CE	PR		TF 504	ACTUAL ADDRESS IS 81 SENIOR DRIVE; REF LF RPLD LIMITER @ TR; REF TR;	1	0
FORCED INTERR	SU	HY 11	11692		4956657	12003115000	T	4/25/2003	071	36	4	144	VINES	VINES	1303 BRIARPAR		TF	495665727				cleared vines from & reinsed power it is open delta bank left voice msg.; REF TR;	1	0
FORCED INTERR	CY	PI 45	2445G	S2808	4572259	22003115001	F	4/25/2003	074	93	12	1116	LIGHTNING ARRE	LTNG ARRS	15935 BUTERA	1	LF	61TN				REPLACE LIGHTNING ARRESTOR ON 2540/7200 TRANSFORMER IN REAR OF LEAD ADDRESS, REFUSE L F 61TN 20T LOCATED AT LEAD ADDRESS ALSO INSTALLED WLP REF LF, RPLD LIGHT	1	0
FORCED INTERR	GP	BA 46	2A141	S77F	4966853	22003115001	L	4/25/2003	080	106	1	106	OH SEC/DR CL H	OH SC CL-H	13911 JUPITER	2	SC					REPLACED BAD MOLD HEAD IN URD PEDESTAL/ SERVICE NOT TAKENED OFF WORKED HOT, RPRD SEC CONN @ PED-1 CUST	1	0
FORCED INTERR.	GA	MDY01	31358	R46N	6737107	32003115000	F	4/25/2003	080	116	39	4524	UNKNOWN	UNKNOWN	3411 DOMINIQU	1	LF	R46N	PR			PICKED UP 1 SPAN #4 CU. PRI. LEFT O.K. P/U PR-FUSE BLOWN.	1	0
FORCED INTERR.	MP	MP 02	41355	30QT	5456858	22003115001	T	4/25/2003	080	71	16	1136	LIGHTNING ARRE	LTNG ARRS	4440 WALKER S	1	TF	545685831				1/0 ARR ON COMB IN EASEMENT 25 PW TR F= 50; REF TR; MAM	1	0
FORCED INTERR.	MP	BG 01	40240	50JV	5356914	22003115001	T	4/25/2003	082	55	1	55	TREE CLEARANC	TREE CLEA	2222 WHEELER	1	SC	535691453	DR		DR	MADE REPAIRS TO SEC & REROUTED DROPS / LEFT SERV ON / NOTIFIED, RPRD SEC CONN @ PL->1 CUST; RPRD DR; RPLD CONN @ WH; REROUTED DR; RPLD POA	1	0
FORCED INTERR.	MP	GG 07	31349	E2W	5654138	22003115001	T	4/25/2003	083	65	7	455	BU DISC OR BARI	DISC/BARRL	3827 COLGATE	1	TF	565413825				REPL. FUSE BARREL ON POWER POT,FUSE BROKE & DIDN'T CLEAR ENOUGH & CAUSE D BARREL TOBURN INTO; RPLD B/U BARREL ON TR.	1	0
FORCED INTERR.	GP	DH 06	21531	29CK	5162402	22003115002	F	4/25/2003	091	42	29	1218	SQUIRREL	SQUIRREL	4444 VICTORY #	2	LF	29CK				REF TP	1	0
FORCED INTERR	MP	UN 11	10975	53MF	5455526	22003115002	T	4/25/2003	091	112	5	560	VINES	VINES	4319 CHARLEST	1	TF	545552613				REFUSED 80 LIGHTER IN BANK WITH 28, REMOVED VINES & TRIMMED TREES; REF TR.	1	0
FORCED INTERR	BA	HL 06	41187	D66C	6180502	32003115001	F	4/25/2003	093	22	49	1078	SQUIRREL	SQUIRREL	617 S MAIN ST	1	LF	D66C				SQUIRREL ON TRANS AT 611 S. MAIN, BLEW LINE FUSE NO FOLLOW UP NEEDED; REF LF;	1	0
FORCED INTERR.	SB	ME 11	20934		4857346	12003115002	T	4/25/2003	094	57	3	171	UNKNOWN	UNKNOWN	14400 MEMORIA		TF	485734679				RPLD B/U BARREL ON TR;	1	0
FORCED INTERR	CH	NM 02	47001	N72K	5858059	32003115001	F	4/25/2003	095	60	20	1200	TREE CLEARANC	TREE CLEA	626 LA RIVIERA	2	LF	N72K				TREE NEEDS REMOVED FROM T/P # N 72 K 60 T @ 618 BIENVILLE @ S/C CONVENC; REF TP; MAM	1	0
FORCED INTERR	GA	GL 06	30491	1G5	6839803	32003115002	L	4/25/2003	0951	89	1	89	OH SEC/DR CL H	OH SC CL-H	1112 9TH ST	1	DR					REPL. CLAMPS AT WH OFF OF 3 LADDERS; RPLD CONN @ WH;	1	0
FORCED INTERR.	MP	HM 02	11014	HM7	5454541	22003115002	F	4/25/2003	095	48	27	1296	SQUIRREL	SQUIRREL	4525 BALKIN ST	1	LF	HM7				REF LF	1	0
FORCED INTERR	MP	HE 02	41106	PD5	5259918	22003115002	L	4/25/2003	100	31	1	31	OH SEC/DR CL H	OH SC CL-H	1505 DOROTHY	1	DR					REPLACED BAD CLAMPS @ WH -- LEFT SERV ON / NOTIFIED; RPLD CONN @ WH;	1	0
FORCED INTERR	SH	PA 09	30765	F21Y	5754332	32003115002	F	4/25/2003	102	12	12	144	SQUIRREL	SQUIRREL	ALLENDALE, E	1	LF	F21Y				REFUSED 3-PHASE LF -SQUIRREL @ PRI MTR'N EQUIP @ 5800 BLK ALLENDALE, REF LF	1	0
FORCED INTERR.	SB	GE 46	21186	S22K	4780148	12003115003	T	4/25/2003	104	341	5	1705	URD BUSHING	URD BSHIN	16311 MOARY F	2	BU	478014861				REPLACED 25 KVA 19.9 120/240 URD T/F RPLD B/U TR.	1	0
FORCED INTERR.	FB	WR 12	11748	J99F	38370381	12003115003	F	4/25/2003	104	87	28	2436	SQUIRREL	SQUIRREL	1102 S CANEY T	1	LF	J99F				REFUSED L/F---SQUIRREL --CAUSE---W/G WAS INSTALLED; REF LF	1	0
FORCED INTERR	GP	WF 02	20377	D47E	5368156	22003115003	F	4/25/2003	105	118	20	2360	UNKNOWN	UNKNOWN	2014 BRIARCRE	2	LF	D47E				21406 SILVER SWITCH RED COVER FELL OFF, REF TP	1	0
FORCED INTERR	FB	WA 43	12843	87GB	3950106	12003115003	T	4/25/2003	110	12	1	12	BU DISC OR BARI	DISC/BARRL	15404 FM 1489	1	TF	395010642				REPL.BURNED UP FUSE BARREL, RPLD B/U BARREL ON TR;	1	0
FORCED INTERR	CY	KL 43	21990	70HK		22003115003	F	4/25/2003	112	210	44	9240	ANTS	ANTS	13015 CRICKET	1	LF	70HK	SC	476514417		REF TP, RPLD CONN @ TR @ 12910 CRICKETT HOLLOW MAM	1	0
FORCED INTERR	BA	CD 02	40327	88PK	6358719	32003115003	L	4/25/2003	112	89	1	89	OH SEC/DR CL NI	OH SC CL-N	3600 1/2 N MAIN	1	DR					REPLACED NEUTRAL CONNECTION AT WH; RPLD CONN @ WH;	1	0
FORCED INTERR.	CH	NM 02	47001	N72K	5858059	32003115003	T	4/25/2003	112	504	20	10080	UNKNOWN	UNKNOWN	610 LA RIVIERA	2	BU	585805978				REPLACE 25LIVE FRONT TRAN WITH A 25 DEAD FRONT; RPLD B/U TR. NO SUBCASING--ABK	1	0
FORCED INTERR	MP	BG 02	40247	G56	5355958	22003115004	L	4/25/2003	114	168	1	168	OH SEC/DR CL NI	OH SC CL-N	2906 SOUTHMO	1	DR					MADE REPAIRS TO # 4 3/C TW DROPS , NEU RPRD DR.	1	0
FORCED INTERR	FB	CRB41	11633		4550005	12003115004	T	4/25/2003	114	125	1	125	VINES	VINES	1232 HIGHWAY		TF	455000506				REFUSED TR---VINES, REF TR;	1	0
FORCED INTERR	GP	TWG4	2388M	5SER	5366447	22003115004	T	4/25/2003	115	421	1	421	UNKNOWN	UNKNOWN	2000 FARRELL F	3	BU	536644786				REPLACED 2 BAD 19.9 KV 50KVA 277/480 TRANS. K-MATES LIGHTING ARRESTORS REFUSED LINE FUSE 64 FV-20T REF LF; RPLD B/U TR. RPLD LIMITER @ TR.	1	0
FORCED INTERR.	GP	LK 04	21874	40DR	5263102	22003115004	T	4/25/2003	115	190	11	2090	UNKNOWN	UNKNOWN	10706 CORA #	1	BU	526310230				change out 75kva 7200 120-240 volt trans with the same; RPLD B/U TR.	1	0
FORCED INTERR	FB	OB 42	11378		45505561	12003115004	T	4/25/2003	115	178	4	712	VINES	VINES	2539 COUNTRY		TF	455055615	PR			REFUSED TR.--- VINES REPAIRED PEDESTAL, RPLD LIMITER @ TR, REF TR.	1	0
FORCED INTERR	GP	THW4	2E135	S3166	4966246	22003115004	F	4/25/2003	115	75	16	1200	COLLISION	COLLISION	6103 ROEBOUR	2	LF	S3166				TRUCK HUNG CABLE T V KNOCKED LINE FUSE FEEDING STEP POT THAT FEED URD LOOP / CLOSED IN LEFT ON, REF TP	1	0
FORCED INTERR	HM	KW 44	21149	80QG	58686461	22003115005	F	4/25/2003	130	62	33	2046	LIGHTNING ARRE	LTNG ARRS	19719 WATER P	2	LF	80QG				REF TP; NO SUBCASING NEEDED_JRK	1	0
FORCED INTERR.	BL	DV 10	21721		5056455	12003115005	L	4/25/2003	131	77	1	77	CONTRACTOR-N	CON-NT HLF	18 W STILLFORI		DR					I LEFT THIS SERVICE CLOCKWISE ROTATION; RPLD CONN @ WH;	1	0
FORCED INTERR	HC	HOC0	11178	RM2	51519511	12003115005	T	4/25/2003	131	39	7	273	SQUIRREL	SQUIRREL	5302 W OREM	1	TF	515195112				GUARDED NOW BUT HE CSTILL GOT IN TO IT, REF TR.	1	0
FORCED INTERR	HM	TWG4	20229	79ADF		22003115007	F	4/25/2003	133	175	0	0	CONTRACTOR-N	CON-NT HLF	20618 FOXGLEN	2	LF	79ADF	PR			URD S/O 8171 DUG UP URD PRIMARY IN FRONT OF AND BETWEEN 7226 AND 7230 FOXBROOK ---ABK	1	0
FORCED INTERR	HC	SO 41	10832	74UA	5350905	32003115004	F	4/25/2003	1341	138	51	7038	BU DISC OR BARI	DISC/BARRL	3030 RIVER BIR	2	LF	74UA	DB			REPLACE BAD 19.9 DISCONNECT RPLD B/U DISC-TP BLOWN.	1	0
FORCED INTERR.	KY	FZ 45				12003115005	C	4/25/2003	134	3	932	2796	WORK TAG	WORK TAG	FZ45 CKT LOC		CL	FZ45				CREW HOLDING WORK TAG .. WORKING KINGSLAND BLVD @ PROVINCIAL BLVD ..SEE S/O 164 CREW SAID THEY HEARD SOMETHING IN THE DISTANCE, MAYBE FUSE BLOW ,REQUESTED	1	1
FORCED INTERR	KY	MAR4				12003115005	C	4/25/2003	134	3	1899	5697	WORK TAG	WORK TAG	FZ45 CKT LOC		CL	FZ45				CREW HOLDING WORK TAG .. WORKING KINGSLAND BLVD @ PROVINCIAL BLVD ..SEE S/O 164 CREW SAID THEY HEARD SOMETHING IN THE DISTANCE, MAYBE FUSE BLOW ,REQUESTED	0	0
FORCED INTERR	CH	PW 06	40928	J32H	5780005	32003115004	T	4/25/2003	134	61	4	244	BU DISC OR BARI	DISC/BARRL	5424 OATES	1	TF	578000593				RPLD B/U BARREL ON TR;	1	0
FORCED INTERR	KY	FZ 45				12003115007	C	4/25/2003	135	2	932	1864	WORK TAG	WORK TAG	FZ45 CKT LOC		CL	FZ45				CREW HOLDING WORK TAG.. ..WORKING @ KINGSLAND BLVD @ PROVINCIAL BLVD ...SEE S/O166 CREW REQUESTED WORK TAG AG'N AFTER 1ST LOCKOUT TO FINISH REMOVING ISOLAT	1	1
FORCED INTERR	KY	MAR4				12003115007	C	4/25/2003	135	2	1899	3798	WORK TAG	WORK TAG	FZ45 CKT LOC		CL	FZ45				CREW HOLDING WORK TAG.. ..WORKING @ KINGSLAND BLVD @ PROVINCIAL BLVD ...SEE S/O166..CREW REQUESTED WORK TAG AGAIN AFTER 1ST LOCKOUT TO FINISH REMOVING ISOLAT	0	0
FORCED INTERR.	SU	CE 05	11975	X71H	4853824	12003115006	T	4/25/2003	135	107	8	856	ANTS	ANTS	11734 PLUMBR	2	SC	485382496				Made repairs to bad neut conn in unit caused by ants Cust has damage to power strip & carpet burnt up. Also garage door opener & several lights not working see damage report, RPLD CONN @ TR.	1	0
FORCED INTERR.	SB	EC 03	21694	15EJ	50585131	12003115006	T	4/25/2003	135	285	2	530	OH SEC/DR CL H	OH SC CL-H	11117 BEINHOR	1	BU	505851310	SC			REPL. 50 CSP /50 CONV INST DISC & WLP REP./40 TRANSF LEADS; RPLD B/U TR RPLD CONN @ TR.	1	0
FORCED INTERR	SB	GE 47	21894	N65Y	4660005	12003115006	F	4/25/2003	135	0	0	0	URD BUSHING	URD BSHIN	18763 GLENBR	2	LF	N65Y	BU	48600056E		URD ORDER # 8194 REPLACED BAD 25 KVA NON-LOAD XMFR WITH A 50 KVA 19.9 120/240 DEAD - BREAK. XMFR TAKEN AND RETURNED TO SPB RPLD B/U TR.	1	0
FORCED INTERR	SB	GE 47				12003115006	F	4/25/2003	135	197	4	788	URD BUSHING			2	LF	N65Y					0	0
FORCED INTERR	SB	GE 47				12003115006	F	4/25/2003	135	197	12	2364	URD BUSHING			2	LF	N65Y					0	0
FORCED INTERR	SB	GE 47				12003115006	F	4/25/2003	135	338	4	1352	URD BUSHING			2	LF	N65Y					0	0
FORCED INTERR	GA	STW0	30696	E16E	6334823	32003115004	T	4/25/2003	140	37	6	222	LIGHTNING	LIGHTNING	16521 E BAYSID	1	BU	633482372				50CSP TF LEAKING SENT W/A REPORT ON 4/26/03 FOREMAN HUGHES WILL SEND CREW OUT MONDAY AM 4/28 TO REPLACE NO SVC OFF MTE	1	0
FORCED INTERR	BL	ST 11	12763	H13K	5155401	12003115007	L	4/25/2003	142	76	1	76	FLLNG TREE IN E	TREE FL/IE	5512 JESSAMIN	1	SC					REPLACED CLAMP AT POLE AND CLEARED TREE BRANCHES FROM SEC , RPLD SEC CONN @ PL-1 CUST	1	0
FORCED INTERR.	BZ	LJ 09	3521B	H71R	5427604	32003115004	F	4/25/2003	1421	64	3	192	INSULATOR	INSULATOR	3003 STRATTO	1	PR	H71R				P/UP PR-FUSE NOT BLOWN.	1	0
FORCED INTERR.	GP	DH 08	22191		5162031	22003115007	T	4/25/2003	1431	60	1	60	SQUIRREL	SQUIRREL	7625 ALABONS		TF	516203173				REFUSED TRANSFORMER TAKEN OUT BY SQUIRREL / TRANS ALREADY HAS W.L.P/CN48; REF TR.	1	0
FORCED INTERR	SH	SH 09	30931	49LT	5852021	32003115005	T	4/25/2003	143	98	1	98	UNKNOWN	UNKNOWN	8820 GALVEST	1	BU	585202132				REPLACE A 25 KVA POWER POT; RPLD B/U TR;	1	0
FORCED INTERR	GP	RU 01	41293	6T9	5261938	22003115007	F	4/25/2003	143	119	30	3570	FLLNG TREE OUT	TREE FL/OE	YALE N OF W S	1	LF	6T9	TF	526193866		REMOVED LARGE TREE FROM PRI. & SEC. REF LF, REF TR; REROUTED DR; CORRECTED 3HR/CRH 04-28-03	1	0
FORCED INTERR	KY	FZ 45	24830		4457941	12003115007	T	4/25/2003	143	22	1	22	LIGHTNING ARRE	LTNG ARRS	21669 KINGSLA		TF	445794176				NEED TO REPLACE L/A ON 277/480 VOLT BANK--METRO PARK & RIDE----ALSO REPL L/A ON STREET LIGHT TRF, REF TR, RPLD LIGHTNING ARRESTOR. MAM	1	0
FORCED INTERR	KY	FL 44				12003115008	C	4/25/2003	144	12	235	2820	WORK TAG	WORK TAG	HARLEM, S OF		CL	O843				10%---CREW GOT 8 PHASE PRI TOGETHER CLOSING ISOLATORS TEING 2 CIRCUIT S---CREW IN CLEAR, CLOSED BRKR ON TBL S/O#166---PROBLEM ON SECTION#22729---ALL CPE CREWS AR	1	1
FORCED INTERR	GP	LK 06	21879	T27	5163131	22003115007	F	4/25/2003	145	53	44	2332	UNKNOWN	UNKNOWN	6205 CHIPPEW	1	LF	T27				REF LF	1	0
FORCED INTERR	SU	WI 42	12879		4756704	12003115008	L	4/25/2003	150	82	1	82	OH SEC/DR CL H	OH SC CL-H	13510 SHADOW		SC					REPL BAD CLAMP AT PL.PLACE LK UP NO XCESS TO MTR OR BKR BOX LK UP INSIDE OLD AGE. RPLD SEC CONN @ PL-1 CUST	1	0
FORCED INTERR.	GP	LU 41	2B148	P11M	5167750	22003115008	T	4/25/2003	151	111	5	555	UNKNOWN	UNKNOWN	15518 SILVER R	1	TF	516775059				TLA	1	0
FORCED INTERR.	CY	PI 41	2A120	S42C	4377939	22003115008	F	4/25/2003	153	0	0	0	FALLING DEAD T	TR FL/DEAD	1821 KING RICH	1	LF	S42C	PR		SC	PICKED UP ONE SPAN # 2PRIMARY AND STATIC; P/U PR-FUSE BLOWN; REF LF, P/U PR NEUT.	1	0
FORCED INTERR	CY	PI 41				22003115008	F	4/25/2003	153	88	14	1232	FALLING DEAD T			1	LF	S42C					0	0
FORCED INTERR	CY	PI 41				22003115008	F	4/25/2003	153	156	32	4992	FALLING DEAD T			1	LF	S42C					0	0
FORCED INTERR	KY	FZ 44	24804	B96P	4558249	12003115008	F	4/25/2003	154	68	128	8704	TREE CLEARANC	TREE CLEA	2000 WESTBOR	2	LF	B96P				TRIMMED TREES OUT OF TERMINAL POLE REF TP	1	0
FORCED INTERR.	BZ	FP 02	30415	B83D	5522504	32003115006	F	4/25/2003	154	117	18	2106	INSULATOR	INSULATOR	2546 DEEP SEA	1	LF	B83D	PR			REF LF, P/U PR-FUSE BLOWN;	1	0
FORCED INTERR	SH	CA 06	30247	U29O	5953607	32003115006	F	4/25/2003	154	116	51	5916	ANTS	ANTS	4222 HEATHFIE	2	LF	U29O				REPLACED ELBOW 4310 HEATHFIELD X PRI, REF TP	1	0
FORCED INTERR	SH	PE 04	30815	E42B	5548216	32003115007	T	4/25/2003	155	37	4	148	SQUIRREL	SQUIRREL	3614 BLUEBIRD	1	TF	554821652				REFUSE TRANSF, REF TR.	1	0
FORCED INTERR	GP	GZ 41	2H169	I31W	5165657	22003115008	T	4/25/2003	160	61	4	244	HUMAN ERROR	HUMN ERR	11922 UPPER H	2	TF	516565750				F/M HAD A DNP AT 11919 QUANDER---PULLING METER WITH BROKEN LOAD JAWS RESULTED IN TRIPPING OFF A 50KVA 19.9KV NLB TRANS RESET TRANS SERVICE RESTORED& RESET TR	1	0
FORCED INTERR	BA	BT 07	40156		6258527	32003115007	T	4/25/2003	160	37	1	37	BU DISC OR BARI	DISC/BARRL	4401 DECKER D		TF	625852746				REF TR,	1	0
FORCED INTERR	BL	SF 02	10415	MT8	5257502	12003115009	T	4/25/2003	160	52	1	52	UNKNOWN	UNKNOWN	3365 DEL MONT	1	TF	525750295				REFUSE 37.5 POWER POT CAUSE BY PULL FUSE; REF TR.	1	0
FORCED INTERR	BL	KB 09	14177	T4Z	5256609	12003115009	T	4/25/2003	161	86	5	430	BU DISC OR BARI	DISC/BARRL	2906 ALBANS S	1	TF	525660962				RPLD B/U BARREL ON TR;	1	0
FORCED INTERR	BL	JN 05	10013	J57M	5055245	12003115009	T	4/25/2003	161	144	7	1008	OH SEC/DR CL H	OH SC CL-H	8000 HARWIN D	1	SC	505524540				RPLCD CONN @ TF TLA	1	0
FORCED INTERR	SB	ADK42	21319	S2135	4961722	12003115009	T	4/25/2003	162	53	8	424	UNKNOWN	UNKNOWN	10038 CHICKAS	1	TF	496172220				REFUSED 50 KVA TRANS REF TR.	1	0
FORCED INTERR	GA	KM 07	30605	17E	6347235	32003115007	T	4/25/2003	162	97	6	582	FOREIGN MATER	FRGN MATR	524 LOUISIANA	1	TF	634723562				REPLACED BURNED UP FUSE BARREL ON A 50KVA TRANS; RPLD B/U BARREL ON TR.	1	0
FORCED INTERR.	BA	LP 07	41696	9T7	6253556	32003115008	T	4/25/2003	163	125	3	375	OTHER WILDLIFE	OTHER WL	215 S BROADW	1	TF	625355676				tale in cust.s equipment., REF TR;	1	0
FORCED INTERR	SH	TE 05	31090	28AEB	5651443	32003115008	T	4/25/2003	163	69	11	759	BU DISC OR BARI	DISC/BARRL	8134 SAYLYNN	1	TF	565144341				REF TR;	1	0
FORCED INTERR.	GP	BA 44	20693	W27G	5086954	22003115009	T	4/25/2003	163	198	4	792	UNKNOWN	UNKNOWN	4223 RIVERCHA	2	BU	508695447				repl bu 50 pmt 19.9-120-240 with 75pmt; RPLD B/U TR.	1	0
FORCED INTERR	SH	PO 09	41183		6249043	32003115006	T	4/25/2003	163	282	9	2538	TERMINATOR	TERMINATO	3528 E NASA R		BU	624904375				RPLD B/U TR.	1	0
FORCED INTERR	SB	BM 03	21485	C40L	4659909	12003115010	T	4/25/2003	164	117	2	234	TREE CLEARANC	TREE CLEA	1602 WYCLIFFE	1	TF	465990991				TRIM TREES OUT OFF OPEN WIRE SECONDARIES, RESET TR;	1	0
FORCED INTERR.	GP	BA 02	20623	G60B	5066634	22003115009	T	4/25/2003	164	118	4	472	OH SEC/DR CL H	OH SC CL-H	5115 THEALL	1	SC	506663485	SC			REPRD TRANS BUSS., RPLD CONN @ TR; RPRD BUSS WORK @ TR;	1	0
FORCED INTERR	HC	MV 02	14215	36KR	5443230	12003115010	F	4/25/2003	165	90	22	1980	LIGHTNING ARRE	LTNG ARRS	CO RD 69 & AC	1	LF	36KR				CLEAR-UP-LIGHTING-ARRESTOR-ON-DISCONNECT-10231-HANSELMAN-ALSO-C/O-... NO SUBCASING ---ABK	1	0
FORCED INTERR.	CH	BY 05	41982	55U	5462401	32003115008	L	4/25/2003	1701	62	1	62	OH SEC/DR CL NI	OH SC CL-N	2341 MARGARE	1	DR		SC			repl broken up hot leg at wh made perm repairs to neutral up pole, RPLD CONN @ WH, RPLD SEC CONN @ PL-1 CUST.	1	0
FORCED INTERR.	GP	RU 02	40014	I39J	5361152	22003115009	T	4/25/2003	170	47	6	282	HUMAN ERROR	HUMN ERR	238 ECHO GLEN	1	TF	536115247				FUSE BROKE; REF TR;	1	0
FORCED INTERR	CY	TB 46	2B116	50DF	4670704	22003115010	T	4/25/2003	171	44	2	88	BU DISC OR BARI	DISC/BARRL	15614 CYPRESS	1	TF	467070431				REPL. BURNED FUSE BARREL & REFUSED A 25KVA 19.9/120/240 TRAN AT 15614 CYPRESS GARDENS RPLD B/U BARREL ON TR, REF TR.	1	0
FORCED INTERR	SU	WI 07	13024		48560061	12003115011	T	4/25/2003	172	75	6	450	UNKNOWN	UNKNOWN	2936 ASHFORD		TF	485600616				fuse pulled in 2; REF TR.	1	0
FORCED INTERR	FB	BV 42	12966	32TG		12003115011	F	4/25/2003	173	112	24	2688	TREE CLEARANC	TREE CLEA	4207 PECAN BE	1	LF	32TG	PR		SC	FOUND 4 PALM TREES HAD GOTTEN INTO THE PRIMARY & NUETRAL CONDUCTORS , THE TREES CAUGHT FIRE ,BURNING THE CONDUCTORS DOWN WE CUT THE TOPS OF TREES AND PR	1	0
FORCED INTERR	GA	MDY03	31022	H91X	6736152	32003115009	F	4/25/2003	173	57	1	57	LIGHTNING ARRE	LTNG ARRS	8127 STEWART	1	LF	H91X				NEED TO REPLACE THE NEUTRAL DEADEND AND THE LIGHTING ARRESTOR REFUSED LF # 41AEA 25T HAD TO GO ON EME TBL REF LF SEE ALSO CASE #320031150011	1	0
FORCED INTERR	GA	MDY03	31022	41AEA		32003115011	F	4/25/2003	173	57	0	0	LIGHTNING ARRE	LTNG ARRS	SOUTH SIDE OF	1	LF	41AEA				NEED TO REPLACE THE NEUTRAL DEADEND AND THE LIGHTING ARRESTOR. MBG WAS SENT TO S/C ON CASE #32003115009 TLA	1	0
FORCED INTERR	HC	SO 41	10832	74UA	5350905	32003115009	F	4/25/2003	175	99	51	5049	HUMAN ERROR	HUMN ERR	3022 RIVER BIR	2	LF	74UA				REPLACED 35 KV STANDOFF IN SWITCHING TRANS......NO BUSHING ON ONE SIDE.....SEND MESSAGE TO SOH ,NEED A DOUBLE FEED THROUGH AND A URD ARRESTER REF TP MBG SE	1	0
FORCED INTERR	MP	HG 04	41083		5655141	22003115010	T	4/25/2003	180	143	5	715	SQUIRREL	SQUIRREL	7703 EDEN		TF	565514105				REF LF,	1	0
FORCED INTERR	CY	SA 45	21348	83CC	48634471	22003115010	F	4/25/2003	181	92	89	8188	URD ELBOW	URD ELBOW	9647 W WITHER	2	LF	83CC	PR	486344712		S.O 8188 REPLACED ELBOW AND BUSHING ON X PRIMARY AT 11727 MEADOWCHASE; REF LF RPLD TR BUSH, RPLD ELBOW @ TR. NOSUBCASING---ABK	1	0
FORCED INTERR	GA	GL 01	30500	2N3	68380347	32003115010	F	4/25/2003	181	64	81	5184	BU DISC OR BARI	DISC/BARRL	3802 AVENUE N	1	LF	2N3	PR			REPLACED LOAD SIDE ON LF 2N3 AND BARREL, REF LF RPLD S/O PR JUMPER-FUSE BLOWN. RPLD B/U BARREL ON LF.	1	0
FORCED INTERR	BA	CD 11	41947	I60N	6357846	32003115010	T	4/25/2003	184	25	8	200	BU DISC OR BARI	DISC/BARRL	107 CHANDLER	1	TF	635784688				REF TR,	1	0
FORCED INTERR.	CH	SW 06	41684	2GE	5561553	32003115010	T	4/25/2003	185	37	14	518	VINES	VINES	10110 ROYAL O	1	TF	556155341				CLEARED SOME VINES OFF TRANS REPL BARREL NEED TO REPL SQUIRREL WIRE ,SQUIRREL GUARD , KILL AND REMOVE VINES FROM TRANS EASEMENT EXCESS 10110 ROYOL OAKS REF	1	0
FORCED INTERR.	CY	TB 45	21044	B43C	4670957	22003115011	T	4/25/2003	192	170	1	170	BIRD	BIRD	15139 TREICHE	1	TF	467095723				REF TR.	1	0
FORCED INTERR	MP	UN 05	41404	C19E	55562111	22003115011	T	4/25/2003	192	60	12	720	TREE CLEARANC	TREE CLEA	5512 TRUETT	1	TF	555621110				REMOVE TREE LIMB OFF TR , REF TR; RMVD TREE/LIMBS FROM DR.	1	0
FORCED INTERR	BL	GT 12	10658		5356136	12003115012	L	4/25/2003	194	128	1	128	OH SEC/DR CL H	OH SC CL-H	1751 W MAIN		DR					RPLD CONN @ WH;	1	0
FORCED INTERR	CY	KL 45	2473C	P62V	4766504	22003115011	T	4/25/2003	200	294	2	588	OH SEC/DR CL H	OH SC CL-H	12526 TEXAS A	1	BU	476650480				repl bu 50 conv 19.9-120-240 with same; RPLD B/U TR.	1	0
FORCED INTERR	MP	WO 04	41844		5260447	22003115011	T	4/25/2003	2031	77	6	462	UNKNOWN	UNKNOWN	5007 APOLLO S		TF	526044789				REF TR.	1	0
FORCED INTERR	SU	BAR45	11895	U77E	4754849	12003115013	T	4/25/2003	213	273	6	1638	UNKNOWN	UNKNOWN	13543 GABY VIR	2	BU	475484949				RPLD 75 KVA URD 19.9 120/240 IN REAR OF THIS ADDRESS (OLD AGE); RPLD B/U TR.	1	0
FORCED INTERR.	SU	DL 45	14094		4850734	12003115013	T	4/25/2003	215	58	5	290	SNAKE	SNAKE	1807 CREEKSHI		TF	485073490				FOUND A SNAKE AT THE BUTT OF THE POLE, REF TR.	1	0
FORCED INTERR	GP	RU 05	41674	26LK		22003115012	F	4/25/2003	220	98	91	8918	UNKNOWN	UNKNOWN	951 HARTWICK	1	LF	26LK				REF LF COULD NOT LOCATE CAUSE. POSSIBLE TREE LIMB THAT FELL IN CLEAR REF LF	1	0
FORCED INTERR	FB	WA 43	14060	80GB	3950312	12003116000	T	4/26/2003	002	122	2	244	BIRD	BIRD	14637 FM 1489	1	TF	395031266				REPLACED BLOWN LIMITER FUSE ON TRANS AND REFUSED THE DISC ALSO REWORKED THE SECONDARY LUGS (CLAMPS) AT TRANS INSTALLED WILD LIFE PROTECTION AND TRIMMED T	1	0
FORCED INTERR.	KY	FZ 41	22610	28CA	4457320	12003116000	F	4/26/2003	011	136	82	11152	URD ELBOW	URD ELBOW	22947 INDIAN R	2	LF	28CA	PR			REF TP. RPRD URD PR. "REPAIRED (X) ELBOW IN TF#27 @ 814 LONG PRAIRIE "DIDN'T CALL FOR ANY S/O _ "MPO	1	0
FORCED INTERR	GA	GA 02	31188	39FH	6738824	32003116000	T	4/26/2003	025	304	6	1824	COLLISION	COLLISION	4 CEDAR LAWN	1	SC	673882407	PD			REPLACED 1 30 SEC POLE AND 2 SP OPEN WIRE # 2 CU SEC GALV PD NO ONE AT SCENE, RPRD CONN @ TR; RPLD PL.	1	0
FORCED INTERR	GP	HV 06	22360	Y84A	5263435	22003116000	F	4/26/2003	043	69	3	207	UNKNOWN	UNKNOWN	BLUE BELL, E O	1	LF	Y84A				REF LF	1	0
FORCED INTERR	GA	GL 05	30483	B72F	6838432	32003116000	T	4/26/2003	045	60	17	1020	OVERLOAD	OVERLOAD	2525 AVENUE O	1	SC	683843202				REPLACED BAD CONNECTION @ TRANS, RPLD CONN @ TR.	1	0
FORCED INTERR	HM	TWG4	20229	M91X	54689231	22003116000	F	4/26/2003	060	187	73	13651	OTHER WILDLIFE	OTHER WL	20211 FOX GLE	2	LF	M91X				REMOVED VINES AND TREE LIMBSOFF TERMINAL POLE, REF TP	1	0
FORCED INTERR	GA	GL 05	30483	B72F	6838432	32003116000	T	4/26/2003	063	39	17	663	OVERLOAD	OVERLOAD	2513 AVENUE O	1	SC	683843202				THIS TIES WITH THE 2525 AVE O 1/2........REPLACED CONN @ TRANS; RPLD CONN @ TR.	1	0
FORCED INTERR	SB	ME 02				12003116000	C	4/26/2003	070	47	883	41501	TRANSFORMER	TRANSFRM	14557 CAROLC		CL	ME02				CREW CLEARED UP HIGHSIDE JUMPER ON CSP TF @ 14557 CAROLCREST CIR **SECTION 21584 CEW/TWT	1	1

FORCED INTERR	SB	ME 02	21584	485723547	120031160013	T	4/26/2003	0700	240	3	720	UNKNOWN	UNKNOWN	14557	CAROLCF	BU	485723546	SC	REPL 25 CSP TRANS WITH 25 KVA CONV AND ALSO IN INSALLED DISCAND REPL BUSS WORK AND 12 KV INSULATOR NEED TO HAVE STREET LIGHT DEPT TO COME AND REPL LIGHT # 21	1	0
FORCED INTERR	CY	PI 43	21025	S2941	467264652	120031160010	T	4/26/2003	0741	116	2	232	OH SEC/DR CL HK	OH SC CL-H	27302	DECKER I	SC	467264639	REPLACE 167 TRANSFORMER LUGS ON 25 CSP, RPLD CONN @ TR,	1	0
FORCED INTERR	MP	WV 03	41812		555853862	120031160012	L	4/26/2003	0752	168	1	168	OH SEC/DR CL HK	OH SC CL-H	503	ZOE ST	SC		replaced 4/0 secondarys and drops RPLD 9EC-1 CUST,	1	0
FORCED INTERR	CH	HR 03	41042	C6W	546052681	120031160006	F	4/26/2003	0752	77	27	2079	UNKNOWN	UNKNOWN	VAUGHN @ JEN	1	LF	C6W	REFUSE LINE FUSE,	1	0
FORCED INTERR	BL	ST 12	31498		505581542	120031160016	T	4/26/2003	0811	139	2	278	O/H PRIMARY CU	OH PR CLMB	6600	BELLAIRE	TF	505581541	RPLD BURNED OFF HOT LINE CLAMP ON LIGHTER POT,	1	0
FORCED INTERR	CH	NM 02	47001	N14K	585910132	120031160016	F	4/26/2003	0831	30	29	870	SQUIRREL	SQUIRREL	12714	LE CHATE	2	LF	N14K	CLEARED VINES OFF TERMINAL POLE, ALL SERVICE BACK ON., REF TP, CALLED OFF VAN, CREW GOT LOOP BACK ON.,JRK	1	0
FORCED INTERR	CH	CV 10	40468	J34A	585852142	120031160017	F	4/26/2003	0830	73	12	876	SQUIRREL	SQUIRREL	13709	DUNCUM	1	LF	J34A	REFUSED B PHASE ON LINE FUSE J34A, FOUND SQUIRREL AT BUTT OF POLE @13737 DUNCUM CSP TRANSF AT THAT LOCATION ALL SERVICE BACK ON AT THIS TIME REF LF	1	0
FORCED INTERR	CY	PI 44	21123	11BU	477520863	120031160020	F	4/26/2003	0854	65	41	2665	SQUIRREL	SQUIRREL	BTWN	DALLAS	1	LF	11BU	REF LF,	1	0
FORCED INTERR	GP	LU 03	20408	16PJ	506991161	120031160023	T	4/26/2003	0911	110	13	1430	CUST EQP RELAT	CUST RLTD	18450	KUYKENE	1	SC	506991165	REPAIRED 3JR BUSS WORK --OUT OUT 18428 KUYKENDAHL MTR# 6125782 16 DUE TO FIRE AND BURNT UP LINE WIRES-BUSINESS NAME WHO STOP TRANS BANK FED MULTI CUSTS. ALL	1	0
FORCED INTERR	MP	WO 04	41845		526042885	120031160024	T	4/26/2003	0911	181	8	1448	COLLISION	COLLISION	4230	ELLA	BU	526042855	REPL 2 - 50 KVA 7200 120/240 O.H. TRANS WITH THE SAME, RPLD B/U TR,	1	0
FORCED INTERR	CH	GP 06	40815	N23K	565655587	120031160025	T	4/26/2003	0920	52	18	832	SQUIRREL	SQUIRREL	118	GEORGIA	1	TF	565655874	refused trx --repl/no-- dead here rebate, REF TR,	1	0
FORCED INTERR.	MP	CL 08	40493	J68U	555850420	120031160026	L	4/26/2003	0938	96	1	96	FLLNG TREE OUT	TREE FL/OE	1139	ROUSE	1	DR		CUST WAS TRAVELING TREE AN DROPED A LARGE LIMB AN PULLED THEM DOWN. PU DR. RPLD CONN @ WH,	1	0
FORCED INTERR	HM	AD 03	20402	9HS	536488507	120031160027	T	4/26/2003	0941	59	5	295	SQUIRREL	SQUIRREL	1122	ALDINE ME	1	TF	536485079	REFUSED 25 KVA DUE TO SQUIRREL HAS WILD LIFE PROTECTION INSTALLED 4-HOLDER B OFF REF TR,	1	0
FORCED INTERR	BA	BT 05	40139	E24K	635813390	120031160020	T	4/26/2003	0940	202	5	1010	UNKNOWN	UNKNOWN	1802	W MAIN #1	1	BU	635613990	REPL 1-50CSP TR W/ THE SAME ADD TO CUT OUT TO TR BANK RPLD B/U TR, RPLD B/U DISC-TF BLOWN, RPLD LIGHTNING ARRESTOR,	1	0
FORCED INTERR	FB	CR845	12775	S3KT	444973621	120031160021	F	4/26/2003	1011	56	19	1064	SQUIRREL	SQUIRREL	AUSTIN @ FRO	1	LF	S3KT	TF 444973702	REFUSED STEP DOW TRANSFORMER , LIF CAUSED BY SQUIRREL O PRIMARY AT 818 BARRETT TRANSFORMERS HAD WILD LIFE PROTECTION .. REF LF (CORRECTED THE OUTAGE TYPE	1	0
FORCED INTERR	GA	MD 03	31021	R25N	663684400	120031160021	F	4/26/2003	1031	53	1	53	LIGHTNING	LIGHTNING	9402	SEAWALL	1	LF	R25N	PAST WEATHER CUST HAD IT OFF LAST WEEK BUT DID NOT CALL IN BLOWN LIGHTNING ARRESTOR ON TRANSFORMER. NEED TO REPLACE LATER DATE REF LF,	1	0
FORCED INTERR.	FB	WA 43	12943	K90Y	395140481	120031160024	T	4/26/2003	1033	58	1	58	LIGHTNING	LIGHTNING	13517	FM 1489	1	TF	395140491	16 TR, REF TR,	1	0
FORCED INTERR	HM	HB 04	20103	H69M	566989224	120031160025	T	4/26/2003	1035	43	4	172	BU DISC OR BARI	DISC/BARRL	1310	WALNUT L	1	TF	566992424	RPLD B/U BARREL ON TR,	1	0
FORCED INTERR	SL	SE 41	1F162	5N9	375862221	120031160027	F	4/26/2003	1111	112	113	12656	SQUIRREL	SQUIRREL	3748	LAZY RIVE	1	LF	5N9	NEED WILD LIFE PER AND SWITCH ON CBP AT 3638 RIVER RD OFF BARTLETTE RD REFUSED PARNELLE 500 STEP DOWN& NEED FUSE NO FOR STEP DOWN& INSTALLED SERVICE IS UNAWA	1	0
FORCED INTERR	GP	HV 03	20505	E87V	526370021	120031160034	F	4/26/2003	1138	100	20	2000	SPLICE	SPLICE	8926	BUNNY RU 2	1	LF	E87V	PR	1	0
FORCED INTERR	FB	EB 08	11295	A69L	374690411	120031160033	T	4/26/2003	1140	63	2	126	SQUIRREL	SQUIRREL	4710	FM 2919	1	TF	374690417	NO SUBCASING NEEDED.,JRK	1	0
FORCED INTERR	GP	FR 41	20665	79ADN	496353111	120031160036	L	4/26/2003	1145	239	1	239	TREE CLEARANC	TREE CLEAR	9810	PLUM RIDG	1	DR		50 CSP EASEMENT REF TR, ROR	1	0
FORCED INTERR.	GP	BY 06	47037		536188332	120031160036	L	4/26/2003	1214	93	1	93	OH SEC/DR CL HK	OH SC CL-H	10239	BAUMAN	1	DR	SC	FOUND CUT OUT-#CONC; REPLACED ALL 3 CONNECTIONS ON MID-SPAN TAP RPLD CONN @ WH; RPLD 9EC CONN @ PL-1 CUST R/C H/C RMVD FREE,M/66 FROM OR	1	0
FORCED INTERR	FB	RE 08	14173	26TG	444972641	120031160034	F	4/26/2003	1215	70	5	350	SQUIRREL	SQUIRREL	100	HILLCREST	1	LF	26TG	REPLACED BAD HOT CLAMP @ WEATHERHEAD, RPLD CONN @ WH,	1	0
FORCED INTERR	SH	MY 05	3550C		574740867	120031160030	T	4/26/2003	1228	24	4	96	COLLISION	COLLISION	1124	COUNTY R	TF	574740874	WE WALKED THE LINE OUT THROUGH EASEMENT AND REMOVED VINES OFF TRANS AT 302 HILLCREST REFUSED LINE FUSE POSSIBLY A SQUIRREL ON THE WIRE , REF LF	1	0
FORCED INTERR	SU	DL 45	12082	16JD	485052701	120031160036	F	4/26/2003	1233	119	44	5236	BU DISC OR BARI	DISC/BARRL	2019	RICHLAND	2	LF	16JD	REF TR,	1	0
FORCED INTERR	BA	BT 04	40125	34A	635685136	120031160037	F	4/26/2003	1238	98	16	1536	BIRD	BIRD	415	W PEARCE	1	LF	34A	TF 635685136	REFUSED 16 JD DUE TO ALL SERVICE BACK ON CUST NOTIFIED; REF TP CORRECTED 2HR/CRN 04-28-03	1	0
FORCED INTERR	GA	PH R01	30869	93HN	654625841	120031160037	L	4/26/2003	1240	147	1	147	OH SEC/DR CL HK	OH SC CL-H	313	AVENUE A	1	DR		REFUSED LF 34A 66T & TR @ 411 W PEARCE ST , REF LF, REF TR,	1	0
FORCED INTERR	HM	LA 04	41246		546480647	120031160041	T	4/26/2003	1244	80	3	240	SQUIRREL	SQUIRREL	13125	PONDER	1	TF	546480642	RPLD CONN @ WH,	1	0
FORCED INTERR.	GP	LK 03	41292	E43T	526185421	120031160042	T	4/26/2003	1307	87	3	261	BIRD	BIRD	7019	N SHEPHE	1	TF	526185477	REFUSED 25 KVA TR DUE TO SQUIRREL HAS WLF ON IT REF TR,	1	0
FORCED INTERR	RS	AV 03	14218	AC1	564225571	120031160036	F	4/26/2003	1324	74	10	740	SQUIRREL	SQUIRREL	12414	COUNTY	1	LF	AC1	REF TR,	1	0
FORCED INTERR	CH	AD 02	40066	DU4	546213240	120031160038	T	4/26/2003	1344	82	8	656	BU DISC OR BARI	DISC/BARRL	11107	EXETER S	1	TF	546213240	REF LF,	1	0
FORCED INTERR	FB	BC 08	12880		120031160051	C	4/26/2003	1444	7	827	5789	UNKNOWN	UNKNOWN	BC08	CKT LOCI	CL	BC08		RPLD B/U BARREL ON TR,	1	0
FORCED INTERR	BA	BT 02	40157	AE5	625881661	120031160043	T	4/26/2003	1454	53	2	106	LIGHTNING ARRE	LTNG ARRS	5007	GLENHAVE	1	TF	625881660	LOCKED OUT ON (2) TRIPS MADE ANNOUNCEMENTS & TRIED BRKR HELD. GOM ***LOCKED OUT ON 2 TRIPS - WILL HAVE B3O CHECK RELAYS ON MONDAY TWT CUSTOMER AT 4608	1	1
FORCED INTERR	MP	HG 04	41331	88QT	565512391	120031160051	L	4/26/2003	1522	119	1	119	OH SEC/DR CL NI	OH SC CL-N	7730	ARBERRY	1	DR		REFUSED 37.8 TR. IN OPEN DELTA BANK NEED TO REPL L.A. 12KV EASEMENT REF TR,	1	0
FORCED INTERR	GP	RU 03	41319	C96F	536284101	120031160052	F	4/26/2003	1528	237	8	1896	BU DISC OR BARI	DISC/BARRL	1207	BREA CRE	1	DB	C96F	REPLACED DROPS ON MOIRAN TAP IN EASEMENT RPLD DR,	1	0
FORCED INTERR	GP	FR 45	21370	T21T	505234422	120031160061	F	4/26/2003	1601	89	45	4455	URD ELBOW	URD ELBOW	8107	WARREN	2	PR	T21T	SC 506234422	RPLD B/U DISC-TF BLOWN,	1	0
FORCED INTERR	HM	LW 43	20405	S3276	558435732	120031160065	T	4/26/2003	1611	85	25	1625	VANDALISM	VANDALISM	5819	ALDAINE BE	2	TF	558435734	URD SPAC 6207, REPL "Y" ELBOW & BUSHING AT 6038 BPUT PIME REF TP; RPLD TR BUSH, RPLD ELBOW @ TR	1	0
FORCED INTERR	SU	WZ 44	12357	U67P	495585411	120031160065	F	4/26/2003	1621	119	87	10353	SPLICE	SPLICE	9767	PAGEWOC	2	LF	U67P	DB PR	REPLACED BROKE METER OLD METER READING 24328 D34668 NEW METER 76770782 BANGANO X56 WIRE 120/240 READING 00000 RESET TR	1	0
FORCED INTERR	SB	SA 48	21258		476250141	120031160067	T	4/26/2003	1627	329	8	1974	LIGHTNING	LIGHTNING	6826	GROVE FIE	1	BU	476250143	FOUND BAD 8PAN OF PRIMARY BETWEEN TRAN # 5 AND TRANS #4 PUT X ON STANDOFF IN TRANS 4 PUT Y ON STANDOFF IN TRAN 5 CAN SPLICE OUT PRIMARY IN TRANS 5 WERE IT IS BLOW	1	0
FORCED INTERR	HC	HM 05	11029	TA4	545301806	120031160066	T	4/26/2003	1641	85	9	765	TREE CLEARANC	TREE CLEAR	9229	MARTELL	1	TF	545301806	clean part lightning burns thru RPLD B/U TR,	1	0
FORCED INTERR	MP	AN 07	40039	A85R	535925232	120031160072	F	4/26/2003	1654	58	16	928	UNKNOWN	UNKNOWN	103	E 32ND #7	1	LF	A85R	IN-THE-REAR-OF 8220-MARTELL-TREES-IN-OPEN-WIRE-9EC , REBET TR,	1	0
FORCED INTERR	SB	DV 03	10592	X87H	505632571	120031160072	L	4/26/2003	1701	62	1	62	OH SEC/DR CL HK	OH SC CL-H	2830	CROSSVIE	1	DR		REFUSED LF A85R, REF LF	1	0
FORCED INTERR	SH	PE 05	31244		554873331	120031160063	T	4/26/2003	1710	74	2	148	BU DISC OR BARI	DISC/BARRL	5513	MAGNOLIA	1	TF	554873316	RPLD CONN @ WH,	1	0
FORCED INTERR	HC	HOCO	11159	G21L	515382771	120031160075	T	4/26/2003	1716	56	10	560	BIRD	BIRD	4805	WILLOWBI	1	TF	515382778	REF TR	1	0
FORCED INTERR	GP	LK 10	20870	Y14J	516260614	120031160076	F	4/26/2003	1730	0	0	0	UNKNOWN	UNKNOWN	3911	CYPRESS	2	LF	Y14J	BU 516260614	REF TR	1	0
FORCED INTERR	GP	LK 10				120031160076	F	4/26/2003	1730	201	14	2814	UNKNOWN				2	LF	Y14J	F S B/OM:200 CT 21 16 ALL SERV RES EXCEPT BO PMT 3619 BADGER FRST DR RES B/OM:200 CT 00 27, RPLD B/U TR,	1	0
FORCED INTERR	GP	LK 10				120031160076	F	4/26/2003	1730	218	45	9810	UNKNOWN				2	LF	Y14J		0	0
FORCED INTERR	GP	LK 10				120031160076	F	4/26/2003	1730	409	5	2045	UNKNOWN				2	LF	Y14J		0	0
FORCED INTERR	CH	SW 09	41234	3U7	546294332	120031160054	T	4/26/2003	1811	37	6	222	UNKNOWN	UNKNOWN	4513	MOONEY F	1	TF	546294338	REF TR,	1	0
FORCED INTERR	BL	FD 09	10704		505462501	120031160080	T	4/26/2003	1825	50	11	550	BIRD	BIRD	8216	FONOREN	1	TF	505462509	REF TR,	1	0
FORCED INTERR	FB	RE 05	11439	Y15B	444953070	120031160084	F	4/26/2003	1840	91	16	1456	ANTS	ANTS	402	S.11TH BLD	2	LF	Y15B	REPLACED BAD Y PRIMARY BUSHING IN URD TRANSFORMER #2 REFUSED T P Y15B -Y FEED REF TP RPLD TR BUSH;	1	0
FORCED INTERR	SH	HA 04	30564	RF7	575122052	120031160056	F	4/26/2003	1855	256	23	5888	OTHER	OTHER	FUQUA, W OF A	1	LF	RF7	BU 575122052	REPLACED 50 CSP WITH A 50 CONV INSTALLED SWITCH & LIGHTENING ARRESTER CAL	1	0
FORCED INTERR	HM	HB 43	20078	96FA	586861958	120031160094	T	4/26/2003	1857	105	10	1050	UNKNOWN	UNKNOWN	19718	POWERS	2	TF	586861960	REF TR,	1	0
FORCED INTERR	SH	PA 09	30772	W30C	575460221	120031160057	F	4/26/2003	1857	102	1	102	LIGHTNING ARRE	LTNG ARRS	2710	SOUTH HC	1	LF	W30C	REFUSED E PHASE OF LF--BAD LIGHTING ARRESTER REF LF	1	0
FORCED INTERR	BL	ST 03	10202		515500531	120031160098	T	4/26/2003	1910	71	8	568	TREE CLEARANC	TREE CLEAR	7111	HILLCROF	1	TF	515500530	REFUSED 37.5 KVA AND TRIMMED TREES, REF TR,	1	0
FORCED INTERR	CY	HK 42	21103	S2459		120031160101	F	4/26/2003	1931	53	54	2862	UNKNOWN	UNKNOWN	24230	BAUER M	1	LF	S2459	RODE #2459 NO APPARENT CAUSE CHECKED STEP POT CLOSED IN #2459, REF LF	1	0
FORCED INTERR	MP	HR 01	41027	U1S	535993232	120031160105	T	4/26/2003	1952	79	4	316	UNKNOWN	UNKNOWN	5104	DUNLOP	1	TF	535993273	refused a 50 kva lighter W bank w/ a 25 power 5102 main breaker is still HI, REF TR,	1	0
FORCED INTERR	KY	FZ 46	22806	31GN	456081431	120031160091	T	4/26/2003	2000	114	1	114	UNKNOWN	UNKNOWN	19103	CYPRESS	1	SC	456081439	Prob repeater to trans bank - cust complaining about arks melting & lands burning off, RPRD BUSS WORK @ TR,	1	0
FORCED INTERR	CH	UV 06	41515	T36X	585933132	120031160055	F	4/26/2003	2004	88	35	3080	SQUIRREL	SQUIRREL	13315	MYRNA LI	2	LF	T36X	REF TP	1	0
FORCED INTERR	CY	HK 42	22257	93S	456422161	120031160106	F	4/26/2003	2011	150	3	450	BU DISC OR BARI	DISC/BARRL	17701	HOUSE H	3	DB	93S	PREVIOUS REF LF, RPLD B/U BARREL ON LF	1	0
FORCED INTERR	SB	SA 47	21225	N90U	476265521	120031160105	F	4/26/2003	2012	237	59	13983	UNKNOWN	UNKNOWN	7707	MUIRFIELD	2	LF	N90U	FOUND T P N-90-U BLOWN CHECKED LOOP WITH VAN FOUND NO PROB REFUSED T P N-90-U , REF TP	1	0
FORCED INTERR	BL	GT 10	10645	X84M	535641740	120031160092	T	4/26/2003	2013	264	1	264	UNKNOWN	UNKNOWN	5000	MONTROS 3	1	BU	535641744	Chg'd out 75 kvm with same 120/240 , RPLD B/U TR,	1	0
FORCED INTERR	MP	GG 01	40952	3RI	555465221	120031160113	F	4/26/2003	2030	74	24	1776	TREE CLEARANC	TREE CLEAR	6802	GOLFWAY	1	LF	3RI	REF LF,	1	0
FORCED INTERR	SB	BM 06	21498	78MP	485884901	120031160097	F	4/26/2003	2033	38	1	38	UNKNOWN	UNKNOWN	1424	SHERWOC	1	LF	78MP	REF LF	1	0
FORCED INTERR	SU	DL 45	12082	16JD	485062051	120031160096	F	4/26/2003	2038	219	44	9636	URD BUSHING	URD BSHING	3307	WATERS W	2	LF	16JD	PR	FOUND BAD WELL BUSHING AND ELBOW IN TRANS #11 Y FEED CHANGED IT OUT GOT ALL THE SERVICE BACK ON, REF TP RPLD ELBOW @ TR "NO SUBCASING NECESSARY"	1	0
FORCED INTERR	SB	SR 15	21678	16SH	495961752	120031160100	F	4/26/2003	2050	0	0	0	UNKNOWN	UNKNOWN	1615	IMPERIAL I	1	LF	16SH	BU 495961752	NEED TO REPLACE 100 POWER POT WITH 167 NONE IN CENTER WHEN NEEDED CAN GET TRUCK TO IT BANKED WITH 2 OTHER 167 7200 RPLD B/U TR, MEK CORRECTED 2HR	1	0
FORCED INTERR	SB	SR 15				120031160100	F	4/26/2003	2050	108	35	3780	UNKNOWN				1	LF	16SH		0	0
FORCED INTERR.	SB	SR 15				120031160100	F	4/26/2003	2050	593	1	593	UNKNOWN				1	LF	16SH		0	0
FORCED INTERR	BL	BR 12	10818	X41L	525442411	120031160101	T	4/26/2003	2107	95	9	855	TRANSFORMER	TRANSFRM	9014	LINKMEAD	1	SC	525442410	NEED TO REPLACE STIRRUP ON 25 POWER POT BANK WITH 50 FIRST THING IN AM 4/26/03	1	0
FORCED INTERR	SH	PA 06	30785	D2W	585404151	120031160067	T	4/26/2003	2123	30	1	30	BU DISC OR BARI	DISC/BARRL	613	HOUSTON J	1	TF	585404153	FUSE GAVE UP REF TR,	1	0
FORCED INTERR	SH	SB 01	31032	J46K	585443661	120031160085	F	4/26/2003	2240	44	2	88	TREE CLEARANC	TREE CLEAR	1803	PASADENA	1	LF	J46K	REF LF	1	0
FORCED INTERR	CY	WL 42	21939	2CT	407151562	120031170002	F	4/27/2003	0132	64	13	832	UNKNOWN	UNKNOWN	31324	KNEBEL	1	LF	2CT	RODE OUT LF 2CT NO APPARENT CAUSE, REF LF,	1	0
FORCED INTERR	SU	SIE42	11730		494722670	120031170004	T	4/27/2003	0233	87	1	87	VINES	VINES	7219	THOMPSO	TF	494722670	PR	REMOVED VINES FROM TRANS HO E O.T. SYSTEM WAS DOWN REFUSED AND REPLACED LIMITER FUSE, REF TR,	1	0
FORCED INTERR	SB	SA 47	21225	N90U	476264582	120031170014	T	4/27/2003	0325	535	4	2140	URD BUSHING	URD BSHING	14507	MUIRFIEL 2	BU	476264588	SC PR DR	REPLACED BAD 500KVA 19.9/240-120 URD TR @ 14507 MUIRFIELD LANE REPLACED 2 ELBOWS AND SPLICED 9EC AND DROPS RPLD B/U TR RPRD 9EC-1 CUST RPLD TR BUSH RPLD ELBOW	1	0
FORCED INTERR	MP	MP 08				120031170003	C	4/27/2003	0422	0	0	0	COLLISION	COLLISION	3907	CANAL	CL	MP08		NON 10% NO AUTOMATION. CREW FOUND CAR HIT POLE MADE MINOR REPAIRS ON OH TBL BOB 272 CEW	1	1
FORCED INTERR	MP	MP 08	2G208			120031170003	C	4/27/2003	0422	49	0	0	COLLISION				CL	MP08			0	0
FORCED INTERR	SB	SR 13	21681	H97U	495755561	120031170002	T	4/27/2003	0600	263	3	789	UNKNOWN	UNKNOWN	12518	OVERCUI	1	BU	495755623	Repl. 25 kvm trans 7200 – 120/240 with 50 kvm trans. 7200 – 120/240 RPLD B/U TR,	1	0
FORCED INTERR	SU	AF 06	12857	16SB	485434001	120031170007	F	4/27/2003	0700	119	23	2737	UNKNOWN	UNKNOWN	7046	S.DAIRY A	2	LF	16SB	BOB #216 # CLEANED PRIMARY BUSHING IN #216 # 16, RPLD URD PR, REX CORRECTED 2HR/CRH 04-26-03	1	0
FORCED INTERR.	SB	SR 15	21678	16SH	495961752	120031170008	T	4/27/2003	0710	83	1	83	OVERLOAD	OVERLOAD	1711	GESSNER	1	TF	495961753	cust has beide wiring problems service is turned on and has good voltage REF TR	1	0
FORCED INTERR	CY	PI 44	2C123	B74Z	487521002	120031170042	T	4/27/2003	0718	163	2	326	VINES	VINES	8619	PRINE	1	PR	487521082	RPLD LIMITER @ TR, REF TR MEK	1	0
FORCED INTERR	MP	GG 01	40950		555424412	120031170043	T	4/27/2003	0730	98	6	588	BU DISC OR BARI	DISC/BARRL	6124	LONG	1	TF	555424419	RPLD B/U BARREL ON TR,	1	0
FORCED INTERR	FB	EB 05	11290	A8C	364411851	120031170006	T	4/27/2003	0740	41	1	41	UNKNOWN	UNKNOWN	19925	COUNTY 1	TF	364411853	REF TR,	1	0
FORCED INTERR	CH	AD 08	40386		546255302	120031170007	T	4/27/2003	0748	81	4	324	SQUIRREL	SQUIRREL	2709	BERTRANI	1	TF	546255309	REF TR,	1	0
FORCED INTERR	HC	FD 05	10859	2AM	515301161	120031170012	T	4/27/2003	0800	49	4	196	SQUIRREL	SQUIRREL	8019	BENNING I	1	TF	515301160	REF TR,	1	0
FORCED INTERR	BL	HT 09	10310	B55R	505594441	120031170014	F	4/27/2003	0812	85	2	170	VINES	VINES	6015	HILLCROF	1	LF	B55R	REMOVED VINES AND REFUSED MIDDLE PHASE LIF REF LF RPLD B/U BARREL ON LF MEK	1	0
FORCED INTERR	SB	WT 01	12672	8CX	515900699	120031170015	T	4/27/2003	0825	120	8	960	UNKNOWN	UNKNOWN	1608	GLOURIE	1	TF	515900699	refused 50 kva stay pulled fuse REF TR,	1	0
FORCED INTERR	SU	WI 42	12519		475863450	120031170017	T	4/27/2003	0831	82	6	372	SQUIRREL	SQUIRREL	13726	BURGOYI	TF	475863450	REF TR,	1	0
FORCED INTERR	CY	WL 42	21939	2CT	407151682	120031170045	T	4/27/2003	0838	81	1	81	SNAKE	SNAKE	31326	KNEBEL 1	TF	407151658	DB	REPLACE SWITCH ON 50 CSP RPLD B/U DISC-TF BLOWN,	1	0
FORCED INTERR	FB	EB 06	11295	1MS	374670361	120031170015	T	4/27/2003	0844	79	2	158	COLLISION	COLLISION	1916	COUNTY R	1	TF	374670362	DR	REBET TR, PU DR, RPLD NTR JAMS/LUGS MEK	1	0
FORCED INTERR	CH	CV 01	40422	Y57S	585855761	120031170010	T	4/27/2003	0845	232	2	464	INSULATOR	INSULATOR	510	FREEPORT	1	BU	585855769	RELOCATED LIGHTER POT TO STRAIGHTEN POLE, RPLD B/U TR, RPLD LIGHTNING ARRESTOR	1	0
FORCED INTERR	SH	GV 05	30523	M17	556231662	120031170011	L	4/27/2003	0848	70	1	70	OH SEC/DR CL HK	OH SC CL-H	6320	MADDEN L	1	DR		RPLD CONN @ WH,	1	0
FORCED INTERR	BA	HL 05	41180		619303341	120031170012	L	4/27/2003	0900	50	1	50	SQUIRREL	SQUIRREL	1309	E WALLISV	1	SC		RPRD 9EC CONN @ PL-1 CUST	1	0
FORCED INTERR	CY	PI 41	2A120	U38B	437695391	120031170046	F	4/27/2003	0903	91	4	364	SQUIRREL	SQUIRREL	726	FM 1488	1	LF	U38B	TF 437695391	REFUSED LIF U38B @ 888 FM 1488 REFUSED TRANS @ 734 FM 1488 REP LF REF TR, MEK	1	0
FORCED INTERR	BA	HL 01	41146		625864201	120031170013	T	4/27/2003	0910	28	3	84	SQUIRREL	SQUIRREL	5408	SHIRLEY S	1	TF	625864205	REFUSED TR NEED TO REPL 12KV LA. ALL NEEDS WILDLIFE PROT IN EASEMENT REF TR MEK	1	0
FORCED INTERR	GP	RU 05	41671		536281681	120031170046	L	4/27/2003	0917	72	1	72	FLLNG TREE OUT	TREE FL/OE	11621	BANNISTI	DR			PICKUP IN DROPS AND REMOVED TREE RPLD CONN @ WH,	1	0
FORCED INTERR	SH	DR 02	31353	UK9	585482113	120031170014	F	4/27/2003	0917	80	24	1920	UNKNOWN	UNKNOWN	RADCLIFF, S OF	1	LF	UK9	REF LF	1	0
FORCED INTERR.	FB	CR845	11442	50TT		120031170021	F	4/27/2003	0924	41	42	1722	SQUIRREL	SQUIRREL	812	BLAISDALE	1	LF	50TT	REF 50TT---PROBABLY SQUIRRELL---QUITE A FEW CBP'S REF LF	1	0
FORCED INTERR	MP	GS 22	40767	4GC	545771001	120031170050	T	4/27/2003	0946	27	1	27	SQUIRREL	SQUIRREL	3304	SHERMAN	1	TF	545771065	REF TR, MEK	1	0
FORCED INTERR	SH	WE 02	31250	C74W	585500221	120031170015	T	4/27/2003	0946	72	6	432	OH SEC/DR CL NI	OH SC CL-N	1015	WAFER ST	1	SC	585500223	RPLD 9EC CONN @ PL-1 CUST	1	0
FORCED INTERR.	CH	OA 04	41597	2M8	585892642	120031170020	T	4/27/2003	1020	88	6	396	SQUIRREL	SQUIRREL	10318	DUNCUM	1	TF	585892642	REF TR,	1	0
FORCED INTERR	FB	RE 07	12616	19FB	444531861	120031170022	F	4/27/2003	1045	100	18	1800	BU DISC OR BARI	DISC/BARRL	1618	GREENFIE	2	LF	19FB	BAD FUSE BARRELL ON UR

FORCED INTERR	SB	ME 02	20810	8PP	48573318	120031170038	L	4/27/2003	142	44	1	44	FALLING DEAD TI	TR FL/DEAD	14503 RIVER FC	1	DR					PAU DR;	1	0
FORCED INTERR	GP	FR 45	21369	P24E	50623355	220031170067	T	4/27/2003	144	62	5	310	CONTRACTOR-N	CON-NT HLF	7463 WOODOAI	2	TF	506233556				CUST OUT URD DROPS , GAVE TEMP DISC. METER # D23995008 READING 45428, RESET TR, TEMP DISC-LEFT MTR & DR.	1	0
FORCED INTERR	CY	TB 06	23015	N16B		220031170066	F	4/27/2003	1451	119	108	12852	SQUIRREL	SQUIRREL	625 E. CARROLI	1	LF	N16B	LF	A67W	PR	REPLACED X-ARM @ 625 E. CARROLL 2106 REFUSED C PHASE OF LF N16B @ 15 10 3666 CLOSED C PHASE CU BLADE @ 505 E. CARROLL @ 16 50, REF LF, PAU PR-FUSE BLOWN. CORRE-	1	0
FORCED INTERR	FB	DA 08	11326	X17P	45373275	120031170042	F	4/27/2003	150	98	1	98	ROTTEN POLE	ROTTEN PL	2ND @ MULCAH	1	LF	X17P	PD			FLOATED PRIMARY ON D DEAD END POLE 1 SPAN SOUTH OF WJ6 REFUSE 3 PHASES OF WJ6; REF LF RMVD DOWNED PL.	1	0
FORCED INTERR	FB	DA 06	11327	WJ6		120031360071	F	4/27/2003	150	98	6	588	ROTTEN POLE	ROTTEN PL	19100 DAMON C	1	LF	WJ6				OA CREATED OUT REF CASE 120031170042 (IOM)	1	0
FORCED INTERR.	BZ	VL 03	3511B	H2R	55257295	320031170034	F	4/27/2003	153	61	55	3355	VINES	VINES	2622 SHADY CR	1	LF	H2R				CLEARED VINES FROM CSP TRANS, REF LF	1	0
FORCED INTERR	GA	STWO	3549C		62312407	320031170035	T	4/27/2003	160	94	8	752	BU DISC OR BARI	DISC/BARRL	3903 NUECES		TF	623124026	DB			REPLACED BAD BAU DISC., RPLD BAU DISC-TF BLOWN.	1	0
FORCED INTERR.	MP	NS 05	41567	EG2	54587340	220031170076	T	4/27/2003	1611	32	12	384	UNKNOWN	UNKNOWN	2312 BREWSTE	1	TF	545873406				REFUSED A 50 KVA 7200 120 240 V TRANSFORMER, REF TR.	1	0
FORCED INTERR	SB	TO 11	21784	19MP	51600394	120031170054	F	4/27/2003	163	42	15	630	COLLISION	COLLISION	W. 43RD BTWN	1	LF	19MP				REFUSED ALL THREE FUSES DO TO CAR HIT POLE, REF LF;	1	0
FORCED INTERR	SH	SB 02	31034	PPS	58548568	320031170037	F	4/27/2003	1651	50	1	50	SQUIRREL	SQUIRREL	SOUTHMORE @	1	LF	PPS	TF	585485664		REFUSED MIDDLE AND WEST TRANS_IN A 13.2 BANK,ALSO REFUSED LINE FUSE.___VARMIT.___SEND MESSAGE TO SOH,NEEDS WILDLIFE PROTECTION. REF LF REF TR.	1	0
FORCED INTERR	HM	RA 44	21211	70PL	52730286	220031170080	F	4/27/2003	170	148	35	5180	UNKNOWN	UNKNOWN	502 HEARTHST	2	LF	70PL				CHECKED LOOP OUT AND TRASFORMER FOUND O.K REFUSED T.P70PL, REF TP	1	0
FORCED INTERR	BL	DN 01	10539	W67V	52578169	120031170056	F	4/27/2003	172	63	14	882	UNKNOWN	UNKNOWN	2111 PINE VALL	1	LF	69KE				CHILD FUSE -69KE LOCATED 2111 PINE VALLEY; REF LF	1	0
FORCED INTERR	SH	PA 04	30777	C40F	57558143	320031170043	F	4/27/2003	173	32	22	704	UNKNOWN	UNKNOWN	W HARRIS, W C	1	LF	C40F	TF	575581433		REFUSED POWER TRANS___EAST POWER POT ,PULLED FUSE; REF TR.	1	0
FORCED INTERR	BL	DN 01	10539		52579125	120031170063	T	4/27/2003	173	73	7	511	UNKNOWN	UNKNOWN	2209 PINE VALL		TF	525791258				REF TR;	1	0
FORCED INTERR	HM	AD 03	22916	49CQ	53648187	220031170087	T	4/27/2003	180	197	1	197	BIRD	BIRD	13921 REEVEST	1	TF	536481877				birds got in trasformer; REF TR.	1	0
FORCED INTERR	FB	DA 05	11878	91EG	44399245	120031170066	F	4/27/2003	183	110	14	1540	O/H PRIMARY CL	OH PR CLMF	15426 JOHN MIL	1	LF	91EG	PR			PICKED UP TWO SPANS #4 PRIMARY LOCATED AT 15424 JOHN MILLER RD PRIMARY GAVE UP AT STIRRUP REPLACED AND SPLICED OUT ABOUT 40 FEET OF #4 WIRE, REF LF PAU PR-FUSE I	1	0
FORCED INTERR	BA	FT 07	40724		61532486	320031170047	L	4/27/2003	183	106	1	106	UNKNOWN	UNKNOWN	10330 CATLETT		DR					RPLD CONN @ WH.	1	0
FORCED INTERR	BA	TRM02	4101C		66540260	320031170054	T	4/27/2003	1951	129	3	387	TREE CLEARANC	TREE CLEAI	8634 OCEAN DR		SC	665402609				RPRD SEC->1 CUST;	1	0
FORCED INTERR	BA	BT 01	40094	6SE	63563336	320031170057	T	4/27/2003	1957	49	11	539	UNKNOWN	UNKNOWN	1309 BURBANK	1	TF	635633369				RESET TR.	1	0
FORCED INTERR	MP	BH 07	40299	EG7	54588358	220031170096	T	4/27/2003	204	21	9	189	UNKNOWN	UNKNOWN	2305 PANNELL	1.	TF	545883589				REFUSED A 50 KVA 7200120 240 V TRANSFORMER; REF TR;	1	0
FORCED INTERR	CY	CYF42	21213		46629543	220031170097	T	4/27/2003	210	63	11	693	UNKNOWN	UNKNOWN	7736 PARK FALL		TF	466295435				REFUSED A 100KVA 19.9/120/240 TRAN. IN THE REAR OF 7743 HIGH VILLAGE. BAD FUSE., REF TR.	1	0
FORCED INTERR	MP	VV 03	41812	L7Z	55586308	220031170098	T	4/27/2003	211	26	9	234	BU DISC OR BARI	DISC/BARRL	6819 VICTORIA	1	TF	555863099				RPLD BAU BARREL ON TR;	1	0
FORCED INTERR	GP	LK 06	22554	5A7	51625518	220031170102	T	4/27/2003	2221	60	1	60	SNAKE	SNAKE	10401 W MONT	1	TF	516255199				REF TR.	1	0
FORCED INTERR	CY	PI 43	21118	36GC	44703425	220031180001	T	4/28/2003	013	71	3	213	UNKNOWN	UNKNOWN	21810 MUSKET I	1	TF	447034254				REFUSED 75 KVA; REF TR;	1	0
FORCED INTERR	GP	HV 03	20505	E87V	52637001	220031180002	F	4/28/2003	023	117	20	2340	UNKNOWN	UNKNOWN	9018 BUNNY RU	2	LF	E87V				SO# 8221, REF TP	1	0
FORCED INTERR	CH	GW 01	40890	T68E	56614596	320031180003	F	4/28/2003	025	74	1	74	COLLISION	COLLISION	10004 MESA	1	LF	T68E				NEED TO REPLACE 45' CLASS 4 POLE ASAP ONE POLE TO THE EAST BEHIND LINE FUSE T68E. HPD CASE # 56312003V OFFICER ABERCIA UNIT # 8C51N, REF LF,	1	0
FORCED INTERR	BL	SF 45	10456		51576096	120031180002	T	4/28/2003	040	115	5	575	VINES	VINES	1722 SKY LRK LI		PR	515760992				RPLD LIMITER @ TR, REF TR.	1	0
FORCED INTERR	HC	MV 01	14206	A2J	54451051	120031180004	T	4/28/2003	051	69	2	138	UNKNOWN	UNKNOWN	6524 JORDAN	1	TF	544510511				REPLACED FUSE BARREL ON TRANS SWICTH, RPLD BAU BARREL ON TR,	1	0
FORCED INTERR	GP	RU 02	41655	9HR	53620556	220031180004	T	4/28/2003	055	51	6	306	BU DISC OR BARI	DISC/BARRL	6533 YALE ST	1	TF	536205582				REFUSED 50 KVA, RPLD BAU BARREL ON TR, REF TR. BJH	1	0
FORCED INTERR	GP	DH 09	40594	FP9	51605557	120031180006	F	4/28/2003	061	63	13	819	COLLISION	COLLISION	5039 HARDWAY	1	LF	FP9				DUMP TRK BUMPED POLE GOT PRI TOGETHER (POLE IS OK); REF LF	1	0
FORCED INTERR	GP	RA 43	20416	F14F	51728491	220031180008	T	4/28/2003	070	229	8	1832	OH SEC/DR CL H	OH SC CL-H	24635 INTERST	1	TF	517284917	SC			REPLACED 2 HOT CLAMP @ POLE REMOVED VINES REFUSED TRXS, REF TR; RPLD CONN @ TR, BJH	1	0
FORCED INTERR	SU	HY 06	11708		48569436	120031180010	T	4/28/2003	070	86	6	516	SQUIRREL	SQUIRREL	11410 DEL MON		TF	485694366				INSTALLED NEW W.P.L. OLD WAS BURNED UP, REF TR;	1	0
FORCED INTERR	BA	FT 08	31268	I66K	59539283	320031180006	T	4/28/2003	070	48	1	48	SNAKE	SNAKE	6110 RED BLUFI	1	TF	595392826				REUSE 26 SNAKE, REF TR.	1	0
FORCED INTERR	BL	UL 47	13011	P80H	51572133	120031180013	F	4/28/2003	072	63	31	1953	SQUIRREL	SQUIRREL	1300 AUGUSTA	2	LF	P80H				THIS STEP TRANS HAS WILD LIFE PROT REF TP	1	0
FORCED INTERR	SU	AF 10	11820	T57M	48548083	120031180016	F	4/28/2003	073	68	37	2516	SQUIRREL	SQUIRREL	11615 BEXLEY	2	LF	T57M				LOOP OUT SQUIRREL BACK ON REFUSED REF TP;	1	0
FORCED INTERR	KY	KT 02	22567	W89U	43580158	120031180017	T	4/28/2003	074	63	2	126	SQUIRREL	SQUIRREL	1002 EAST	1	TF	435801597				Feeds off main feeder circuit., REF TR.	1	0
FORCED INTERR	BA	TRM02	43168	51FQ	66594187	320031180009	F	4/28/2003	074	97	1	97	UNKNOWN	UNKNOWN	8060 FM 3180	1	LF	51FQ				REF LF.	1	0
FORCED INTERR	SB	WT 06	22173		51581286	120031180016	T	4/28/2003	075	45	2	90	UNKNOWN	UNKNOWN	8155 KATY FWY		TF	515812868				REFUSED 50 KVA 277 TRAN IN BANK, CAUSE UNKNOWN. CUST HERE SAID SAME TRAN BLEW FEW MONTHS BACK, REF TR.	1	0
FORCED INTERR	RS	RZ 01	3573A	W92O	50414125	320031180012	F	4/28/2003	081	94	10	940	BIRD	BIRD	14336 COUNTY	1	LF	W92O				REFUSED LINE FUSE; REF LF;	1	0
FORCED INTERR	CH	OA 04	41597	2M8	56568265	320031180013	T	4/28/2003	081	153	6	918	TREE CLEARANC	TREE CLEAI	10138 VALENCI	1	TF	565882654				REF 50 KVA XFMER--OUT BY TREE LIMBS,VINES,SQUIRREL----LEFT WORKING NEED WLP REPL THIS WEEK---IN EASEMENT----POLE IS COVERED WITH POISON SUMAC-IVY----ALSO TREES-2	1	0
FORCED INTERR	SH	PO 03	30718	35NF	60502406	320031180014	F	4/28/2003	0821	56	1	56	SQUIRREL	SQUIRREL	EL DORADO @	3	LF	35NF				REF TP;	1	0
FORCED INTERR	SB	ADK43	20959	T75T	49617311	120031180026	T	4/28/2003	082	28	2	56	SQUIRREL	SQUIRREL	10050 TALLEY L	1	TF	496173113				SECOND REQEST/ CLOSED DELTA BANK / EASMENT / COMMERCIAL ACCOUNT STATES NO OUTAGE NEEDS SET UP JUST NOTIFIED BEFORE TAKING OUT PLEASE SEND MMOP TP [illegible]	1	0
FORCED INTERR	SU	RO 03	12204		49532342	120031180027	L	4/28/2003	083	38	1	38	OTHER WILDLIFE	OTHER WLE	10535 WILCRES		MT					REPL DAMAGED MTR---CUST NEEDS TO REPL 3-125 AMP BUSS FUSES OLD MTR-W71428836-READING KWH19634 X 1-KVA4X1-NEW MTR #23506834 TYPE SV4 SR-30 A-200 CL-277V-4W Y RPLI	1	0
FORCED INTERR	SU	CE 03	11952	834Z	48532182	120031180028	T	4/28/2003	083	22	3	66	SQUIRREL	SQUIRREL	10531 SUE LN	1	TF	485321822				REFUSED TRANS SQUIRREL BACK ON, REF TR;	1	0
FORCED INTERR.	MP	AN 04	40025	8L5	53597191	220031180020	L	4/28/2003	0851	40	1	40	FOREIGN MATER	FRGN MATR	1006 WALTON S	1	DR					THEY HAD SOME OLD ELECTRICIAN CLAMPS AT WH, CHANGED OUT ALL 3, RPLD CONN @ WH.	1	0
FORCED INTERR	SL	SE 41	1D162	94AAY	37545404	120031180031	T	4/28/2003	085	278	1	278	ROTTEN POLE	ROTTEN PL	8626 FM 1458	1	PR	375454041	PD			REPLACED 35 FT POLE WITH SAME PICKUP ONE SPAN #4 PRIMARY, PAUP PR-FUSE NOT BLOWN, RPLD PL. BJH	1	0
FORCED INTERR.	SH	DR 02	30266	KF3	56543051	320031180023	T	4/28/2003	085	32	5	160	TREE CLEARANC	TREE CLEAI	7902 MONTGLE	1	TF	565430514				refused tran -- trees -- removed tree; REF TR.	1	0
FORCED INTERR	BL	DN 02	13122	UG7	53573194	120031180034	T	4/28/2003	090	61	10	610	VINES	VINES	1208 W GRAY S	1	TF	535731948				CLEARED VINES FROM TRANSFORMER, REFUSED 50 KVA T/F REF TR.	1	0
FORCED INTERR	BL	GN 09	40915	MT1	53551153	120031180037	T	4/28/2003	090	55	1	55	UNKNOWN	UNKNOWN	2116 W HOLCO	1	TF	535511538				RE-SET THE CSP POWER TRANSFORMER IN AN OPEN DELTA BANK; RESET TR.	1	0
FORCED INTERR	HM	SW 08	41693	A99S	56634161	220031180022	T	4/28/2003	091	30	1	30	BU DISC OR BARI	DISC/BARRL	8630 1/2 MT HOI	1	TF	566341616				CUST STILL HAS INSIDE TROUBLE / WIRE TO TRAILER I DID REFUSE A TR IN A BANK (FUSE WORE INTO), REF TR.	1	0
FORCED INTERR	CH	LB 02	41257	GW2	56601057	320031180028	T	4/28/2003	094	69	1	69	UNKNOWN	UNKNOWN	5715 BACHER S	1	TF	566010572				REF TR.	1	0
FORCED INTERR	BL	UL 15	10367	71CT	51560104	120031180052	T	4/28/2003	095	196	1	196	UNKNOWN	UNKNOWN	6301 RICHMONE	1	BU	515601046				REPLACED A 75 KVA 277/480 TRANSFORMER, RPLD BAU TR.	1	0
FORCED INTERR	KY	MAR41	24820	38LA	45578124	120031180054	F	4/28/2003	1001	65	3	195	LIGHTNING ARRE	LTNG ARRS	2100 BAKER	1	LF	38LA				REPLACED A BLOWN LIGHTNING ARRESSTOR CAUSED BY VINES; REF LF REF TR. BJH	1	0
FORCED INTERR	CH	HR 03	41046		54599527	220031180032	L	4/28/2003	1001	187	1	187	CONTRACTOR-N	CON-NT HLF	6003 HIRSCH RI		SC		PD			STUBBED UP 45'4 POLE THAT WAS HIT & BROKEN BEFORE TODAY, ALSO PICKED UP # 4 3/C TW SEC CROSSING HIRSCH, PAU SEC-1 CUST, STUBBED UP PL. MEK	1	0
FORCED INTERR	BL	HE 05	11653	7CG	52576381	120031180056	T	4/28/2003	100	40	7	280	LIGHTNING	LIGHTNING	6035 GLEN COV	1	TF	525763812				RE-FUSED THE POWER TRANSFORMER CUSTOMER SAID IT HAS BEEN OUT FOR A WHILE. PROBABLY PREVIOUS WEATHER, REF TR.	1	0
FORCED INTERR	HM	HB 49	20093	S2270	55678416	220031180039	L	4/28/2003	102	42	1	42	OH SEC/DR CL H	OH SC CL-H	9026 MARTIN LU	1	DR					RPLD CONN @ WH,	1	0
FORCED INTERR	MP	OA 07	41606	Y49S	56599062	220031180044	T	4/28/2003	103	28	1	28	BU DISC OR BARI	DISC/BARRL	87 1/2 OATES	1	TF	565990628				REFUSED AND DISC. @ TRX -BARREL; REF TR; RPLD BAU BARREL ON TR; MEK	1	0
FORCED INTERR	BL	JN 05	10013		50551388	120031180069	L	4/28/2003	104	57	1	57	UNKNOWN	UNKNOWN	9333 HARWIN D		MT					FOUND BAD METER, REPLACED OLD METER #627061674 NEW METER # 623608867 TYPE SV4SN CLASS 200 AMPS 30 UNABLE TO GET READING ON OLD METER, RPLD MTR.	1	0
FORCED INTERR	SU	DL 45	14094		48507354	120031180084	T	4/28/2003	111	47	6	282	BU DISC OR BARI	DISC/BARRL	1823 SUGAR CF		TF	485073545				REPLACED BURNED UP FUSE BARREL ON 75 KVA ., RPLD BAU BARREL ON TR;	1	0
FORCED INTERR.	SH	CC 03	31661	37CF	54517257	320031180042	F	4/28/2003	1121	66	54	3564	UNKNOWN	UNKNOWN	4610 ALLISON R	1	LF	37CF				REF LF	1	0
FORCED INTERR	BL	CR 06	45000	32F	53577445	120031180088	T	4/28/2003	1131	29	5	145	UNKNOWN	UNKNOWN	2018 N MEMORI	1	TF	535774457				REF TR.	1	0
FORCED INTERR	SH	CC 03	10834	60FP	54511467	120031180090	T	4/28/2003	114	74	3	222	OH SEC/DR CL H	OH SC CL-H	12919 SOUTHBF	2	SC	545114676				CORROSION ON CLAMP AT TRF RPLD CONN @ TR.	1	0
FORCED INTERR	BL	BR 03	10488	W38	52547452	120031180095	T	4/28/2003	1151	42	6	252	BU DISC OR BARI	DISC/BARRL	2931 S BRAESW	1	TF	525474527				REPLACED BURNED UP FUSE BARREL ON 25 KVA POWER POT UNABLE TO CHECK VOLTAGE AT 2031 BRAESWOOD BAD DOG IN BACK YARD RPLD BAU BARREL ON TR. BJH	1	0
FORCED INTERR	HM	LW 41	43258	N65K	57634367	320031180055	T	4/28/2003	123	232	7	1624	OH SEC/DR CL H	OH SC CL-H	12207 CURRIN F	2	SC	578343626				RPRD SEC CONN @ PED->1 CUST	1	0
FORCED INTERR	MP	MP 03	41364	49LC	55557468	220031180075	T	4/28/2003	131	21	1	21	BU DISC OR BARI	DISC/BARRL	7026 LAWNDALI	1	TF	555574689				REFUSED LTR TRX -BARREL; REF TR; RPLD BAU BARREL ON TR; BJH	1	0
FORCED INTERR	CH	UV 04	41769	J67H	58589531	320031180060	T	4/28/2003	131	39	14	546	UNKNOWN	UNKNOWN	14522 GAINESVI	1	TF	585895319				REF TR.	1	0
FORCED INTERR	MP	CL 03	40472	A11F	55582060	220031180080	L	4/28/2003	131	61	1	61	HUMAN ERROR	HUMN ERRC	5429 SAN JUAN	1	SC					RPLD SEC CONN @ PL-1 CUST	1	0
FORCED INTERR	HM	LA 01	41219		55632321	220031180082	T	4/28/2003	132	54	1	54	UNKNOWN	UNKNOWN	12037 EASTEX F		TF	566323215				REFUSED 25 LIGHTEA TRNS-- BROKE FUSE, REF TR.	1	0
FORCED INTERR	SB	TO 11	21784	19MP	51600394	120031180109	F	4/28/2003	132	54	10	540	HUMAN ERROR	HUMN ERRC	W 43RD BTWN	1	LF	19MP			PR	LF PL LEANING A LITTLE BUT ENOUGH TO ADD SLACK TO SLACK SP LAT SO THAT HSIDE OF TRF SPH CONTACTED A PH PRI AND BLEW LN FUSE- RPRD PRI & HSIDE STAIGHTEN PL OR RESA	1	0
FORCED INTERR	SB	DH 01	21511	U80V	51603563	220031180084	T	4/28/2003	134	69	6	414	UNKNOWN	UNKNOWN	5341 ANTOINE I	1	TF	516035637				FUSE PULLED INTO ON POWER TRANS; REF TR; BJH	1	0
FORCED INTERR	GA	AL 10	30041	72DM	61411401	320031180068	F	4/28/2003	1421	44	23	1012	SQUIRREL	SQUIRREL	12527E BAR DR	1	LF	72DM				REF LF SQUIRREL IN 50 CSP 5 CSP TRANS BEHIND THIS LF NO SWITCHES NO WLP REF LF	1	0
FORCED INTERR.	SU	BAR43	11873		47555576	120031180128	T	4/28/2003	142	145	8	1160	BIRD	BIRD	2927 WESTHOL		TF	475555767				REPLCAED K MATE, REF TR.	1	0
FORCED INTERR	MP	MP 01	41378	F24G	56560512	220031180092	T	4/28/2003	142	28	8	224	BU DISC OR BARI	DISC/BARRL	1314 76TH	1	TF	565605121				REF TR.	1	0
FORCED INTERR	SB	EC 11	21753	A75U	50582058	120031180132	T	4/28/2003	1451	58	4	232	BU DISC OR BARI	DISC/BARRL	11513 ECHO HO	1	TF	505820587				Fuse broke. Wasn't blown. REF TR.	1	0
FORCED INTERR.	SH	SP 01	31817	I97K	58534581	320031180069	T	4/28/2003	1451	26	10	260	BU DISC OR BARI	DISC/BARRL	2916 BURKE RD	1	TF	585345814				REFUSED PWR. TRX -FUSE BROKE; REF TR.	1	0
FORCED INTERR	SB	WD 45	21566		47585273	120031180136	T	4/28/2003	151	66	2	132	BIRD	BIRD	14100 OLD KAT		PR	475852733				WOLF IN PLACE, RPLD LIMITER @ TR, REF TR.	1	0
FORCED INTERR	SH	CG 03	31391		56537473	320031180072	T	4/28/2003	151	26	1	26	BU DISC OR BARI	DISC/BARRL	7211 EASTHAVE		TF	565374730				RPLD BAU BARREL ON TR.	1	0
FORCED INTERR.	SB	EC 05	21705	R46	50586518	120031180140	F	4/28/2003	152	49	1	49	UNKNOWN	UNKNOWN	8856 WESTVIEV	1	LF	R46				REF LF.	1	0
FORCED INTERR	CY	KL 45	22439	26FE	48653368	220031180102	T	4/28/2003	153	270	10	2700	LIGHTNING ARRE	LTNG ARRS	11558 CYPRESS	1	TF	486533682				REPLACED 19.9 OH LIGHTENING ARRESTOR ON 100KVA, REF TR; RPLD LIGHTNING ARRESTOR	1	0
FORCED INTERR	SH	CC 01	30174		54525360	320031180076	T	4/28/2003	1541	136	1	136	BU DISC OR BARI	DISC/BARRL	5021 SOUTH AC		DB	545253609				REPLACED 12 KV SWITCH; RPLD BAU DISC-TF NOT BLOWN.	1	0
FORCED INTERR.	GP	FR 44	21402		51632141	220031180104	T	4/28/2003	155	107	5	535	VINES	VINES	5806 FAIR FORE		TF	516321416				CHANGED LIMETER & REFUSED 50kVA T/R, RPLD LIMITER @ TR; REF TR.	1	0
FORCED INTERR	BL	GN 09	40915	MT1	53551153	120031180145	T	4/28/2003	161	60	1	60	CUST EQP RELA	CUST RLTD	2116 W HOLCO	1	TF	535511538				RESET TR.	1	0
FORCED INTERR	GP	LK 04	21874	N23W	52623524	220031180115	F	4/28/2003	181	0	0	0	UNKNOWN	UNKNOWN	8719 BRACKLEY	2	LF	N23W	PR			S.O. #8237 BAD SPAN OF PRI BAD UNDER TERMINATOR AT X END; REF TP ISOL URD PR, MSG TO SC TO MAKE REPAIRS WHEN POSSIBLE SUBCASING COMPLETE MGJ	1	0
FORCED INTERR.	GP	LK 04				220031180115	F	4/28/2003	181	162	16	2592	UNKNOWN			2	LF	N23W					0	0
FORCED INTERR.	CY	TB 45	21046	43ABC	45695518	220031180122	T	4/28/2003	185	132	5	660	HUMAN ERROR	HUMN ERRC	20503 ROSEHILI	1	TF	456955165				IST-Cust Notified; IST-Cust's Wire., REF TR.	1	0
FORCED INTERR	SH	SP 02	30971	8LX	58540178	320031180091	T	4/28/2003	191	33	3	99	UNKNOWN	UNKNOWN	801 ALTA VISTA	1	TF	585401785				REFUSED TRANSFORMER, REF TR.	1	0
FORCED INTERR	HC	FD 16	10853	PZ2	51534130	120031180167	L	4/28/2003	202	145	1	145	OH SEC/DR CL H	OH SC CL-H	5427 HUMMINGI	1	DR					RMVD TREE/LIMBS FROM DROPS; GUY WIRE NEEDS TO BE PULL AND REPLACE ANCHOR, RPLD CONN @ WH.	1	0
FORCED INTERR.	HC	BR 13	10522	6M7	51547025	120031180168	T	4/28/2003	202	55	9	495	BU DISC OR BARI	DISC/BARRL	5002 N BRAESW	1	TF	515470258				REFUSED TWO TRANSF REF TR.	1	0
FORCED INTERR	HC	BR 13	10522	538	51546054	120031180168	T	4/28/2003	2041	45	2	90	BU DISC OR BARI	DISC/BARRL	9000 S RICE AVI	1	TF	515460545				REFUSED TWO TRANSF, REF TR.	1	0
FORCED INTERR	CY	TB 45	21043	60EA	47704465	220031180133	F	4/28/2003	212	77	4	308	LIGHTNING	LIGHTNING	FM 149 @ THEIS	1	LF	60EA				REPLACED BAD BARREL ON B PHASE OF 3 PHASE LF 60EA, RPLD BAU BARREL ON LF, REF LF	1	0
FORCED INTERR	SH	PA 01	30749		57556344	320031180097	T	4/28/2003	213	38	1	38	UNKNOWN	UNKNOWN	410 RICHEY ST		TF	575563440				REFUSED NORTH POWER TRANS,IN AN CLOSED DELTA BANK,_MELTED FUSE CUSTOMERS HAVING PROBLEMS WITH WALK IN FREEZER, BREAKER IS TRIPPING. ..DONT KNOW IF IT MELTED	1	0
FORCED INTERR.	CH	UV 02	31309	15GU		320031180103	F	4/28/2003	224	272	97	26384	UNKNOWN	UNKNOWN	13830 MAISEMO	1	LF	15GU	PR			BAD SPAN PRIMARY AT 13828 MAISEMORE STOOD OFF X AND STOOD OFF Y AT 13818 MAISEMORE ON SWITCHING 8239, REF TP ISOL URD PR.	1	0
FORCED INTERR	CH	UV 07	41795	N59K	59590380	320031180104	F	4/28/2003	224	101	43	4343	LIGHTNING	LIGHTNING	14802 S SILVER	1	LF	N59K				ALSO TRIMMED TREES AWAY FROM LINE FUSE REF LF	1	0
FORCED INTERR	CH	BE 02	40223	B47L	55600390	320031180105	T	4/28/2003	224	37	4	148	LIGHTNING	LIGHTNING	7718 LAVENDEF	1	TF	556003907				REFUSED A 15 KVA 7200 120 240 V TRANSFORMER, REF TR.	1	0
FORCED INTERR	CH	UV 07	41786	R97C	58599377	320031180106	F	4/28/2003	225	0	0	0	PRIMARY CONDU	PRIMARY	1207 CASTLE GI	2	LF	R97C	PR			BAD X PRI AT 1343 CASTLE GLEN ISOLATED X CLOSED Y AT 1319 CASTLE GLEN ISOLATED Y CLOSE TP ON ORDER8240.	1	0
FORCED INTERR	CH	UV 07				320031180106	F	4/28/2003	225	159	14	2226	PRIMARY CONDU			2	LF	R97C					0	0
FORCED INTERR	CH	UV 07				320031180106	F	4/28/2003	225	159	7	1113	PRIMARY CONDU			2	LF	R97C					0	0
FORCED INTERR	BA	HNY03	41014	N82E	62809032	320031180108	F	4/28/2003	230	30	42	1260	LIGHTNING	LIGHTNING	7507 SEMINOLE	2	LF	N82E				REF TP;	1	0
FORCED INTERR	SH	SP 08	30976	K46G	58535058	320031180115	F	4/28/2003	234	59	32	1888	LIGHTNING	LIGHTNING	3918 SANDLEW	2	LF	K46G				REFUSED TP K46G, REF TP	1	0
FORCED INTERR	SH	SP 06	30690	I73R	58534053	320031180117	F	4/28/2003	234	50	43	2150	LIGHTNING	LIGHTNING	4006 WILLOWVI	2	LF	I73R				REFUSED TERMINAL POLE,.....WEATHER REF TP	1	0
FORCED INTERR	SH	SP 08	30990	G72N	58537067	320031180118	F	4/28/2003	234	34	22	748	LIGHTNING	LIGHTNING	4211 AZTEC ST	2	LF	G72N				REFUSED TP G72N, REF TP	1	0
FORCED INTERR	SH	SP 01	31817	I86K	58534543	320031180119	F	4/28/2003	234	76	60	4560	LIGHTNING	LIGHTNING	1610 DABNEY D	1	LF	I86K				REFUSED LF REF LF	1	0
FORCED INTERR.	BA	BT 04	40414	K59Z		320031180120	F	4/28/2003	2351	52	309	16068	LIGHTNING	LIGHTNING	1005 PARKWAY	1	LF	K59Z				REF LF.	1	0
FORCED INTERR	SH	CA 02	30589		59530598	320031180126	T	4/28/2003	235	81	3	243	LIGHTNING	LIGHTNING	5229 SPENCER		TF	595305961				REFUSED 75 LIGHTER REF TR.	1	0
FORCED INTERR	BA	CD 06	30592		64562333	320031190005	T	4/29/2003	000	71	5	355	LIGHTNING	LIGHTNING	300 EDGEWOOI		TF	645623323				REF TR.	1	0
FORCED INTERR	BA	FT 01	40654	Y93G	61535333	320031190006	F	4/29/2003	000	178	19	3382	SPLICE	SPLICE	10929 PECAN DI	2	LF	Y93G	PR			FOUND BAD URD PRI @ TRANS # 87 @ 3613 EAST REDBUD ON URD SO 8241 REF TP ISOL URD PR.	1	0
FORCED INTERR	SH	CA 02	30589	G3D	59540036	320031190006	F	4/29/2003	000	98	25	2450	LIGHTNING	LIGHTNING	PANSY, N OF SI	1	LF	G3D				REFUSED MIDDLE PHASE OF LF REF LF	1	0
FORCED INTERR	SH	FT 02	30398	B73L	60530511	320031190011	F	4/29/2003	001	53	13	689	LIGHTNING	LIGHTNING	7426 CARRIE LN	1	LF	B73L				REFUSED L-F B-73-L......WEATHER, REF LF	1	0
FORCED INTERR	SH	CG 06	30204	H23D	57534194	320031190014	T	4/29/2003	005	141	5	705	LIGHTNING	LIGHTNING	667 MARLEEN	1	BU	575341943				REPLACED TRANSFORMER, RPLD BAU TR.	1	0
FORCED INTERR	GA	AL 06	30032		60429375	320031190020	T	4/29/2003	015	40	3	120	LIGHTNING	LIGHTNING	12727 4 1/2		TF	604293758				REFUSED TRANS REF TR.	1	0
FORCED INTERR	GA	STWO	35350	4CE	62314570	320031190022	T	4/29/2003	021	153	3	459	LIGHTNING	LIGHTNING	4219 MASON	1	TF	623145700	DB			REPLACED BAD SWITCH ON TRANS RPLD BAU DISC-TF BLOWN.	1	0
FORCED INTERR	SH	MY 02	30044	K86F	57494029	320031190023	F	4/29/2003	022	94	20	1880	LIGHTNING	LIGHTNING	1914 SLEEPY H	1	LF	K86F				REFUSE LF K86F 20T REF LF	1	0
FORCED INTERR	BL	KB 06	10160	M9P	52568376	120031190001	F	4/29/2003	023	61	40	2440	LIGHTNING	LIGHTNING	2322 BRANARD	1	LF	M9P				REF LF	1	0
FORCED INTERR	GA	GA 10	30024	2WE	67373318	320031190025	F	4/29/2003	024	41	49	2009	LIGHTNING	LIGHTNING	2513 CEDAR ST	1	LF	2WE				REFUSED NORTH PHASE OF LINE FUSE, REF LF	1	0
FORCED INTERR	BA	BT 04	40414	90DN	63567591	320031190027	T	4/29/2003	031	284	13	3692	LIGHTNING	LIGHTNING	214 E PEARCE	1	BU	635675910				REPLACED TRANSFORMER, RPLD BAU TR.	1	0
FORCED INTERR	GA	LM 04	31486	1KB	64396542	320031190029	F	4/29/2003	032	150	25	3750	O/H PRIMARY CL	OH PR CLMF	7203 JEANETTE	1	LF	1KB	PR			PICKED UP 1 SPAN OF # 4 CU STRANDED 1 SPAN S OF LF REF LF PAU PR-FUSE BLOWN.	1	0

FORCED INTERR	GA	STWO	31001	57CB	65354020	32003190003	F	4/29/2003	0331	28	72	2016	LIGHTNING	LIGHTNING	13039 JOHN RE	1	LF	58CB							REFUSED LINE FUSE 58CB #57 REF LF	1	0
FORCED INTERR	RS	LV 03	30574	A88K	56380400	32003190031	F	4/29/2003	0334	162	9	1458	LIGHTNING	LIGHTNING	107 MOCKINGBI	1	LF	A88K							REFUSED LINE FUSE; REF LF	1	0
FORCED INTERR	RS	LV 03	30594	H83F	55390450	32003190032	F	4/29/2003	0359	119	20	2380	LIGHTNING	LIGHTNING	8500 COUNTY R	1	LF	H83F							REFUSED LINE FUSE; REF LF	1	0
FORCED INTERR	HC	HOCO	11162	A78G	51539030	32003190003	F	4/29/2003	0447	91	11	1001	TREE CLEARANC	TREE CLEAI	4722 SPELLMAN	1	TF	515360348							Trim TREES REFUSE 50KVA TF TREE TRIM ASAP, REF TR.	1	0
FORCED INTERR	SH	CG 06	30204	H23D	57534165	32003190034	T	4/29/2003	0444	75	3	225	LIGHTNING	LIGHTNING	879 MARLEEN	1	TF	575341633							NEED TO REPLACE 8 KV LIGHTENING ARRESTOR ON TRANSFORMER IN EASEMENT REF TR.	1	0
FORCED INTERR	SH	MY 02	30044	K86F	57494020	32003190036	T	4/29/2003	0559	80	4	320	VINES	VINES	2610 TAYLOR LI	1	TF	574940299							REFUSED A 50 C3P TRANS., REF TR.	1	0
FORCED INTERR	SH	PA 06	30787	7GT	58541360	32003190043	F	4/29/2003	0723	48	25	1200	UNKNOWN	UNKNOWN	1724 1/5 PASA B	1	LF	7GT							REFUSED LF; REF LF	1	0
FORCED INTERR	SH	GA 04	30166	52ACP	59525460	32003190044	T	4/29/2003	0723	42	1	42	BU DISC OR BARI	DISC/BARRL	4822 JANA LN	1	TF	595254655							REFUSED MID TRX 4FUSE BROKEN REF TR.	1	0
FORCED INTERR	SU	IM 47	12107	S3901	48511290	32003190006	T	4/29/2003	0728	64	3	192	SQUIRREL	SQUIRREL	302 W ALKIRE L	1	TF	485112967							refused it out by equipment it already has all prot. REF TR	1	0
FORCED INTERR	FB	WR 13	11287	94KK	37381420	32003190007	F	4/29/2003	0730	47	47	2209	SQUIRREL	SQUIRREL	2623 ALABAMA	1	LF	94KK							REFUSED 1 PHASE OF LF IN KK - SQUIRREL. REF LF;	1	0
FORCED INTERR	BA	FT 07	31340	48CF	60536347	32003190045	F	4/29/2003	0731	63	1	63	BU DISC OR BARI	DISC/BARRL	3337 CANADA	1	LF	48CF							REPL VBH UP FUSE BARRELON MIDDLE PH LF, REF LF.	1	0
FORCED INTERR	BA	BT 04	40414	33GL	63567581	32003190047	T	4/29/2003	0800	121	4	484	UNKNOWN	UNKNOWN	205 E TEXAS AV	1	BU	835675812							replaced trans and its isolated wip. RPLD B/U TR. RPLD LIGHTNING ARRESTOR.	1	0
FORCED INTERR	BL	KB 04	10151	2PK	52569370	32003190006	L	4/29/2003	0800	71	1	71	OH SEC/DR CL HI	OH SC CL-H	2133 BRANARD	1	SC								REPLACED BAD CLAMPS @ POLE /TIGHTENED CONN @ BKR BOX / LEFT BCRV ON / NOTIFIED. RPLD CONN @ PL.	1	0
FORCED INTERR	SU	FD 15	10895	P17C	50630335	32003190002	F	4/29/2003	0811	56	1	56	CONTRACTOR (H	CON-HLP	8801 GUSTINE	1	LF	P17C							CENTERPOINT CONTRACTOR. MOWER'S HIT GUY WIRE SLAPPING PHASES TOGETHER. REF LF.	1	0
FORCED INTERR	SH	SP 01	30711	199K	58533480	32003190005	F	4/29/2003	0815	72	1	72	LIGHTNING	LIGHTNING	3409 SPENCER	1	PR	199K							REPLACED HIGHSIDE JUMPER ON U SWITCH ONLY-- LIGHTING LAST NIGHT. RPLD B/O PR JUMPER-FUSE NOT BLOWN. MEK	1	0
FORCED INTERR	FB	OB 44	13231	36PN		12003190010	F	4/29/2003	0825	49	12	588	UNKNOWN	UNKNOWN	12050 FM 1464	1	LF	36PN							REF A PHASE OF 36PN. REF LF	1	0
FORCED INTERR	CH	UV 08	42004		58612190	32003190005	T	4/29/2003	0825	75	4	300	UNKNOWN	UNKNOWN	8110 ROYALWO	T	TF	586121945							REF TR.	1	0
FORCED INTERR	SB	ADK43	20959	EC3		12003190011	F	4/29/2003	0829	53	137	7261	TREE CLEARANC	TREE CLEAI	TEAGUE @ TAN	1	LF	EC3							REFUSED 1 TRANS STEP POT ALL BACK ON TREES SOUTH TRANS. REF TR. MEK	1	0
FORCED INTERR	SB	WT 06	22393	U7C	50578540	32003190012	F	4/29/2003	0829	58	23	1334	FLLNG TREE IN E	TREE FL/IE	10660 MEMORIA	1	LF	U7C							TREE CREW TRIMMING TREES AT 825 WELLESLEY LIMB FELL ON PHASES GOT THEM TOGETHER AND BLEW LINE FUSE. REF LF	1	0
FORCED INTERR	GA	STWO	31011	E36D	64359030	32003190050	F	4/29/2003	0850	43	9	387	BU DISC OR BARI	DISC/BARRL	13722 SAN LUIS	1	LF	E36D							REF LF REPL BURNT UP JOBLYN FUSE BARREL. REF LF.	1	0
FORCED INTERR	RS	MU 01	30736	H90F	58410470	32003190056	F	4/29/2003	0900	35	19	665	UNKNOWN	UNKNOWN	5006 RIVERVIEV	1	LF	H90F							REFUSE LINE FUSE; REF LF	1	0
FORCED INTERR.	MP	WV 03	41811	K3M	55586430	22003190017	F	4/29/2003	0900	31	29	899	SQUIRREL	SQUIRREL	6907 GAINESVIL	1	LF	K3M							REF LF.	1	0
FORCED INTERR	CY	WL 42	21158	S3267	40691360	22003190018	T	4/29/2003	0931	97	5	485	TREE CLEARANC	TREE CLEAI	1318 C ST	1	SC	406913698							TRIM TREES AND REPAIR BROKE NEUTRAL IN 4M TWIST SECONDARIES; RPRD SEC CONN @ PL->1 CUST;	1	0
FORCED INTERR	SH	FW 03	30436	P88B	58477530	32003190065	F	4/29/2003	0934	31	2	62	UNKNOWN	UNKNOWN	4201 FRIENDSW	1	LF	P88B	TF	584775358					REPLACE FUSE BARREL IN LINE FUSE, REF LF. RPLD B/U BARREL ON TR. MEK	1	0
FORCED INTERR.	HC	HM 08	11051	C1M	54545050	12003190022	T	4/29/2003	0944	27	9	243	BU DISC OR BARI	DISC/BARRL	5025 MAYFLOW	1	TF	545450560							REFUSED TRX 4BARRELL REF TR. RPLD B/U BARREL ON TR. MEK	1	0
FORCED INTERR.	BZ	RT 01	30902	H43R	55312261	32003190066	F	4/29/2003	0947	60	1	60	LIGHTNING	LIGHTNING	27601 FM 2004	1	LF	37RN							REFUSED LINE FUSE, REF LF MEK	1	0
FORCED INTERR	HC	BL 06	10790	860A	51523410	12003190022	T	4/29/2003	0948	27	8	216	SQUIRREL	SQUIRREL	5507 DRYAD	1	TF	515234101							REFUSED POWER POT... HAD WILDLIFE PROTECTION. REF TR.	1	0
FORCED INTERR	SH	CC 01	30174	LB2	54528320	32003190067	T	4/29/2003	0951	62	2	124	LIGHTNING	LIGHTNING	10960 MARTIN L	1	TF	545283206							REFUSED CENTER POT. REF TR. MEK	1	0
FORCED INTERR	SH	SB 01	31653	U34	58547241	32003190072	F	4/29/2003	1020	36	24	864	BU DISC OR BARI	DISC/BARRL	2608 PASADENA	1	LF	U34							RPLD B/U BARREL ON LF	1	0
FORCED INTERR	MP	WO 04	41845		52603274	32003190033	T	4/29/2003	1028	47	8	376	BU DISC OR BARI	DISC/BARRL	1349 W 43RD	T	TF	528032742							REPLACED A BURNED UP FUSE BARREL. RPLD B/U BARREL ON TR.	1	0
FORCED INTERR	HM	LW 44	20113	95JB	55658380	22003190036	T	4/29/2003	1040	5	1	5	UNKNOWN	UNKNOWN	6809 BENDER R	1	TF	556583808	PR						TOOK BANK OFF LINE FEEDS WATER WELL. ALL SERVICE BACK ON; RPLD LIMITER @ TR; REF TR.	1	0
FORCED INTERR	SB	WO 07	21620	RT4	51605270	12003190037	T	4/29/2003	1041	48	6	276	FLLNG TREE IN E	TREE FL/IE	5122 SAXON DR	1	TF	516052771							tree crew trimming trees and limb fell on secondaries blew trans fuse. REF TR	1	0
FORCED INTERR.	BL	CN 11	10978	31FP	52548450	12003190042	F	4/29/2003	1142	35	1	35	FOREIGN MATER	FRGN MATR	8330 MAIN	1	LF	31FP							REFUSED LF 31FP 30T SOUTH PHASE. REF LF. RON	1	0
FORCED INTERR	GP	SA 41	12443	A24K	49616290	12003190044	T	4/29/2003	1144	37	5	185	SQUIRREL	SQUIRREL	10118 GROVER	1	TF	496152958							REFUSED TRANS BACK ON SQUIRREL. REF TR.	1	0
FORCED INTERR	SH	DR 02	30267	81GD	56536520	32003190077	T	4/29/2003	1152	28	10	280	UNKNOWN	UNKNOWN	8470 GULF FWY	1	TF	565365225							REFUSED NORTH PHASE POWER POT IN CLOSED DELTA BANK / CALLS / NEED LIGHTENING ARRESTOR REPLACED ON COMB. DISCONNECT FEEDING SAME POWER POT / TRUCK ACCESSIBLE	1	0
FORCED INTERR	SH	PE 01	30804	F27Y	55495020	32003190078	T	4/29/2003	1154	14	5	70	UNKNOWN	UNKNOWN	8010 BROADWA	2	TF	554950258							REFUSED TRANS. REF TR.	1	0
FORCED INTERR	GA	STWO	31001	N503		32003190076	F	4/29/2003	1158	41	168	6888	BU DISC OR BARI	DISC/BARRL	12704 BERMUDA	1	DB	N503							REPL BAD DISC. ON THE LINE FUSE. RPLD B/U DISC-LF NOT BLOWN.	1	0
FORCED INTERR	CH	LB 01	41254	58HS	55603140	32003190086	T	4/29/2003	1200	28	12	336	BU DISC OR BARI	DISC/BARRL	8715 HOFFMAN	1	TF	558031457							RPLD B/U BARREL ON TR.	1	0
FORCED INTERR	SH	WE 08	31281	C34F		32003190084	F	4/29/2003	1240	203	43	8729	CONTRACTOR-N	CON-NT HLF	BROADWAY @	1	PR	G22Y							PM PR-FUSE BLOWN.	1	0
FORCED INTERR	KY	FZ 46	22803		45606350	12003190066	T	4/29/2003	1330	128	6	768	UNKNOWN	UNKNOWN	19503 CYPRESS		DB	458063552	SC						RPLAC DISCONNECT AND LUGS; RPLD B/U DISC-TF NOT BLOWN. RPLD CONN @ TR.	1	0
FORCED INTERR	MP	WO 10	41869	A50L	52598310	22003190061	L	4/29/2003	1330	49	1	49	OH SEC/DR CL HI	OH SC CL-H	935 W 26TH RR	1	DR		SC						FOUND LIGHTERS MELTED TOGETHER AT WIH. HAD TO GO AT POLE TO PULL APART. REPLACED CLAMPS AT POLE AND WIH. RPLD CONN @ WIH. RPLD CONN @ PL;	1	0
FORCED INTERR	CY	PI 45	28126	DGGQ	44743320	22003190063	T	4/29/2003	1352	84	4	336	SQUIRREL	SQUIRREL	28811 FORESTI	1	TF	447432092							REFUSED TRANSFORMER THE TRANSFORMER HAS WILD LIFE ALREADY. REF TR.	1	0
FORCED INTERR	MP	AN 09	40054	43F	53603480	22003190064	F	4/29/2003	1400	42	59	2478	LIGHTNING	LIGHTNING	526 SPRILL	1	LF	43F							REF LF	1	0
FORCED INTERR	RS	LV 03	30574	T68R	56380530	32003190094	T	4/29/2003	1411	86	1	86	LIGHTNING	LIGHTNING	8901 HIGHWAY	1	TF	563805391							REFUSED TRANS. REF TR.	1	0
FORCED INTERR	GP	FR 44	21407	M32Z	50625490	22003190070	F	4/29/2003	1444	91	79	7189	LIGHTNING	LIGHTNING	7703 WOODSMI	2	LF	M32Z							REPLACED BAD LIGHTING ARESTOR / REPAIRED T ERMINATOR PUT LOOP BACK TO NORMAL. REF TP. RPLD LIGHTNING ARRESTOR.	1	0
FORCED INTERR	MP	GS 22	40770	6S4	54578080	22003190077	L	4/29/2003	1451	41	1	41	UNKNOWN	UNKNOWN	201 ESTELLE	I	DR								REPLACED BAD CLAMP @ WEATHERHEAD / CHALK. RPLD CONN @ WIH.	1	0
FORCED INTERR	SH	MY 04	30571	B36J	56477530	32003190098	T	4/29/2003	1457	16	1	16	UNKNOWN	UNKNOWN	4344 S MAIN	1	TF	564775304							REFUSED TRANS. REF TR.	1	0
FORCED INTERR	BA	BT 04	40414	B49F	63567560	32003190096	T	4/29/2003	1522	16	6	96	UNKNOWN	UNKNOWN	103 E TEXAS AV	1	TF	635675683							REF TR.	1	0
FORCED INTERR	HC	HM 05	11029	TA4	54530140	12003190081	T	4/29/2003	1522	130	3	390	FLLNG TREE IN E	TREE FL/IE	3610 REED	1	SC	545301457							RPRD CONN @ TR.	1	0
FORCED INTERR	CY	KL 44	21989		45679180	22003190076	T	4/29/2003	1522	183	1	183	COLLISION	COLLISION	17631 HUFFMEI		BU	456791800	PR		DR		PD		REPLACED 25KVA 18 BV30-240 OH TR AND 25' POLE NO-ONE HERE TO GET DAMAGE INFO. RPLD B/U TR. RPLD LIMITER @ TR. RPLD DR. RPLD SEC-1 CUST. RPLD PL. RPLD LIGHTNING ARRES	1	0
FORCED INTERR	SH	DE 01	30236		59556220	32003190100	T	4/29/2003	1534	47	1	47	BU DISC OR BARI	DISC/BARRL	1716 W 13TH		TF	595562233							REFUSED TR FUSE. REF TR.	1	0
FORCED INTERR	HC	HOCO	11178	71A	51518520	12003190083	T	4/29/2003	1538	18	2	36	SQUIRREL	SQUIRREL	5429 1/2 W ORE	1	TF	515185202							REFUSED LIGHTER TR IN OPEN DELTA BANK NEEDS WIL PROT B/C CONN TRUCK ACCESSIBLE. REF TR. NO BUSCARE NEEDED. MSG SENT TO SERVICE CEN	1	0
FORCED INTERR	MP	BG 09	41967	D3D	54551310	22003190078	T	4/29/2003	1540	48	3	144	UNKNOWN	UNKNOWN	3402 BINZ	1	TF	545513173							REFUSED POWER POT IN OPEN DELTA BANK / CALLS. REF TR.	1	0
FORCED INTERR.	GA	AL 10	30043		61413240	32003190102	T	4/29/2003	1547	81	2	162	UNKNOWN	UNKNOWN	11929 HIGHWAY		TF	614132457							REF TR.	1	0
FORCED INTERR	SH	WEBH	30309	73CS	60480410	32003190102	F	4/29/2003	1600	42	1	42	BU DISC OR BARI	DISC/BARRL	450 BLOSSOM	1	LF	73CS							REF LF.	1	0
FORCED INTERR	SH	CA 04	30166		59525470	32003190106	L	4/29/2003	1622	30	1	30	LIGHTNING	LIGHTNING	4720 JANA LN		SC									1	0
FORCED INTERR	SB	DH 04	21529	WD7	51603390	12003190085	L	4/29/2003	1626	143	1	143	CONTRACTOR-N	CON-NT HLF	5515 W 43RD	1	DR								REPLACED BAD ELECTRICIAN CONNECTIONS AT WEATHERHEAD. RPLD CONN @ WH.	1	0
FORCED INTERR.	SH	GV 04	11068	K85H	54526520	12003190090	T	4/29/2003	1630	136	3	408	FLLNG TREE IN E	TREE FL/IE	5114 RICKY	1	TF	545265246							REF TR.	1	0
FORCED INTERR	BL	BI 02	10055	HD3	51569270	12003190091	L	4/29/2003	1635	99	1	99	OH SEC/DR CL HI	OH SC CL-H	4819 RICHMONI	1	DR								RPLD CONN @ WH.	1	0
FORCED INTERR	MP	AN 03	40020	B6T	53609050	22003190068	T	4/29/2003	1646	52	5	260	UNKNOWN	UNKNOWN	219 KING	1	TF	536090560							REF TR. JBS	1	0
FORCED INTERR.	SH	SB 08	31062	81ABN	58544440	32003190112	F	4/29/2003	1700	42	26	1092	SQUIRREL	SQUIRREL	1707 JANE DR	1	LF	81ABN	TF	585444455					REFUSED LINE FUSE AND TRANSFORMER FEEDING 1707 JANE DUE TO SQUIRREL / TRANS ALREADY HAS WLF / CNLS. REF LF, REF TR.	1	0
FORCED INTERR	GP	AD 04	40073	SLB	52639070	22003190093	T	4/29/2003	1715	273	8	2184	UNKNOWN	UNKNOWN	527 PEACH SPR	1	BU	526380734	SC						REPLACED 50 KVA T 2/120-240 OH TR IN THE EABEMENT CAUSE WAS OLD ACIE. RPLD B/U TR. REF TR. RPRD SEC-1 CUST. RPLD LIGHTNING ARRESTOR.	1	0
FORCED INTERR	CY	PI 44	21031	T50K	46739570	22003190095	L	4/29/2003	1728	183	1	183	FALLING DEAD TI	TR FL/DEAD	7		1		DR						REPLACED 1/0 DROPS & LEFT OFF DUE TO METER LOOP DAMAGE. RPLD DR. RMVD TREE/LIMBS FROM DR. S-1 R-83605	1	0
FORCED INTERR	MP	BH 05	41557	D76B	54586120	22003190100	T	4/29/2003	1750	71	1	71	BU DISC OR BARI	DISC/BARRL	1505 JENSEN		1	DB		545861287					REF TR. RPLD B/U BARREL ON TR.	1	0
FORCED INTERR	BL	HT 03	10286	6NX		12003190096	F	4/29/2003	1815	93	3	279	UNKNOWN	UNKNOWN	6440 SOUTHWE	1	LF	K14U							REFUSED MIDDLE PHASE OF CHILD FUSE K 14 U #57 UNKNOWN. REF LF.	1	0
FORCED INTERR	CH	GP 03	40792	18VK	57576490	32003190116	T	4/29/2003	1830	195	9	1755	COLLISION	COLLISION	1712 PARKEY LI	1	TF	575764955	PD						NEEDS TO REPLACE 40 CLASS 2 POLE AND 37 5 TRANS AND DEAD END ANCHOR NEEDS TO GO IN MORNING ARAP ALL IN EASTMENT NEEDS STUBS POLE ON BROKEN POLE — JUST HAS RO	1	0
FORCED INTERR	SH	SP 01				32003190117	C	4/29/2003	1831	0	0	0	FLLNG TREE IN E	TREE FL/IE	1211 DUNSTAN		CL	SP01							NON 10% CREW IN ROUT TREE ON PRI @ 1211 DUNSTAN. CREWS REMOVING TREE LIMB FROM PRIMARY. ALL BUT ONE SECTION IS BACK ON PEK. SECTION 3 HR21. WPS	1	1
FORCED INTERR	SH	SP 01	3G165			32003190117	C	4/29/2003	1831	25	1293	32325	FLLNG TREE IN E				CL	SP01								0	0
FORCED INTERR	SH	SP 01	31621			32003190117	C	4/29/2003	1831	46	50	2300	FLLNG TREE IN E				CL	SP01								0	0
FORCED INTERR	SH	HA 03	30558	F79Y	57506415	32003190126	T	4/29/2003	1900	90	10	900	OH SEC/DR CL HI	OH SC CL-H	11031 SAGEWIN	1	SC	575064150							REPLACED BURSWORK ON TRANSFORMER. RPRD SEC-1 CUST.	1	0
FORCED INTERR	GA	STWO	31020		66366221	32003190127	T	4/29/2003	1910	40	2	80	BU DISC OR BARI	DISC/BARRL	3802 COVE VIEW		TF	663662216	DB						REPLACED BARRELL ON POWER POT. RPLD B/U DISC-TF BLOWN.	1	0
FORCED INTERR	SU	IM 47	12107		48512030	12003190113	T	4/29/2003	1950	130	3	390	TREE CLEARANC	TREE CLEAI	910 ALKIRE LAK		TF	485120372							REF TR.	1	0
FORCED INTERR	SH	SH 01	30894	PR6	57525530	32003190131	T	4/29/2003	2011	96	10	960	TREE CLEARANC	TREE CLEAI	602 EASTLAKE	1	TF	575255332							REF TR.	1	0
FORCED INTERR	MP	ES 02	40645		54568520	22003190102	T	4/29/2003	2015	63	2	126	BIRD	BIRD	110 1/2 TELEPH		TF	545685262							TR HAS WLF. REF TR.	1	0
FORCED INTERR	BZ	FP 02	30415	87GJ	56222310	32003190135	T	4/29/2003	2040	64	1	64	UNKNOWN	UNKNOWN	904 DEWEY	1	SC	562223189	DR						REPLACED BAD HOT LEG AT HOUSE-BAD HOT LEG AND NEU AT TRANS SALT CONT. RPLD CONN @ TR. RPLD CONN @ WH.	1	0
FORCED INTERR	FB	EB 05	11734	A3E	36483190	12003190116	F	4/29/2003	2047	56	4	224	SNAKE	SNAKE	2802 CO 291	1	LF	A3E							REMOVED SNAKE FROM TRANS SWITCH REFURED AEJ. REF LF	1	0
FORCED INTERR	SU	BAR4	12032	49CJ	47547070	12003190117	F	4/29/2003	2055	0	0	0	URD BUSHING	URD BSHING	8626 HEMLOCK	2	LF	49CJ	PR						FOUND BAD SPAN OF PRIMARY BETWEEN TRAN #13 AND TRAN # 12 PUT X ON STANDOFF IN TRAN 13 PUT Y ON STAND OFF IN TRAN #12 ALSO REPLACED Y ELBOW @ BUSHING IN TRAN # 20	1	0
FORCED INTERR	SU	BAR4				12003190117	F	4/29/2003	2055	198	46	9108	URD BUSHING			2	LF	49CJ								0	0
FORCED INTERR	SU	BAR4				12003190117	F	4/29/2003	2055	198	9	1782	URD BUSHING			2	LF	49CJ								0	0
FORCED INTERR	SH	GG 04	30542	44JM	55543140	22003190104	F	4/29/2003	2100	48	1	48	COLLISION	COLLISION	8024 HOGUE	1	LF	44JM							CAR HIT 45FT POLE INLINE BEHIND LINE FUSE, RPRD 30T POLE WE NEED TO BE STRAIGHTEN AND BRACE POLE MAYBE BROKE CAN BE DONE IN THE MORNING REF LF REDUCED CUST CI	1	0
FORCED INTERR	SH	GG 04	30542	99RQ		22003360171	F	4/29/2003	2100	48	4	192	COLLISION	COLLISION	NORTHDALE @	1	LF	99RQ							CAR HIT 45FT POLE INLINE BEHIND LINE FUSE, RPRD 30T POLE WE NEED STRAIGHTEN AND BRACE POLE MAYBE BROKE CAN BE DONE IN THE MORNING REF LF OUT CREATED BY QA (	1	0
FORCED INTERR	GA	HX 01	31547		62409300	32003190140	T	4/29/2003	2106	58	6	348	UNKNOWN	UNKNOWN	7825 N RAILROA		TF	624093027							REF TR.	1	0
FORCED INTERR	SU	QV 03	12861	82DQ	49495000	12003190121	F	4/29/2003	2123	59	11	649	BU DISC OR BARI	DISC/BARRL	HWY 8, E OF GL	1	LF	82DQ								1	0
FORCED INTERR	HM	HB 48	21524	44L	60693210	22003190106	F	4/29/2003	2215	79	31	2449	VINES	VINES	1220 SMITH	1	LF	44L	TF	606932135					REPLACED LIMITER ON A 25 19 8 KVA 120/240 OVER HEAD TRANSFORMER. REF LF. RPLD LIMITER @ TR. REF TR.	1	0
FORCED INTERR	SU	QV 02	12157	H17Z	50490530	12003190123	F	4/29/2003	2240	88	20	1760	SQUIRREL	SQUIRREL	2323 FAIRGREE	2	LF	H17Z							REFUSED T P. REF TP	1	0
FORCED INTERR	HC	SO 41	12619	61EK	52479190	12003190124	F	4/29/2003	2257	137	4	548	BU DISC OR BARI	DISC/BARRL	CO 48, BTW FRI	1	LF	61EK	DB						CHG OUT DISC FEEDING 4721 CR 48 BLEEDING OVER. REF LF. RPLD B/U DISC-TF NOT BLOWN. BRS	1	0
FORCED INTERR	GP	KDL42	2323A	P87L	51712230	22003200001	F	4/30/2003	0141	0	0	0	HUMAN ERROR	HUMN ERRC	22316 ACORN G	2	LF	P87L	BU	51712291C					REF TP. RPLD B/U TR.	1	0
FORCED INTERR	GP	KDL42				22003200001	F	4/30/2003	0141	205	39	7995	HUMAN ERROR			2	LF	P87L								0	0
FORCED INTERR	GP	KDL42				22003200001	F	4/30/2003	0141	443	1	443	HUMAN ERROR			2	LF	P87L								0	0
FORCED INTERR	MP	UN 08	10970	W6F	54546361	22003200002	T	4/30/2003	0230	46	11	506	UNKNOWN	UNKNOWN	5015 YELLOWS	1	TF	545463618								1	0
FORCED INTERR	GA	MDY01	31515		67372280	32003200001	T	4/30/2003	0240	38	8	304	BU DISC OR BARI	DISC/BARRL	12 E DANSBY DI		TF	673722859							REFUSED 50 KVA AFMR # FUSE LINK BROKE. REF TR.	1	0
FORCED INTERR.	MP	HM 10	11063	ID7	54541270	22003200005	F	4/30/2003	0310	75	9	675	LIGHTNING ARRE	LTNG ARRS	7219 SCOTT ST	1	LF	ID7	TF	545412708					REPL. BAD FUSE BARREL ON TRANS. RPLD B/U BARREL ON TR.	1	0
FORCED INTERR	GP	THW4	21905	X62J	48639490	22003200001	F	4/30/2003	0450	151	71	10721	URD ELBOW	URD ELBOW	10107 SANDS TI	2	LF	X62J	PR						REFUSED NORTH PHASE OF LF # REFUSED LIGHTER X# MR IN OPEN DELTA @ 7219 SCOTT ST. REF LF. REF TR. SENT MSG TO TAD. BRS	1	0
FORCED INTERR	KY	KT 45	22642		43572300	12003200002	T	4/30/2003	0511	113	4	452	TREE CLEARANC	TREE CLEAI	1211 BREEZY BI		TF	435723026							URD BO # 8256. REPLACED X - ELBOW @ 10 107 SANDS TRAIL CT. REFUSED X - T P - X#2J REF TP. RPLD ELBOW @ TR. BRS	1	0
FORCED INTERR	CY	TB 45	21046	26ABF	46710131	22003200001	T	4/30/2003	0630	66	1	66	VINES	VINES	22719 WATER C	1	PR	467101317							RMVD VINES & TREES FROM AROUND TR. RF TR AFTER REPLACING LIMITER. REF TR.	1	0
FORCED INTERR	MP	AN 05	40030	A65U	53612080	22003200003	T	4/30/2003	0657	43	1	43	SQUIRREL	SQUIRREL	316 E BURRESS	1	TF	536120800							TRIMMED TREES CUT & PULLED VINES OFF OF THE POLE REPLACED LIMITER. RPLD LIMITER @ TR. REF TR. MEK	1	0
FORCED INTERR	GP	RU 01	41293	ES1	53611250	22003200014	F	4/30/2003	0720	51	17	867	SQUIRREL	SQUIRREL	121 FLORADOR	1	LF	ES1							REFUSED E TRNS / LEFT BERV ON / NOTIFIED PLEASE INSTALL SQUIRREL WIRE @ B/C CONV. --CAN GET TRX TO IT - BUS CLOSED ON WEEK-ENDS REF TR MEK	1	0
FORCED INTERR	KY	KT 45	22644	A50G	43562570	12003200003	T	4/30/2003	0754	80	3	240	VINES	VINES	2230 CEDAR LN	1	TF	435625753							REF LF	1	0
FORCED INTERR	SH	PE 04	30815	E39B	55481130	32003200010	F	4/30/2003	0758	192	19	3648	COLLISION	COLLISION	5300 CO 844	1

| | | |

| | | |

FORCED INTERR	KY	KT 41	22564	K71Y	4258927	120032760010	T	10/3/2003	0254	86	2	172	UNKNOWN	UNKNOWN	1303 AVENUE C	1	TF	425892746											
FORCED INTERR	SB	CB 07	12604	9WT	5060518	120032760011	F	10/3/2003	0325	119	9	1071	VINES	VINES	SONNEVILLE, B	1	LF	9WT	TF	50605183C									
FORCED INTERR	HM	KW 43	20173	26CH	5770641	120032760000	F	10/3/2003	0600	0	0	0	TERMINATOR	TERMINATO	4131 MEADOW :	2	LF	26CH	PR										
FORCED INTERR	HM	KW 43				120032760000	F	10/3/2003	0600	110	65	7150	TERMINATOR			2	LF	26CH											
FORCED INTERR	KY	KT 45	22644	64HP	4357415	120032760012	F	10/3/2003	0617	121	6	726	FLLNG TREE OUT	TREE FL/OE	2018 SADDLEHO	1	LF	64HP											
FORCED INTERR	SU	CRB45	14327		4650428	120032760015	T	10/3/2003	0700	155	5	775	SQUIRREL	SQUIRREL	4926 JAYMAR D	1	TF	465042850											
FORCED INTERR	BZ	RT 02	30875	H76R	5128811	320032760000	F	10/3/2003	0730	136	15	2040	SQUIRREL	SQUIRREL	210 BUFFALO TI	1	LF	H76R											
FORCED INTERR.	GP	LK 01	21876	M18R	5262311	220032760000	L	10/3/2003	0757	55	1	55	OH SEC/DR CL N	OH SC CL-N	7721 VIRGIL ST	1	SC												
FORCED INTERR	BL	SF 45	10457		5157505	120032760022	T	10/3/2003	0758	139	1	139	BU DISC OR BARI	DISC/BARRL	1715 YORKTOW		PR	515750520											
FORCED INTERR	BL	JN 04	10000	38T	4956904	120032760023	T	10/3/2003	0759	79	5	395	SQUIRREL	SQUIRREL	9654 JUDALON I	1	TF	495690420											
FORCED INTERR	BA	CD 04	40352	I66N	6458493	320032760005	F	10/3/2003	0800	92	66	6072	O/H PRIMARY CU	OH PR CLMF	3529 CROSBY C	1	LF	I66N	PR										
FORCED INTERR.	KY	MAR4C	22704	M85P	4457544	120032760024	F	10/3/2003	0800	51	18	918	SQUIRREL	SQUIRREL	22315 CIMARRC 2		LF	M85P											
FORCED INTERR	SH	CG 03	30215	H52P	5653957	320032760017	F	10/3/2003	0800	23	1	23	SQUIRREL	SQUIRREL	203 CANNIFF RI	1	TF	565395730											
FORCED INTERR	HC	FD 14	10676		5152152	320032760022	T	10/3/2003	0805	50	6	300	SQUIRREL	SQUIRREL	11615 HILLCROI		TF	515215244											
FORCED INTERR	CH	CV 01	40420	J40A	5858934	120032760011	F	10/3/2003	0800	67	40	2680	SQUIRREL	SQUIRREL	14529 BANDERA	1	LF	J40A											
FORCED INTERR	CY	TB 06	21014	3C2	4771725	220032760005	F	10/3/2003	0800	47	73	3431	SQUIRREL	SQUIRREL	S. CHERRY @ F	1	LF	3C2											
FORCED INTERR	SH	PA 01	30747	E34	5755605	320032760016	F	10/3/2003	0828	64	4	256	SQUIRREL	SQUIRREL	901 SUNSET	1	LF	E34	TF	575560564									
FORCED INTERR	HM	LW 43	20193	71R	5565506	220032760017	T	10/3/2003	0830	42	1	42	SQUIRREL	SQUIRREL	14726 MARINE F	1	TF	556550901											
FORCED INTERR	SH	CA 01	30157	J50K	5854913	320032760017	F	10/3/2003	0840	26	2	52	SQUIRREL	SQUIRREL	4915 PINE	1	LF	J50K											
FORCED INTERR	HC	TV 03	11142	G10W	5150817	120032760025	F	10/3/2003	0840	77	27	2079	SQUIRREL	SQUIRREL	16303 CLEARWC	2	LF	G10W											
FORCED INTERR.	SH	DR 07	30293	J6X	5554929	220032760013	T	10/3/2003	0844	51	13	663	SQUIRREL	SQUIRREL	7611 EL RANCH	1	TF	555492953											
FORCED INTERR	BA	CD 06	40380	4W2	6457217	320032760021	T	10/3/2003	0850	66	6	396	SQUIRREL	SQUIRREL	1704 CLAYTON I	1	TF	645721757											
FORCED INTERR	RS	RZ 02	30377	128T	5238445	320032760025	F	10/3/2003	0851	59	2	118	SQUIRREL	SQUIRREL	201 CO 51 (BEH	1	LF	128T											
FORCED INTERR	BL	DN 03	10547	3CJ	5356146	120032760034	L	10/3/2003	0918	241	1	241	OH SEC/DR CL H	OH SC CL-H	1748 HAROLD S	1	DR												
FORCED INTERR.	MP	ES 01	40638	8J4	5457621	220032760016	T	10/3/2003	0921	70	1	70	SQUIRREL	SQUIRREL	2900 SHERMAN	1	TF	545762130											
FORCED INTERR	BL	UL 41	10459	EM1	5156656	120032760035	L	10/3/2003	0934	113	1	113	OH SEC/DR CL N	OH SC CL-N	5136 DEL MONT	1	DR												
FORCED INTERR	CH	UV 06	41628	N42K	5860304	320032760025	F	10/3/2003	1000	56	23	1288	SQUIRREL	SQUIRREL	6202 LARCHBRC	2	LF	N42K											
FORCED INTERR	RS	LV 03	3531A	K56F	5640309	320032760030	T	10/3/2003	1000	87	1	87	SQUIRREL	SQUIRREL	5809 PINE TREE	1	TF	564030928											
FORCED INTERR	SH	SB 01	31653	56R	5854728	320032760031	T	10/3/2003	1017	57	6	342	SQUIRREL	SQUIRREL	2218 PURDUE S	1	TF	585472678											
FORCED INTERR	FB	BV 42	11728	16UL		120032760050	F	10/3/2003	1020	75	13	975	BU DISC OR BARI	DISC/BARRL	2215 PECAN LAI	1	LF	16UL											
FORCED INTERR	MP	WO 05	41650		5260133	220032760027	L	10/3/2003	1028	76	1	76	TREE CLEARANC	TREE CLEAF	1723 DE MILO D		SC												
FORCED INTERR	HC	HO02C	11169	JG9	5250320	120032760053	L	10/3/2003	1031	99	1	99	OH SEC/DR CL H	OH SC CL-H	4610 STILLBROO	1	SC												
FORCED INTERR	BA	AT 41	41478	S2174	6088821	320032760038	F	10/3/2003	1052	52	1	52	UNKNOWN	UNKNOWN	415 REDLAND	1	LF	S2174											
FORCED INTERR	SB	BM 03	21485	14LN	4858952	120032760056	T	10/3/2003	1100	20	8	160	UNKNOWN	UNKNOWN	1771 UPLAND D	1	TF	485895268											
FORCED INTERR	MP	MP 10	41401	B19P	5556126	220032760039	L	10/3/2003	1120	48	1	48	TREE CLEARANC	TREE CLEAF	5317 LINDSAY S	1	DR		DR										
FORCED INTERR	BL	HE 07	41137	B28Z	5358335	120032760062	L	10/3/2003	1124	73	1	73	HUMAN ERROR	HUMN ERRC	723 ARLINGTON	1	DR												
FORCED INTERR.	SU	RO 02	12232	F29C	4853815	120032760070	T	10/3/2003	1136	38	1	38	BIRD	BIRD	10830 S KIRKWI	1	TF	485381510											
FORCED INTERR	CY	TB 06	21016	AG9	4771630	220032760037	F	10/3/2003	1138	50	49	2450	SQUIRREL	SQUIRREL	601 HICKS ST	1	LF	AG9											
FORCED INTERR	SU	AF 01	11750	C26P	4954233	120032760071	F	10/3/2003	1140	0	0	0	TERMINATOR	TERMINATO	10715 HAZEN S'	2	LF	C26P	PR										
FORCED INTERR	SU	AF 01				120032760071	F	10/3/2003	1140	272	19	5168	TERMINATOR			2	LF	C26P											
FORCED INTERR	SU	AF 01				120032760071	F	10/3/2003	1140	272	8	1632	TERMINATOR			2	LF	C26P											
FORCED INTERR	BL	UL 41	10459	EM1	5156656	120032760074	T	10/3/2003	1149	209	20	4180	SEC COND OR DI	SECONDAR	5136 DEL MONT	1	SC	515665627	DR										
FORCED INTERR	SH	SP 07	30983	6LX	5753737	320032760044	F	10/3/2003	1149	43	18	774	UNKNOWN	UNKNOWN	1106 AVENUE G	1	LF	6LX											
FORCED INTERR	BL	HP 01	40620		5357734	120032760081	T	10/3/2003	1200	173	8	1384	COLLISION	COLLISION	1201 W DALLAS		BU	535773470											
FORCED INTERR	CH	SW 10	41231		5463801	320032760046	T	10/3/2003	1211	26	1	26	SQUIRREL	SQUIRREL	11630 HARTLEY		TF	546380197											
FORCED INTERR	FB	EB 06	11295	X46T	3746246	120032760085	F	10/3/2003	1214	132	10	1320	UNKNOWN	UNKNOWN	842 CLUBSIDE	1	LF	X46T											
FORCED INTERR	SH	GG 04	30542	25E	5554212	220032760036	F	10/3/2003	1300	43	1	43	COLLISION	COLLISION	5830 HALMART	1	LF	25E											
FORCED INTERR	BA	BT 04	40123	40LL	6356145	320032760057	F	10/3/2003	1311	68	8	544	COLLISION	COLLISION	1919 1/2 AVON (	1	PR	40LL	PR										
FORCED INTERR	HC	HM 09	11047	NB7	5453251	120032760086	L	10/3/2003	1318	72	1	72	TREE CLEARANC	TREE CLEAF	4405 ROSEMON	1	SC												
FORCED INTERR.	SU	CE 01	11933		4753506	120032760092	T	10/3/2003	1330	24	3	72	SQUIRREL	SQUIRREL	14223 BAY GARI		TF	475350666											
FORCED INTERR	MP	HG 05	41087	CW5		120032760094	F	10/3/2003	1350	32	60	1920	FOREIGN MATER	FRGN MATR	615 93RD	1	LF	CW5											
FORCED INTERR	FB	CRB4E	12775	Y21B	4449732	120032760095	T	10/3/2003	1350	63	9	567	SQUIRREL	SQUIRREL	609 FRONT ST E	1	TF	444973275											
FORCED INTERR	BA	MB 05	38159	8CN	6761613	320032760066	L	10/3/2003	1410	49	1	49	COLLISION	COLLISION	8119 S FM 565 R	1	PD												
FORCED INTERR	BA	MB 05	3C164	31RM	6763148	320032760067	F	10/3/2003	1420	121	3	363	SQUIRREL	SQUIRREL	15406 WOODCF	1	LF	31RM											
FORCED INTERR	MP	BY 08	40197		5460236	220032760055	L	10/3/2003	1437	75	1	75	VANDALISM	VANDALISM	7715 1/2 W HAR		MT												
FORCED INTERR	BZ	BZ 02	30137	12RN	5326905	320032760072	T	10/3/2003	1500	35	9	315	BU DISC OR BARI	DISC/BARRL	517 COBB ST	1	TF	532690523											
FORCED INTERR	CY	PI 43	21024	U22B	4672658	220032760061	F	10/3/2003	1520	96	23	2208	LIGHTNING ARRE	LTNG ARRS	27536 DECKER I	1	LF	U22B	TF	467265988									
FORCED INTERR	CH	GP 06	40815	N47	5656649	220032760064	T	10/3/2003	1533	30	16	480	UNKNOWN	UNKNOWN	218 PENNSYLVI	1	TF	565664995											
FORCED INTERR	SU	CE 02	12626		4753702	120032760114	T	10/3/2003	1540	228	4	912	VINES	VINES	10803 PARKLAN		TF	475370283											
FORCED INTERR	HC	FD 03	10842	SEM	5053936	120032760115	T	10/3/2003	1550	79	6	474	SQUIRREL	SQUIRREL	6036 CHEENA D	1	TF	505393607											
FORCED INTERR	GP	LK 04	21871	7PR	5262443	220032760065	F	10/3/2003	1610	68	3	204	UNKNOWN	UNKNOWN	HORNE AT WHI	1	LF	7PR											
FORCED INTERR	CH	PW 04	41637	B4TT	5860147	320032760078	T	10/3/2003	1630	32	1	32	SQUIRREL	SQUIRREL	13225 GLADDEN	1	TF	586014763											
FORCED INTERR	MP	GG 01	40950	C09	5554148	220032760075	L	10/3/2003	1637	30	1	30	OH SEC/DR CL H	OH SC CL-H	8014 CHERRYHI	1	DR												
FORCED INTERR	MP	AN 05	40080		5360150	220032760076	T	10/3/2003	1640	91	2	182	TREE CLEARANC	TREE CLEAF	4901 YALE ST		TF	536015050											
FORCED INTERR	MP	BU 03	41908	B35N	5657440	220032760074	T	10/3/2003	1644	54	12	648	SQUIRREL	SQUIRREL	8702 OTHELLO :	1	TF	565744065											
FORCED INTERR	GA	PHR0C	31303	6A2	6347529	320032760086	F	10/3/2003	1655	92	17	1564	O/H PRIMARY CU	OH PR CLMF	GRAND @ 4TH	1	LF	8A2	PR										
FORCED INTERR	FB	RS 05	11545	82GT	4347317	120032760125	F	10/3/2003	1730	46	1	46	BIRD	BIRD	HWY 59, W OF I	1	LF	82GT											
FORCED INTERR	SU	RO 07	12240	T36M	4953437	120032760130	F	10/3/2003	1734	69	3	207	COLLISION	COLLISION	9990 BISSONNE	1	LF	T36M											
FORCED INTERR	CY	PI 45	2445F	S16C	4573507	120032760077	F	10/3/2003	1735	75	25	1875	FLLNG TREE OUT	TREE FL/OE	33318 ALTON W	1	LF	S16C											
FORCED INTERR	GP	KI 45	20886		4869320	220032760081	L	10/3/2003	1755	154	1	154	URD DROPS (HUI	URD DR-HUI	11730 SANDY S'		SC												
FORCED INTERR	KY	FM 02	22858	99QQ	3864353	220032760086	T	10/3/2003	1835	199	1	199	OH SEC/DR CL H	OH SC CL-H	12002 SCHMIDT	1	TF	386435322											
FORCED INTERR	CH	OA 05	41602	J60Z	5758037	320032760090	T	10/3/2003	1851	34	8	272	SQUIRREL	SQUIRREL	539 WESTSHIRI	1	TF	575803734											
FORCED INTERR	FB	EB 05	11292	X90T	3348313	120032760152	T	10/3/2003	2030	64	1	64	SQUIRREL	SQUIRREL	25727 MAIN	1	TF	334831301											
FORCED INTERR.	SH	WE 07	31276		5956448	320032760097	T	10/3/2003	2041	49	1	49	UNKNOWN	UNKNOWN	4207 PASADENA		TF	595644847											
FORCED INTERR	BL	DV 09	10616		5056131	120032760162	T	10/3/2003	2202	104	2	208	LIGHTNING ARRE	LTNG ARRS	2501 1/5 WESTE		TF	505613115											
FORCED INTERR	HC	AM 05	10745	7F4	5251653	120032760163	T	10/3/2003	2209	63	6	378	BU DISC OR BARI	DISC/BARRL	3543 WESTHAM	1	TF	525165343											
FORCED INTERR	KY	FZ 41	22766		4458436	120032760164	T	10/3/2003	2213	183	4	732	UNKNOWN	UNKNOWN	22451 BUCKTRC		TF	445843629											
FORCED INTERR	SH	CA 01	30157			320032760124	C	10/3/2003	2300	0	0	0	VANDALISM	VANDALISM	LILLY @ SPENC		PC	CA01											
FORCED INTERR	SH	CA 01	30156			320032760125	C	10/3/2003	2300	25	987	24675	VANDALISM				PC	CA01											
FORCED INTERR	GP	FR 44	21402	S83F	5163310	220032770001	F	10/4/2003	0000	113	67	7571	VINES	VINES	8911 LAKESIDE	2	LF	S83F											
FORCED INTERR	GP	KI 44	20580	72AEJ	5069320	220032770002	T	10/4/2003	0015	82	1	82	UNKNOWN	UNKNOWN	5819 SPRING C'	1	TF	506932087											
FORCED INTERR	GP	BA 43	2J144	X73J	5165140	220032770003	F	10/4/2003	0011	237	32	7584	URD ELBOW	URD ELBOW	11838 WELSHPO	2	LF	X73J	PR										
FORCED INTERR	MP	WO 02	41829	MP1	5260704	220032770007	T	10/4/2003	0307	135	11	1485	VINES	VINES	843 JUDIWAY S'	1	TF	526070455											
FORCED INTERR	GA	MDY01	31357	8WD	6737110	320032770002	T	10/4/2003	0330	151	5	755	UNKNOWN	UNKNOWN	2817 DOMINIQU	1	TF	673711084											
FORCED INTERR.	SU	IM 43	14256	25LQ	4752144	120032770005	F	10/4/2003	0454	152	45	6840	LIGHTNING ARRE	LTNG ARRS	15322 OAK LAKE	2	LF	25LQ											
FORCED INTERR	SL	SE 04	22472	W239		120032770007	F	10/4/2003	0611	322	57	18354	COLLISION	COLLISION	9719 SW I-10 FR	1	LF	W239	PD										
FORCED INTERR.	CY	TB 45	21046	S228S		220032770011	F	10/4/2003	0634	113	1	113	UNKNOWN	UNKNOWN	20632 ROSEHILI	1	LF	I97L											
FORCED INTERR	FB	NEWO	11245	X63T	4038332	120032770013	T	10/4/2003	0711	178	1	178	SQUIRREL	SQUIRREL	9450 GUESS RD	1	TF	403853293											
FORCED INTERR	GP	BA 42	20698	U25Y	5167203	320032770014	T	10/4/2003	0750	199	8	1592	UNKNOWN	UNKNOWN	14022 WALTER 1	1	PR	516720363											
FORCED INTERR	SB	EC 02	11330	R13L	5057009	120032770014	F	10/4/2003	0752	106	89	9434	SQUIRREL	SQUIRREL	11711 MEMORIA	2	LF	R13L											
FORCED INTERR	CH	OA 04	41365	HG6	5657958	320032770005	T	10/4/2003	0755	62	15	930	SQUIRREL	SQUIRREL	10330 NORVIC 1	1	TF	565795847											
FORCED INTERR	GP	NB 42	29868		5265838	220032770016	T	10/4/2003	0800	99	1	99	LIGHTNING ARRE	LTNG ARRS	17001 NORTHCI	1	TF	526583880											
FORCED INTERR	MP	GG 06	10951	A3Z	5454932	120032770022	T	10/4/2003	0811	53	5	265	SQUIRREL	SQUIRREL	5801 SOUTHCR	1	TF	545493283											
FORCED INTERR	GP	KL 42	21938	X68J	4866225	220032770017	T	10/4/2003	0811	402	4	1608	UNKNOWN	UNKNOWN	11635 SNOWMA	2	SC	486822557											
FORCED INTERR	MP	UN 03	41716	2AC	5555255	120032770018	T	10/4/2003	0821	96	10	960	SQUIRREL	SQUIRREL	5707 HARRIET S	1	TF	555525514	DB										
FORCED INTERR	CH	JP 07	41207	C79H	6058027	320032770007	T	10/4/2003	0829	77	7	539	SQUIRREL	SQUIRREL	16018 RED OAK	1	TF	605802794											
FORCED INTERR	SH	MY 05	31736	33ED	5748131	320032770008	T	10/4/2003	0829	101	2	202	SQUIRREL	SQUIRREL	3417 LONGHERI	1	TF	574813109											
FORCED INTERR	CY	PI 45	2A126		4474356	220032770020	T	10/4/2003	0835	79	2	158	VINES	VINES	29703 NICHOLS		TF	447435691											
FORCED INTERR	SB	TO 03	20825	65CD	5159449	120032770025	T	10/4/2003	0838	92	1	92	SQUIRREL	SQUIRREL	5812 MITCHELLI	1	TF	515944917											
FORCED INTERR.	MP	MP 08	41397	85EV	5457925	220032770022	T	10/4/2003	0857	167	10	1670	SQUIRREL	SQUIRREL	4124 BERING S1	1	TF	545792520											
FORCED INTERR.	SU	HY 04	11700	9WH	4957205	120032770026	F	10/4/2003	0858	64	33	2112	SQUIRREL	SQUIRREL	10627 HOLLY SF	1	LF	9WH											
FORCED INTERR	BA	CD 10	40409	F83X	6457032	320032770010	T	10/4/2003	0900	33	3	99	SQUIRREL	SQUIRREL	717 CEDAR BAY	1	TF	645703256											
FORCED INTERR.	BL	UL 02	10328		5156000	120032770029	T	10/4/2003	0910	84	10	840	SQUIRREL	SQUIRREL	6315 SKYLINE D		TF	515800054											
FORCED INTERR	BL	HE 03	10670	AP3	5257659	120032770031	F	10/4/2003	0908	161	69	11109	FALLING DEAD TI	TR FL/DEAD	8011 ROSE ST	1	LF	AP3											
FORCED INTERR.	MP	BG 02	40247	A74H		220032770027	F	10/4/2003	0922	114	209	23820	FOREIGN MATER	FRGN MATR	3108 WICHITA S	1	LF	A74H											
FORCED INTERR.	MP	HM 10	10855		5455418	220032770022	T	10/4/2003	0948	70	1	70	BU DISC OR BARI	DISC/BARRL	5819 1/2 SIDNEY		TF	545541610											
FORCED INTERR	BL	GN 11	10978	31FP	5254940	120032770039	F	10/4/2003	1000	126	1	126	HUMAN ERROR	HUMN ERRC	8330 MAIN	1	LF	31FP											
FORCED INTERR	HC	AR 42	13191	Y88C	5246246	120032770040	F	10/4/2003	1000	138	27	3726	UNKNOWN	UNKNOWN	5415 VICTORIA	1	LF	Y88C											
FORCED INTERR.	SH	PJ 03	30072		5848834	320032770012	L	10/4/2003	1000	82	1	82	OH SEC/DR CL H	OH SC CL-H	18001 HOPE VIL		SC												
FORCED INTERR.	BA	LP 04	41668	19ABM	6253723	320032770015	F	10/4/2003	1000	42	7	294	TREE CLEARANC	TREE CLEAF	510 LEE CIRCLE	1	LF	19ABM											
FORCED INTERR	HC	FD 05	10659	2AM	5053916	120032770041	T	10/4/2003	1010	51	6	306	SQUIRREL	SQUIRREL	6030 SPELLMAN 1		TF	505391990											
FORCED INTERR	FB	NEWO	11246		3837853	120032770043	T	10/4/2003	1012	35	2	70	COLLISION	COLLISION	5907 FM 1301 RI		TF	383785371	PD										
FORCED INTERR	CH	PW 02	40931	N75W	5761228	320032770016	F	10/4/2003	1022	85	12	1020	SQUIRREL	SQUIRREL	10328 VALLEY W	2	LF	N75W											
FORCED INTERR	GP	AD 04	21764	25FN	5263628	220032770031	T	10/4/2003	1048	172	2	344	VINES	VINES	530 FRAZER LN	1	TF	526362827											
FORCED INTERR	BL	SF 41	10463	Z68	5157728	120032770040	T	10/4/2003	1100	43	3	129	UNKNOWN	UNKNOWN	28 N WYNDEN (	1	TF	515772664											
FORCED INTERR	SU	STF02	14279	31BZ	4851509	120032770047	F	10/4/2003	1100	141	2	282	VINES	VINES	4 REGENT CT (	2	LF	31BZ											

REPLACED LIMITER & REFUSED O H TRANS CAUSE UNKNOWN. REF TR.				1	0
REF LF. REF TR.				1	0
SWITCHING#1884 ISOL URD PR.				1	0
				1	0
CLEARED TRE LIMB FROM PRIMARY & RF LF; REF LF.				1	0
REPL 12 K-MATE INSTALLED W/LP REFUSED 37 KVA TR. SQUIRREL. REF TR.				1	0
REFUSED LF H-76-R 50-T , REF LF				1	0
REPAIRED NEUT @ POLE VOLTAGE WAS W/OUT LOAD & NOONE AROUND. RPLD SEC CONN @ PL- 1 CUST				1	0
REPLACED CURRENT LIMITER ON A 50 KVA 18 8 120/208 XFMR. RPLD LIMITER @ TR.				1	0
REFUSED TRANS. REF TR.				1	0
RPLD B/O PR JUMPER-FUSE BLOWN. REF LF				1	0
ADDED HKD LIFE. REF TP.				1	0
TRK 6484 ——— REFUSED TRK #SQUIRREL)———NEEDS W L P TRK ACCESS FRNT OF ADDRESS REF TR.			BJH	1	0
BQ. REF TR.				1	0
SQUIRREL GOT ON A CBP XFMR @ 14628 BANDERA--BLEW HIGH SIDE OUT OF LF J40A--REPLACED HIGH SIDE--LEFT ALL SERV WORKING. REF LF RPLD B/O PR JUMPER-FUSE BLOWN.				1	0
REF LF.	BJH			1	0
REF LF REF TR.				1	0
replaced 25 kva trans. wildlife guards in place. REF TR.				1	0
TRK 6484 ——— REFUSED LF #SQUIRREL)———3-C B P 'S NO W L P OR DISC IN TRK ACCESS REF LF				1	0
REFUSE TRK#10 W 80 T ALSO TRIMMED TREES. REF TP				1	0
REMOVED VINES OFF TRANS & REFUSED / LEFT SERV ON / NOTIFIED. REF TR.				1	0
REF TR.				1	0
REFUSED LINE FUSE. REF LF				1	0
REPLACED BAD IN HOUSE DROPS WITH 1/0 HOUSE DROPS 80 FT , RPLD DR.				1	0
REF TR.	BJH			1	0
REPLACED ALL CLAMPS AT VIH FOR BT. RPLD CONN @ WH.				1	0
REF TP				1	0
REFUSED 28 CONV TRANS , REF TR				1	0
REFUSED TRANSFORMER TAKEN OUT BY SQUIRREL / TRANSFORMER ALREADY HAS WLP. REF TR.				1	0
FOUND STEP DOWN TRANSF 167 #63612 FUSE BLOWN AND LIMITER BAD ——MADE REPAIRS———ALLEN TR 3233. REF LF REF TR.				1	0
REPAIRED HOT LEG AT POLE HO ONE HOME LEFT DOOR HANGER. RPRD SEC CONN @ PL-1 CUST				1	0
Reassigned Drops. RPLD CONN @ PL.				1	0
REFUSED STEP POT--82174--20T--PULLED FUSE. REF LF.				1	0
REPLACED BU FUSE BARREL ON SOUTH POWER. RPLD BU BARREL ON TR.				1	0
TRIMMED TREES & MADE REPAIRS TO DROPS / LEFT SERV ON / NOTIFIED. RPRD DR. RPLD CONN @ WH				1	0
REPLACED BOTH LIGHTER CLAMPS AT WH FOR BT. RPLD CONN @ WH.				1	0
REFUSED 100 KVA XFMR ON 277/480 VOLT BANK BIRD LEFT ON AND WORKING CUST NOTIFIED. REF TR.				1	0
REF LF REF TR.				1	0
ISOLATED BAD SPAN OF DIRECT BURY PRI ON SO # 1080. REF TP			SENT MESSAGE TO BUG.	1	0
				0	0
PLEASE RESCHEDULE THIS ORDER TO BE REWORKED AT 1800 THIS AFTERNOON WHEN THE SCHOOL CLOSES TO HAZARDOUS TO WORK ON XFMR AT THIS TIME T

FORCED INTERR.	GP	FR 42	21384	T36L	49635411	22003277003	F	10/4/2003	1125	58	71	4118	VINES	VINES	ZAKA, W OF CO	1	LF	T36L	CLEARED VINES REFUSED LF-T36L REF TR	TW7	1	0
FORCED INTERR.	HC	HOCO	11155	9K9	52514527	22003277005	F	10/4/2003	1200	57	22	1254	UNKNOWN	UNKNOWN	13910 WHITE HI	1	LF	9K9	REFUSE EAST PHASE LF REF LF		1	0
FORCED INTERR	SL	SE 04	22470	89E	32542269	22003277005	F	10/4/2003	1207	57	5	285	UNKNOWN	UNKNOWN	2260 BECKENDI	1	LF	89E	CUST NOTIFIED BY PHONE LIGHTS ON RF LF INE ROAD OUT LINE EVERTHING OK, REF LF		1	0
FORCED INTERR	RS	AE 06	30076	48S	54349580	22003277002	F	10/4/2003	1237	37	13	481	BU DISC OR BARI	DISC/BARRL	2111 AVENUE L	1	LF	48S	REFUSED LINE FUSE, REF LF		1	0
FORCED INTERR	FB	DA 05	1187A	2GH	44396101	22003277006	F	10/4/2003	1244	45	22	990	UNKNOWN	UNKNOWN	19712 HIGHWAY 1		LF	2GH	NO CAUSE AT THIS TIME RODE LINE OUT TWW 10-04-03, REF LF		1	0
FORCED INTERR	CH	PW 04	40440	86R	58612106	22003277003	T	10/4/2003	1327	103	5	515	UNKNOWN	UNKNOWN	13319 FOREST I 1		TF	586121081	RPLD B&J BARREL ON TR.		1	0
FORCED INTERR	BA	FT 07	40655	E20H	61530438	22003277003	T	10/4/2003	1321	302	5	1510	UNKNOWN	UNKNOWN	9919 STONEMO 1		BU	615304392	RPLD B&J TR.		1	0
FORCED INTERR	SU	QV 05	12152	U38F	50495361	22003277006	F	10/4/2003	1341	50	16	800	SQUIRREL	SQUIRREL	17403 EDGEHAV 2		LF	U38F	REF TP.		1	0
FORCED INTERR.	HC	BR 13	10521	85D	51536534	22003277006	T	10/4/2003	1359	157	8	1256	TREE CLEARANC	TREE CLEAF	5118 BRAESHEJ 1		TF	515365349	REPLACED BURNT KEARNEY BARREL ON LIGHTER POT OUT BY TREES RPLD B&J BARREL ON TR.		1	0
FORCED INTERR	HC	BR 13				22003277008	C	10/4/2003	1400	0	0	0	PRIMARY CONDU	PRIMARY	610 LOOP @ GF		PC	BR13	PR	CREW MADE REPAIR TO B&J A PHASE JUMPER, S SIDE OF 610 LOOP @ GREENWILLOW.....RST	1	0
FORCED INTERR	HC	BR 13	10519			22003277008	C	10/4/2003	1400	26	1189	30914	PRIMARY CONDU				PC	BR13			1	0
FORCED INTERR	SU	CE 11	11979	J53M	48542095	22003277007	F	10/4/2003	1416	72	42	3024	FOREIGN MATER	FRGN MATR	8902 BROOKWL 2		LF	J53M	REFUSED TP N47P REMOVED BALLOON LEFT ON CUST NOTIFIED; REF TP.		1	0
FORCED INTERR	FB	OB 44	13231	36PN	46525106	22003277007	T	10/4/2003	1416	43	2	86	UNKNOWN	UNKNOWN	4919 SHILOH LA 1		TF	465251088	NO IDEAD WHY TRANS FUSE BLEW NO ONE HOME IN OTHER HOUSE; REF TR.		1	0
FORCED INTERR	GP	WF 42	20321	T10U	52682113	22003277004	F	10/4/2003	1424	0	0	0	URD ELBOW	URD ELBOW	505 WELLS FAR 2		LF	T10U	PR	BAD SPAN URD PRIMARY WIRE BETWEEN TRANS # 6 & 7----BOTH ENDS CLOSED; 180L URD PR; ISOLATED ON URD BOR1867	848	1	0
FORCED INTERR	GP	WF 42				22003277004	F	10/4/2003	1424	97	130	12610	URD ELBOW		2		LF	T10U			0	0
FORCED INTERR	GP	WF 42				22003277004	F	10/4/2003	1424	97	36	3492	URD ELBOW		2		LF	T10U			0	0
FORCED INTERR	SU	CE 11	11979	N47P	48543003	22003277008	F	10/4/2003	1428	49	29	1421	FOREIGN MATER	FRGN MATR	12716 DAIRY BR 2		LF	N47P			1	0
FORCED INTERR	SU	CE 11	11979	J52M	48542066	22003277008	F	10/4/2003	1438	43	33	1419	FOREIGN MATER	FRGN MATR	8810 BROOKWL 2		LF	J52M	REMOVED BALLOON OFF TP N47P REFUSED LEFT ON AND WORKING CUST NOTIFIED; REF TP.		1	0
FORCED INTERR	BA	NP 44	41301	82MM	62664213	22003277003	T	10/4/2003	1444	231	4	924	UNKNOWN	UNKNOWN	4306 GATEWOC 1		BU	626642133	REPLACED 25 CBP-WITH 37 5 KVA CONV 7200-120/240, RPLD B&J TR.		1	0
FORCED INTERR	GP	THW4	22349	72AD	49642210	22003277004	F	10/4/2003	1446	156	135	21060	URD ELBOW	URD ELBOW	9243 RIPPLING I 2		PR	Y52Z	REFUSED LF Y52Z 80T @ AUTUMNBONG & GRABBY GLEN REPLACED Y ELBOW @ 9133 AUTUMNBONG REFUSED X T/P 72AD @ 11018 EARLY HARVEST REF LF REF TP RPLD ELBOW @ TR.		1	0
FORCED INTERR	CH	AD 08	40088	KE2	54626313	22003277003	T	10/4/2003	1455	77	1	77	UNKNOWN	UNKNOWN	3101 CEDAR HIL 1		TF	546263133	REFUSED 50 KVA CONV-7200-480 REF TR		1	0
FORCED INTERR	SU	WW 0	12397	R27B	49547341	22003277008	F	10/4/2003	1459	91	58	5278	URD ELBOW	URD ELBOW	7955 KENDALIA 2		LF	R27B	PR 495473474	REF TP RPLD ELBOW @ TR.	1	0
FORCED INTERR	BZ	VL 03	3511B	HJ3	55256503	22003277003	T	10/4/2003	1500	45	8	360	VINES	VINES	134 BALDWIN R 1		TF	552565032	REFUSED 25 CONV TRANS REF TR.		1	0
FORCED INTERR.	BZ	VL 03	3518A	9WX	55258590	22003277003	T	10/4/2003	1500	71	8	568	BU DISC OR BARI	DISC/BARRL	400 CREEK DR 1		TF	552585905	REFUSED 50 CONV TRANS., REF TR.		1	0
FORCED INTERR	SB	TO 11	11294	JTS	51600211	22003277009	L	10/4/2003	1512	56	1	56	OH SEC/DR CL HI	OH SC CL-H	6614 FELDSPAR 1		DR		CHANGED OUT CLAMPS AT WEATHERHEAD RPLD CONN @ WH.		1	0
FORCED INTERR	CH	BY 07	40190	J9E	54616140	22003277003	F	10/4/2003	1515	35	59	2065	UNKNOWN	UNKNOWN	3111 WHABERL 1		LF	J9E	REFUSED 2 PHASES OF 3 PHASE LF REF LF		1	0
FORCED INTERR	HC	SO 41	12619		53470259	22003277009	T	10/4/2003	1546	60	1	60	BU DISC OR BARI	DISC/BARRL	4611 COUNTY R		TF	534702552	RPLD B&J BARREL ON TR.		1	0
FORCED INTERR	FB	RE 04	11445	K51B	44484995	22003277009	F	10/4/2003	1541	29	130	3770	CUST EQP RELA	CUST RLTD	LAMAR, S OF C 1		LF	K51B	REFUSED A AND B PHASE OF K51B 85T THIS IS FEEDING CUSTOMER OWNED DISTRIBUTION THEY HAVE A TERMINAL POLE BLOWN THEY ARE NOTIFIED TO GET ELECT TMW 10-04-03, RE		1	0
FORCED INTERR	BA	LP 02				32003277004	C	10/4/2003	1611	0	0	0	TREE CLEARANC	TREE CLEAF	741 N CIRCLE		CL	LP02	CREWS FOUND TREES ON PRIMARY @ SYLVAN BEACH SECTION 30131 10 % OKT ADI AND CADI CREWS RMVED TREES OFF PRIMARY ALL OK 8/0 305---ODM ABK PER CREW TREE CO		1	1
FORCED INTERR	BA	LP 02	41686			32003277004	C	10/4/2003	1611	31	1623	50313	TREE CLEARANC				CL	LP02			0	0
FORCED INTERR	BA	LP 02	3G113			32003277004	C	10/4/2003	1611	82	0	0	TREE CLEARANC				CL	LP02			0	0
FORCED INTERR	BA	LP 02	30131			32003277004	C	10/4/2003	1611	76	241	18316	TREE CLEARANC				CL	LP02			0	0
FORCED INTERR	BA	CO 08	40377	3TX	84575298	32003277004	F	10/4/2003	1611	125	13	1625	SQUIRREL	SQUIRREL	2014 KILGORE F 1		LF	3TX			1	0
FORCED INTERR	CH	BY 02	40193		54603377	32003277075	L	10/4/2003	1651	75	1	75	FLLNG TREE OUT	TREE FLOE	7913 SCHNEIDE		SC		THREE CBPS @ EAIMENT FEEDING FROM BO LINE FUSE NEEDS GAURDS, REF LF		1	0
FORCED INTERR	RS	MU 01	31440	22FJ	57412388	32003277010	T	10/4/2003	1745	159	8	1272	UNKNOWN	UNKNOWN	4815 S QUAIL RI 1		BU	574123803	RPRD NO PR JUMPER-FUSE NOT BLOWN.		1	0
FORCED INTERR	SU	WI 04	12368	G52X	48565531	22003277011	F	10/4/2003	1750	112	44	4928	O/H PRIMARY CL/	OH PR CLMF	12115 WEDGEH 2		PR	G58X	PICKED UP A4 PRIMARY AND NUETRAL TAKEN DOWN BY HIGH LOAD; REF LF PAJ PR-FUSE BLOWN, PAJ PR NEUT		1	0
FORCED INTERR	GA	AL 06	30139	A22F	81420549	32003277010	F	10/4/2003	1831	64	1	64	UNKNOWN	UNKNOWN	2529 FM 846 N F 1		PR	A22F	SC	chg out bad 50/7200/240/480 with the same., RPLD B&J TR.	1	0
FORCED INTERR	SU	RO 04	12218		49526346	32003277012	C	10/4/2003	1946	179	1	179	UNKNOWN	UNKNOWN	9915 DORRANC		BU	495263487	ALSO TIGHTENED UP CASE OR LUG REF TR, RPLD DR.		1	0
FORCED INTERR	KY	FM 02	22858	99QQ	38643533	22003277005	T	10/4/2003	2000	163	1	163	OH SEC/DR CL HI	OH SC CL-H	12002 SCHMIDT 1		TF	386435322	DR	REF TR	1	0
FORCED INTERR	BA	AT 41	22352	F96N	59679481	32003277010	T	10/4/2003	2021	79	3	237	OTHER WILDLIFE	OTHER WLE	1427 SPANISH C 1		TF	596794876	Cleared Vines from Pole. REF TR.		1	0
FORCED INTERR	CY	PI 43	21026	N35D	46720262	22003277005	T	10/4/2003	2021	131	3	393	VINES	VINES	24603 LORI 1		TF	467202659	REF TR;		1	0
FORCED INTERR	BA	LP 02	30131	56JT	62537129	32003277014	T	10/4/2003	2221	68	3	204	UNKNOWN	UNKNOWN	215 JEFFERSON 1		TF	625371289	TREE TRIMING NEEDED A&AP UNABLE TO BEE TRA AND POLE. REF TR.		1	0
FORCED INTERR	SH	GG 04	30542	45JM	55543143	22003277009	C	10/4/2003	2300	96	6	576	FLLNG TREE IN E	TREE FLOE	8007 HOGUE ST 1		TF	555431820	IN THE REAR OF 888 OVERBLUFF 80 KVA 7200 120/240 NEED TO BE REPLACED ALSO LR AND DISCONNECT CAN GET TRUCK TO IT IF IT DON'T RAIN, REF TR		1	0
FORCED INTERR	CH	CV 08	40459		59582515	32003278001	T	10/5/2003	0008	75	7	525	UNKNOWN	UNKNOWN	858 OVERBLUFI		BU	595825122	NEED TO GET INSULATORS AND SPECIAL DISCONNECTS FOR CONTAMINATED AREA REF 12 -27KV DISCONNECTS AND 8 27KV INSULATORS WITH EPOXY COATED MATERIALS TO ELIMINATE		1	0
FORCED INTERR	GP	FR 43	22200	86KC	51824339	22003278000	F	10/5/2003	0100	512	2	1024	INSULATOR	INSULATOR	7922 ANTOINE C 1		LF	86KC	DB	REF LF.	1	0
FORCED INTERR	BL	JN 09	10036	5EN	50542552	32003278004	F	10/5/2003	0144	63	10	630	UNKNOWN	UNKNOWN	8014 ROOS RD 1		LF	5EN	RPLD LIMITER @ TR.		1	0
FORCED INTERR	CH	LY 44	41344		59625059	32003278002	T	10/5/2003	0148	411	4	1644	SQUIRREL	SQUIRREL	16910 FOLSOM		PR	596250590	REPLACED 50 CBP WITH 50 KVA 7200 120/240 INSTALL SWITCH AND W.L.P. RPLD B&J TR RPLD B&J DISC-TF NOT BLOWN, RPRD B/O PRI JUMP-TF NOT BLOWN, REF TR		1	0
FORCED INTERR.	BL	JN 09	10036	SEN	50542552	32003278005	T	10/5/2003	0300	298	8	2384	TRANSFORMER	TRANSFRME	8011 ROWAN LP 1		BU	505425224	DB	PR	REPURED LF REF LF	1	0
FORCED INTERR	GP	KI 43	28133	71EJ	49675246	22003278000	F	10/5/2003	0310	211	8	1688	UNKNOWN	UNKNOWN	9502 CYPRESS\ 1		LF	71EJ		REPURED LINE FUSE, REF LF	1	0
FORCED INTERR	RS	LV 01	30080	K1Z	57371299	22003278000	F	10/5/2003	0457	84	5	420	UNKNOWN	UNKNOWN	CO 210 @ CO 2(1		LF	K1Z		REF TR;	1	0
FORCED INTERR	CY	CYF45	22263	94KD	46622492	22003278000	T	10/5/2003	0500	77	1	77	UNKNOWN	UNKNOWN	18018 FOREST I 1		TF	466224928		PICKED UP 3-8PANS OF #2 PRIMARY & STREIGHTENED 1- 48' CL 4 IN LINE POL E. HIT BY CAR ALL SERVICE BACK ON AT THIS TIME PAJ PR-FUSE BLOWN.	1	0
FORCED INTERR	RS	LV 01	30080	55GK	56368422	32003278004	F	10/5/2003	0511	248	6	1476	COLLISION	COLLISION	11422 COUNTY 1		LF	55GK	PR	REMOVED VINES REF TR	1	0
FORCED INTERR	SH	CG 04	30218	5DU	57540159	32003278000	T	10/5/2003	0600	158	4	632	VINES	VINES	5102 TRAIL CRE 1		TF	575401581		REF TR, RPLD LIGHTNING ARRESTOR.	1	0
FORCED INTERR	GP	NB 43	22367		53655461	22003278001	T	10/5/2003	0655	179	9	1611	LIGHTNING ARRE	LTNG ARRS	1347 GREENS R		TF	536554612		REF TR.	1	0
FORCED INTERR	BA	TRM01	42052	30LD	64566221	32003278001	T	10/5/2003	0752	41	2	82	BIRD	BIRD	2610 SPUR 55 1		TF	645682136		REPLACED BAD 50KVA 18 @ 120/240 OH POT WBAME. RPLD B&J TR, REF TR.	1	0
FORCED INTERR	GP	BA 42	20698	U25Y	51672039	22003278001	T	10/5/2003	0755	88	8	704	OVERLOAD	OVERLOAD	14022 WALTER! 1		BU	516720363		REPLACED DROPS RPLD DR.	1	0
FORCED INTERR	HC	IR 02	11062	E84R	52515223	22003278001	L	10/5/2003	0811	74	1	74	OH SEC/DR CL HI	OH SC CL-H	3823 GRAPEVIN 1		DR		REPL 12 K-MATE--REF 25KVA--BQ. RPLD LIMITER @ TR. REF TR. ROR		1	0
FORCED INTERR	FB	CRB4	11672	50JC	46483387	12003278012	T	10/5/2003	0822	61	5	305	SQUIRREL	SQUIRREL	1527 ALDERWO 2		TF	464833876	PR	DISC WAS OPEN FUSE NOT BLOWN. CHKD OUT AND CLOSED BACK IN. REF TR;	1	0
FORCED INTERR	HM	LA 01	41222	9D1	55643087	22003278001	T	10/5/2003	0829	122	7	854	UNKNOWN	UNKNOWN	5610 ETHELINE 1		TF	556430800		REPLACED BT/RRUP AND HOTLINE CLAMP RPLD B/O PR JUMPER-FUSE NOT BLOWN,ROR	1	0
FORCED INTERR	HC	FD 18	10902	7KL	51533104	12003278001	T	10/5/2003	0838	59	65	3835	O/H PRIMARY CL/	OH PR CLMF	11007 CRESTMK 1		PR	7KL		REF TRANS. NEED TO INSTALL WIL PROT. REF TR. ROR	1	0
FORCED INTERR	GP	AD 06	20177	A51H	52649366	22003278001	T	10/5/2003	0838	78	9	702	SQUIRREL	SQUIRREL	139 COACH LAN 1		TF	528403668		REFURED 50 KVA 120/240 7.2, REF TR.	1	0
FORCED INTERR	SB	ME 06	21604		48562011	22003278001	T	10/5/2003	0902	59	4	236	SQUIRREL	SQUIRREL	818 OLNEY OAK		TF	485620124		picked up 1- open at # 4 actor PAJ PR-FUSE BLOWN.	1	0
FORCED INTERR	KY	FM 01	21040	B9E	44640284	22003278001	F	10/5/2003	0911	92	14	1288	O/H PRIMARY CL/	OH PR CLMF	22531 HOUSE H 1		LF	B9E	PR	TRIMMED TREES REFUSED A PHASE OR LF 46OR. REF LF	1	0
FORCED INTERR	GP	LK 07	20070	95QS		22003278001	F	10/5/2003	0933	60	43	2580	TREE CLEARANC	TREE CLEAF	775 FAIR ST 1		LF	95QS		REFUSED LF Y28U & REFUSED TRAN. @ 18218 BECKER, REF LF REF TR; ROR	1	0
FORCED INTERR	CY	HK 42	21104	Y26U	43693067	22003278002	F	10/5/2003	0937	122	1	122	VINES	VINES	18219 BECKER 1		LF	Y28U	TF 43693067C	REFUSE 100 KV BANK 2, 7b CONV IN A CLOSE DELTA BANK. REF TR.	1	0
FORCED INTERR	MP	HM 02	11014	3P7	54545481	22003278002	T	10/5/2003	0937	79	3	237	BIRD	BIRD	6840 1/2 WESTC 1		TF	545454810		REPAIRED SEC @ MID IPAN. RPLD SEC CONN @ PL-1 CUST	1	0
FORCED INTERR	BZ	VL 04	3533B	61AAC	60285451	32003278013	T	10/5/2003	0944	86	8	688	UNKNOWN	UNKNOWN	12906 JOLLY RC 1		SC	602854578		RPLD LIMITER @ TR. REF TR.	1	0
FORCED INTERR	CY	WL 41	21153		40697214	22003278022	T	10/5/2003	0947	148	1	148	BIRD	BIRD	19203 STOKES I 1		TF	406972148	PR	REF 2 TR IN CL DELTA. NEED TO INSTALL WIL PROT ON TR Bank TRK AC88L. REF TR: ROR	1	0
FORCED INTERR	GP	HV 03	22206	F82L	52637421	22003278002	T	10/5/2003	1000	55	8	440	BIRD	BIRD	9715 MAREK DR 1		TF	526374212		refuses trans, REF TR;	1	0
FORCED INTERR	GA	PHR01	30931	52HN	64464411	22003278001	F	10/5/2003	1011	82	1	82	UNKNOWN	UNKNOWN	880 25TH A 1		TF	644644100		REPLACE LIMITER ON 25 KVA TRANSFORMER & REFURED LINE FUSE WLP ALREADY INSTALLED; REF LF RPLD LIMITER @ TR. REF TR ROR	1	0
FORCED INTERR	CY	KI 42	22878	F24S	48670543	22003278002	F	10/5/2003	1026	86	8	688	SQUIRREL	SQUIRREL	16861 WEST MA 1		LF	F24S	TF 486705435 PR	CUST HAS SEVERAL MACHINES FUSE MELTED ON POWER TRANS THAT WAR REPLACE FRIDAY NEED SERVICE CONSULTANT TO CHK W/CUST REF TR.	1	0
FORCED INTERR	MP	WV 02	41806	G6R	55587338	22003278003	T	10/5/2003	1043	114	8	912	CUST EQP RELA	CUST RLTD	7305 LAREDO S 1		TF	555873365		REFUSE 3 PHASE LINE FUSE, CAUSE BY CAR HIT GUY AT 5 00 A.M. THIS MORNING. REF LF	1	0
FORCED INTERR	MP	UN 09	41728	2S9	54568116	22003278003	F	10/5/2003	1124	87	8	696	COLLISION	COLLISION	SCHARPE @ DL 1		LF	2S9		REF TP;	1	0
FORCED INTERR	SH	PO 06	31491	U76G	60501118	32003278001	F	10/5/2003	1128	34	7	238	BIRD	BIRD	1900 EL DORAD 3		LF	U76G		@ 1218 COE BAD 250 BTEP TRAN. & ROTTEN 50' CLASS 2 POLE STOOD OFF & PRI. @ 1218 COE CUT Y PRI THRU @ 1307 MERE BOX 1980;	1	0
FORCED INTERR.	CY	PI 45	22015	S151B	45739494	22003278003	F	10/5/2003	1130	0	0	0	TRANSFORMER	TRANSFRME	1218 COE Y(S1! 2		LF	S151B	PD		1	0
FORCED INTERR	CY	PI 45				22003278003	F	10/5/2003	1130	116	16	1856	TRANSFORMER		2		LF	S151B			0	0
FORCED INTERR	SH	TE 06	31080	93QN	55504472	32003278002	L	10/5/2003	1134	82	1	82	COLLISION	COLLISION	12219 OAKLINE 1		DR			picked up drop taken down by cust tree trimming, PAJ DR.	1	0
FORCED INTERR	SH	DR 02	30266	FZ1	56534530	32003278002	T	10/5/2003	1140	41	3	123	SQUIRREL	SQUIRREL	8311 GLENCRE! 1		TF	565345389		REF TR;	1	0
FORCED INTERR	BA	LP 05	41848	55AAC	61546228	32003278002	T	10/5/2003	1152	43	2	86	UNKNOWN	UNKNOWN	11311 N H ST 1		TF	615462265		refuse lighter star n open delta bank & arcing.... REF TR	1	0
FORCED INTERR	CH	PW 02	40391	23ES	57615376	32003278002	T	10/5/2003	1211	83	8	378	BU DISC OR BARI	DISC/BARRL	12218 S SAN CH 1		TF	576153789		REPLACED FUSE BARRELL ON 50 CONV. REF TR. RPLD B&J BARREL ON TR	1	0
FORCED INTERR	SU	WI 07	14316		48562077	12003278003	T	10/5/2003	1215	171	7	1197	URD DROPS (HL8	URD DR-HLF	3119 ASHLOCK		SC	485620735		RAN SECONDARY BYPASS FROM PEDESTAL IN REAR OF 3118 ASHLOCK DR---FOLLOW-UP NEEDED INST SEC BYPASS.	1	0
FORCED INTERR	SB	SR 12	21677	8N6	49594012	12003278003	L	10/5/2003	1215	35	1	35	OH SEC/DR CL HI	OH SC CL-H	1867 SHADOW I 1		DR		REPL HIGH LEG CLAMP AT WH. RPLD CONN @ WH.		1	0
FORCED INTERR	GP	FR 42	20728	U45Y		22003278043	F	10/5/2003	1224	93	5	465	VINES	VINES	9618 SUGAR MA 1		LF	U45Y	PR	REFUSED LF-U45Y @ 1341 REPLACED LIMITER @ 8607 BRIMRIDING MAPLE @ 1420 LEFT 120 120 240 CLEARED VINES FROM TRANSFORMER REF LF RPLD LIMITER @ TR REF TR.	1	0
FORCED INTERR	SU	DL 41	12644		48508394	12003278034	T	10/5/2003	1241	51	4	204	BIRD	BIRD	1806 PEBBLE HI		TF	485063943		REFUSED 25 KVA 18 B TRANS OH OUT BY BIRD REF TR.	1	0
FORCED INTERR	CH	PW 02	40391	W52K	57616346	32003278002	F	10/5/2003	1300	114	38	4332	UNKNOWN	UNKNOWN	12355 TIDWELL 2		LF	W52K		INSPECTED LOOP WITH URD VAN--NO CAUSE FOUND--REFUSED TP; REF TP.	1	0
FORCED INTERR	BA	AT 41	22352	F96N	59679481	32003278003	T	10/5/2003	1300	113	3	339	BIRD	BIRD	1427 SPANISH C 1		TF	596794876		TRANS HAD WLP ADDED GUARD TO LR, REF TR.	1	0
FORCED INTERR	FB	WR 12	11748	B7S	38398115	12003278003	F	10/5/2003	1300	73	18	1314	UNKNOWN	UNKNOWN	2220 DONALDS(1		LF	B7S		refuse trans fuse REF LF	1	0
FORCED INTERR	GP	GZ 41	2F189	I27W	51655552	22003278004	T	10/5/2003	1314	203	5	1015	TREE CLEARANC	TREE CLEAF	2815 WHITINHA 2		PR	516555533		TRIMMED BAMBOO NEED TO HAVE TREE CREW KILL SOURCE REPL LIMITER, REF TR ; REINSTALLED WIL PROT AC88L FROM PARKING LOT IN REAR RPLD LIMITER @ TR REF TR.	1	0
FORCED INTERR	BA	HL 01	41151	S19H	62586403	32003278003	F	10/5/2003	1314	35	11	385	BIRD	BIRD	5404 CAROUSEI 2		LF	S19H		REF TP	1	0
FORCED INTERR	MP	HE 01	41104		53582465	22003278004	T	10/5/2003	1333	74	17	1258	UNKNOWN	UNKNOWN	924 YALE ST		TF	535824606		REF TR;	1	0
FORCED INTERR	BA	FT 07	40724	5FC	61530524	32003278003	T	10/5/2003	1344	52	9	468	VINES	VINES	9810 OLD ORCH 1		TF	615305241		REF TR;	1	0
FORCED INTERR	GP	BA 43	20667	84EJ		22003278005	F	10/5/2003	1342	194	295	57230	O/H PRIMARY CL/	OH PR CLMF	1		DB	84EJ		PAJ PR-FUSE BLOWN RPLD B&J DISC-LF BLOWN REF LF.	1	0
FORCED INTERR	CH	GW 02	40899	CU9	56616071	32003278003	T	10/5/2003	1400	76	5	380	COLLISION	COLLISION	9122 CRESTVIE 1		TF	586180710		REFUSE A 50 CBP TR CAUSE BY DIRT BIKE RIDER HIT POLE REF TR	1	0
FORCED INTERR	SU	DL 42	12971	19KJ	49500013	12003278003	F	10/5/2003	1411	58	64	3776	TREE CLEARANC	TREE CLEAF	4523 RINGROSE 2		LF	19KJ		REFUSED 1 PHASE T/P 62KC CUST HEARD THESE FUSES BLOW HAD TO CUT DOWN 3 LARGE BANANA TREES THAT IS WHAT TOOK THEM OUT REF TP	1	0
FORCED INTERR	FB	CRB41	11644	17GB	46501284	12003278003	F	10/5/2003	1438	115	76	8740	TERMINATOR	TERMINATO	228 W NEW MEX 2		LF	17GB		REPL ELBOW IN TR HE REF TP	1	0
FORCED INTERR	CY	TB 47	2427B	S197B	48730264	22003278005	T	10/5/2003	1455	50	1	50	COLLISION	COLLISION	9011 ROSIE LN 1		TF	487302642		REFUSED 50/7200 POT., TRACTOR CAUGHT DUY REF TR.	1	0
FORCED INTERR	GA	PHR01	30833	32M	65460331	32003278004	T	10/5/2003	1520	130	6	780	SQUIRREL	SQUIRREL	706 12TH 1		TF	654803128		refuse transf REF TR	1	0
FORCED INTERR	RS	LV 02	30077	FU1	55354578	32003278041	F	10/5/2003	1522	78	3	234	BU DISC OR BARI	DISC/BARRL	13700 CO 171 1		LF	FU1		REPL. FUSE BARREL ON URD PHASE LF FU1 RPLD B&J BARREL ON LF	1	0
FORCED INTERR	SU	WI 01				12003278004	C	10/5/2003	1555	0	0	0	OTHER EQUIPME	XARM	12846 WESTME		CL	WI01		CREWS ARE IN ROUTE. CREWS FOUND BROKEN CROSSARM AT 12846 WESTMERE, IS CLATING TO MAKE RPRS TRK 3513 ASSIGNED AS CIRCUIT COORDINATOR CRES MAKING RPRS TO XAR	1	1
FORCED INTERR	SU	WI 01	1G326			12003278004	C	10/5/2003	1555	37	1695	62752	OTHER EQUIPME				CL	WI01			0	0
FORCED INTERR	SU	WI 01	13067			12003278004	C	10/5/2003	1555	62	135	8370	OTHER EQUIPME				CL	WI01			0	0
FORCED INTERR	SU	WI 01	12875			12003278004	C	10/5/2003	1555	89	20	1780	OTHER EQUIPME				CL	WI01			0	0
FORCED INTERR	SU	WI 01	12366			12003278004	C	10/5/2003	1555	227	406	92162	OTHER EQUIPME				CL	WI01			0	0
FORCED INTERR	CH	UV 08	41936	F95M	58613008	32003278043	T	10/5/2003	1600	265	6	1590	UNKNOWN	UNKNOWN	13414 VILLAGR(1		BU	586130067		RPLD B&J TR RPLD LIGHTNING ARRESTOR.	1	0
FORCED INTERR	GA	STWO	35350	25P	62314540	32003278044	T	10/5/2003	1642	78	3	234	UNKNOWN	UNKNOWN	4014 REEVES 1		TF	623145409		LINE FUSE WAS NOT OUT ONLY THE TRANSFORMER IN THE REAR OF 4014 REEVES REF TR

| | | |

| | | |

FORCED INTERR	CY	TB 44	21021	J94G	4672910(	22003280022	T	10/7/2003	103(	51	2	102	LIGHTNING ARRE	LTNG ARRS'	14902	SCRUB JI	1	TF	467291084											1	0
FORCED INTERR	SH	WE 04	31267	13GD	57564097	32003280022	F	10/7/2003	103(	32	10	320	LIGHTNING	LIGHTNING	BEHIND CO GEI		1	LF	13GD											1	0
FORCED INTERR	BL	BI 04	10060	G55H	52560355	32003280043	L	10/7/2003	103(	169	1	169	HUMAN ERROR	HUMN ERRC	4 LANA LN		1	DR												1	0
FORCED INTERR	SH	CA 01	30154	144K	58539434	32003280024	T	10/7/2003	103(	24	5	120	SQUIRREL	SQUIRREL	4613 HONEYSUI		1	TF	585394364											1	0
FORCED INTERR	CY	SA 42	20935		48634266	22003280031	T	10/7/2003	104(	267	1	267	OH SEC/DR CL HI	OH SC CL-H	12115 WEST RC			BU	486342685	PR		SC								1	0
FORCED INTERR	KY	WA 42	11733	S3773	38525552	12003280004	F	10/7/2003	104(	137	8	1096	LIGHTNING	LIGHTNING	10207 FM 1489		1	LF	S3773											1	0
FORCED INTERR	RS	RZ 01	3573A	S3MU	50390528	32003280022	F	10/7/2003	104(	98	1	98	BIRD	BIRD	16803 CO. RD. 5		1	LF	S3MU											1	0
FORCED INTERR	GP	LK 01	21540	E95V	51625161	22003280034	F	10/7/2003	105(	90	25	2250	LIGHTNING ARRE	LTNG ARRS'	4210 LEMON TR		2	LF	E95V											1	0
FORCED INTERR	MP	HE 02	41117	C9C	52599234	22003280033	L	10/7/2003	105(	78	1	78	FLLNG TREE OUT	TREE FL/OE	732 W 20TH		1	DR												1	0
FORCED INTERR	SH	PE 04	30810	D6R	55492113	32003280022	T	10/7/2003	110(	34	1	34	UNKNOWN	UNKNOWN	2537 ROY RD		1	TF	554921139											1	0
FORCED INTERR	FB	WR 11	11588	G19I	35386422	12003280005	F	10/7/2003	114(	98	7	686	LIGHTNING	LIGHTNING	3431 FM 102 (BI		1	LF	G19I											1	0
FORCED INTERR	BL	UL 41	10459	Y82N	51566515	22003280005	F	10/7/2003	120(	30	8	240	BU DISC OR BARI	DISC/BARRL	SAGE, N OF ST/		1	LF	Y82N											1	0
FORCED INTERR	BL	BI 05	10068	34CT	51555480	12003280006	T	10/7/2003	120(	177	2	354	SEC COND OR DI	SECONDAR'	5110 GLENMON		1	SC	515554808											1	0
FORCED INTERR	HM	SW 08	41692	98P	55636222	32003280044	T	10/7/2003	122(	71	5	355	OH SEC/DR CL NI	OH SC CL-N	6315 HERMANN		1	SC	556362224	SC										1	0
FORCED INTERR	KY	MAR4	22688	63BH	45572167	12003280006	F	10/7/2003	123(	87	10	870	HUMAN ERROR	HUMN ERRC	1547, HOVEDEN 2			LF	63BH											1	0
FORCED INTERR.	GP	FR 44	21402	83AD	51631111	22003280004	T	10/7/2003	124(	65	6	390	CONTRACTOR-N	CON-NT HLF	6130 DOWNWO 2			TF	518311116	SC										1	0
FORCED INTERR	SH	CG 02	30208	JC9	57533154	22003280003	T	10/7/2003	131(	38	5	190	O/H PRIMARY CL/	OH PR CLMF	2208 MAIN ST		1	TF	575331544											1	0
FORCED INTERR	GP	AD 08	2A177		53642474	22003280005	T	10/7/2003	132(	11	1	11	TREE CLEARANC	TREE CLEAF	422 ALDINE BEA			TF	536424749											1	0
FORCED INTERR	HM	LW 43	20949	A86C		22003280051	F	10/7/2003	133(	43	15	645	COLLISION	COLLISION	14926 BEATTY E 1			DB	A86C											1	0
FORCED INTERR	GA	PHR02	31303	5Z4	63473118	32003280004	T	10/7/2003	135(	49	3	147	SQUIRREL	SQUIRREL	4423 14TH		1	TF	634731854											1	0
FORCED INTERR	HC	BR 13	10815	7W3	51537565	12003280004	F	10/7/2003	141(	21	29	609	UNKNOWN	UNKNOWN	4954 DUMFRIES 1			LF	7W3											1	0
FORCED INTERR.	MP	GG 08	10951	G91W	54549106	12003280008	T	10/7/2003	141(	21	8	168	SQUIRREL	SQUIRREL	5827 SOUTHFOI 1			TF	545491054											1	0
FORCED INTERR	GA	SCW0	30880	S9F	68369400	32003280046	L	10/7/2003	142(	72	1	72	OH SEC/DR CL NI	OH SC CL-N	120 DOLPHIN AV 1			DR												1	0
FORCED INTERR	BL	GS 21				12003280086	C	10/7/2003	143(	26	1	26	3 PHASE UG CAB	3 P/UG CBL	LABRANCH AT			CL	GS21											1	0
FORCED INTERR.	BL	GS 28				12003280086	C	10/7/2003	143(	28	4	104	3 PHASE UG CAB	3 P/UG CBL	LABRANCH AT			CL	GS21											1	0
FORCED INTERR	SH	MY 05	3550A	61KA	57482188	32003280054	F	10/7/2003	145(	35	20	700	SQUIRREL	SQUIRREL	2310 BUCKHOL' 1			LF	61KA											1	0
FORCED INTERR	MP	EU 08	21005	99GE	51590056	12003280009	F	10/7/2003	150(	51	2	102	LIGHTNING ARRE	LTNG ARRS'	100 NORTHWES 3			LF	99GE											1	0
FORCED INTERR	GA	AL 08	30032	9W6	80425524	32003280005	F	10/7/2003	150(	50	53	2650	UNKNOWN	UNKNOWN	2810 SHOUSE S 1			LF	9W6											1	0
FORCED INTERR	HC	BR 02	10604	W75	52544363	12003280009	L	10/7/2003	150(	97	1	97	OH SEC/DR CL HI	OH SC CL-H	8508 ILONA LN		1	SC												1	0
FORCED INTERR.	GA	PHR01	30832	2NM	64484207	32003280005	F	10/7/2003	151(	67	54	3618	O/H PRIMARY CL/	OH PR CLMF	2490 AVENUE L 1			LF	2NM	PR										1	0
FORCED INTERR	FB	RS 05	1555G	94AEY	43452217	12003280010	T	10/7/2003	155(	79	1	79	LIGHTNING	LIGHTNING	4911 GERKEN R 1			TF	434522178											1	0
FORCED INTERR.	GA	AL 10	30106	44EC	61420288	32003280067	F	10/7/2003	161(	76	5	380	BU DISC OR BARI	DISC/BARRL	12533 FM 1764 F 1			LF	44EC											1	0
FORCED INTERR	CH	LY 44	30427		58625098	32003280065	T	10/7/2003	161(	38	2	76	BU DISC OR BARI	DISC/BARRL	9205 PINELAND			TF	586250990											1	0
FORCED INTERR.	SB	TO 05	12675		51592545	32003280106	T	10/7/2003	162(	34	4	136	BIRD	BIRD	6205 W 34TH C			TF	515925456											1	0
FORCED INTERR	CH	LB 02	41257	6D4	56600334	32003280006	T	10/7/2003	162(	87	13	871	BU DISC OR BARI	DISC/BARRL	7978 RITZ ST		1	TF	566003480											1	0
FORCED INTERR	SL	SE 02	24288	67LA	36562284	32003280107	F	10/7/2003	163(	80	34	2720	TREE CLEARANC	TREE CLEAF	1322 FM 1458N		1	LF	67LA											1	0
FORCED INTERR	GA	KM 06	3100A		63474494	32003280071	T	10/7/2003	163(	58	4	232	SQUIRREL	SQUIRREL	3914 BAYSHORI			LF	634744941											1	0
FORCED INTERR	RS	LV 01	30079	D33F	56388252	32003280072	F	10/7/2003	163(	258	8	2064	LIGHTNING ARRE	LTNG ARRS'	108 SURREY DR 2			LF	D33F	DB										1	0
FORCED INTERR.	MP	BH 08	40305	J98U	55582148	22003280070	T	10/7/2003	164(	28	1	28	BU DISC OR BARI	DISC/BARRL	5401 EAST FWY 1			TF	555821499											1	0
FORCED INTERR	MP	CR 03	40529		53593057	22003280071	T	10/7/2003	170(	62	2	124	UNKNOWN	UNKNOWN	501 E 13TH			TF	535800573											1	0
FORCED INTERR	HM	AD 03	20401		53647284	22003280075	T	10/7/2003	171(	38	5	190	UNKNOWN	UNKNOWN	14039 LUTHE RI			TF	536472880											1	0
FORCED INTERR	RS	RZ 01	3573A	2F7	50408231	32003280076	T	10/7/2003	172(	75	1	75	SQUIRREL	SQUIRREL	3302 FM 1462W	1		TF	504082315											1	0
FORCED INTERR	HC	AM 06	10753	KP1	53520021	12003280012	T	10/7/2003	172(	26	3	78	LIGHTNING	LIGHTNING	2615 TIDEWATE 1			TF	535200218											1	0
FORCED INTERR	BZ	LJ 05	30634	A31G	53270084	32003280082	T	10/7/2003	173(	87	13	871	UNKNOWN	UNKNOWN	309 WISTERIA S 1			TF	532708043											1	0
FORCED INTERR	MP	WO 03	41834	J4D	52604242	22003280082	T	10/7/2003	174(	99	8	792	TRANSFORMER	TRANSFRM	1225 LAMONTE 1			BU	526042420											1	0
FORCED INTERR	GP	RU 04	41667	23MN	53611397	22003280086	T	10/7/2003	174(	58	12	696	VINES	VINES	109 TROY RD	1		TF	536113977											1	0
FORCED INTERR	MP	MP 01	41378		56560398	22003280090	T	10/7/2003	175(	64	10	640	UNKNOWN	UNKNOWN	7835 CANAL ST			TF	565603967											1	0
FORCED INTERR	BL	UL 49	10346		51565184	12003280012	T	10/7/2003	182(	98	3	294	TREE CLEARANC	TREE CLEAF	5330 SCHUMAC			PR	515651822											1	0
FORCED INTERR	SH	FT 05	30401	9EU	60536494	32003280088	T	10/7/2003	182(	48	3	144	SQUIRREL	SQUIRREL	3201 BERNARD 1			TF	605364949											1	0
FORCED INTERR	SB	DV 03	21722	L84	50564454	32003280126	F	10/7/2003	185(	103	9	927	VINES	VINES	101 RADNEY RC 1			LF	L84											1	0
FORCED INTERR	BL	KB 04	10149	FO8	53560250	12003280125	T	10/7/2003	190(	80	5	400	VINES	VINES	2017 COLQUITT 1			TF	535602509											1	0
FORCED INTERR	FB	NEW0	11245	13RB	40360367	12003280131	F	10/7/2003	190(	70	3	210	LIGHTNING	LIGHTNING	KEMP, NORTH (1			LF	13RB											1	0
FORCED INTERR	CH	OA 04	41587	2M8	56589256	32003280091	T	10/7/2003	190(	70	6	420	SQUIRREL	SQUIRREL	10334 DUNCUM 1			TF	565892642											1	0
FORCED INTERR	SB	WT 08	21843	M6D	51560027	12003280132	T	10/7/2003	191(	80	2	320	VINES	VINES	324 BUCKINGHI 1			TF	515600274											1	0
FORCED INTERR	SU	BAR43	11869		47563054	12003280136	T	10/7/2003	191(	79	1	79	LIGHTNING	LIGHTNING	2660 HIGHWAY			TF	475630548											1	0
FORCED INTERR	GA	KM 01	31476	C96S	61489510	32003280092	L	10/7/2003	192(	55	1	55	OH SEC/DR CL HI	OH SC CL-H	2203 REDWOOI 1			SC												1	0
FORCED INTERR	SU	QV 04	12902		49494333	12003280136	T	10/7/2003	194(	98	4	392	TREE CLEARANC	TREE CLEAF	3618 COVEY TR			TF	494943337											1	0
FORCED INTERR	MP	WO 02	41837	J15	52603472	22003280096	L	10/7/2003	194(	84	1	84	FLLNG TREE OUT	TREE FL/OE	1317 RICHELIEL 1			SC												1	0
FORCED INTERR.	GP	LK 02	21867	W37H	52624057	22003280100	T	10/7/2003	195(	120	3	360	BU DISC OR BARI	DISC/BARRL	1041 WALL ST	1		TF	526240578											1	0
FORCED INTERR	GP	LK 05	41296		52611504	22003280102	T	10/7/2003	200(	232	3	696	LIGHTNING	LIGHTNING	2122 W LITTLE '			BU	526115084											1	0
FORCED INTERR	BL	SF 01	10402		52560435	12003280141	T	10/7/2003	200(	77	6	462	BU DISC OR BARI	DISC/BARRL	4315 WESTHEIM			TF	525604353											1	0
FORCED INTERR	BA	AL 07	41148	69GS	61557297	32003280093	F	10/7/2003	202(	37	1	37	BU DISC OR BARI	DISC/BARRL	11900 STRANG 1			LF	69GS											1	0
FORCED INTERR	FB	NV 02	11220	99KT	42413107	12003280145	F	10/7/2003	202(	198	2	396	FLLNG TREE IN E	TREE FL/OE	8211 BOCKHOR 1			PR	99KT											1	0
FORCED INTERR	HC	BR 09	10614	7U7	51537491	12003280144	T	10/7/2003	203(	7	1	7	LIGHTNING	LIGHTNING	4930 W BELLFO 1			TF	515374914											1	0
FORCED INTERR.	CH	GP 05	40800	HG7	56578496	32003280095	T	10/7/2003	205(	29	10	290	UNKNOWN	UNKNOWN	10206 CHADWIC 1			TF	565784699											1	0
FORCED INTERR	HC	HOC0	11153	1DT	52524222	12003280147	T	10/7/2003	210(	35	8	280	LIGHTNING	LIGHTNING	4015 REGENCY 1			TF	525242254											1	0
FORCED INTERR	BZ	LJ 02	30618	68U	53269332	32003280099	T	10/7/2003	211(	38	7	266	TREE CLEARANC	TREE CLEAF	134 E DENT ST	1		TF	532693323											1	0
FORCED INTERR	BL	JN 09	10034		49559277	12003280148	T	10/7/2003	222(	239	4	956	OVERLOAD	OVERLOAD	6102 REDDING I			BU	495592738											1	0
FORCED INTERR	BA	NP 41	3765C	P30X	60657271	32003281001	T	10/8/2003	013(	46	1	46	UNKNOWN	UNKNOWN	17415 STEEVE (1			TF	606572712											1	0
FORCED INTERR	HC	AR 42	1583C	77UA	51479555	12003281002	F	10/8/2003	023(	83	11	913	UNKNOWN	UNKNOWN	719 W JASMINE 1			LF	77UA											1	0
FORCED INTERR	SB	WT 02	10433	UP9	51584404	12003281004	T	10/8/2003	045(	49	2	98	VINES	VINES	1202 ANTOINE (1			TF	515844047											1	0
FORCED INTERR	SU	IM 45	13081	X78E	47519555	12003281006	F	10/8/2003	055(	51	42	2142	VINES	VINES	914 BOURNEWC 2			LF	X78E											1	0
FORCED INTERR	GP	KI 46	22312	S66Y	49684522	22003281000	T	10/8/2003	070(	197	4	788	URD SEC PDSTL	URD SC PEC	8002 NULL CT	2		SC	496845258											1	0
FORCED INTERR.	SU	CE 08	12024	91BD	47536577	12003281007	F	10/8/2003	071(	157	79	12403	URD ELBOW	URD ELBOW	9302 WESTACR 2			LF	91BD	PR										1	0
FORCED INTERR	GP	AD 09	20367	H60W	53632548	22003281006	F	10/8/2003	072(	42	16	672	CONTRACTOR-N	CON-NT HLF	238 HAMBRICK 1			LF	H60W											1	0
FORCED INTERR	GA	PHR02	31330	E31H		32003281004	F	10/8/2003	073(	168	222	37296	COLLISION	COLLISION	4801 HWY 146	1		LF	E31H											1	0
FORCED INTERR	SU	IM 45	13081	X78E	47519555	12003281011	F	10/8/2003	080(	156	42	6552	TREE CLEARANC	TREE CLEAF	914 BOURNEWC 2			LF	X78E											1	0
FORCED INTERR	BZ	BZ 06	30636	71KL	53262425	32003281006	T	10/8/2003	080(	75	9	675	BU DISC OR BARI	DISC/BARRL	114 MULBERRY 1			TF	532624298											1	0
FORCED INTERR	CY	PI 43	21025	20AB	46724364	22003281015	T	10/8/2003	083(	70	2	140	BU DISC OR BARI	DISC/BARRL	25902 E MEMOR 1			TF	467243645											1	0
FORCED INTERR	GP	NB 45	20284		53653081	22003281016	T	10/8/2003	083(	141	1	141	OH SEC/DR CL HI	OH SC CL-H	1120 GOODNITE			SC	536530613											1	0
FORCED INTERR	MP	EU 03	41824	BD1	53591285	22003281002	T	10/8/2003	085(	52	19	988	SQUIRREL	SQUIRREL	2115 RUTLAND 1			TF	535912609											1	0
FORCED INTERR	BL	ST 03	13519	62ABN	50545594	12003281002	L	10/8/2003	085(	102	1	102	OH SEC/DR CL HI	OH SC CL-H	7156 REEF ST	1		DR												1	0
FORCED INTERR	HC	BL 03	10771	U32R	50521256	12003281024	F	10/8/2003	090(	56	33	1848	VINES	VINES	8739 E RYLANDI 2			LF	U32R											1	0
FORCED INTERR	CH	LY 44	41344	E34J		32003281006	F	10/8/2003	090(	38	23	874	SQUIRREL	SQUIRREL	17014 BLAIRWO 2			LF	E34J											1	0
FORCED INTERR	GA	TIK01	30102	R3SH	65385344	32003281001	T	10/8/2003	092(	28	2	56	OH SEC/DR CL NI	OH SC CL-N	110 QUAYSIDE 1 1			SC	653853440											1	0
FORCED INTERR	MP	NS 02	41034	6U8	54590151	22003281002	T	10/8/2003	093(	57	13	741	SQUIRREL	SQUIRREL	4121 HAIN ST	1		TF	545901513											1	0
FORCED INTERR	FB	WR 09	1553A	75KK	36377280	12003281002	F	10/8/2003	094(	88	1	88	BIRD	BIRD	915 S ALABAMA 1			LF	75KK											1	0
FORCED INTERR	FB	WR 13	11285	J73F		12003281031	F	10/8/2003	095(	47	20	940	SQUIRREL	SQUIRREL	1416 LINWOOD 2			LF	J73F											1	0
FORCED INTERR	FB	OB 44	13231	61TA	46526240	12003281003	F	10/8/2003	100(	192	1	192	BIRD	BIRD	11621 FM 1464	1		LF	61TA											1	0
FORCED INTERR	GA	SCW0	30882		69392311	32003281002	T	10/8/2003	101(	239	1	239	OH SEC/DR CL HI	OH SC CL-H	411 EAST BEAC			SC	693923162	DR										1	0
FORCED INTERR	MP	WO 02	41839	R10A	52605070	32003281003	T	10/8/2003	112(	41	8	328	BIRD	BIRD	902 JUDWAY S 1			TF	526080787											1	0
FORCED INTERR	MP	BH 07	40299	24DH	54508530	22003281004	L	10/8/2003	114(	43	1	43	OH SEC/DR CL HI	OH SC CL-H	3718 LELIA ST	1		DR												1	0
FORCED INTERR	GA	STW0	31690		66361178	32003281002	T	10/8/2003	115(	229	1	229	OH SEC/DR CL HI	OH SC CL-H	11280 STEWAR'			SC	663611787											1	0
FORCED INTERR	HC	AM 06	10751		53526568	12003281005	T	10/8/2003	122(	182	1	182	UNKNOWN	UNKNOWN	9851 SOUTH FW			BU	535285607											1	0
FORCED INTERR	CY	PI 41	2A120	22KD	44763240	22003281004	T	10/8/2003	123(	58	3	174	TREE CLEARANC	TREE CLEAF	306 SMITH RD	1		TF	447632404											1	0
FORCED INTERR	SH	PO 09	41390	P5SS	61496407	32003281041	T	10/8/2003	125(	58	2	116	LIGHTNING	LIGHTNING	4900 E NASA RC 1			TF	614964078											1	0
FORCED INTERR	BA	CD 12	40346	86KB	64590243	32003281004	F	10/8/2003	130(	47	3	141	SQUIRREL	SQUIRREL	1015 E ARCHER 1			LF	86KB											1	0
FORCED INTERR	BZ	BZ 06	30636	71KL	53262425	32003281004	L	10/8/2003	130(	52	1	52	FALLING DEAD TI	TR FL/DEAD	101 SAGE ST	1		SC												1	0
FORCED INTERR	FB	RS 03	11199	58GB	43487517	12003281008	T	10/8/2003	131(	20	1	20	BIRD	BIRD	2700 AVENUE A 1			TF	434875177											1	0
FORCED INTERR	SU	STF04	12279	R61Y	48516011	12003281007	F	10/8/2003	131(	85	17	1615	UNKNOWN	UNKNOWN	101 KESWICK 2			LF	R61Y	DB										1	0
FORCED INTERR	RS	AE 06	30076	48S	54349658	32003281004	F	10/8/2003	131(	43	13	559	BU DISC OR BARI	DISC/BARRL	2002 AVENUE K 1			LF	48S											1	0
FORCED INTERR	FB	LC 01	11249	B1T		12003281007	F	10/8/2003	132(	105	13	1365	O/H PRIMARY CL/	OH PR CLMF	3352 S BILLIE NI 1			LF	B1T	PR		PD								1	0
FORCED INTERR	GP	LK 06	21880	97SL		22003281004	F	10/8/2003	133(	74	99	7326	O/H PRIMARY CL/	OH PR CLMF	7905 MAXROY S 1			LF	97SL	PR										1	0
FORCED INTERR	MP	AN 02	40007	A69X	53592444	22003281005	T	10/8/2003	133(	46	10	460	SQUIRREL	SQUIRREL	109 E 27TH	1		TF	535924425											1	0
FORCED INTERR	SH	TE 03	31306	6D9	55503355	32003281005	T	10/8/2003	134(	118	109	12862	O/H PRIMARY CL/	OH PR CLMF	5959 S SAM HOI 1			PR	6D9											1	0
FORCED INTERR	SU	HY 11	11691	42H	49566425	12003281007	T	10/8/2003	140(	27	10	270	HUMAN ERROR	HUMN ERRC	10030 OLYMPIA	1		TF	495664293											1	0
FORCED INTERR	CH	GW 02	40896	CU5	56614242	32003281005	F	10/8/2003	142(	55	14	770	CONTRACTOR-N	CON-NT HLF	MESA @ FRING 1			LF	CU5											1	0
FORCED INTERR	CH	GW 02	40896	EK8	56615214	32003281006	F	10/8/2003	142(	161	21	3381	COLLISION	COLLISION	9239 LAKE PARI 1			DB	EK8	PR										1	0
FORCED INTERR	MP	WO 03	41838	K89C	52603446	22003281005	T	10/8/2003	143(	91	6	546	SQUIRREL	SQUIRREL	5007 HOLLOW E 1			TF	526034468											1	0
FORCED INTERR	SB	EC 14	21730	B95K	50570438	12003281008	T	10/8/2003	143(	238	5	1190	UNKNOWN	UNKNOWN	19 WILLIAMSBU 1			BU	505704386											1	0
FORCED INTERR	HC	HM 04	11023		54530345	12003281009	T	10/8/2003	150(	88	5	440	SQUIRREL	SQUIRREL	8723 COMAL ST	1		TF	545303456											1	0
FORCED INTERR	CY	WL 41	21154	71ML	40698001	22003281006	T	10/8/2003	150(	98	1	98	VINES	VINES	18612 MATHIS F 1			TF	406980015											1	0
FORCED INTERR	MP	BH 06	40293	J62U	55571422	22003281064	T	10/8/2003	152(	61	2	122	VINES	VINES	200 EMILE ST	1		TF	555714237											1	0
FORCED INTERR	FB	RS 04	11400	N5H	43485370	12003281009	F	10/8/2003	153(	50	15	750	SQUIRREL	SQUIRREL	1109 3RD	1		LF	N5H											1	0
FORCED INTERR	MP	UN 03	41714	D9F	55551533	22003281007	F	10/8/2003	153(	36	8	288	BU DISC OR BARI	DISC/BARRL	5330 GULF FWY 1			LF	D9F											1	0
FORCED INTERR	GA	KM 07	30605	B33	63472415	32003281007	F	10/8/2003	155(	82	76	6232	TREE CLEARANC	TREE CLEAF	3214 ALSWORT 1			LF	B33											1	0

NEED TO REPLACE LIK YOU CAN GET A TRUCK TO IT REF TR. BJH
REF LF;
REPLACED CLAMPS AT WHEAD RPLD CONN @ WH.
REFUSE 90 CONV REAR OF 4603 GARDENA LF WAS NOT BLOWN; REF TR; BJH
REPLACED 167KVA 19.9/277 OH TR WITH THE SAME UNABLE TO GET LOAD READING...NO LOAD RPLD BAJ TR, RPLD LIMITER @ TR, RPRD BUSS WORK @ TR.
REF LF; BJH
REFUSED LF, REF LF;
WILL NEED LIGHTING ARRESTOR & SQUIRREL GUARD TIP ERW; REF TP; BJH
REATTACHED THE DROPS BACK TO WH., CUT OUT AT WH, METER GONE, PIJ DR
REFUSED OPEN DELTA BANK / OMIR, REF TR.
REFUSED LF 0 HI 25T PASY LIGHTING. ALSO CLEANED VINES OFF LINE POLE REF LF;
REFUSED 8 PHASE #FUSE BROKE; REF LF
CUSTOMER WANTS OUTAGE AFTER 18:00 HRS TODAY ALL SERVICE ON AT THIS TIME WILL NEED CLAMP REPLACEMENT @ WEATHERHEAD ALSO WILL NEED TO GET WITH PIC TO UPGRADI
MADE REPAIRS TO BEC LEADS & BROKEN NEUTRAL ON DROPS / LEFT SERV ON / NOTIFIED, RPRD BUSS WORK @ TR RPRD BEC CONN @ PL-1 CUST.
REFUSED Y P DUE TO A PULLED FUSE, REF TP;
NEED TO REPLACE URD BEC HAVE SEC BY-PASS HOW NEED TO REPAIR OR REPLACE ..... I MADE REPAIRS TO BY-PASS TRACTOR RAN OVER RESET TR, RPRD BEC-1 CUST RPRD PED.
REFUSE 25 BK WITH 50 FUSE PULLED INTOO OH 20; REF TR.
REFUSED 90 LIGHTER-W L-- NEED TO TRIM PALM TREE AWAY FROM TRNS BANK & PRI--BCIC; REF TR. BJH
I BELIEVE MOWER BUMPED THE LINE FURE POLE CAUSING C PHASE BARREL TO FALL OPEN. RPLD BAJ DISC-LF NOT BLOWN.
REFUSED TRANSFORMER..... HAS WLP, REF TR;
REFUSED N & M L.F. /UNKNOWNK REF LF
infinite trbs. REF TR
RPLD CONN @ WH.
3 BLDG HA

| | | |

FORCED INTERR	GP	LK 03	41291	589	52616500	220032820061	F	10/9/2003	1259	137	21	2877	FLLNG TREE IN E	TREE FU/E	6805	KNOX ST	1	LF	589	PR									1	0
FORCED INTERR	HC	HOCO	11155	A17W	52515530	120032820125	T	10/9/2003	1259	46	8	368	STRONG WIND	WIND	3807	WESTHAM	1	TF	525155360										1	0
FORCED INTERR	GA	AL 07	30038	A36B	60414515	320032820065	T	10/9/2003	1301	47	1	47	VINES	VINES	14108	STH	1	TF	604145181										1	0
FORCED INTERR.	SB	BM 01	22272	7J1	49591020	120032820126	T	10/9/2003	1302	56	2	112	BU DISC OR BARR	DISC/BARRL	10830	WARWAN	1	TF	495910208										1	0
FORCED INTERR	SH	TE 06	31080	53RH	55504170	320032820064	T	10/9/2003	1302	52	6	312	LIGHTNING	LIGHTNING	1409	ODAY RD	1	TF	555041789										1	0
FORCED INTERR	BL	KB 09	10166	T3Z	52567000	120032820127	F	10/9/2003	1310	65	127	8255	LIGHTNING	LIGHTNING	2903	BISSONNE	1	LF	T3Z										1	0
FORCED INTERR	SU	IM 42	14050		48491314	120032820125	T	10/9/2003	1319	84	6	504	TREE CLEARANC	TREE CLEAR	2523	WOODSTR		TF	484913149										1	0
FORCED INTERR	BL	HE 04	11659	B39S	53570518	120032820132	F	10/9/2003	1320	62	8	496	UNKNOWN	UNKNOWN	4710	LILLIAN ST	1	LF	B39S										1	0
FORCED INTERR	MP	UN 11	10975	53MF	54555528	220032820065	T	10/9/2003	1322	61	6	366	SQUIRREL	SQUIRREL	4401	CHARLES1	1	TF	545552822										1	0
FORCED INTERR	SB	SA 43	21295	E36N	48619468	120032820133	T	10/9/2003	1322	55	10	550	UNKNOWN	UNKNOWN	11107	HAYSLIP	1	TF	486194882										1	0
FORCED INTERR.	BL	SF 02	10415	MU1		120032820137	F	10/9/2003	1331	64	29	1856	TREE CLEARANC	TREE CLEAR	3314	CHEVY CH	1	LF	MU1										1	0
FORCED INTERR	GP	KL 42	21941		48663477	220032820066	T	10/9/2003	1333	62	9	558	TREE CLEARANC	TREE CLEAR	11611	MOORCR		TF	486634727										1	0
FORCED INTERR	BA	NP 44	41301	29ABD	62674004	320032820074	F	10/9/2003	1333	76	1	76	SQUIRREL	SQUIRREL	4901	DAIRY OAI	1	LF	29ABD	TF	626740040								1	0
FORCED INTERR	SH	CC 03	10634	75DU	54511446	120032820136	F	10/9/2003	1335	66	20	1320	LIGHTNING	LIGHTNING	12923	SCOTT S	2	LF	75DU										1	0
FORCED INTERR	GA	STWD	31643	Y69F	66373315	320032820076	T	10/9/2003	1338	51	3	153	BU DISC OR BARR	DISC/BARRL	1214	103RD ST	1	TF	663733121										1	0
FORCED INTERR	HM	HB 45	21068	N61S	58671434	220032820071	F	10/9/2003	1337	0	0	0	LIGHTNING	LIGHTNING	18827	DROITWI	2	LF	N61S	BU	586723466								1	0
FORCED INTERR	HM	HB 45				220032820071	F	10/9/2003	1337	207	49	10143	LIGHTNING				2	LF	N61S										0	0
FORCED INTERR	HM	HB 45				220032820071	F	10/9/2003	1337	207	50	10350	LIGHTNING				2	LF	N61S										0	0
FORCED INTERR	HM	HB 45				220032820071	F	10/9/2003	1337	402	4	1608	LIGHTNING				2	LF	N61S										0	0
FORCED INTERR	BZ	VL 04	3526D	E98F	57259203	320032820080	L	10/9/2003	1338	73	1	73	UNKNOWN	UNKNOWN	223	1ST	1	DR											1	0
FORCED INTERR	CH	AD 02	40066	DU5	54622376	320032820081	T	10/9/2003	1340	43	12	516	LIGHTNING	LIGHTNING	2157	CROMWEL	1	TF	546223797										1	0
FORCED INTERR	BL	SF 42	10714	J32M	51574401	120032820140	F	10/9/2003	1341	170	6	1360	UNKNOWN	UNKNOWN	26	W BROAD D/	2	LF	J32M										1	0
FORCED INTERR	BL	JN 07	10019		50552261	120032820142	T	10/9/2003	1344	95	5	475	LIGHTNING	LIGHTNING	6006	TAM O'SH/		TF	505522617										1	0
FORCED INTERR	GP	LK 10	22122	H8K	52610577	220032820074	T	10/9/2003	1344	374	6	2244	LIGHTNING	LIGHTNING	6901	EZZARD CI	1	TF	526105771										1	0
FORCED INTERR	HC	MV 01	1524A		54466546	120032820144	T	10/9/2003	1350	68	3	204	VINES	VINES	5330	PATTERSC		TF	544665465										1	0
FORCED INTERR	GP	LK 01	20862	50MH	52823084	220032820076	F	10/9/2003	1350	56	7	392	LIGHTNING	LIGHTNING	EDMOUNT	@ W	1	LF	50MH	TF	526230841								1	0
FORCED INTERR	HM	RA 44	21076	8738	52725310	220032820078	T	10/9/2003	1414	211	1	211	VINES	VINES	29114	GENEVA	1	TF	527253101										1	0
FORCED INTERR	HM	KW 41	20255		57699952	220032820081	T	10/9/2003	1415	476	2	952	UNKNOWN	UNKNOWN	2702	LAUREL G		TF	576995234										1	0
FORCED INTERR	BL	BR 12	10819		52543191	120032820146	L	10/9/2003	1415	187	1	187	UNKNOWN	UNKNOWN	3722	SUN VALLE		DR											1	0
FORCED INTERR	CY	PI 43	21028		45721042	320032820082	T	10/9/2003	1420	206	6	1236	BIRD	BIRD	16328	CECILIA C		PR	457210431										1	0
FORCED INTERR	GA	GL 08	30505	E74E	68385350	320032820090	L	10/9/2003	1430	54	1	54	OH SEC/DR CL H	OH SC CL-H	2023	AVENUE O	1	DR											1	0
FORCED INTERR	BL	CR 05	41052	BA5	53589040	120032820146	F	10/9/2003	1430	100	24	2400	TREE CLEARANC	TREE CLEAR	HOLLY @ BINGI		1	LF	BA5										1	0
FORCED INTERR	SB	OH 05	21530	K31A	51611204	120032820151	F	10/9/2003	1430	110	34	3740	LIGHTNING	LIGHTNING	5801	LUMBERDI	2	LF	K31A										1	0
FORCED INTERR	GP	AD 09	20387	H60W	53632554	220032820087	F	10/9/2003	1440	81	32	2592	UNKNOWN	UNKNOWN	305	HAMBRICK	1	LF	H60W										1	0
FORCED INTERR	CY	TB 45	21044	S33C	47701533	220032820088	T	10/9/2003	1440	41	5	205	VINES	VINES	14503	MARY JAI	1	TF	477015371										1	0
FORCED INTERR	FB	NV 02	11212	52RR	41423598	120032820153	T	10/9/2003	1445	171	1	171	LIGHTNING	LIGHTNING	10211	BRINKME	1	BU	414235983										1	0
FORCED INTERR	GP	LU 02	20554	F83S	51682548	220032820088	F	10/9/2003	1447	77	12	924	LIGHTNING	LIGHTNING	4033	CYPRESS	2	LF	F83S										1	0
FORCED INTERR	SH	PE 05	30811	68PC	55484573	320032820090	F	10/9/2003	1450	38	1	38	BIRD	BIRD	15030	CO 91	1	LF	68PC										1	0
FORCED INTERR	MP	WD 02	41829		52607104	220032820092	T	10/9/2003	1500	57	5	285	LIGHTNING	LIGHTNING	3710	ALBA ST C		TF	526071040										1	0
FORCED INTERR	CH	GW 06	40904	FK6	55618356	320032820096	T	10/9/2003	1500	189	6	1134	FLLNG TREE IN E	TREE FU/E	7720	BRETSHIR	1	SC	556183587										1	0
FORCED INTERR	MP	MP 07	41388		55564390	220032820098	T	10/9/2003	1515	36	1	36	LIGHTNING	LIGHTNING	338	S WAYSIDE		TF	555643933										1	0
FORCED INTERR	HM	RA 03	20411	95KF	51739268	220032820097	F	10/9/2003	1515	232	31	7192	UNKNOWN	UNKNOWN	25603	SPRING F	1	LF	95KF	PR									1	0
FORCED INTERR	GP	LK 07	41298	LH4	52628074	220032820101	T	10/9/2003	1520	287	2	574	LIGHTNING	LIGHTNING	7429	DE PRIEST	1	BU	526280747										1	0
FORCED INTERR	KY	FZ 41	22607	P29K	44583087	120032820161	F	10/9/2003	1520	200	65	13000	TERMINATOR	TERMINATO	118	CONCORD	2	LF	P29K	PR	445830622								1	0
FORCED INTERR	HM	TWG4	20290	S263I		220032820104	F	10/9/2003	1530	350	6	2100	RISING WATER	RISING H20	23082	BANQUO	1	LF	F41S	PR									1	0
FORCED INTERR	CY	TB 45	21046	S226T		220032820105	F	10/9/2003	1530	311	1	311	LIGHTNING	LIGHTNING	22222	DECKER I	1	LF	I12P										1	0
FORCED INTERR	MP	HG 04	41082		55559475	220032820106	T	10/9/2003	1540	65	2	130	UNKNOWN	UNKNOWN	7224	BOWIE ST		TF	555594759										1	0
FORCED INTERR	GP	LK 10	22122	K41L	51619368	220032820106	T	10/9/2003	1555	91	3	273	UNKNOWN	UNKNOWN	2501	GARAPAN	1	TF	516193695										1	0
FORCED INTERR	BA	BT 07	30925	BA8	62589206	320032820100	T	10/9/2003	1600	11	2	22	TREE CLEARANC	TREE CLEAR	5020	GOOSE CF	1	SC	625892094										1	0
FORCED INTERR	CY	PI 42	2320A	24AAQ	48774368	220032820110	T	10/9/2003	1600	155	2	310	LIGHTNING	LIGHTNING	7006	DILLON DR	1	PR	487743881										1	0
FORCED INTERR	SU	IM 45	12068		47507350	120032820170	T	10/9/2003	1611	407	7	2849	OH SEC/DR CL H	OH SC CL-H	1480	HIGHWAY		SC	475073505										1	0
FORCED INTERR	GP	BA 41	20652	F46B	50678241	220032820111	T	10/9/2003	1611	113	6	678	UNKNOWN	UNKNOWN	3919	MIDFORES	1	TF	506782412										1	0
FORCED INTERR	BA	CD 05	40370	I50N	63576584	320032820104	T	10/9/2003	1616	63	3	189	TREE CLEARANC	TREE CLEAR	308	INWOOD DI	1	TF	635786841										1	0
FORCED INTERR	CH	GP 06	40815	N47	56566467	220032820114	T	10/9/2003	1618	67	8	536	VINES	VINES	118	PENNSYLVA	1	TF	565664674										1	0
FORCED INTERR	SU	AF 10	11823	D81B	48547285	120032820175	F	10/9/2003	1624	372	55	20460	TREE CLEARANC	TREE CLEAR	8001	S KIRKWO	1	LF	D81B										1	0
FORCED INTERR	SB	ADK42	22016	68CD	47619221	120032820174	F	10/9/2003	1628		0	0	LIGHTNING	LIGHTNING	13623	HARPERS	2	LF	68CD	PR									1	0
FORCED INTERR.	SB	ADK42				120032820174	F	10/9/2003	1628	225	32	7200	LIGHTNING				2	LF	68CD										1	0
FORCED INTERR	BL	HE 06	10681	90DU	53583015	120032820175	T	10/9/2003	1630	169	7	1183	VINES	VINES	130	HEIGHTS BL	1	TF	535830193										1	0
FORCED INTERR	BL	DN 05	10554	P8R	53571257	120032820176	F	10/9/2003	1630	95	14	1330	LIGHTNING	LIGHTNING	DUNLAVY, S OF		1	LF	P8R	TF	535712570								1	0
FORCED INTERR	MP	GG 01	40952	92DH	55544582	220032820120	T	10/9/2003	1630	37	4	148	LIGHTNING	LIGHTNING	3607	FLORINE E	1	TF	555445928										1	0
FORCED INTERR	SB	ADK45	22017	S22T	49604341	120032820177	F	10/9/2003	1640	32	113	3616	OTHER	BOND WIRE	10728	CLEAR CI	2	SB	S22T										1	0
FORCED INTERR	FB	NV 02	11202		42418525	120032820178	L	10/9/2003	1640	132	1	132	FLLNG TREE OUT	TREE FL/OE	3210	NORTH AV		DR											1	0
FORCED INTERR	SU	WW 0	12417	25X	49548552	120032820176	E	10/9/2003	1640	106	24	2544	LIGHTNING	LIGHTNING	8919	ROWAN LI	1	LF	25X	TF	495485522								1	0
FORCED INTERR	SH	CC 03	10834	75DU	54511444	120032820182	F	10/9/2003	1650	212	20	4240	RISING WATER	RISING H20	12923	SCOTT S	2	LF	75DU										1	0
FORCED INTERR	SU	CE 10	11945		47528285	120032820184	T	10/9/2003	1650	211	5	1055	VINES	VINES	13719	LYNNWO		TF	475282635										1	0
FORCED INTERR	SH	FW 03	30447	I27K		320032820110	F	10/9/2003	1700	70	247	17290	STRONG WIND	WIND	17231	BLACKHA	1	LF	I27K										1	0
FORCED INTERR	SU	QV 02	12157	H17Z	50490534	120032820187	F	10/9/2003	1700	257	48	12336	LIGHTNING	LIGHTNING	2319	BRADFORI	2	LF	H17Z										1	0
FORCED INTERR	HC	PZ 42	13003	85AN	53545431	120032820188	F	10/9/2003	1700	245	181	44345	OH SEC/DR CL H	OH SC CL-H	2121	HEPBURN	2	LF	85AN										1	0
FORCED INTERR	SB	EC 05	21707	K29S		120032820188	F	10/9/2003	1700	358	57	20406	LIGHTNING	LIGHTNING	8320	CEDARSPI	1	LF	K29S										1	0
FORCED INTERR	BA	BT 07	30925	A24T	62588198	320032820111	T	10/9/2003	1700	49	2	98	VINES	VINES	5000	GOOSE CF	1	TF	625881988										1	0
FORCED INTERR	BA	BT 07	30925	AW7	62588180	320032820112	T	10/9/2003	1700	44	5	220	VINES	VINES	5000	ARROWHE	1	TF	625881809										1	0
FORCED INTERR	HC	MC 03	11103	N4SL	50505570	120032820191	F	10/9/2003	1710	168	31	5208	LIGHTNING	LIGHTNING	1707	THORNBR	2	LF	N4SL										1	0
FORCED INTERR	SU	QV 01	11341	F94Z	50490175	220032820192	F	10/9/2003	1710	101	27	2727	LIGHTNING	LIGHTNING	3514	CROSS CR	2	LF	F94Z										1	0
FORCED INTERR	HC	TV 01	11228	R11W	50496460	120032820192	F	10/9/2003	1710	170	34	5780	LIGHTNING	LIGHTNING	8303	QUAIL BUF	2	LF	R11W										1	0
FORCED INTERR	GP	DH 10	40599	F23H	51619040	220032820130	F	10/9/2003	1714	0	0	0	UNKNOWN	UNKNOWN	5526	GOLDSPIE	2	LF	F23H	PR									1	0
FORCED INTERR	GP	DH 10				220032820130	F	10/9/2003	1714	184	7	1288	UNKNOWN				2	LF	F23H										1	0
FORCED INTERR	GP	DH 10				220032820130	F	10/9/2003	1714	184	19	3496	UNKNOWN				2	LF	F23H										1	0
FORCED INTERR	SU	WI 04	12367	E24M	48563474	120032820194	F	10/9/2003	1715	54	32	1728	LIGHTNING	LIGHTNING	12430	NOVA DR	2	LF	E24M										1	0
FORCED INTERR.	SU	IM 44	12095		48507044	120032820195	T	10/9/2003	1715	118	3	354	LIGHTNING	LIGHTNING	4103	KITCHEN	1	TF	485070401										1	0
FORCED INTERR	SB	WO 06	41864	M80F	52594911	220032820196	F	10/9/2003	1720	298	17	5066	BU DISC OR BARR	DISC/BARRL	E TC	JESTER @	1	LF	M80F										1	0
FORCED INTERR	BL	ST 12	12829	45AR	51550181	120032820196	T	10/9/2003	1721	189	6	1134	LIGHTNING	LIGHTNING	6955	ASHCROF	1	TF	515501875										1	0
FORCED INTERR	BL	BI 45	10105	U51A	51555500	120032820200	F	10/9/2003	1722	258	129	33282	TERMINATOR	TERMINATO	5401	CHIMNEY I	2	LF	U51A	PR									1	0
FORCED INTERR	SU	STF01	12256	F44A	48528420	120032820201	F	10/9/2003	1722	0	0	0	UNKNOWN	UNKNOWN	11910	SCOTTSC	2	LF	F44A	PR		BU	485						1	0
FORCED INTERR	SU	STF01				120032820201	F	10/9/2003	1722	70	14	980	UNKNOWN				2	LF	F44A										0	0
FORCED INTERR.	SU	STF01				120032820201	F	10/9/2003	1722	438	2	876	UNKNOWN				2	LF	F44A										0	0
FORCED INTERR	SB	GE 41	21193	N47U	46819224	120032820202	F	10/9/2003	1724	88	98	8624	LIGHTNING	LIGHTNING	16811	GRAMPIN	2	LF	N47U										1	0
FORCED INTERR.	HC	SO 41	12620	904	53480131	120032820203	F	10/9/2003	1728	191	60	11480	LIGHTNING	LIGHTNING	3203	COUNTY R	1	LF	904										1	0
FORCED INTERR	HC	MC 03	11108	R70F	50517195	120032820204	F	10/9/2003	1728	145	42	6090	RISING WATER	RISING H20	7842	CHASECRI	2	LF	R70F										1	0
FORCED INTERR	HC	QV 08	11481	R53F	50504247	120032820207	F	10/9/2003	1728	146	70	10220	LIGHTNING	LIGHTNING	1319	TINY TREE	2	LF	R53F										1	0
FORCED INTERR	BZ	BZ 01	30143		53267167	320032820115	T	10/9/2003	1730	22	4	88	UNKNOWN	UNKNOWN	167	S MAIN ST	8	TF	532671678										1	0
FORCED INTERR	HC	MC 05	12198	M62C	50503468	120032820210	F	10/9/2003	1734	196	41	8036	TREE CLEARANC	TREE CLEAR	1311	WHISPERI	2	LF	M62C										1	0
FORCED INTERR	SU	BAR 46	11883	U54A	48546340	120032820211	F	10/9/2003	1734	282	75	21150	URD ELBOW	URD ELBOW	7436	LOBERA D	2	LF	U54A										1	0
FORCED INTERR	HC	TV 02	11130	K81H	51500298	120032820212	F	10/9/2003	1738	173	17	2941	LIGHTNING	LIGHTNING	15919	WILLBRIA	2	LF	K81H										1	0
FORCED INTERR	HC	MC 05	12192	N71G	50501386	120032820213	F	10/9/2003	1738	110	39	4290	LIGHTNING	LIGHTNING	1818	GREEN ST	2	LF	N71G										1	0
FORCED INTERR.	HC	TV 04	12813	U89R	51504274	120032820215	F	10/9/2003	1741	135	47	6345	LIGHTNING	LIGHTNING	18206	CANARID	2	LF	U89R										1	0
FORCED INTERR	GP	SA 03	21358	I50S	49622301	220032820134	F	10/9/2003	1741	94	31	2914	LIGHTNING	LIGHTNING	18017	SINGAPO	2	LF	I50S										1	0
FORCED INTERR	CH	GA 06	41813	F10M	57584338	320032820117	F	10/9/2003	1741	81	12	972	LIGHTNING	LIGHTNING	880	MAXEY RD	2	LF	F10M										1	0
FORCED INTERR	HC	TV 02	14326	G31W	51502247	120032820216	F	10/9/2003	1744	124	17	2108	LIGHTNING	LIGHTNING	8906	TRIGATE E	2	LF	G31W										1	0
FORCED INTERR	GP	FR 46	22003	M71Z	50807537	220032820136	F	10/9/2003	1748	55	111	6105	LIGHTNING	LIGHTNING	7200	PINEMONT	2	LF	M71Z										1	0
FORCED INTERR	SH	PE 04	31599	W98O	54489019	320032820118	F	10/9/2003	1748	124	13	1612	LIGHTNING	LIGHTNING	4825	ARNOLD D	1	LF	W98O										1	0
FORCED INTERR.	HC	BL 04	10775	M34U	51500423	120032820218	F	10/9/2003	1748	168	38	6384	LIGHTNING	LIGHTNING	15502	GATEVIEI	2	LF	M34U										1	0
FORCED INTERR.	HC	TV 02	11129	G34W	51503222	120032820219	F	10/9/2003	1748	159	37	5883	LIGHTNING	LIGHTNING	8838	TRIGATE E	2	LF	G34W										1	0
FORCED INTERR	HC	TV 02	14326	G30W	51502230	120032820220	F	10/9/2003	1748	141	46	6486	LIGHTNING	LIGHTNING	8911	KRAUSE D	2	LF	G30W										1	0
FORCED INTERR.	GA	AL 05	30029	28FJ	60415184	320032820120	T	10/9/2003	1748	305	3	915	LIGHTNING	LIGHTNING	5422	TREEPOIN	1	TF	604151886										1	0
FORCED INTERR.	HC	QV 06	11121	U45F	50504118	120032820221	F	10/9/2003	1752	170	29	4930	LIGHTNING	LIGHTNING	2806	INDIAN TR	2	LF	U45F										1	0
FORCED INTERR.	SU	CE 01	12962	P10F	47537100	120032820222	F	10/9/2003	1752	212	55	11660	LIGHTNING	LIGHTNING	10402	STOCKMV	2	LF	P10F										1	0
FORCED INTERR	BA	UW 05	31115	P72B	61540268	320032820121	F	10/9/2003	1752	0	0	0	LIGHTNING	LIGHTNING	2209	MEADOWL	2	LF	P72B	BU	615402683								1	0
FORCED INTERR	BA	UW 05				320032820121	F	10/9/2003	1752	213	2	426	LIGHTNING				2	LF	P72B										0	0
FORCED INTERR	BA	UW 05				320032820121	F	10/9/2003	1752	213	18	3834	LIGHTNING				2	LF	P72B										0	0
FORCED INTERR	BA	UW 05				320032820121	F	10/9/2003	1752	593	6	3558	LIGHTNING				2	LF	P72B										0	0
FORCED INTERR	SB	ADK45	22731	S22T	49604322	120032820224	T	10/9/2003	1758	55	6	330	URD ELBOW	URD ELBOW	4603	MISTY SHA	2	PR	496043236										1	0
FORCED INTERR	RS	AV 03	3505A	B8A	55425330	320032820123	F	10/9/2003	1800	190	132	25080	LIGHTNING	LIGHTNING	12900	CO 185 (1	1	LF	B8A										1	0
FORCED INTERR	SU	CE 02	11935	G98Z	47528200	120032820225	F	10/9/2003	1800	145	10	1450	LIGHTNING	LIGHTNING	1523	BRIARBAN	2	LF	G98Z										1	0
FORCED INTERR	SU	IM 41	12042		48490545	120032820227	T	10/9/2003	1807	193	3	579	STRONG WIND	WIND	2111	GREEN CC		TF	484905494										1	0
FORCED INTERR	RS	LV 01	30080	55GK		320032820124	F	10/9/2003	1807	127	6	762	LIGHTNING	LIGHTNING	8525	COUNTY R	1	LF	55GK										1	0
FORCED INTERR	SU	CE 10	11948	H87Y	47529140	120032820230	F	10/9/2003	1809	103	39	4017	TREE CLEARANC	TREE CLEAR	13611	HAMPTOI	2	LF	H87Y										1	0

PU PR-FUSE BLOWN.
WIND AND TREES BLEW BEC TOGETHER. REF TR.
REFUSED TRANS (10 AMP FUSE). REF TR.
RPLD BU BARREL ON TR.
REF TR.
FOUND ALL THE PRI IN THE CLEAR. REFUSED B AND C PHASE OF LF T32 #61. TAKEN OUT BY LIGHTNING. REF LF
NEED TO TRIM BAMBOO PLANT IN THE REAR OF 2518 WOODSTREAM 2ND TIME PLANT TOOK OUT TRAN. REF TR. BJH
FOUND 2 OF 3 PHASES OUT ON THIS LF ONE CUST STOPPED ME AND SAID IT IS ALWAYS THE SAME 2 OUT COULD NOT FIND CAUSE UNLESS SOMEONE BUMPED A POLE BEHIND THIS LF RE
REFUSED POWER POT ON OPEN DELTA BANK. REF TR. BJH
REFUSED TRANSFORMER CAUSE UNKNOWN / CH&B. REF TR.
REF LF
REF TR.
REFUSED L F AND TRANS AT SAME ADDRESS REF LF REF TR.
REF TP.
TRANSRED TREE AND REPL. A BAD BARREL. RPLD BAD BARREL ON TR. BJH
CREW RPLCD TRANS @ #6 @ 18622 TWIGBWORTH LN URD VAN EN ROUTE @ 13:45 GOM

hgt. # 4 house drops. RPLD DR.
REFUSED 75 kva--480v TRNS--W1. REF TR.
isolated srd vap on loop. found sh. refused LF REF TP
REF TR. TLA
RPLD BU TR
REF TR.
REF LF, REF TR
CUT TREES & VINES FROM POLE. REF TR.
REPLACED LIMITER ON TRANSFORMER. REF TR.
replaced drop fall c/o erosion replaced 60 feet # 4 solid. 4 cond with 1/0 alum 4 cond. RPLD DR.
RPLD LIMITER @ TR. REF TR.
RPLD CONN @ WH.
CUT TREES OUT OF PRI AT 1115 BINGHAM AND TOOK BLACK OUT OF # 8 COPPER PRI AT THE LF POLE BA6 25T SPLICED ON PR. RMVD TREE/AMB OFF PR.
REFUSED Y TERM POLE. REF TP
NOT SURE IF LIGHTNING TOOK OUT OR TREES. NEED SOME TREE TRIMMING BAD ABO UT 3 SPANS WEST OFF LF WHERE IT GOES THRU TREES. ALSO 4F PL NEEDS STRAIGHTENING THAT S
REFUSED TRANS @ 14603 MARY JANE. REF TR.
rpld bk trans 35 cap / 10 conn - lightning / stock 3668 - 10-8-03. RPLD BU TR.
REF TP
REF LF.
REF TR.
REPLACE M8 OPEN WIRE WITH M8 TWIST. RPRD BEC--1 CUST.
refused per tr. dwlf------dbg. REF TR.
PICKED UP PRIMARY AND REFUSED LINE FUSE ALL SERVICE BACK ON. PU PR-FUSE BLOWN.
REPLACED BAD 25 KVA 7200 120/240 OH POT W/SAME OPTI OPT. RPLD BU TR. REF TR.
REPLACED ELBOW IN X-FORMER #22 @ 22718 DEVILLE. TRANS HAS CRACKED BUSHING. RPLD ELBOW @ TR.
MADE REPAIRS TO X-PRIMARY IN TRANSFORMER AT 23048 BANQUO. REFUSED F41B T P. REF TP RPRD URD PR. NEED TO MAKE REPAIRS TO TP @ 23082 BAN

FORCED INTERR	CH	NM 02	47001	M69N	5859108	32003282012	F	10/9/2003	180	294	8	2352	O/H PRIMARY CL	OH PR CLMF	12907 LABELLE	2	LF	M69N	MADE TEMP REPAIRS TO URD PRIMARY NOT MARKED LIVE FRONT TRANS AT 12906 LABELLE, REF TP	NO SUBCASING--ABK	1	0
FORCED INTERR	SU	CE 10	11947	H85Y	4852001	32003282023	F	10/9/2003	181	128	43	5504	LIGHTNING	LIGHTNING	1122 RAVENSCI	2	LF	H85Y	REFUSED HWY LIGHTNING; REF TP		1	0
FORCED INTERR	SU	STF05	12301	H31X	4852644	32003282023	F	10/9/2003	181	140	49	6860	LIGHTNING	LIGHTNING	12042 STURDIV	2	LF	H31X	REFUSED TP; REF TP;		1	0
FORCED INTERR	GA	KM 07	31741	33QB	6347322	32003282012	F	10/9/2003	183	199	5	995	LIGHTNING	LIGHTNING	BAKER @ HOBE	1	LF	33QB	REFUSED WEST PHASE OF LINE FUSE 33QB 2 PHASE 25T, ALL SERVICE BACK HOT; REF LF		1	0
FORCED INTERR	SU	CE 10	11946	H83Y	4852011	32003282023	F	10/9/2003	181	140	21	2940	LIGHTNING	LIGHTNING	1215 ASHWOOD	2	LF	H83Y	REF TP;		1	0
FORCED INTERR	GA	AL 05	30513	71KA	6040709	32003282012	F	10/9/2003	181	73	115	8395	LIGHTNING	LIGHTNING	7819 HIGHLAND	1	LF	71KA	REF LF;		1	0
FORCED INTERR	SU	WW 0	12408	7C2	4954910	32003282023	F	10/9/2003	181	117	48	5616	UNKNOWN	UNKNOWN	9215 IMOGENE	1	LF	7C2	REFUSED NORTH PH. OF 7C2,NEEDS TO BE WALKED OUT IN DAY LIGHT CUST CMPL. FREQUENT OUTAGES.LOOK AT 8PAH REAL CLOSE ACROSS BAYOU. REF LF;		1	0
FORCED INTERR	SU	IM 48	12118		4751943	32003282023	F	10/9/2003	181	358	8	2864	VINES	VINES	619 LAKEVIEW	1	TF	475194372	REF TP, RPLD LIGHTNING ARRESTOR; TLA		1	0
FORCED INTERR	SU	CE 10	11945	H82Y	4752918	32003282023	F	10/9/2003	181	154	31	4774	RISING WATER	RISING H20	1207 BRAMBLEE	2	LF	H82Y	RE-FUSED T.P. ..HIGH WATER; REF TP		1	0
FORCED INTERR	SU	CE 02	11936	F97T	4752808	32003282024	C	10/9/2003	181	151	24	3624	LIGHTNING	LIGHTNING	1134 FAIRACRE	2	LF	F97T	REF TP		1	0
FORCED INTERR	GP	FR 42	2F138	S3175	5064505	32003282013	F	10/9/2003	182	116	22	2552	LIGHTNING	LIGHTNING	7638 CRISP WO	2	LF	S3175	TRIED 8TEP-POT REFUSED TP63175 LEFT WORKING; REF TP		1	0
FORCED INTERR	BA	BT 06	40145	G80E	6258204	32003282013	F	10/9/2003	182	118	17	2008	LIGHTNING	LIGHTNING	6900 ATCID LN	2	LF	G80E	REF TP		1	0
FORCED INTERR.	SU	CE 10	11945	H80Y	4752929	32003282044	F	10/9/2003	182	173	25	4325	TREE CLEARANC	TREE CLEA	13507 WIMBLEC	2	LF	H80Y	1427 ASHWOOD AT TP; REF TP;		1	0
FORCED INTERR	HC	AR 42	1583A	14NK	5247417	32003282024	F	10/9/2003	182	166	5	830	LIGHTNING	LIGHTNING	707 REDWOOD	1	LF	14NK	REF LF;		1	0
FORCED INTERR	GP	TWG4	20299	S66E	5369434	32003282014	T	10/9/2003	183	121	1	121	UNKNOWN	UNKNOWN	22618 ALDINE W	1	TF	536943424	REPLACED LIMITER ON TRANSFORMER, REF TR,	NO SUBCASING--ABK	1	0
FORCED INTERR	CH	UV 06	41628	N99K	5858353	32003282013	F	10/9/2003	183	111	22	2442	UNKNOWN	UNKNOWN	14615 LORNE DI	2	LF	N99K	REF TP,		1	0
FORCED INTERR	HC	TV 02	11131	P45C	5150232	32003282025	F	10/9/2003	184	122	34	4148	LIGHTNING	LIGHTNING	15810 GALLING	2	LF	P45C	REF TP,		1	0
FORCED INTERR	SU	IM 41	12043	81CJ	4849142	32003282025	F	10/9/2003	184	0	0	0	SPLICE	SPLICE	2446 PARKWOC	2	LF	81CJ	ISOLATED BAD URD TERMINATOR ON TP 81CJ. 1/0 AL. PRI IN PIPE. ISOL URD PR.		1	0
FORCED INTERR.	SU	IM 41				32003282025	F	10/9/2003	184	229	37	8473	SPLICE			2	LF	81CJ			0	0
FORCED INTERR.	SU	OV 01	11436	F88Z	4949935	32003282025	F	10/9/2003	184	142	15	2130	LIGHTNING	LIGHTNING	3018 CYPRESS	2	LF	F88Z	refused tp 8ft2 cause lightning; REF TP;		1	0
FORCED INTERR.	SU	HY 09	11697	H99K	4956445	32003282025	F	10/9/2003	184	86	19	1634	LIGHTNING	LIGHTNING	1627 W SAM HO	2	LF	H99K	REF TP;		1	0
FORCED INTERR.	SB	SR 01				32003282025	C	10/9/2003	184	0	0	0	LIGHTNING	POLE/FIRE	12410.BOHEME	CL	CL	SR01	PD	CREWS IN ROUTE TO A TBL CALL @ 12414 BOHEME.RECT 20745 TOP BURNED OUT OF 40'POLE 84N @ ANGLE BRACE,,18% CKT., CREW CALLED OUT TO MAKE REPS WPS BEE TBL BWO P	1	1
FORCED INTERR	SB	SR 01	1G377			32003282025	C	10/9/2003	184	46	506	23276	LIGHTNING			CL	CL	SR01			0	0
FORCED INTERR	SB	SR 01	21631			32003282025	C	10/9/2003	184	65	545	35425	LIGHTNING			CL	CL	SR01			0	0
FORCED INTERR	SB	SR 01	20745			32003282025	C	10/9/2003	184	343	77	26411	LIGHTNING			CL	CL	SR01			0	0
FORCED INTERR	GP	DH 06	20962	G77G	5162423	32003282043	F	10/9/2003	184	132	4	528	LIGHTNING	LIGHTNING	5611 BLACKJAC	2	LF	G77G	REFUSED TP G77G--85 T--Wt1, REF TP,		1	0
FORCED INTERR.	SH	PJ 04	30449	G84N	5848722	32003282046	F	10/9/2003	185	410	31	12710	UNKNOWN	UNKNOWN	16118 LEIGH CA	2	LF	G84N	DB	BAD DISCONN. ON TP G84N. SWITCHING ORDER #3094. REF TP;	1	0
FORCED INTERR.	MP	NS 02	41034	U4U	5459009	32003282014	T	10/9/2003	185	329	1	329	FLLNG TREE IN E	TREE FLAE	3818 HAIN ST	1	SC	545900936	SC	DR	Rpmvd Trsnx/Lmb from Secondary REPAIRED 2 STREETLITES.... RPRD CONN @ TR; RPRD BUSS WORK @ TR. RPRD DPL	1	0
FORCED INTERR	GA	KM 01	31506		6249304	32003282046	T	10/9/2003	190	214	2	428	LIGHTNING	LIGHTNING	1006 JUNIPER R	1	TF	624930486	REFUSED TRANSFORMER,HELD, ALL SERVICE BACK HOT AT THIS TIME ... NEED TO CLEAR VINES OFF OF POLE. AT SERVICE CENTER CONV., REF TR;		1	0
FORCED INTERR	SU	SIE42	11730	44KC	4948527	32003282025	F	10/9/2003	190	191	1	191	LIGHTNING	LIGHTNING	7007 FLAT BANI	3	LF	44KC	REF LF;		1	0
FORCED INTERR	SU	WW 0	12417	25X	4954855	32003282025	T	10/9/2003	191	802	10	8020	LIGHTNING	LIGHTNING	8814 ROOS RD	1	BU	495485523	SC	REMOVED 1 75KVA & 2 25 KVA TRANSFORMER, REPLACED WITH 1 75 & 25. REPLACED ALL TR. LEADS,REPAIRED DROPS. RPLD BAJ TR, RPLD BEC CONN @ PL-> 1 CUST ..CRH	1	0
FORCED INTERR	MP	AN 02	40010		5359615	32003282014	T	10/9/2003	191	82	2	164	LIGHTNING	LIGHTNING	1807 AIRLINE DI	1	TF	535981527	REF TR, RPLD BAJ BARREL ON TR.		1	0
FORCED INTERR	HM	LW 44	20141	87FR	5666123	32003282015	F	10/9/2003	192	0	0	0	URD BUSHING	URD BSHING	ADAMS BENNET	2	LF	87FR	BU 566612371	RPLD BJ TP46 @ 2610,CARDINAL LN URD #3082080 ... SUBCASING NECESSARY WPO	1	0
FORCED INTERR	HM	LW 44				32003282015	F	10/9/2003	192	180	29	5220	URD BUSHING			2	LF	87FR			0	0
FORCED INTERR	HM	LW 44				32003282015	F	10/9/2003	192	501	9	4509	URD BUSHING			2	LF	87FR			0	0
FORCED INTERR	SH	TE 03	31079	49BS		32003282015	F	10/9/2003	192	83	116	9628	TREE CLEARANC	TREE CLEA	10610 TELEPHO	1	LF	49BS	REFUSED LINE FUSE, REF LF		1	0
FORCED INTERR	CY	TB 46	21034	73PS	4870151	32003282015	F	10/9/2003	193	80	3	240	LIGHTNING	LIGHTNING	930.AGG RD.	1	LF	73PS	REF LF		1	0
FORCED INTERR	CH	SW 10	41860	J45S	5563425	32003282015	F	10/9/2003	193	136	12	1632	LIGHTNING	LIGHTNING	HIRSCH @ HER	3	LF	J45S	REF LF;		1	0
FORCED INTERR	BA	LP 02	41686	G76A	6252519	32003282015	T	10/9/2003	193	577	7	4039	INSULATOR	INSULATOR	3305 E COUNTR	1	BU	625251975	REF LF;	REPL 26 KVA 7200/120/240. RPLD BAJ TR	1	0
FORCED INTERR	HM	LW 44	20141	J82P	5666121	32003282016	F	10/9/2003	193	54	1	54	UNKNOWN	UNKNOWN	7600 RANKIN RC	1	LF	J82P	refused 3 phase of line fuse J82p. REF LF		1	0
FORCED INTERR	BA	NP 41	41463	82FQ	5964539	32003282016	F	10/9/2003	201	83	1	83	LIGHTNING	LIGHTNING	LAKE HOU DAM	1	LF	82FQ	REF LF		1	0
FORCED INTERR.	SU	WW 0	12408	G98X	4954917	32003282027	F	10/9/2003	201	156	7	1092	UNKNOWN	UNKNOWN	8979 IMOGENE	2	LF	G98X	PR	REF TP. RPRD URD PR.	1	0
FORCED INTERR	FB	DA 06	11327	S8M	4537021	32003282027	F	10/9/2003	201	211	12	2532	LIGHTNING	LIGHTNING	18515 DAMON C	1	PR	S8M	TF 453702112	LIFTED JUMPER PICKED UP PRI LOWERED PRI ON POLE HIT BY LIGHTNING REFUSED 16 KVA TRANS. PMJP PR-FUSE NOT BLOWN. REF TR.	1	0
FORCED INTERR	RS	LV 01	30080	55GK	5636842	32003282017	T	10/9/2003	201	96	1	96	LIGHTNING	LIGHTNING	11422 COUNTY	1	TF	563684239	REF TR;		1	0
FORCED INTERR	GP	FR 42	2F138	S3175	5064505	32003282016	F	10/9/2003	204	49	22	1078	LIGHTNING	LIGHTNING	9411 JOLLY WO	2	LF	S3175	REF TP		1	0
FORCED INTERR	KY	MAR41	22678		4556149	32003282027	T	10/9/2003	204	152	1	152	LIGHTNING	LIGHTNING	2340 WESTGRE	TF	TF	455614982	REPL. 10 8 LINGKING ARRESTOR ONE 12 K-MATE AND ONE 10 8 FUSE BARREL. RPLD LIMITER @ TR, RPLD LIGHTNING ARRESTOR		1	0
FORCED INTERR	BZ	BZ 06	30636	A97Z	5326242	32003282017	T	10/9/2003	204	179	10	1790	VINES	VINES	110 SAGE ST	1	TF	532824296	CLEARED UP VINES REFUSED TRANS REF TR.		1	0
FORCED INTERR	BZ	LJ 07	30921	C51J	5428053	32003282017	T	10/9/2003	205	178	1	178	LIGHTNING	LIGHTNING	500 W RILEY	1	TF	542805393	RPLD BAJ BARREL ON TR.		1	0
FORCED INTERR	BZ	RT 02				32003282018	C	10/9/2003	205	0	0	0	LIGHTNING	LIGHTNING	R102 CKT LOCI	CL	CL	RT02	NON 10%,IMC PTB 25183 FAULT A & NEUT.OPEN,CLOSED.R102 BRKR,ALL CREWS OUT OF BFT &C AREA.	NO CAUSE FOUND WPS	1	1
FORCED INTERR	BZ	RT 02	30873			32003282018	C	10/9/2003	205	2	220	440	LIGHTNING			CL	CL	RT02			0	0
FORCED INTERR	BZ	RT 02	30353			32003282018	C	10/9/2003	205	110	214	23540	LIGHTNING			CL	CL	RT02			0	0
FORCED INTERR.	FB	LC 01	11251	3MS	3633553	32003282029	F	10/9/2003	205	149	30	4470	TREE CLEARANC	TREE CLEA	10011 HALL	1	LF	3MS	NEED TO TRIM TREES FROM LF TO THE END OF LINE, REF LF		1	0
FORCED INTERR	SH	CC 03	10834	75DU	5451144	32003282029	F	10/9/2003	210	95	20	1900	SPLICE	SPLICE	12939 SCOTT S	2	LF	75DU	SPLICE PRIMARY ON TRANS AT 12918 SOUTHBRIDGE DR X PRI. REF TP		1	0
FORCED INTERR	BA	LP 03	41748	U82G	6253020	32003282018	F	10/9/2003	211	117	7	819	LIGHTNING	LIGHTNING	BAY AREA BLVD	1	LF	U82G	REFUSED LINE FUSE, REF LF		1	0
FORCED INTERR	GA	KM 05	41211	5NA	6351303	32003282018	T	10/9/2003	212	74	3	222	LIGHTNING	LIGHTNING	5115 LOUISE ST	1	TF	635130319	REF TR,		1	0
FORCED INTERR	GP	TWG4	22374	F39S	5469032	32003282017	F	10/9/2003	212	16	5	80	RISING WATER	RISING H20	23015 BANQUO	2	LF	F39S	PR	MADE REPAIRS TO TRANSFORMER AT 23015 BANQUO REFUSE T.P. F39S; REF TP; RPRD URD PR.	1	0
FORCED INTERR	BA	NP 44	41490	W69D	6163343	32003282019	F	10/9/2003	215	62	35	2170	TREE CLEARANC	TREE CLEA	304 KRENEK RC	2	LF	W68D	REF LF;		1	0
FORCED INTERR	CH	GW 01	40890	CU1	5662404	32003282019	T	10/9/2003	220	45	4	180	VINES	VINES	8718 COCKBUR	1	TF	566240471	REMOVED VINES FROM 50KVA TFMR AND POLE. REPLACED BURN UP FUSE BARREL ON TFMR, RPLD BAJ BARREL ON TR;		1	0
FORCED INTERR.	GP	WF 41	20894	67LW	5268230	32003282017	F	10/9/2003	222	59	1	59	LIGHTNING ARRE	LTNG ARRS	310 FM 1960 W	1	LF	67LW	CLEARED UP LIA ON TRANS / REFUSED A PHASE LF / LEFT BERV ON / PLEASE BEND MESSAGE TO GPT TO REPLACE LIA @ B/C CONV., REF LF,		1	0
FORCED INTERR	BA	LP 03				32003282019	C	10/9/2003	224	12	16	192	PRIMARY CONDU	PRIMARY	13TH. S OF FAIF	PC	PC	LP03	PR	SWICH#16 SECTION 41726 NON 10% PUC CKT CREW FOUND WEST PHASE OF PTB 5647 ON THE SOUTH SIDE OF THE SWITCH BURNED OFF AND IN THE CLEAR FIELD SWITCHED TO	1	0
FORCED INTERR	SH	HG 06	30264	5SM	5654725	32003282019	T	10/9/2003	225	50	5	250	BU DISC OR BARI	DISC/BARRL	8354 HOWARD	1	TF	565472557	REF TR,		1	0
FORCED INTERR	BA	NP 44	41490	W69D	6163343	32003282019	F	10/9/2003	230	0	0	0	UNKNOWN	UNKNOWN	304 KRENEK RC	2	LF	W68D	LF W69D BU 616E DB	REPLACED 75 KVA-18-8-120/240 URD XFMR WITH BAME--REPLACED HLB ELBOWS-- REPLACED DISCONNECT ON TP W76D--REFUSED 1 PHASE OF LF W68D--FOUND BLOWN AND WORKING T	1	0
FORCED INTERR	BA	NP 44				32003282019	F	10/9/2003	230	393	27	10611	UNKNOWN			2	LF	W68D			0	0
FORCED INTERR	BA	NP 44				32003282019	F	10/9/2003	230	490	7	3430	UNKNOWN			2	LF	W68D			0	0
FORCED INTERR	HM	TWG4	20290	F41S	5469041	32003282018	F	10/9/2003	234	176	6	1056	OTHER	HI-WATER	23062 BANQUO	2	LF	F41S	PR	SWITCH#2099 RPRD URD PR. "2ND TIME OUT TONITE-DUE HIGH WATER REPAIRED PRI IN TF @ 23046 BANQUO "THIE TF HOE RAISED 8-8" (APPRX 4" RAIN FLOODS-I	1	0
FORCED INTERR	KY	KT 43	22615	34HP	4258109	32003830001	F	########	000	109	4	436	LIGHTNING	LIGHTNING	KATY BROOKSI	1	LF	34HP	TF 42581090E	REF LF REF TR.	1	0
FORCED INTERR	SU	QV 07	12597	R27W	5050513	32003830002	F	########	000	0	0	0	O/H PRIMARY CL	OH PR CLMF	16338 QUAIL EC	2	LF	R27W	PR	BAD SPLICE IN TRANS #34 IN REAR OF 16302 QUAIL ECHO DR-PUT Y ON ST OFF - IN REAR OF 16322 IN TRANS #36 PUT X ON ST OFF- CLEAR Y PRI IN RW TRANS #3 3 AT 16310 QUAIL PK DR AND	1	0
FORCED INTERR	SU	QV 07				32003830002	F	########	000	231	7	1617	O/H PRIMARY CL			2	LF	R27W			0	0
FORCED INTERR	SU	QV 07				32003830002	F	########	000	231	14	3234	O/H PRIMARY CL			2	LF	R27W			0	0
FORCED INTERR	HC	PZ 42	13003	85AN	5354545	32003830003	F	########	000	94	181	17014	URD ELBOW	URD ELBOW	2121 HEPBURN	2	LF	85AN		MADE-REPAIRS-TO-Y-ELBOW-IN-POT-#8-2121-HEPBURN-BUILDING-12. REF TP	0	0
FORCED INTERR	GP	KI 46	2A134	S1759	4968741	32003830007	T	########	005	611	2	1222	UNKNOWN	UNKNOWN	17706 CARELLA	2	BU	496874106		replaced 25 kva pad mount trans. with same. RPLD BU TR.	1	0
FORCED INTERR	SU	QV 01	12179	R33W	4949903	32003830005	F	########	010	90	42	3780	LIGHTNING	LIGHTNING	3810 W VALLEY	2	LF	R33W		REF TP	1	0
FORCED INTERR	SU	AF 01	11752	F60C	4954300	32003830006	F	########	012	120	14	1680	LIGHTNING	LIGHTNING	8806 HEATHTOI	2	LF	F60C	DB	REPLACED 12 KV SWITCH ON TP F 60 C 50 T & RPLD BAJ DISC-LF BLOWN.	1	0
FORCED INTERR	SH	CA 06	30598	S27B	5953414	32003830004	F	########	012	79	66	5214	BU DISC OR BARI	DISC/BARRL	6014 HONEY LN	2	LF	S27B	DB	REFUSED TP. RPLD BAJ BARREL ON TP	1	0
FORCED INTERR	SU	RO 03	12205	P85W	4953158	32003830007	F	########	013	0	0	0	URD ELBOW	URD ELBOW	10905 GLENWO	2	LF	P85W	PR	BAD-X-PRIMARY-IN-POT-11-IN-CONDUIT-BEND-TICKET-TO-BUDARLAND-SERVICE-CEN- TER REF TP	1	0
FORCED INTERR	SU	RO 03				32003830007	F	########	013	334	9	3006	URD ELBOW			2	LF	P85W		MKC	1	0
FORCED INTERR	SU	RO 03				32003830007	F	########	013	334	15	5010	URD ELBOW			2	LF	P85W			0	0
FORCED INTERR	HC	TV 03	11143	56GR	5150717	32003830006	F	########	014	0	0	0	SPLICE	SPLICE	16311 PAITER	2	LF	56GR	PR	ISOLATED URD PRIMARY; ISOL URD PR. URD #3082103 ISOL. BAD PRI(DR BURY) STHAN TFMR & 47 PRI BAD UNDER TFM46 @ 5303,COURT RD "SUBCASING NECESSARY	0	0
FORCED INTERR	HC	TV 03				32003830006	F	########	014	211	8	1688	SPLICE			2	LF	56GR			0	0
FORCED INTERR	HC	TV 03				32003830006	F	########	014	266	4	1064	SPLICE			2	LF	56GR			0	0
FORCED INTERR	HC	IR 01	11059	U93F	5150750	32003830006	F	########	020	207	10	2070	LIGHTNING	LIGHTNING	5607 ANDERSOI	2	LF	U93F	PR	MADE REPAIRS TO PRI. IN XFMR #1. REF TP. RPRD URD PR.	0	0
FORCED INTERR.	CY	CYF44				22003830007	C	########	022	0	0	0	PRIMARY CONDU	PRIMARY	12611 ADAMS R	CL	CL	CYF44	PR	NON 10 % CKT IRE TBL BWO #171 PRI DWN 12611 ADAMS RUN	1	1
FORCED INTERR	CY	CYF44	2G071			22003830007	C	########	022	54	658	35532	PRIMARY CONDU			CL	CL	CYF44			0	0
FORCED INTERR	CY	CYF44	21971			22003830007	C	########	022	86	820	70520	PRIMARY CONDU			CL	CL	CYF44			0	0
FORCED INTERR	CY	CYF44	20815			22003830007	C	########	022	104	2688	279344	PRIMARY CONDU			CL	CL	CYF44			0	0
FORCED INTERR	CY	CYF44	21967			22003830007	C	########	022	244	440	107360	PRIMARY CONDU			CL	CL	CYF44			0	0
FORCED INTERR	GP	KDL43	2437A	S27C	4972315	32003830011	T	########	025	436	2	872	LIGHTNING	LIGHTNING	7918 HENNESS	1	PR	497231564		RPLD LIMITER @ TR.	1	0
FORCED INTERR	FB	WR 09	11252		3637349	32003830022	L	########	041	130	1	130	OH SEC/DR CL HI	OH SC CL-H	404 S FORD ST	SC	SC			RPLD BEC CONN @ PL-1 CUST.	1	0
FORCED INTERR	CY	TB 04	21007	75EW	4871326	32003830017	T	########	042	286	1	286	LIGHTNING	LIGHTNING	11420 MAHAFFE	1	TF	487132644		refused 15mva 7200. REF TR.	1	0
FORCED INTERR	GP	FR 41	22835	39RT	4962737	32003830018	F	########	044	88	72	6336	COLLISION	COLLISION	9422 FERN WOI	2	LF	39RT		REF TP	1	0
FORCED INTERR.	BL	GT 04	40853		5356328	32003830025	T	########	050	200	9	1800	CUST EQP RELA	CUST RLTD	1312 VASSAR S	TF	TF	535632851		cuts burned up 3 phase semi-und d'ape caused fuses on open delta bank to blow-refused and set 244-8 wip-opened up and out and out and out eg-lamp 123/122/244- pebble internal elect dmg to 7 fuses-out out 1308 vis	1	0
FORCED INTERR	GP	KL 48	22914		4767929	32003830023	T	########	052	90	4	360	STRONG WIND	WIND	12818 HIGHLANI	TF	TF	476792974		REF TR.	1	0
FORCED INTERR	SU	AF 08	11812	U76P	4954125	32003830027	F	########	053	129	36	4644	INSULATOR	INSULATOR	7914 WILCREST	2	LF	U76P	PR	REPLACED X ELBOW IN XFMR #2 AT 7816 WILCREST LEFT ON AND WORKING CUST NOTIFIED REF TP RPLD ELBOW @ TR	1	0
FORCED INTERR	KY	FL 44	22728	54AF3	4554348	32003830022	T	########	061	339	1	339	LIGHTNING	LIGHTNING	19707 FM 1093 F	1	BU	455434858		REPLACED BAD 250KV 18 8 277/480 WIRAME. WO SUTTON WAB HIT TIMM 10-10- RPLD BAJ TR.	1	0
FORCED INTERR	HM	TWG4	20290	F41S	5469041	32003830024	F	########	064	0	0	0	RISING WATER	RISING H20	23046 BANQUO	2	LF	F41S	PR	BU 5461	REPLACED 37 8 URD 7200 WITH 50 KVA URD DEAD FRONT MADE REPAIRS TO X PRIMARY AT THAT TRANS LOCATED AT 23046 BANQUO ALSO REPLACED TRANS FORMER PAD REF TP RPRD I	1	0
FORCED INTERR	HM	TWG4				22003830026	F	########	064	219	4	876	RISING WATER			2	LF	F41S			0	0
FORCED INTERR	HM	TWG4				22003830026	F	########	064	351	2	702	RISING WATER			2	LF	F41S			0	0
FORCED INTERR	BA	LP 06	41857	W30J	6354138	32003830013	F	########	065	224	1	224	COLLISION	COLLISION	2729 E MAIN #1	1	LF	W30J	PR	Rebarred burnt off jumper replaced chicken wire & insulators across street, refused W30J, left service vertical, RPLD B/O PR JUMPER-FUSE BLOWN.	1	0
FORCED INTERR	FB	OR 02	11301	T1K	4045430	32003830033	F	########	070	201	5	1005	LIGHTNING	LIGHTNING	HWY 59, W OF I	1	LF	T1K	PR	PRI PR-FUSE BLOWN, REF LF,	1	0
FORCED INTERR	GA	GL 06	30491		6839806	32003830016	T	########	071	185	8	1480	LIGHTNING	LIGHTNING	701 BROADWA	TF	TF	683980625		chg out burned up fuse bernre on single 8 cause weather RPLD BAJ BARREL ON TR.	1	0
FORCED INTERR	FB	OB 42	12826	83JR	4551358	32003830036	L	########	074	172	1	172	URD DROPS (CUS	URD DR-C/O	1510 PECAN CR	2	DR			MADE REPAIRS TO CUST. UG DROPS IN PEDESTAL RPRD HLJP OWNED URD DR	1	0
FORCED INTERR	HC	MV 01	14221	43LJ	5446841	32003830044	F	########	081	79	1	79	LIGHTNING	LIGHTNING	FM 1128 AT CO	1	LF	43LJ		REF LF	1	0
FORCED INTERR	GP	KDL42	22463	L13X	5071912	32003830034	T	########	081	83	2	166	LIGHTNING	LIGHTNING	22131 SPRING C	1	TF	507191264		REF TR,	1	0
FORCED INTERR	BA	MB 03	41425	P32G	8559151	32003830024	F	########	084	84	24	2016	FLLNG TREE OUT	TREE FLAOE	10028 SWEET G	1	LF	P32G		REF LF,	1	0
FORCED INTERR	BL	HT 03	10286	43ACV	5055940	32003830005	T	########	085	47	1	47	LIGHTNING	LIGHTNING	6536 1/2 SOUTH	1	TF	505584011		RPLD BAJ BARREL ON TR.	1	0
FORCED INTERR	SH	WE81	30308	P39S	6048051	32003830026	L	########	085	73	1	73	METER EQUIPME	MTR EQUIP	16848 HIGHWA	1	MT			RPLD MTR.	1	0
FORCED INTERR	FB	NEWD	11244	8GH	4036407	32003830005	T	########	085	157	3	471	LIGHTNING	LIGHTNING	103 HUMBLE	1	TF	403640752		REF TR,	1	0
FORCED INTERR	BA	HNY02	40308	C63U	6359008	32003830026	T	########	090	80	3	240	VINES	VINES	2211 CONNALLY	1	TF	635900872		REMOVE VINES OFF POLE & TR. & REFUSED. REF TR	1	0
FORCED INTERR	MP	HE 01	41142	PE4	5359119	32003830037	T	########	091	71	1	71	VINES	VINES	1532 RUTLAND	1	TF	535911943		VINES ON TRANS FIRING UP CAUSING BLINKING VOLTAGE. TRIMMED VINES OF TRA BANK & REFUSED TRANS. REF TR.	1	0
FORCED INTERR	CY	PI 42	2454A	T93Z	4077406	32003830036	L	########	091	72	1	72	FLLNG TREE OUT	TREE FLAOE	4849 FM 1488 #1	1	DR				1	0
FORCED INTERR	KY	KT 43	11577	40SJ	3759824	32003830057	F	########	092	178	11	1958	UNKNOWN	UNKNOWN	1835 CLEMONS	1	LF	40SJ		Retaged drops on open delta bank due to tree across them. PIU DR.	1	0
FORCED INTERR	BA	KM 02	41189		6249326	32003830032	T	########	092	42	1	42	OH SEC/DR CL HI	OH SC CL-H	2425 E NASA RC	SC	SC	624932627		NOTIFIED BY PHONE BACK ON LINE FUSE HAS GONE OUT 4 TIMES IN PAST 2 MO AFTER RAINS WE WILL TURN OVER TO B/C AND LOOK AT FURTHER REF LF	1	0

FORCED INTERR	SB	EC 13	21715	P1C	5057327	12003283006	E T	########	100	80	7	560	BIRD	BIRD	21 S CHESKA LI	1	TF	505732754											
FORCED INTERR	MP	GG 10	40995	E1Z	5555637	12003283004	L	########	100	168	1	168	OH SEC/DR CL NI	OH SC CL-N	8635 MYRTLE S	1	DR												
FORCED INTERR	SH	DR 07	30293	J6K	5554929	12003283004	E T	########	101	68	13	884	VINES	VINES	7615 EL RANCH	1	TF	555482953											
FORCED INTERR	SH	CG 03	30215	H52P	5653957	12003283004	E F	########	101	86	7	602	LIGHTNING	LIGHTNING	203 CANNIFF RI	1	LF	H52P	TF	56539573C									
FORCED INTERR	BL	BI 06	10078		5155924	12003283007	E T	########	102	58	6	348	TREE CLEARANC	TREE CLEAR	4541 PARK CT		TF	515582472												
FORCED INTERR	SH	CC 03	10834		5451254	12003283007	T	########	102	67	5	335	SQUIRREL	SQUIRREL	12615 SEGREST		TF	545125406												
FORCED INTERR	SB	GE 47	21179	168C	4660517	12003283007	E F	########	103	71	1	71	UNKNOWN	UNKNOWN	CLAY, E OF GEF	1	LF	168C	LF	68GE									
FORCED INTERR	FB	OB 42	11370	50DB	4552202	12003283007	E F	########	104	0	0	0	TERMINATOR	TERMINATO	1903 RICHMONI	2	LF	50DB	PR										
FORCED INTERR	FB	OB 42				12003283007	E F	########	104	95	70	6650	TERMINATOR			2	LF	50DB											
FORCED INTERR	CY	KL 45	21978	S264B	4765719	12003283005	T	########	104	44	3	132	SQUIRREL	SQUIRREL	13103 VERNON	1	TF	476571909											
FORCED INTERR	BA	CD 05	40370	X53F	6357553	12003283005	T	########	104	107	8	856	SQUIRREL	SQUIRREL	701 RIVERBENI	1	TF	635755311											
FORCED INTERR	SB	GE 47	12261		4680350	12003283008	T	########	105	266	1	266	UNKNOWN	UNKNOWN	5055 BARKER C		BU	468035022											
FORCED INTERR	SU	SIE41	10946	W79W	4947951	12003283008	T	########	111	48	1	48	BIRD	BIRD	8202 OYSTER C	1	TF	494795108											
FORCED INTERR	FB	NEWO	10931	22KK	4036817	12003283008	L	########	113	39	1	39	LIGHTNING	LIGHTNING	11836 NEWGUL	1	MT												
FORCED INTERR	MP	NS 03	41550	C11N	5458108	12003283005	T	########	114	167	3	501	LIGHTNING	LIGHTNING	21 DALY PL	1	SC	545810806											
FORCED INTERR	GP	AD 05	40077		5363434	12003283005	E	########	114	111	1	111	BU DISC OR BARI	DISC/BARRL	880 ALDINE MAI		DB	536343415											
FORCED INTERR	MP	GG 03	40965	P9U	5654158	12003283005	E F	########	114	149	81	12069	UNKNOWN	UNKNOWN	3308 BERKLEY	1	LF	P9U	PR										
FORCED INTERR	GP	AD 05	2C112	C96N	5364115	12003283006	E F	########	115	81	18	1458	SQUIRREL	SQUIRREL	14807 MC LEOD	1	LF	C96N	TF	53641157C									
FORCED INTERR	CH	BE 04	40235		5561524	12003283006	T	########	115	50	2	100	BU DISC OR BARI	DISC/BARRL	9318 HOMESTE/		TF	556152430											
FORCED INTERR	SU	QV 04	12169	F73Z	4949650	12003283008	E F	########	123	0	0	0	UNKNOWN	UNKNOWN	3331 ASHMONT	2	LF	F73Z	PR										
FORCED INTERR	SU	QV 04				12003283009	E F	########	123	166	8	1328	UNKNOWN			2	LF	F73Z											
FORCED INTERR	SU	QV 04				12003283009	E F	########	123	166	7	1162	UNKNOWN			2	LF	F73Z											
FORCED INTERR	BL	BI 09	10089	3GL	5255254	12003283010	I F	########	124	39	4	156	BU DISC OR BARI	DISC/BARRL	WESLAYAN @ S	1	LF	3GL											
FORCED INTERR	SU	WZ 44	12360	P38T	4956811	12003283010	F	########	125	120	207	24840	FLLNG TREE IN E	TREE FL/AE	9797 MEADOWC	2	LF	P38T											
FORCED INTERR	MP	GS 22	40771		5457723	12003283006	T	########	125	40	4	160	LIGHTNING	LIGHTNING	3302 CANAL ST		TF	545772321											
FORCED INTERR	CH	SW 07	42015	E23T	5562215	12003283006	T	########	130	59	4	236	OH PRIMARY CL	OH PR CLM	5211 YORKWOC	1	TF	556221559											
FORCED INTERR	MP	CL 05	40400	N19A	5657148	12003283006	E L	########	130	72	1	72	OH SEC/DR CL HI	OH SC CL-H	1626 DEMAREE	1	DR												SC
FORCED INTERR	BL	SF 03	10419	B50	5256454	12003283011	C T	########	131	118	5	590	LIGHTNING	LIGHTNING	3615 MEADOW	1	TF	525645497											
FORCED INTERR	MP	BU 03	40314		5658219	12003283007	1 T	########	132	70	2	140	LIGHTNING	LIGHTNING	8543 MARKET S		TF	565821941											
FORCED INTERR	GA	GA 09	31226	M6W	6838003	12003283007	L	########	132	81	1	81	OH SEC/DR CL NI	OH SC CL-N	4211 AVENUE S	1	SC												
FORCED INTERR	SH	SH 09	30930	20GD	5752617	12003283007	4 T	########	132	34	1	34	BIRD	BIRD	9012 N BROADV	1	TF	575261798											
FORCED INTERR	BL	SF 05				12003283011	C	########	133	0	0	0	OTHER	OTHER	SF05 CKT LOCI		CL	SF05											
FORCED INTERR	BL	SF 05	1G150			12003283011	C	########	133	28	468	12116	OTHER				CL	SF05											
FORCED INTERR	BL	SF 02				12003283011	C	########	133	0	0	0	TERMINATOR	TERMINATO	1600 RIVER OAI		CL	SF02											
FORCED INTERR	BL	SF 02	1G148			12003283011	C	########	133	42	421	17682	TERMINATOR				CL	SF02											
FORCED INTERR	BL	SF 02	10415			12003283011	C	########	133	62	165	10230	TERMINATOR				CL	SF02											
FORCED INTERR	BL	SF 02	10412			12003283011	C	########	133	61	17	1037	TERMINATOR				CL	SF02											
FORCED INTERR	BL	SF 02	10413			12003283011	C	########	133	94	7	658	TERMINATOR				CL	SF02											
FORCED INTERR	BL	FD 09				12003283012	C	########	135	0	0	0	TREE CLEARANC	TREES CES	TREES IN PRI	2	CL	FD09											
FORCED INTERR	BL	FD 09	1G529			12003283012	C	########	135	30	590	17700	TREE CLEARANC				CL	FD09											
FORCED INTERR	BL	FD 09	10702			12003283012	C	########	135	70	1953	136710	TREE CLEARANC				CL	FD09											
FORCED INTERR	MP	WO 04	41843		5280509	12003283007	T	########	135	62	3	186	LIGHTNING	LIGHTNING	3612 GOLF DR		TF	528050985											
FORCED INTERR	SH	WE 08	31319	H43J	5855425	12003283007	F	########	140	148	1	148	O/H PRIMARY CL	OH PR CLM	418 BEARLE ST	1	PR	H43J											
FORCED INTERR	BA	LP 06	41857	7KD	6354223	12003283007	E T	########	140	135	3	405	VINES	VINES	410 S OAK ST	1	TF	635422365											
FORCED INTERR	SH	DE 04	30236	418E	5955702	12003283007	E F	########	140	84	47	3948	OH PRIMARY CL	OH PR CLM	1309 WHITEBRI	2	LF	418E	DB										
FORCED INTERR	CY	PI 45	22973		4573627	12003283008	1 T	########	141	48	2	96	LIGHTNING	LIGHTNING	33816 DEER CR		TF	457362797											
FORCED INTERR	BL	HE 03	10670	40ACO	5257646	12003283015	1 T	########	145	162	2	324	LIGHTNING	LIGHTNING	218 TERRACE C	1	BU	525764652											
FORCED INTERR	SH	PO 01	30864	95EE	6050536	12003283009	E F	########	145	36	3	108	SQUIRREL	SQUIRREL	16514 BROOK F	1	LF	95EE											
FORCED INTERR	BA	FT 06	40663	S87G	6053935	12003283009	4 F	########	145	62	14	868	UNKNOWN	UNKNOWN	9726 OAKMONT	2	LF	S87G											
FORCED INTERR	CY	KL 45	21950	24FL	4785358	12003283008	E F	########	150	60	14	840	FALLING DEAD TI	TR FL/DEAD	13215 HUFFMEI	1	LF	24FL											
FORCED INTERR.	SU	BAR 46	11903	S23U	4655901	12003283015	E F	########	150	235	78	18330	URD ELBOW	URD ELBOW	6718 LOS TIOS	2	LF	S23U											
FORCED INTERR	CH	SW 09	41699	M57R	5562139	12003283009	L	########	151	112	1	112	COLLISION	COLLISION	5014 ASKINS LN	1	DR		DR										
FORCED INTERR	MP	UN 11	10975	81AEX	5455521	12003283008	T	########	152	46	4	184	VINES	VINES	4202 ROSENEA'	1	TF	545552168											
FORCED INTERR	GA	GL 07	30499		6836016	12003283009	L	########	153	86	1	86	OH SEC/DR CL HI	OH SC CL-H	1914 40TH ST		DR												
FORCED INTERR	CH	UV 07	41794	N91K	5959334	12003283010	L	########	153	111	1	111	OH SEC/DR CL NI	OH SC CL-N	1347 STEVENAC	2	SC												
FORCED INTERR	FB	CRB45	14885	59AEV	4647011	12003283016	1 F	########	154	119	2	238	SQUIRREL	SQUIRREL	6207 WATERW/	1	LF	59AEV											
FORCED INTERR	FB	WR 10	1118C	G63I	3742131	12003283016	T	########	154	176	1	176	LIGHTNING	LIGHTNING	1802 HIGHWAY	1	BU	374213122							DB				
FORCED INTERR	KY	KT 04	22579		3958809	12003283016	T	########	155	61	1	61	UNKNOWN	UNKNOWN	3802 N DEPOT		TF	395880968											
FORCED INTERR	CY	PI 45	22015	K44N	4674029	12003283009	7 F	########	164	109	24	2616	VINES	VINES	35111 BRANCH	1	LF	K44N											
FORCED INTERR	SB	TO 10	21767	I77S	5059937	12003283017	2 T	########	164	423	9	3807	UNKNOWN	UNKNOWN	8049 HAMMERL'	1	BU	505993776											
FORCED INTERR	CH	BY 04	40177	J5E	5461632	12003283011	C F	########	172	24	2	48	UNKNOWN	UNKNOWN	9743 JENSEN	1	LF	J5E											
FORCED INTERR	BA	BT 06	40144	M3N	6258108	12003283011	2 T	########	173	36	9	324	SQUIRREL	SQUIRREL	205 E SCHRECK	1	TF	625810803											
FORCED INTERR	GP	THW4	21056	85PR	4963231	12003283011	C F	########	175	0	0	0	TRANSFORMER	TRANSFRMR	9219 STONE PO	2	LF	85PR	BU	496323132									
FORCED INTERR	GP	THW4				12003283011	C F	########	175	218	4	864	TRANSFORMER			2	LF	85PR											
FORCED INTERR	GP	THW4				12003283011	C F	########	175	216	24	5184	TRANSFORMER			2	LF	85PR											
FORCED INTERR	GP	THW4				12003283011	C F	########	175	572	6	3432	TRANSFORMER			2	LF	85PR											
FORCED INTERR	FB	WR 10	1118B	G24I	3541804	12003283018	T	########	180	90	2	180	FLLNG TREE IN E	TREE FL/AE	3230 COUNTY R	1	TF	354180403											
FORCED INTERR	BA	HL 03	41166	R56X	6159602	12003283012	F	########	183	30	7	210	UNKNOWN	UNKNOWN	1821 CENTER S	1	LF	R56X											
FORCED INTERR	GP	LK 10	22122	FWI	5261048	12003283013	T	########	184	362	3	1086	UNKNOWN	UNKNOWN	8514 EZZARD CI	1	BU	526104822											
FORCED INTERR	BA	HL 06	41187	2HG	6160021	12003283023	F	########	185	55	16	880	FOREIGN MATER	FRGN MATR	1327 CLEAR LA	1	LF	2HG											
FORCED INTERR	BA	NP 44	41496	W95D	6164314	12003283012	7 T	########	200	67	2	134	BU DISC OR BARI	DISC/BARRL	5305 GUM ST	1	TF	616431461											
FORCED INTERR	FB	BC 08	13149	98DB	4346631	12003283019	4 F	########	201	54	5	270	BU DISC OR BARI	DISC/BARRL	1901 J MEYER R	1	LF	98DB											
FORCED INTERR	FB	WR 13	11284		3637644	12003283019	E T	########	201	51	4	204	BU DISC OR BARI	DISC/BARRL	208 E BURLESO		TF	363764408											
FORCED INTERR	SH	WE 02	31249		5854151	12003283013	C T	########	211	164	1	164	UNKNOWN	UNKNOWN	1202 PASADENI		BU	585415156											
FORCED INTERR	BA	PO 02	41386	84DS	6149554	12003283013	F	########	221	662	24	15888	FLLNG TREE OUT	TREE FL/OE	418 FOREST LA	1	LF	84DS	PR										
FORCED INTERR	BZ	VL 04	3526D	54GJ	5825034	12003283013	7 T	########	223	48	2	96	OH SEC/DR CL HI	OH SC CL-H	4806 BLUEWATI	1	SC	582503452											
FORCED INTERR	SH	SP 06	30684	N40F	5852648	12003284001	F	########	001	207	3	621	BU DISC OR BARI	DISC/BARRL	4725 BURKE	1	LF	N40F	DB										
FORCED INTERR	SH	SH 04	30909		5751452	12003284002	T	########	012	184	3	552	UNKNOWN	UNKNOWN	10147 TORRING		TF	575145212											
FORCED INTERR	BL	JN 11	10038	72DU	5055058	12003284006	F	########	060	120	46	5520	UNKNOWN	UNKNOWN	9443 PAGEWOC	2	LF	72DU											
FORCED INTERR	SU	CE 09	11960	M44G	4853323	12003284011	F	########	073	87	29	2523	SQUIRREL	SQUIRREL	12515 HUNTING	2	LF	M44G											
FORCED INTERR.	HC	BR 10	12796	82FP	5153834	12003284013	T	########	074	120	9	1080	OH SEC/DR CL HI	OH SC CL-H	4840 TONAWAN	1	SC	515383443	DR										
FORCED INTERR.	GP	LU 44	2446C	V56R	5066639	12003284000	E T	########	081	133	9	1197	OH SEC/DR CL HI	OH SC CL-H	17627 OAKSHAI	1	TF	506863924	SC										
FORCED INTERR	RS	RZ 01	3573A	W534		12003284006	E F	########	091	64	69	4416	SQUIRREL	SQUIRREL	14140 COUNTY	1	LF	I31T											
FORCED INTERR	SB	WO 06	41864		5259240	12003284011	T	########	092	41	1	41	SQUIRREL	SQUIRREL	2200 N LOOP W		TF	525924054											
FORCED INTERR	CY	KL 41	2474D	P35L	4686357	12003284014	T	########	095	66	2	132	SQUIRREL	SQUIRREL	14410 MELBA R	1	TF	466635760											
FORCED INTERR	SU	HY 09	11697	F33W	4956551	12003284002	F	########	095	98	18	1764	SQUIRREL	SQUIRREL	10218 BRIAR FC	2	LF	F33W											
FORCED INTERR	SU	HY 09	11697	K12J	4956457	12003284021	F	########	095	98	23	2254	SQUIRREL	SQUIRREL	10326 BRIAR FC	2	LF	K12J											
FORCED INTERR	SU	BAR 46	11908		4655509	12003284022	T	########	090	91	6	546	PRIMARY CONDU	PRIMARY	8418 SAN PABL		TF	465550972	PR										
FORCED INTERR	BA	FT 07	40855	E21H	6053640	12003284010	T	########	090	58	2	116	SQUIRREL	SQUIRREL	3313 ANDRICKS	1	TF	605364032											
FORCED INTERR.	FB	NV 03	11236	18AAZ	4441826	12003284002	T	########	090	225	1	225	HUMAN ERROR	HUMN ERRC	10226 DANNHAI	1	SC	444182649											
FORCED INTERR.	FB	RE 03				12003284002	C	########	090	0	0	0	WORK TAG	WORK TAG	RE03 CKT LOCI		CL	RE03											
FORCED INTERR	FB	RE 03	1G445			12003284002	C	########	090	4	453	1812	WORK TAG				CL	RE03											
FORCED INTERR	FB	RE 05	1G445			12003284002	C	########	090	4	1188	4752	WORK TAG				CL	RE03											
FORCED INTERR	FB	RE 03	13274			12003284002	C	########	090	4	0	0	WORK TAG				CL	RE03											
FORCED INTERR	SH	CA 06	31484	54HW	5953804	12003284001	T	########	090	142	6	1136	URD SEC PDSTL	URD SC PEI	7031 LITTLE WN	2	SC	595380418											
FORCED INTERR	HM	AT 42	2314E	35NN	5971911	12003284015	T	########	092	43	4	172	BIRD	BIRD	1214 VISTA DEL	1	TF	597191181											
FORCED INTERR	SH	PA 03	30761	96FF	5754252	12003284014	L	########	094	59	1	59	OH SEC/DR CL HI	OH SC CL-H	906 MAYO	1	DR												
FORCED INTERR	GA	GL 09	30515	J16L	6836607	12003284016	L	########	095	78	1	78	OH SEC/DR CL HI	OH SC CL-H	1301 WINNIE ST	1	SC												
FORCED INTERR	BL	FD 07	10694	C42U	5053547	12003284041	F	########	100	28	4	112	SQUIRREL	SQUIRREL	7702 BRAESVIE'	1	LF	C42U											
FORCED INTERR	MP	WO 02	41828	T54W	5259656	12003284002	T	########	100	43	3	129	BU DISC OR BARI	DISC/BARRL	1208 W 34TH	1	TF	525965979											
FORCED INTERR	BL	SF 08	10432	C94X	5157816	12003284042	F	########	100	82	3	246	BU DISC OR BARI	DISC/BARRL	HOLLYHURST @ 3		LF	C94X											
FORCED INTERR	FB	RE 09	11429	T56P	4347851	12003284047	F	########	102	45	36	1610	SQUIRREL	SQUIRREL	2801 AIRPORT E	2	LF	T56P											
FORCED INTERR	GP	LK 06	21879		5163531	12003284003	T	########	104	80	6	480	COLLISION	COLLISION	11804 PROCTOI		TF	516353158											
FORCED INTERR	MP	NS 01	41537	ER4	5459446	12003284003	L	########	105	90	1	90	FLLNG TREE OUT	TREE FL/OE	2401 MILWAUKE	1	SC												
FORCED INTERR	BL	GN 10	11588	61EG	5255620	12003284004	E F	########	110	74	18	1332	TREE CLEARANC	TREE CLEAR	8545 RUTGERS	1	LF	61EG											
FORCED INTERR	GA	GL 05	30460	2T4	6838131	12003284024	L	########	110	89	1	89	OH SEC/DR CL HI	OH SC CL-H	2401 30TH ST	1	DR		SC										
FORCED INTERR	SB	WD 43	21557	52650	4758517	12003284005	I F	########	111	0	0	0	URD XFMR SEC E	URD TR BUS	323 E FAIR HAR	2	LF	52650	BU	47585184C									
FORCED INTERR	SB	WD 43				12003284005	I F	########	111	221	14	3094	URD XFMR SEC E			2	LF	52650											
FORCED INTERR	SB	WD 43				12003284005	I F	########	111	415	3	1245	URD XFMR SEC E			2	LF	52650											
FORCED INTERR	GP	KL 42	21935		4866153	12003284003	E L	########	111	86	1	86	OH SEC/DR CL HI	OH SC CL-H	14707 SPRING L		SC												
FORCED INTERR	SH	DR 02	30267	16CW	5653553	12003284022	F	########	120	136	11	1496	SQUIRREL	SQUIRREL	STONE, N OF W	1	LF	16CW											
FORCED INTERR.	RS	LV 02	30077	FU2		12003284003	C F	########	121	40	3	120	BIRD	BIRD	2031 COUNTY R	1	LF	580K											
FORCED INTERR	BA	CD 10	40413	5CA	6357704	12003284003	T	########	122	210	10	2100	OH SEC/DR CL HI	OH SC CL-H	615 N COMMER	1	BU	635770497											
FORCED INTERR	CH	PW 04	41638		5761902	12003284003	T	########	124	24	8	192	UNKNOWN	UNKNOWN	12802 GREEN R		TF	576190278											
FORCED INTERR	CH	UV 04	41770	B93Z	5859513	12003284003	T	########	125	54	5	270	SQUIRREL	SQUIRREL	380 STONEHEN	1	TF	585951394											
FORCED INTERR	GA	STWD 31643		Y89F	6637436	12003284003	E L	########	125	105	1	105	COLLISION	COLLISION	9720 AIRWAYS I	1	DR												

REF TR;
BROKEN NEUTRAL AT POLE & REPAIRED BOTH OTHER WIRES AT POLE ALSO. RPRD DR;
REF TR;
REFUSED LF AND TRANS AT 203 CANNIFF. REF LF. REF TR;
REF TR;
REFUSED 37 & LIGHTER--A1--NEED TO INSTALL WLP &CIC ALSO RPLC BLOWN LA-- TRNS LOCD REAR 12811 SEGREST. REF TR;
FOUND 8 PH BLOWN ON LH F8 AND 8 AND C PH'S BLOWN ON 3PH TP - NO PHYSICAL EVIDENCE FOUND BUT SPECULATE MAY HAVE BEEN BIRD. REF LF, REF TP
FOUND TP 80 DB X... FOUND BAD PRI. AT TRANSIATOR ON ON TP 30DB X FEED OPEN & FEED IN TR # 34 AT 1118 BRAZOS SPRING...CLOSE TP 51DB Y FEED REPAIR AT B/C CONN ... REF TP

REFUSED TRANS. @ 13103 VERNON, REF TR;
replaced blown lighting arrester and put wildlife protection on. REF TR;
REPLACED 75 KVA 19.9 277/480 TP RPLD B/U TR;
INSTALLED WLP ON LIGHTING ARRESTOR. REF TR;
REPL METER AND JAWS. RPLD MTR;
PICKED UP # 4 ACSR NEU. CROSSING TRAIN TRACK. ALSO REMOVED METER # BANG 1753483 READING 44450 X 001 KVA IND. 13 @ ADDRESS 23 DALY LIGHT, PJU PR NEUT
RPLD B/U DISC-TP NOT BLOWN.
PICK UP # 2 PRIMARY PJU PR-FUSE BLOWN;
REF LF, REF TR;
RPLD B/U BARREL ON TR. REF TR;
BAD PRI BETWEEN AND 3227 AND 3303 ABHMONT DIRECT BURIED #2 CU PRI, #8OL URD PR;

REPLACED BURNED FUSE BARREL ON B PHASE DISC OF LF 3GL 40T RPLD B/U BARREL ON LF;
REF TP
REFUSED POWER POT LIKELY OFF SINCE YESTERDAY. CUST BAD SERVICE ALL CAME BACK ON. REF TR;
FUSE PULLED ONTO ON 50 CONV. REF TR;
REPLACED IN RUBBER COATED DROPS / LEFT SERV ON / NOTIFIED. RPLD DR, RPLD CONN @ WH, RPLD CONN @ PL
PEVIOUS WEATHER. REF TR;
FOUND POWER POT BLOWN. REFUSED AND CLOSED IN. ALL BACK ON... RPLD B/U BARREL ON TR;
RPLD CONN @ PL;
REF TR;
BF06 ON B BRKR BEHIND BF02. WHEN BF02 LOCKED OUT WE LOST BF-06 PICKED UP IN THE FIELD ONTO BF-15 T&L BCN117 OOM
TP 1662 HAD MIDDLE PHASE POT HEAD MELTED OPEN & TAGGED OUT OF INC ON T&L BCN117 NOW 1076 T&L #SECTION#104 13 & 10713 OOM

NON 1076. CREWS IN ROUTE,TP BURNING @ 8116 FONDREN. CREW CLEARED UP TR 2E8 @ 8132 FONDREN. NO FOLLOW UP NEEDED.SECTION 10704.....BRT

REFUSE 25 BK BK WITH 50 OUT BY PREV WEATHER. REF TR;
RPLD B/U BARREL ON LF RPLD B/O PR JUMPER-FUSE NOT BLOWN
REF TR;
MADE REPAIRS TO DISCONNECT LOW SIDE ALL BACK HOT RPLD TERMINATOR
REFUSED 25KVA 16 B OH TRANS REF TR;
REPLACED BAD 10 KVA 7200 120/240 TRANSFORMER. RPLD B/U TR LATER;
REFUSED LF ACQUIRRELL REF LF
REPL FUSE BARREL & REFUSED TP REF TP;
REFUSED LF 24FL 85T @ HUFFMEISTER N. OF WHISPERING VALLEY REF LF
REPLACED X ELBOW IN ESME 18 ON BW ORDER 2114. REF TP;
PIU DR. RPLD CONN @ WH. REBAGGED DR. RMVD TREE/LIMBS FROM DR TLA
BLOWN POWER POT DUE TO VINES REFUSED ALL BACK ON. REF TR;
RPLD CONN @ WH;
MADE REPAIRS TO NEUTRAL IN PED. ALSO FOLLOW UP HI-LEG IN PED T-HEAD NEEDS TO BE REPLACED SOON CORRODED AND EXPOSED PED IN REAR OF 1351 STEVENADE. RPLD SEC CC
REF LF - SQUIRREL ON IN LINE POLE / STACK 3150 10/10/03. REF LF
REPLACED BURNED UP 50 CBP TRANS WITH 150KVA CONV IN OPEN DELTA BANK INSTALLED TWO 12KV DISC ON BOTH TRANSFORMERS CAUSE PREVIOUS LIGHTENING RPLD B/U TR, R
refused o h. trans cause unknown; REF TR;
REF LF;
RPLD B/U TR
REF LF
NEED# WL PROTECTION. REF TR;
RPLD B/U TR. 50KVA W/BAME URD B/O#2114

REFUSED 25 KVA TRANS - TREES IN OPEN WIRE SECONDARIES @ 3 BPANS. REF TR;
REF LF
RPLD B/U TR;
REF LF
REFUSED TRANS. REF TR;
RPLD B/U BARREL ON LF REF LF; TLA
REPLACED BAD FUSE BARRELL ON 25KVA TRANS - STACK 3150 10-10-03 RPLD B/U BARREL ON TR TLA
AGE. RPLD B/U TR
REPLACED (2) 8' WOODEN X-ARMS WITH 4' WOODEN X-ARMS--MADE REPAIRS @ 2 ADDITIONAL X-ARMS-PICKED UP 3 BPANS OF 800 PRI --REPAIRED 2 SERVICE DROPS & REMAGGED--CAUSE
RPLD CONN @ TR
RPLD B/U DISC-TP BLOWN
REFUSED A 25 KVA. REF TR;
REF TP
CUST BAD SQUIRREL TOOK IT OUT DIDN'T FIND SQUIRREL BUT SHOOT IT ALL BACK ON. REF TP
REPLACED BAD CLAMP AT TRANS AND AT WHEAD. RPLD CONN @ TR. RPLD CONN @ WH.
EPAIRED PARREL 40 BUSINWORK AND REPLACED SECONDARY TO DROPS CONN @ PL (ROR)
REF LF;
REFUSED MIDDLE PHASE OF TR FUSE. CUST BAD ALL SERVICE CAME BACK ON. REF TR;
REPLACE LIMITER ON 37 S/19 B TRANSFORMER... LEAKING AROUND SECONDARY BUSHINGS... HAND JOB @ THIS TIME OR BOARDS. RPLD LIMITER @ TR. REF TR ***BENT TO FPC TWT
SQUIRREL TOOK OUT TP REFUSED BACK ON. REF TP
SQUIRREL TAKEN OUT TP TREES NEED TO BE TRIMMED OUT FROM AROUND TP TO HIGH FOR US TO REACH. REF TP
REFUSED TP REPLACED K-MATE
REFUSED TRAN FEEDING 3316 ANDRICKS --TREES OR SQUIRREL--DID TRIM TREES REF TR.
CHECK OUT TR FOUND DAD TR. LUO REPL AND RE-ROUTED DROPS IN TREES TR. BURNING OK LEFT 123-123- 246 RPLD CONN @

FORCED INTERR	FB	WR 10 1118B		36408233	120032840065	T	########	134(	65	4	260	SQUIRREL	SQUIRREL	5802 HIGHWAY	TF	364082339													
FORCED INTERR	BL	KB 20 10139	B80T	52558444	120032840066	T	########	134-	87	1	87	UNKNOWN	UNKNOWN	5935 KIRBY DR	1	SC	525584457												
FORCED INTERR	KY	KT 43 11577	11HP	37598240	120032840067	F	########	135(	66	2	132	UNKNOWN	UNKNOWN	2323 HARTWELI	1	LF	11HP												
FORCED INTERR	SH	SB 08 31859	B58L	59551110	120032840038	T	########	140(	61	10	610	SQUIRREL	SQUIRREL	807 BUSSE CIR	1	TF	595511104												
FORCED INTERR	BA	LP 01 41651	Y10G	62544490	320032840044	T	########	143(	84	1	84	SQUIRREL	SQUIRREL	1303 N 1ST	1	TF	625444991												
FORCED INTERR	BL	DN 03 10547		53561590	120032840072	T	########	144-	49	12	588	BU DISC OR BARI	DISC/BARRL	1706 WESTHEIM		TF	535615830												
FORCED INTERR	SU	AF 01 11753	F54C	49532598	120032840076	F	########	151(	0	0	0	UNKNOWN	UNKNOWN	10539 EVESBOF	2	LF	F54C	PR											
FORCED INTERR	SU	AF 01			120032840076	F	########	151(	99	18	1782	UNKNOWN			2	LF	F54C												
FORCED INTERR	SU	AF 01			120032840076	F	########	151(	107	6	642	UNKNOWN			2	LF	F54C												
FORCED INTERR	CH	GW 06 40903	48EQ	56811538	320032840047	L	########	152(	89	1	89	OH SEC/DR CL HI	OH SC CL-H	8121 RHOBELL	1	DR													
FORCED INTERR	SH	SB 08 31049	FB8	59540575	320032840050	F	########	160-	79	17	1343	SQUIRREL	SQUIRREL	3505 GUTHRIE	1	LF	I53K												
FORCED INTERR.	CY	PI 45 28126	S2729	44751335	220032840046	T	########	162(	65	1	65	SQUIRREL	SQUIRREL	30835 OLD HOC	1	TF	447513332												
FORCED INTERR	GP	FR 42 21384	54LP	49635384	320032840048	T	########	162(	86	1	86	SQUIRREL	SQUIRREL	9302 CORNETT	1	PR	496353847												
FORCED INTERR	MP	MP 01 41350	C71L	55569384	220032840051	L	########	163(	26	1	26	OH SEC/DR CL HI	OH SC CL-H	7630 AVENUE E	1	DR													
FORCED INTERR.	HC	QV 06 11120	98CE	50506432	120032840085	T	########	164(	66	5	330	ANTS	ANTS	622 FOXBOROU	2	SC	505064232												
FORCED INTERR	HC	HM 05 11026	77EB	54531367	120032840087	T	########	164(	37	5	185	SQUIRREL	SQUIRREL	8702 FERDINAN	1	TF	545313678												
FORCED INTERR	HM	LW 42 20127	25N		220032840055	F	########	172:	295	66	19470	FLLNG TREE OUT	TREE FL/OE	6307 TOWNSAN	1	LF	25N												
FORCED INTERR	CY	KL 45 2F129		48642408	220032840057	T	########	173(	90	1	90	VINES	VINES	12007 FOXBURC		TF	486424056												
FORCED INTERR	SH	SB 07 31051	GF8	58556066	320032840054	T	########	174(	33	8	264	BU DISC OR BARI	DISC/BARRL	1107 SATSUMA	1	TF	585560623												
FORCED INTERR	SH	PA 09 30765	F21Y	57543374	320032840059	T	########	180(	67	9	603	OTHER WILDLIFE	OTHER WLD	1515 QUAIL ST	1	TF	575433748												
FORCED INTERR	CH	GW 02 40897		56617121	320032840056	L	########	180(	110	1	110	FLLNG TREE OUT	TREE FL/OE	9226 TALTON S		DR													
FORCED INTERR	CH	AD 02 40211	7F5	54624234	320032840063	F	########	182(	87	10	870	UNKNOWN	UNKNOWN	2506 TRENTON	1	LF	7F5												
FORCED INTERR	SL	SE 04 22472	J33	32574085	120032840096	F	########	203(	133	13	1729	FOREIGN MATER	FRGN MATR	2368 OLD COLU	1	LF	J33												
FORCED INTERR	GP	RU 03 41661		53628224	220032840071	L	########	212(	63	1	63	CUST EQP RELA	CUST RLTD	11922 BAUMAN		DR													
FORCED INTERR	CH	SW 06 41685		55616592	320032840074	T	########	215(	56	18	998	UNKNOWN	UNKNOWN	7402 PARKER R		TF	556185921												
FORCED INTERR	HC	TV 03 11143	P47R	51507072	120032840106	L	########	233(	123	1	123	HUMAN ERROR	HUMN ERRC	16358 DETRIC L	2	DR													
FORCED INTERR	BL	JN 11 10039	DS8	50551550	120032840116	C	########	234(	119	9	1071	OH SEC/DR CL HI	OH SC CL-H	3705 OCEE ST	1	SC	505515504												
FORCED INTERR	BL	JN 11 10039	DS7	50551420	120032840111	L	########	235(	502	1	502	COLLISION	COLLISION	9600 WESTPAR	1	PD													
FORCED INTERR	HC	HOCQ 11166	X96L	51527562	120032840005	L	########	030(	403	1	403	COLLISION	COLLISION	11300 S POST C	1	PD													
FORCED INTERR	GA	GA 02 31188	C82P	67388186	320032850002	T	########	031(	84	24	2016	VINES	VINES	1917 45TH ST	1	TF	673881802												
FORCED INTERR	MP	UN 11 41752	B2A	54556151	220032850003	T	########	031(	39	12	468	UNKNOWN	UNKNOWN	4714 MARIETTA	1	TF	545561513												
FORCED INTERR	SU	IM 43 12061		47513021	120032850007	T	########	035(	90	2	180	VINES	VINES	13839 HIGHWA\		TF	475130217												
FORCED INTERR	SH	SB 01 31653	Y84E	58547375	320032850004	F	########	045(	192	36	7296	LIGHTNING ARRE	LTNG ARRS	2701 PASADENA	2	LF	Y84E												
FORCED INTERR	MP	MP 05 41376	RN5	55567540	220032850004	L	########	053(	88	1	88	COLLISION	COLLISION	7030 NAVIGATIC	1	SC		DR											
FORCED INTERR	GA	AL 09 30107	90LU	61428387	320032850005	F	########	071(	122	9	1098	BIRD	BIRD	AVE A, N OF AU	1	LF	90LU												
FORCED INTERR	MP	HR 04 41051	S6U	54591425	220032850007	T	########	080(	87	3	261	BIRD	BIRD	719 ELEANOR S	1	TF	545914259												
FORCED INTERR	SH	PO 06 30858	U59G	60562074	320032850007	F	########	080(	203	29	3567	BIRD	BIRD	18505 TIFFANY /	2	LF	U59G												
FORCED INTERR	SB	TO 05 28773	1KJ	51806241	120032850014	T	########	090(	61	1	61	SQUIRREL	SQUIRREL	4213 MANGUM	1	TF	518062414												
FORCED INTERR	SH	MY 05 3550A	74KA	57483006	320032850014	L	########	092(	181	1	181	TREE CLEARANC	TREE CLEAF	2117 COUNTY R	1	SC													
FORCED INTERR	MP	NS 02 41544	4LR	54582552	220032850012	T	########	094(	36	9	324	SQUIRREL	SQUIRREL	2927 ROBERTS	1	TF	545825522												
FORCED INTERR	SU	IM 45 12070	U40L		120032850017	F	########	104(	100	85	8500	LIGHTNING ARRE	LTNG ARRS	1411 MAYGROV	1	LF	U40L												
FORCED INTERR	KY	KT 02 22566	B43A	42588165	120032850016	T	########	104(	262	7	1834	URD SEC POSTL	URD SC PEE	908 VICTORIA L	2	SC	425881536												
FORCED INTERR	SH	PA 08 30797	H94P	57559033	320032850016	F	########	112(	47	41	1927	LIGHTNING ARRE	LTNG ARRS	1101 MAIN ST	1	LF	H94P												
FORCED INTERR	GP	HV 04 20524	527D	52640165	320032850016	T	########	113(	73	4	292	OH SEC/DR CL HI	OH SC CL-H	10102 VETERAN	1	SC	526401630												
FORCED INTERR	SU	IM 43 11268		48582115	120032850021	T	########	114(	73	4	292	BIRD	BIRD	12719 WESTHE		TF	485621159												
FORCED INTERR	HC	HM 09 11049	J86J	54536311	220032850022	F	########	114(	229	33	7557	UNKNOWN	UNKNOWN	8119 REDFERN	1	PR	J86J	BU	545363192										
FORCED INTERR	GP	SA 50 20863	P82	50620100	220032850017	T	########	115(	56	2	112	BIRD	BIRD	8718 EMMOTT F	1	TF	506201054												
FORCED INTERR	GP	FR 42 2F138	S3051	50646192	220032850021	T	########	120(	78	6	468	UNKNOWN	UNKNOWN	7403 WOODNET	2	TF	506461953												
FORCED INTERR	GP	NB 41 20264	P59P	53650290	320032850024	F	########	121(	0	0	0	SPLICE	SPLICE	16828 CARL BLE	2	LF	P59P	PR											
FORCED INTERR	GP	NB 41			220032850024	F	########	121(	127	63	8001	SPLICE			2	LF	P59P												
FORCED INTERR	GP	NB 41			220032850024	F	########	121(	127	100	12700	SPLICE			2	LF	P59P												
FORCED INTERR	FB	WR 11 12698	W33	33414234	120032850025	F	########	122(	61	16	976	SQUIRREL	SQUIRREL	NORTHINGTON	1	LF	W33												
FORCED INTERR	GP	LU 42 20591	89MH	52700415	220032850022	T	########	122(	80	1	80	SQUIRREL	SQUIRREL	1710 SPRING C	1	PR	527004157												
FORCED INTERR	CY	HK 42 22255	S3265	45674320	220032850026	T	########	123(	96	3	288	SNAKE	SNAKE	19107 CYPRESS	1	TF	456743208												
FORCED INTERR	BA	CS 03 40581			320032850046	C	########	124(	0	0	0	PRIMARY CONDU	PRIMARY	PTS 10733		PC	CS03	PR											
FORCED INTERR	BA	CS 03 40576			320032850046	C	########	124(	37	1682	62234	PRIMARY CONDU				PC	CS03												
FORCED INTERR	BL	GT 13 10642	G8K	53562011	120032850026	T	########	131(	400	37	14800	ROTTEN POLE	ROTTEN PLI	1751 WROXTON	1	BU	535620113	PD											
FORCED INTERR	SH	WE 08 31281	G13Y	57559357	320032850052	T	########	135(	40	3	120	UNKNOWN	UNKNOWN	420 RANDALL S	1	TF	575593570												
FORCED INTERR.	SU	CE 02 13026	K50B	47538256	120032850035	F	########	141(	137	48	6576	URD ELBOW	URD ELBOW	10218 KENT TOV	2	LF	K50B	PR											
FORCED INTERR	SU	AF 01 11752	F60C	49543013	120032850035	F	########	142(	28	14	392	SQUIRREL	SQUIRREL	10514 NEWBOR	2	LF	F60C												
FORCED INTERR	GP	LU 41 2D148	S3077	51686269	220032850035	L	########	143(	56	1	56	OH SEC/DR CL NI	OH SC CL-N	1526 HAMLIN VI	1	DR													
FORCED INTERR	SB	SR 01 21632	LN9	49578200	120032850041	T	########	154(	94	4	376	UNKNOWN	UNKNOWN	202 WARRENTC	1	TF	495782052												
FORCED INTERR	SH	PA 05 30779	UC4	57545490	320032850056	T	########	155(	54	8	432	UNKNOWN	UNKNOWN	1108 REDBUD C	1	TF	575454902												
FORCED INTERR	BL	SF 14 10442	N75B	51595671	120032850043	T	########	160(	46	1	46	BIRD	BIRD	4323 SAN FELIP	1	TF	515695780												
FORCED INTERR.	*SU*	*STF08 12266*	*95KW*	*48503548*	*120032850044*	*F*	########	*180(	108*	*19*	*2052*	*BU DISC OR BARI*	*DISC/BARRL*	*1735 COUNTRY*	*2*	DB	95KW												
FORCED INTERR	SU	BAR42 13212	58AS	47531268	120032850046	T	########	161(	146	4	584	UNKNOWN	UNKNOWN	15232 OLD RICH	1	PR	475312688												
FORCED INTERR	GP	LK 03 41291	SC2	52617586	320032850041	F	########	163(	60	18	1080	VINES	VINES	GRANVILLE E O	1	LF	SC2												
FORCED INTERR	SU	CE 02 11940	K31B	47538261	120032850047	L	########	164(	224	1	224	OH SEC/DR CL NI	OH SC CL-N	13718 TOWNE V	2	SC													
FORCED INTERR	CY	TB 02 21002	J20G	47713335	220032850042	F	########	170(	40	1	40	HUMAN ERROR	HUMN ERRC	29110 FM 149	1	LF	J20G												
FORCED INTERR	GP	LK 02 21869	E36V	52626368	220032850043	T	########	172(	472	2	944	CUST EQP RELA	CUST RLTD	866 GRENSHAW	2	BU	526263689												
FORCED INTERR	GA	HX 02 30662	I56G	63401222	320032850061	T	########	191(	73	2	146	OH SEC/DR CL HI	OH SC CL-H	6819 DREW ST	1	SC	634012229												
FORCED INTERR	MP	AN 07 40044		53590414	220032850046	L	########	191(	83	1	83	FLLNG TREE OUT	TREE FL/OE	2727 LAWRENC		DR													
FORCED INTERR	CH	GP 08 40829	45ES	57562444	320032850065	L	########	193(	127	1	127	UNKNOWN	UNKNOWN	1508 6TH #1	1	SC		DR											
FORCED INTERR	GA	GA 05 31202		67375485	320032850064	T	########	212(	20	6	120	*BU DISC OR BARI*	*DISC/BARRL*	5912 AVENUE T	1	TF	673754831												
FORCED INTERR	FB	WR 10 11258	G59I	36388485	120032850066	L	########	214(	70	1	70	OH SEC/DR CL HI	OH SC CL-H	2317 WALNUT S	1	SC													
FORCED INTERR.	FB	OR 02 11228	W166	39436564	120032850062	T	########	225(	29	3	87	UNKNOWN	UNKNOWN	1038 DARST RD	1	TF	394385485												
FORCED INTERR	SH	MY 05 31738	I98C	57480306	320032850068	T	########	233(	62	3	186	UNKNOWN	UNKNOWN	2005 DEEPBROK	1	TF	574803085												
FORCED INTERR	BA	BT 02 40108	G19E		320032860001	F	########	004(	29	91	2639	TREE CLEARANC	TREE CLEAF	3205 BRIAR CT	1	LF	G19E												
FORCED INTERR	SB	ME 01 21580	B36C	48574486	120032860001	T	########	005(	377	7	2639	UNKNOWN	UNKNOWN	14311 APPLE TF	1	BU	485744804												
FORCED INTERR	HC	MV 02 14214	W51O	54446404	120032860003	T	########	013(	144	7	1008	TRANSFORMER	TRANSFRM	8407 E SHERRI	1	TF	544454044												
FORCED INTERR	SH	CK 02 31713	76JT	59515099	320032860003	F	########	032(	149	37	5513	UNKNOWN	UNKNOWN	13528 ROBIN HI	2	LF	76JT	PR											
FORCED INTERR.	SB	ADK44 20965	E12N	50800076	120032860004	T	########	040(	293	1	293	UNKNOWN	UNKNOWN	9501 BAYTHORI	1	PR	508005786												
FORCED INTERR	HM	HB 45 20071	44MJ	58679454	220032860004	F	########	051(	0	0	0	LIGHTNING ARRE	LTNG ARRS	18830 DEMPSEY	2	LF	44MJ	PR											
FORCED INTERR	HM	HB 45			220032860004	F	########	051(	102	67	6834	LIGHTNING ARRE			2	LF	44MJ												
FORCED INTERR	MP	MP 03 40684	97AJ	55567274	320032860005	T	########	054(	95	1	95	TREE CLEARANC	TREE CLEAF	335 FOREST HII	1	TF	555672476												
FORCED INTERR.	SU	IM 43 12731	63UD	46526288	120032860005	T	########	064(	162	1	162	BIRD	BIRD	16425 MELLOW	2	PR	465262898												
FORCED INTERR	SH	TE 04 31083	42PT	55499550	320032860006	T	########	070(	142	1	142	CUST EQP RELA	CUST RLTD	1710 MYKAWA F	1	TF	554995079												
FORCED INTERR	BL	DN 03 10547	5FP	53562527	120032860006	L	########	071(	65	1	65	OH SEC/DR CL HI	OH SC CL-H	1841 FAIRVIEW	1	DR													
FORCED INTERR	HC	HM 05 11031	81DU	54521534	120032860006	F	########	071(	33	15	495	LIGHTNING	LIGHTNING	SCOTT, BTW CI	1	LF	81DU												
FORCED INTERR	SH	DR 09 31296	P5L	55527316	320032860007	F	########	073(	75	6	450	UNKNOWN	UNKNOWN	777 BRISBANE	1	LF	P5L												
FORCED INTERR	SH	CG 03 30216	U73O	56549001	320032860008	T	########	073(	75	1	75	BU DISC OR BARI	DISC/BARRL	4847 TIMBER CI	1	TF	565490015												
FORCED INTERR	HC	BL 03 10771		50523212	120032860011	T	########	080(	35	7	245	SQUIRREL	SQUIRREL	8319 FURLONG	1	TF	505232128												
FORCED INTERR	SH	DR 01 30263	N5F	56545157	320032860011	L	########	080(	90	1	90	TREE CLEARANC	TREE CLEAF	8036 BONNER C	1	SC													
FORCED INTERR	SH	CG 01 30186	65CW	56539210	320032860012	T	########	081(	65	1	65	SQUIRREL	SQUIRREL	7635 MOSLEY R	1	TF	565392109												
FORCED INTERR	CY	SA 45 21345		48635472	220032860010	T	########	081(	65	10	650	BU DISC OR BARI	DISC/BARRL	11210 STEEPLE	1	TF	486354738												
FORCED INTERR	CH	OA 01 41581	B2TT	57582246	320032860014	T	########	081(	83	7	581	CONTRACTOR -N	CON-NT HLF	11035 FLEMING	1	TF	575822468												
FORCED INTERR	MP	WO 02 41838	29EQ	52603422	220032850011	T	########	081(	49	2	98	UNKNOWN	UNKNOWN	4918 OAK FORE	1	TF	526034237												
FORCED INTERR	CH	CV 03 40433	T53X	59569451	320032860017	T	########	083(	51	8	408	SQUIRREL	SQUIRREL	15908 AVENUE	1	TF	595694579												
FORCED INTERR	SU	HY 13 11724		49574001	120032860013	T	########	084(	77	1	77	UNKNOWN	UNKNOWN	10402 VALLEY F		TF	495740010												
FORCED INTERR	CH	UV 04 41770		58596024	320032860016	L	########	084(	86	1	86	CONTRACTOR -N	CON-NT HLF	13634 HOLLYPA		DR		DR											
FORCED INTERR	CY	TB 46 28116	S2814	46686585	220032860018	T	########	090(	168	1	168	TREE CLEARANC	TREE CLEAF	18119 TELGE	1	PR	466865899												
FORCED INTERR	SB	TO 11 21784	29AAS	51600285	120032860021	T	########	091(	36	6	216	SQUIRREL	SQUIRREL	8508 FELDSPAR	1	TF	516002834												
FORCED INTERR	SU	BAR4E 11912	93PV	48555277	120032860022	F	########	091(	108	72	7632	LIGHTNING ARRE	LTNG ARRS	22 CRESTVIEW	2	LF	93PV												
FORCED INTERR	GA	AL 08 30047	W54O	61423011	320032860022	F	########	091(	34	25	850	UNKNOWN	UNKNOWN	12004 MCGREG	1	LF	W54O												
FORCED INTERR	SH	CA 01 30154	I43K	58539461	320032860022	T	########	091(	31	10	310	SQUIRREL	SQUIRREL	4912 HOLLY PAI	1	TF	585394616												
FORCED INTERR	KY	KT 43 11577	24AAV	38597298	120032860025	F	########	091(	91	31	2821	TREE CLEARANC	TREE CLEAF	3235 AVENUE G	1	LF	24AAV												
FORCED INTERR	BL	HE 06 10681	90DU	53583016	120032860026	T	########	092(	56	7	392	VINES	VINES	133 HARVARD S	1	TF	535830193												
FORCED INTERR	GP	RU 02 41655		52629222	220032860022	L	########	092(	53	1	53	CUST EQP RELA	CUST RLTD	510 W CANINO	1	DR													
FORCED INTERR	SH	DR 07 30293	W8B	56540124	220032860030	L	########	093(	64	1	64	OH SEC/DR CL NI	OH SC CL-N	7630 OAK VISTA	1	SC													
FORCED INTERR	GP	DH 07 2397E	J28R	50627308	220032860031	F	########	093(	163	16	2608	SPLICE	SPLICE	9710 DEANWOC	2	LF	J28R												
FORCED INTERR	FB	WR 09 11256	11GW	36378288	120032860032	F	########	095(	64	63	4032	SQUIRREL	SQUIRREL	1221 WESTGAT	1	LF	11GW												
FORCED INTERR	FB	RE 09 12975	99GB	44473505	120032860034	T	########	101(	73	2	146	BU DISC OR BARI	DISC/BARRL	4910 AIRPORT /	1	TF	444735058												
FORCED INTERR	FB	WR 10 11259	5FL	36368538	120032860037	T	########	102(	53	6	318	SQUIRREL	SQUIRREL	111 E EMILY	1	TF	363685383												
FORCED INTERR	GP	AD 06 2A177	77BB	53643404	220032860041	T	########	104(	45	2	90	UNKNOWN	UNKNOWN	460 ALDINE BEI	1	TF	536434049												
FORCED INTERR	GP	AD 01 20388	B83A	53645134	220032860046	T	########	111(	204	1	204	LIGHTNING	LIGHTNING	14830 HENRY R	1	BU	536451381	SC											
FORCED INTERR.	BA	MB 09 4704E		67630218	320032860044	T	########	112(	35	2	70	UNKNOWN	UNKNOWN	12922 INDIAN RI		TF	676302182												

26 TR, REF TR.																													
RPLD BEC CONN @ PL-1 CUST.																													
OKED BY CUST REF LF																													
REF TR.																													
REF TR.																													
RPLD BAU BARREL ON TR.																													
ISOLATED PRI STWN TR # 47 @ 10530 EVESBOROUGH AND TR # 48 AT 10534 EVESBOROUGH SO # 2118 BAD PIN ABOUT 10 FT INFRONT OF TR # 48. REF TP. BOL URD PR.																													
RPLD DR.																													
REF LF.																													
REF TR.																													
REPLACED LIMITER, RPLD LIMITER @ TR; REF TR.																													
RPLD CONN @ WH.																													
RPLD CONN @ TR.																													
REF TR.																													
TOOK OUT #3136...TREE CREW REMOVED LG PINE TREE OFF PRIMARY...RE ENERGIZ AFTER TREE WAS REMOVED; REF LF. RMVD TREE&MB OFF PR.																													
REMOVED VINES REPLACED LIMITER REFUSED TRANS. RPLD LIMITER @ TR, REF TR; RMVD TREE&MB OFF PR.																													
AGE REF TR.																													
REF TR.																													
NEED TO REPLACE # 4 DROPS IN EASMENT PAU DR:																													
REF LF.																													
PICKED UP 1 SPAN OF # 4 PRIMARY IN THE 7300 BLK OF OLD COLUMBUS. REF LF;																													
1ST-CUST'S WIRE. REPL ELECTR CONN AT WH; RPRD DROPS; RPRD DR, RPLD CONN @ WH.																													
REF TR.																													
RPRD CUST OWNED URD DROPS. ABOUT 8FT 1/0 DROP. RPRD DR.																													
MADE REPAIRS TO 1/0 SECONDARY ON TRANS; RPRD BEC--1 CUST.																													
REPLACED 45 CLASS 2 POLE WITH SAME OUT BY COLLISION; RPLD PL.																													
REPL 45 FT POLE 15 KVA TAP 2 CROSSARMS PICK UP #4 SEC #8 CU NEUTRAL NEED STREET LIGHT DEPT TO REPL BLK28786. RPLD PL.																													
REMOVED VINES AND REFUSED TP ...																													
REFUSED 50 KVA IN REAR OF 4710 MARIETTA # 36 HI HOWARD; REF TR.																													
REF TR.																													
8 KV LIA ON TERMINAL POLE IN EASMENT NEEDS TO BE REPLACED. Y84E, REF TP.																													
CLEARED 30 FT 8W9 POLE OFF HOUSE AND LET DOWN TO THE GROUND # PICKED UP 1 SPAN OF #4 SECONDARIES AND MADE REPAIRS TO MATERIALS ON 2 SETS OF DROPS LEFT POLE BL																													
REF LF.																													
REFUSED 25 CONV TRANS. REF TR.																													
REF TP																													
REFUSED NEW KVA TAP SQUIRREL. REF TR																													
repaired an installed sec and tree line—had installed bad lag nuts; RPRD BEC-1 CUST; REROUTED DR;																													
REF TR.																													
HAD BLOWN LIGHTING ARRESTOR ON A 600 STEP POT ON LF U40L REPLACED ALL LIGHTS BACK ON; REF LF. RPLD LIGHTNING ARRESTOR.																													
BAD URD BEC FROM TR #8 TO URD PED AT 808 VICTORIA LAKES DR COULD NOT PULL IN NEW BEC RAN BY-PASS CABLE NEED TO REPLACE BEC (APPROX 120 FT.) CONDUIT INSTALLED																													
REF LF.																													
RPLD CONN @ TR.																													
REF TR																													
REPLACED BAD 25 KVA 7200-120-240 TRANS WITH 37.5 ALSO RETIED IN PRIMAR; PAUP PR-FUSE NOT BLOWN, RPLD BAU TR.		

| | | |

FORCED INTERR	SH	FT 02	30398	B69L	59549097	320032870053	T	########	1400	34	12	408	LIGHTNING ARRE	LTNG ARRS	7413	FAITH DR	1	TF	595490972								1	0
FORCED INTERR	BL	GN 06	10620	J6H	52559022	120032870073	F	########	1411	36	19	684	TREE CLEARANC	TREE CLEAI	2422	GLEN HAV	1	LF	J6H								1	0
FORCED INTERR	HC	HOC0	11156	RH1	52530195	120032870074	T	########	1424	49	10	490	TREE CLEARANC	TREE CLEAI	4405	KINGLET S	1	TF	525301979								1	0
FORCED INTERR	GP	NB 41	22366		53656336	320032870146	T	########	1431	49	11	539	TREE CLEARANC	TREE CLEAI	931	VELLER DR		TF	536563360								1	0
FORCED INTERR.	CY	HK 04	21139	32EM	41672466	220032870147	T	########	1433	57	1	57	LIGHTNING	LIGHTNING	29801	BETKA RI	1	TF	416724662								1	0
FORCED INTERR.	SH	MY 05	35508		57475326	320032870052	T	########	1433	47	2	94	SQUIRREL	SQUIRREL	2026	1/5 COUNT		TF	574753267								1	0
FORCED INTERR	BL	UL 46	10365		50579075	120032870075	T	########	1434	69	7	483	UNKNOWN	UNKNOWN	6225	CEDAR CR		TF	505790753								1	0
FORCED INTERR	BA	FT 01	31036	37KS	61533474	320032870055	F	########	1436	63	7	441	SQUIRREL	SQUIRREL	10446	ANTRIM L	1	LF	37KS	TF	615334747						1	0
FORCED INTERR	MP	NS 01	41535	X27G	54593286	320032870014	L	########	1442	45	1	45	TREE CLEARANC	TREE CLEAI	4507	HARDY ST	1	SC									1	0
FORCED INTERR.	SB	SR 01	21629	8GF	49586105	120032870077	L	########	1450	59	1	59	OH SEC/DR CL NI	OH SC CL-N	12458	BARRYKN	1	SC									1	0
FORCED INTERR.	SB	ADK44	22149	H40D	49593431	320032870078	T	########	1450	47	11	517	VINES	VINES	10822	EMNORA	1	TF	495934314								1	0
FORCED INTERR	CH	BY 05	41982	DU2	54623147	320032870060	T	########	1450	103	2	206	HUMAN ERROR	HUMN ERRC	10617	ALDINE W	1	TF	546231473								1	0
FORCED INTERR	BZ	BZ 06	30636		53262558	320032870061	T	########	1450	79	5	395	TREE CLEARANC	TREE CLEAI	131	MULBERRY		TF	532625930								1	0
FORCED INTERR	SH	PO 09	41183		61498459	320032870062	T	########	1510	29	2	58	SQUIRREL	SQUIRREL	101	BAYOU VIEI		TF	614984905								1	0
FORCED INTERR	BL	DV 11	21724	B18G		120032870084	F	########	1522	96	13	1248	FLLNG TREE IN E	TREE FLAE	1	WOODS EDGI	1	LF	B18G	PR							1	0
FORCED INTERR	BA	BT 03	31304	8D5	63575367	320032870061	L	########	1552	47	1	47	VANDALISM	VANDALISM	613	GRESHAM S	1	MT									1	0
FORCED INTERR	FB	BV 42	11363	49UE	43515491	120032870091	T	########	1554	128	1	128	VINES	VINES	4712	PECAN CR	1	TF	435154944								1	0
FORCED INTERR.	BL	HE 09	11556	2EZ	52579271	120032870097	F	########	1618	97	9	873	UNKNOWN	UNKNOWN	2178	TROON	1	LF	2EZ								1	0
FORCED INTERR	BL	ES 06	40664	8P5	54563324	220032870165	T	########	1618	76	4	304	TREE CLEARANC	TREE CLEAI	2305	BRAILSFOI	1	SC	545633248								1	0
FORCED INTERR	KY	MAR41	21573		4658311	320032870096	T	########	1623	81	2	162	UNKNOWN	UNKNOWN	206	BARKER CL		PR	465831155								1	0
FORCED INTERR	SU	HY 13	14232		49575171	120032870101	T	########	1628	60	10	600	VINES	VINES	10111	PINE FOR		TF	495751783								1	0
FORCED INTERR	SB	WT 02	21846	K85M	51596041	320032870102	T	########	1630	65	7	455	TREE CLEARANC	TREE CLEAI	8508	SCHILLER	1	TF	515060449								1	0
FORCED INTERR	FB	RS 04	12725	12KT	43486081	120032870102	T	########	1630	35	12	420	SQUIRREL	SQUIRREL	2207	4TH #28	1	TF	434860644								1	0
FORCED INTERR	KY	KT 41	22591	11JG	43592221	120032870106	L	########	1636	135	1	135	UNKNOWN	UNKNOWN	5315	REXORA L	1	SC									1	0
FORCED INTERR.	BL	HT 05	10306		50568121	120032870107	T	########	1640	43	7	301	BIRD	BIRD	6440	RICHMONI		TF	505681217								1	0
FORCED INTERR	SH	SB 03	31038	J35K	56559301	320032870075	L	########	1644	100	1	100	OH SEC/DR CL HI	OH SC CL-H	3116	WASHING'	1	DR									1	0
FORCED INTERR	GP	LU 44	20574	66DR	50696054	220032870167	T	########	1646	178	2	356	TREE CLEARANC	TREE CLEAI	5410	DUNLEITH	1	TF	506960542								1	0
FORCED INTERR	CH	OA 01	41581	653T	57580284	320032870077	T	########	1650	85	8	680	SQUIRREL	SQUIRREL	10614	VALENCIA	1	TF	575802894								1	0
FORCED INTERR	MP	NS 04	41552		54584252	220032870166	T	########	1700	28	9	252	BU DISC OR BARI	DISC/BARRL	2018	MAURY ST		TF	545842539								1	0
FORCED INTERR	SB	EC 07	21731		49589045	120032870106	T	########	1704	445	4	1780	UNKNOWN	UNKNOWN	725	RIEDEL DR		BU	495890453	PD							1	0
FORCED INTERR	SB	EC 05	21707	K42M	50589567	120032870111	T	########	1710	69	4	414	BU DISC OR BARI	DISC/BARRL	8318	LEAFY LN	1	TF	505895670	PR							1	0
FORCED INTERR	HM	AT 42	23140	P82G	60712136	220032870173	T	########	1713	82	5	410	CONTRACTOR-IN	CON-NT HLF	28615	LOCHLEV	2	TF	607121360								1	0
FORCED INTERR	SH	WE 03	31257	B87U	57557496	320032870062	T	########	1723	29	7	203	BU DISC OR BARI	DISC/BARRL	302	W SHAW A	1	TF	575574998								1	0
FORCED INTERR	HM	HB 47	20027	4EW	56685247	220032870172	T	########	1725	75	2	150	VINES	VINES	1022	MANNING I	1	TF	566852473								1	0
FORCED INTERR	SH	SO 42	31348	3EX	54483384	320032870084	T	########	1734	134	4	536	SQUIRREL	SQUIRREL	2246	STERLING	1	TF	544833864								1	0
FORCED INTERR	BL	ST 13	10203		50549506	120032870113	T	########	1735	62	6	372	TREE CLEARANC	TREE CLEAI	8517	STROUD D		TF	505495090								1	0
FORCED INTERR	SB	CB 07	21448	2WT	50606024	120032870113	T	########	1738	62	5	310	UNKNOWN	UNKNOWN	2903	SOWAY ST	1	TF	506060243								1	0
FORCED INTERR.	BA	LP 03	41773	B71D	62535401	320032870086	L	########	1738	61	1	61	ROTTEN POLE	ROTTEN PLI	721	S 3RD	1	PD									1	0
FORCED INTERR	CH	UV 04	41768	57PK	58599025	320032870067	T	########	1743	118	16	1668	TREE CLEARANC	TREE CLEAI	14529	WOODFC	1	TF	585990299								1	0
FORCED INTERR	BL	GT 04	40853		53566222	120032870115	T	########	1800	55	4	220	BIRD	BIRD	4714	MAIN ST		TF	535662234								1	0
FORCED INTERR	BA	BT 04	40127	H35L	63572024	320032870086	F	########	1804	56	29	1624	SQUIRREL	SQUIRREL	1901	ONTARIO S	1	LF	H35L								1	0
FORCED INTERR	MP	WO 12	21952	94QS	52608522	220032870176	T	########	1807	122	7	854	OH SEC/DR CL NI	OH SC CL-N	807	LEHMAN ST	1	SC	526085232	SC							1	0
FORCED INTERR	RS	LV 01	30098	PP1		320032870086	F	########	1813	94	21	1974	UNKNOWN	UNKNOWN	8118	WILLIAMS	1	LF	PP1								1	0
FORCED INTERR	SH	EL 09	30361	S85B	58505584	320032870092	F	########	1820	0	0	0	SPLICE	SPLICE	13710	GROSVEI	2	LF	S85B	PR							1	0
FORCED INTERR	SH	EL 09				320032870092	F	########	1820	148	7	1036	SPLICE				2	LF	S85B								0	0
FORCED INTERR	SH	EL 09				320032870092	F	########	1820	148	14	2072	SPLICE				2	LF	S85B								0	0
FORCED INTERR	CH	BY 05	40179		54613478	320032870094	L	########	1830	74	1	74	OH SEC/DR CL HI	OH SC CL-H	9930	ALDINE WI		DR									1	0
FORCED INTERR.	HM	LA 03	41242	FB4L	54636424	220032870180	T	########	1904	60	5	300	CUST EQP RELA	CUST RLTD	3603	ALDINE MA	1	TF	546364281								1	0
FORCED INTERR	CH	CV 10	40464	J21A	58588241	320032870096	T	########	1905	60	2	120	SQUIRREL	SQUIRREL	14328	MUSCATI	1	TF	585882412								1	0
FORCED INTERR	HC	FD 06	10690		50535384	120032870122	T	########	1914	62	4	248	VINES	VINES	7711	TWIN HILL		TF	505353841								1	0
FORCED INTERR	GA	GL 07	30499	1M2	68380061	320032870104	F	########	2036	45	38	1620	FOREIGN MATER	FRGN MATR	4002	AVENUE R	1	LF	1M2	TF	683800616						1	0
FORCED INTERR	BL	UL 45	14001	47MD	50569371	120032870126	L	########	2110	94	1	94	FOREIGN MATER	FRGN MATR	6237	OVERBRO	1	DR									1	0
FORCED INTERR	GP	LK 04	21875	G52G	52632177	220032870186	F	########	2111	0	0	0	UNKNOWN	UNKNOWN	9214	BURFORD	2	LF	G52G	PR							1	0
FORCED INTERR	GP	LK 04				220032870186	F	########	2111	204	10	2040	UNKNOWN				2	LF	G52G								0	0
FORCED INTERR	GP	LK 04				220032870186	F	########	2111	204	15	3060	UNKNOWN				2	LF	G52G								0	0
FORCED INTERR	CY	HK 05	2A110			220032870190	C	########	2113	366	30	10980	STRONG WIND	WIND	KICKAPOO AND			PC	HK05								1	0
FORCED INTERR	GA	GL 07	30499	1M2	68380071	320032870110	T	########	2134	121	5	605	UNKNOWN	UNKNOWN	2317	39TH ST	1	TF	683800719								1	0
FORCED INTERR.	SH	DE 04	31375	4NS	59558490	320032870112	F	########	2356	70	58	4060	UNKNOWN	UNKNOWN	110	E 3RD #1	1	LF	4NS								1	0
FORCED INTERR	GA	TIK01	30102	Y83F	65383488	320032880000	T	########	0547	213	5	1065	UNKNOWN	UNKNOWN	1343	LEILANI	1	BU	653834892								1	0
FORCED INTERR	HC	HM 06	11033	I31X	54542064	120032880000	T	########	0711	59	12	708	OH SEC/DR CL HI	OH SC CL-H	4305	KAY CIR	1	SC	545420647								1	0
FORCED INTERR	SH	CA 02	30589	K17G	58541040	320032880000	T	########	0721	62	3	186	OTHER WILDLIFE	OTHER WLE	5317	HOLLY	1	TF	595410430								1	0
FORCED INTERR	BA	LP 04	41663	B73E		320032880001	F	########	0734	62	36	2232	UNKNOWN	UNKNOWN	614	S IDAHO ST	1	LF	B73E	LF	75ADQ						1	0
FORCED INTERR	BA	CS 01	40557	46J	61833035	320032880005	L	########	0735	176	1	176	UNKNOWN	UNKNOWN	13410	BLANCHA	1	SC									1	0
FORCED INTERR	HC	MV 01	14207	A97P	54456111	120032880007	F	########	0740	37	14	518	SQUIRREL	SQUIRREL	20230	MORRIS	1	LF	A97P								1	0
FORCED INTERR.	CH	GP 04	40803	H62E	57582073	320032880006	F	########	0740	51	6	306	UNKNOWN	UNKNOWN	HOLLAND @ WI		1	LF	H62E								1	0
FORCED INTERR	FB	LC 01	12935	77AP	38358461	120032880006	T	########	0749	42	2	84	SQUIRREL	SQUIRREL	7810	FM 3012 RI	1	TF	383584613								1	0
FORCED INTERR.	SB	SA 43	21295	E36N	48619484	120032880006	T	########	0753	77	10	770	SQUIRREL	SQUIRREL	11115	HAYSLIP I	1	TF	486194882								1	0
FORCED INTERR	SH	SB 06	31049	B85M	59550008	320032880011	F	########	0801	74	78	5772	UNKNOWN	UNKNOWN	3510	SUITER W.	1	LF	B85M								1	0
FORCED INTERR	GP	GZ 43	2J168	S1421	52658441	220032880013	T	########	0805	55	7	385	SQUIRREL	SQUIRREL	326	SOUTHBRO	1	TF	526584412								1	0
FORCED INTERR	BA	FT 01	40654	84BF	61534387	320032880012	F	########	0800	55	33	1815	SQUIRREL	SQUIRREL	10915	BIRCH DF	2	LF	84BF								1	0
FORCED INTERR	SH	SP 02	30973	23EH	58541200	320032880013	F	########	0810	82	22	1804	SQUIRREL	SQUIRREL	2118	BASKET S'	1	LF	23EH								1	0
FORCED INTERR	HC	FD 03	10846	3BR	51531584	120032880017	T	########	0811	65	6	390	SQUIRREL	SQUIRREL	5727	S BRAESW	1	TF	515315960								1	0
FORCED INTERR	SB	SR 05	21446	K74T	49593055	120032880011	T	########	0815	46	1	46	SQUIRREL	SQUIRREL	1730	STEBBINS	1	TF	495930599								1	0
FORCED INTERR	HC	AR 43	10942	9AN	51478088	120032880014	F	########	0820	0	0	0	COLLISION	COLLISION	910	DAVIS	1	PR	9AN								1	0
FORCED INTERR	HC	AR 43				120032880014	F	########	0820	55	61	3355	COLLISION				1	PR	9AN								0	0
FORCED INTERR	HC	AR 43				120032880014	F	########	0820	157	4	628	COLLISION				1	PR	9AN								0	0
FORCED INTERR	SU	HY 01	11677		49572138	120032880015	T	########	0825	61	7	427	SQUIRREL	SQUIRREL	10706	CANDLEV		TF	495721380								1	0
FORCED INTERR	MP	WO 03	41837	P8K	52604330	220032880016	F	########	0835	75	44	3300	SQUIRREL	SQUIRREL	1219	THORNTO	1	LF	P8K								1	0
FORCED INTERR	BA	CD 05	40370	RE3	63575421	320032880020	T	########	0837	37	10	370	BU DISC OR BARI	DISC/BARRL	703	HAROLD LN	1	TF	635754214								1	0
FORCED INTERR	SH	SP 02	30973	2KW	58540103	320032880021	T	########	0837	45	6	270	UNKNOWN	UNKNOWN	504	PAULINE	1	TF	585401077								1	0
FORCED INTERR	HC	HOC0	11169	20M	51536130	120032880016	T	########	0840	72	5	360	SQUIRREL	SQUIRREL	5159	KINGFISHE	1	TF	515361300								1	0
FORCED INTERR	CH	UV 02	41767	E84J	58597284	320032880022	F	########	0850	39	26	1014	SQUIRREL	SQUIRREL	203	WICKHAMF	2	LF	E84J								1	0
FORCED INTERR	FB	NEWO	11245	13RB	40360365	120032880022	F	########	0900	67	3	201	SQUIRREL	SQUIRREL	KEMP, NORTH		1	LF	13RB								1	0
FORCED INTERR.	CH	GP 07	40820	RA9	57561568	320032880027	T	########	0905	33	4	132	SQUIRREL	SQUIRREL	1713	10TH	1	TF	575815605								1	0
FORCED INTERR	SH	FT 02	30398	11DT	60541115	320032880028	T	########	0920	31	7	217	SQUIRREL	SQUIRREL	4213	DAHLIA LN	1	TF	605411195								1	0
FORCED INTERR.	FB	WR 13	11284	64KK	36375548	120032880028	F	########	0922	98	8	784	OH SEC/DR CL NI	OH SC CL-N			1	LF	64KK	TF	363755482	SC					1	0
FORCED INTERR	RS	LV 03	30574	87PH		320032880033	F	########	0922	46	28	1344	SQUIRREL	SQUIRREL	23	KENNY CT	1	LF	87PH								1	0
FORCED INTERR	HC	HOC0	11178	WS7	51516461	120032880030	T	########	0923	71	11	781	TREE CLEARANC	TREE CLEAI	13623	AMBLE LN	1	TF	515184612	SC							1	0
FORCED INTERR	FB	OR 02	11228	77KK	38438506	120032880030	T	########	0930	109	5	545	O/H PRIMARY CL	OH PR CLM	639	FM 2919 RD	1	TF	384385063								1	0
FORCED INTERR.	BA	ST 01	40095	A42T	63563367	320032880034	F	########	0940	45	68	3060	UNKNOWN	UNKNOWN	1127	CARVER S	1	LF	K5N								1	0
FORCED INTERR	SU	SE42	11536	33JP	49487352	120032880036	F	########	0944	77	1	77	LIGHTNING	LIGHTNING	4807	OIL FIELD	1	LF	33JP								1	0
FORCED INTERR	FB	DA 05	11018	29NV	46460161	120032880037	T	########	0944	139	1	139	LIGHTNING	LIGHTNING	9835	PROVIDEN	1	TF	464032107								1	0
FORCED INTERR	MP	BH 06	40301	41X	55580144	220032880030	C	########	0955	43	8	344	SQUIRREL	SQUIRREL	4804	VERNON S	1	LF	41X								1	0
FORCED INTERR	MP	UN 10	41742	F4N	55552368	220032880031	F	########	0954	31	13	403	BU DISC OR BARI	DISC/BARRL	2826	SUTHERLA	1	LF	F4N								1	0
FORCED INTERR	CH	SW 09	41699	B77C	55621340	320032880043	T	########	1001	34	4	136	SQUIRREL	SQUIRREL	11127	PERCY RI	1	TF	556213407								1	0
FORCED INTERR	MP	GG 07	40978		55547398	220032880033	T	########	1000	26	9	234	VINES	VINES	5310	TELEPHON		TF	555473955								1	0
FORCED INTERR	CH	LY 42	4706E	N13E	58599304	320032880045	T	########	1000	60	4	240	UNKNOWN	UNKNOWN	1220	SHELDON	1	TF	585993048								1	0
FORCED INTERR.	SB	SA 43	21295	E33N	48610401	120032880040	F	########	1000	49	30	1470	SQUIRREL	SQUIRREL	11030	DYSON LI	1	LF	E33N								1	0
FORCED INTERR.	SU	QV 02	12157	H17Z	50480516	120032880041	F	########	1007	62	48	2978	BU DISC OR BARI	DISC/BARRL	2403	BRADFORI	2	DB	H17Z								1	0
FORCED INTERR	MP	WO 05	41837	P8K	52604306	220032880034	T	########	1008	29	14	406	SQUIRREL	SQUIRREL	1251	THORNTO	1	TF	526043084								1	0
FORCED INTERR	SH	CA 01	30156	16LT	58538461	320032880046	T	########	1015	21	11	231	VINES	VINES	3203	PRESTON	1	TF	585384616								1	0
FORCED INTERR	RS	LV 02	30077	FU2		320032880050	F	########	1022	29	10	290	BIRD	BIRD	2123	COUNTY R	1	LF	FU2								1	0
FORCED INTERR.	BA	CD 09	40403	E10K	64572204	320032880052	T	########	1028	165	1	165	UNKNOWN	UNKNOWN	2304	BAY PLZ	1	BU	645722069								1	0
FORCED INTERR.	RS	LV 01	30098	PP1	56388138	320032880056	F	########	1031	46	21	966	TREE CLEARANC	TREE CLEAI	2931	ST PHILLIP	1	LF	PP1								1	0
FORCED INTERR	GA	AL 09	31731	M25		320032880057	F	########	1034	35	54	1890	UNKNOWN	UNKNOWN	5	PINE OAK CIR	1	LF	M25								1	0
FORCED INTERR	CY	TB 45	21030	42NJ	45714106	220032880041	T	########	1045	33	2	66	VINES	VINES	18802	HERON	1	TF	457141066								1	0
FORCED INTERR	CY	HK 04	21141	28FE	40653324	220032880042	T	########	1050	102	1	102	BIRD	BIRD	31945	BERRY LI	1	TF	406533241								1	0
FORCED INTERR	GP	HV 05	20517	W97W	52646362	220032880044	F	########	1100	53	5	265	UNKNOWN	UNKNOWN	11000	NORTH F	1	LF	W97W								1	0
FORCED INTERR	SU	JK 10	12130		48556184	120032880057	T	########	1111	80	1	80	TREE CLEARANC	TREE CLEAI	6401	WESTLINE		SC	485561893								1	0
FORCED INTERR	SB	WT 02	21846	M7D	51595089	120032880061	T	########	1112	48	12	576	TREE CLEARANC	TREE CLEAI	6618	WHARTON	1	TF	515950930								1	0
FORCED INTERR	RS	MU 02	30740	H89F	58400277	320032880066	F	########	1122	39	1	39	LIGHTNING	LIGHTNING	8400	CO 170	1	LF	H89F								1	0
FORCED INTERR	HC	BR 08	10523	81W	51535585	120032880073	L	########	1225	37	1	37	OH SEC/DR CL HI	OH SC CL-H	5202	CONTOUR	1	DR									1	0
FORCED INTERR	GP	SA 50	20863	A44K	49629164	220032880061	F	########	1225	45	20	900	VINES	VINES	7131	HOLMSLEY	1	LF	A44K								1	0
FORCED INTERR	CH	PW 02	40383	E69J	57614370	320032880075	T	########	1233	72	10	720	SQUIRREL	SQUIRREL	11975	TIDWELL	1	TF	576143704								1	0
FORCED INTERR	GP	FR 46	21309		50605577	220032880066	T	########	1241	72	2	144	VINES	VINES	5295	HOLLISTEI		PR	506055739								1	0
FORCED INTERR	GA	GL 05	30483	E75E	68383290	320032880082	T	########	1244	162	28	4536	TREE CLEARANC	TREE CLEAI	1910	27TH ST	1	SC	683832989								1	0

REF TR.
REMOVED PIECES OF BAMBOO FRO PRI--REFUSED MID & BO. PHS OF LF JIH-461 CREWLEADER HAFERKAMP @ 8EL. B/C TO BEHD TREE CREW TO TRIM BAMBOO BELOW PRI REF LF F
trimmed enough trees to keep it from tripping & need it need tree crew to finish rmv this address already has been turned in earlier by Mr Fletcher; RESET TR.
REF TR.
PROBABLY OUT SINCE 10/09 WATER WELL WAY @ END OF LINE FUSE. REF TR.
REF TR.
REFUSED & REPLACED LIMITER, REF TR.
REFUSE LINE FUSE AND TRANSF REF LF, REF TR. TLA
TREE LIMB BROKE LIGHTER OFF AT POLE, MADE REPAIRS RPRD BEC CONN @ PL-1 CUST
RPLD CONN @ PL. RETAPED CONN @ WH.
CLEARED VINES REFUSED TRANS BACK ON ..... REF TR;
[illegible] REF TR.
REFUSED TRANS AND TRIM TREES, REF TR.
REF TR.
PICKED UP 1 SPAN # 4 PRIMARY P&J PR-FUSE BLOWN, REF LF TLA
[illegible] REPL MTR.
REMOVED VINES REFUSED 25, REF TR.
REF LF.
TLA
REPLACED BAD LIMITER FUSE & REFUSED O.H. TRANS. RPLD LIMITER @ TR. REF TR.
CLEARED VINES FROM OPEN DELTA BANK, REF TR.
LINE FUSE WAS NOT OUT; RESET TR.
REFUSED 100 KVA TRANS BOURREL HAS WLP. REF TR.
REPLACED NEUTRAL CONNECTIONS @ MID SPAN TAP & @ WEATHERHEAD, RPLD CONN @ PL. RPLD BEC CONN @ PL-1 CUST TLA
REFUSED 50 KVA POWER POT IN CLOSED DELTA BANK, REF TR.
ADE, RPLD CONN @ WH.
NEED TO TRIM OR REMOVE WILLOW TREE AND NEED TO TRIM TALLOW TREE MAY GET WITH CUST HE SAID WOULD PROBABLY BE ALRIGHT TO REMOVE TALLOW TRIM TREES REPL LIMIT
TRIMMED TREES AND REFUSED TRANS, REF TR.
[illegible] REF TR.
RPLD BAD TR, STUMBED UP PL.
MADE REPAIRS TO HIGH-SIDE JUMPER ON TRANSFORMER, RPRD B/O PR JUMPER-FUSE NOT BLOWN
FENCE COMPANY HIT URD DROPS AND TRIPPED URD TRANSFORMER. RESET TR.
ADE, RPLD BAD BARREL ON TR.
REMOVED VINES AND CHANGED OUT 12K LIMITER AND REFUSED TRANS. RPLD LIMITER @ TR, REF TR. TLA
REF TR.
REFUSED 50 KVA LIGHTER DUE TO TREE CLEARANCE, REF TR.
RESET CBP TRANSFORMER, RESET TR.
NEED TO REPLACE 25' BVC POLE IN EASEMENT HELD UP W/ COTTON LINE. STUMBED UP PL. TLA
TRIMMED TREES AND REFUSED TRANS. REF TR.
REFUSED 100 KVA LIGHTER POT IN CLOSED DELTA BANK, REF TR.
4-8 CBP NO PROTECTION, REF LF TLA
RPRD BUSS WORK @ TR. RPLD CONN @ PL.
refused LF, REF LF
REF TP 8/01 URD PR ISOLATED PRI ON B/O #2152 BTWN TF #42 & #43 (DIRECT BURY) W/30 BENT TO B/C TO REPLACE SPAN LATER TLA

RPLD CONN @ WH.
CUSTOMER HAS A BURNED UP METER CAN DISCCONNECT DROPS AND REMOVED METER READING 45090 AND RESET CBP TRANSF RESET TR.
REFUSED 37.8 KVA, REF TR.
TREE TRIMMING NEEDED BAD ALSO NEED TO PICK UP LIMBS IN REAR OF ADDRESS, REF TR. TLA
SOUTH PHASE OF LF 1162 501 2 PHASE, WAS FOUND BLOWN, REFUSED AND TRIED, HELD AND LEFT WITH GOOD VOLTAGE REF LF REF TR TLA
CHANGED OUT BAD CLAMPS AT WEATHERHEAD DUE TO CORRUSION NOTIFIED; RPLD CONN @ WH.
URD BWD 2153. ISOLATE BAD PRIM BTWN 2027& 2035 BARNBLEY DIRECT BURIED 12KV, LIVE FRONT TRANSFR., REF TP 8/01 URD PR.

CREW FOUND RECTIONALIZER 110N LOCKED OUT RODE PRI OUT AND FOUND SEVERAL SPANS OF WIRE DOWN, 14 SPANS EAST OF 110N PICKED UP PRI AND RESTORED SERV "OH
REF TR.
REFUSED IN PHASE OF LF, REF LF
REPL BAD TRANS, RPLD BAD TR.
rep bad conn at pole left door hanger on back door, RPLD BEC CONN @ PL-1 CUST;
REFUSE 50 CONV REF TR.
REFUSED LF UNKNOWN; REF LF
RPLD CONN @ PL.

FORCED INTERR	GA	STW0	3549B	E42D	61318041	320032880083	T	########	1248	148	3	444	HUMAN ERROR	HUMN ERRC	4123 6TH ST	1	SC	613180415											
FORCED INTERR	BZ	BZ 04	30639	K5Z	53260424	320032880085	T	########	1250	53	4	212	SQUIRREL	SQUIRREL	842 MAGNOLIA	1	TF	532804260											
FORCED INTERR	SH	FW 04	30439		59480115	320032880086	T	########	1250	46	5	230	VINES	VINES	2722 PORT CAR		TF	594801153											
FORCED INTERR	CY	PI 44	21031	T51K		220032880077	F	########	1300	130	41	5330	TREE CLEARANC	TREE CLEAF	12011 SAMANTH	1	LF	T51K											
FORCED INTERR	KY	MAR4				120032880084	C	########	1320	0	0	0	PRIMARY CONDU	PRIMARY	19810 SUNBRID		CL	MAR44	PR										
FORCED INTERR	KY	MAR4	1G368			120032880084	C	########	1320	32	1616	51712	PRIMARY CONDU				CL	MAR44											
FORCED INTERR	KY	MAR4	12385			120032880084	C	########	1320	38	2842	107996	PRIMARY CONDU				CL	MAR44											
FORCED INTERR	KY	MAR4	24837			120032880084	C	########	1320	112	178	19936	PRIMARY CONDU				CL	MAR44											
FORCED INTERR	HM	AD 10	41977	34LK	5464238	220032880082	L	########	1330	143	1	143	FLLNG TREE OUT	TREE FL/OE	2226 MAXIMILIAI	1	PD												
FORCED INTERR	SH	GV 04	30529	K93H	5452950	320032880103	T	########	1340	56	8	448	SQUIRREL	SQUIRREL	5719 WATERFO	1	TF	545295021											
FORCED INTERR	MP	MP 05	41379	4BY	5557914	220032880083	T	########	1340	42	1	42	UNKNOWN	UNKNOWN	3 WHARF	1	TF	555791461											
FORCED INTERR	MP	NS 02	41544	4LR	5458255	220032880084	T	########	1340	42	9	378	SQUIRREL	SQUIRREL	2927 ROBERTSI	1	TF	545825522											
FORCED INTERR	CH	NM 04	41526	M23N	5757742	320032880092	F	########	1340	45	51	2295	SQUIRREL	SQUIRREL	BIRDIE @ FEDE	1	LF	M23N											
FORCED INTERR	SH	SH 01	30695	36D	5752340	320032880094	F	########	1350	37	45	1685	SQUIRREL	SQUIRREL	10007 HINDS ST	1	LF	36D											
FORCED INTERR	CY	KL 46	21013	59NB	4866016	220032880087	F	########	1401	86	13	1118	TREE CLEARANC	TREE CLEAF	11834 DEEP WC	1	LF	59NB											
FORCED INTERR	KY	KT 41	22564	26SU	4358032	120032880126	T	########	1430	81	5	405	CONTRACTOR (H	CON-HLP	1511 AVENUE A	1	SC	435803261											
FORCED INTERR	GP	KI 44	2324A	54CN	4969605	220032880094	L	########	1500	99	1	99	COLLISION	COLLISION	7506 AUBURN F	2	SC												
FORCED INTERR	GA	GA 07	31211	4DE	6738413	320032880106	L	########	1520	138	1	138	UNKNOWN	UNKNOWN	1027 BAYOU CIF	1	DR												
FORCED INTERR	HC	MV 02	14215	38KR		120032880137	F	########	1520	68	103	6798	SQUIRREL	SQUIRREL	9715 TWIN OAK	1	LF	38KR											
FORCED INTERR	GP	LK 10	22122	FW2	5161949	220032880095	T	########	1520	239	4	956	UNKNOWN	UNKNOWN	2445 MAYVIEW	1	BU	516194928											
FORCED INTERR	SH	SH 11	31404	A20S	5752908	320032880106	L	########	1530	47	1	47	FLLNG TREE OUT	TREE FL/OE	12118 DUMAS S	1	DR												
FORCED INTERR	SB	SR 15	21678	I65H	4959617	120032880142	T	########	1541	68	7	476	SQUIRREL	SQUIRREL	1750 MAUX DR	1	TF	495961754											
FORCED INTERR	BA	KM 04	30595	1LJ	6248454	320032880111	F	########	1540	92	24	2208	SQUIRREL	SQUIRREL	72 HARBOR LN	1	LF	1LJ											
FORCED INTERR	CH	CV 06	40456	57GU	5858254	320032880114	F	########	1550	43	70	3010	SQUIRREL	SQUIRREL	13202 FORCE S	1	LF	57GU											
FORCED INTERR	CY	PI 44	21031	T51K	4774002	220032880096	T	########	1600	55	2	110	VINES	VINES	26503 BAYOU TI	1	TF	477400241											
FORCED INTERR	CH	SW 08	41684	MC4	5561751	320032880117	L	########	1600	162	1	162	OH SEC/DR CL H	OH SC CL-H	7402 WILEY RD	1	DR		SC										
FORCED INTERR	CY	KL 46	21013	15VL	4866023	220032880100	T	########	1600	59	2	118	UNKNOWN	UNKNOWN	11934 DEEP WC	1	TF	486602352											
FORCED INTERR	CH	GW 01	40890	HB3	5661552	320032880115	T	########	1600	81	5	405	UNKNOWN	UNKNOWN	8830 NYSSA ST	1	TF	566155217											
FORCED INTERR	MP	NS 01	41537	ER4	5459544	220032880101	T	########	1610	72	12	864	SQUIRREL	SQUIRREL	2613 MILWAUKE	1	TF	545954444											
FORCED INTERR	HC	FD 05	10859	7AR	5053919	120032880152	T	########	1630	48	8	384	BU DISC OR BARI	DISC/BARRL	6030 SANFORD	1	TF	505391974											
FORCED INTERR	SH	CG 06	30207		5753733	320032880126	T	########	1700	176	13	2288	SQUIRREL	SQUIRREL	1007 AVENUE H		BU	575373392											
FORCED INTERR	SH	SB 01	31653	Y86E	5854737	320032880131	F	########	1710	55	34	1870	SQUIRREL	SQUIRREL	2701 PASADENA	2	LF	Y86E											
FORCED INTERR	HC	HOC0	11177	PC7	5151828	320032880162	T	########	1720	93	3	279	BU DISC OR BARI	DISC/BARRL	5326 TRAFALGA	1	TF	515182839											
FORCED INTERR	SH	EL 06	30370	S648	5850032	320032880134	L	########	1720	97	1	97	URD DROPS (CU	URD DR-C/O	11210 SANDWO	2	SC												
FORCED INTERR	HC	HM 04	11026	RD8	5352945	320032880164	T	########	1740	35	11	385	TREE CLEARANC	TREE CLEAF	10413 CATHEDR	1	TF	535294547											
FORCED INTERR	SH	SB 04	31044	I85K	5855620	320032880135	T	########	1740	89	7	623	VINES	VINES	2320 NORMAN S	1	TF	585562008											
FORCED INTERR	GP	AD 04	40070	E90V	5363114	220032880111	L	########	1800	96	1	96	TREE CLEARANC	TREE CLEAF	231 1/2 SPRADS	1	SC												
FORCED INTERR	GP	THW4	20765	56MV	4965737	220032880112	F	########	1811	58	1	58	UNKNOWN	UNKNOWN	HWY249 & W GI	1	LF	56MV											
FORCED INTERR	SL	SE 41	22763	15JG	3351450	120032880167	F	########	1810	224	7	1568	BIRD	BIRD	4653 ORANGE H	1	LF	15JG	PR										
FORCED INTERR	BA	HL 06	41185	29C		320032880137	F	########	1810	46	13	598	UNKNOWN	UNKNOWN	JONES @ MIZEI	1	LF	B16D											
FORCED INTERR	BZ	LJ 03	30620	E39F	5327215	320032880136	T	########	1810	46	8	368	SQUIRREL	SQUIRREL	126 BUTTERCUI	1	TF	532721505											
FORCED INTERR	CH	LY 42	4706C	54ACR	6060402	320032880136	T	########	1820	171	1	171	UNKNOWN	UNKNOWN	16712 SHADY LI	1	TF	606040210											
FORCED INTERR	KY	KT 41	22563	69LA	4258629	120032880166	T	########	1830	47	2	94	BIRD	BIRD	6530 MERT	1	TF	425862966											
FORCED INTERR	KY	WA 42	11337	2L2	3752405	120032880172	T	########	1850	83	2	166	LIGHTNING	LIGHTNING	244 CEMETERY	1	TF	375240514											
FORCED INTERR	BL	BI 44	10128	85AR	5256443	120032880174	T	########	1850	118	6	708	OH PRIMARY CU	OH PR CLAM	2719 JOANBERI ST	1	PD	525644301											
FORCED INTERR	HC	BL 01	10759	39EB	5151520	120032880177	F	########	1920	77	38	2926	COLLISION	COLLISION	CROQUET, S OI	1	LF	39EB											
FORCED INTERR	CY	PI 43	21033		4673617	220032880117	T	########	1940	86	1	86	BU DISC OR BARI	DISC/BARRL	32739 FM 149		TF	467361718											
FORCED INTERR	GP	FR 44	21402	83AD	5163111	220032880121	T	########	2002	98	6	588	UNKNOWN	UNKNOWN	8130 DOWNWO	2	SC	516311116											
FORCED INTERR	SH	DR 03	30271	C43M	5653555	320032880146	F	########	2030	77	7	539	HUMAN ERROR	HUMN ERRC	8505 GLEN VIST	1	PR	C43M											
FORCED INTERR	BL	GT 04	10651	4JF	5356316	120032880185	F	########	2121	150	38	5700	VINES	VINES	1307 BANKS	1	LF	4JF											
FORCED INTERR	FB	RE 06	11470		4449126	220032880188	T	########	2210	62	1	62	OTHER WILDLIFE	OTHER WLD	5414 RIVERWOO		TF	444912684											
FORCED INTERR	SB	DV 03	12696	23KE	5056238	120032880195	F	########	2300	70	4	280	UNKNOWN	UNKNOWN	2302 PINEFIELD	2	LF	23KE											
FORCED INTERR	MP	AN 06	40036	A42Z	5360200	220032880122	F	########	2300	91	37	3367	COLLISION	COLLISION	YALE @ E 37TH	1	LF	A42Z	PR		PD								
FORCED INTERR	HC	BR 08	10514	A65B	5153941	120032890001	T	########	0020	175	7	525	UNKNOWN	UNKNOWN	4610 MC DERME	1	TF	515394140											
FORCED INTERR	SB	WT 05	21852	B32	5158807	120032890002	F	########	0240	162	12	1944	CONTRACTOR-N	CON-NT HLF	505 W LOOP N	1	LF	B32	PR										
FORCED INTERR	HC	FD 03	10843	2JG	5053941	120032890000	T	########	0300	44	12	528	OTHER WILDLIFE	OTHER WLD	6110 VALKEITH	1	TF	505394195											
FORCED INTERR	CY	TB 45	22980	66SQ	4670641	220032890002	T	########	0510	44	2	88	BIRD	BIRD	15920 FM 2920 F	1	TF	467064199											
FORCED INTERR	GP	LK 03	40923	A64F	5261731	220032890000	T	########	0655	52	6	312	TREE CLEARANC	TREE CLEAF	8509 MORROW	1	TF	526173129											
FORCED INTERR	BL	BR 03	10486		5254355	120032890007	L	########	0730	88	1	88	OH SEC/DR CL H	OH SC CL-H	3822 DRUMMON		SC												
FORCED INTERR	FB	CR 45	14885	44SE	4647011	120032890006	F	########	0735	45	1	45	BIRD	BIRD	10302 READING	1	LF	44SE											
FORCED INTERR	MP	LB 04	41269	GZ8	5659128	220032890007	T	########	0740	44	5	220	BIRD	BIRD	3928 HERALD S	1	TF	565912870											
FORCED INTERR	CH	LY 42	4707F	J87A	5962059	320032890006	F	########	0815	65	31	2015	SQUIRREL	SQUIRREL	BERNINA LN W	1	LF	J87A											
FORCED INTERR	CY	HK 42	22255	79HK	4567240	220032890015	T	########	0850	93	2	186	BIRD	BIRD	19600 CYPRESS	1	TF	456724055											
FORCED INTERR	GA	PHR0	31330	24SC	6346250	320032890006	L	########	0855	155	1	155	UNKNOWN	UNKNOWN	1503 1/2 FM 646	1	DR												
FORCED INTERR	MP	BY 09	40201		5360958	220032890017	T	########	0911	35	1	35	SQUIRREL	SQUIRREL	619 BERRY RD		TF	536095614											
FORCED INTERR	SU	BAR44	11853		4754259	120032890016	T	########	0922	108	3	324	FOREIGN MATER	FRGN MATR	14723 EL TESOI		SC	475425987											
FORCED INTERR	HC	HM 05	11032	J22Y	5453426	120032890022	F	########	0955	40	24	960	BU DISC OR BARI	DISC/BARRL	4744 CLOVER S	1	LF	J22Y											
FORCED INTERR	SB	HY 10	21600		4957044	120032890027	T	########	1010	64	6	384	LIGHTNING	LIGHTNING	403 W GAYWOO		TF	495704419											
FORCED INTERR	FB	EB 05	1103A	M103	3347453	120032890026	T	########	1020	105	7	735	CONTRACTOR (H	CON-HLP	430 BROADWAY	1	SC	334745388											
FORCED INTERR	BA	MB 05	3C184	57JK	6763047	320032890015	F	########	1025	51	4	204	BIRD	BIRD	15025 S WOOD(	1	LF	57JK											
FORCED INTERR	SH	SO 43	12703	34FP	5448429	320032890022	F	########	1030	223	69	15387	LIGHTNING	LIGHTNING	2820 MORGAN	2	PR	34FP											
FORCED INTERR	GP	THW4	20778		4965222	220032890022	T	########	1030	115	4	460	OH SEC/DR CL H	OH SC CL-H	9103 FM 1960 W		SC	496522211											
FORCED INTERR	SU	RO 03	12205		4953158	120032890030	T	########	1030	92	1	92	LIGHTNING	LIGHTNING	9227 WILCREST		TF	495315904											
FORCED INTERR	GA	STW0	31001	N503		320032890021	F	########	1030	100	143	14300	UNKNOWN	UNKNOWN	1		PR	58C3											
FORCED INTERR	HC	HOC0	11158	JH2	5253121	120032890033	T	########	1030	59	9	531	SQUIRREL	SQUIRREL	4317 BRIARBEN	1	TF	525312170											
FORCED INTERR	BZ	BZ 02	30135	N98Y	5425043	320032890022	F	########	1040	45	1	45	BU DISC OR BARI	DISC/BARRL	600 BLK COMME	1	LF	N98Y											
FORCED INTERR	BA	LP 07	41715	90QC	6253234	320032890022	F	########	1120	58	4	232	UNKNOWN	UNKNOWN	1300 W FAIRMO	1	LF	90QC											
FORCED INTERR	GV	GV 03	10912	51LG	5553122	120032890037	L	########	1120	41	1	41	OH SEC/DR CL N	OH SC CL-N	5958 BELDART	1	DR												
FORCED INTERR	GA	AL 09	31731	102Z	6143043	320032890023	T	########	1125	204	1	204	UNKNOWN	UNKNOWN	1023 FM 646 N R	1	BU	614304378											
FORCED INTERR	BA	NP 44	42043	60MM	6165800	320032890034	T	########	1230	155	4	620	ELECTRICAL COI	ELECT CON	5419 HIGHWAY	1	BU	616580052	SC		SC								
FORCED INTERR	BL	DN 08	10544	WA4	5357308	120032890046	L	########	1240	55	1	55	HUMAN ERROR	HUMN ERRC	1226 JACKSON	1	DR												
FORCED INTERR	GA	AL 09	30107	I31A	6142324	320032890034	F	########	1240	49	37	1813	SQUIRREL	SQUIRREL	3431 AVENUE J	1	LF	I31A											
FORCED INTERR					5353940	120032890056	L	########	1240	2	1	2	ROTTEN POLE	ROTTEN PLI	3005 BELLFORT		PD												
FORCED INTERR	GP	LU 41	24860	X90A	5168411	220032890047	F	########	1325	46	28	1196	VINES	VINES	17504 PONDER(	2	LF	X90A											
FORCED INTERR	FB	LC 01	11250	L93	3734618	120032890054	T	########	1325	91	2	182	TREE CLEARANC	TREE CLEAF	1439 BERNSTEI	1	TF	373461836											
FORCED INTERR	CH	SW 09	21355	FT5	5563509	320032890041	F	########	1325	88	90	7920	TREE CLEARANC	TREE CLEAF	6110 MICOLLET	1	LF	FT5											
FORCED INTERR	HM	HB 44	20047	15RJ	5866828	220032890046	F	########	1330	86	1	86	UNKNOWN	UNKNOWN	1700 ATASCOCI	1	LF	15RJ											
FORCED INTERR	GP	THW4	28150	S1068	5164030	220032890050	F	########	1330	91	15	1365	TREE CLEARANC	TREE CLEAF	5715 SANDSWE	2	LF	S1068											
FORCED INTERR	GA	GA 07	31211		6738525	320032890044	L	########	1340	66	1	66	COLLISION	COLLISION	5427 BROADWA		MT												
FORCED INTERR	BA	CD 09	40380	I20N	6457317	320032890046	L	########	1400	97	1	97	OH SEC/DR CL H	OH SC CL-H	1515 NARCILLE	1	SC												
FORCED INTERR	SU	STF04	12278	G36Z	4851720	120032890063	F	########	1400	38	38	1444	SQUIRREL	SQUIRREL	2707 HIGHLAND	2	LF	G36Z											
FORCED INTERR	MP	MP 01	41378	93DH	5656045	120032890054	T	########	1410	19	19	BU DISC OR BARI	DISC/BARRL	900 78TH	1	TF	565604833												
FORCED INTERR	RS	AV 02	30057	99GK	5844921	320032890055	F	########	1440	67	9	603	VINES	VINES	2925 MC FARLA	1	LF	99GK											
FORCED INTERR	BL	UL 48	12425		5156436	120032890065	L	########	1510	117	1	117	FLLNG TREE OUT	TREE FL/OE	2806 MC CULLO		DR												
FORCED INTERR	FB	TM 04	12660	92VC	4845412	120032890084	F	########	1520	18	2	36	SLACK SPANS	SLACK SPAI	GUBBELS, S. OI	1	LF	92VC											
FORCED INTERR	BZ	BZ 05	30629	K15W	5225535	320032890067	T	########	1520	48	1	48	BU DISC OR BARI	DISC/BARRL	130 COUNTY RC	1	TF	522553540											
FORCED INTERR	SB	BM 01	21470		4959046	120032890066	L	########	1540	89	1	89	OH SEC/DR CL N	OH SC CL-N	10917 FULLERT		DR												
FORCED INTERR	SU	HY 06	11718	P76W	4856942	120032890091	L	########	1600	122	1	122	CONTRACTOR-N	CON-NT HLF	11410 BRIAR RC	2	DR												
FORCED INTERR	BL	KB 01	10137	U81	5256903	120032890087	T	########	1650	129	24	3096	VINES	VINES	2331 ALBANS S	1	TF	525890340											
FORCED INTERR	GP	LU 44	24464	N64D	5068655	220032890067	F	########	1650	41	14	574	UNKNOWN	UNKNOWN	5211 LACREEK I	1	LF	N64D											
FORCED INTERR	RS	AE 06	30078	4BS	5434958	320032890071	F	########	1730	87	13	1131	UNKNOWN	UNKNOWN	2106 AVENUE K	1	LF	4BS											
FORCED INTERR	CY	PI 43	21118	84JL	4470255	220032890072	T	########	1820	74	1	74	SQUIRREL	SQUIRREL	20411 NEW KEN	1	TF	447025586											
FORCED INTERR	SH	DR 03	30270	1SB	5653349	320032890081	F	########	1850	108	14	1512	UNKNOWN	UNKNOWN	8527 GLENCREI	1	LF	1SB											
FORCED INTERR	GP	FR 42	20728	K28M	4964502	220032890076	F	########	1930	83	8	744	VINES	VINES	9818 FOX RD	1	LF	K28M											
FORCED INTERR	BL	BI 07	1572C	30CT	5255221	120032890115	T	########	2000	202	7	1414	UNKNOWN	UNKNOWN	4143 VILLANOV	1	BU	525522177											
FORCED INTERR	BZ	VL 04	3528C	7PF	5623626	320032890067	L	########	2010	107	1	107	OH SEC/DR CL H	OH SC CL-H	222 SEASHELL I	1	DR												
FORCED INTERR	KY	WA 42	1208J	L97	3965401	120032890126	L	########	2020	11	1	11	HUMAN ERROR	HUMN ERRC	6418 HUNT LN	1	SC												
FORCED INTERR	GP	AD 08	20392	47SD	5364630	220032890081	F	########	2340	67	1	67	UNKNOWN	UNKNOWN	14315 HARDY (I	3	LF	47SD											
FORCED INTERR	HC	AR 42	1563F	Y75C	5148636	120032890136	T	########	2340	299	2	598	UNKNOWN	UNKNOWN	2535 ILLINOIS R	1	BU	514863614											
FORCED INTERR	SH	GG 04	40970	K5G	5554737	320032900001	T	########	0000	119	7	833	VINES	VINES	7311 GILLEN ST	1	TF	555473755											
FORCED INTERR	BL	HE 05	10677	89CT	5357155	120032900001	T	########	0000	61	18	976	CUST EQP RELA	CUST RLTD	4218 WASHING	1	TF	535715549											
FORCED INTERR	BA	BT 04	40115		6357604	320032900001	T	########	0020	134	5	670	COLLISION	COLLISION	609 N PRUETT S		TF	635760468											
FORCED INTERR	SU	QV 01	12161		4949901	120032900003	T	########	0250	403	3	1209	SPLICE	SPLICE	2719 GLENN LA		SC	494990110											
FORCED INTERR	SB	TO 05	28773	P35N	5160711	120032900005	F	########	0330	0	0	0	UNKNOWN	UNKNOWN	4800 LAMONTE	2	LF	P35N	BU	516071346									
FORCED INTERR	SB	TO 05				120032900005	F	########	0330	167	56	9352	UNKNOWN			2	LF	P35N											
FORCED INTERR	SB	TO 05				120032900005	F	########	0330	167	64	10688	UNKNOWN			2	LF	P35N											

REPAIRED NEUTRAL BUSS @ TRANSFORMER DUE TO ALUMINUM #8DUNK USED TO CONNECT COPPER BUSS. RPRD BUSS WORK @ TR. 1 0
REFUSED 37.5 TRANS. REF TR. 1 0
removed many vines to refuse stay need to apply herbicide REF TR. 1 0
REF LF. 1 0
NON 10%. NO R/C EQUIP FOUND "B" PHASE INSULATOR BROKEN @ 18610 SUNBR EDGE...BIG CREW MADE REPAIRS & ALL BACK HOT ON TBL BOB117 BRS 1 1
0 0
0 0
0 0
REPLACED 28 FT SERVICE POLE RPLD PL. RMVD DOWNED PL. 1 0
RE-FUSED TRANSFORMER..... SQUIRREL REF TR. 1 0
FOUND OPEN DELTA BANK WITH BOTH FUSES OPEN, NO 3 PHASE HERE. JUST A BIN OLE PHASE METER. FUSE WAS GOOD. CLOSED LIGHTER THAN BACK IN. JUST FEEDS A FEW LIGHTS ARC 1 0
REF TR. 1 0
REFUSED NORTH PHASE OF LF M23N... TLA 1 0
SEVERAL CSP'S UNCOVERED ON THIS LATERAL. REF LF BJH 1 0
REFUSED LF 59NB 307 @ 13485 LITTLE RANCH. REF LF. MSG SENT TO SC FOR TREE TRIMMING TLA 1 0
TLA 1 0
REPLACE PED LID AND ONE HOT MOLE HEAD. RPRD SEC-1 CUST. RPRD PED. 1 0
REPLACED BAD #4 4 WIRE COPPER DROPS WITH #4 AL 3 C TW / CUSTOMER NO LONG ER USES 3 PHASE / CNUE. RPRD DR; 1 0
REFUSED LINE FUSE..... SQUIRREL. REF LF 1 0
RPLD BU TR. 1 0
repaired broken neutral due to cust trimming tree as it falling on our drop. RPRD DR. 1 0
REFUSED XFMR. SQUIRREL. REF TR; 1 0
FOUND SQUIRREL AT BOTTOM OF CSP AT 67 HARBOR. REF LF 1 0
REF LF 1 0
REF TR. 1 0
RPLD CONN @ WH. RPLD CONN @ PL. 1 0
REFUSED 25 LIGHTER-.. REF TR. 1 0
REF TR. 1 0
REFUSED A 50 KVA 7200 120 240 V TRANSFORMER AND REMOVED VINES OFF OF POLE. REF TR. 1 0
REF TR. 1 0
PLACED SQUIRREL GUARD. RPLD BU TR. 1 0
REF TP 1 0
REF TR. 1 0
MADE REPAIRS TO CUSTOMERS SERVICE DROP. RPRD SEC-1 CUST. 1 0
IN-REAR-10408-CATHEDRAL-NEED-T-TRIMMING-HOLD-EASEMENT RESET TR 1 0
REMOVED VINES OFF POLE. REF TR. 1 0
REPL CONN AT POLE NEED TO TRIM ENTIRE EASMENT. RPLD SEC CONN @ PL-1 CUST 1 0
REF LF 1 0
PICKED UP 1 SPAN OF # 4 AL PRIMARY CONDUCTOR IN A PASTURE WE HAD TO WALK SEVERAL MILES TO LOCATE TROUBLE REFUSED LINE FUSE CAUSE BIRD DROPPINGS ON THE WIRE 1 0
REF LF 1 0
REF TR. 1 0
REF TR. 1 0
Refused trans and replaced k-seals. REF TR. 1 0
REPLACED 12 R MATE UNITER FUSE DUE TOO PAST WEATHER FROM MONDAY NITE PER CUST. REF TR. 1 0
RPLD B/O PRI JUMP-TF HOT BLOWN 1 0
REFUSED MIDDLE PHASE TLA 1 0
RPLD BAD BARREL ON TR. REF TR. 1 0
NEED TO REPAIR SEC 2ND TIME BYPASS HAS BEEN DAMAGED AMP READING IS FOR BYPASS ONLY FEEDS 2 HOUSES INST SEC BYPASS 1 0
REPLACED HOT HOT LINE CLAMP ON LF RPLD B/O PR JUMPER-FUSE HOT BLOWN. 1 0
REF TR. 1 0
REFUSED AND REPLACED FUSE BARREL ON 25 KVA TRANSFORMER 480 V REF TR. RPLD B/U BARREL ON TR. 1 0
REF TP 1 0
REPL 40' 4 POLE WITH THE SAME, TRANSFERED PRI SEC & GUYS SPLICED ON PR. RPLD PL. 1 0
TRIMMED TREES. REPLACED BU FUSE BARREL. REF TR. 1 0
PICKED UP PRIMARY ACROSS 610 LOOP @ MEMORIAL. CONTRACTORS GOT BOOM INTO PRIMARY PAU PR-FUSE BLOWN. REF LF 1 0
BEAT RACCOON OFF TOP OF TF REFUSED TF REF TR. 1 0
REFUSED A 25 KVA OUT BY BIRD. REF TR. 1 0
tire trees release 50 kva. REF TR. 1 0
RPRD SEC CONN @ PL-1 CUST. 1 0
REFUSED LF 44 SE - BIRD . REF LF 1 0
REFUSED 25 CONV REF TR. 1 0
SQUIRREL AT BUTT POLE ON LF J87A BRS 1 0
REFUSED TRANS @ 10622 BANDY HILL CT REF TR. 1 0
INSTALLED DROP REMOVED SOMETIME IN THE PAST AND RESEALED METER. RPLD DR; 1 0
REFUSED 50 CONV ...ON ROAD CLOSED DELTA BANK AT CHURCH. REF TR BJH 1 0
REPL TRANS SEC LUG RPLD CONN @ TR. 1 0
REFURB LF REF LF. 1 0
EASMENT/POWE XSMER LIGHTING ARRES TO NEED REPLACED/ PRIMARY VOLT 7200. REF TR. 1 0
TRACTOR WITH HI MLOAD TORE SECONDARTY & DROPS DOWN--- 4AL 3C TWIST. RPRD CONN @ TR. RPRD SEC-> 1 CUST. RPLD DR. 1 0
REF LF. 1 0
RPLD B/O PR JUMPER-FUSE BLOWN RPLD LIMITER @ TR. RPLD LIGHTNING ARRESTOR BJH 1 0
RPLCD BUSS WORK @ TF TLA 1 0
TRIMMED TREE AND REFUSED 15 KVA - PAST WEATHER AND TREES - NEED MORE TREE TRIMMING AROUND TRANSF - CUST ALSO AS BAD 20 AMP BREAKERS REF TR; RMVD TREE AJMS OF 1 0
PICK

FORCED INTERR	SB	TO 05				120032900000	F	########	033(	367	34	12478	UNKNOWN			2		LF	P35N									0	0
FORCED INTERR	BL	EU 09	10685	B11G		120032900000	F	########	053-	0	0	0	SLACK SPANS	SLACK SPAI	SCHULER, BTW	1		PR	63AR									0	0
FORCED INTERR	BL	EU 09				120032900000	F	########	053-	351	4	1404	SLACK SPANS			1		PR	63AR									0	0
FORCED INTERR	GP	AD 05	20148		52638247	120032900000	T	########	070(	50	1	50	COLLISION	COLLISION	9330 NORTH FV			TF	526382430									1	0
FORCED INTERR	BA	HL 06	41187	B97C	61604154	320032900000	T	########	080(	42	13	546	SQUIRREL	SQUIRREL	308 S MAGNOLI	1		TF	618041592									1	0
FORCED INTERR	MP	AN 02	40006	37G	53603067	220032900000	T	########	082(	35	6	210	BU DISC OR BARI	DISC/BARRL	7415 N MAIN ST	1		TF	536030831									1	0
FORCED INTERR	SB	WT 01	21815	A21	51592022	120032900013	L	########	084(	95	1	95	OH SEC/DR CL HI	OH SC CL-H	1510 JOHANNA	1		DR										1	0
FORCED INTERR	CH	LY 41	3762A	15HR	59634011	320032900011	T	########	084(	38	1	38	SNAKE	SNAKE	15627 GARRETT 1			TF	596340116									1	0
FORCED INTERR	GP	KL 48	21942	50GQ	48665534	220032900011	F	########	090(	50	1	50	COLLISION	COLLISION	14902 JONES RI 1			LF	50GQ									1	0
FORCED INTERR	HC	FD 13	10839	H57Z	50525434	120032900017	F	########	091(	34	19	646	BU DISC OR BARI	DISC/BARRL	7918 DAWNRIDI 2			LF	H57Z									1	0
FORCED INTERR	HM	AT 42	2314E	29LF	61700454	220032900016	F	########	092(	372	1	372	ROTTEN POLE	ROTTEN PLI	2431 WOLF TRC 1			LF	29LF	BU	517004584		PD					1	0
FORCED INTERR	FB	EB 05	11291	K94	35465468	120032900021	T	########	093(	86	1	86	BU DISC OR BARI	DISC/BARRL	20243 COUNTY 1			TF	354654930									1	0
FORCED INTERR	MP	BG 09	40273	34JE	54552446	220032900017	T	########	094(	75	10	750	OH SEC/DR CL HI	OH SC CL-H	3423 ARBOR ST 1			SC	545524499									1	0
FORCED INTERR	SH	SB 01	31653	U34	58547241	320032900018	T	########	095(	43	1	43	O/H PR CLMF	OH PR CLMF	2806 PASADENA 1			TF	585472419									1	0
FORCED INTERR	MP	NS 03	41547	B89L	54581284	220032900016	T	########	095(	43	8	344	BU DISC OR BARI	DISC/BARRL	908 HENRY ST & 1			TF	545812849									1	0
FORCED INTERR	BL	HP 04	40626	RU3	53567532	120032900024	T	########	100(	43	7	301	SQUIRREL	SQUIRREL	3006 BRAZOS S 1			TF	535875328									1	0
FORCED INTERR	HM	RA 42	2D113			220032900023	C	########	100(	3	1316	3948	HUMAN ERROR	HUMN ERRC	RA42 PART CIR			PC	RA42									1	0
FORCED INTERR	HC	IR 03	11067	E89R	51508296	120032900026	T	########	102(	108	4	432	ANTS	ANTS	5307 RIDGEVAN 2			SC	515082951									1	0
FORCED INTERR	SU	IM 48	12067	2E5	47517354	120032900030	T	########	104(	175	1	175	UNKNOWN	UNKNOWN	419 WOOD ST 1			BU	475173589									1	0
FORCED INTERR	CH	SW 09	41699	B77C	55621346	320032900026	T	########	104(	36	4	152	SQUIRREL	SQUIRREL	11127 PERCY RI 1			TF	556213407									1	0
FORCED INTERR	MP	CR 01	40533	G38K	53587502	220032900030	T	########	105(	28	6	168	SQUIRREL	SQUIRREL	708 PECORE ST 1			TF	535875093									1	0
FORCED INTERR	MP	AN 08	40053		53604446	220032900031	T	########	105(	42	6	252	SQUIRREL	SQUIRREL	618 NEST LN			TF	536044462									1	0
FORCED INTERR	RS	AE 06	3007E	C4N	54349368	320032900033	T	########	112(	64	2	128	OH SEC/DR CL HI	OH SC CL-H	2427 GIECKE #1 1			SC	543493687									1	0
FORCED INTERR	FB	BV 42	11372	S65O	45501584	120032900036	F	########	113(	61	60	4860	TREE CLEARANC	TREE CLEAI	423 OLD COLON 2			LF	5450									1	0
FORCED INTERR	GP	LK 07	41299	F30H	52628106	220032900034	F	########	113(	25	1	25	CONTRACTOR-IN	CON-NT HLF	7503 N SHEPHE 3			LF	F30H									1	0
FORCED INTERR	KY	FZ 42	24787	S26M	45594084	120032900035	T	########	113(	186	2	372	CONTRACTOR-IN	CON-NT HLF	2515 CREEK ME 2			TF	455940845									1	0
FORCED INTERR	SB	TO 01	21787	M8T	51563246	120032900042	T	########	113(	36	17	612	BU DISC OR BARI	DISC/BARRL	1824 THONIG RI 1			TF	515932450									1	0
FORCED INTERR	HC	FD 16	10853	4KL	51534216	120032900044	T	########	115(	90	9	810	BU DISC OR BARI	DISC/BARRL	5428 BRIARBEN 1			TF	515342166									1	0
FORCED INTERR	SH	DR 03	30270	1SB	56533471	320032900036	T	########	115(	60	11	660	UNKNOWN	UNKNOWN	7907 GLENHEA 1			TF	565334716									1	0
FORCED INTERR	HC	MV 01	14211	H43F	54456332	120032900050	T	########	123(	53	1	53	BU DISC OR BARI	DISC/BARRL	6915 MASTERS 1			TF	544563245									1	0
FORCED INTERR	BZ	BZ 03	30195	64MC	53260123	320032900047	T	########	124(	36	1	36	BU DISC OR BARI	DISC/BARRL	620 HIGHWAY 3 1			TF	532801271									1	0
FORCED INTERR	GA	PHR01	30869	5M3	65470017	320032900046	L	########	124(	76	1	76	OH SEC/DR CL HI	OH SC CL-N	1404 E BAYSHO 1			DR										1	0
FORCED INTERR	SB	CB 09	21438		48804117	120032900052	F	########	125(	52	6	312	TREE CLEARANC	TREE CLEAI	3031 1/2 KISMET			TF	488041128									1	0
FORCED INTERR	GP	THW4	2A142	49DR	49654302	220032900056	L	########	134(	61	1	61	OH SEC/DR CL NI	OH SC CL-N	12402 ANN LN A 1			SC										1	0
FORCED INTERR	FB	DA 06	11327	75DB	44377266	120032900062	T	########	134(	74	1	74	LIGHTNING	LIGHTNING	18202 DAMON C 1			TF	443772661									1	0
FORCED INTERR	CH	CV 08	40459	E92J	59594037	320032900061	T	########	143(	69	14	966	VINES	VINES	811 CANNA ST 1			TF	595940304									1	0
FORCED INTERR	SH	DR 09	31203	C78L	55529342	320032900063	T	########	143(	72	10	720	VINES	VINES	8818 TEWANTIN 1			TF	555293437									1	0
FORCED INTERR	SU	AF 05	11790		48558200	120032900067	T	########	144(	85	2	170	TREE CLEARANC	TREE CLEAI	4231 AMIR ST			SC	485582031									1	0
FORCED INTERR	SB	TO 04	21778	C66T	51595300	120032900068	L	########	144(	151	1	151	OH SEC/DR CL HI	OH SC CL-H	10826 HEMPSTE 1			SC										1	0
FORCED INTERR	GP	LU 03	20409	16PJ	50869111	220032900066	F	########	145(	37	17	629	SQUIRREL	SQUIRREL	18450 KUYKENI 1			LF	18PJ									1	0
FORCED INTERR	SU	BAR47	11836	U46T	47532596	120032900071	F	########	145(	0	0	0	SPLICE	SPLICE	14827 KNIGHTS 2			LF	U46T	PR								1	0
FORCED INTERR	SU	BAR47				120032900071	F	########	145(	171	52	8892	SPLICE		2			LF	U46T									1	0
FORCED INTERR	SU	BAR47				120032900071	F	########	145(	171	89	11799	SPLICE		2			LF	U46T									1	0
FORCED INTERR	FB	TM 04	10808	28PN		120032900072	F	########	150(	57	5	285	SQUIRREL	SQUIRREL	8735 THOMPSO 1			LF	28PN									1	0
FORCED INTERR	MP	GG 06	10951		55540391	220032900075	L	########	152(	155	1	155	OH SEC/DR CL HI	OH SC CL-H	8022 SOUTHLEA			SC										1	0
FORCED INTERR	SH	SH 06	30917	76LG		320032900067	F	########	152(	79	116	9164	SQUIRREL	SQUIRREL	10280 WINDMILL 1			LF	76LG									1	0
FORCED INTERR	HM	KW 45	22041	52JB	58711055	220032900068	F	########	153(	108	107	11556	FLING TREE OUT	TREE FL/OE	4531 NATURAL 2			LF	52JB									1	0
FORCED INTERR	BL	DN 02	10567		53573287	120032900077	T	########	154(	64	1	64	VINES	VINES	2620 W DALLAS			TF	535732879									1	0
FORCED INTERR	SH	TE 06	31060	C8P	55503396	320032900066	T	########	154(	96	4	384	SQUIRREL	SQUIRREL	12546 MIDLANE 1			TF	555033905									1	0
FORCED INTERR	CH	LB 02	41257	GWB	56590554	320032900067	T	########	160(	177	11	1947	BU DISC OR BARI	DISC/BARRL	7965 SPARTA S 1			TF	565905543									1	0
FORCED INTERR	GA	GA 10	30024	1WE	67372373	320032900071	L	########	160(	121	1	121	OH SEC/DR CL NI	OH SC CL-N	7001 SYCAMOR 1			SC										1	0
FORCED INTERR	CH	AD 08	40088	E5SX	54626475	320032900074	L	########	161(	120	1	120	FALLING DEAD TI	TR FL/DEAD	11229 BENTLEY 1			DR										1	0
FORCED INTERR	FB	WA 41	10192	7N1	36532154	120032900075	F	########	162(	193	1	193	BIRD	BIRD	20548 HWY 36A 1			LF	7N1									1	0
FORCED INTERR	RS	AE 06	3536C	C41	56343275	320032900076	T	########	163-	75	2	150	OH SEC/DR CL HI	OH SC CL-H	1615 LAKE 1			TF	563432755	SC								1	0
FORCED INTERR	SB	DV 03	21719	E29	50572042	120032900082	F	########	163(	98	5	490	UNKNOWN	UNKNOWN	11612 MEMORIA 1			LF	E29									1	0
FORCED INTERR	GA	STW0	3549C	70BA	62311143	320032900077	T	########	163(	186	3	498	BU DISC OR BARI	DISC/BARRL	3902 BRIDGE HV 2			TF	623114335									1	0
FORCED INTERR	GP	KL 42	23010	S3590	48667117	220032900077	F	########	164(	171	11	1881	URD BUSHING	URD BSHING	10830 NORCHES 2			LF	S3590	SC	486671174							1	0
FORCED INTERR	BL	BR 03	10486		52543551	120032900083	L	########	165(	42	1	42	OH SEC/DR CL HI	OH SC CL-H	3835 MERRICK 1			DR										1	0
FORCED INTERR	HC	HOC0	12958	6DS	52522165	120032900085	F	########	171(	51	18	918	OH SEC/DR CL HI	OH SC CL-H	13310 GLENWY 1			LF	6DS									1	0
FORCED INTERR	HC	BR 13	10521		51547074	120032900085	T	########	174(	70	10	700	SQUIRREL	SQUIRREL	4861 BRAESHEA			TF	515470740									1	0
FORCED INTERR	KY	FZ 46	12031		45592514	220032900096	T	########	175(	60	9	720	TREE CLEARANC	TREE CLEAI	3851 LAUDERW			TF	455925164									1	0
FORCED INTERR	HC	HOC0	11178	27B	51518525	120032900091	T	########	175(	31	3	93	TREE CLEARANC	TREE CLEAI	5358 GLEN RIO 1			TF	515185257									1	0
FORCED INTERR	GA	GA 05	31202	H63X	67375434	320032900081	F	########	175(	50	29	1450	O/H PRIMARY CU	OH PR CLMF	2600 59TH 1			LF	H63X									1	0
FORCED INTERR	RS	AE 06	3536C	C41	56343275	320032900082	T	########	175(	53	2	106	UNKNOWN	UNKNOWN	1615 LAKE 1			BU	563432755									1	0
FORCED INTERR	FB	NV 01	11207	3DX	43440234	120032900095	F	########	184(	118	18	2088	BIRD	BIRD	5507 SADDLE DI 1			LF	3DX									1	0
FORCED INTERR	SU	WZ 43	12341		49541524	120032900097	T	########	190(	104	1	104	UNKNOWN	UNKNOWN	10921 2/3 BELLA			TF	495415249									1	0
FORCED INTERR	CH	BY 04	40181	75F	54627000	320032900086	T	########	191(	22	10	220	BU DISC OR BARI	DISC/BARRL	3313 1/2 MARZE 1			TF	546270002									1	0
FORCED INTERR	SH	HA 06	30567	P69D	57506000	320032900088	F	########	192(	0	0	0	UNKNOWN	UNKNOWN	11519 SAGEKIN 2			LF	P69D	PR								1	0
FORCED INTERR	SH	HA 06				320032900088	F	########	192(	266	30	7980	UNKNOWN		2			LF	P69D									1	0
FORCED INTERR	BZ	LJ 07	30843	U49J	53275511	320032900091	L	########	193(	42	1	42	OH SEC/DR CL HI	OH SC CL-H	238 SCHLEY ST 1			DR										1	0
FORCED INTERR	BA	FT 01	31352	62BF	61534355	320032900092	F	########	195(	38	16	608	OTHER WILDLIFE	OTHER WLC	10850 MESQUIT 2			LF	62BF									1	0
FORCED INTERR	GA	AL 09	3109A	C92Z	60444100	320032900094	T	########	202(	375	4	1500	UNKNOWN	UNKNOWN	3526 E MEADOV 1			BU	604441039									1	0
FORCED INTERR	SU	WZ 44	12360	P38T	48568121	120032900106	F	########	212(	0	0	0	URD ELBOW	URD ELBOW	9797 MEADOWC 2			LF	P38T	PR								1	0
FORCED INTERR	SU	WZ 44				120032900106	F	########	212(	215	156	33540	URD ELBOW		2			LF	P38T									1	0
FORCED INTERR	SU	WZ 44				120032900106	F	########	212(	215	51	10965	URD ELBOW		2			LF	P38T									1	0
FORCED INTERR	HM	AD 10	41977	JU6	54640151	220032900084	T	########	215(	151	5	755	OH SEC/DR CL HI	OH SC CL-H	1618 STRAWN R 1			SC	546401514									1	0
FORCED INTERR	CH	SW 10	41701		55635134	320032900107	T	########	221(	47	1	47	UNKNOWN	UNKNOWN	11658 HOMESTI			TF	556351383									1	0
FORCED INTERR	MP	CL 04	40476	M47K	55576432	220032900086	F	########	234(	97	1	97	BU DISC OR BARI	DISC/BARRL	1520 LATHROP 3			DB	M47K									1	0
FORCED INTERR	GA	KM 05	41205	68CS	62507375	320032910001	F	########	004(	189	29	5481	VINES	VINES	4321 SPOONBIL 2			LF	68CS									1	0
FORCED INTERR	SH	FT 02				320032910002	C	########	010(	0	0	0	COLLISION	COLLISION	SPENCER @ LU			CL	FT02	PD								1	0
FORCED INTERR	SH	FT 02	3G085			320032910002	C	########	010(	70	210	14700	COLLISION					CL	FT02									1	0
FORCED INTERR	SH	FT 02	30384			320032910002	C	########	010(	92	707	65044	COLLISION					CL	FT02									1	0
FORCED INTERR	SH	FT 02	30383			320032910002	C	########	010(	197	56	11032	COLLISION					CL	FT02									1	0
FORCED INTERR	GA	STW0	3549B	Z3FH	60298424	320032910004	T	########	011(	244	1	244	BU DISC OR BARI	DISC/BARRL	35930 SAN LUIS 1			TF	602964261									1	0
FORCED INTERR	BL	DV 05	10600	I38B	50567445	120032910002	F	########	025(	0	0	0	PRIMARY CONDU	PRIMARY	2206 FULHAM C 2			LF	I38B	PR								1	0
FORCED INTERR	BL	DV 05				120032910002	F	########	025(	276	63	17388	PRIMARY CONDU		2			LF	I38B									1	0
FORCED INTERR	SB	CB 06	21441		50603015	120032910004	T	########	030(	86	5	430	UNKNOWN	UNKNOWN	3307 THEYSEN 1			TF	508030199									1	0
FORCED INTERR	KY	MAR4	24858	14LR	45578501	120032910005	F	########	030(	158	57	9006	URD BUSHING	URD BSHING	902 CHINNI CT 2			LF	14LR	PR								1	0
FORCED INTERR	GP	LK 10	40802	14AH		220032910004	F	########	032(	143	155	22185	COLLISION	COLLISION	3500 W LITTLE 1			LF	14AH									1	0
FORCED INTERR	CY	KL 45	2F129	S3630	48652028	220032910007	T	########	045(	135	2	270	OTHER WILDLIFE	OTHER WLC	11911 BEXHILL 1			TF	486520283									1	0
FORCED INTERR	BL	GT 06	40849	7HZ	53566336	120032910012	T	########	070(	68	7	476	UNKNOWN	UNKNOWN	401 RICHMOND 1			TF	535663369									1	0
FORCED INTERR	SU	AF 03	11798	M60P	48543331	120032910015	F	########	072(	70	41	2870	VINES	VINES	12722 VILLAWO 2			LF	M60P									1	0
FORCED INTERR	CH	GW 01	40890	CU2		320032910027	F	########	074(	76	44	3344	VINES	VINES	9430 MADERA 1			LF	CU2									1	0
FORCED INTERR	MP	WV 03	41812	S3ABK	55584422	220032910006	T	########	075(	49	11	539	SQUIRREL	SQUIRREL	131 HAHLO ST 1			TF	555844277									1	0
FORCED INTERR	SU	CE 06	12025		47535402	120032910016	T	########	075(	81	4	324	UNKNOWN	UNKNOWN	14503 SWANFIE 1			TF	475354032									1	0
FORCED INTERR	KY	KT 43	22626	58CL	39579532	120032910017	T	########	081(	115	8	920	TREE CLEARANC	TREE CLEAI	529 VILLAGE W 1			TF	395795355									1	0
FORCED INTERR	BL	ST 01	10246	UR6	51545151	120032910022	T	########	081(	69	10	690	SQUIRREL	SQUIRREL	5203 JASON ST 1			TF	515451575									1	0
FORCED INTERR	SU	WW 02	12405	5TM	48549261	120032910022	F	########	082(	129	90	11610	UNKNOWN	UNKNOWN	8110 LA ROCHE 1			PR	5TM									1	0
FORCED INTERR	BA	AI 07	41148	78SM	61554355	320032910033	F	########	082(	89	1	89	BIRD	BIRD	10900 STRANG 1			LF	78SM									1	0
FORCED INTERR	SH	HA 05	31823	F22E	57505291	320032910036	F	########	082(	41	31	1271	SQUIRREL	SQUIRREL	11318 SAGETRA 2			LF	F22E									1	0
FORCED INTERR	MP	AN 01	40001	62LK	53604136	220032910011	T	########	083-	44	12	528	VINES	VINES	815 E 42ND 1			TF	536041309									1	0
FORCED INTERR	BL	ST 01	10194	F46C	51543246	120032910027	T	########	083(	77	10	770	SQUIRREL	SQUIRREL	5422 INDIGO ST 1			TF	515432453									1	0
FORCED INTERR	BL	GN 06	10627	F86C	52558143	120032910022	F	########	085(	75	1	75	CUST EQP RELA	CUST RLTD	6802 KIRBY DR 1			TF	525581473									1	0
FORCED INTERR	SH	SB 01	31030	I14K	58558011	320032910036	T	########	090(	70	2	140	UNKNOWN	UNKNOWN	1107 PRESTON 1			SC	585580192									1	0
FORCED INTERR	CY	HK 04				220032910013	C	########	090(	0	0	0	CAPACITOR	CAPACITOR	B/U CAP BANK			CL	HK04									1	0
FORCED INTERR	CY	HK 04	21140			220032910013	C	########	090(	8	645	3870	CAPACITOR					CL	HK04									1	0
FORCED INTERR	CY	HK 04	20963			220032910013	C	########	090(	32	220	7040	CAPACITOR					CL	HK04									1	0
FORCED INTERR	CY	HK 04	21137			220032910013	C	########	090(	36	134	4824	CAPACITOR					CL	HK04									1	0
FORCED INTERR	BZ	LJ 02	30819	G1T	54260528	320032910040	T	########	091(	38	4	152	SQUIRREL	SQUIRREL	852 YAUPON ST 1			TF	542605251									1	0
FORCED INTERR	SH	WE 08	31319	GF3	58554242	320032910042	T	########	092(	25	1	25	OTHER WILDLIFE	OTHER WLC	1611 RED BLUFI 1			TF	585542475									1	0
FORCED INTERR	SH	SH 04	30910	A71S	57515332	320032910043	T	########	093(	46	8	368	SQUIRREL	SQUIRREL	10430 SOUTHPO 1			TF	575153257									1	0
FORCED INTERR	SU	JN 01	10001	W84A	49558076	120032910043	T	########	095(	43	9	387	BU DISC OR BARI	DISC/BARRL	8880 BELLAIRE 1			TF	495580768									1	0
FORCED INTERR	HC	MC 03	11102	M60C	50503591	120032910031	F	########	095(	64	28	1792	SQUIRREL	SQUIRREL	1306 TWINING C 2			LF	M60C									1	0
FORCED INTERR	MP	HR 01	41029	M1W	54590406	220032910031	T	########	100(	63	6	378	SQUIRREL	SQUIRREL	407 AVENUE OF 1			TF	545904068									1	0
FORCED INTERR	BZ	VL 04	35260	E81F	57242102	320032910041	T	########	100(	53	2	106	STRONG WIND	WIND	107 NESMITH PI 1			TF	572421028									1	0
FORCED INTERR	RS	AV 03	3505A	3NK	56420233	320032910046	T	########	101(	59	2	118	SQUIRREL	SQUIRREL	3603 COUNTY R 1			TF	564202324									1	0

MADE REPAIRS TO URD PRI INSIDE THE PVC PIPE.REFUSED TP 63 AR 861 , RPRD URD PR.

TRUCK BACK INTO POLE SLAPPING PRIMARY TOGETHER BLOWING TR FUSES... BRS

OUT BY SQUIRREL ON 60 CONV ..... NO WILDLIFE PROTECTION NEEDED. REF TR.

TRIMMED TREES / REPLACED FUSE BARREL / LEFT SERV ON / NOTIFIED. RPLD BAU BARREL ON TR. RMVD TREE/LIMB OFF PR.

BAD CONNECTION AT WEATHERHEAD/REPLACED ALL LEFT ON; RPLD CONN @ WH.

REFUSED 25 CONV ..... SNAKE. REF TR.

NEED TO REPLACE 12" ANCHOR ON DOUBLE DE POLE. TRX RUN OVER ANCHOR LOCATED AT LIF POLE. ANCHOR FOR 600 MCM DE. REF LF

REPLACED A BURNED-UP FUSE BARREL ON THE T P.. RPLD BAU BARREL ON TP.

REPL ROTTEN 40 FOOT POLE WITH 40 FOOT POLE . REPL 25 KVA 7200/120/240 CONV WITH THE SAME SIZE . REPL BROKEN 12 KV SWITCH. REF LF. RPLD BAU TR. RPLD BAU DISC-TF BLOWN. R

REPL. BAD FUSE BARREL ON TR. & CUT VINES ON 2 POLES. RPLD BAU BARREL ON TR.

MADE REPAIRS TO BUSSWORK ON POWER TRANS IN OPEN DELTA BANK. RPRD BUSS WORK @ TR.

FUSE FELL OF ON 75 KVA TRF OLD BACK IN FUSE WAS NOT BLOWN. REF TR.

REF TR.

OUT BY SQUIRREL TR ALREADY HAS WIL PROT NEED TO REROUTE BOND WIRE FROM DISC OR INSTALL WFF ARM FOR DISC. SQUIRRELS GETTING BETWEEN POLE BOND & DISC CAUSING (

SWITCHING ERROR.WPS

REPLACED X-2 BUSHING IN URD PADMOUNT & SPLICED 2 NEUTRAL DROPS. RPLD BUSS WORK @ TR.

replaced 60 hrs 7200--120/240 with the same. RPLD BAU TR.

REFUSED 25 LIGHTER--A1--WLP INSTALLED. REF TR.

50 TR. REF TR.

REF TR.

REPLACED BAD NEUTRAL CLAMP AT TRANS; RPLD CONN @ TR.

TRIMMED BANANA TREE ON 1 END OF LOOP - (#860) - AND REFUSED TP #860 NEED TO TRIM TREE AWAY FROM TP #860 AND DO MORE EXTENSIVE TRIMMING ON BANANA TREE ON 1 END

REFUSED East & Mid Phs OF LF 7304--407--CONTRACTOR DIGGING & PULLING CABLE BURIED POLE--FRESH SCRAPE MARKS @ BUTT--NO OWNED UP TO IT. REF LF

RESET URD TRAN . RAN BY-PASS ON CUST URD DROPS TIME WANNER CUT CUST URD DROPS TRIPPED TRAN., RESET TR.

REPLACED FUSE BARREL ON TRANSFORMER. RPLD BAU BARREL ON TR.

bad barrel was on power side! In open delta bank. RPLD BAU BARREL ON TR.

REF TR.

REFUSE TRAN. REF TR. RPLD BAU BARREL ON TR. BJH

REFUSED 50 CONV TRANS , REF TR.

RPRD DR.

REFUSED 50 KVA 277/480 BACK ON NO ACCESS TO CHECK VOLTAGE. REF TR.

TRIMMED TREES & MADE REPAIRS TO BROKE NEUTRAL ON DROPS @ POLE LEFT SERV ON / NOTIFIED. RPLD CONN @ PL.

NEED 2 REPL LIN ON TR-TR LOCATED OFF RID NEEDS TO DRY UP BEFORE I CAN GET. 2 POLE--PL HAS 3 PHASE WY-RUNNING UNDER P-VINE 7280-ABOUT 1 MILE WEST OF WHERE 6TH ST RI

REFUSED TRANSFORMER- CLEARED VINES FOR TOP OF POLE THE BEST I COULD. - ALSO CUT VINES AT BOTTOM OF POLE. REF TR.

REMOVED VINES. REF TR.

MADE REPAIRS TO XFMR LEAD LEFT ON AND WORKING CUST NOTIFIED TREES. RPRD BUSS WORK @ TR.

REPL CLAMPS MID SPAN. RPLD CONN @ PL.

REF LF.

RESTORED ON SWITCH ORDER # 2182 WITH HELP FROM TRUCK 2861 NEED TO REPLACE 1 SPAN 16 8 PRIMARY ISOLATET BETWEEN TR # 31 & TR # 30 11627 & 11811 CHARLMONT PRIMARY

REF LF

RPLD REC CONN @ PL-1 CUST

REF TP

CLOSED BARREL. LOOKS LIKE LIMB FELL AND OPENED BARREL FUSE WASN'T BLOWN. REF TP

REFUSED MID X-FMER DUE TO VINES. REF TR.

REF TR.

REF TR.

RPLD CONN @ PL.

RPRD CONN @ WH. PAU DR. RPLD POA.

REF LF.

REF TR. RPLD CONN @ TR.

REF LF.

RPLD BAU BARREL ON TR.

URD SWO 2186. MADE REPAIRS TO PRIMARY CONN ON LIVE FRONT TRANS #1. REF TP. RPLD CONN @ TR.

RPLD CONN @ WH.

REPLACE-P

FORCED INTERR	BA	HL 03	4759A	97DN	6158849	320032910045	T	########	1031	40	6	240	SQUIRREL	SQUIRREL	124 N HOLLY DF	1	TF	615884950									REMOVED VINES OFF POLE & REFUSED TR., REF TR.	1	0
FORCED INTERR	BL	FD 09	10701	I79X	5053642	320032910037	F	########	103	113	11	1243	SQUIRREL	SQUIRREL	7855 S BRAESW	2	LF	I79X	DB		TF	505					MADE REPAIRS TO A DISCONNECT MADED REPAIRS TO TRANSF PRIMARY BUSHING REPLACED BARREL IN DISCONNECT ADDED WILD LIFE PROTECTION. RPLD BAJ DISC-LF BLOWN. REF T	1	0
FORCED INTERR	MP	GG 06	10951		5554039	320032910036	L	########	103	72	1	72	UNKNOWN	UNKNOWN	6022 SOUTHLEA		SC										REPLACED CLAMP AT POLE. RPLD CONN @ PL.	1	0
FORCED INTERR	SU	WW 0	12407	S10L	4954513	320032910042	F	########	104	0	0	0	PRIMARY CONDU	PRIMARY	10222 PEBBLE F	2	LF	S10L	PR								BAD PRIMARY AT 10222 PEBBLE PARK MARKED #POT WITH RED PAINT #BOL URD PR. S/O#2166 GOM	0	0
FORCED INTERR	SU	WW 0				320032910042	F	########	104	118	28	3304	PRIMARY CONDU			2	LF	S10L										0	0
FORCED INTERR	SB	EU 06	40733	71HS	5258127	320032910044	T	########	105	155	1	155	UNKNOWN	UNKNOWN	7019 OLD KATY	1	BU	525812777									REPL 50 KVA 7200 120/240 POWER TRAN. IN CL. DELTA BANK. RPLD BAJ TR.	1	0
FORCED INTERR	GP	RU 05	41674	C63G	5362234	320032910036	L	########	110	182	1	182	TREE CLEARANC	TREE CLEAR	210 BELLMAR D	1	DR										MADE REPAIRS TO 64 DROPS MID SPAN. RPRD DR.	1	0
FORCED INTERR	BL	HE 08	41118	NU7	5258646	320032910040	T	########	110	29	9	261	SQUIRREL	SQUIRREL	1007 BAY OAKS	1	TF	525884688									REFUSED 25 KVA XFMR / SQUIRREL ON SEC BUSHINGS / HAS WILDLIFE PROTECTION HAVE AN ABANDONED 10 INCH ANCHOR BEHIND GARAGE OF 1007 BAY OAKS. REF TR.	1	0
FORCED INTERR	BZ	LJ 01	30611	R61T	5227755	320032910050	T	########	111	41	9	369	SQUIRREL	SQUIRREL	102 DAHLIA	1	LF	R61T									REFUSED LF R-41-T 66-T. REF LF	1	0
FORCED INTERR	SH	DE 03	30058	38LT	6054010	320032910051	F	########	113	68	7	476	BU DISC OR BARI	DISC/BARRL	4120 CENTER S	1	TF	605401067									RPLD BAJ BARREL ON TR.	1	0
FORCED INTERR	BL	KB 06	10157		5256830	320032910051	T	########	1311	49	1	49	BU DISC OR BARI	DISC/BARRL	3002 KIRBY DR		TF	525683038									RPLCD BURNED UP FUSE BARREL ON POWER POT	1	0
FORCED INTERR	SU	AF 03	12363	95DK	4854427	320032910053	F	########	132	0	0	0	COLLISION	COLLISION	6000 COOK BLD	2	LF	95DK	BU	485442844							REPLACED 75 KVA XFMR 7200-120/240 WITH SAME COLLISION LEFT ON AND WORKING. RPLD BAJ TR.	1	0
FORCED INTERR	SU	AF 03				320032910053	F	########	132	44	43	1892	COLLISION			2	LF	95DK										0	0
FORCED INTERR	SU	AF 03				320032910053	F	########	132	143	21	3003	COLLISION			2	LF	95DK										0	0
FORCED INTERR.	GA	GL 06	30491	S1H	6838851	320032910056	L	########	1341	114	1	114	FOREIGN MATER	FRGN MATR	918 AVENUE M	1	DR										REPLACED CONN AT WATHER HEAD. RPLD CONN @ WH.	1	0
FORCED INTERR	BA	LP 02	41866	T2B	6252652	320032910056	L	########	1346	145	1	145	OH SEC/DR CL H	OH SC CL-H	5 BAY HARBOR	1	DR										REPL 8H DROPS W 140 DROPS. RPLD DR.	1	0
FORCED INTERR	BZ	VL 04	35260	95X	5623739	320032910060	F	########	1425	89	8	552	STRONG WIND	WIND	203 FRANCIS C	1	LF	95X	PR								PICKED UP 1-SPAN IN AL. PRIMARY. PU PR-FUSE BLOWN.	1	0
FORCED INTERR	SH	TE 05	31091	S77W	5652409	320032910061	T	########	1430	26	1	26	UNKNOWN	UNKNOWN	8302 ALMEDA G	1	TF	565240962									FUSE PULLED INTO. REF TR.	1	0
FORCED INTERR	SU	WZ 43	12341	B63Z	4954152	320032910056	T	########	1431	184	1	184	BIRD	BIRD	10921 2/3 BELLA	1	TF	495415249									REFUSED STEP POT OUT BY BIRDS ALL OVER PRI DOWN THE LINE 1 GOT ON STEEL ARM TOOK OUT LIF. REF TR.	1	0
FORCED INTERR	FB	RS 02	11395	M7E	4348822	320032910056	F	########	1434	47	21	987	SQUIRREL	SQUIRREL	1315 AUSTIN ST	1	LF	M7E									REF LF	1	0
FORCED INTERR	SH	PE 03	31590	M18S	5550224	320032910068	T	########	1610	186	1	186	UNKNOWN	UNKNOWN	5741 COUNTY R	1	BU	555022463									RPLD BAJ TR.	1	0
FORCED INTERR	SH	SP 02	30973	23EH	5854120	320032910070	F	########	1612	54	22	1188	SQUIRREL	SQUIRREL	801 ARMOR	1	LF	23EH									REF LF.	1	0
FORCED INTERR.	KY	KT 04	22578	82GN	4058113	320032910080	T	########	1614	30	3	90	SQUIRREL	SQUIRREL	3128 2ND	1	TF	405811395									REF TR.	1	0
FORCED INTERR	HC	HOCO	11150	33VA	5251430	320032910067	T	########	1617	83	2	166	OH SEC/DR CL H	OH SC CL-H	4207 SIMSBROC	1	SC	525143059									RPRD BUSS WORK @ TR.	1	0
FORCED INTERR	SH	SB 04	31044		5855520	320032910071	T	########	1625	46	4	184	SQUIRREL	SQUIRREL	2103 CAMILLE S	1	TF	585552054									REF TR.	1	0
FORCED INTERR	SH	SB 04	31044		5855429	320032910076	T	########	1642	25	6	150	SQUIRREL	SQUIRREL	2106 RAYMOND	1	TF	585542914									REF TR.	1	0
FORCED INTERR	CY	KL 46	22422	32BL	4865359	320032910061	F	########	1715	95	35	3325	URD ELBOW	URD ELBOW	11300 REGENC	2	LF	32BL	PR								REPL. BAD ELBOW & BUSHING ON 100KVA 18 8/240/120 L.B. TRAN. TRAN. # 13. REFUSED T.P. 32BL 40T. B.O. # 21180 , REF TP. RPLD TR BUSH. RPLD ELBOW @ TR.	1	0
FORCED INTERR	SH	MY 02	30044	K86F	5749402	320032910082	F	########	1730	51	20	1020	TREE CLEARANC	TREE CLEAR	1918 SLEEPY HI	1	LF	K86F									TREES NEED TRIMMING BEHIND LINE FUSE BADLY. REF LF	1	0
FORCED INTERR	FB	OB 44	13231	61TA	4652924	320032910077	T	########	1734	34	1	34	SQUIRREL	SQUIRREL	11627 FM 1464	1	TF	465282422									REF TR.	1	0
FORCED INTERR	CH	PW 01	40434		5761805	320032910084	T	########	1740	93	4	372	TREE CLEARANC	TREE CLEAR	12637 GREEN R		TF	576180518									REFUSED 50 CONV.-OUT BY LIMB--TRIMMED TREES. REF TR. CORRECTED ON DATE /CRH	1	0
FORCED INTERR	BZ	BZ 06	31466	X83K	5325259	320032910086	F	########	1828	36	27	972	BIRD	BIRD	915 HWY 332W	1	LF	X83K	TF	532525918						REF LF. REF TR.	1	0
FORCED INTERR	SH	SP 05	30952	9LY	5854231	320032910087	T	########	1835	29	7	203	SQUIRREL	SQUIRREL	1102 GARNER R	1	TF	585423104									REF TR.	1	0
FORCED INTERR	MP	BG 06	40267	P32	5455432	320032910085	F	########	1846	100	35	3500	UNKNOWN	UNKNOWN	3845 PALM ST	1	LF	P32									REFUSED SINGLE PH LF. REF LF	1	0
FORCED INTERR	BA	BT 07	31518		6258639	320032910086	T	########	1902	30	3	90	UNKNOWN	UNKNOWN	4503 SAGE CIR		TF	625863950									REF TR.	1	0
FORCED INTERR	GA	KM 06	3100A	44ABF	6347428	320032910096	T	########	1913	102	3	306	TREE CLEARANC	TREE CLEAR	4229 COVERT S	1	TF	634742889									TRIMMED TREES AROUND DISC. REF TR.	1	0
FORCED INTERR	BL	FD 07	10694	8KP	5053533	320032910084	F	########	2040	98	28	2688	O/H PRIMARY CL	OH PR CUMF	7802 TWIN HILL	1	PR	8KP									RPRD B/O PR JUMPER-FUSE NOT BLOWN.	1	0
FORCED INTERR	BL	FD 07	10697		5054418	320032910085	T	########	2055	38	14	532	OTHER WILDLIFE	OTHER WLC	7800 BISSONNE		TF	505441860									REFUSED A 1 & 2 RATHER LARGE DEAD RAT. REF TR.	1	0
FORCED INTERR	BZ	LJ 07	30952	X15K	5332952	320032910087	T	########	2122	46	1	46	BU DISC OR BARI	DISC/BARRL	2023 OAKWOOD	1	TF	532892528									RPLD BAJ BARREL ON TR.	1	0
FORCED INTERR	GA	GL 10	31828	J7K	6839523	320032910096	F	########	2304	67	4	268	BU DISC OR BARI	DISC/BARRL	AVE A @ 15TH	1	LF	J7K	DB								RPLD BAJ DISC-LF BLOWN	1	0
FORCED INTERR	SH	DE 05	30240	P16U	5954450	320032910097	F	########	2311	35	35	1225	BU DISC OR BARI	DISC/BARRL	4147 BERMUDA	2	LF	P16U									AGE. RPLD BAJ BARREL ON TP	1	0
FORCED INTERR	GA	AL 10	30043	I61A	6141212	320032910096	T	########	2355	89	8	712	OTHER WILDLIFE	OTHER WLC	12130 24TH	1	TF	614121236									POSSUM THE ANT NO CITY RATE. REF TR.	1	0
FORCED INTERR	SH	FT 02	30398	B64L	5954914	320032920002	T	########	0225	56	11	616	UNKNOWN	UNKNOWN	4314 DURANT S	1	TF	595491451									REF TR.	1	0
FORCED INTERR	SH	GV 06	30539	JP7	5553441	320032920002	T	########	0446	116	6	696	OH SEC/DR CL H	OH SC CL-H	6515 BELARBOF	1	SC	555344163									REPLACED BUSS WORK ON TRANSFORMER. BAS	1	0
FORCED INTERR	SB	TO 05	21804	E44	5180325	320032920004	T	########	0700	50	8	400	OTHER EQUIPME	FUSE BROKI	4102 HILL OAK	1	TF	518032386									MAM	1	0
FORCED INTERR	MP	WO 05	41837	S05	5260430	320032920004	T	########	0723	52	12	624	SQUIRREL	SQUIRREL	1239 CHESHIRE	1	TF	526043058									MOBIL DATA NOT WORKING. BECKETT NOTIFIED. REFUSED TF. MAM	1	0
FORCED INTERR	SH	PA 07	30793	40HD	5753951	320032920000	T	########	0728	103	7	721	SQUIRREL	SQUIRREL	1537 CHRISTA L	1	TF	575395119									REF TR.	1	0
FORCED INTERR	MP	CL 03	40474		5558729	320032920000	T	########	0741	103	17	1751	UNKNOWN/FORMER	TRANSFRMR	7421 DENISON	1	TF	555872919									REF TRF AND MADE REPAIRS TO PHONE CABLE. CAC	1	0
FORCED INTERR	FB	WA 43	12943	S3770		320032920008	F	########	0800	104	18	1872	TREE CLEARANC	TREE CLEAR	1616 LONG LN	1	LF	86TG	PR								PICK UP PRIMARY @ 9736 JOHNSON. REF LF	1	0
FORCED INTERR	GA	PHRO	31303	7M9	6347423	320032920006	T	########	0813	73	9	657	UNKNOWN	UNKNOWN	4304 10TH	1	TF	634742322									REF TR.	1	0
FORCED INTERR	SH	SH 05	30915	30A	5652945	320032920008	F	########	0822	52	14	728	TREE CLEARANC	TREE CLEAR	8723 EASTHAVE	1	LF	30A									REFUSED EAST PHASE OF LF 30A--TRIMMED TREES. CAC	1	0
FORCED INTERR	HC	AR 43	10942	W76S	5146851	320032920007	F	########	0833	69	4	276	BIRD	BIRD	13100 HWY 6	1	LF	W76S	TF	514685192							REFUSED TRANSF AND LINE FUSE. REF LF. REF TR.	1	0
FORCED INTERR.	HM	AT 42	2386A		6069404	320032920013	T	########	0900	64	1	64	VINES	VINES	12111 TWIN OAI		TF	609940438									REMOVED VINES. REF TR.	1	0
FORCED INTERR	SH	CC 03	31661	S96N	5451658	320032920017	T	########	0908	89	12	1068	URD SEC PDSTL	URD SC PEE	12823 REDFERN	2	SC	545165892									RPLD SEC CONN @ PED->1 CUST	1	0
FORCED INTERR	HC	CC 02	30179	81L	5452339	320032920017	T	########	0924	90	6	540	SQUIRREL	SQUIRREL	10907 DUANE S	1	TF	545233985									REF TR.	1	0
FORCED INTERR	KY	KT 43	11577	J86X	3859825	320032920017	T	########	0930	63	1	63	SQUIRREL	SQUIRREL	3304 AVENUE I	1	TF	385962597									noted arki tile per. REF TR.	1	0
FORCED INTERR	GP	NB 43	20263	U39N	5365135	320032920015	F	########	0933	0	0	0	SQUIRREL	SPLICE	770 GREENS BL	2	LF	U39N	PR								NEED TO RPL BAD SPAN OF PRI S/O#2201 #BOL URD PR. ISOLATED A BAD #PAN OF URD PRIMARY BTWN Y TPH#JOH AND TRM#0 LOCATED AT 770 GREENS RD BLDG#600. ALFRED	1	0
FORCED INTERR	GP	NB 41				320032920015	F	########	0933	1	54	54	SPLICE			2	LF	U39N										0	0
FORCED INTERR	GP	NB 41				320032920015	F	########	0933	209	59	12331	SPLICE			2	LF	U39N										0	0
FORCED INTERR	GP	LU 41	20571	I94I	5168214	320032920017	F	########	0944	73	38	2774	SQUIRREL	SQUIRREL	16808 WAYCRE	1	LF	I94I									REFUSED LINE FUSE. REF LF.	1	0
FORCED INTERR	FB	CRB4	14863	84RB		320032920017	F	########	1000	45	28	1260	UNKNOWN	UNKNOWN	5510 BRIDLEWC	1	LF	84RB									reset fire fuse. REF LF	1	0
FORCED INTERR	SH	SB 03	31039	I68K	5955043	320032920014	F	########	1011	59	29	1711	UNKNOWN	UNKNOWN	210 GLENMORE	1	LF	I68K									REF LF.	1	0
FORCED INTERR	HC	HOCO	11185	W9Z	5253331	320032920015	F	########	1018	43	40	1720	BIRD	BIRD	4029 WOODCRI	1	LF	W9Z									REF LF.	1	0
FORCED INTERR	RS	AE 05	30051	9R2	5336341	320032920015	F	########	1018	57	8	456	UNKNOWN	UNKNOWN	CO 49, E OF CO	1	LF	9R2									REF LF.	1	0
FORCED INTERR	BA	CD 08	40396	PT9	6457104	320032920016	F	########	1018	25	39	975	UNKNOWN	UNKNOWN	1303 ADAMS ST	1	LF	PT9									CREW RODE OUT LF NO CAUSE FOUND	1	0
FORCED INTERR	SH	GV 05	31379	11LG	5553716	320032920016	F	########	1033	45	92	4140	UNKNOWN	UNKNOWN	7151 EVANS ST	1	LF	11LG									REF LF.	1	0
FORCED INTERR	HC	MV 02	14231	E90G	5444315	320032920022	T	########	1034	60	1	60	SQUIRREL	SQUIRREL	9211 MASTERS	1	TF	544431501									reluced LF --equipmi ??? REF LF	1	0
FORCED INTERR	BL	BI 09	11852	K25T	5256302	320032920022	F	########	1041	51	69	3519	UNKNOWN	UNKNOWN	3846 LAW #1	1	LF	K25T									REFUSED LINE FUSE. REF TR	1	0
FORCED INTERR	SB	ME 02	21585		4857533	320032920026	T	########	1125	76	3	228	SQUIRREL	SQUIRREL	422 HICKORY PI		TF	485753301									REFUSE NORTH PHASE OF LF. REF LF	1	0
FORCED INTERR	SU	WI 01	13067	B65X	4856055	320032920026	L	########	1127	113	1	113	UNKNOWN	UNKNOWN	12907 WESTME	2	SC										NEED TO INSTALL WILD LIFE PROT. ON TRAN IN REAR OF THIS ADRESS. REF TR.	1	0
FORCED INTERR	SH	CC 01	30176	KS6	5452447	320032920022	F	########	1200	66	33	2178	UNKNOWN	UNKNOWN	4826 HOLLOWA	1	LF	KS6									INSTALLED SECONDARY BYPASS	1	0
FORCED INTERR	HC	HM 09	11048	86JJ	5453239	320032920023	T	########	1210	71	11	781	SQUIRREL	SQUIRREL	4518 GALESBUF	1	TF	545323998									REF LF.	1	0
FORCED INTERR	BA	FT 01	31036	37KS	6153348	320032920022	F	########	1220	53	7	371	SQUIRREL	SQUIRREL	10447 CATLETT	1	LF	37KS	TF	615334877							REF TR.	1	0
FORCED INTERR	CH	CV 06	40452		5859904	320032920024	T	########	1230	47	1	47	SQUIRREL	SQUIRREL	14602 WOODFC		TF	585990497									REF LF. RPLD BAJ BARREL ON TR.	1	0
FORCED INTERR	SU	WI 04	12367	E23M	4856353	320032920034	F	########	1300	0	0	0	SPLICE	SPLICE	12507 WESTELL	2	LF	E23M	PR								REF TR.	1	0
FORCED INTERR	SU	WI 04				320032920034	F	########	1300	147	19	2793	SPLICE			2	LF	E23M									ISOLATED BAD URD BETWEEN TRANSFORMERS# 26 & 27 URD B/O 2202 REF TP #BOL URD PR. JSE	1	0
FORCED INTERR	SU	WI 04				320032920034	F	########	1300	147	8	1176	SPLICE			2	LF	E23M										0	0
FORCED INTERR	SH	PA 03	30764	27FF	5754318	320032920027	T	########	1316	68	10	680	UNKNOWN	UNKNOWN	5719 WOOD CR	1	TF	575431859									REF TR.	1	0
FORCED INTERR	BA	NP 41	37666	78EN	6164019	320032920026	T	########	1316	104	3	312	SQUIRREL	SQUIRREL	122 W 2ND	1	TF	616401949									replaced broke installed wip. REF TR.	1	0
FORCED INTERR	SH	MY 08	30731	T80R	5749612	320032920030	T	########	1400	36	2	76	SQUIRREL	SQUIRREL	2410 CREEKRID	1	TF	574961250									reluced tran --equipmi. REF TR.	1	0
FORCED INTERR.	FB	EB 05	11291	C40M	3548544	320032920036	F	########	1420	24	1	24	BIRD	BIRD	19150 CO 268	1	LF	C40M									REF LF	1	0
FORCED INTERR	SH	DR 01	30260	KF2	5654413	320032920031	F	########	1424	41	36	1476	UNKNOWN	UNKNOWN	8306 GULF FWY	1	LF	KF2									REF LF.	1	0
FORCED INTERR	GA	KM 07	30605		6347044	320032920033	T	########	1430	53	6	318	SQUIRREL	SQUIRREL	3015 HIGHWAY	1	TF	634704452									REF TR.	1	0
FORCED INTERR	HC	AR 42	15838	J1D	5248418	320032920042	F	########	1450	42	22	924	SQUIRREL	SQUIRREL	531 MARILYN	1	LF	J1D									REF LF	1	0
FORCED INTERR	SH	TE 05	31088	A74D	5651412	320032920037	L	########	1456	54	1	54	CUST EQP RELAI	CUST RLTD	8206 COASTWA	1	DR										ELECT CLAMPS CAUSED WIRE TO MELT TOGETHER AN BURN INTO MADE REPAIR AT WEATHERHEAD. RPLD CONN @ WH.	1	0
FORCED INTERR	GA	GL 09	30463		6839706	320032920038	L	########	1552	67	1	67	FOREIGN MATER	FRGN MATR	1012 SEALY ST	1	DR										RPLD CONN @ WH.	1	0
FORCED INTERR	HC	CC 02	10827		5452301	320032920047	T	########	1620	64	7	448	BIRD	BIRD	4226 FAIRGREE		TF	545230108									REF TR.	1	0
FORCED INTERR	HC	HOCO	11169		5153409	320032920050	T	########	1716	63	6	378	BU DISC OR BARI	DISC/BARRL	11403 CHIMNEY		TF	515340949									RPLD BAJ BARREL ON TR.	1	0
FORCED INTERR	CH	LY 44	41344	S1714	5962604	320032920043	F	########	1718	73	42	3066	TREE CLEARANC	TREE CLEAR	18903 WOODBU	1	LF	S1714	TF	596260482							REPAIRED STEP DOWN TRANS. NEEDS TO BE TURNED OVER FOR TREE TRIMMING DOWN EASEMENT. REF TR.	1	0
FORCED INTERR	RS	RZ 01	35738	18KA	4938452	320032920046	T	########	1730	79	2	158	SQUIRREL	SQUIRREL	18314 PECAN S	1	TF	493845267									REFURED TRANSFORMER TAKEN OUT BY SQUIRREL	1	0
FORCED INTERR	CH	SW 07	41689	PE6	5662408	320032920047	T	########	1735	70	14	980	SQUIRREL	SQUIRREL	10510 BRETTON	1	TF	556240868									REF TR.	1	0
FORCED INTERR	CH	CV 08	40459	7PL	5959409	320032920048	T	########	1740	59	11	649	SQUIRREL	SQUIRREL	810 GRASSMON	1	TF	595940944									out by squirrel__trans loss not protective. REF TR.	1	0
FORCED INTERR	HC	AR 42	10925	BM3	5146917	320032920051	T	########	1746	32	4	128	VANDALISM	VANDALISM	414 COEN RD	1	TF	514691786									KIDS THREW FOOT BALL INTO OPEN WIRE SEC. REF TR.	1	0
FORCED INTERR	BA	FT 08	40693		6153138	320032920046	T	########	1752	128	2	256	TREE CLEARANC	TREE CLEAR	3619 ROSEBERI		TF	615313646									CUT AND TRIM BACK TREE OFF OF SWITCH AND OAK TRANS FEEDING UG SEC REFUSED TRANS.___. REF TR.	1	0
FORCED INTERR	CY	PI 45	24495K	S84C	4371128	320032920025	F	########	1757	99	10	990	BIRD	BIRD	23202 LAZY HOL	1	LF	S84C	TF	437174985							REF LF. REF TR.	1	0
FORCED INTERR	SH	GV 05	31379	F6J	5553922	320032920050	T	########	1800	69	6	414	SQUIRREL	SQUIRREL	7309 EVANS ST	1	TF	555392203									REFURED TRAN.S. REF TR.	1	0
FORCED INTERR	BL	BR 01	12956	1N7	5254416	320032920056	T	########	1846	46	5	230	UNKNOWN	UNKNOWN	3603 SUN VALLI	1	TF	525441803									PULLED FUSE. REF TR.	1	0
FORCED INTERR.	KY	WA 42	11733	90TG	3953229	320032920056	F	########	2017	58	2	116	BU DISC OR BARI	DISC/BARRL	9626 BARNES	1	LF	90TG									REFUSED 801 PULLED FUSE AB CHANGE BARREL. REF LF	1	0
FORCED INTERR	BA	CD 01	30673	86ND	6358338	320032920066	F	########	2113	42	3	126	UNKNOWN	UNKNOWN	RICELAND, W O	1	LF	86ND									REF LF.	1	0
FORCED INTERR	GP	DH 09	40593	E86X	5161517	320032920031	F	########	2232	193	130	25090	ROTTEN POLE	ROTTEN PLI	W.TIDWELL @ 1	1	LF	E84M	PD								NEED TO REPL 40 CL. 3 POLE SINGLE PHASE #2 PRI. 40 SEC. CAN GET TRK TO LOCATED AT 4846 BAYOU VISTA DR. STUBBED UP PL.	1	0
FORCED INTERR	KY	KT 43	20035	22SU	3658537	320032920064	F	########	2240	5	2	10	UNKNOWN	UNKNOWN	FM 359 AT GARY	1	LF	22SU									REF LF	1	0
FORCED INTERR	SH	TE 05	31091	41EH	5652308	320032930001	T	########	0100	82	6	492	TREE CLEARANC	TREE CLEAR	8114 CONSTELL	1	TF	585230805									TRIMMED TREES FROM AN OPEN DELTA BANK. REF TR.	1	0
FORCED INTERR	CH	SW 06	41684	A97M	5561555	320032930002	F	########	0125	384	33	12672	COLLISION	COLLISION	10101 HOMESTI	1	DB	A97M			PD						PU PR-FUSE BLOWN. RPLD BAJ DISC-LF BLOWN. RPLD PL.	1	0
FORCED INTERR	CY	KL 45	24129	H33D	4765901	320032930001	F	########	0140	680	4	2720	UNKNOWN	UNKNOWN	11702 CHETMAI	2	BU	476590149									CHANGED OUT BAD URD TRANS / RADIAL FEED LOOP ALSO HAS A BAD SPAN OF 120V PRI BETWEEN 1ST AND 2ND TRANS / 11708 11702 RAN SEC BY PASS BETWEEN 11706 AND 11702. LIGH	1	0
FORCED INTERR	HC	SO 41	12620	9D4	5348410	320032930001	F	########	0325	122	60	7320	PRIMARY CONDU	PRIMARY	2845 COUNTY R	1	PR	9D4	TF	534841046							REPAIRED PRIMARY JUMPER. REPLACED BAD LIMITER ON T/F. RPRD B/O PR JUMPER-FUSE NOT BLOWN. RPLD LIMITER @ TR.	1	0
FORCED INTERR	BZ	LJ 09	3521A	E76F		320032930002	F	########	0430	59	43	2537	BU DISC OR BARI	DISC/BARRL	200 TIMBERCRE	1	LF	N75Y									REPL. BAD FUSE BARREL ON T/ P. N75Y. RPLD BAJ BARREL ON TP	1	0
FORCED INTERR	SH	WE 03	31282	G18Y	5755829	320032930004	T	########	0430	51	14	714	TREE CLEARANC	TREE CLEAR	514 MAIN ST	1	TF	575582997									TREER ALL AROUND TRANSFORMER. REF TR.	1	0
FORCED INTERR	HC	SO 41	12620	A65A	5347041	320032930004	T	########	0520	45	1	45	UNKNOWN	UNKNOWN	4142 COUNTY R	1	TF	534704100									RPLD BAJ BARREL ON TR.	1	0
FORCED INTERR	MP	MP 01	41378	F22G	5656045	320032930003	T	########	0746	36	1	36	SQUIRREL	SQUIRREL	7707 AVENUE L	1	TF	565604568									REFUSED TRANS / LEFT SERV ON / NOTIFIED. REF TR.	1	0
FORCED INTERR	BA	AI 07	41148	78SM	6155435	320032930011	F	########	0755	78	1	78	UNKNOWN	UNKNOWN	10900 STRANG	1	LF	78SM									POUND 3 PHASE PRI. GOOD UP TO PRI. MT.---REF. C PHASE AND LEFT OK---LF M 78BN-1007---DID NOT SEE A CAUSE---. REF LF	1	0
FORCED INTERR	SU	WI

| | | |

FORCED INTERR	SH	SP 01	31817	I86K	5853355	320032940016	T	########	0921	57	8	456	SQUIRREL	SQUIRREL	2808 MULBERR'	1	TF	585335528											
FORCED INTERR	KY	FZ 46	22601		4560527	120032940021	T	########	0925	78	4	312	VINES	VINES	4435 HAWK ME/		PR	456052789											
FORCED INTERR	BL	BI 06	10084	A99A	5255103	120032940022	T	########	0945	36	9	324	SQUIRREL	SQUIRREL	4306 JOHATHAN	1	TF	525510374											
FORCED INTERR	HC	HM 04	11022		5354907	120032940022	T	########	100	54	2	108	SQUIRREL	SQUIRREL	7906 LAWLER S	1	TF	535490723											
FORCED INTERR	HC	BR 10	12528		5253234	120032940032	L	########	100	66	1	66	OH SEC/DR CL NI	OH SC CL-N	10606 BASSOOI		DR												
FORCED INTERR	KY	MAR41	22692		4557418	120032940035	T	########	1011	122	4	488	OH SEC/DR CL HI	OH SC CL-N	1723 MISSION S		TF	455741870	SC										
FORCED INTERR	FB	NEW0				120032940036	C	########	103	0	0	0	HUMAN ERROR	TREE	NEW01 CKT LO		CL	NEW01											
FORCED INTERR	FB	NEW0	10931			120032940036	C	########	103	2	1135	2270	HUMAN ERROR				CL	NEW01											
FORCED INTERR	MP	WO 02	41838	29EQ	5260342	220032940024	T	########	103	66	6	398	VINES	VINES	4922 OAK FORE	1	TF	526034228											
FORCED INTERR	GP	BA 42	2E149	U75N	5167449	220032940027	L	########	104	22	1	22	VANDALISM	VANDALISM	2402 BAMMELW	2	MT												
FORCED INTERR	GP	RU 04	41665	DH3	5361459	220032940028	F	########	105	69	100	6900	UNKNOWN	UNKNOWN	AIRLINE @ MC	1	LF	DH3	TF	536145922									
FORCED INTERR	SH	CC 01	30176	KS6	5452443	320032940032	F	########	112	31	33	1023	UNKNOWN	UNKNOWN	10 HOLLOWAY	1	LF	KS6											
FORCED INTERR	SH	DR 03	30271	39S	5653540	320032940036	F	########	113	39	13	507	SQUIRREL	SQUIRREL	8102 ROCKHILL	1	LF	39S											
FORCED INTERR	GP	DH 08	22191		5162028	320032940037	T	########	114	40	1	40	SQUIRREL	SQUIRREL	7435 ALABONS(		TF	516202859											
FORCED INTERR	GA	PHR01	30854	24M	6546139	320032940040	T	########	122	30	5	150	UNKNOWN	UNKNOWN	523 BROADWAY	1	TF	654613528											
FORCED INTERR	GP	TWG4	2388A	U29N	5368439	220032940040	T	########	124	159	11	1749	OH SEC/DR CL HI	OH SC CL-N	3040 FM 1960 RI	1	SC	536843924											
FORCED INTERR	CY	PI 43	2A118	57EA	4472849	220032940042	T	########	125	61	1	61	LIGHTNING ARRE	LTNG ARRS	15911 N COOTE	1	TF	447284971											
FORCED INTERR	FB	NEW0				120032940060	C	########	131	0	0	0	WORK TAG	WORK TAG	NEW01 CKT LO		CL	NEW01											
FORCED INTERR	FB	NEW0	10931			120032940060	C	########	131	4	1135	4540	WORK TAG				CL	NEW01											
FORCED INTERR	MP	AN 09				220032940046	C	########	132	0	0	0	COLLISION	COLLISION	OXFORD @ CR(		CL	AN09	PD		PR								
FORCED INTERR	MP	AN 09	2G009			220032940046	C	########	132	29	209	6061	COLLISION				CL	AN09											
FORCED INTERR	MP	AN 09	40053			220032940046	C	########	132	32	827	26464	COLLISION				CL	AN09											
FORCED INTERR	MP	AN 09	40052			220032940046	C	########	132	111	107	11877	COLLISION				CL	AN09											
FORCED INTERR	BA	NP 44	41301	82MM	6266325	320032940056	T	########	133	215	3	645	UNKNOWN	UNKNOWN	4102 GATEWOC	1	BU	626632571											
FORCED INTERR	GA	AL 09	30107	104M		320032940054	F	########	135	56	328	18256	UNKNOWN	UNKNOWN	FMT 1784 E OF	1	LF	104M											
FORCED INTERR	HC	TV 03	11139	W6SY	5149850	120032940074	F	########	141	109	1	109	STRONG WIND	WIND	6809 FM 2234	1	DB	W6SY											
FORCED INTERR	GA	GA 04	31196	J93L	6737250	320032940058	T	########	141	79	4	316	SPLICE	SPLICE	12 BACK BAY CI	2	SC	673725030											
FORCED INTERR	SH	WE 02	31248		5855114	320032940060	T	########	142	44	3	132	BU DISC OR BARI	DISC/BARRL	1002 HARRIS AV		TF	585511401											
FORCED INTERR	BA	CD 12	41988	3TW	6459727	320032940064	L	########	143	68	1	68	UNKNOWN	UNKNOWN	5627 BAYOU BL	1	DR												
FORCED INTERR	SB	SR 09	21648	X60B	4959212	120032940081	T	########	145	54	1	54	BU DISC OR BARI	DISC/BARRL	1645 W SAM HO	1	TF	495921286											
FORCED INTERR	KY	KT 04	22894		4158201	120032940082	T	########	150	71	1	71	OH SEC/DR CL HI	OH SC CL-N	30491 KATY BR(		SC	415820198											
FORCED INTERR	BZ	LJ 02	30618	ED4	5426028	320032940070	T	########	151	51	4	204	SQUIRREL	SQUIRREL	215 STRATTON	1	TF	542602867											
FORCED INTERR	SL	PT 07	22035	SJ4	3561910	120032940086	F	########	152	135	12	1620	UNKNOWN	UNKNOWN	STECK BOTTOI	1	SL	SJ4											
FORCED INTERR	HC	GV 02	10825	GH9	5553031	120032940091	T	########	153	54	7	378	HUMAN ERRC	HUMN ERRC	5850 BELMARK	1	TF	555303185											
FORCED INTERR	HM	LW 42	22977	S3139		220032940086	F	########	153	252	108	27216	O/H PRIMARY CL	OH PR CLMF		1	PR	S3139											
FORCED INTERR	HM	SW 08	41692	23AH	5563628	220032940090	T	########	155	68	10	680	UNKNOWN	UNKNOWN	8421 HERMANN	1	TF	556362875											
FORCED INTERR	SH	FT 05	40741	C90L	8153350	320032940074	T	########	155	81	1	81	BU DISC OR BARI	DISC/BARRL	202 FARRINGTC	1	TF	615335079											
FORCED INTERR	SB	CB 07	21448	6WS		120032940095	F	########	155	409	91	37219	FLLNG TREE IN E	TREE FL/IE	8934 ROCKHUR	1	LF	6WS	PR		TF	5061	SC						
FORCED INTERR	FB	CRB45	14885	68RR		120032940096	F	########	161	70	9	630	BIRD	BIRD	5735 WATERW/	1	LF	68RR											
FORCED INTERR	BL	CR 05	40514	8K2	5358904	120032940101	F	########	162	92	4	368	UNKNOWN	UNKNOWN	DART @ GOLIAI	1	LF	8K2											
FORCED INTERR	SH	CG 01	30185	9SF	5753030	320032940080	T	########	163	84	2	168	OVERLOAD	OVERLOAD	1311 GEORGIA	1	SC	575303050											
FORCED INTERR	CY	TB 44	21021	15PF	4871750	220032940084	T	########	163	140	6	840	LIGHTNING ARRE	LTNG ARRS	23723 INDIAN HI	1	TF	487175028											
FORCED INTERR	CH	LB 06	41277	G57B	5559723	320032940081	F	########	165	45	6	270	COLLISION	COLLISION	7210 N LOOP E	1	LF	G57B											
FORCED INTERR	GA	AL 07	30033		6042603	320032940085	L	########	170	99	1	99	OH SEC/DR CL HI	OH SC CL-N	13402 6TH		DR												
FORCED INTERR	MP	EU 03	41824	8D1	5359128	220032940097	T	########	170	77	19	1463	SQUIRREL	SQUIRREL	2115 RUTLAND	1	TF	535912609											
FORCED INTERR	BA	MB 08	3713B	E25K	6760356	320032940084	T	########	171	63	2	126	UNKNOWN	UNKNOWN	7227 S FM 565 R	1	TF	678035674											
FORCED INTERR	RS	AE 06	30075	A65M	5437715	320032940087	F	########	171	254	12	3048	O/H PRIMARY CL	OH PR CLMF	1015 COUNTY R	1	LF	A65M	PR										
FORCED INTERR	SH	SP 03	30897	8SU	5854821	320032940091	F	########	173	51	31	1581	SQUIRREL	SQUIRREL	2304 WICHITA S	1	LF	8SU											
FORCED INTERR	FB	BV 42	11363	49UE	4351841	120032940106	T	########	175	52	1	52	TREE CLEARANC	TREE CLEAI	4803 OLD OAK	1	TF	435164174											
FORCED INTERR	BA	BW 09	41524	46ABD	6153410	320032940097	T	########	180	87	1	87	UNKNOWN	UNKNOWN	13301 BAYPARK	3	TF	615341022											
FORCED INTERR	SB	BM 05	21497	26AV	4859614	120032940112	T	########	181	321	8	2568	UNKNOWN	UNKNOWN	11625 KATY FW	1	BU	485861419											
FORCED INTERR	CH	CV 01	40423	27GU	5858340	320032940101	T	########	183	53	8	424	SQUIRREL	SQUIRREL	1319 CORPUS	1	TF	558340067											
FORCED INTERR	MP	AN 03	40015	KN7	5359559	220032940100	T	########	184	71	10	710	UNKNOWN	UNKNOWN	1231 E 33RD	1	TF	535955968											
FORCED INTERR	HC	FD 05	10858	H38H	5053829	120032940115	F	########	184	135	15	2025	LIGHTNING ARRE	LTNG ARRS	10902 BOB WHI	2	LF	H38H	PR										
FORCED INTERR	GA	AL 07	30033		6042603	320032940105	T	########	192	38	1	38	UNKNOWN	UNKNOWN	13402 6TH		TF	604260382											
FORCED INTERR	HM	LA 04	41245	T96E	5464919	120032940107	F	########	201	109	2	218	UNKNOWN	UNKNOWN	LAUDER RD E C	1	LF	T96E											
FORCED INTERR	GP	AD 05	40077		5363533	220032940106	T	########	204	224	2	448	OVERLOAD	OVERLOAD	806 ALDINE MAI		BU	536353356											
FORCED INTERR	SH	UW 04	31461	F44Y	6055203	320032940116	F	########	211	43	51	2193	OTHER WILDLIFE	OTHER WLE	1014 N KAUFMA	1	LF	F44Y											
FORCED INTERR	CY	PI 42	2454B	U35B	4876401	220032940110	T	########	213	32	1	32	BIRD	BIRD	31110 ROY	1	TF	487640188											
FORCED INTERR	FB	NV 03	11230	L6H	4341114	120032940128	T	########	224	37	2	74	BU DISC OR BARI	DISC/BARRL	13210 COLONY	1	TF	434111479											
FORCED INTERR	CH	IND02	40633		5857724	320032950008	T	########	071	79	1	79	UNKNOWN	UNKNOWN	14047 INDUSTR		TF	585772496											
FORCED INTERR	SH	PE 04	30714		5447742	320032950000	T	########	073	52	4	208	HUMAN ERROR	HUMN ERRC	3831 OLD CHOC		TF	544774289											
FORCED INTERR	MP	HG 05	41087	CW5	5655653	320032950004	L	########	074	121	1	121	VINES	VINES	9325 MANCHES	1	DR												
FORCED INTERR	BL	DN 06	10558	2B8	5257902	120032950007	T	########	081	170	4	680	OH SEC/DR CL NI	OH SC CL-N	2222 MIMOSA D	1	SC	525790202	SC										
FORCED INTERR	FB	OB 44	10920	17NV	4653112	120032950010	F	########	081	165	8	990	UNKNOWN	UNKNOWN	N OF 17724 MAI	1	LF	17NV	TF	465311254									
FORCED INTERR	HC	HOC0	11157		5253012	120032950012	T	########	084	52	9	468	SQUIRREL	SQUIRREL	4538 SANFORD		TF	525301293											
FORCED INTERR	SB	TO 11	21784	2A3	5180016	120032950015	T	########	085	101	8	808	BU DISC OR BARI	DISC/BARRL	3614 LANG RD	1	TF	518001836											
FORCED INTERR	GA	KM 07	30213	36CS	8246606	320032950014	F	########	090	0	0	0	SQUIRREL	SQUIRREL	2301 S KEMAH	1	LF	36CS	TF	624880651									
FORCED INTERR	GA	KM 07				320032950014	F	########	090	36	9	324	SQUIRREL			1	LF	36CS											
FORCED INTERR	GA	KM 07				320032950014	F	########	090	44	2	88	SQUIRREL			1	LF	36CS											
FORCED INTERR	SH	PJ 03	31826	U80O	5848929	320032950015	F	########	090	100	26	2600	UNKNOWN	UNKNOWN	15818 KINGS CH	2	PR	U79O											
FORCED INTERR	HC	AR 43	13144	18AN	5147328	120032950016	F	########	090	48	1	48	BIRD	BIRD	11927 HWY 6	1	LF	18AN											
FORCED INTERR	SH	SH 11	31404	A22S	5752914	320032950016	T	########	090	18	10	180	SQUIRREL	SQUIRREL	12017 PALMCRE	1	TF	575291404											
FORCED INTERR	KY	WA 42	2161A	15UP	3854715	120032950021	T	########	091	82	1	82	HUMAN ERROR	HUMN ERRC	1235 PONY LN	1	SC	385471571											
FORCED INTERR	HM	HB 47	22252		5867256	220032950012	T	########	092	32	1	32	UNKNOWN	UNKNOWN	268 W 1ST		TF	586725653											
FORCED INTERR	GP	RU 01	41645	63CV	5361255	220032950016	T	########	093	38	8	304	SQUIRREL	SQUIRREL	130 E ECHO GLI	1	TF	536125526											
FORCED INTERR	RS	AE 06	30075	77PH	5436454	320032950023	F	########	095	55	12	660	BU DISC OR BARI	DISC/BARRL	1101 COUNTY R	1	LF	77PH											
FORCED INTERR	SB	EC 05	21707	K24S	5058636	120032950027	T	########	100	80	6	480	UNKNOWN	UNKNOWN	8827 WINNINGH	1	TF	505863688											
FORCED INTERR	BL	HE 07	41139	B14T	5358249	220032950015	L	########	100	61	1	61	OH SEC/DR CL HI	OH SC CL-H	944 HEIGHTS BI	1	DR												
FORCED INTERR	BA	CD 12	40349	78GL	6459853	320032950027	F	########	103	38	33	1254	UNKNOWN	UNKNOWN	2923 LANDMARI	1	LF	78GL											
FORCED INTERR	SB	SR 10	21675	51UV	4857454	120032950039	T	########	103	66	8	398	SQUIRREL	SQUIRREL	1214 COBBLES	1	TF	485745412											
FORCED INTERR	MP	AN 08	40048	A20	5360629	220032950027	L	########	104	69	1	69	TREE CLEARANC	TREE CLEAI	145 THERON ST	1	DR												
FORCED INTERR	GP	HV 03	22206		5263733	220032950028	T	########	104	35	1	35	SQUIRREL	SQUIRREL	9521 SUNNYWC		TF	526373306											
FORCED INTERR	MP	WV 03	41810		5558841	220032950034	T	########	105	38	5	190	SQUIRREL	SQUIRREL	7434 EAGLE PA		TF	555884131											
FORCED INTERR	CY	KL 45	21976	S2648	4765717	220032950037	T	########	112	85	7	595	VINES	VINES	13102 CYPRESS	1	TF	478571797											
FORCED INTERR	BL	GS 29	40192	85MB	5457257	120032950041	L	########	113	55	1	55	OH SEC/DR CL HI	OH SC CL-H	1020 WOOD ST	1	DR												
FORCED INTERR	BZ	BZ 06	30641		5326128	320032950035	L	########	115	62	1	62	FLLNG TREE IN E	TREE FL/IE	818 SYCAMORE		DR												
FORCED INTERR	SU	JN 10	12130		4955619	120032950044	T	########	120	30	1	30	TREE CLEARANC	TREE CLEAI	6309 WESTLINE		TF	495561904											
FORCED INTERR	FB	TM 04	12657	60VC	4945654	120032950046	F	########	121	132	7	924	FLLNG TREE OUT	TREE FL/OE	403 JERRY RD	1	LF	60VC											
FORCED INTERR	SH	CG 06	30205	F84E	5753629	320032950070	F	########	124	25	12	300	UNKNOWN	UNKNOWN	709 AVE J	1	LF	F84E											
FORCED INTERR	HC	HM 06	11034	3ED	5454413	220032950046	F	########	125	225	5	1125	COLLISION	COLLISION	4564 HOLMES R	1	LF	3ED	DB										
FORCED INTERR	HC	MV 01	13138	72AEA	5445011	120032950050	T	########	125	59	2	118	SQUIRREL	SQUIRREL	8103 KIRCHNER	1	TF	544501138											
FORCED INTERR	GA	GA 02	31187	24EE	6838000	320032950077	L	########	130	179	1	179	OH SEC/DR CL NI	OH SC CL-N	4125 AVENUE Q	1	SC												
FORCED INTERR	BL	GT 03	40848	C43H	5356625	120032950056	T	########	134	59	6	354	OH SEC/DR CL HI	OH SC CL-H	4802 MAIN ST	1	TF	535682517	DR										
FORCED INTERR	BL	GT 13	10642		5356204	120032950066	L	########	134	188	1	188	OH SEC/DR CL NI	OH SC CL-N	5312 CHEROKEI		DR												
FORCED INTERR	SU	WD 42	11744		4757824	120032950063	T	########	135	142	1	142	SQUIRREL	SQUIRREL	13301 SANDBRII		PR	475782496											
FORCED INTERR	GP	WF 41	22175	99BW	5168925	220032950063	T	########	140	239	1	239	OVERLOAD	OVERLOAD	17070 RED OAK	1	BU	516892527											
FORCED INTERR	BL	UL 15	10370		5058334	120032950076	T	########	145	136	2	272	LIGHTNING	LIGHTNING	6505 1/5 WESTI		BU	505683400											
FORCED INTERR	CY	PI 45	2446Y	94GQ	4472258	220032950065	F	########	150	55	15	825	COLLISION	COLLISION	21802 ROMERO	1	LF	94GQ											
FORCED INTERR	CY	CYF45	21209	X10X	4662730	220032950070	F	########	150	213	57	12141	URD ELBOW	URD ELBOW	7330 BUBBLING	2	LF	X10X											
FORCED INTERR	SB	SR 07	21660	7B9	4957851	120032950078	T	########	152	40	10	400	SQUIRREL	SQUIRREL	12115 BROKEN	1	TF	495785108											
FORCED INTERR	BL	CR 05	40514	39GV	5458003	120032950078	T	########	152	131	7	917	UNKNOWN	UNKNOWN	1320 1/2 ELDER	1	TF	545800323											
FORCED INTERR	FB	RS 05	1555A	5W6	4346644	120032950085	F	########	152	30	21	630	CONTRACTOR-H	CON-NT HLF	HWY 36 @ MAG	1	LF	5W6											
FORCED INTERR	SH	PA 04	30776	G11	5755810	320032950100	F	########	153	164	56	9184	UNKNOWN	UNKNOWN	702 CHARLES S	1	LF	G11	PR										
FORCED INTERR	CH	SW 09	41697	J58S	5582646	320032950110	T	########	154	123	8	984	FLLNG TREE IN E	TREE FL/IE	6314 HANLEY LI	1	TF	556264691											
FORCED INTERR	BZ	LJ 09	3521E	E77F	5428654	320032950114	T	########	160	41	7	287	BU DISC OR BARI	DISC/BARRL	9731 FM 523 #4	1	TF	542865499											
FORCED INTERR	SU	WI 04	12377	S75A	4856035	120032950091	F	########	164	89	35	3115	BU DISC OR BARI	DISC/BARRL	12927 SANDRI L	2	LF	S75A											
FORCED INTERR	SH	HA 03	30558	F79Y	5750641	320032950122	T	########	172	17	10	170	BU DISC OR BARI	DISC/BARRL	11026 SAGEFAF	1	TF	575064150											
FORCED INTERR	BA	KM 04	30654	42JT	6250710	320032950125	F	########	174	50	5	250	SQUIRREL	SQUIRREL	3401 N MEYER	1	LF	42JT											
FORCED INTERR	MP	BY 03	40166	T1W	5360850	220032950096	T	########	175	113	7	791	SQUIRREL	SQUIRREL	119 FEUHS LN	1	TF	536085029											
FORCED INTERR	HM	AT 42	2314E	25QG	5970720	220032950097	F	########	175	102	9	918	SQUIRREL	SQUIRREL	1421 SHORE SH	1	LF	25QG											
FORCED INTERR	SH	GG 04	30542	M96	5554323	320032950096	F	########	175	67	10	670	SQUIRREL	SQUIRREL	DIXIE @ NORTH	1	LF	M96											
FORCED INTERR	SH	GG 04	30542	56KH	5554310	220032950096	F	########	175	57	2	114	SQUIRREL	SQUIRREL	5744 NOTRHDA	1	LF	56KH											
FORCED INTERR	HC	FD 14	10861	1KL	5153006	120032950096	T	########	182	156	8	1248	VINES	VINES	5902 MC KNIGH	1	TF	515300633											
FORCED INTERR	GP	TWG4	22374	F39S	5469032	220032950100	F	########	182	114	5	570	UNKNOWN	UNKNOWN	23003 BANQUO	2	LF	F39S	PR										
FORCED INTERR	GP	KDL42	2B170	F98S	5171301	220032950111	T	########	184	109	10	1090	SQUIRREL	SQUIRREL	21815 ROTHERI	1	PR	517130193											

REFUSED POWER TRNS / LEFT SERV ON / NOTIFIED. REF TR. BJH 1 0

RMV VINES/RPLC 12 KVA/TE-ARSTR-KRMY F2 BARREL, RPLD LIMITER @ TR, REF TR. RPLD B/U BARREL ON TR. RPLD LIGHTNING ARRESTOR. BJH 1 0

RE-FUSED TRANSFORMER. SQUIRREL. REF TR 1 0

REF TR. 1 0

REPLACED BURNED NEUTRAL CONN AT THE WH., RPLD CONN @ WH. 1 0

RPL TR LUG ON OH/RPL F8 BRL AND BOLTS. RPLD B/U BARREL ON TR. RPLD CONN @ TR. 1 0

CREW DROPPED TREE IN PRIMARY AT LF 57PH. MEK 1 1

RMVD VINES & REFUSED TRANS. REF TR. 1 0

RPLCD DESTROYED MTR. D27042006 , NO READING NEW MTR W8901 1653 00000 X 001 CUST TRIED RJC BELF LEFT B/O. BUT NEEDS TAMPER PROOF LID INSTALLED. RPLD MTR. 1 0

REF LF. REF TR. BJH 1 0

SEVERAL UNPROTECTED CIP TRANS NEED WLP. REF LF BJH 1 0

SG ON CIP, IN REAR OF 5211 ANACORTES. REF LF BJH 1 0

REFUSED A 15KVA LIGHTER TFMR. NEEDS SQUIRREL WIRE. AN HAS BAD LIGHTNING ARRESTER ON IT. TRUCK ACCESSABLE. REF TR; BJH 1 0

REF TR. 1 0

REPAIRD BUSS WORK AT TRX. RPRD BUSS WORK @ TR 1 0

REPLACE LIGHTNING ARRESTOR ON 25/18.9 TRANSFORMER, REF TR. RPLD LIGHTNING ARRESTOR. 1 0

LOCKED OUT ON WH. CREW DID NOT SEE ANYTHING. TWB NON PUC 1 1

WHO# 244 NON 10%PUC. SECTION 40052 CAR HIT POLE ON OXFORD @ CROSSTIMBERS. CREWS STUMBED POLE AND REPLACED BROKEN INSULATORS. RESTORED. SERVICE AND C 1 1

REPL BAD STEP XFMR 250 KVA WITH SAME. REPL 18.9 LIA. LFT WRKNG. RPLD B/U TR. 1 0

REFUSE LINE FUSE, REF LF. 1 0

RPLD B/U DISC-LF HOT BLOWN. 1 0

REPAIRED URD SECONDARY SPLICES ON BOTH HOT LEGS AT PEDESTAL. RPRD SEC->1 CUST 1 0

REFUSED POWER POT IN CLOSED DELTA BANK. REF TR. 1 0

RPRD DR. 1 0

FUSE PULLED LINE FUSE WILL IN. ONLY ONE CUSTOMER AFFECTED. REF TR 1 0

RPL TR LUG ON LEAD. RPLD CONN @ TR. 1 0

refused 25 kva. REF TR. 1 0

refused line fuse 5H 10E cause unknown. REF LF 1 0

refused 5 wat by broken fuse. REF TR. 1 0

REPLACED ONE SPAN #8 COPPER PRIMARY WITH #4 ALUMINUM 120 FT. SPLICED ON PR. 1 0

REPLACED 7200- BARREL ON TRANSFORMER. RPLD B/U BARREL ON TR. REF TR 1 0

RPLD B/U BARREL ON TR. 1 0

PICKED UP & SPLICED OUT IN PRI. & REPLACED OPEN WIRE SECONDARY TO 1/0 3C TW & ALSO CUT TREE LIMBS IN CLEAR TO FREE UP PRIMARY. REFUSED OH TRANSFORMER. BRS 1 0

REFUSED A PHASE OFF LINE FUSE IN PRI. - 40 T. WE RODE THE LINE OUT . CONDUCTOR'S WERE GOOD. RPRD DOT INTO DISC , ON LINE FUSE. REF LF 1 0

CUST. CALLING ABOUT LINE FUSE AT REAR OF PROPERTY. REF LF 1 0

RPLD REC CONN @ PL-1 CUST 1 0

REPL. LIGHTNING ARR. ON A REFUSED A 50KVA 18.9/120/240 TRANS. IN THE REAR OF 23716 INDIAN HILLS CIR. REF TR. RPLD LIGHTNING ARRESTOR. 1 0

REF LF 1 0

RPLD CONN @ WH. 1 0

REF TR. 1 0

REF TR. 1 0

REPL 1 SP #4 AL ACSR WITH # 2 AL. REF LF. PU PR-FUSE BLOWN. 1 0

REF LF 1 0

REFUSED 25 TRIMMED TREES. REF TR. 1 0

REF TR. RPLD B/U BARREL ON TR. 1 0

REPLACED 100 KVA 7200 120/240 V CONV. TRF WITH SAME. WA 10K10 AREA. COCREATE BERL # OLD TRF 3-118838. RPLD B/U TR. 1 0

REF TR. 1 0

REFUSED A 25 KVA 7200 120 240 V TRANSFORMER FUSE BROKE. REF TR. 1 0

BAD LIGHTNING ARRESTOR AND AT TRANSFORMER #60 HAD A BAD LUG REPLACED. #60 TO B/C TO REPLACE LIGHTNING ARRESTOR. MGJ VAN EN ROUTE 1 0

REPL. BROKEN FUSE, REF TR. 1 0

refused line fuse 79de 89L REF LF 1 0

REPLACED A 15 KVA 7200 120/240 O.H. TRANSFORMER WITH A 25 KVA 7200 120/240 O.H. TRANSFORMER. RPLD B/U TR. 1 0

REF LF 1 0

REFUSED 25KVA TRANS 18.9 120/240. OWL TOOK TRANS FUSE OUT, REF TR. 1 0

REPLACED BURNED UP FUSE BARREL ON 25 KVA TRANSFORMER. REF TR. RPLD B/U BARREL ON TR. BRS 1 0

REF TR. 1 0

refused 5 wat due to broken base. REF TR. 1 0

FOUND BAD VOLTAGE, BROKE METER GETTING STUCK LOCKBAND OFF. ALSO HAD TO CLEAR POISON IVY AWAY FROM WH TO REPAIR BROKE NEU. OLD METER READING 3134 BY 10, NEW 1 0

REPLACED #2 COPPER NEUTRAL LEAD WITH #6 ALUM ON A 75 KVA 7200 120/240 LIGHTER XFMR IN AN OPEN DELTA BANK LOCATED IN THE REAR OF 2211 WELCH ALSO REPLACED THE NEU 1 0

REFUSED 50 KVA TR AND REFUSED C PHB OF LF 17NV. BJH 1 0

REFUSED LIGHTER AND POWER POTS. REF TR. 1 0

REFUSED 50 KVA TRANS. REF TR. RPLD B/U BARREL ON TR. BJH 1 0

TRK 6484 ------ REFUSED

FORCED INTERR	GP	KI 43	21931	N68X	49674355	220032950113	T	########	190(	201	10	2010	VINES	VINES	9407	GODSTON	1	PR	496743558	CLEAR VINES REPL LIMITER, REF TR, RPLD LIMITER @ TR, REF TR								1	0
FORCED INTERR.	SH	PE 05	30811	41UR	55483403	320032950130	F	########	1937	57	1	57	OTHER WILDLIFE	OTHER WILD	6614	FITE RD	1	LF	41UR	refused fireface, and two transformers on two different banks. left all on and working... only; REF LF								1	0
FORCED INTERR.	FB	EB 05	11290	K66	36448497	120032950106	F	########	1942	66	1	66	COLLISION	COLLISION	18111	CO 204	1	LF	K66	FARMER BUMPED LIME POLE WE REFUSED KIM K; REF LF;								1	0
FORCED INTERR	SB	EC 05	21707		50586574	120032950117	T	########	2120	69	4	276	VINES	VINES	8834	MERLIN		TF	505865742	REPLACED LIGHTNING ARRESTOR ON TRANS. , NEED TO TRIM TREES IN EASEMENT, REF TR. RPLD LIGHTNING ARRESTOR,								1	0
FORCED INTERR	HC	HOC0(	11185	W8Z	52532376	120032950116	F	########	2130	126	40	5120	OTHER WILDLIFE	OTHER WILD	4133	WOODCRA	1	LF	W8Z	REF LF								1	0
FORCED INTERR.	SU	QV 05	12153	M54U	50492225	120032950115	F	########	2200	87	30	2610	BU DISC OR BARI	DISC/BARRL	3218	MISSION V	2	LF	M54U	RPLD BU BARREL ON TP. REF TP								1	0
FORCED INTERR	HC	HM 04	11026	RD8	53529454	120032950003	T	########	0010	142	11	1562	TREE CLEARANC	TREE CLEAR	10406	SIERRA C	1	TF	535294547	REMOVED TREE LIMBS FROM AROUND T/F. TREES ARE GROWN UP IN OPEN WIRE SECONDARIES UP AND DOWN EASEMENT, NEEDS TREE TRIMMING BAD. HAS ALREADY BEEN TURNED IN F								1	0
FORCED INTERR.	BL	SF 43	10468	25NK	51579084	120032950002	F	########	0030	184	84	15456	O/H PRIMARY CU	OH PR CLMF	1911	POST OAK 2		TF	25NK	BAD SPAN OF PRI BETWEEN T/P 28NK (1) AND TRANS AT 5101 POST OAK PK DR PUT Y ON STANDOFF AND TAGGED IN THIS TRANS-CLSD T/P 25NK (X). REF TP BENT MBG TO T&D SR/S		PR						1	0
FORCED INTERR	SU	AF 06	12857	I66B	48543421	120032960005	F	########	0041	0	0	0	UNKNOWN	UNKNOWN	7030	S DAIRY AV	2	LF	I66B	ISOLATED BAD SPAN PRIMARY BETWEEN 1/F # 30 & 31. REF TP. BOL URD PR. BENT MBG TO T&D. SR/S		PR						1	0
FORCED INTERR	SU	AF 06				120032960006	F	########	0041	189	13	2457	UNKNOWN				2	LF	I66B									0	0
FORCED INTERR	SU	AF 06				120032960006	F	########	0041	189	6	1134	UNKNOWN				2	LF	I66B									0	0
FORCED INTERR	SB	EC 05	21707	K42M	50589506	120032960007	F	########	0125	0	0	0	VINES	VINES	8334	LEAFY LN.	1	LF	K42M	TF 505895372 REFUSED BOTH PHASES OF L/F - K42M @ 03 12. RM VINES AND REFUSED TRANSFORMER @ 8334 LEAFY LN. ** NEED TO TRIM EBMT AND RM VINES OFF TRAN. AT 8334 LEAFY LN. BENT MB								0	0
FORCED INTERR	SB	EC 05				120032960007	F	########	0125	103	12	1236	VINES				1	LF	K42M									0	0
FORCED INTERR	SB	EC 05				120032960007	F	########	0125	134	4	536	VINES				1	LF	K42M									0	0
FORCED INTERR	CY	KL 43	21983	27DR	46658488	220032960006	T	########	0247	78	5	390	OTHER WILDLIFE	OTHER WILD	12723	E CYPRES	1	PR	466584855	RPLD LIMITER @ TR.								1	0
FORCED INTERR	CH	PW 08	40928	S37D	57590540	320032960000	F	########	0414	15	1	15	COLLISION	COLLISION	5121	OATES RD	1	LF	S37D	HIGH LOAD HIT WIRES, REF LF								1	0
FORCED INTERR	HC	HM 04	11024		53538198	120032960006	T	########	0500	51	6	306	FIRE	FIRE	9202	ROSEHAVI		TF	535381995	REMOVED 140 DROP AT POLE ON AN OPEN DELTA BANK. REMOVED METER COULD NOT READ DUE TO FIRE DAMAGE. CLOSED IN LIGHTER T/F IN AN OPEN DELTA BANK. REF TR. FIRE-RMVD								1	0
FORCED INTERR	CH	AD 08	40087	GE7	54626473	320032960007	T	########	0646	70	18	1260	TREE CLEARANC	TREE CLEAR	3221	WARDMOR	1	TF	546264735	TREES NEED TRIMMED @ B/C. REF TR. BJH								1	0
FORCED INTERR.	MP	OA 07	41508	J68Z	57590456	320032960006	F	########	0700	112	3	336	COLLISION	COLLISION	W SIDE OATES		1	LF	J68Z	REFUSED 2 PHASES (POWER FUSES) 200CR / HIGH LOAD CAME THROUGH HERE LAST AND DAMAGED WIRE UP AND DOWN OATES RD. NEED TO SEE IF WE CAN ELIMINATE THESE FUSED AI								1	0
FORCED INTERR	SU	AF 04	11773	F62R	48552254	120032960011	F	########	0715	0	0	0	SPLICE	SPLICE	12835	HARWIN I	2	LF	F62R	ISOLATED BAD SPAN PRIMARY BETWEEN 1/F # 6 & 7. REF TP. BOL URD PR. ***SUBCABED TWT		PR						1	0
FORCED INTERR	SU	AF 04				120032960011	F	########	0715	171	12	2052	SPLICE				2	LF	F62R									0	0
FORCED INTERR	SU	AF 04				120032960011	F	########	0715	171	21	3591	SPLICE				2	LF	F62R									0	0
FORCED INTERR.	BA	CS 03	40577		61616282	320032960010	T	########	0741	50	2	100	SQUIRREL	SQUIRREL	723	BARBERS H		TF	616162826	REFUSED 25 CONV.... SQUIRREL NO FOLLOW UP NEEDED ON WILD-LIFE PROTECTION. REF TR.								0	0
FORCED INTERR	SB	SR 01	21684	4SE	49577200	320032960016	F	########	0800	32	57	1824	SQUIRREL	SQUIRREL	226	VANDERPOE	1	LF	4SE	REFUSED LINE FUSE BACK ON SQUIRREL. SINGLE PHASE LINE FUSE IN REAR OF 302 DESBENER. NOT MARKED 3 SPANS SOUTH OF MEMORIAL. REF LF								1	0
FORCED INTERR	BL	GN 06	10619	N70S		120032960016	F	########	0800	97	6	582	SQUIRREL	SQUIRREL	2323	UNDERWC	1	LF	N9L	REFUSE MIDDLE PH MBL 80 T OUT BY BOL. ALSO TRIMMED TREES TOO REFUSE T/P. REF TP. BJH								1	0
FORCED INTERR	BA	CD 08	40362	42S	64573365	320032960012	T	########	0805	89	6	534	SQUIRREL	SQUIRREL	2204	VIKING LN	1	TF	545733624	REFUSED TR @ 2204 VIKING LN. REFUSED 30KD 257 NEED TO MAKE REPAIRS TO BT. LIGHT #311886 @ VIKING LN @ EAVES IN BAYTOWN. REF LF. REF TR. 30KD IS THE TR FUSE N								1	0
FORCED INTERR	BL	ST 11	10255	G22X	51556031	120032960022	T	########	0815	49	1	49	BU DISC OR BARI	DISC/BARRL	5104	JESSAMIN	1	TF	515560314	REPLACED BURNED FUSE BARREL ON A 25 KVA 7200 120/240 POWER XFMR. IN AN OPEN DELTA BANK. RPLD BAD BARREL ON TR.								1	0
FORCED INTERR	CY	KL 41	24740	38TF	46966170	220032960010	L	########	0818	90	1	90	CUST EQP RELA	CUST RLTD	16228	HADEN C	2	DR		URD Drops Open-No By-Pass MADE REPAIRS TO NEUTRAL AT URD PEDESTAL. RPRD DR.								1	0
FORCED INTERR	SU	BAR44	11882	S62U	46547355	120032960023	F	########	0827	148	49	7154	URD ELBOW	URD ELBOW	7334	CAMINO VI	2	LF	S62U	PR ON URD ORDER # 2267 REPLACED THE X AND Y ELBOW IN TRANSFORMER # 26 @ 7302 SAN SIMEON. ... REF TP. RPRD URD PR.								1	0
FORCED INTERR	SH	SP 05	31604	24HW	58533284	320032960017	F	########	0855	165	3	495	UNKNOWN	UNKNOWN	STRAWBERRY.		1	LF	24HW	BU 585332845 REF # 0100 12482 TR AT 8. HOU., REF LF, RPLD BU TR. BJH								1	0
FORCED INTERR	BL	EU 05	40723	G9A	52585076	120032960020	L	########	0858	54	1	54	OH SEC/DR CL NI	OH SC CL-N	8507	WESTCOT	1	DR		REPLACED ALL CONNECTIONS AT WH FOR BT. RPLD CONN @ WH.								1	0
FORCED INTERR	SH	FT 04	30392	C51T		320032960018	F	########	0901	49	74	3626	UNKNOWN	UNKNOWN	8523	ASHWYNE	1	LF	C51T	REFUSED WEST PHASE OF LINE FUSE / CAUSE UNKNOWN / CHAR. REF LF.								1	0
FORCED INTERR	MP	MP 02	41355	30QT	54589467	220032960014	T	########	0909	21	10	210	SQUIRREL	SQUIRREL	4619	MCKINNEY	1	TF	545894679	REFUSED TRX #SQUIRREL REF TR;								1	0
FORCED INTERR	CY	TB 45	21046	P58L	45706143	220032960017	F	########	0922	62	13	806	VINES	VINES	18207	BURKHAR	1	LF	P58L	REFUSED L/F P58L 267 @ 20638 ROBEHILL CHURCH REMOVED VINES OFF POLE IN EASEMENT. REF LF.								1	0
FORCED INTERR	SB	ADK43	20958	S35	49617088	120032960036	T	########	0938	53	2	106	OH SEC/DR CL HI	OH SC CL-H	5546	TEAGUE R	1	SC	496170888	RPLD CONN @ TR.								1	0
FORCED INTERR	SH	SP 03	30908	R70K	58536554	320032960021	T	########	0938	23	1	23	SQUIRREL	SQUIRREL	2835	PRESTON	1	TF	585365599	NEED TO HAVE TREES TRIMMED AWAY FROM BANK. REF TR. CRH								1	0
FORCED INTERR	GP	FR 43	21398	S3003	51631246	220032960020	L	########	0944	74	1	74	OH SEC/DR CL HI	OH SC CL-H	6210	SPINDLE C	1	DR		ISOLATED "T" T/P E5M4 ON BOK2267 , DUE TO BAD TERMINATOR. PM IN CONDUIT BUT WILL HAVE TO BE SPLICED. ALSO DOUBLE TIP EASEMENT. REF TP.								1	0
FORCED INTERR.	HM	LA 04	41247	E56M	54638423	220032960022	F	########	0955	122	13	1586	TERMINATOR	TERMINATO	4426	SANDYDAI	2	LF	E56M	REPLACED BOTH OUTAGE PHASES (L/F 91NL) LEFT 8VC ON - HIGH LOAD BRACKED. LEILE & CATV AND GOT OUT PHASES TOGEATHER ALL HLAP IN THE CLEAR #CRH.								1	0
FORCED INTERR	CH	GP 03	40792	91NL		320032960046	F	########	1000	57	2	114	COLLISION	COLLISION	2002	FEDERAL	1	LF	91NL	REAR 3 PH TP N8H HAS 80 IN IT INSTEAD OF 30 NEED TOO BLEW PARENT FUSE E M8L 801 NEED TOO CK OUT AND CHG OUT TOO 30T8 INSTEAD OF 80T8. REF LF BJH								1	0
FORCED INTERR	BL	GN 06	10619	N70S		120032960041	F	########	1009	66	6	396	SQUIRREL	SQUIRREL	2307	BLUE BON	1	LF	N9L	REFUSED A PHASE L/F 1-T-4E, REF LF;								1	0
FORCED INTERR	SU	WW 0	12416	1TM	49544985	120032960044	F	########	1013	37	44	1628	UNKNOWN	UNKNOWN	8910	BEECHNU	1	LF	1TM	REPL. BROKEN NTR-COLLIGNORDG L-R X001----84887 WITH NTR #0882263114 ------TYPE 1195/2-------RDG L-R X001----00000; REPLD NTR. CRH								1	0
FORCED INTERR	SH	TE 04	31085	T63A	56491435	320032960036	L	########	1015	59	1	59	COLLISION	COLLISION	2018	N MAIN ST	1	MT		REF LF								1	0
FORCED INTERR	BA	CD 01	40324	W67D	63585215	320032960040	F	########	1022	44	1	44	UNKNOWN	UNKNOWN	1020	BIRDSONG	1	LF	20DN	REPLACED ALL ELEC. CLAMPS AT WH. RPRD CONN @ WH.								1	0
FORCED INTERR	CH	BY 02	40159		54603352	320032960046	L	########	1100	52	1	52	CONTRACTOR-H	CON-NT HLF	1802	BOSTIC ST		DR		REPLACED 350 LUG IN IN AND OUT PEESTAL. BEND MESSAGE TO BUGARLAND NEED TO REPLACE PEDESTAL AT 7711 AND 7707 INTREPID CORRDBION CUST NOTIFIED. RPLD BEC CONN @ P								1	0
FORCED INTERR	SU	AF 11	11781	S95Q	48543341	120032960057	T	########	1108	175	8	1400	OH SEC/DR CL HI	OH SC CL-H	7711	INTREPID .	2	SC	485453445	RPLD BU BARREL ON TR.								1	0
FORCED INTERR	BA	CD 12	40349		64594220	320032960046	T	########	1110	26	5	130	BU DISC OR BARI	DISC/BARRL	5620	SJOLANDE		TF	645942265	ISOLATED BAD SPAN OF PRIMARY BETWEEN T/R @ 14285 AND 14288 MISTY MEADOWS SWITCHING ORDER 2273 (PRIMARY IN PIPE) REF TP. BOL URD PR. KUP								1	0
FORCED INTERR	SB	BM 06	21505	H35U	48584140	120032960056	F	########	1113	0	0	0	UNKNOWN	UNKNOWN	14295	MISTY ME	2	LF	H35U	PR								1	0
FORCED INTERR	SB	BM 06				120032960056	F	########	1113	119	6	714	UNKNOWN				2	LF	H35U									0	0
FORCED INTERR.	SB	BM 06				120032960056	F	########	1113	119	6	714	UNKNOWN				2	LF	H35U									0	0
FORCED INTERR	SH	FW 04	30441	K37G	59482154	320032960052	F	########	1130	105	112	11760	CONTRACTOR (H	CON-HLP	2502	FRIENDSW	1	LF	K37G	PR PM PR-FUSE BLOWN.								1	0
FORCED INTERR	CH	CV 06	40456	57GU	58583530	320032960053	F	########	1134	39	70	2730	SQUIRREL	SQUIRREL	UVALDE SO	FO	1	LF	57GU	CLEARED UP LIA ON CBP TRNS LOC @ 13108 FORCE / REFUSED L/F LEFT BERV ON / PLEASE SEND MESSAGE TO B/C TO REPLACE L/A @ B/C CONV. IN EASEMENT CAN NOT GET TRK TO IT. RE								1	0
FORCED INTERR	GA	TI K01	30102	C96J	65384481	320032960055	F	########	1140	48	20	960	COLLISION	COLLISION	1119	MAKATEA	1	LF	C96J	REFUSE LINE FUSE. REF LF								1	0
FORCED INTERR	BA	CD 01	40324	20DN	63585215	320032960056	T	########	1140	25	4	100	SQUIRREL	SQUIRREL	4308	GARTH RD	1	TF	635852136	REFUSED 100 CONV. REF TR. BJH								1	0
FORCED INTERR	SH	CK 04	31624	64HN	58509344	320032960056	F	########	1200	121	31	3751	BIRD	BIRD	14803	EVERGRI 2		LF	64HN	DB REPLACE BAD 12 KVA DISCONNECT ON TP. 64-HN. RPLD BAD DISC-TP BLOWN.								1	0
FORCED INTERR	KY	KT 43	11577	11AEL	38580534	120032960076	F	########	1220	65	6	390	UNKNOWN	UNKNOWN	2302	CLEMONS	1	LF	11AEL	ROAD OUT LIME NOTHING FOUND. REF LF.								1	0
FORCED INTERR	BL	GN 09	40915	G3P	53550225	120032960077	L	########	1220	147	1	147	OH SEC/DR CL HI	OH SC CL-H	2222	MAC ARTH	1	SC		REPLACED BAD CONN ON ONE LIGHTER LEG AT THE POLE ON OPEN WIRE SEC. RPLD CONN @ PL.								1	0
FORCED INTERR	GP	RU 02	41655	S45D	53620177	220032960042	F	########	1230	129	71	9159	CONTRACTOR-H	CON-NT HLF	330	W LITTLE Y	1	LF	S45D	SC NEED TO RPLC ANCHOR, PICKED UP 1 BP. L0 NEUTRAL, DUE TO TIME WARNER OVER BARDING CABLE, NEUTRAL BELOW CABLE, MADE TEMP REPAIRS ON GUY TO GET CLEARANCE ON CAB								1	0
FORCED INTERR	GA	STW0(	31005	E23E	62311585	320032960077	T	########	1230	54	3	162	BIRD	BIRD	22213	DEAF SMI	1	TF	623115873	IT HAS WILDLIFE PROTECTION ON IT. REF TR								1	0
FORCED INTERR	MP	AN 03	40017	Y26K	53608111	220032960046	T	########	1240	70	5	350	OH SEC/DR CL HI	OH SC CL-H	119	DORCHEST	1	SC	536081114	RPLCD CONN @ T/F.								1	0
FORCED INTERR	BA	HL 03	47598	B47D	61585936	320032960007	T	########	1240	38	9	342	VINES	VINES	113	TANGLEWC	1	TF	615893659	REFUSED 50 CONV. REF TR.								1	0
FORCED INTERR	BA	AT 41	41478	K43Z	60667123	320032960074	F	########	1250	59	13	767	VINES	VINES	19126	AKIN	1	LF	K43Z	REF LF								1	0
FORCED INTERR	RS	LV 03	30594	34ACP	55407229	320032960077	F	########	1300	78	11	858	UNKNOWN	UNKNOWN	1850	COUNTY R	1	LF	34ACP	REFUSED L/F. REF LF								1	0
FORCED INTERR	HM	TWG4	24511	S51R	53704356	220032960052	F	########	1310	35	67	2345	VINES	VINES	24011	SPRING C	2	LF	S51R	REF TP.								1	0
FORCED INTERR	CY	PI 45	2445F	S16C	45735057	320032960052	F	########	1310	54	25	1350	UNKNOWN	UNKNOWN	33318	ALTON W	1	LF	S16C	REF LF.								1	0
FORCED INTERR	GA	AL 09	30107	36UG	61429120	320032960085	F	########	1340	73	1	73	BIRD	BIRD	3935	AVENUE A	1	LF	36UG	REFUSED LF FEEDING PRI METERING. REF LF TLA								1	0
FORCED INTERR	BA	MB 08				320032960087	C	########	1348	0	0	0	HUMAN ERROR	HUMN ERRC	M808	CKT LOC		CL	M808	SWITCHING OUT M808 FOR 3 PH LINE. BID 3618 BENT CREW TO WRONG SWITCH CRH								1	1
FORCED INTERR.	BA	MB 08	3A163			320032960087	C	########	1348	23	1186	27278	HUMAN ERROR					CL	M808									0	1
FORCED INTERR.	BL	GT 04	10652	J20E	53564154	120032960085	F	########	1354	70	4	280	SQUIRREL	SQUIRREL	YOAKUM, BTW I		1	LF	J20E	REF LF								1	0
FORCED INTERR	KY	FZ 41	22771	R59E	44593075	120032960087	T	########	1400	42	6	252	UNKNOWN	UNKNOWN	22631	ELKANA D	2	TF	445930768	REBET CBP SWITCH IN URD TRANS. REBET TR.								1	0
FORCED INTERR	BA	HL 04	41173	R97X	62583542	320032960107	T	########	1422	17	1	17	SQUIRREL	SQUIRREL	5304	DECKER D	1	TF	625835422	already has wip. REF TR.								1	0
FORCED INTERR	GA	GA 07	31211	T2C	67385043	120032960106	L	########	1424	105	1	105	OH SEC/DR CL HI	OH SC CL-H	5712	LA FITTE	1	SC		RPLD CONN @ PL.								1	0
FORCED INTERR	MP	WO 02	41838	A90N	52604504	220032960066	T	########	1430	56	8	448	FLLNG TREE IN E	TREE FL/E	1303	DEL NORT	1	TF	526045043	REFUSED POWER POT IN OPEN DELTA BANK. REF TR.								1	0
FORCED INTERR	SH	UW 04	31461	E42A	60652171	320032960111	L	########	1440	81	1	81	CONTRACTOR-H	CON-NT HLF	1202	PHYLLIS S	1	DR		TREE CONTRACTOR GOT HUNG UP IN DROP FIRING UP AND BURNT ONE HOT LEG IN TWO SPLICED WIRE MIDSPAN LEFT WORKING. RPRD DR.								1	0
FORCED INTERR	SB	DV 03	10593	J52C	50563406	120032960096	F	########	1500	54	6	324	URD BUSHING	URD BSHING	38	WINDEMERE 2		PR	J52C	PER PRIM 8316 KIASTER @ 1800. ALL SERVICE BACK ON - REPAIRED BUSHING IN T# @ 38 WINDEMERE - 8316 UNABLE TO TELL IF IT IS X OR Y SIDE - HAS NO MAP ***NOTIFIED FRMN D BOW								1	0
FORCED INTERR	FB	RS 02	11389		43486250	120032960096	L	########	1510	114	1	114	INSULATOR	INSULATOR	1210	7TH	1	DR		NEED TO BEND 2-MAN CREW FIRST THING FRIDAY MORNING TO REPL. 40 BEC CONNECTIONS AT BEC POLE TRUCK ACCESS THRU ALLEY AT 1210 7TH ST 2-RETIRED HLP EMPLOYEES AFF								1	0
FORCED INTERR	HC	HM 05	12800	B86	54536188	120032960101	T	########	1522	307	2	614	OH SEC/DR CL HI	OH SC CL-H	5201	HIGGINS S	1	BU	545361880	REPLACE 25 KVA CBP W 37.5 KVA , SWITCH AND ARRESTER , RPLD BU TR. MATERIAL TRACKING COMPLETE TLA								1	0
FORCED INTERR	SB	TO 05	12675		51592548	120032960103	T	########	1525	28	4	112	BIRD	BIRD	6205	W 34TH A	1	TF	515925456	REFUSED A 25KVA POWER TP MR IN A CLOSED DELTA BANK. BROB. REF TR.								1	0
FORCED INTERR	GA	AL 10	30042	I35G	61412325	320032960116	T	########	1530	45	1	45	UNKNOWN	UNKNOWN	12148	15TH	1	TF	614123253	REFUSE TRANSF. REF TR.								1	0
FORCED INTERR	MP	NS 02	41542	3LS	54583531	220032960082	T	########	1641	81	8	488	BU DISC OR BARI	DISC/BARRL	3408	CHAPMAN	1	TF	545835318	REFUSE TRA ATC 3314 CHAPMAN. RPLD BAU BARREL ON TR. TLA								1	0
FORCED INTERR.	SB	WT 04	21862	KK7	50577551	120032960112	L	########	1640	42	1	42	ROTTEN POLE	ROTTEN PLI	10811	SMITHDA	1	PD		NEED TO CHANGE OUT 25FT SERVICE POLE . IN THE EASEMENT NON TRUCK ACCESSIBLE. PROMISED CUSTOMER FIRST THING IN THE MORNING. TLA								1	0
FORCED INTERR	MP	CR 04	41068	TA9	53587386	220032960063	T	########	1640	59	6	354	BU DISC OR BARI	DISC/BARRL	514	BYRNE ST	1	TF	535873888	REF TR.								1	0
FORCED INTERR	BL	DV 05	10598		50568258	120032960114	T	########	1650	314	2	628	OH SEC/DR CL HI	OH SC CL-N	7925	WESTHEIA		BU	505682569	RPLD BU TR.								1	0
FORCED INTERR	KY	MAR4(	24636	H4E	45674458	120032960115	F	########	1700	0	0	0	UNKNOWN	UNKNOWN	20131	HARDWIC	2	LF	H4E	PR BO 2273 BAD CABLE BETWEEN XFMR #30 AND XFMR # 31 OPEN Y IN 31 AND OPEN X IN XFMR 30 CL H4E AND CL Y IN XFRM 27 SWITCHING XFMR. REF TP								1	0
FORCED INTERR	KY	MAR4(				120032960115	F	########	1700	128	8	1024	UNKNOWN				2	LF	H4E									1	0
FORCED INTERR	KY	MAR4(				120032960115	F	########	1700	128	8	1024	UNKNOWN				2	LF	H4E									1	0
FORCED INTERR	RS	AV 02	30057	73HJ	58439018	320032960132	T	########	1704	57	3	171	SQUIRREL	SQUIRREL	801	HERRINGTC	1	TF	584390190	REF TR.								0	0
FORCED INTERR	GA	AL 06	30050	49LU	60420444	320032960133	T	########	1710	60	1	60	BU DISC OR BARI	DISC/BARRL	3240	TOWER RI	1	TF	604204446	REFUSED TRANS. REF TR.								1	0
FORCED INTERR	SH	SB 03	31038	UO5	58559328	320032960134	F	########	1754	27	28	756	SQUIRREL	SQUIRREL	3120	EARL ST	1	LF	UO5	REF LF								1	0
FORCED INTERR	CY	TB 47	2427D	S1980	48742330	220032960085	F	########	1800	52	21	1092	O/H PRIMARY CU	OH PR CLMF	8625	MATTHEW	1	LF	S1980	REPLACED BURNED UP HOT LINE CLAMP & STIRRUP ON LOAD SIDE OF LF # 1980. REF LF								1	0
FORCED INTERR	SH	TE 01	31064	1LT	56512433	320032960135	T	########	1800	98	13	1274	VINES	VINES	7763	RED ROBIN	1	TF	565124325	REF TR.								1	0
FORCED INTERR	FB	OR 03	11308	E88N	40450054	120032960122	F	########	1800	37	2	74	TREE CLEARANC	TREE CLEAR	GRUNWALD, W		1	LF	E88N	REFUSED EAIN TREE CLEARANCE. REF LF								1	0
FORCED INTERR	MP	UH 05	41724		55560254	220032960096	L	########	1800	84	1	84	CONTRACTOR-H	CON-NT HLF	1500	TELEPHOF		PD		BEND MESSAGE TO CENTER NEED TO REPLACE 35 FT POLE. FIRST THING TOMORROW. HIGH LOAD. HUNG 440 TWIST. NIGHT CREW SPLICED POLE. POLE 48 BROKE 8FT FROM GROUND. NO								1	0
FORCED INTERR	BA	CD 10	30911	8E2	63577215	320032960136	T	########	1820	50	11	550	UNKNOWN	UNKNOWN	315	WILLIAMS A	1	TF	635772134	REF TR.								1	0
FORCED INTERR	GP	RU 04	41666	K77P	53615236	320032960096	T	########	1901	59	3	177	COLLISION	COLLISION	5701	AIRLINE DI	1	TF	536152300	REF TR.								1	0
FORCED INTERR	GP	WF 05	24408	C97B	52694552	220032960096	T	########	1941	50	4	200	OTHER WILDLIFE	OTHER WILD	19530	WHITEWI	1	TF	526945527	removed a big racoon off tree refused. REF TR.								1	0
FORCED INTERR.	FB	BC 09	11312	W109	44436277	120032960142	T	########	1950	52	1	52	SQUIRREL	SQUIRREL	10610	VACEK RI	1	TF	444362773	REFUSED 10 KVA TRANSFORMER AND INSTALLED WILD LIFE PROTECTION . CAUSE WAS POSSIBLE SQUIRREL. . REF TR.								1	0
FORCED INTERR	MP	BY 09	41983	H27	53608558	220032960101	L	########	1957	124	1	124	TREE CLEARANC	TREE CLEAR	36	PENWAY ST	1	SC		NEED TREES TRIMMED OUT AND OPEN WIRE SECONDARIES REPLACED GIVE TO POWER CONSULTANT TO CREAT WORK ORDER FOR REHAB. RPLD CONN @ PL. TLA								1	0
FORCED INTERR	CH	LY 44	30427	56ACL	58625100	320032960146	T	########	2049	28	4	112	BU DISC OR BARI	DISC/BARRL	14218	1/2 MEAD	1	TF	586251070	REF TR.								1	0
FORCED INTERR	GA	GL 09	30508		68395003	320032960151	L	########	2118	235	1	235	OH SEC/DR CL HI	OH SC CL-H	1816	POST OFF		SC		RPLD BEC CONN @ PL-1 CUST								1	0
FORCED INTERR	BZ	BZ 08	30148		52277094	320032970001	T	########	0130	131	3	393	FIRE	FIRE	122	GRAPEVINE		TF	522770946	REMOVED DROPS FROM SER

FORCED INTERR	CH	CV 05	40445	2WK	5959506(	32003297002	F	########	0929	68	27	1836	UNKNOWN	UNKNOWN	739 BARNESVIL	1	LF	2WK										1	0
FORCED INTERR	SU	IM 48	12118	U28L	4751949(	32003297003	F	########	0931	169	56	9464	PRIMARY CONDU	PRIMARY	838 ROLLING MI	2	LF	U28L		PR									
FORCED INTERR	BL	ST 07	10230	B46P	5154010(	32003297003	F	########	0944	79	18	1422	BIRD	BIRD	5833 ARTEL	1	LF	B46P											
FORCED INTERR	SU	CE 01	11933		4753508(	32003297004	T	########	0955	35	3	105	SQUIRREL	SQUIRREL	14223 BAY GARI		TF	475350866											
FORCED INTERR	BZ	LJ 03	30621		5326342(	32003297003	T	########	1007	85	5	425	UNKNOWN	UNKNOWN	321 CHESTNUT		BU	532634279											
FORCED INTERR	MP	BH 05	40289	58JE	5458810(	32003297002	F	########	1015	47	7	329	SQUIRREL	SQUIRREL	GREGG @ STOI	1	LF	58JE											
FORCED INTERR	RS	AE 06	30075	A65M		32003297003	F	########	1030	36	12	432	COLLISION	COLLISION	1410 COUNTY R	1	LF	A65M											
FORCED INTERR	CH	UV 04	41769	R96C	5859506(	32003297003	F	########	1030	35	3	105	COLLISION	COLLISION	MANOR, N OF A	1	LF	R96C											
FORCED INTERR	HC	FD 12	10890	71AA	5053506(	32003297005	F	########	1030	48	62	3038	SQUIRREL	SQUIRREL	11222 BRAESRI	2	LF	71AA											
FORCED INTERR	BZ	RT 02	30875	K28W	5128500(	32003297003	F	########	1055	96	15	1425	SQUIRREL	SQUIRREL	329 BUFFALO TI	1	LF	K28W											
FORCED INTERR	SL	SE 03	22490	48DU	3457912(	32003297006	F	########	1131	24	6	144	CONTRACTOR-N	CON-NT HLF	ATCHISON, S O	1	LF	48DU											
FORCED INTERR	SH	PO 07	31823	54SW	6050221	32003297004	F	########	1144	0	0	0	PRIMARY CONDU	PRIMARY	15707 SPRINGC	2	LF	54SW		PR									
FORCED INTERR	SH	PO 07				32003297004	F	########	1144	157	7	1099	PRIMARY CONDU			2	LF	54SW											
FORCED INTERR	SH	PO 07				32003297004	F	########	1144	158	35	5530	PRIMARY CONDU			2	LF	54SW											
FORCED INTERR	BA	LP 05	41705	9AL	6254300(	32003297004	T	########	1211	26	6	156	UNKNOWN	UNKNOWN	908 W MAIN ST	1	TF	625430332											
FORCED INTERR	HM	AT 42	23140	S2225	6070101(	32003297003	T	########	1220	62	17	1054	UNKNOWN	UNKNOWN	142 CRYBABY LI	1	SC	607010117											
FORCED INTERR	RS	RZ 01	3573A	69FJ	5039021(	32003297005	F	########	1227	67	14	938	UNKNOWN	UNKNOWN	5015 OLD COFF	1	LF	69FJ											
FORCED INTERR	FB	WR 09	11254	3FS	3637956(	32003297008	F	########	1322	87	17	1479	VINES	VINES	424 MAHAN ST	1	LF	3FS	TF	363795632									
FORCED INTERR	MP	GG 01	40952		5554551(	32003297004	T	########	1330	26	5	140	SQUIRREL	SQUIRREL	6627 FAIRWAY I		TF	555455115											
FORCED INTERR	BA	HL 03	41166	E74K	6158658(	32003297005	L	########	1340	119	1	119	UNKNOWN	UNKNOWN	1703 HILLCRES	1	DR			SC									
FORCED INTERR	MP	HG 01	41099	R85	5655756(	32003297004	L	########	1359	68	1	68	TREE CLEARANC	TREE CLEAI	9529 1/2 E AVEN	1	SC												
FORCED INTERR.	SB	BM 01	21470	C19T	4859041(	32003297009	F	########	1400	45	11	495	FLLNG TREE OUT	TREE FLOE	10954 FULLERT	1	LF	C19T											
FORCED INTERR.	SH	TE 03	31066	A84A	5652101(	32003297006	F	########	1400	32	3	96	BIRD	BIRD	9506 TELEPHO	1	LF	A84A											
FORCED INTERR	BL	ST 01	10195	B30R	5154317(	32003297009	T	########	1420	74	8	592	TREE CLEARANC	TREE CLEAI	5415 JASON ST	1	TF	515431765	DR										
FORCED INTERR	MP	WO 02	41828	T54W	5259751(	32003297004	T	########	1423	34	1	34	BU DISC OR BARI	DISC/BARRL	1130 W 34TH	1	TF	525975129											
FORCED INTERR	SU	QV 04	12168	F78Z	4950609(	32003297009	F	########	1434	64	22	1408	VINES	VINES	3206 MEADOWC	2	LF	F78Z											
FORCED INTERR	CH	BY 04	40181	72F	5462609(	32003297006	L	########	1440	163	1	163	COLLISION	COLLISION	3217 LANGLEY I	1	DR			SC					PD				
FORCED INTERR	GP	KL 42	21936	R18D	4866136(	32003297005	F	########	1507	93	45	4185	VINES	VINES	13815 CEDAR P	1	LF	R18D	TF	486613876									
FORCED INTERR	BL	GN 06	10627	C5F	5255912(	32003297010	L	########	1516	32	1	32	OH SEC/DR CL HI	OH SC CL-N	2402 DORING 1	1	DR												
FORCED INTERR	RS	AE 06	30075	A65M		32003297007	F	########	1516	61	12	732	UNKNOWN	UNKNOWN	1410 COUNTY R	1	LF	77PH											
FORCED INTERR	BZ	LJ 01	30611	46GJ	5227950(	32003297007	T	########	1530	33	36	1188	BIRD	BIRD	56 PEPPERMINT	2	LF	46GJ											
FORCED INTERR	SH	FW 02	31793		5948523(	32003297007	T	########	1532	58	9	522	O/H PRIMARY CU	OH PR CLIMI	1533 W BAY ARI		PR	59485230											
FORCED INTERR	HC	MV 01	15244	T94R	5447519(	32003297010	T	########	1530	37	3	111	SQUIRREL	SQUIRREL	4615 SYLVIA LN	1	TF	54475193											
FORCED INTERR	MP	AN 01	40001	A51X	5360405(	32003297005	L	########	1540	154	1	154	TREE CLEARANC	TREE CLEAI	727 E 36TH	1	SC												
FORCED INTERR	CH	CV 02	40428	J88H	6058149(	32003297007	L	########	1550	65	1	65	FIRE	FIRE	16227 MARKET	1	DR												
FORCED INTERR	CH	CV 10	40466	J34A	5858521(	32003297007	F	########	1552	35	12	420	UNKNOWN	UNKNOWN	NADOLNEY @ C	1	LF	J34A											
FORCED INTERR	MP	MP 04	41368	7L7	5557703(	32003297005	L	########	1600	56	1	56	TREE CLEARANC	TREE CLEAI	7004 AVENUE P	1	DR			SC									
FORCED INTERR	SH	HA 02	31819	N76T	5750236(	32003297007	F	########	1615	0	0	0	OTHER	URD PRI	10203 KIRKASPI	2	LF	N76T		PR									
FORCED INTERR	SH	HA 02				32003297007	E	########	1615	375	15	5625	OTHER			2	LF	N76T											
FORCED INTERR	SH	HA 02				32003297007	E	########	1615	375	21	7875	OTHER			2	LF	N76T											
FORCED INTERR	FB	WA 43	14060	77GB	3950617(	12003297011	T	########	1618	54	1	54	UNKNOWN	UNKNOWN	9539 HIGHWAY	1	TF	395081792											
FORCED INTERR	GP	THW4	20931	79PJ	4966621(	32003297006	I	########	1618	115	29	3335	TREE CLEARANC	TREE CLEAI	13711 VINTAGE	2	LF	78PJ	LF	79PJ									
FORCED INTERR	GP	RU 01	41645	30G	5361259(	32003297006	T	########	1621	108	7	756	OH SEC/DR CL HI	OH SC CL-H	7014 WERNER S	1	TF	536125977	SC										
FORCED INTERR	SH	PJ 01	30358	F54E	5849957(	32003297006	F	########	1642	1	1	1	LIGHTNING	LIGHTNING	16718 GULF FW	1	LF	F54E	BU	584095701	SC								
FORCED INTERR	HC	BR 13	10815	88D	5153754(	12003297012	F	########	1650	32	18	576	FOREIGN MATER	FRGN MATR	4958 VALKEITH	1	LF	88D											
FORCED INTERR	GP	KI 43	21931	N66X	4967445(	32003297008	L	########	1654	123	1	123	OH SEC/DR CL HI	OH SC CL-H	9214 APPIN FAL	1	DR												
FORCED INTERR	SH	PA 08	31061	LL8	5854458(	32003297008	T	########	1721	118	2	236	UNKNOWN	UNKNOWN	1820 SOUTHMO	1	BU	585445805											
FORCED INTERR	CY	KL 49	20842	51CK	4767934(	32003297007	L	########	1801	181	1	181	FALLING DEAD TI	TR FL/DEAD	16402 RHINEFIE	2	DR												
FORCED INTERR	HM	HB 45	22401	S1338		32003297074	F	########	1831	65	58	4930	UNKNOWN	UNKNOWN	18918 ARTESIAI	1	LF	S1338											
FORCED INTERR	GP	HV 04	20523	R45G	5264003(	32003297007	L	########	1842	201	1	201	OH SEC/DR CL HI	OH SC CL-H	1434 WILSHIRE	2	DR												
FORCED INTERR	BA	MB 05	3C164	P92X	6763253(	32003297009	T	########	1843	43	3	129	SQUIRREL	SQUIRREL	14307 OAK FOR	1	TF	676325355											
FORCED INTERR	SB	CB 07	21450	U80I	5060535(	32003297014	F	########	1852	97	16	1552	UNKNOWN	UNKNOWN	CLAY @ HOLLIS	1	LF	U80I											
FORCED INTERR	SU	HY 11	11691	43H	4956642(	32003297014	T	########	1857	75	10	750	HUMAN ERROR	HUMN ERRC	10026 CHEVY CI	1	TF	495664285											
FORCED INTERR	MP	WO 12	41059		5259758(	32003297008	L	########	1904	42	1	42	OVERLOAD	OVERLOAD	913 W 34TH		DR												
FORCED INTERR	BA	MB 08	3D163	23KB	6759154(	32003297009	T	########	1917	68	8	544	SQUIRREL	SQUIRREL	6218 PLANTATK	1	TF	675915401											
FORCED INTERR	MP	NS 01	41537	ER4	5455544(	32003297008	T	########	2030	117	12	1404	FLLNG TREE IN E	TREE FLOE	2611 MILWAUKE	1	TF	545454444											
FORCED INTERR	SB	CB 01	21415	KW5	4959916(	32003297015	T	########	2120	201	5	1005	FALLING DEAD TI	TR FL/DEAD	1733 PINE VILLA	1	TF	495991685	SC						DR				
FORCED INTERR	GP	SA 41	21287	57BC	5081246(	32003297008	E	########	2224	41	1	41	OTHER	OTHER	8602 FLINTLOCI	1	MT												
FORCED INTERR	BA	CS 01	40556	75FQ	6162136(	32003297010	T	########	2230	31	12	372	UNKNOWN	UNKNOWN	512 CYPRESS A	1	TF	616213604											
FORCED INTERR	GA	AL 10	31158	94TR	6139447(	32003297010	F	########	2321	73	26	1898	TREE CLEARANC	TREE CLEAI	8401 FM 646	1	LF	94TR											
FORCED INTERR.	BZ	RT 01	30867	X34K	5131900(	32003297010	E	########	2335	229	17	3893	UNKNOWN	UNKNOWN	127 JAMISON DI	1	LF	X34K											
FORCED INTERR	CH	DV 08	40458	4DL	5958135(	32003298000	T	########	0114	104	11	1144	UNKNOWN	UNKNOWN	14907 ARUNDEL	1	TF	595813576											
FORCED INTERR	GP	KI 44				22003298000	C	########	0430	47	2916	137052	COLLISION	COLLISION	9635 SPRING C		CL	K344											
FORCED INTERR	SU	BAR47	13223	U44T	4754301(	12003298000	F	########	0651	0	0	0	TRANSFORMER	TRANSFRM	8810 HEATHERI	2	LF	U44T	BU	475420630									
FORCED INTERR	SU	BAR47				12003298000	F	########	0651	219	127	27813	TRANSFORMER			2	LF	U44T											
FORCED INTERR	SU	BAR47				12003298000	F	########	0651	374	3	1122	TRANSFORMER			2	LF	U44T											
FORCED INTERR	SB	DH 05	21533	85ABL	5061931(	32003298013	T	########	0731	132	6	792	VINES	VINES	8922 PINE VIST/	1	TF	506193161											
FORCED INTERR	SH	CG 04	30217		5754102(	32003298000	E	########	0741	66	8	528	SQUIRREL	SQUIRREL	2806 FOREST O		TF	575410261											
FORCED INTERR	MP	GG 06	10951		5554014(	12003298001	T	########	0822	56	7	392	VINES	VINES	6857 CRESTMO		TF	555401493											
FORCED INTERR	BZ	VL 04	3526C	29GJ	5623628(	32003298001	T	########	0834	103	8	824	LIGHTNING	LIGHTNING	210 BEACH DR	1	TF	562362863											
FORCED INTERR	SB	CB 01	21415	KW5	4959916(	12003298002	L	########	0855	68	1	68	FLLNG TREE OUT	TREE FLOE	20 SHADOW LN	1	DR												
FORCED INTERR	GA	AL 08	30047	W89O	6142502(	32003298001	E	########	0855	107	26	2782	LIGHTNING	LIGHTNING	11402 7TH	1	LF	W89O											
FORCED INTERR.	GA	AL 10	30045	33AAJ	6140821(	32003298001	E	########	0855	110	5	550	LIGHTNING	LIGHTNING	6911 GREENBRI	1	TF	614062149											
FORCED INTERR.	BA	MB 08	3D163	69KB	6759144(	32003298001	L	########	0902	109	1	109	VANDALISM	VANDALISM	6210 CAJUN WA	1	DR												
FORCED INTERR	CH	BE 02	40220	W18E	5561000(	32003298001	T	########	0915	55	1	55	SQUIRREL	SQUIRREL	8611 KNOXWOC	1	TF	556100046											
FORCED INTERR	GA	AL 07	30038	46AET		32003298002	F	########	0917	49	9	441	LIGHTNING	LIGHTNING	14012 S BAYLAN	1	LF	46AET											
FORCED INTERR	GA	GA 03	31229	H34X	6638628(	32003298002	F	########	0928	42	36	1512	LIGHTNING	LIGHTNING	8009 CHANNELI	1	LF	H34X											
FORCED INTERR	GA	HX 03	30659	Y84F	6241427(	32003298002	F	########	0931	58	70	4060	LIGHTNING	LIGHTNING	5500 FM 2004 RI	1	LF	Y84F											
FORCED INTERR	GA	GL 02				32003298002	C	########	0931	0	0	0	UNKNOWN	UNK - CES	GL02 CKT LOCI		CL	GL02											
FORCED INTERR	GA	GL 02	3G081			32003298002	C	########	0931	19	136	2584	UNKNOWN				CL	GL02											
FORCED INTERR	CH	SW 06	41685	K8W	5561743(	32003298002	T	########	0940	55	16	880	SQUIRREL	SQUIRREL	7425 CADDO RD	1	TF	556174349											
FORCED INTERR	GA	GA 02	31187	23EE	6738912(	32003298003	I	########	0949	98	7	686	LIGHTNING	LIGHTNING	43RD, N OF AVE	1	LF	23EE											
FORCED INTERR	SH	FW 04	30441	W66J	5948212(	32003298003	E	########	0955	73	4	292	BIRD	BIRD	2507 W.BAY ARI	1	LF	W66J											
FORCED INTERR	SU	WW 01	12406	N31P	4954529(	12003298003	T	########	0955	65	10	650	LIGHTNING	LIGHTNING	9795 BEECHNU	1	TF	495452924											
FORCED INTERR	GA	GL 07	30499	32EF		32003298004	F	########	1015	55	222	12210	LIGHTNING	LIGHTNING	3520 AVENUE P	1	LF	32EF											
FORCED INTERR	GA	GL 05	30460	23B	6838219(	32003298004	F	########	1020	42	88	3612	BU DISC OR BARI	DISC/BARRL	2211 31ST ST	1	LF	23B											
FORCED INTERR.	GA	GA 09	31225	6DB	6737951(	32003298005	F	########	1030	68	21	1428	LIGHTNING	LIGHTNING	4628 SHERMAN	1	LF	6DB											
FORCED INTERR	GP	RU 01	41645	30G	5361259(	22003298001	E	########	1039	69	7	483	TREE CLEARANC	TREE CLEAI	7018 WERNER S	1	TF	536125977											
FORCED INTERR	SU	FO 15	10869	I53X	5052042(	32003298003	F	########	1040	89	17	1513	BU DISC OR BARI	DISC/BARRL	12419 LIGHTCLI	2	LF	I53X											
FORCED INTERR	SU	BAR42	13212	89ACD	4653625(	12003298003	E	########	1051	37	123	4551	LIGHTNING	LIGHTNING	15716 BOSS GA	1	LF	89ACD											
FORCED INTERR	SU	AF 02	11759	G14P	4954214(	12003298004	F	########	1059	86	22	1892	LIGHTNING	LIGHTNING	8581 WILCREST	2	LF	G14P											
FORCED INTERR	SU	MC 02	12708		4951506(	12003298004	T	########	1057	50	5	250	VINES	VINES	306 FAIR OAK D		TF	495150649											
FORCED INTERR	GP	KI 46	28134	66JS	4968527(	32003298001	F	########	1059	44	36	1584	LIGHTNING	LIGHTNING	17210 SILVERTH	2	LF	66JS											
FORCED INTERR	GA	SCWD	30988	46NE	6839903(	32003298005	T	########	1101	549	1	549	LIGHTNING	LIGHTNING	427 SEAWALL B	1	BU	683990368	DB										
FORCED INTERR	BL	BR 12	10821	CD7		12003298004	E	########	1104	131	134	17554	LIGHTNING	LIGHTNING	8511 GREENBU	1	LF	CD7		PR									
FORCED INTERR	GP	KL 42	21936	H87N	4886359(	32003298002	T	########	1107	296	8	2368	LIGHTNING	LIGHTNING	11610 NORMON	1	BU	488635901											
FORCED INTERR	GA	GL 05	30460	R8R	6838217(	32003298005	F	########	1107	41	22	902	LIGHTNING	LIGHTNING	2309 32ND	1	LF	R8R											
FORCED INTERR	GA	KM 07	30605	17E	6347137(	32003298005	E	########	1108	103	26	2678	LIGHTNING	LIGHTNING	HWY 146 @ GOI	1	LF	17E	DB	634713751									
FORCED INTERR	BL	KB 09	10169	22CT	5255747(	12003298004	T	########	1110	68	12	816	VINES	VINES	2649 AMHERST	1	TF	525574730											
FORCED INTERR	SU	BAR42	13224	60AS	4753221(	12003298004	T	########	1113	295	1	295	LIGHTNING	LIGHTNING	15131 OLD RICH	1	BU	475322180											
FORCED INTERR	KY	FM 03	1107A	12AT	4160455(	12003298005	F	########	1113	28	17	476	LIGHTNING	LIGHTNING	GOYNES @ FM	1	LF	12AT											
FORCED INTERR	CY	TB 08	21015		4771734(	22003298002	T	########	1121	127	5	635	LIGHTNING	LIGHTNING	106 N CHERRY		TF	477173406	DB										
FORCED INTERR	CH	CV 03	41371	F69D	6059003(	32003298001	T	########	1123	38	8	304	SQUIRREL	SQUIRREL	15936 RIDLON S	1	TF	605900333											
FORCED INTERR	CY	PI 43				22003298002	C	########	1131	49	959	46991	LIGHTNING	TREE FLOE	21200 MUESCHI		PC	PI43											
FORCED INTERR	MP	AN 07	40044	F7D	5359033(	32003298024	L	########	1132	75	1	75	TREE CLEARANC	TREE CLEAI	519 W 25TH	1	DR												
FORCED INTERR	SB	GE 41	21193	N47U	4661924(	12003298005	F	########	1132	62	98	6076	LIGHTNING	LIGHTNING	16811 MACLEISI	2	LF	N47U											
FORCED INTERR	GP	LU 45	20610	S72C	5169943(	22003298002	E	########	1134	111	33	3663	URD BUSHING	URD BSHING	507 PINE WALK	2	LF	S72C	PR	516994342									
FORCED INTERR	BA	BW 05	41558	41M	6150621(	32003298006	L	########	1138	93	1	93	OH SEC/DR CL HI	OH SC CL-H	1231 SHOREWC	1	DR												
FORCED INTERR.	SB	ADK41	22142		4960006(	32003298005	T	########	1151	175	4	700	BU DISC OR BARI	DISC/BARRL	10875 KEMPWD		TF	496000642	DB										
FORCED INTERR.	BA	CD 04	41426		6559014(	32003298006	T	########	1152	23	2	46	UNKNOWN	UNKNOWN	8225 HIGHWAY		TF	655901458											
FORCED INTERR	SB	SA 46	22883	N58U	4762931(	12003298006	E	########	1152	0	0	0	TRANSFORMER	TRANSFRM	7319 STONE PIN	2	LF	N58U	BU	476293173									
FORCED INTERR	SB	SA 46				12003298006	E	########	1152	156	96	14976	TRANSFORMER			2	LF	N58U											
FORCED INTERR	SB	SA 46				12003298006	E	########	1152	453	6	2718	TRANSFORMER			2	LF	N58U											
FORCED INTERR	GA	GL 02	30471	45FH	6738958(	32003298006	F	########	1201	32	1	32	LIGHTNING	LIGHTNING	3600 MECHANIC	1	LF	45FH											
FORCED INTERR	SB	EC 07	21731	F20K	4958906(	12003298006	T	########	1207	69	6	414	LIGHTNING	LIGHTNING	11905 QUEENSE	1	TF	495890607											
FORCED INTERR	CY	TB 45	21046	S2284	4570456(	22003298004	F	########	1208	129	5	645	LIGHTNING	LIGHTNING	18614 FM 2920 F	1	LF	S2284											

REF LF.
REPLACED Y ELBOW IN NFMR # 11 AT 838 ROLLING MILL LEFT ON AND WORKING. RPLD ELBOW @ TR.
REFUSED SOUTH PHASE OF LF 846 P 807 TAKEN OUT BY A BIRD REF LF
RE-FUSED TRANSFORMER SQUIRREL REF TR.
REPLACED BAD 37.5 W 25 CONV 120/240. RPLD BU TR.
REFUSED TR AND LF. REF LF
REFUSED LINE FUSE--GULF COAST TREE CO MOVING TREES PUPPED NEUTRAL INTO PRIMARY-- TOOK BLACK OUT OF NEUTRAL. REF LF
REFUSED B PHASE 4,4HHHHOWER; REF LF.
REF LF.
REFUSED LINE FUSE. REF LF;
Independent tree contractor dropped limb on primary.. REF LF.
SWITCHED LOOP, ISOLATED BAD PRIMARY, CLOSED OPEN TIE AND TERMINAL POLE. REF TP ISOLATED BAD PRI BETWEEN TF #58 AND TF #67 PRI IN CONDUIT MAM

refused power pot in open delta bank. REF TR;
MADE REPAIRS TO BURNED OFF HIGH SIDE JUMPER ON A 50 KVA TRANS. RPLD CONN @ TR.
REF LF;
REMOVED VINES FROM TRANS AND PRI @ MAHAN 420 REFUSED 75 KVA TRANS AND REFUSED ROAD PHASE OF 3FB VINES. REF LF REF TR; BRB
SQUIRREL GOT ACROSS LOADBREAK OF SWITCH TO BOND WIRE, TOOK 3 FUSES TO GET BACK ON. BARREL WAS HANGING UP AND BREAKING FUSE. GREASED IT UP AND NOW WORKING FI
REPLACED #4 3/C TWIST SEC. & DROPS--CUST NOTIFIED. RPLD DR, RPLD SEC-1 CUST;
REPL. L1 2 NEUTRAL CLAMPS @ SEC POLE--TREES; RPLD SEC CONN @ PL, 1 CUST;
RM LIMB FROM B N C FABER / REFUSED LINE FUSE. REF LF.
REF LF.
RESET C&P TRAN REPLACE ELETRACAN CONNECTION, RESET TR, RPRD CONN @ WH; TLA
NORTH DISC. REPLACED BURNT UP BARREL ON TRAN BANK. RPLD BU BARREL ON TR.
REFUSED TP F782 CLEARED VINES OFF POLE CUST NOTIFIED LEFT ON AND WORKING. REF TP
REPLACED 35 R POLE WITH THE SAME RAN NEW SEC DROPS AND DROPS # 4 C/O SERVICE AT WH AT 3217 LANGLEY DUE TO MRT LOOP DAMAGE MRT QS3947480 IRED 5312 EXG. RPLD DR.
RM VINES OFF TRANS BANK REF LF, REF TR. TLA
REPLACED BAD NEUTRAL CONN AT THE WH RPLD CONN @ WH;
NEED TO RAISE #4 PRI & MEU @ 1430 CR-47 REF LF. MBG SENT TO B/C TLA
REF TP;
REPAIRED HI SIDE JUMPER ON TRANS, RPRD B/O PRI JUMP-TF NOT BLOWN.
TRK 8464 -- NEED WL P & C B P --HO DISC ------TRK ACCESS; REF TR. BRB
REPLACED CLAMPS AT POLE AND TRIMMED TREES CUST HAS FAULT INSIDE OF BUILDING FIXED UP WHEN MAKING CONNECTIONS CUST HAS NEW WIRING HOLES IN BREAKER BOX WE NEED
MADE UP AT WEATHERHEAD LEFT WORKING. RPLD CONN @ WH;
POSSIBLE BOL. DID NOT FIND 12 AMPS ON JIDDLE PH; REF LF.
2 W SERVICE. BAD CLAMP AT WEATHERHEAD, AND AT THE POLE, RPLD CONN @ WH, RPLD CONN @ PL.
CREWS REPAIRED 1 FAULT AND TERMINAL POLE STILL BLEW BACK. MADE REPAIRS TO "X" PRI IN TP475 @ 10011 KIRKASPEN ISOLATED BAD PRI BTWN TF475 AND TF474. (HM)

REPLACED BLOWN LIMITER FUSE & REFUSED 10 KVA 18 9 TRANS. 120- 240 V THERE WAS NOT ANY LOAD AT THIS METERPOLE. ELECTRICIAN WAS NOTIFIED BY PHONE. RPLD LIMITER @
TRM TREES. REF TP REF LF., REF LF REF TP;
PICKED UP 1 SPAN OF 1 1/0 OPEN WIRE SEC REFUSED 50 KVA T/R IN REAR OF THIS ADDRESS. TLA
REF LF RPLD BU TR, PU PR NEUT MATERIAL TRACKING COMPLETE TLA
REF LF
REPL CONN AT WH; RPLD CONN @ WH;
RPLD BU TR. MATERIAL TRACKING COMPLETE TLA
REPLACED DROPS FEEDING PHONE CO METER # W00846607 & PICKED UP DROPS FEEDING CATV CO METER # G7733846, RPLD DR. RPRD DR. TLA
REFUSED STEP POT # 1336 NO CAUSE FOUND. REF LF.
REPL CONN AT WH SHOWS URD BUT IS OVH SVC NEED TO REPL 1/0 3C TWIST DROP IN REAR MAY BE TRK ACSR, FROM BUSINESS BEHIND INSULATION BREAKING DOWN SEVERELY GET
it do have self protection. REF TR.
REF LF;
REFUSED 50 KVA LIGHTER TRAN PULL FUSE. REF TR.
NEED TO SEND MESSAGE TO CENTER TO REPLACE 140 DROPS TO 40 DROPS ABOUT 150 FT 140 DROPS TO SMALL TO CARRY LOAD. RPLD SEC CONN @ PL-1 CUST.
HAS WL NEED TREES TRIMMED REF TR. MBG SENT TO B/C TLA
NEED TREE TRIMMING ASAP REF TR. MBG SENT TO B/C TLA
REPLACED BUSH WORK ON TRANSFORMER,REPLACED 140 SECONDARIES AND DROPS DUE TO BIG TREE FALLING BRB
REPLACED BURN UP MTR DUE TO BURN UP MTR JANE RRD 71542 X1 BRB
REF TR.
TREES NEED TO BE TRIMMED AT 6218 AV E 1/2 REF LF. SENT MBG TO T&D. BRB
REFURED LINE FUSE. REF LF
14815 Anyone location of trans.. REF TR.
CREWS IN ROUTE CAR HIT POLE 2 SPANS EAST OF #2 44 E/P 25380 1 PHASE PRI WRAPPED AROUND 3 PHASE PRI. CREW CLEARED UP PRI. CREWS IN ROUTE TO MAKE REPAIRS TO LATERA
CREW INSTALLED FE

FORCED INTERR	SH	DE 05	30240	U67D	5954351	32003298606E	F	########	120	59	20	1380	LIGHTNING	LIGHTNING	1196	LYRIC LN	2	LF	U67D					REF TP	1	0
FORCED INTERR	GP	KI 44	22496	X39J	5068255	32003298004E	T	########	121	131	11	1441	TREE CLEARANC	TREE CLEAI	8318	WILLOW P	2	PR	506825509					REPLACE 12 K MATE LIMITER ON TRX, RPLD LIMITER @ TR, REF TR,	1	0
FORCED INTERR	CY	WL 42	24871	C37	3973507	32003298005Z	T	########	123	224	1	224	LIGHTNING	LIGHTNING	24702	FM 362 RI	1	TF	397350793						1	0
FORCED INTERR	GA	PHR01	30833	26M	6546112	32003298007C	T	########	123	87	8	696	UNKNOWN	UNKNOWN	1043	6TH	1	SC	654611208					replaced end hog on iron lead, RPRD BUSS WORK @ TR,	1	0
FORCED INTERR	SU	AF 05	12563	68UD	4855527	32003298006E	F	########	123	62	8	496	LIGHTNING	LIGHTNING			1	LF	68UD					REF LF	1	0
FORCED INTERR	GA	STW0(				32003298007I	C	########	123	0	0	0	OTHER	CONTAMINA	16000	FM 3005		CL	STW05	PD				CREWS REPLACED 55 FT POLE @ 16000 FM 3005 POLE FELL DUE TO CONTAMINA TION. ..B/O 333. .SECTION 31424	1	1
FORCED INTERR	GA	STW0(	30196			32003298007J	C	########	123	31	1374	42594	OTHER					CL	STW05						0	0
FORCED INTERR	GA	STW0(	31004			32003298007L	C	########	123	77	407	31339	OTHER					CL	STW05						0	0
FORCED INTERR	GA	STW0(	3G179			32003298007O	C	########	123	104	194	20176	OTHER					CL	STW05						0	0
FORCED INTERR	CY	HK 06				22003298010Z	C	########	123	162	7	1134	LIGHTNING	LIGHTNING	KATY HOCKLEY			PC	HK06	PR				NON 10%,NO AUTOMATION B/O PRI JUMPER A PHASE,.PT'S 878 CREW MADE PERM REPS B/O 204 WPS	1	0
FORCED INTERR	CH	BY 04	40181	72F	5462703	32003298007Q	T	########	123	44	8	352	LIGHTNING	LIGHTNING	3315	LANGLEY I	1	TF	546270349					REF TR,	1	0
FORCED INTERR	CY	PI 43	22143		4571322	32003298005S	T	########	124	134	1	134	VINES	VINES	18915	PHEASAN		PR	457132202					REPLACED LIMITER & REFUSED TRAN @ 18915 PHEASANT, RPLD LIMITER @ TR, REF TR,	1	0
FORCED INTERR	SB	WD 41	21551	55AI	4858439	32003298007Z	F	########	124	0	0	0	LIGHTNING	LIGHTNING	11900	WICKCHE	2	LF	55AI					REPL 250KVA/187KVA PDMT - AT BLDG 2000 PRI. LEFT ISOLATED BTWN NEW TRF AND TRF AT BLDG 800 TO EXPEDITE SERV.RESTORATION -PRI O K. BUT HAVE TO OPEN TP'S TO SW TO NORI	1	0
FORCED INTERR	SB	WD 41				12003298007Z	F	########	124	326	84	27384	LIGHTNING				2	LF	55AI						0	0
FORCED INTERR	SB	WD 41				12003298007Z	F	########	124	542	25	13550	LIGHTNING				2	LF	55AI						0	0
FORCED INTERR	CH	CV 06	40456	57GU	5858254	32003298007[	T	########	130	28	13	364	LIGHTNING	LIGHTNING	13208	FORCE S	1	TF	585825486					REFUSED TR. REF TR,	1	0
FORCED INTERR	SB	EC 05	21704	K12S		12003298007[	F	########	130	60	35	2100	VINES	VINES	4	PARKLAND C	1	LF	K12S					REFUSED LINE K128 AND T.P .28LN CLEARED VINES OFF T.P REF LF REF TP,	1	0
FORCED INTERR	FB	OB 42	10409	2SC	4553813	12003298007[	F	########	131	80	5	400	LIGHTNING	LIGHTNING	HARLEM RD @		1	LF	2SC						1	0
FORCED INTERR	SU	DL 42	12638	39KJ	4949153	12003298007[	F	########	131	70	1	70	BIRD	BIRD	4411	RINGROSE	1	LF	39KJ	TF	494915326			REF LF, REF TR,	1	0
FORCED INTERR	GP	RU 04	41666	K77P	5361520	32003298005E	T	########	132	125	7	875	LIGHTNING	LIGHTNING	5618	ZELMA DR	1	TF	536152081	DB				RPLD B/U DIBC-TF BLOWN,	1	0
FORCED INTERR	CY	TB 45	21030	45NJ	4571329	22003298005E	T	########	132	227	3	681	OH SEC/DR CL H	OH SC CL-H	18806	MEADOW	1	SC	457132912					replaced 4/0 paddle at trans., RPLD CONN @ TR,	1	0
FORCED INTERR	BL	BR 12	10821	CD7	5254733	12003298008Z	T	########	132	198	7	1372	LIGHTNING	LIGHTNING	8511	HATTON S	1	BU	525473340					REPL. 50 CONV. LITER POT IN OPEN DELTA BANK, RPLD B/U TR,	1	0
FORCED INTERR	KY	FZ 41	22611	H51I	4457456	12003298008E	F	########	133	84	16	1344	LIGHTNING	LIGHTNING	511	CONCORD	2	LF	H51I					REFUSED LINE FUSE TAKEN OUT BY LIGHTNING, PEK	1	0
FORCED INTERR	CY	KL 43	21990	P72L	4785351	32003298008S	T	########	133	196	1	196	UNKNOWN	UNKNOWN	12923	ENCHANT	1	SC	478535181					REPLACED LIMITER3	1	0
FORCED INTERR	SU	JM 44	12061		4850508	12003298008T	T	########	134	88	13	1144	BU DISC OR BARI	DISC/BARRI	3628	HIGHWAY		TF	485050864					REPLACED BURNED UP KEARNEY FUSE BARREL ON LIGHTER AFMR LEFT ON AND WORKING CUST NOTIFIED, RPLD B/U BARREL ON TH.	1	0
FORCED INTERR	GA	AL 09	30107	86QB	6142828	32003298006Z	F	########	134	70	2	140	LIGHTNING	LIGHTNING	AVE AT SUNSE		1	LF	86QB					REFUSED LF REF LF	1	0
FORCED INTERR	FB	EB 06	11295	12LS		12003298008E	F	########	134	51	125	6375	LIGHTNING	LIGHTNING	13619	POWELL	1	LF	12LS					REFUSED ALL 3 PHASED OF LF 12LS LIGHTING TX 3168. REF LF	1	0
FORCED INTERR	BL	GT 03	40851		5356744	12003298008S	T	########	134	260	1	260	LIGHTNING	LIGHTNING	3401	LOUISIANA		TF	535674439					REF TR,	1	0
FORCED INTERR	FB	RS 04	12725	6K5		12003298009C	F	########	134	64	127	8128	LIGHTNING	LIGHTNING	2207	4TH #30	1	LF	6K5					NEED TO REPLACE LINE FUSE NUMBER OKE WITH 6K5 .3 PHASE FUSE IS LOCATED AT MAIN AND 1ST IN ROSENBERG , REF LF,M&Q TO B/C TO RESTENCA. POLE WPS	1	0
FORCED INTERR	FB	RS 02	11395	M20	4348920	12003298009I	F	########	135	93	38	3534	LIGHTNING	LIGHTNING	1401	GEORGINA	1	LF	M20					REF LF,	1	0
FORCED INTERR	CY	KI 42	22309	37ADF	4669728	22003298006S	F	########	135	86	43	3698	LIGHTNING	LIGHTNING	10306	EARLING'	2	LF	37ADF					REFUSED B PHASE ON LINE FUSE #41ADF, REF LF,	1	0
FORCED INTERR	SB	CB 08	21451	D68C	5059353	12003298009A	F	########	135	123	38	4674	LIGHTNING	LIGHTNING	9214	NORTON L	1	LF	D68C					FOUND PRI UP AND IN THE CLEAR. REFUSED SINGLE PHASE LF D 88 C 50 T TAKEN OUT BY LIGHTNING , REF LF,	1	0
FORCED INTERR	FB	BV 42	11263	99TT	4351632	12003298009E	F	########	135	161	31	4991	LIGHTNING	LIGHTNING	BOB WHITE AT		1	LF	99TT						1	0
FORCED INTERR	FB	BV 42	11728	27UL		12003298009E	F	########	140	120	32	3840	LIGHTNING	LIGHTNING	4405	OLD ABAN	1	LF	27UL						1	0
FORCED INTERR	GA	SCWD	30679	33UJ	6839929	32003298006E	T	########	140	51	13	663	OH SEC/DR CL H	OH SC CL-H	37	SAN JACINT(	1	SC	683992915					CORROSION ON LIGHTER LEG CLAMP REPL, RPLD BEC CONN @ PL-+1 CUST	1	0
FORCED INTERR	GP	LK 02	20501	J88S	5262655	32003298006T	F	########	140	155	16	2480	LIGHTNING	LIGHTNING	1108	W NELDA	2	LF	J88S					refused tp REF TP	1	0
FORCED INTERR	FB	BV 42	11728	16UL		12003298010E	F	########	140	387	13	5031	LIGHTNING	LIGHTNING	RAIL ROAD W	C	1	LF	16UL						1	0
FORCED INTERR	FB	BV 42	12866	24HC	4451252	12003298010[	F	########	140	150	18	2700	LIGHTNING	LIGHTNING	4250	CLAY HEAI	1	LF	24HC					REFUSED LINE FUSE 34HC 25T OUT BY WEATHER, REF LF	1	0
FORCED INTERR	SB	GE 47	21183	U51V	4760033	12003298010T	T	########	140	53	1	53	LIGHTNING	LIGHTNING	18530	CLAY RD	1	TF	476003390					REFUSED 75 KVA TRANS. REF TR,	1	0
FORCED INTERR	BA	TRM0(	4101C		8654025	32003298010C	T	########	140	98	2	196	UNKNOWN	UNKNOWN	8614	OCEAN DR		TF	865402597					REFUSED TRANSFORMER	1	0
FORCED INTERR	CH	HR 03	41046	2G2	5559053	32003298006T	T	########	140	34	8	272	LIGHTNING	LIGHTNING	8013	1/2 KASHM	1	TF	555805306					REF TR,	1	0
FORCED INTERR	CH	GW 06	40905	A42U	5681025	32003298010T	T	########	140	195	7	1365	LIGHTNING	LIGHTNING	8102	RECORD S	1	BU	568102502					REPLACED 25 KVA CONV WITH SAME-7200-120/240. RPLD B/U TR,	1	0
FORCED INTERR	SH	DE 02	30250	76GD	5954627	32003298004F	F	########	141	85	14	910	SQUIRREL	SQUIRREL	3514	GREENWC	1	LF	76GD	TF	595462776			REFUSED TRANS. REF LF REF TR	1	0
FORCED INTERR	GP	DH 09	40500	X69G	5161421	22003298007I	F	########	141	202	5	1010	LIGHTNING	LIGHTNING	8002	ANTOINE	1	LF	X69G					REF LF	1	0
FORCED INTERR	GP	LK 06	22554	63PJ	5162935	22003298007Z	F	########	142	112	91	10192	LIGHTNING	LIGHTNING	8618	EASTER S'	1	LF	63PJ					REF LF,	1	0
FORCED INTERR	HC	MV 01	13138	38MD	5345903	12003298011C	F	########	142	58	14	812	LIGHTNING	LIGHTNING	8001	BURNETT	1	LF	38MD					REFUSED LF REF LF	1	0
FORCED INTERR	FB	RS 02	11395	8R7	4348837	12003298011Z	F	########	142	54	42	2268	LIGHTNING	LIGHTNING	AVE J, E OF LO(		1	LF	8R7					REFUSED BOTH PHASES OF M20 8R7. REF LF,	1	0
FORCED INTERR	SU	AF 06	11796	I54M	4854428	12003298011Z	F	########	142	0	0	0	UNKNOWN	UNKNOWN	12421	WINDJAM	2	LF	I54M	PR				BAD 8PAN PRIMARY BETWEEN TRF # 87 & TRF # 66 REFER TO B/O 2341. REF TP. I80L URD PR, RPLD LIGHTNING ARRESTOR. ---WAS BUSCABED TWT	1	0
FORCED INTERR	SU	AF 08				12003298011Z	F	########	142	343	8	2744	UNKNOWN				2	LF	I54M						0	0
FORCED INTERR	SU	AF 06				12003298011Z	F	########	142	343	14	4802	UNKNOWN				2	LF	I54M						0	0
FORCED INTERR	HC	BL 07	10796	X71L	5052625	12003298011E	F	########	143	37	30	1110	LIGHTNING	LIGHTNING	12515	VITRY LN	2	LF	X71L					REF TP;	1	0
FORCED INTERR	SU	DL 44	14068	S19S	4851936	12003298011F	F	########	143	61	16	976	LIGHTNING	LIGHTNING	327	DULLES	1	LF	S19S	TF	485193409			REF LF REF TR,	1	0
FORCED INTERR	GP	KI 43	21931	89ADF	4967422	22003298007S	T	########	143	385	6	2310	LIGHTNING	LIGHTNING	9827	FENCHURI	1	BU	496742215					REPLACED 75 KVA 19.9 120/240 WITH SAME. RPLD B/U TR,	1	0
FORCED INTERR	SU	AF 04				12003298011G	C	########	143	0	0	0	LIGHTNING	LIGHTNING	AFD4	CKT LOCI		CL	AF04					CREW IN ROUTE TO CIRCUIT WHEN CLEAR UP ON TROUBLE ORDERS	1	1
FORCED INTERR	SU	AF 04	1G285			12003298011G	C	########	143	28	1168	30368	LIGHTNING					CL	AF04						1	0
FORCED INTERR	HC	BL 07	10796	X73L	5052628	12003298011E	F	########	143	169	30	5070	LIGHTNING	LIGHTNING	7808	POITIERS I	2	LF	X73L	BU	505262828			RPLD B/U BARREL ON TP RPLD B/U TR;	1	0
FORCED INTERR	BL	ST 06	10222	78J	5154220	12003298011G	T	########	143	325	7	2275	LIGHTNING	LIGHTNING	5535	EDITH ST	1	BU	515422039					REPLACED BAD 50 KVA WITH SAME IN OPEN DELTA BANK LIGHTER. RPLD B/U TR,	1	0
FORCED INTERR	SU	AF 07	11804	A13W		12003298012C	F	########	143	186	71	13208	LIGHTNING	LIGHTNING	11922	HIGH STA	1	LF	A13W					REF LF,	1	0
FORCED INTERR	GP	BA 45	21148	Y33T	5067407	22003298007E	F	########	144	268	214	57352	SPLICE	SPLICE	14222	WUNDER 2		LF	Y33T	PR				ISOLATED BAD 8PAN OF PRI BETWEEN TRX # 2 & TRX # 1 B0R2308 ACCORDING TO URD LAMBERT PRI IS MARKED WRONG PRI IN CONDUIT, REF TP. I80L URD PR,	1	0
FORCED INTERR	SH	GV 06	30537	3T9	5553437	22003298008Z	T	########	144	414	6	2484	VINES	VINES	8614	WESTOVE	1	TF	555343757					RAM VINES- REPL. BLOWN LIA. REFUSE TR REF TR, RPLD LIGHTNING ARRESTOR,	1	0
FORCED INTERR	SU	WW 0	12418	27X	4854748	12003298012S	F	########	144	184	21	3864	LIGHTNING	LIGHTNING	7402	PELLA DR	1	LF	27X					REFUSED LF 27X LEFT ON AND WORKING LIGHTNING CUST NOTIFIED, REF LF	1	0
FORCED INTERR	CY	KL 47	24630	91LV	4668220	22003298008H	T	########	145	11	2	22	LIGHTNING	LIGHTNING	17220	GRANT R	1	TF	466822078					REF 25 KVA 1/F	1	0
FORCED INTERR	SU	CE 01	12965		4753536	12003298014S	T	########	145	519	4	2076	TREE CLEARANC	TREE CLEAI	14114	TOWNE V		BU	475353873					REPLACED BAD 50 KVA ON TRANS 7200 120/ 240 WITH SAME PICKED UP TRAN BUG RETURNED BELLAIRE. RPLD B/U TR,	1	0
FORCED INTERR	MP	NS 06	40955	AS3		22003298008E	F	########	145	275	75	20625	INSULATOR	INSULATOR	3614	DES CHAU	1	LF	AS3	PR				REPL. ROTTEN BUCKARMS W/ STEEL CONSTRUCTION. REFUSE LF, PIU PR-FUSE BLOWN,	1	0
FORCED INTERR	MP	GS 22				22003298009E	C	########	145	0	0	0	LIGHTNING	LIGHTNING	GS22	CKT LOCI		CL	GS22					B/O 203.. NON 10% NO AUTOMATION, WEATHER IN AREA.. EWING ECDC TRIED 0 622 HOT WPS..	1	1
FORCED INTERR	MP	GS 22	2G310			22003298009E	C	########	145	19	1045	19855	LIGHTNING					CL	GS22						0	0
FORCED INTERR	BL	BI 46	14235	F85C	5155919	12003298015E	F	########	145	249	98	24402	LIGHTNING	LIGHTNING	4536	LIVE OAK I	1	LF	F85C	DB		PR		REPLACE CUT OUT ON B PHASE OF LF (F85C) @ 18 20 /REPACE LIMITER'S @ (12 PAMELIA/17 15/12SPAMELLIA/18 39) TRIM TREES MAXWELL (3222). RPLD B/U DIBC-LF BLOWN. RPLD LIMITE	1	0
FORCED INTERR	BL	BI 09	10088	K20T	5255147	12003298015I	F	########	145	124	20	2480	LIGHTNING	LIGHTNING	FAIRMONT @ JI		1	LF	K20T					-RE-FUSED LINE FUSE THE NUMBER DID NOT MATCH THE NUMBER ON THE POLE, REF LF	1	0
FORCED INTERR	FB	EB 06	11295	36MU	3744654	12003298015Z	F	########	145	84	10	840	LIGHTNING	LIGHTNING	14800	POWELL	1	LF	36MU						1	0
FORCED INTERR	SH	DE 05	30240	U67D	5954351	32003298011F	F	########	145	133	20	2660	SPLICE	SPLICE	1166	LYRIC LN	2	LF	U67D	PR				REF TP; RPRD URD PR, RPLD TERMINATOR, . WPS	1	0
FORCED INTERR	GP	HV 03	22208	78JS	5263539	22003298009S	F	########	150	123	2	246	LIGHTNING	LIGHTNING	1109	BLUE BELL	1	LF	78JS					REFUSED LF, REF LF	1	0
FORCED INTERR	SU	AF 04	12446	38DE		12003298015H	F	########	150	120	151	18120	PRIMARY CONDU	PRIMARY			1	DB	38DE	PR				PICKED UP 8PAN OF PRI & REFUSED LF RPLCD DISCONNECT	1	0
FORCED INTERR	CY	PI 43	24118	51ABL	4472734	32003298004T	T	########	150	102	2	204	LIGHTNING	LIGHTNING	16223	BEAVER I	1	TF	447273404						1	0
FORCED INTERR.	KY	WA 42	27828	78ABM	3852519	12003298016I	F	########	151	34	2	68	LIGHTNING	LIGHTNING	3321	GUYLINE R	1	LF	78ABM						1	0
FORCED INTERR	SU	AF 04	12446	51DE	4854851	12003298016Z	T	########	151	394	1	394	LIGHTNING	LIGHTNING	11724	BELLAIRE	1	BU	485485129					REPL. 50 KVA 7200-120/240 VOLT TRANSFORMER WITH THE SAME. RPLD B/U TR;	1	0
FORCED INTERR.	HC	BL 05	10797	V84F	5052730	12003298016S	T	########	151	328	11	3608	LIGHTNING	LIGHTNING	12308	FONDREI	1	BU	505273043					RPLD B/U TR,	1	0
FORCED INTERR	SH	CC 01	30176	65JM	5452545	32003298012I	F	########	151	101	50	5050	LIGHTNING	LIGHTNING	5021	RICHFIELC	1	LF	65JM					REF LF	1	0
FORCED INTERR	MP	GS 22	40769	61MT	5457719	22003298010T	T	########	151	336	8	2688	LIGHTNING	LIGHTNING	3514	CANAL ST	1	BU	545771906					REPL. CLOSED DELTA BANK ONE-40- & TWO 37 5 CONV 7 2 120/240 W ONE 75 AND TWO 50 CONV 7200 120/240 CONV XFMR, RPLD B/U TR.	1	0
FORCED INTERR	HC	FD 02	12393	W36S	5052445	12003298016H	T	########	151	540	19	10260	LIGHTNING	LIGHTNING	12007	E CIRCLE	2	BU	505244525					RPLD B/U TR,	1	0
FORCED INTERR	CH	NM 04	41526	4D2	5757850	32003298012H	F	########	151	30	19	570	LIGHTNING	LIGHTNING	12634	COULSON	1	LF	4D2					RODE OUT AND REFUSED BOTH PHASES OF LF 4D2--WEATHER, REF LF	1	0
FORCED INTERR	SH	WE80	31157	17DS	5948928	32003298012F	F	########	151	155	14	2170	LIGHTNING	LIGHTNING	TEXAS @ MEDI	3	LF	99EH					REF LF	1	0
FORCED INTERR	SB	SA 48	21904	29KQ	4762717	12003298018S	T	########	151	35	9	315	LIGHTNING	LIGHTNING	13502	WEIMAN I	1	TF	476271702					REFUSED 25 KVA TRANS , REF TR,	1	0
FORCED INTERR	GA	KM 07	30605	17E	6347331	32003298012S	F	########	152	243	77	18711	OH PRIMARY CU	OH PR CLME	524	LOUISIANA	1	LF	17E	PR				RPLD B/O PR JUMPER-FUSE BLOWN.	1	0
FORCED INTERR	SU	RO 07	12242	T76M	4953540	12003298018E	F	########	152	130	52	6760	LIGHTNING	LIGHTNING	10111	BISSONN	2	LF	T76M						1	0
FORCED INTERR	HC	HOC0	11162	W87I	5153801	12003298017C	T	########	152	80	10	800	LIGHTNING	LIGHTNING	11202	WAXWIN	1	TF	515380127					REF TR;	1	0
FORCED INTERR.	SH	PA 04	30777	C40F	5755814	32003298013C	F	########	152	79	7	553	LIGHTNING	LIGHTNING	830	SHAVER ST	1	LF	C40F					refused 1# phase at LF REF LF	1	0
FORCED INTERR	GA	PHR01	30869	93HN	8546256	32003298013I	T	########	152	458	65	29770	LIGHTNING	LIGHTNING	402	AVENUE A	1	BU	854625689					RPLD B/U TR.	1	0
FORCED INTERR	BL	JN 02	10005	7A9	5056014	12003298017E	F	########	153	150	35	5250	TREE CLEARANC	TREE CLEAI	9506	MEADOWE	1	LF	7A9					REFUSED 2 PHASES OF LINE FUSE 7A9 50 T NEED TO BEND TREE TRIMMERS A.B.A.P. TO TRIM EASEMENT REF LF, RMVD TREE,A.B8 OFF PR, M&Q TO B/C TREE TRIM WPS	1	0
FORCED INTERR	SU	RO 42	14015	S3720	4952544	12003298017E	F	########	153	122	3	366	LIGHTNING	LIGHTNING	DOVER @ DORI		1	LF	S3720					REF 2 167 STPDWN, REF LF	1	0
FORCED INTERR	FB	OR 02	11302	B11F	4045318	12003298017E	F	########	154	92	2	184	LIGHTNING	LIGHTNING	HWY 59 @ FM 3		1	LF	B11F	PD				NEED TO REPLACE POLE 35' CL 4 CAN GET WITH TRUCK WHEN DRY REF LF RMVD DOWNED PL, M&Q TO B/C REPL 8KN 38TPOLE WPS	1	0
FORCED INTERR	MP	WO 12				22003298010T	C	########	154	0	0	0	TREE CLEARANC	TREE CLEAI	TREE IN PRI @			CL	WO12					NON 10% CREW IN ROUT WB 1231 THORNTON,NO AUTOMATION. REMOVE TREE FOR PRI @ 860 BETHLEHEM. NEED FOLLOW UP TO TRIM TREES. BENT TO B/C	1	1
FORCED INTERR	MP	WO 12	2G307			22003298010T	C	########	154	41	535	21935	TREE CLEARANC					CL	WO12						0	0
FORCED INTERR	MP	WO 12	21952			22003298010T	C	########	154	80	930	74400	TREE CLEARANC					CL	WO12						0	0
FORCED INTERR	BL	ST 05	10214	E45X	5154343	12003298018Z	L	########	154	120	1	120	OH SEC/DR CL H	OH SC CL-H	813	S ATWELL S	1	DR							1	0
FORCED INTERR	SU	AF 09	11818	89DQ	4853748	12003298018H	F	########	154	175	11	1925	LIGHTNING	LIGHTNING	11800	BISSONN	1	LF	89DQ	TF	485384192			REPLACED CONN ON ONE HOT LEG AND THE HI LEG AT THE WH RPLD CONN @ WH.	1	0
FORCED INTERR	GA	KM 06	30603		6248816	32003298013E	T	########	154	42	1	42	LIGHTNING	LIGHTNING	1925	HIGHWAY		TF	624881622					REFUSED 3 PHASE OF LINE FUSE 8R D Q 45 T ALSO PULLED VINES OFF OF TRANS BANK 3 167 AND REFUSED ALL 3 TRANS. REF LF REF TR	1	0
FORCED INTERR	CH	PW 03	41629	R19C	5660101	32003298013E	F	########	154	61	40	2440	LIGHTNING	LIGHTNING	14235	FLAIR DR	2	LF	R19C					REF TR,	1	0
FORCED INTERR	SU	AF 02				12003298018E	C	########	155	0	0	0	OTHER	X-ARM	11315	NEW BRC		CL	AF02					REF TP	1	0
FORCED INTERR	SU	AF 02	1G283			12003298018E	C	########	155	37	734	27158	OTHER					CL	AF02					SECTION #11758 CREW REPLACED BROKEN CROSS ARM & PICKED UP 1 8PAN OF PRIMARY IN REAR OF 11315 NEWBROOK. SEE B/O 124 CAL	1	1
FORCED INTERR	SU	AF 02	11757			12003298018E	C	########	155	49	493	24157	OTHER					CL	AF02						0	0
FORCED INTERR	SU	AF 02	11758			12003298018E	C	########	155	55	204	11220	OTHER					CL	AF02						0	0
FORCED INTERR	SU	AF 02	11756			12003298018E	C	########	155	148	78	11544	OTHER					CL	AF02						0	0
FORCED INTERR	BA	UW 05	31115	U40G	8154116	32003298013E	F	########	155	77	79	6083	LIGHTNING	LIGHTNING	10200	N H	1	LF	U40G					REF LF	1	0
FORCED INTERR	GP	KL 48	21911	R33P	4867311	22003298011Z	T	########	155	556	8	4448	LIGHTNING	LIGHTNING	11706	STILLWA'	2	BU	486731129					REPLACED 75 KVA URD TRANS WRAME. RPLD B/U TR	1	0
FORCED INTERR.	MP	GS 22	40769	E19C	5457729	22003298011S	T	########	155	210	12	2520	LIGHTNING	LIGHTNING	3406	SALTUS S'	1	BU	545772931					REPLACED 50 KVA CONV 7200-120/240. RPLD B/U TR	1	0
FORCED INTERR.	GP	LK 06	22554	80CN	5162646	22003298011E	T	########	155	70	7	490	LIGHTNING	LIGHTNING	9905	BONAZZI S	1	TF	516264669					REF TR,	1	0
FORCED INTERR	GP	DH 09	40503	E84M		22003298011F	T	########	160	367	130	47710	ROTTEN POLE	ROTTEN PU	W.TIDWELL @		1	LF	E84M	PD				STUMBED 40' CL 3 POLE NEED TO REPL ASAP. TRK AC88L FROM TIDWELL REF LF E84X LIF E44M WAS NOT OUT REF LF STUMBED UP PL	1	0
FORCED INTERR	BA	CD 03	40345	R54X		32003298014C	F	########	160	38	22	836	LIGHTNING	LIGHTNING	6218	BARKALOC	1	LF	16DN					REF LF WPS	1	0
FORCED INTERR	FB	OR 02	11302	77KG	4045908	12003298019Z	F	########	160	87	1	87	LIGHTNING	LIGHTNING	1327	HARDIN	1	LF	77KG					4 POLES NORTH OF LIF 77KG NEED TO REPLACE 40 CL 4 POLE GET WITH TRUCK, REF LF M&Q TO B/C REPL 40/CL4 POLE WPS	1	0
FORCED INTERR	SH	SH 08	30928	95AF	5753497	32003298014S	T	########	160	3	153	459	CUST EQP RELAT	CUST RLTD	3925	ARLINGTO	1	TF	575349704					****** CUSTOMER OWNED DISTRIBUTION CUST HAS FUSE BLOWN ON THEIR SIDE ****** BJH	1	0
FORCED INTERR	CY	PI 45	2A126	53ML	4473145	22003298012C	T	########	160	266	2	532	LIGHTNING	LIGHTNING	19614	INDIGO L	1	BU	447314569					REPLACED 37 5 19 8 W 50 KVA 120/240. RPLD B/U TR.	1	0
FORCED INTERR	FB	OR 03	11307	F38T		12003298019C	F	########	161	108	108	11342	LIGHTNING	LIGHTNING	FM 1875	S OF F-	1	LF	F38T						1	0
FORCED INTERR	FB	WA 43	11332

FORCED INTERR	BA	BT 03	40373	Z80W	6357438	32003298015 1 F	########	1641	64	3	192	LIGHTNING	LIGHTNING	1931 PARK	1	LF	Z80W								
FORCED INTERR	BL	BR 12	10821	P29	5254623	12003298021 E T	########	1645	515	30	15450	LIGHTNING	LIGHTNING	3222 ELMRIDGE	1	BU	525462331								
FORCED INTERR	BA	NP 44	42043	60MM	6165800	32003298015 2 F	########	1640	158	4	632	LIGHTNING	LIGHTNING	16800 LINDSTRI	1	LF	60MM	TF	616580052	PR					
FORCED INTERR	HC	GV 03	10912		5453924	12003298022 C T	########	1655	48	16	768	VINES	VINES	5763 HERON DR		TF	545392484								
FORCED INTERR.	MP	HM 02	11014	J48Y	5454531	22003298013 E F	########	1655	58	24	1392	LIGHTNING	LIGHTNING	4706 YELLOWS'	1	LF	J48Y								
FORCED INTERR.	CH	PW 03	41629	R19C	5860102	32003298054 F	########	1655	0	0	0	URD BUSHING	URD BSHING	14318 DARTWO	2	LF	R19C	PR							
FORCED INTERR.	CH	PW 03				32003298054 F	########	1655	304	20	6080	URD BUSHING			2	LF	R19C								
FORCED INTERR.	CH	PW 03				32003298054 F	########	1655	304	20	6080	URD BUSHING			2	LF	R19C								
FORCED INTERR.	SL	SE 01	28766	27JG	34583001	12003298022 1 T	########	1655	248	1	248	SQUIRREL	SQUIRREL	1531 LAKEFIELD	1	TF	345830014								
FORCED INTERR	SU	RO 02	12259		48538096	12003298022 T	########	1655	214	1	214	LIGHTNING	LIGHTNING	11650 1/5 W BEI		BU	485380986								
FORCED INTERR	BA	TRMOC	43168	62AAK	66586461	32003298015 T	########	1655	94	1	94	LIGHTNING	LIGHTNING	4720 KENDALL	1	TF	665864612								
FORCED INTERR	MP	UN 01	41707	E41C	5555112	22003298013 7 F	########	1701	93	34	3162	LIGHTNING	LIGHTNING	8051 PINEWAY	1	LF	E41C								
FORCED INTERR.	FB	WR 10	11259	W545	3739119	12003298022 4 T	########	1704	133	1	133	SQUIRREL	SQUIRREL	3822 LEES LN	1	TF	373911902								
FORCED INTERR.	GP	DH 09	40590		51614209	22003298013E T	########	1704	48	1	48	LIGHTNING	LIGHTNING	6000 ANTOINE D		TF	516142058								
FORCED INTERR.	MP	MP 01	41378	11DH		22003298013E F	########	1706	62	89	5518	LIGHTNING	LIGHTNING	7710 AVENUE	1	LF	11DH								
FORCED INTERR.	HM	AD 10	41977	JU6	54640182	22003298014C T	########	1708	139	6	834	LIGHTNING	LIGHTNING	1717 STRAWN F	1	TF	546401824								
FORCED INTERR	CY	HK 06	21714	28LB	43674109	22003298043 F	########	1711	78	11	858	LIGHTNING	LIGHTNING	BECKER, E OF	1	LF	28LB								
FORCED INTERR	FB	WR 10	11160	R29S		12003298022E F	########	1711	95	25	2375	LIGHTNING	LIGHTNING	6218 WEST CRE	1	LF	RO5	PD							
FORCED INTERR	CY	WL 41	21160	41AB	40692540	22003298047 T	########	1721	55	8	330	SQUIRREL	SQUIRREL	2115 PENICK RI	1	TF	406925434	PR							
FORCED INTERR	FB	NV 02	11223	G40I	41400491	12003298023C F	########	1722	155	7	1085	LIGHTNING	LIGHTNING	7550 DALE DOD	1	LF	G40I								
FORCED INTERR.	FB	WR 12	11748	49GW	38364200	12003298023 1 T	########	1724	159	4	636	TREE CLEARANC	TREE CLEAR	1830 OAKWOOD	1	TF	383642062								
FORCED INTERR	GP	KI 43	2A133	61JA	49670293	22003298014E T	########	1724	50	2	100	LIGHTNING	LIGHTNING	10102 1/2 LOUE	1	TF	496702939								
FORCED INTERR.	FB	NV 02	11222	59EG	41405211	12003298023 2 T	########	1725	189	2	378	LIGHTNING	LIGHTNING	13200 BLK. OF F	1	LF	59EG								
FORCED INTERR.	CH	NM 01	41501	T15	58581241	32003298016C F	########	1725	0	0	0	LIGHTNING	LIGHTNING	930 LEAR ST	1	LF	T15	BU	585812414						
FORCED INTERR.	CH	NM 01				32003298016C F	########	1725	95	36	3420	LIGHTNING			1	LF	T15								
FORCED INTERR	GP	KI 44	21918	42AEG	48689351	22003298015 1 L	########	1725	194	1	194	COLLISION	COLLISION	9635 SPRING C	1	DR									
FORCED INTERR.	BA	CD 04	40361	59HL	85596153	32003298016 1 F	########	1729	72	1	72	LIGHTNING	LIGHTNING	2525 FM 565S	1	LF	59HL								
FORCED INTERR.	FB	NV 02	11221	1Z7	42402224	12003298023 F	########	1730	192	6	1194	LIGHTNING	LIGHTNING	16300 BLK OF F	1	LF	1Z7								
FORCED INTERR	BL	HP 05	40609	89AEN	53578165	12003298024 1 F	########	1730	88	6	528	LIGHTNING	LIGHTNING	504 GRAY	1	LF	89AEN								
FORCED INTERR	GA	GL 01	30457	1N4	68383403	32003298063 F	########	1740	32	24	768	LIGHTNING	LIGHTNING	2700 BROADWA	1	LF	1N4								
FORCED INTERR	FB	NV 02	11220	J83	42415356	12003298024E F	########	1740	133	39	5187	LIGHTNING	LIGHTNING	F.M. 1236 AT 90	1	LF	J83	TF	424153561						
FORCED INTERR	SU	RO 07	12242	T76M	49535404	12003298024E F	########	1750	81	52	4212	URD BUSHING	URD BSHING	10111 BISSONN	2	LF	T76M	PR							
FORCED INTERR	GP	DH 08	22160	E30Y		22003298015E F	########	1751	64	104	6656	LIGHTNING	LIGHTNING	7039 BENT BRA	1	LF	E30Y								
FORCED INTERR	FB	EB 06	11295	G46I	37449286	12003298025 1 T	########	1800	124	3	372	LIGHTNING	LIGHTNING	14906 POWELL	1	TF	374492820								
FORCED INTERR	CY	KL 41	21956	S5RA	47862585	22003298015E F	########	1800	63	19	1197	LIGHTNING ARRE	LTNG ARRS	LONGWOOD TF	2	LF	S5RA								
FORCED INTERR	FB	NEWO	11246	R86S	36367557	12003298026E F	########	1820	42	3	126	TREE CLEARANC	TREE CLEAR	8700 FM 1301, E	1	LF	R86S								
FORCED INTERR	MP	HM 02	11055	C47D	54544522	22003298016E F	########	1830	97	10	970	LIGHTNING	LIGHTNING	6208 SIDNEY ST	1	LF	C47D	SC	545445246						
FORCED INTERR	FB	NV 03	11232	W196	44417454	12003298028 2 T	########	1831	179	2	358	LIGHTNING	LIGHTNING	12502 ZAMANEP	1	TF	444174598								
FORCED INTERR	FB	WA 41	10192	5STT	38512151	12003298026 2 T	########	1830	175	1	175	LIGHTNING	LIGHTNING	2367 W FM 1093	1	TF	365121527								
FORCED INTERR	BL	BR 03	10488	K73H	52547525	12003298026E T	########	1847	60	5	300	UNKNOWN	UNKNOWN	3019 S BRAESW	1	TF	525475250								
FORCED INTERR	SU	BAR45	11895		47549556	12003298026E T	########	1850	63	2	126	UNKNOWN	UNKNOWN	13402 BELLAIRE	1	TF	475495609								
FORCED INTERR	SU	AF 01	11752	G37P	49543011	12003298027C F	########	1850	57	19	1083	LIGHTNING	LIGHTNING	8622 HEATHERV	2	LF	G37P								
FORCED INTERR	BL	GT 09	10649	56AC	53563351	12003298027 2 T	########	1901	22	2	44	BU DISC OR BARI	DISC/BARRL	1401 SUL ROSS	3	LF	56AC								
FORCED INTERR	CH	AD 08	40088	KE2	54626361	32003298017 1 T	########	1903	77	18	1386	LIGHTNING	LIGHTNING	3222 ROSEMAR	1	TF	546283614								
FORCED INTERR	HM	AT 42	2314F	M41M	46619030	12003298027 3 T	########	1900	240	7	1680	FOREIGN MATER	FRGN MATR	5102 GRETNA G	1	SC	466190387								
FORCED INTERR	BL	WW 01	10693	H3R	50543105	12003298027E T	########	1920	170	3	510	FLLNG TREE OUT	TREE FL/OE	8714 WATEKA D	1	SC	505431054								
FORCED INTERR	FB	NSHO	11318	W185	49334515	12003298027E F	########	1931	173	4	692	LIGHTNING	LIGHTNING	7336 MANOR LK	1	LF	W185								
FORCED INTERR	BL	BI 06	10083		52551137	12003298027 L	########	1933	61	1	61	OH SEC/DR CL NI	OH SC CL-N	4229 1/2 BELLAI		DR									
FORCED INTERR	GA	STWO	35498	30FH	61304436	32003298017E F	########	1930	121	6	726	LIGHTNING	LIGHTNING	25015 INTREPID	2	LF	30FH								
FORCED INTERR	BZ	BZ 04	30187	AS6P	52267413	32003298017E F	########	1940	837	80	66960	LIGHTNING	LIGHTNING	308 WALNUT ST	1	LF	AS6P	PR							
FORCED INTERR	BZ	BZ 04	30187	AS4P	52267413	32003298017E F	########	1940	375	37	13675	FLLNG TREE IN E	TREE FL/E	120 HICKORY S	1	PR	AS4P								
FORCED INTERR	GA	KM 07	30605	17E	63472384	32003298017E T	########	1945	80	5	400	TREE CLEARANC	TREE CLEAR	524 LOUISIANA	1	TF	634723861								
FORCED INTERR	BL	HE 08	41114		53580435	32003298172 T	########	1950	91	15	1365	BU DISC OR BARI	DISC/BARRL	1035 LAWRENC		TF	535804399								
FORCED INTERR	CH	LY 42	4709C	33HR	60592523	32003298018 1 F	########	1955	99	61	6039	LIGHTNING	LIGHTNING	1715 JAMIE LN	1	LF	33HR								
FORCED INTERR	RS	RZ 02	30376	T16	52391148	32003298018E F	########	2000	187	6	1122	BIRD	BIRD	17102 FM 521 RI	1	LF	T16								
FORCED INTERR	RS	AE 06	3537A	H85R	57333188	32003298019E F	########	2000	87	4	348	LIGHTNING	LIGHTNING	21400 FM 2004	1	LF	H85R								
FORCED INTERR.	BZ	RT 02	31402	D9R	52271381	32003298187 F	########	2007	353	1	353	LIGHTNING	LIGHTNING	54 LAKE	1	LF	D9R								
FORCED INTERR.	FB	WA 43	12943	K81	39507495	12003298028C T	########	2008	110	1	110	LIGHTNING	LIGHTNING	1209 LONG LN	1	BU	395074959								
FORCED INTERR	BZ	BZ 01	31173	K86W		32003298185 E F	########	2014	142	207	29394	LIGHTNING	LIGHTNING	615 DIXIE DR #1	1	LF	K86W								
FORCED INTERR.	BZ	VL 04	3526C	29GJ	56236271	32003298192 T	########	2017	284	9	2556	LIGHTNING	LIGHTNING	311 SEASHELL	1	TF	562362701								
FORCED INTERR	FB	WC 01	1290A	68NA	47355278	12003298028 2 F	########	2023	163	6	978	LIGHTNING	LIGHTNING	CO 456 @ E RH	1	LF	68NA								
FORCED INTERR.	SU	AF 06	11796	I54M	48544275	12003298028 4 F	########	2045	126	14	1764	HUMAN ERROR	HUMN ERRC	12405 WINDJAM	2	PR	I54M								
FORCED INTERR	SU	BAR45	11895		47548501	12003298028E T	########	2055	43	1	43	LIGHTNING	LIGHTNING	13700 BELLAIRE		TF	475485027								
FORCED INTERR	FB	OR 02	11302	B11F	40453116	12003298028E T	########	2110	59	1	59	LIGHTNING	LIGHTNING	9203 HIGHWAY	1	TF	404531823								
FORCED INTERR	FB	NV 03	11232	W196	44416584	12003298029 1 T	########	2132	226	1	226	LIGHTNING	LIGHTNING	12134 ZAMANEP	1	BU	444165864								
FORCED INTERR.	HC	PZ 41	12706		53545241	12003298029 3 T	########	2204	21	2	42	LIGHTNING	LIGHTNING	2555 1/5 HOLLY		TF	535452416								
FORCED INTERR	BZ	FP 06	4534C	50ADZ	54212063	32003298194 F	########	2205	298	2	596	LIGHTNING	LIGHTNING	W FLOODGATE	1	LF	50ADZ	LF	P79	TF	542				
FORCED INTERR	FB	EB 05	11291	W51	36471081	12003298029 7 F	########	2240	105	13	1365	LIGHTNING	LIGHTNING	18438 COUNTY	1	LF	W51								
FORCED INTERR	MP	AN 06	40036	95K	53602128	22003298017E F	########	2300	67	9	603	LIGHTNING	LIGHTNING	4212 DOUGLAS	1	LF	95K								
FORCED INTERR	BA	MB 05	3C164	15MM	67641111	32003298019E T	########	2313	44	5	220	FLLNG TREE OUT	TREE FL/OE	15808 ALAZAN S	1	TF	676411179								
FORCED INTERR.	FB	EB 06	11295	11LS	37466145	12003298030C F	########	2314	41	23	943	LIGHTNING	LIGHTNING	2423 HARGIS ST	1	LF	11LS								
FORCED INTERR.	HC	AR 42	1583D	28BR	51476571	12003298030 1 F	########	2337	40	31	1240	LIGHTNING	LIGHTNING	3610 INEZ	1	LF	28BR								
FORCED INTERR	BZ	BZ 04	30146	R12T	52267304	32003298197 L	########	2355	79	1	79	FLLNG TREE OUT	TREE FL/OE	117 MAPLE ST	1	DR									
FORCED INTERR	FB	EB 06	11295	11LS	37464171	12003298000E T	########	0040	32	1	32	LIGHTNING	LIGHTNING	2027 LEVERIDG	1	BU	374641752								
FORCED INTERR	HC	TV 02	12802	77DD	50509001	12003298000E F	########	0050	71	1	71	LIGHTNING	LIGHTNING	FM 2234 @ TUL	1	LF	77DD								
FORCED INTERR	SB	EC 06	21696	A29D	50586025	12003299001 2 T	########	0110	169	1	169	VINES	VINES	6 HAMPTON CT	1	TF	505860291								
FORCED INTERR	SB	CB 08	21453	HW7	50603224	12003299001 2 T	########	0130	211	10	2110	VINES	VINES	4006 GALWAY L	1	TF	506032244								
FORCED INTERR	SH	WE 08	31318	R1G	58553265	32003299000 L	########	0140	22	1	22	TREE CLEARANC	TREE CLEAR	903 STRATFORI	1	DR									
FORCED INTERR	HC	MV 01	14212	43ABH	55446571	12003299000 7 F	########	0150	2	21	42	LIGHTNING	LIGHTNING	330 COUNTY RC	1	LF	43ABH								
FORCED INTERR	SB	EC 13	11871	KJ7	50574361	12003299000E T	########	0150	129	9	1161	TREE CLEARANC	TREE CLEAR	11310 GREENVI	1	TF	505743809								
FORCED INTERR	SH	DR 06	30287	HA3	55533384	22003299000C T	########	0152	118	5	590	LIGHTNING	LIGHTNING	6319 BELMARK	1	BU	555333848								
FORCED INTERR	BL	KB 09	10168	G17	52556461	12003299001 1 T	########	0156	70	7	490	LIGHTNING	LIGHTNING	3012 RICE	1	TF	525564685								
FORCED INTERR	SU	BAR47	11834	E72S	47544127	12003299001E T	########	0200	103	2	206	VINES	VINES	8558 HIGHWAY	1	TF	475441260								
FORCED INTERR	FB	RE 04	11446	F80T	44494037	12003299001E F	########	0210	55	22	1210	SNAKE	SNAKE	1612 CEDAR DR	2	LF	F80T								
FORCED INTERR	SH	PE 02	30816	18RH	55473561	32003299002 1 T	########	0240	267	2	534	LIGHTNING	LIGHTNING	6506 BAILEY RD	1	BU	554735615								
FORCED INTERR	BL	ST 11	10255	5TB	51555501	12003299002 1 F	########	0240	89	7	623	LIGHTNING	LIGHTNING	JESSAMINE @ C	1	LF	5TB								
FORCED INTERR.	RS	AV 03	3505A	2NX	56421107	32003299000E F	########	0340	344	25	8600	LIGHTNING	LIGHTNING	CO 185 @ CO 1	1	LF	2NX	BU	564211075	PR					
FORCED INTERR	SB	WD 43	21594	P20V		12003299002 4 F	########	0420	417	80	25020	UNKNOWN	UNKNOWN	E. OF ADDICKS	1	LF	P20V								
FORCED INTERR.	FB	EB 05	11291	K94	35468444	12003299002E F	########	0430	66	2	132	LIGHTNING	LIGHTNING	CO 258 @ FM 11	1	LF	K94								
FORCED INTERR.	HM	HB 44	20047	92LF	57662144	22003299000 3 F	########	0440	109	2	218	LIGHTNING	LIGHTNING	2300 ATASCOCI	1	LF	92LF								
FORCED INTERR	SU	MC 02	12140	B63U	50510117	12003299002E F	########	0450	149	86	12814	LIGHTNING	LIGHTNING	511 KIRKWOOD	2	LF	B63U								
FORCED INTERR	HC	HOOD	12948		52520553	12003299002 7 T	########	0510	56	2	112	LIGHTNING	LIGHTNING	12106 1/2 MAIN		TF	525205325								
FORCED INTERR	FB	EB 06	11295	11LS	37465114	12003299003C T	########	0620	45	2	90	LIGHTNING	LIGHTNING	2213 SAN BERN	1	TF	374651143								
FORCED INTERR	SU	DL 42	12638	39KJ	49491153	12003299003 1 F	########	0630	118	1	118	LIGHTNING	LIGHTNING	4411 RINGROSE	1	LF	39KJ	PR							
FORCED INTERR	FB	NV 03	11232	L8N	43426334	12003299003 3 T	########	0640	117	2	234	LIGHTNING	LIGHTNING	9528 JESKE RD	1	TF	434263301								
FORCED INTERR	BZ	LJ 07	31782	E59F	53284311	32003299001 2 F	########	0655	30	39	1170	SQUIRREL	SQUIRREL	11 ROBINHOOD	1	LF	E59F								
FORCED INTERR	GP	LK 01	21540	E62V	51625315	22003299000E F	########	0655	233	32	7456	LIGHTNING	LIGHTNING	7726 STREAMSI	2	LF	E62V								
FORCED INTERR.	FB	RS 05	1555A	40VC	44460371	12003299003E T	########	0655	153	1	153	LIGHTNING	LIGHTNING	4011 MEADOWE	1	TF	444603789								
FORCED INTERR.	MP	EU 11	40758	32BN	52595171	22003299000E F	########	0655	54	101	5454	SQUIRREL	SQUIRREL	1710 W T C JES	2	LF	32BN								
FORCED INTERR	SB	SR 12	21677	BN3	49584541	12003299003 7 F	########	0700	226	23	5198	UNKNOWN	UNKNOWN	10503 HAZELHU	1	PR	BN3								
FORCED INTERR	FB	WA 43	11332	69ABV	36515006	12003299003E F	########	0700	62	1	62	LIGHTNING	LIGHTNING	1923 NORCROS	1	LF	69ABV								
FORCED INTERR	GA	AL 06	30031	71HT	61420398	32003299013 F	########	0710	68	6	396	UNKNOWN	UNKNOWN	12310 4 1/2	1	LF	71HT								
FORCED INTERR	CH	AD 08	40088	KD9	54625363	32003299014 F	########	0711	60	75	4500	UNKNOWN	UNKNOWN	3002 MOHAWK	1	LF	KD9								
FORCED INTERR	SH	CC 03	31662	8EW	54513284	12003299004C T	########	0711	112	7	784	SQUIRREL	SQUIRREL	3934 FUQUA ST	1	TF	545132842								
FORCED INTERR.	SN	UW 04	31461	F10E	80552004	32003299001E L	########	0711	148	1	148	OH SEC/DR CL HI	OH SC CL-H	818 E AVENUE	1	DR									
FORCED INTERR	HM	LA 04	40566	G37S	54634464	22003299001C F	########	0722	0	0	0	SQUIRREL	SQUIRREL	2723 CHARRITC	2	LF	G37S	PR							
FORCED INTERR.	HM	LA 04				22003299001C F	########	0722	146	24	3504	SQUIRREL			2	LF	G37S								
FORCED INTERR.	GP	DH 09	40593	W41E	51615158	22003299011 T	########	0722	199	8	1592	SQUIRREL	SQUIRREL	5011 FALLEN OV	1	TF	516151892								
FORCED INTERR.	SN	FW 03	30448	N50F	58468707	32003299016 F	########	0730	167	89	14863	SPLICE	SPLICE	16411 TIBET RD	2	LF	N50F	PR							
FORCED INTERR.	MP	HR 02	41031	91QS	54604051	22003299012 F	########	0730	89	129	11481	SQUIRREL	SQUIRREL	2108 KING ST	1	LF	91QS								
FORCED INTERR.	MP	LB 05	41276		55593081	22003299012 T	########	0730	298	4	1184	INSULATOR	INSULATOR	3802 1/5 DABNE		BU	555630819								
FORCED INTERR	SB	BM 04	21493	8AB	48577455	12003299004C F	########	0730	101	37	3737	UNKNOWN	UNKNOWN	610 REGENTVIE	1	LF	8AB								
FORCED INTERR	CH	LB 01	41254	AT2	55603017	32003299002C T	########	0730	92	15	1380	SQUIRREL	SQUIRREL	6309 SHOTWEL	1	TF	556030177								
FORCED INTERR	SH	MY 02	30728	88KA	57481592	32003299001 F	########	0740	202	2	404	SQUIRREL	SQUIRREL	3007 YOST	1	LF	88KA								
FORCED INTERR	MP	WO 12	41085		52608048	22003299015 T	########	0740	119	1	119	BU DISC OR BARI	DISC/BARRL	3604 BRINKMAN		TF	526080485								
FORCED INTERR	MP	BG 01	40243	MN9	53567195	22003299016 F	########	0750	48	29	1392	SQUIRREL	SQUIRREL	1701 BLODGETT	1	LF	MN9								

REF LF;
REPL. 50 W/50 CONV., RPLD BAJ TR;
REF LF REF TR, RPRD B/O PRI JUMP-TF BLOWN;
REF TR;
REF LF;
SWITCHING ORDER 2312 ISOLATED BAD SPAN OF DIRECT BURIED URD PRIMARY IBTWN TF45 & TF46 TWT

REFUSED TRANS,CAUSE VARMET, REF TR;
RPL 10/7 2 WITH 25RPL SWITCH AND ARRSTER, RPLD BAJ TR, RPLD BAJ DISC-TF BLOWN; RPLD LIGHTNING ARRESTOR;
REF TR;
REF LF
REF TR

REF LF;
REF TF;
REF MIDDLE PHASE LF;
NEED TO REPLACE 2 - 40' CL4 POLES GET WITH TRUCK REF LF RMVD DOWNED PL. ltr&G TO B/C WIPS REPL 40'CL4 POLE
REMOVED SQUIRREL, REPLACED LIMITER, REFUSED TRANS. RPLD LIMITER @ TR, REF TR;
REFUSED LINE FUSE OAB 25T OUT BY LIGHTNING, REF LF;
TRIMMED TREE, REF TR;
REFUSED TRANS, REF TR;
REFUSED LINE FUSE, LIGHTNING, REF LF;
REPLACED 25 KVA CBP WITH 25 KVA CONV-7200-120/240-INSTALLED SWITCH ARM-SWITCH-TANK MOUNTED LIA & VM, PROTECTION--VM ON GROUND NOTIFIED BOARD-NON RESIDENTIAL--

RAN NEW #1/0 DROP DUE TO CAR HIT POLE, RPLD DR;
LF REFUSED EAST AND WEST PAHSE OF LF 59HL BJH

REF LF
REF LF;

FD OK BY PHONE @ 1811 - CREW RPLCD Y ELBOW IN TF40 @ 86 #6 TWT
REF TP;
REFUSED 10 KVA TRANSFORMER AND CHECKED VOLTAGE , REF TR;
RPLCD LIGHTNING ARRESTOR, REF LF

REF LF, REF TR, 18OL BEC+1 CUST, RPRD BUSS WORK @ TR, REBAGGED DR.

TRIMMED TREES AND RE-FUSED A LIGHTER TRANSFORMER LIGHTNING, REF TR;
RPLD BAJ BARREL ON TR;
REPLACED HIGHSIDE ON LINE SWITCH THAT FEEDS STEP-POTS 10 & TO 2400, REF TR;
REF TP
REPLACED 2 BURNED 4JP FUSE BARRELS . RPLD BAJ BARREL ON TP
REF TR;
repaired secondary conn. at pad RPRD BEC CONN @ PED-> 1 CUST
LG TREE TOOK DOWN THE WIH AT 8714 @ 8702 WATEKA REPLACED 2 SPANS OF 1/0 BEC NEED TO HAVE TREES TRIMMED BETWEEN FIRST SERVICE BY THE STREET@ WEST TO BEC SERVIC
REF LF;
Replace clamps @ WIH found bad neutral RPRD CONN @ WIH;
REF TP;
308 OLEANDER R/W AND DROP MTR/BN#0317630 READ LTO R 45782 X 1 LOOP DAMAGE 88 LOTUS CT R/W AND DROP MTR B4860588 READ L TO R 08052 X 1 LOOP DAMAGE ALSO PICKED UP
PICKED-UP2-SPANS IN PRIMARY@115 8 MAGNOLIA STILL NEEDS TREE CREW TO REMOVE TREE OFF SEC @ THE LOCATION. REF LF INJ PR-FUSE BLOWN
HAD TO TRIMM SEVERAL TREES VIEWS OFF POLE, REF TR;
RPLD BAJ BARREL ON TR
REF LF;
REF LF
REFUSED LF, REF LF
REFUSE N PH, REF LF;
REPL. 10/25 KVA TR 7200/120/240 LIGHTING RPLD BAJ TR;
REF LF
REF TR;
REF LF
FOUND TRANS ISOLATED WITH RED HOOD LEANING ON PRI SWITCHED LOOP BACK TO NORMAL LOOP WAS OUT DUE TO TRANS #68 HOOD ON PRI OVER LOOKED WHEN IT WAS SWITCHED
REF TR;
REFUSED 25 CBP TRANSFORMER IN THE EASEMENT NO ONE HOME , LIGHTS ARE ON AT THE HOUSE FENCED IN YARD , REF TR;
REPLACED BAD TRANS 25 W/15 7200 120/240 TARW 10-24-03 WORK BUTTON WAS HIT, RPLD BAJ TR;
REF TR;
REF LF REF TR; BRS
RODE OUT THE LINE AND REFURED TWO PHASES OF LINE FUSE , REF LF
REFUSED THE SOUTH PH OF TWO PH LF REF LF;
NEED TO PUT UP ADRESS, REF TR;
REFUSED LINE FUSE ALSO RODE OUT THE LINE REF LF;
REF LF CORRECTED ON TIME /CRH
PICKED UP 10 DROPS DOWN BY MTR/BN#0317626 REF TR REBET 50 CBP RAJ DR;
REPLACED BURNED UP 25 KVA 15 TRANSFORMER AND 12 KV ARRESTOR 7200-120 240V DAY LIGHT SAVINGS TIME , ONE HOUR BACK RPLD BAJ TR RPLD LIGHTNING ARRESTOR
REF LF; CORRECTED ON TIME & DATE /CRH
CLEARED VINES FROM TF & REFUSED 50 KVA 7200 120/240 REF TR; BENT MRG TO T&D BRS
REF TR, RMVD TREES,IMB OFF PR;
NEED TO REPLACE DROPS FEEDING HOUSE TO THE RIGHT OF THIS ADDRESS TREES ALL IN DROPS RUBBING IN THEM.
EHR at 0200, OHS at 0240 ESMP at 0300 REF LF;
REFUSED 75 KVA 7200 120/240 T/F IN OPEN DELTA TREES REF TR; BENT MRG TO T&D BRS
REPLACE BAD 50 CONV TRNS WITH SAME RPLD BAJ TR; BRS
REF TR;
REPLACED 12 6-MATE NEED TO TRIM TREES AT TRANS BANK REF TR. BENT MRG TO T&D BRS
TRIMMED TREE LIMBS OFF T.P AND REMOVED A SNAKE REFUSED T.P RESTORING SERVICE NEED TO HAVE TREE TRIMMED FROM THE POLE & T.P REFER TO TREE CREW REF TP BS
REPLACE BAD 25 CONV TRAN RPLD BAJ TR;
REF LF
REPLACE BAD 50 KVA TRN 7200/120/240 REFUSED LINE FUSE 2HX 16 T ALSO REPLACE BAD ARRESTOR PICKED UP TWO SPANS OF IN PRIM ALSO ABC TREE COMP ARE TRIMMING TREES, R
RPLD 250 KVA STEP POT BEHIND LINE FUSE P 20 V SOUTH XFMR, REF LF, RPLD BAJ TR;
REF LF
LOOKS LIKE THERE ARE SEVERAL TREES GETTING INTO PRIMARY ABOUT HALF WAY DOWN THE LINE REF L

FORCED INTERR	GA	AL 07	30038	A35B	6041354	32003299002	T	########	075	132	2	264	BU DISC OR BARI	DISC/BARRL	4206	JACKSON	1	TF	604135465					
FORCED INTERR	SH	CA 03	30113	80EC	5953505	32003299002	F	########	075	175	2	350	UNKNOWN	UNKNOWN	4327	HAITI LN	2	LF	80EC					
FORCED INTERR	HM	LW 43	23017	27KF	5564247	32003299001	T	########	075	113	6	678	STRONG WIND	WIND	14326	SURLES D	1	TF	556424792					
FORCED INTERR	BL	HE 08	41116	ME6	5258945	32003299002	T	########	080	405	10	4050	TRANSFORMER	TRANSFRM	943	N SHEPHER	3	TF	525894585					
FORCED INTERR	BA	BW 02	41315		6250119	32003299002	T	########	080	42	7	294	SQUIRREL	SQUIRREL	1422	CREEK HO		TF	625011922					
FORCED INTERR	SU	AF 11	11771		4854554	32003299004	T	########	080	68	5	340	OH SEC/DR CL HI	OH SC CL-H	12313	BELLAIRE		SC	485455425					
FORCED INTERR	MP	CR 01	40534	77HE	5358855	32003299002	T	########	081	59	3	177	LIGHTNING	LIGHTNING	3636	N MAIN ST	1	TF	535885576					
FORCED INTERR	BL	GN 10	10626	C6E	5255921	32003299004	T	########	081	54	5	270	UNKNOWN	UNKNOWN	2419	ADDISON	1	TF	525592119					
FORCED INTERR	SH	TE 06	3577A	14RQ	5549413	32003299002	T	########	081	139	3	417	SQUIRREL	SQUIRREL	5205	W BROAD	1	TF	554981304					
FORCED INTERR	HC	HOC0	11184	H98	5253228	32003299005	F	########	082	141	3	423	LIGHTNING	LIGHTNING	11525	MAIN	1	LF	H98					
FORCED INTERR	HC	HM 05	11032	W5T	5453224	32003299005	T	########	082	44	11	484	SQUIRREL	SQUIRREL	4353	PHLOX ST	1	TF	545322431					
FORCED INTERR	SH	SB 07	31052	NC5	5855601	32003299003	F	########	083	71	48	3408	LIGHTNING	LIGHTNING	922	PAUL ST	1	LF	NC5					
FORCED INTERR	GP	AD 05	2A112	B6W	5363043	32003299002	F	########	083	40	60	2400	TREE CLEARANC	TREE CLEAR	202	MEMORY LN	1	LF	B6W					
FORCED INTERR	RS	AV 03	3505A	51AEH	5542851	32003299003	T	########	083	90	2	180	LIGHTNING	LIGHTNING	12311	COUNTY	1	TF	554285191					
FORCED INTERR	MP	AN 05	40030	A62U	5360258	32003299003	T	########	084	56	3	168	SQUIRREL	SQUIRREL	4836	WERNER S	1	TF	536025801					
FORCED INTERR	SH	SH 01	31374	PS1	5753502	32003299003	T	########	084	87	8	696	TREE CLEARANC	TREE CLEAR	615	REGAL ST	1	TF	575350280					
FORCED INTERR	GP	RU 01	41313	T6E	5361122	32003299003	F	########	084	102	16	1632	LIGHTNING	LIGHTNING	241	ISHMEAL ST	1	LF	T6E					
FORCED INTERR	SH	PE 03	30803	N68F	5549446	32003299003	T	########	085	168	4	672	LIGHTNING	LIGHTNING	2126	ODAY RD	1	TF	554944601					
FORCED INTERR.	KY	FZ 44	24803		4558541	12003299005	T	########	085	98	2	192	LIGHTNING	LIGHTNING	10623	YOUNGLU		TF	455854192					
FORCED INTERR.	HC	FAN45	14228	R68W	5354048	32003299054	F	########	090	0	0	0	URD BUSHING	URD BSHING	7950	N.STADIUM	2	LF	R68W	BU	535405690			
FORCED INTERR	HC	FAN45				12003299054	F	########	090	145	29	4205	URD BUSHING				2	LF	R68W					
FORCED INTERR	HC	FAN45				12003299054	F	########	090	145	133	19285	URD BUSHING				2	LF	R68W					
FORCED INTERR	HC	FAN45				12003299054	F	########	090	288	12	3456	URD BUSHING				2	LF	R68W					
FORCED INTERR	MP	BY 03	40171		5361915	22003299033	T	########	090	109	8	872	TREE CLEARANC	TREE CLEAR	9401	1/2 MC GAI		TF	536191565					
FORCED INTERR	SH	PA 03	30760	MD1	5754345	32003299037	T	########	092	218	9	1962	TREE CLEARANC	TREE CLEAR	1406	PECAN DR	1	SC	575434516					
FORCED INTERR	RS	AV 02	3103A	BL5	5842855	32003299039	F	########	092	97	26	2522	STRONG WIND	WIND	810	THOMPSON	1	LF	BL5					
FORCED INTERR	HC	MV 01	14206		5444540	12003299057	T	########	092	49	3	147	SQUIRREL	SQUIRREL	7322	JORDAN R	1	TF	544454069					
FORCED INTERR	BZ	BZ 05	30399	71PH	5226512	32003299004	F	########	093	225	1	225	STRONG WIND	WIND	MEDICAL S	OF	1	LF	71PH					
FORCED INTERR	HC	BR 08	10514	A6SB	5153846	32003299006	T	########	094	36	9	324	UNKNOWN	UNKNOWN	4638	MC DERMI	1	TF	515364660					
FORCED INTERR	MP	MP 06	41392		5557114	22003299003	T	########	095	232	3	696	LIGHTNING	LIGHTNING	5003	NAVIGATI		BU	555711446					
FORCED INTERR	GA	KM 07	30605	17E	6347137	32003299041	T	########	095	107	2	214	LIGHTNING ARRE	LTNG ARRS	3611	E MABEL S	1	TF	634713751	DR				
FORCED INTERR	GA	STW0	3549C		6231157	32003299042	T	########	100	155	2	310	STRONG WIND	WIND	3802	NUECES		TF	623115761					
FORCED INTERR	SB	BM 03	21487	A91D	4858840	12003299061	F	########	101	32	14	448	SQUIRREL	SQUIRREL	11310	MAPLE ST	1	LF	A91D					
FORCED INTERR	BL	GT 05	22452	L6A	5355754	22003299036	T	########	101	62	43	2666	VINES	VINES	1911	BINZ ST	4	TF	535575407					
FORCED INTERR	HC	HM 06	11036	9PB	5454722	32003299065	T	########	102	40	2	80	SQUIRREL	SQUIRREL	5209	MALMEDY	1	TF	545472207					
FORCED INTERR	BZ	LJ 01	31331	10GJ	5227542	32003299004	F	########	102	115	1	115	LIGHTNING	LIGHTNING	550	OAK	1	LF	10GJ					
FORCED INTERR	GA	SCW0	30879	E41E	6839927	32003299004	F	########	102	140	1	140	CUST EQP RELA	CUST RLTD	100	C	1	LF	E41E					
FORCED INTERR	MP	AN 01	40001	A53X	5360521	22003299041	F	########	110	43	53	2279	SQUIRREL	SQUIRREL	4229	EUROPA S	1	LF	A53X	TF	536052124			
FORCED INTERR	RS	AV 02	3103B	30HT	5942149	32003299005	T	########	110	37	3	111	SQUIRREL	SQUIRREL	211	AVENUE D	1	TF	594214991					
FORCED INTERR	CY	TB 47	24278	S197B	4873026	22003299004	T	########	111	60	1	60	BIRD	BIRD	9011	ROSIE LN	1	TF	487302642					
FORCED INTERR	BL	HE 06	41131	C47K	5358235	12003299006	F	########	113	83	4	332	LIGHTNING	LIGHTNING	YALE	@ W 6TH	1	LF	C47K	DB				
FORCED INTERR	CH	BY 07	40190	U7E	5461602	32003299005	T	########	114	103	14	1442	TREE CLEARANC	TREE CLEAR	2915	FIRNAT ST	1	DB	546160257	SC		DR		
FORCED INTERR	SH	TE 06	3577C	1LK	5649111	32003299057	T	########	115	24	1	24	BU DISC OR BARI	DISC/BARRL	4202	W WALNUT	1	TF	564911182					
FORCED INTERR	GP	GZ 44	20487		5165510	22003299044	L	########	120	224	1	224	ROTTEN POLE	ROTTEN PLI	11240	VETERAN		PD						
FORCED INTERR	SU	RO 42	12834		4953649	12003299007	T	########	121	43	8	344	BU DISC OR BARI	DISC/BARRL	9805	BISSONNE		TF	495364986					
FORCED INTERR	MP	MP 10	40918	41MB	5554243	22003299044	F	########	122	78	1	78	LIGHTNING	LIGHTNING	5301	POLK #11	1	LF	41MB					
FORCED INTERR	RS	AE 05	30062	42NH	5137213	32003299006	F	########	122	110	1	110	LIGHTNING	LIGHTNING	201	CO 845	1	LF	42NH					
FORCED INTERR	GP	LU 45	20610	S72C	5169839	22003299044	F	########	123	133	33	4389	TREE CLEARANC	TREE CLEAR	539	PINE WALK	2	LF	S72C					
FORCED INTERR	SH	PA 01	30749		5755634	32003299062	T	########	124	37	1	37	UNKNOWN	UNKNOWN	410	RICHEY ST		TF	575563440					
FORCED INTERR	SH	SP 07	30984	I66R	5753725	32003299063	T	########	124	30	4	120	SQUIRREL	SQUIRREL	1013	AVENUE I	1	TF	575372509					
FORCED INTERR	BA	BW 05	41316	7PM	6250113	32003299065	T	########	124	71	6	426	VINES	VINES	510	SEAWAY DI	1	TF	625011383					
FORCED INTERR	FB	NV 03	11232	L8N	4342629	12003299007	T	########	125	46	2	92	BIRD	BIRD	9718	JESKE RD	1	TF	434262926					
FORCED INTERR.	FB	WA 41	11990	65AAC	3451633	12003299007	F	########	125	171	3	513	LIGHTNING	LIGHTNING	2287	JOHNSTON	1	LF	65AAC					
FORCED INTERR	FB	WA 43	14060	76GB	3950711	12003299074	T	########	125	69	1	69	LIGHTNING	LIGHTNING	130	LAKE	1	PR	395071130					
FORCED INTERR	SU	AF 05	12563		4855721	12003299007	T	########	130	28	2	56	SQUIRREL	SQUIRREL	11914	7TH		TF	485572102					
FORCED INTERR	GA	SCW0	30879	33LU	6839929	32003299066	F	########	132	52	35	1820	CONTRACTOR-NI	CON-NT HLT	157	SO SAN MA	1	LF	33LU	LF	E41E			
FORCED INTERR	GA	PHRO	31330	63ABU	6346157	32003299007	T	########	133	361	1	361	UNKNOWN	UNKNOWN	4610	VICKSBUR	1	BU	634615738					
FORCED INTERR	SU	RO 01	12201		4954408	12003299007	T	########	133	29	7	203	UNKNOWN	UNKNOWN	9441	W SAM HO		TF	495440892					
FORCED INTERR	SB	SR 05	21644		4958358	12003299007	T	########	134	215	4	860	SQUIRREL	SQUIRREL	10835	NORTHBI		BU	495835890					
FORCED INTERR	SU	BAR4	13212	2BG	4653726	12003299081	F	########	134	28	3	78	UNKNOWN	UNKNOWN	16223	BOSS GA	1	LF	2BG					
FORCED INTERR	SH	PA 01	30750	22ED	5755511	32003299074	T	########	142	39	8	312	SQUIRREL	SQUIRREL	1307	SUSAN ST	1	TF	575551112					
FORCED INTERR	KY	FM 01	12909	99AAQ		12003299096	F	########	143	113	6	678	UNKNOWN	UNKNOWN			1	PR	99AAQ					
FORCED INTERR	HM	LW 41	43258	28BM	5763429	32003299075	L	########	143	74	1	74	VANDALISM	VANDALISM	11830	GREENSF	2	MT						
FORCED INTERR	SH	SB 02	31034	JZ1	5855300	32003299076	L	########	143	47	1	47	OH SEC/DR CL HI	OH SC CL-H	3107	CEDARCRI	1	SC						
FORCED INTERR	CH	CV 06	40456	57GU	5658335	32003299077	F	########	144	57	70	3990	SQUIRREL	SQUIRREL	13108	HALIFAX	1	LF	57GU	PD				
FORCED INTERR	GP	BA 43	22074	86UB	5065340	22003299054	F	########	144	58	1	58	LIGHTNING	LIGHTNING	BOURGEOIS	RC	1	LF	86UB					
FORCED INTERR	CY	CYF45	22069	16SG	4664439	12003299056	F	########	145	129	59	7611	O/H PRIMARY CU	OH PR CUMS	10646	DESERT	2	LF	16SG	PR				
FORCED INTERR	SU	RO 07	12242	X97C	4953545	12003299094	F	########	145	36	1	36	LIGHTNING	LIGHTNING	BISSONNET	@ I 1	1	LF	X97C					
FORCED INTERR	FB	WA 41	10192	47BT	3551535	12003299095	F	########	150	100	2	200	LIGHTNING	LIGHTNING	3636	FM 1093	(S 2	LF	47BT	TF	355153566			
FORCED INTERR	SH	DR 08	30295	M8G	5653150	32003299077	T	########	151	32	5	160	SQUIRREL	SQUIRREL	7710	BROADVIE	1	TF	565315093					
FORCED INTERR	SH	DR 09	30429	96DT	5553923	32003299086	T	########	151	52	2	104	SQUIRREL	SQUIRREL	7402	CAYTON S	1	TF	555392369					
FORCED INTERR	BL	HE 03	14263	L3W	5258916	12003299010	T	########	155	65	6	390	BU DISC OR BARI	DISC/BARRL	1609	DURHAM D	1	DB	525891802					
FORCED INTERR	BA	CD 08	40393	RU2	6457026	32003299086	L	########	160	94	1	94	TREE CLEARANC	TREE CLEAR	904	PATSY ST	1	DR		SC				
FORCED INTERR	FB	NV 02	11212	56RR	4143849	12003299010	T	########	163	122	2	244	LIGHTNING	LIGHTNING	8427	BRINKMEY	1	BU	414384693					
FORCED INTERR	CY	PI 43	2H118	S199D	4470742	22003299064	F	########	165	78	3	234	LIGHTNING	LIGHTNING	20032	TOMBALL	1	LF	S199D	TF	447074216			
FORCED INTERR	MP	BH 05	41557	C67M	5458614	22003299065	T	########	171	62	2	124	LIGHTNING	LIGHTNING	1330	JENSEN DI	1	TF	545861481					
FORCED INTERR	GP	THW4	22179	T20D	4964158	22003299067	F	########	172	0	0	0	TRANSFORMER	TRANSFRM	11510	TURTLE L	2	LF	T20D	BU	496415707			
FORCED INTERR	GP	THW4				22003299067	F	########	172	217	19	4123	TRANSFORMER				2	LF	T20D					
FORCED INTERR	GP	THW4				22003299067	F	########	172	217	29	6293	TRANSFORMER				2	LF	T20D					
FORCED INTERR	GP	THW4				22003299067	F	########	172	634	6	3804	TRANSFORMER				2	LF	T20D					
FORCED INTERR	SB	WT 06	22173	FS4	5158027	12003299010	F	########	174	73	14	1022	UNKNOWN	UNKNOWN	8311	CHESHIRE	1	LF	FS4					
FORCED INTERR	SB	TO 09	21518	K89S	5160124	12003299010	L	########	175	77	1	77	OH SEC/DR CL HI	OH SC CL-H	8343	CLEMSON	1	DR						
FORCED INTERR	SU	STF01	12256	T71G	4852940	12003299011	F	########	181	56	44	2464	BU DISC OR BARI	DISC/BARRL	11710	BROOK W	2	LF	T71G					
FORCED INTERR	CH	IND03	40366	68QC	5857332	32003299091	F	########	182	85	7	595	LIGHTNING	LIGHTNING	13559	INDUSTR	1	LF	68QC	MT				
FORCED INTERR	GA	LM 03	30663	8JU	6340611	32003299092	T	########	183	174	1	174	TREE CLEARANC	TREE CLEAR	5907	VIRGINIA A	1	SC	634081134					
FORCED INTERR	BL	HE 10	41123	K9M	5258820	12003299011	T	########	184	44	3	132	UNKNOWN	UNKNOWN	5346	DARLING S	1	TF	525842023					
FORCED INTERR	HC	HOC0	12948		5152958	12003299011	T	########	184	109	1	109	BU DISC OR BARI	DISC/BARRL	4621	1/2 GASME		TF	515295875					
FORCED INTERR	SU	OV 01	11436	F87Z	4949933	12003299011	T	########	184	125	2	250	HUMAN ERROR	HUMN ERRC	2936	CYPRESS	2	SC	494993357					
FORCED INTERR	BZ	RT 01				32003299094	C	########	191	0	0	0	TREE CLEARANC	TREE CLEAR	RT01	CKT LOCI		CL	RT01					
FORCED INTERR.	BZ	RT 01	30870			32003299094	C	########	191	3	114	342	TREE CLEARANC					CL	RT01					
FORCED INTERR	BZ	RT 01	3G339			32003299094	C	########	191	47	93	4371	TREE CLEARANC					CL	RT01					
FORCED INTERR	BZ	RT 01	30868			32003299094	C	########	191	95	22	2090	TREE CLEARANC					CL	RT01					
FORCED INTERR	GA	STW0	31001	56CB	6535517	32003299010	T	########	193	279	10	2790	OH SEC/DR CL HI	OH SC CL-H	12701	JOHN RE	1	SC	653561704					
FORCED INTERR	RS	RZ 02	3516A	28RN	5137752	32003300002	T	########	194	136	4	544	BU DISC OR BARI	DISC/BARRL	1803	FM 655 RD	1	TF	513775207	DB				
FORCED INTERR	SB	SA 43	21297	R52L	4962300	12003299011	F	########	195	11	12	132	UNKNOWN	UNKNOWN	7121	PERIMETE	1	LF	R52L					
FORCED INTERR	BL	HE 10	41123	K9M	5258820	12003299011	T	########	201	55	3	165	UNKNOWN	UNKNOWN	5346	DARLING S	1	TF	525882023					
FORCED INTERR.	GP	AD 05	2A112	B6W	5363046	22003299075	F	########	202	114	60	6840	TREE CLEARANC	TREE CLEAR	126	MEMORY LN	1	LF	B6W					
FORCED INTERR	GP	HV 08	21878	34UH	5163728	22003299077	F	########	204	110	41	4510	TREE CLEARANC	TREE CLEAR	11510	MC KINLE	1	LF	34UH					
FORCED INTERR	BA	HNY0	41955	81DN	6359541	32003299010	T	########	205	22	2	44	UNKNOWN	UNKNOWN	702	HUNT RD	1	TF	635654140					
FORCED INTERR	GA	GL 09	30493	S3H	6839707	32003299010	F	########	210	77	70	5390	UNKNOWN	UNKNOWN	800	10TH	1	LF	S3H					
FORCED INTERR	FB	PG 01	10809	W285	4133400	12003299012	T	########	212	69	4	276	TREE CLEARANC	TREE CLEAR	18315	FM 1301	1	TF	413340090					
FORCED INTERR	BZ	RT 01				32003299010	C	########	213	0	0	0	TREE CLEARANC	TREE CLEAR	RT01	CKT LOCI		CL	RT01					
FORCED INTERR	BZ	RT 01	3G339			32003299010	C	########	213	21	115	2415	TREE CLEARANC					CL	RT01					
FORCED INTERR	GP	DH 08	22180	E29Y	5162118	22003299086	T	########	220	94	2	188	PRIMARY CONDU	PRIMARY	7010	BENT BRA	2	PR	516211831					
FORCED INTERR	MP	AN 01	40001	97AH	5360426	22003299081	T	########	222	60	4	240	LIGHTNING	LIGHTNING	823	E 43RD	1	DB	536042601					
FORCED INTERR	GA	STW0	31005	E23E	6232206	32003299115	F	########	222	149	67	9983	STRONG WIND	WIND	21902	GUADALU	1	PR	E23E					
FORCED INTERR	FB	NV 02	11212	Y89B	4144206	12003299122	T	########	224	35	1	35	BU DISC OR BARI	DISC/BARRL	3005	FM 360 RD	1	TF	414420608					
FORCED INTERR	CH	BY 06	40179	48U	5461232	32003299120	T	########	231	53	8	424	OH SEC/DR CL HI	OH SC CL-H	1825	SCHILDER	1	SC	546123299					
FORCED INTERR	BA	BT 03	40373	E99K	6357435	32003299121	T	########	233	44	1	44	TREE CLEARANC	TREE CLEAR	805	SCHILLING	1	TF	635743565					
FORCED INTERR	GA	STW0	35350	39HJ	6231450	32003300001	T	########	000	73	1	73	BU DISC OR BARI	DISC/BARRL	21710	S SHELBY	1	TF	623145083					
FORCED INTERR	GA	MOY0	31336		6737022	32003300002	T	########	013	43	1	43	UNKNOWN	UNKNOWN	2525	JONES DR		TF	673702263					
FORCED INTERR	RS	RZ 02	3516A	28RN	5137754	32003300002	F	########	030	132	52	6864	UNKNOWN	UNKNOWN	1803	FM 655 RD	1	LF	RA1					
FORCED INTERR	RS	RZ 02	3516A	N68G	5138700	32003300002	F	########	035	212	1	212	UNKNOWN	UNKNOWN	1728	FM 655	1	DB	N68G					
FORCED INTERR	RS	RZ 02	3516A	RA1	5137752	32003300007	F	########	052	134	52	6968	BU DISC OR BARI	DISC/BARRL	1803	FM 655 RD	1	LF	RA1					
FORCED INTERR	HM	GR 02	20189	48K	5465938	22003300004	F	########	055	49	2	98	TREE CLEARANC	TREE CLEAR	4500	GREENS	1	LF	48K					
FORCED INTERR	CH	LY 42	4706D		6059148	32003300006	T	########	060	40	4	160	UNKNOWN	UNKNOWN	16214	BEAR BA		TF	605914870					

REFUSED POWER POT AND KEARNEY BARREL IN LIGHTER POT REF TR RPLD B4U BARREL ON TR 1 0
REFUSE LINE FUSE. REF LF 1 0
REF TR. 1 0
CREW REPLACED A BURNED UP 333 7200/12470 120/240 JRK 1 0
already has wip, REF TR 1 0
MADE REPAIRS TO XFMR LEAD ON LIGHTER XFMR CLOSED DELTA BANK LEFT ON AND WORKING CUST NOTIFIED, RPRD BUSS WORK @ TR 1 0
REF TR; 1 0
REFUSED LIGHTER X-FMER @ 2411——CAUSE UNKOWNN REF TR; 1 0
REFUSED TRNS / LEFT SERV ON / NOTIFIED REF TR 1 0
REF LF 1 0
REF TR; 1 0
REF LF 1 0
ROAD OUT B PHASE LF B4W IT NEEDS TREE TRIMMING @ 214 MEMORY LN REFUSED LF-B4W B PHASE, REF LF 1 0
REFUSED 25 KVA TRNS 7200 120/240 REF TR. 1 0
REF TR. 1 0
TRIM TREE AND REFUSE TRANSF REF TR. 1 0
REF LF 1 0
REF TR. 1 0
refused 50kva repl have broke, REF TR. 1 0
RPLD 50 KVA WITH SAME AL BO HAVE W A 3X3 AREA ON PAD AND GROUND ABOUT A HALF GAL WILL CALL U BY PHONE WITH OLD XFMR # WHEN I GET TO 8PB URD # W # 2328, RPLD B4U TF 1 0

REFUSED 25KV 7200 TRUL REF TR. 1 0
PICKED UP 1 8PAN #4 NUTRAL—CLEARED LOTS OF TREES OUT OF OPEN WIRE BEC PAU PR NEUT. 1 0
REFURED LF B L 6 30-T, REF LF; 1 0
REF TR. 1 0
REFURED LF 71PH 15-T, REF LF. 1 0
REFURED LIGHTER X-FMER @ 4646 REF TR. 1 0
RPLD B4U TR. 1 0
REPLACED LTNG ARR, CONNS ATWH, INSTALLED WLP AND REPLACED FUSE BARREL, REF TR. RPLD CONN @ WH. RPLD LIGHTNING ARRESTOR. 1 0
TRIMMED PALM TREE OFF TP — TRNS & REFUSED TRNS / LEFT SERV ON. REF TR. RMVD TREE,IMB OFF PR; 1 0
REFURED LINE FUSE A8 ID 86 T REF LF 1 0
Refused x-frm due to vines, REF TR 1 0
REF TR. 1 0
REFURED LF REF LF 1 0
REFURED E41E FEEDING PRI METERING AND CUSTOMERS TP LEFT CUSTOMER OFF TX. ELECTRICIAN SHOWS UP TO CHECK URD. REF LF. 1 0
REFURED TRX DUE TO SQUIRREL TRIMED TREES & REFUSED LINE FUSE. REF LF REF TR. 1 0
REFURED 35 CONN POWER POT IN OPEN DELTA BANK. REF TR. 1 0
INSTALL WLP & REFUSED 80 KVA POT REF TR. 1 0
REPLACE CUT OUT ON L F (C47K) A PHASE REF LF, RPLD B4U DISC-LF BLOWN. 1 0
REPLACED 120KA DISCONNECT & TRANS REPLACED #4 SECONDARIES AND DROPS TRIMMED TREES FROM OPEN WIRE SECONDARIES. RPLD B4U DISC TF NOT BLOWN. RPRD CONN @ TR. 1 0
NOTHING WRONG WITH BARREL, FUSE PULLED IN TWO, REF TR. 1 0
NEED TO REPLACE 86' CLASS 3 POLE WITH OPEN DELTA BANK ON IT ON THE STREET POLE HAS THREE RUBBER ON THE POLE MBO SENT TO SERVICE CENTER 1 0
REPLACE 2 BURNED UP KEARNEY FUSE BARREL E LEFT ON AND WORKING CUST NOTIFIED, RPLD B4U BARREL ON TR. 1 0
REFURED THE NORTH PHASE OF LF-41 MB- 10BT, REF LF. 1 0
REFURED LF, REF LF, 1 0
REF TR; 1 0
refused power tran (M) in a closed delta bank —tape broke, REF TR. 1 0
REF TR; 1 0
removed vines off pole and trans, REF TR. 1 0
REFURE TRANSF REF TR; 1 0
REF LF; 1 0
REPL 12 K-MATE & REF 26——BEEN OUT A WEEK OR SO RPLD LIMITER @ TR, REF TR 1 0
REFURED 50 KVA 7200-120/240 VOLT TR WLP ALREADY INSTALLED REF TR. 1 0
REFURED W LF 33LU LOC 1ST SO SAN MARINO & LIF E41E LOC 1ST NO OF SAN JACINTO CAUSED BY A & H ELECTRIC WORKING ON CUST OWNED DIST @ 100 MARKET I METER # W 715332 1 0
REPL B4U TRANS RPLD B4U TR. 1 0
REF TR. 1 0
REPLACED 75 KVA CAP 7200-120/240 WITH 50 KVA CONVENTIONAL 7200-120/240 ADDED DISCONNECT AND WLP SQUIRREL LEFT ON AND WORKING CUST NOTIFIED, RPLD B4U TR. 1 0
REFURSED LINE FUSE 28G REF LF 1 0
REF TR; 1 0
PICK UP 2 8PANS #2 PRI / RFZ 500 STPDWN, REF LF PAU PR-FUSE BLOWN. 1 0
OLD MTR Q474225 READING L R 70388 NEW MTR 056073200 READING 00000 CATEGORY 150 RPLD MTR. 1 0
RPRD CONN @ PL. 1 0
REFUSED LF— ROTTEN 40' IN REAR OF 13108 HALIFAX—NEEDS REPLACING ASAP— NTA—HAS 75 KVA CAP ON IT—NEED TO CALL JEFF @ 713-466-4203 TO ARRANGE ENTRY TO BACK YARD- TF 1 0
REFURED LINE FUSE #8# LB 80T REF LF. 1 0
REF TP RPRD URD PR. 1 0
FAST LIGHTING. REF LF 1 0
REFUSE T P AND REPLACE BARNETT FUSE, REF LF RPLD B4U BARREL ON TR. 1 0
REF TR. 1 0
REF TR. 1 0
REPLACED BURNT UP FUSE BARREL ON LIGHTER TRANS IN OPEN DELTA KEARNY BARREL OLD ACE. RPLD B4U BARREL ON TR. 1 0
RPLD CONN @ WH. RPLD CONN @ PL, RMVD TREE,IMB FROM DR. 1 0
REPLACED 16 KVA 7200/120/240 CSP @ 16 KVA CONV INST L/A AND WLP RPLD B4U TR RPLD LIGHTNING ARRESTOR. 1 0
REF LF, REF TR. 1 0
PLEASE NOTIFY CITY TO RESET TRAFFIC SIGNALS REF TR. 1 0
RPLD B4U TR. 1 0

REF LF. 1 0
REPL B4U CLAMP W/H - REATTACHED - RESADDED DROPS RPLD CONN @ WH. RPLD POA. 1 0
REPL B4D FUSE BARREL REF TP 1 0
repaired wip con fd rupt ont hp 32957836 D01 3 1 100 w/ a 24316442 unable to get readings new wip dwled bpw left main off two blown 200 amp fuses, REF LF RPLD MTR. 1 0
REPLACED 1 8PAN OF #2 OPEN WIRE WITH 1/0 3 COND ALTW. RPRD CONN @ TR. 1 0
REF TR. 1 0
REPLRE TRAN REF TR. 1 0
CLEANED UP & REPAIRED 1- HOT DROP CONNECTION IN TRANSFORMER, CUSTOMER STATED TROUBLE WITH A/C COMPRESSER . RPLD CONN @ TR. 1 0
CREW FD TREES BLOWING INTO PRIMARY AT 702.710 AND 435 PHILLIPS RD SE CTION # 30884 S/O 315 10% F&D BEND MESSAGE TO TRIM IN AM ASAP PER HEATHERLY JSB 1 1

REPLACED CONNECTIONS AT THE POLE 0 0
RPLD B4U DISC-TF BLOWN. 0 0
REFUSED & AND C PH LF UNKNOWN CHKD VOLT DRIG CALL 103 10 W LITTLE YORK CAUSE UNKN