



Control Number: 32182



Item Number: 18

Addendum StartPage: 0









7. Please describe any damage sustained by the transmission/distribution control center.

No damage sustained

8. Please describe any damage sustained by the communication system (voice and data) that impacted the restoration after the storm.

Wind damage to a 400 MHz UHF antenna mounted on the top of a 400 foot tower. No damage to the tower. The wind damage consisted of moving the antenna from a vertical position to a skewed position of approximately 80 degree off the horizontal. This did not cause the Cooperative to loose communication but did degrade the coverage.