

Control Number: 32182



Item Number: 142

Addendum StartPage: 0



Echelon Building II, Suite 200 9430 Research Boulevard, Austin, TX 78759 phone: 512-338-0473, fax: 512-346-0822

# PECEIVED 2006 SEP 28 PM 4: 54

September 28, 2006

Mr. James Galloway, Filing Clerk Public Utility Commission of Texas 1701 North Congress Avenue Austin, Texas 78711

Re: Project No. 32182 – Investigation of Methods to Improve Electric and Telecom Infrastructure That Will Minimize Long Term Outages and Restoration Costs

Dear Mr. Galloway:

On behalf of Etex Telephone Cooperative, Inc. ("Etex" or "Cooperative"), I am submitting an original and ten (10) copies of this response to the data request issued in this proceeding on August 23, 2006.

Etex maintains a limited number of aerial lines which are primarily linked to electric utility poles. Therefore, the Cooperative generally practices the processes outlined in the Rural Utility Service's Bulletin 1730-1, for which applicable excerpts are attached hereto. The Cooperative considers these excerpts to adequately define its inspection program and vegetation program.

Please file-stamp the additional copies and return them to me by way of our assistant. Your cooperation in this matter is greatly appreciated.

Sincerely,

Dee Dee Longenecker

Authorized Representative for Etex Telephone Cooperative, Inc.

Attachments

cc:

Ms. Susan Graves, Accountant Etex Telephone Cooperative, Inc.

## Excerpt from RUS Bulletin 1730-1 Exhibit A RUS FORM 300 RATING GUIDE CONDITIONS NORMALLY NEEDED TO JUSTIFY A RATING OF 3

## PART I – TRANSMISSION AND DISTRIBUTION FACILITIES:

### 3. Distribution Lines – Overhead

- a. <u>Inspection and Maintenance Program and Records:</u> ...All overhead lines (including those on private right-of-way) patrolled annually (walking, riding or aerial); more frequently if experience dictates. Records maintained for ...line patrol with deficiencies corrected in a timely manner. ...[E]quipment changeout program in place to keep ...failed equipment to a minimum.
- b. <u>Compliance with Safety Codes Foreign Structures:</u> Utility has policy and practice of immediately remedying foreign structures which conflict with primary lines upon observation.

<u>Compliance with Safety Codes – Attachments:</u> All overheard attachments meet NESC separation and clearance requirements...

### PART II - OPERATION AND MAINTENANCE:

### 6. Line Maintenance and Work Order Procedures

a. <u>Work Planning and Scheduling:</u> ... Work order inspections performed in accordance with 7 CFR 1724, Electric Engineering, Architectural Services and Design Policies and Procedures (i.e., within 6 months of completion of construction.) Utility promptly provides inspector with written notice that clean-up work has been completed...

<u>Work Backlogs – Right-of-Way Maintenance:</u> Adequate resources being provided to address re-clearing on timely basis. Right-of-way re-trimming cycles to be dictated by local conditions.

<u>Work Backlogs – Other:</u> Job orders from line inspection completed in reasonable time frames.