





Water and Sewer CCN Viewer




December 9, 2014

-  Water CCN Facility Lines
-  Water CCN Service Areas

1:72,224



Sources: Esri, HERE, DeLorme, USGS, Intermap, increment P Corp, NRCAN, Esri Japan, METI, Esri China (Hong Kong), Esri (Thailand).





ATTACHMENT

9



PWS/ 0032/CO/03-27-2014/CCI

Bryan W. Sitaw, Ph.D., P.E., *Chairman*
Toby Baker, *Commissioner*
Zak Covar, *Commissioner*
Richard A. Hyde, P.E., *Executive Director*



TEXAS COMMISSION ON ENVIRONMENTAL QUALITY

Protecting Texas by Reducing and Preventing Pollution

May 2, 2014

Mr. Kyle Edwards, President
Union Hill WSC
PO Box 197
Brownsboro, Texas 75756-0197

Re: Comprehensive Compliance Investigation at: Union Hill WSC, South of FM 3204,
East of Brownsboro, (Henderson County), Texas, RN101266161, TCEQ ID No.:
1070032, Investigation No.: 1158934

Dear Mr. Edwards:

On March 27, 2014, Jennifer King of the Texas Commission on Environmental Quality (TCEQ) Tyler Region Office conducted an investigation of the above-referenced facility to evaluate compliance with applicable requirements for public water supply systems. No violations are being alleged as a result of the investigation.

The TCEQ appreciates your assistance in this matter and your compliance efforts to ensure protection of the State's environment. If you or members of your staff have any questions regarding these matters, please feel free to contact Ms. Jennifer King in the Tyler Region Office at (903) 535-5150.

Sincerely,

Ross B. Morgan
Water Section Manager
Tyler Region Office

RBM/JCK

(Rev 01/05/09)

TCLQ Region 5 • 2016 Teague Dr. • Tyler, Texas 75701-3734 • 903-535-5100 • Fax 903-595-1562

Austin Headquarters: 512-239-1000 • tceq.texas.gov • How is our customer service? tceq.texas.gov/customer survey

www.tceq.texas.gov