

Control Number: 49834



Item Number: 7

Addendum StartPage: 0

DOCKET NO. 49834

RECEIVED

2019 SEP 10 PM 3:36

**APPLICATION OF QUADVEST, L.P.
TO AMEND ITS SEWER
CERTIFICATE OF CONVENIENCE
AND NECESSITY IN LIBERTY
COUNTY**

§
§
§
§
§

PUBLIC UTILITY COMMISSION

OF TEXAS

PUBLIC UTILITY COMMISSION
FILING CLERK

ORDER NO. 2

**FINDING APPLICATION INSUFFICIENT, ESTABLISHING DEADLINES AND
OPPORTUNITY TO CURE, AND RESTYLING APPLICATION**

This Order addresses the style and administrative completeness of the application filed on August 8, 2019, by Quadvest L.P. to amend its sewer certificate of convenience and necessity in Montgomery County.

On September 5, 2019, Quadvest submitted a replacement for page 2 of the application, and clarified that they are not seeking dual sewer certification with South Cleveland Water Supply Corporation. The style of this application is changed as reflected in this Order.

The administrative law judge finds the application is administratively incomplete and insufficient for further review in accordance with 16 Texas Administrative Code (TAC) § 24.8(b).

Under 16 TAC § 24.8(d), the Commission does not consider an application filed until it finds the application administratively complete. Thus, at this time the application is not considered filed with the Commission.


On or before October 9, 2019, Quadvest must supplement the application to cure the deficiencies described in Patricia Garcia's September 5, 2019 memorandum. Until the Commission receives and reviews the supplemental information, the application cannot proceed. Quadvest must not issue notice until the application is deemed administratively complete.

On or before November 8, 2019, Commission Staff must file a supplemental recommendation regarding the administrative completeness of the application, along with a proposed procedural schedule, if appropriate.

7

Signed at Austin, Texas the 10th day of September 2019.

PUBLIC UTILITY COMMISSION OF TEXAS



MAYSON PEARSON
ADMINISTRATIVE LAW JUDGE

Q \CADM\Docket Management\Water\CCN\49xxx\49834-2 deficient.docx