



Control Number: 51089



Item Number: 19

Addendum StartPage: 0

Staff 1-2 Please explain how CSWR-Texas and Mr. Wilson plan to remedy the outstanding regulatory assessment fees owed to the Texas Commission on Environmental Quality (TCEQ) for the years of 2015 through 2017. For more information about the unpaid fees, please call the TCEQ at 512-239-4691.

Fee With Penalties for 2015= \$596.18
& 2017 = \$ 597.29
= \$1193.47 paid 10/16/20

