



Control Number: 51415



Item Number: 191

Addendum StartPage: 0



**SOAH DOCKET NO. 473-21-0538
PUC DOCKET NO. 51415**

**APPLICATION OF SOUTHWESTERN §
ELECTRIC POWER COMPANY FOR §
AUTHORITY TO CHANGE RATES §** **BEFORE THE STATE OFFICE
OF
ADMINISTRATIVE HEARINGS**

**SOUTHWESTERN ELECTRIC POWER COMPANY'S RESPONSE TO COMMISSION
STAFF'S TENTH REQUEST FOR INFORMATION**

FEBRUARY 18, 2021

TABLE OF CONTENTS

<u>SECTION</u>	<u>FILE NAME</u>	<u>PAGE</u>
Response No. STAFF 10-1	51415 STAFF10 Pkg.pdf.....	2
Response No. STAFF 10-2	51415 STAFF10 Pkg.pdf.....	3
Response No. STAFF 10-3	51415 STAFF10 Pkg.pdf.....	4
Attachment 1 to No. STAFF 10-3	Staff_10-3_Attachment_1.xlsx.....	5
Response No. STAFF 10-4	51415 STAFF10 Pkg.pdf.....	8
Response No. STAFF 10-5	51415 STAFF10 Pkg.pdf.....	9
Response No. STAFF 10-6	51415 STAFF10 Pkg.pdf.....	10
Attachment 1 to No. STAFF 10-6	Staff_10-6_Attachment_1.xlsx.....	11
Response No. STAFF 10-7	51415 STAFF10 Pkg.pdf.....	12
Attachment 1 to No. STAFF 10-7	Staff_10-7_Attachment_1.xlsx.....	13
Response No. STAFF 10-8	51415 STAFF10 Pkg.pdf.....	14

Files provided electronically on the PUC Interchange

Staff_10-3_Attachment_1.xlsx
Staff_10-6_Attachment_1.xlsx
Staff_10-7_Attachment_1.xlsx

**SOAH DOCKET NO. 473-21-0538
PUC DOCKET NO. 51415**

**SOUTHWESTERN ELECTRIC POWER COMPANY'S RESPONSE TO COMMISSION
STAFF'S TENTH REQUEST FOR INFORMATION**

Question No. STAFF 10-1:

Please state how SWEPCO defines the term "replacement unit."

Response No. STAFF 10-1:

Assuming this question refers to the definition of a "retirement unit" instead of "replacement unit", the Company provides the following response. "Retirement units" as defined by FERC refers to those items of electric plant which, when retired, with or without replacement, are accounted for by crediting the book cost thereof to the electric plant account in which included. Retirement units are the basis of the Company's capitalization policy.

Prepared By: Jason A. Cash

Title: Accounting Sr Mgr

Sponsored By: Jason A. Cash

Title: Accounting Sr Mgr

**SOAH DOCKET NO. 473-21-0538
PUC DOCKET NO. 51415**

**SOUTHWESTERN ELECTRIC POWER COMPANY'S RESPONSE TO COMMISSION
STAFF'S TENTH REQUEST FOR INFORMATION**

Question No. STAFF 10-2:

What is SWEPCO's capital replacement policy?

Response No. STAFF 10-2:

The Company follows Federal Energy Regulatory Commission (FERC) guidelines to determine when expenditures should be classified as capital and considered additions or retirements of electric plant. FERC guidelines state that all property shall be considered as consisting of retirement units and minor items of property. Please refer to the Company's response to Staff 10-1 for the definition of a retirement unit.

Prepared By: Jason A. Cash

Title: Accounting Sr Mgr

Sponsored By: Jason A. Cash

Title: Accounting Sr Mgr

**SOAH DOCKET NO. 473-21-0538
PUC DOCKET NO. 51415**

**SOUTHWESTERN ELECTRIC POWER COMPANY'S RESPONSE TO COMMISSION
STAFF'S TENTH REQUEST FOR INFORMATION**

Question No. STAFF 10-3:

What types of failures are captured/listed in the capital blanket for transmission and distribution?

Response No. STAFF 10-3:

The requested transmission information was provided in attachment, Staff 2-13 Attachment 1. The same attachment has been sorted and re-submitted as Staff_10-3_Attachment_1.xlsx. Refer to Column "F" for the type of failures captured/listed in the capital blanket for transmission.

Below are the types of failures for distribution capital blankets as set forth in Staff 2-13 Attachment 2:

Distribution Line

000007589 SEPTX-UG Cable Repl Failure

This budget project ID is for a program to replace underground primary and secondary cable sections that have failed. Scope limited to cable that has either reached end of life or has failed on multiple occasions. Scope does not include overload conditions or other conditions addressed by Distribution Planning criteria.

000007606 SEPTX-Failed Equip No Outage

This budget project ID is for a program addressing the reactive replacement of failed overhead or underground equipment in situations where the failure of the unit does not result in an outage.

EDN102209 Ds-Septx-Ai Pole Replacement

This budget project ID is for an annual program to replace wooden poles on the distribution system that have failed either above-grade or below-grade inspection.

Distribution Station

(Rows 5281 through 5313 in the Staff 2-13 Attachment 2 spreadsheet)

Multiple budget project IDs to purchase substation transformers replaced in failure scenarios.

Prepared By: William M. Romine

Title: Regulatory Consultant Staff

Prepared By: Paul D. Flory

Title: Regulatory Consultant Sr

Sponsored By: Drew W. Seidel

Title: VP Dist Region Ops

Sponsored By: Wayman L. Smith

Title: Dir Trans Planning

SWEPKO TRANSMISSION
Blanket/Program Projects

CPP_ID	CPP_DESC	PROJECT_ID	PROJ_DESC	WO_ID	WO_DESC	UTILITY_ACCOUNT	IN-SERVICE_DATE	ACTIVITY_COST
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006319	T/SEP-Tx/ ASSOC W/SI194ARRE	T0149602SWP	PRAIRIE GROVE CB GREENLAND 3820 REPLACE FAILED CABLE	35300 - Station Equipment	08/01/2016	5,226
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006319	T/SEP-Tx/ ASSOC W/SI194ARRE	T0149773SWP	MENA TRF P145 2 REPLACE FAILED FANS	35300 - Station Equipment	11/01/2016	1,273
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006319	T/SEP-Tx/ ASSOC W/SI194ARRE	T0150240SWP	SOUTH FAYETTEVILLE REPLACE FAILED METERS ON TRANSFORMERS	35300 - Station Equipment	07/01/2016	2,338
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006319	T/SEP-Tx/ ASSOC W/SI194ARRE	T0152707SWP	NORTH MAGAZINE PT CSIT12035635 - REPLACE FAILED PT WITH CCVT	35300 - Station Equipment	11/01/2016	2,576
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006319	T/SEP-Tx/ ASSOC W/SI194ARRE	T0153230SWP	SOUTH FAYETTEVILLE TRF P161 31 REPLACE FAILED 69 KV PT	35300 - Station Equipment	11/01/2016	2,380
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006319	T/SEP-Tx/ ASSOC W/SI194ARRE	T0154121SWP	EUREKA SPRINGS 161KV - REPLACE FAILED CCVT	35300 - Station Equipment	11/01/2016	4,190
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006319	T/SEP-Tx/ ASSOC W/SI194ARRE	T0177384SWP	REA - ELM SPRINGS DYESS 10457 REPLACE FAILED SF6 INTERRUPTERS	35300 - Station Equipment	07/01/2019	16,844
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006319	T/SEP-Tx/ ASSOC W/SI194ARRE	T0177860SWP	EUREKA SPRINGS 161KV STA REPLACE FAILED INTERCONNECT METERS	35300 - Station Equipment	06/01/2017	14,366
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006321	T/SEP-Tx/ ASSOC W/SI194LARE	42683413SWP	STANLEY NTEC REPLACE FAILED METER	35300 - Station Equipment	04/01/2018	922
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006321	T/SEP-Tx/ ASSOC W/SI194LARE	T0153158SWP	SOUTH SHREVEPORT CB 7260 REPL FAILED SURGE ARRESTERS	35300 - Station Equipment	09/01/2017	2,499
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006321	T/SEP-Tx/ ASSOC W/SI194LARE	T0155138SWP	LIEBERMAN - REPLACE FAILED 138 KV SWITCH 3015	35300 - Station Equipment	09/01/2016	12,211
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006322	T/SEP-Tx/ ASSOC W/SI194TXRE	4239308SWP	PITTSBURG CB 6210 - REPLACE FAILED SWITCH 6213	35300 - Station Equipment	08/01/2016	9,310
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006322	T/SEP-Tx/ ASSOC W/SI194TXRE	42393780SWP	DE KALB 12 5KV REPLACE FAILED METER	35300 - Station Equipment	04/01/2018	127
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006322	T/SEP-Tx/ ASSOC W/SI194TXRE	42466046SWP	NTEC DETC CENTER STATION REPLACE FAILED METER	35300 - Station Equipment	04/01/2018	3,176
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006322	T/SEP-Tx/ ASSOC W/SI194TXRE	42526820SWP	PERDUE SUBSTATION CHANGE OUT FAILED METER	35300 - Station Equipment	04/01/2018	745
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006322	T/SEP-Tx/ ASSOC W/SI194TXRE	42538717SWP	E BURGESS SUBSTATION CHANGE OUT FAILED METER	35300 - Station Equipment	07/01/2017	813
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006322	T/SEP-Tx/ ASSOC W/SI194TXRE	42574344SWP	WELSH HVDC REPLACE FAILED VALVE MODULE REACTORS	35300 - Station Equipment	11/01/2017	24,032
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006322	T/SEP-Tx/ ASSOC W/SI194TXRE	T0141539SWP	CARTHAGE POD - REPLACE FAILED CARRIER TUNER IN CCVT	35300 - Station Equipment	05/01/2016	3
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006322	T/SEP-Tx/ ASSOC W/SI194TXRE	T0150479SWP	ROCK HILL CB 1P70 - REPLACE (2) FAILED BUSHINGS	35300 - Station Equipment	12/01/2016	12,711
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006322	T/SEP-Tx/ ASSOC W/SI194TXRE	T0152088SWP	HUGHES SPRINGS CB 1200 CAPITAL PROJ-REPL FAILED SWITCH 1203	35300 - Station Equipment	11/01/2016	5,793
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006322	T/SEP-Tx/ ASSOC W/SI194TXRE	T0152505SWP	MOUNT PLEASANT CB 1860 REPL FAILED SWITCH 1863 CAP	35300 - Station Equipment	11/01/2016	7,716
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006322	T/SEP-Tx/ ASSOC W/SI194TXRE	T0153334SWP	NORTHWEST TEXARKANA CB 10690 REP FAILED SW 10693	35300 - Station Equipment	12/01/2016	31,082
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006322	T/SEP-Tx/ ASSOC W/SI194TXRE	T0154418SWP	MOUNT PLEASANT CB 1860 - REPLACE FAILED LIGHTNING ARRESTERS	35300 - Station Equipment	09/01/2016	8,696
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006322	T/SEP-Tx/ ASSOC W/SI194TXRE	T0164235SWP	IPC-JEFFERSON - REPLACE FAILED DP RELAY WITH SEL 421 RELAY	35300 - Station Equipment	10/01/2017	5,323
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006322	T/SEP-Tx/ ASSOC W/SI194TXRE	T0164433SWP	CHILDRESS WEST (SEP) - C/O FAILED 69KV PTS	35300 - Station Equipment	06/01/2017	15,302
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006322	T/SEP-Tx/ ASSOC W/SI194TXRE	T0171759SWP	LAKE PAULINE C/O FAILED DISC SWITCHES	35300 - Station Equipment	09/01/2016	2,216
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006322	T/SEP-Tx/ ASSOC W/SI194TXRE	T0175827SWP	SCOTTSDALE - REPLACE FAILED CARRIER WITH A TC10B SET	35300 - Station Equipment	11/01/2017	4,189
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006322	T/SEP-Tx/ ASSOC W/SI194TXRE	T0176273SWP	DIANA CB PIRKEY/SW SHREVEPORT - REPLACE FAILED CB11910	35300 - Station Equipment	07/01/2016	69,770
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006322	T/SEP-Tx/ ASSOC W/SI194TXRE	T0177398SWP	WELSH - REPLACE FAILED LIGHT FIXTURES	35300 - Station Equipment	12/01/2016	20,912
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006322	T/SEP-Tx/ ASSOC W/SI194TXRE	T0177424SWP	WHITNEY P141 66 NORTH - REPLACE (2) FAILED 24" FANS	35300 - Station Equipment	07/01/2016	454
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006322	T/SEP-Tx/ ASSOC W/SI194TXRE	T0177494SWP	DIANA P345 29 CENTER - REPLACE (3) FAILED 24" FANS	35300 - Station Equipment	08/01/2016	230
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006322	T/SEP-Tx/ ASSOC W/SI194TXRE	T0177495SWP	DIANA P345 25 SOUTH - REPLACE (2) FAILED 24" FANS	35300 - Station Equipment	08/01/2016	447
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006322	T/SEP-Tx/ ASSOC W/SI194TXRE	T0177736SWP	MARSHALL 138KV P142 64 NORTH - REPLACE (1) FAILED 24" FAN	35300 - Station Equipment	08/01/2016	354
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006322	T/SEP-Tx/ ASSOC W/SI194TXRE	T0177861SWP	SHAMROCK C/O FAILED CAPACITORS	35300 - Station Equipment	08/01/2016	5,018
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	000006322	T/SEP-Tx/ ASSOC W/SI194TXRE	T0178310SWP	KNOX LEE P141 54 - REPLACE (2) FAILED 24" FANS	35300 - Station Equipment	08/01/2016	638
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111ARSRE	SHADOW for B194ARSRE	T0185320SWP	HUNTINGTON STA - FAILED 12KV INSULATORS & MET CURRENT XFRMRS	35300 - Station Equipment	06/01/2017	5,414
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111ARSRE	SHADOW for B194ARSRE	T0186359SWP	BONANZA STA REPLACE FAILED 34KV SWITCHES	35300 - Station Equipment	06/01/2017	1,340
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111ARSRE	SHADOW for B194ARSRE	T0186763SWP	EAST ROGERS STA - REPLACE FAILING BUS PT	35300 - Station Equipment	05/01/2018	4,725
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111ARSRE	SHADOW for B194ARSRE	T0187135SWP	NORTH HUNTINGTON STA REPLACE FAILED 69KV ARRESTERS	35300 - Station Equipment	11/01/2017	917
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111ARSRE	SHADOW for B194ARSRE	T0187465SWP	FLINT CREEK SUB REPLACE FAILED 345KV ARRESTERS	35300 - Station Equipment	05/01/2018	13,393
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111ARSRE	SHADOW for B194ARSRE	T0187692SWP	S FAYETTEVILLE CAP BANK REPLACE FAILED CAPACITORS & LIMITER	35300 - Station Equipment	05/01/2018	75
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111ARSRE	SHADOW for B194ARSRE	T0187902SWP	EAST ROGERS CAP BANK REPLACE FAILED CAPACITORS & LIMITERS	35300 - Station Equipment	06/01/2017	6,308
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111ARSRE	SHADOW for B194ARSRE	T0189361SWP	SILGAM SPRINGS 161KV STA REPLACE FAILED AC IN CONTROL HOUSE	35200 - Structures and Improvements	08/01/2017	476
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111ARSRE	SHADOW for B194ARSRE	T0189361SWP	SILGAM SPRINGS 161KV STA REPLACE FAILED AC IN CONTROL HOUSE	35300 - Station Equipment	08/01/2017	23
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111ARSRE	SHADOW for B194ARSRE	T0190141SWP	FLINT CREEK SUB TRF P345 50 EAST BUSHING FAILURE	35300 - Station Equipment	10/01/2018	143,135
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111ARSRE	SHADOW for B194ARSRE	T0194218SWP	WEST BOONEVILLE STA REPLACE FAILED TRANSFER SWITCH	35300 - Station Equipment	05/01/2018	2,351
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111ARSRE	SHADOW for B194ARSRE	T0197692SWP	DEQUEEN TRF P141 48 APP39571 CAPITAL PROJECT/FAILED FANS	35300 - Station Equipment	04/01/2018	1,546
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111ARSRE	SHADOW for B194ARSRE	T0199633SWP	CHAMBERS SPRING REPLACE FAILED 345KV CCVT	35300 - Station Equipment	09/01/2018	4,457
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111ARSRE	SHADOW for B194ARSRE	T0199755SWP	MENA TRF P145 02 70705A CAPITAL PROJECT/FAILED FANS	35300 - Station Equipment	08/01/2018	1,691
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111ARSRE	SHADOW for B194ARSRE	T0200536SWP	NORTH HUNTINGTON REPLACE FAILED 69KV ARRESTERS	35300 - Station Equipment	08/01/2018	231
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111ARSRE	SHADOW for B194ARSRE	T0200895SWP	EAST ROGERS REPLACE FAILED 69KV CT	35300 - Station Equipment	01/01/2019	3,742
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111ARSRE	SHADOW for B194ARSRE	T0204643SWP	NORTH HUNTINGTON REPLACE FAILED 161KV CCVT	35300 - Station Equipment	08/01/2018	3,129
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111ARSRE	SHADOW for B194ARSRE	T0215869SWP	NASHVILLE 69KV CB CB-3050 REPL FAILED CB AND REPL LINE PT	35300 - Station Equipment	12/01/2019	20,256
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111ARSRE	SHADOW for B194ARSRE	T50222179SWP	NORTH MAGAZINE BATTERY BANK - REPLACE FAILING BANK	35300 - Station Equipment	12/01/2019	4,617
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111ARSRE	SHADOW for B194ARSRE	T50222659SWP	SOUTH NASHVILLE CB-REPL FAILED AIR COMPRESSOR	35300 - Station Equipment	03/01/2020	2,390
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111LASRE	T/SW/Shadow for B194LASRE	T0179934SWP	NORTHWEST SHREVEPORT REPL FAILED PAD MOUNT XFMR	35300 - Station Equipment	04/01/2017	4,315
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111LASRE	T/SW/Shadow for B194LASRE	T0189828SWP	ARSENAL HILL STA CAPITAL PROJECT/P7184&P7202 FAILED FANS	35300 - Station Equipment	09/01/2017	566
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111LASRE	T/SW/Shadow for B194LASRE	T0189841SWP	BROADMOOR STA CAPITAL PROJECT/FAILED RMC 30	35300 - Station Equipment	09/01/2017	412
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111LASRE	T/SW/Shadow for B194LASRE	T0189860SWP	LOGANSPORT STA CAPITAL PROJECT/CHANGED OUT FAILED FANS	35300 - Station Equipment	12/01/2017	4,116
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111LASRE	T/SW/Shadow for B194LASRE	T0194309SWP	LUCAS CCVT ELLERBE MID 1646701007 CAPITAL PROJECT/FAILED69KV	35300 - Station Equipment	07/01/2018	3,049
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111LASRE	T/SW/Shadow for B194LASRE	T0200287SWP	LIEBERMAN STA CAPITAL PROJECT/FAILED 138KV SWITCHES	35300 - Station Equipment	04/01/2019	26,585
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111LASRE	T/SW/Shadow for B194LASRE	T0206619SWP	NORTH BENTON STA CAPITAL PROJECT/FAILED FANS	35300 - Station Equipment	07/01/2019	9,102
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111LASRE	T/SW/Shadow for B194LASRE	T0206827SWP	ARSENAL HILL CAPB CAP BANK 13730 CAPBANK13730/FAILED CANS	35300 - Station Equipment	11/01/2018	1,439
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111LASRE	T/SW/Shadow for B194LASRE	T0206863SWP	SUPERIOR (SW) CB CB-9060 9739/FAILED BREAKER 9060	35300 - Station Equipment	07/01/2019	50,897
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111TXLRE	T/SW/Shadow for B194TXLRE	T0358065SWP	KNOX LEE - PIRKEY A-1 INSULATOR FAILURE	35600 - Overhead Conductors, Device	09/01/2019	13,187
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111TXSRE	T/SW/Shadow for B194TXSRE	42921285SWP	WELSH HVDC STATION REPLACE FAILED AUTO TRANSFORMER TWO1 L3	35300 - Station Equipment	05/01/2019	43,799
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111TXSRE	T/SW/Shadow for B194TXSRE	T0183430SWP	WELSH STA REPL FAILED SWITCH 11683	35300 - Station Equipment	04/01/2018	33,067
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111TXSRE	T/SW/Shadow for B194TXSRE	T0178212SWP	OVERTON STA REPLACE FAILED CCVT & CARRIER TUNER PK	35300 - Station Equipment	10/01/2017	9,835
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111TXSRE	T/SW/Shadow for B194TXSRE	T0188035SWP	WELSH HVDC CONVERTER CB FILTER CB BM03 REP FAILED CTVT	35300 - Station Equipment	06/01/2017	2,636
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111TXSRE	T/SW/Shadow for B194TXSRE	T0188067SWP	PIRKEY STA PIRKEY - REPLACE FAILED 3 TON AC UNIT	35300 - Station Equipment	04/01/2017	2,736
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B111TXSRE	T/SW/Shadow for B194TXSRE	T0188443SWP	HEDLEY C/O FAILED MOS 1663 1662	35300 - Station Equipment	03/01/2018	7,584

**SWECO TRANSMISSION
Blanket/Program Projects**

CPP_ID	CPP_DESC	PROJECT_ID	PROJ_DESC	WO_ID	WO_DESC	UTILITY_ACCOUNT	IN-SERVICE_DATE	ACTIVITY_COST
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B111TXSRE	B111TXSRE T/SW/Shadow for B194TXSRE	T01889205WP	BUFORD SURVEY DSC MOABS 7625 REPLACE FAILED SWITCH	35300 - Station Equipment	09/01/2018	61,786
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B111TXSRE	B111TXSRE T/SW/Shadow for B194TXSRE	T01892845WP	PERDUE CAPB 86 4 MVAR CAP BANK 138KV REPLACE FAILED CAPACITO	35300 - Station Equipment	06/01/2017	4,040
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B111TXSRE	B111TXSRE T/SW/Shadow for B194TXSRE	T01901865WP	DIANA STA CAPITAL REPL FAILED SWITCH 13098	35300 - Station Equipment	01/01/2018	18,591
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B111TXSRE	B111TXSRE T/SW/Shadow for B194TXSRE	T01932465WP	DIANA STA REPL FAILED SWITCH 13105	35300 - Station Equipment	11/01/2017	15,777
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B111TXSRE	B111TXSRE T/SW/Shadow for B194TXSRE	T01955705WP	DIANA STA DIANA REPLACE FAILED CVT'S	35300 - Station Equipment	01/01/2018	10,481
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B111TXSRE	B111TXSRE T/SW/Shadow for B194TXSRE	T01956495WP	SHAMROCK C/O FAILED CAP BANK CS 6730	35300 - Station Equipment	03/01/2018	56,875
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B111TXSRE	B111TXSRE T/SW/Shadow for B194TXSRE	T01958855WP	EASTON SUBSTATION- REPLACE FAILED ION METER	35300 - Station Equipment	01/01/2020	905
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B111TXSRE	B111TXSRE T/SW/Shadow for B194TXSRE	T01989235WP	JERICHO C/O FAILED A/C UNIT	35200 - Structures and Improvements	03/01/2018	290
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B111TXSRE	B111TXSRE T/SW/Shadow for B194TXSRE	T01989235WP	JERICHO C/O FAILED A/C UNIT	35300 - Station Equipment	03/01/2018	372
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B111TXSRE	B111TXSRE T/SW/Shadow for B194TXSRE	T01989535WP	LYDIA MET LYDIA 345 - VALLIANT 345 REPLACETWO FAILED METERS	35300 - Station Equipment	10/01/2018	1,517
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B111TXSRE	B111TXSRE T/SW/Shadow for B194TXSRE	T02041725WP	CAMP COUNTY POD CAPITAL PROJECT/REPLACE FAILED HVAC	35300 - Station Equipment	12/01/2019	1,862
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B111TXSRE	B111TXSRE T/SW/Shadow for B194TXSRE	T02043105WP	SHAMROCK C/O FAILED RELAY 38062R2	35300 - Station Equipment	10/01/2018	2,686
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B111TXSRE	B111TXSRE T/SW/Shadow for B194TXSRE	T02043105WP	SHAMROCK C/O FAILED RELAY 38062R2	35316 - Station Equipment-SmartGrid	10/01/2018	480
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B111TXSRE	B111TXSRE T/SW/Shadow for B194TXSRE	T02045335WP	LEBROCK MET STG 001 BACKUP 907A716 REPLACE FAILED METER	35300 - Station Equipment	03/01/2020	1,288
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B111TXSRE	B111TXSRE T/SW/Shadow for B194TXSRE	T02046355WP	JERICHO C/O FAILED BATTERY ONLY	35300 - Station Equipment	09/01/2018	3,580
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B111TXSRE	B111TXSRE T/SW/Shadow for B194TXSRE	T02065255WP	WOODLAWN (SW) CB CB-2090 REPLACE FAILED COMPRESSOR AND MOTOR	35300 - Station Equipment	12/01/2019	629
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B111TXSRE	B111TXSRE T/SW/Shadow for B194TXSRE	T02068885WP	MARSHALL 69KV CB ROCKHILL 1340 REPLACE FAILED CB	35300 - Station Equipment	12/01/2018	30,636
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B111TXSRE	B111TXSRE T/SW/Shadow for B194TXSRE	T02100705WP	TROBROOK2772 - PIRKEY STA REPL 3 FAILED LIGHTNING ARRESTERS	35300 - Station Equipment	01/01/2020	8,813
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B111TXSRE	B111TXSRE T/SW/Shadow for B194TXSRE	T02156425WP	ROCK HILL CB CB-10120 REPLACE FAILED COMPRESSOR	35300 - Station Equipment	11/01/2019	2,936
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B111TXSRE	B111TXSRE T/SW/Shadow for B194TXSRE	T02224025WP	CHILDRESS WEST C/O FAILED CB 6480	35300 - Station Equipment	12/01/2019	26,962
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194ARSRE	B194ARSRE T/SW/Non-Specific Work-Station	T0185320	HUNTINGTON STA - FAILED 12KV INSULATORS & MET CURRENT XFRMRS	35300 - Station Equipment	06/01/2017	10,870
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194ARSRE	B194ARSRE T/SW/Non-Specific Work-Station	T0186359	BONANZA STA REPLACE FAILED 34KV SWITCHES	35300 - Station Equipment	06/01/2017	2,950
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194ARSRE	B194ARSRE T/SW/Non-Specific Work-Station	T0186763	EAST ROGERS STA - REPLACE FAILING BUS PT	35300 - Station Equipment	06/01/2018	9,282
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194ARSRE	B194ARSRE T/SW/Non-Specific Work-Station	T0187135	NORTH HUNTINGTON STA REPLACE FAILED 69KV ARRESTERS	35300 - Station Equipment	11/01/2017	1,784
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194ARSRE	B194ARSRE T/SW/Non-Specific Work-Station	T0187486	FLINT CREEK SUB REPLACE FAILED 345KV ARRESTERS	35300 - Station Equipment	06/01/2018	26,365
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194ARSRE	B194ARSRE T/SW/Non-Specific Work-Station	T0187692	S. FAYETTEVILLE CAP BANK REPLACE FAILED CAPACITORS & LIMITER	35300 - Station Equipment	06/01/2018	149
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194ARSRE	B194ARSRE T/SW/Non-Specific Work-Station	T0187902	EAST ROGERS CAP BANK REPLACE FAILED CAPACITORS & LIMITERS	35300 - Station Equipment	06/01/2017	12,288
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194ARSRE	B194ARSRE T/SW/Non-Specific Work-Station	T0189361	SILOAM SPRINGS 161KV STA REPLACE FAILED AC IN CONTROL HOUSE	35200 - Structures and Improvements	08/01/2017	949
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194ARSRE	B194ARSRE T/SW/Non-Specific Work-Station	T0189361	SILOAM SPRINGS 161KV STA REPLACE FAILED AC IN CONTROL HOUSE	35300 - Station Equipment	08/01/2017	45
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194ARSRE	B194ARSRE T/SW/Non-Specific Work-Station	T0190141	FLINT CREEK SUB TRF P345 50 EAST BUSHING FAILURE	35300 - Station Equipment	10/01/2018	284,512
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194ARSRE	B194ARSRE T/SW/Non-Specific Work-Station	T0194218	WEST BOONEVILLE STA REPLACE FAILED TRANSFER SWITCH	35300 - Station Equipment	06/01/2018	4,625
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194ARSRE	B194ARSRE T/SW/Non-Specific Work-Station	T0197692	DEQUEEN TRF P141 48 RPP39571 CAPITAL PROJECT/FAILED FANS	35300 - Station Equipment	04/01/2018	3,048
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194ARSRE	B194ARSRE T/SW/Non-Specific Work-Station	T0199633	CHAMBERS SPRING REPLACE FAILED 345KV CCVT	35300 - Station Equipment	09/01/2018	8,783
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194ARSRE	B194ARSRE T/SW/Non-Specific Work-Station	T0199755	MENA TRF P145 Q2 70705A CAPITAL PROJECT/FAILED FANS	35300 - Station Equipment	08/01/2018	3,350
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194ARSRE	B194ARSRE T/SW/Non-Specific Work-Station	T0200536	NORTH HUNTINGTON REPLACE FAILED 69KV ARRESTERS	35300 - Station Equipment	08/01/2018	493
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194ARSRE	B194ARSRE T/SW/Non-Specific Work-Station	T0200585	EAST ROGERS REPLACE FAILED 69KV CT	35300 - Station Equipment	01/01/2019	7,494
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194ARSRE	B194ARSRE T/SW/Non-Specific Work-Station	T0204643	NORTH HUNTINGTON REPLACE FAILED 161KV CCVT	35300 - Station Equipment	08/01/2018	6,210
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194ARSRE	B194ARSRE T/SW/Non-Specific Work-Station	T0215869	NASHVILLE 69KV CB CB-3050 REPL FAILED CB AND REPL LINE PT	35300 - Station Equipment	12/01/2019	41,247
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194ARSRE	B194ARSRE T/SW/Non-Specific Work-Station	T02222179	NORTH MAGAZINE BATTERY BANK - REPLACE FAILING BANK	35300 - Station Equipment	12/01/2019	9,199
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194ARSRE	B194ARSRE T/SW/Non-Specific Work-Station	T0222659	SOUTH NASHVILLE CB-REPL FAILED AIR COMPRESSOR	35300 - Station Equipment	03/01/2020	4,838
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194LASRE	B194LASRE T/SW/NonSpecificWorkStation-LA	T0179934	SOUTHWEST SHREVEPORT REPL FAILED PAD MOUNT XFMR	35300 - Station Equipment	04/01/2017	8,929
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194LASRE	B194LASRE T/SW/NonSpecificWorkStation-LA	T0189828	ARSENAL HILL STA CAPITAL PROJECT/P7184&P7202 FAILED FANS	35300 - Station Equipment	09/01/2017	1,174
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194LASRE	B194LASRE T/SW/NonSpecificWorkStation-LA	T0189841	BROADMOOR STA CAPITAL PROJECT/FAILED RMC 30	35300 - Station Equipment	09/01/2017	812
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194LASRE	B194LASRE T/SW/NonSpecificWorkStation-LA	T0189880	LOGANSPOUT STA CAPITAL PROJECT/CHANGED OUT FAILED FANS	35300 - Station Equipment	12/01/2017	8,205
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194LASRE	B194LASRE T/SW/NonSpecificWorkStation-LA	T0194309	LUCAS CCVT ELLERBE MID 1646701007 CAPITAL PROJECT/FAILED69KV	35300 - Station Equipment	07/01/2018	6,029
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194LASRE	B194LASRE T/SW/NonSpecificWorkStation-LA	T0200287	LIEBERMAN STA CAPITAL PROJECT/FAILED 138KV SWITCHES	35300 - Station Equipment	04/01/2019	52,994
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194LASRE	B194LASRE T/SW/NonSpecificWorkStation-LA	T0206619	NORTH BENTON STA CAPITAL PROJECT/FAILED FANS	35300 - Station Equipment	07/01/2019	18,161
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194LASRE	B194LASRE T/SW/NonSpecificWorkStation-LA	T0206827	ARSENAL HILL CAPB CAP BANK 13730 CAPBANK13730/FAILED CANS	35300 - Station Equipment	11/01/2018	2,869
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194LASRE	B194LASRE T/SW/NonSpecificWorkStation-LA	T0206863	SUPERIOR (SW) CB CB-9060 9739/FAILED BREAKER 9060	35300 - Station Equipment	07/01/2019	101,965
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194TXLRE	B194TXLRE T/SW/Non-Specific Work - Line	TLO35806	KNOX LEE - PIRKEY A-1 INSULATOR FAILURE	35600 - Overhead Conductors, Device	09/01/2019	27,104
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194TXSRE	B194TXSRE T/SW/Non-Specific Work Station	42921285	WELSH HVDC STATION REPLACE FAILED AUTO TRANSFORMER TWO1 L3	35300 - Station Equipment	05/01/2019	89,845
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194TXSRE	B194TXSRE T/SW/Non-Specific Work Station	T0183430	WELSH STA REPL FAILED SWITCH 11683	35300 - Station Equipment	04/01/2018	65,749
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194TXSRE	B194TXSRE T/SW/Non-Specific Work Station	T0187212	OVERTON STA REPLACE FAILED CCVT & CARRIER TUNER PK	35300 - Station Equipment	10/01/2017	19,322
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194TXSRE	B194TXSRE T/SW/Non-Specific Work Station	T0188035	WELSH HVDC CONVERTER CB FILTER CB BM03 REP FAILED CCVT	35300 - Station Equipment	06/01/2017	5,232
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194TXSRE	B194TXSRE T/SW/Non-Specific Work Station	T0188067	PIRKEY STA PIRKEY - REPLACE FAILED 3 TON AC UNIT	35300 - Station Equipment	04/01/2017	5,325
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194TXSRE	B194TXSRE T/SW/Non-Specific Work Station	T0188443	HEDLEY C/O FAILED MOS 1663 1662	35300 - Station Equipment	03/01/2018	15,451
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194TXSRE	B194TXSRE T/SW/Non-Specific Work Station	T0188920	BUFORD SURVEY DSC MOABS 7625 REPLACE FAILED SWITCH	35300 - Station Equipment	09/01/2018	122,783
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194TXSRE	B194TXSRE T/SW/Non-Specific Work Station	T0189284	PERDUE CAPB 86 4 MVAR CAP BANK 138KV REPLACE FAILED CAPACITO	35300 - Station Equipment	06/01/2017	7,990
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194TXSRE	B194TXSRE T/SW/Non-Specific Work Station	T0190186	DIANA STA CAPITAL REPL FAILED SWITCH 13098	35300 - Station Equipment	01/01/2018	37,059
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194TXSRE	B194TXSRE T/SW/Non-Specific Work Station	T0193246	DIANA STA REPL FAILED SWITCH 13105	35300 - Station Equipment	11/01/2017	31,115
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194TXSRE	B194TXSRE T/SW/Non-Specific Work Station	T0195570	DIANA STA DIANA REPLACE FAILED CVT'S	35300 - Station Equipment	01/01/2018	20,730
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194TXSRE	B194TXSRE T/SW/Non-Specific Work Station	T0195649	SHAMROCK C/O FAILED CAP BANK CS 6730	35300 - Station Equipment	03/01/2018	112,704
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194TXSRE	B194TXSRE T/SW/Non-Specific Work Station	T0195885	EASTON SUBSTATION- REPLACE FAILED ION METER	35300 - Station Equipment	01/01/2020	1,810
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194TXSRE	B194TXSRE T/SW/Non-Specific Work Station	T0198923	JERICHO C/O FAILED A/C UNIT	35200 - Structures and Improvements	03/01/2018	579
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194TXSRE	B194TXSRE T/SW/Non-Specific Work Station	T0198923	JERICHO C/O FAILED A/C UNIT	35300 - Station Equipment	03/01/2018	744
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194TXSRE	B194TXSRE T/SW/Non-Specific Work Station	T0198953	LYDIA MET LYDIA 345 - VALLIANT 345 REPLACETWO FAILED METERS	35300 - Station Equipment	10/01/2018	2,952
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194TXSRE	B194TXSRE T/SW/Non-Specific Work Station	T0204172	CAMP COUNTY POD CAPITAL PROJECT/REPLACE FAILED HVAC	35300 - Station Equipment	12/01/2019	3,623
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194TXSRE	B194TXSRE T/SW/Non-Specific Work Station	T0204310	SHAMROCK C/O FAILED RELAY 38062R2	35300 - Station Equipment	10/01/2018	5,306
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194TXSRE	B194TXSRE T/SW/Non-Specific Work Station	T0204310	SHAMROCK C/O FAILED RELAY 38062R2	35316 - Station Equipment-SmartGrid	10/01/2018	949
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194TXSRE	B194TXSRE T/SW/Non-Specific Work Station	T0204533	LEBROCK MET STG 001 BACKUP 907A716 REPLACE FAILED METER	35300 - Station Equipment	03/01/2020	2,606
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWECO	B194TXSRE	B194TXSRE T/SW/Non-Specific Work Station	T0204635	JERICHO C/O FAILED BATTERY ONLY	35300 - Station Equipment	09/01/2018	7,240

SWEPco TRANSMISSION
Blanket/Program Projects

CPP_ID	CPP_DESC	PROJECT_ID	PROJ_DESC	WO_ID	WO_DESC	UTILITY_ACCOUNT	IN-SERVICE_DATE	ACTIVITY_COST
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B194TXSRE	T/SW/Non-Specific Work Station	T0206525	WOODLAWN (SW) CB CB-2090 REPLACE FAILED COMPRESSOR AND MOTOR	35300 - Station Equipment	12/01/2019	1,283
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B194TXSRE	T/SW/Non-Specific Work Station	T0206888	MARSHALL 69KV CB ROCKHILL 1340 REPLACE FAILED CB	35300 - Station Equipment	12/01/2018	61,335
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B194TXSRE	T/SW/Non-Specific Work Station	T0210070	TROB0002772 - PIRKEY STA REPL 3 FAILED LIGHTNING ARRESTERS	35300 - Station Equipment	01/01/2020	17,394
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B194TXSRE	T/SW/Non-Specific Work Station	T0215642	ROCK HILL CB CB-10120 REPLACE FAILED COMPRESSOR	35300 - Station Equipment	11/01/2019	5,901
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	B194TXSRE	T/SW/Non-Specific Work Station	TSD222402	CHILDRESS WEST C/O FAILED CB 6480	35300 - Station Equipment	12/01/2019	54,300
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SETXAI501	T/SEP/TX/Assoc w/SETXS 00/00/0	42664029SWP	NW HENDERSON REPLACE FAILED CB 10930	35300 - Station Equipment	06/01/2017	15,525
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SETXS1501	T/SEP/TX/Maj Min Storm 00/00/0	42664029	NW HENDERSON REPLACE FAILED CB 10930	35300 - Station Equipment	06/01/2017	30,218
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI111ARLR	TB/SEP-Tx ASSOC W/SI1194ARLR	42579933SWP	DIERKS - MENA REPLACE FAILED CROSS ARM	35500 - Poles and Fixtures	08/01/2016	1,419
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194ARLR	TB/SEP/AR - LINE REHAB	42579933	DIERKS - MENA REPLACE FAILED CROSS ARM	35500 - Poles and Fixtures	08/01/2016	2,859
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194ARRE	TB/SEP-NT ARK SYS REHAB	T0084007	WEST BOONEVILLE CB 9380 - REPLACE 3 FAILING 69KV SURGE ARRES	35300 - Station Equipment	11/01/2008	(127)
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194ARRE	TB/SEP-NT ARK SYS REHAB	T0149602	PRAIRIE GROVE CB GREENLAND 3820 REPLACE FAILED CABLE	35300 - Station Equipment	08/01/2016	10,527
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194ARRE	TB/SEP-NT ARK SYS REHAB	T0149773	MENA TRF P145.2 REPLACE FAILED FANS	35300 - Station Equipment	11/01/2016	2,652
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194ARRE	TB/SEP-NT ARK SYS REHAB	T0150240	SOUTH FAYETTEVILLE REPLACE FAILED METERS ON TRANSFORMERS	35300 - Station Equipment	07/01/2016	4,657
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194ARRE	TB/SEP-NT ARK SYS REHAB	T0152707	NORTH MAGAZINE PT CSIT12035635 - REPLACE FAILED PT WITH CCVT	35300 - Station Equipment	11/01/2016	5,149
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194ARRE	TB/SEP-NT ARK SYS REHAB	T0153230	SOUTH FAYETTEVILLE TRF P161 31 REPLACE FAILED 69 KV PT	35300 - Station Equipment	11/01/2016	4,757
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194ARRE	TB/SEP-NT ARK SYS REHAB	T0154121	EUREKA SPRINGS 161KV - REPLACE FAILED CCVT	35300 - Station Equipment	11/01/2016	8,458
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194ARRE	TB/SEP-NT ARK SYS REHAB	T0177384	REA - ELM SPRINGS DYESS 10457 REPLACE FAILED SF6 INTERRUPTERS	35300 - Station Equipment	07/01/2019	33,232
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194ARRE	TB/SEP-NT ARK SYS REHAB	T0177860	EUREKA SPRINGS 161KV STA REPLACE FAILED INTERCONNECT METERS	35300 - Station Equipment	06/01/2017	28,355
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194LARE	TB/SEP-NT LA SYS REHAB	42683413	STANLEY NTEC REPLACE FAILED METER	35300 - Station Equipment	04/01/2018	1,813
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194LARE	TB/SEP-NT LA SYS REHAB	T0153158	SOUTH SHREVEPORT CB 7260 REPL FAILED SURGE ARRESTERS	35300 - Station Equipment	09/01/2017	4,976
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194LARE	TB/SEP-NT LA SYS REHAB	T0155138	LIEBERMAN - REPLACE FAILED 138 KV SWITCH 3015	35300 - Station Equipment	09/01/2016	23,858
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194TXRE	TB/SEP-Tx TEXAS SYS REHAB	42393085	PITTSBURG CB 6210 - REPLACE FAILED SWITCH 6213	35300 - Station Equipment	08/01/2016	19,157
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194TXRE	TB/SEP-Tx TEXAS SYS REHAB	42393780	DE KALB 12 5KV REPLACE FAILED METER	35300 - Station Equipment	04/01/2018	2,419
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194TXRE	TB/SEP-Tx TEXAS SYS REHAB	42466046	NTEC DETC CENTER STATION REPLACE FAILED METER	35300 - Station Equipment	04/01/2018	6,247
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194TXRE	TB/SEP-Tx TEXAS SYS REHAB	42526820	PERDUE SUBSTATION CHANGE OUT FAILED METER	35300 - Station Equipment	04/01/2018	1,458
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194TXRE	TB/SEP-Tx TEXAS SYS REHAB	42538717	E BURGESS SUBSTATION CHANGE OUT FAILED METER	35300 - Station Equipment	07/01/2017	1,631
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194TXRE	TB/SEP-Tx TEXAS SYS REHAB	42574344	WELSH HVDC REPLACE FAILED VALVE MODULE REACTORS	35300 - Station Equipment	11/01/2017	46,775
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194TXRE	TB/SEP-Tx TEXAS SYS REHAB	T0141539	CARTHAGE POD - REPLACE FAILED CARRIER TUNER IN CCVT	35300 - Station Equipment	05/01/2016	5
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194TXRE	TB/SEP-Tx TEXAS SYS REHAB	T0150479	ROCK HILL CB 1P70 - REPLACE (2) FAILED BUSHINGS	35300 - Station Equipment	12/01/2016	25,178
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194TXRE	TB/SEP-Tx TEXAS SYS REHAB	T0152088	HUGHES SPRINGS CB 1200 CAPITAL PROJ-REPL FAILED SWITCH 1203	35300 - Station Equipment	11/01/2016	12,180
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194TXRE	TB/SEP-Tx TEXAS SYS REHAB	T0152505	MOUNT PLEASANT CB 1860 REPL FAILED SWITCH 1863 CAP	35300 - Station Equipment	11/01/2016	17,559
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194TXRE	TB/SEP-Tx TEXAS SYS REHAB	T0153334	NORTHWEST TEXARKANA CB 10690 REP FAILED SW 10693	35300 - Station Equipment	12/01/2016	60,880
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194TXRE	TB/SEP-Tx TEXAS SYS REHAB	T0154418	MOUNT PLEASANT CB 1860 - REPLACE FAILED LIGHTNING ARRESTERS	35300 - Station Equipment	09/01/2016	17,566
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194TXRE	TB/SEP-Tx TEXAS SYS REHAB	T0164235	IPC-JEFFERSON - REPLACE FAILED DLP RELAY WITH SEL 421 RELAY	35300 - Station Equipment	10/01/2017	10,694
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194TXRE	TB/SEP-Tx TEXAS SYS REHAB	T0164453	CHILDRESS WEST (SEP) - C/O FAILED 69KV PTS	35300 - Station Equipment	06/01/2017	30,532
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194TXRE	TB/SEP-Tx TEXAS SYS REHAB	T0171759	LAKE PAULINE C/O FAILED DISC SWITCHES	35300 - Station Equipment	09/01/2016	4,627
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194TXRE	TB/SEP-Tx TEXAS SYS REHAB	T0175827	SCOTTSVILLE - REPLACE FAILED CARRIER WITH A TC108 SET	35300 - Station Equipment	11/01/2017	8,265
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194TXRE	TB/SEP-Tx TEXAS SYS REHAB	T0176277	DIANA CB PIRKEY/SW SHREVEPORT - REPLACE FAILED CB11910	35300 - Station Equipment	07/01/2016	140,018
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194TXRE	TB/SEP-Tx TEXAS SYS REHAB	T0177398	WELSH - REPLACE FAILED LIGHT FIXTURES	35300 - Station Equipment	12/01/2016	41,317
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194TXRE	TB/SEP-Tx TEXAS SYS REHAB	T0177424	WHITNEY P141 66 NORTH - REPLACE (2) FAILED 24" FANS	35300 - Station Equipment	07/01/2016	887
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194TXRE	TB/SEP-Tx TEXAS SYS REHAB	T0177494	DIANA P345 29 CENTER - REPLACE (3) FAILED 24" FANS	35300 - Station Equipment	08/01/2016	450
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194TXRE	TB/SEP-Tx TEXAS SYS REHAB	T0177495	DIANA P345 25 SOUTH - REPLACE (2) FAILED 24" FANS	35300 - Station Equipment	08/01/2016	874
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194TXRE	TB/SEP-Tx TEXAS SYS REHAB	T0177736	MARSHALL 138KV P142 64 NORTH - REPLACE (1) FAILED 24" FAN	35300 - Station Equipment	08/01/2016	701
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194TXRE	TB/SEP-Tx TEXAS SYS REHAB	T0177861	SHAMROCK C/O FAILED CAPACITORS	35300 - Station Equipment	08/01/2016	9,969
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPco	SI194TXRE	TB/SEP-Tx TEXAS SYS REHAB	T0178310	KNOX LEE P141 54 - REPLACE (2) FAILED 24" FANS	35300 - Station Equipment	08/01/2016	1,252
Grand Total								2,982,924

**SOAH DOCKET NO. 473-21-0538
PUC DOCKET NO. 51415**

**SOUTHWESTERN ELECTRIC POWER COMPANY'S RESPONSE TO COMMISSION
STAFF'S TENTH REQUEST FOR INFORMATION**

Question No. STAFF 10-4:

Provide specific examples for when an equipment failure that has “failed on multiple occasions” is considered in the capital blanket program.

Response No. STAFF 10-4:

Please see the Company's response to Staff 10-3.

Prepared By: William M. Romine

Title: Regulatory Consultant Staff

Prepared By: Paul D. Flory

Title: Regulatory Consultant Sr

Sponsored By: Drew W. Seidel

Title: VP Dist Region Opers

Sponsored By: Wayman L. Smith

Title: Dir Trans Planning

**SOAH DOCKET NO. 473-21-0538
PUC DOCKET NO. 51415**

**SOUTHWESTERN ELECTRIC POWER COMPANY'S RESPONSE TO COMMISSION
STAFF'S TENTH REQUEST FOR INFORMATION**

Question No. STAFF 10-5:

Please identify all capital expenditures that were a result of the outages that occurred during the August 19, 2019 outage event on SWEPCO's system.

Response No. STAFF 10-5:

No capital costs were incurred for the restoration of service following the outages that occurred during the **August 18, 2019** outage event on SWEPCO's system.

Prepared By: William M. Romine

Title: Regulatory Consultant Staff

Prepared By: Paul D. Flory

Title: Regulatory Consultant Sr

Sponsored By: Drew W. Seidel

Title: VP Dist Region Ops

Sponsored By: Wayman L. Smith

Title: Dir Trans Planning

SOAH DOCKET NO. 473-21-0538
PUC DOCKET NO. 51415

SOUTHWESTERN ELECTRIC POWER COMPANY'S RESPONSE TO COMMISSION
STAFF'S TENTH REQUEST FOR INFORMATION

Question No. STAFF 10-6:

Please identify all operations and maintenance expenses that occurred as a result of, or to restore power after, the August 18, 2019 outage event on SWEPCO's system.

Response No. STAFF 10-6:

See Staff 10-6-Attachment 1.xlsx for the non-vegetation operations and maintenance expenses that occurred as a result of, or to restore power after, the August 18, 2019 outage event on SWEPCO's system. This response excludes the Vegetation O&M expense, which is provided in the response to Staff 10-7.

Prepared By: William M. Romine

Title: Regulatory Consultant Staff

Prepared By: Paul D. Flory

Title: Regulatory Consultant Sr

Sponsored By: Daniel R. Boezio

Title: VP Trans Field Services

Sponsored By: Drew W. Seidel

Title: VP Dist Region Ops

SWEPCO Transmission

SOAH Docket No. 473-21-0538
PUC Docket No. 51415
Staff's 10th RFI, Q. # Staff 10-6
Attachment 1
Page 1 of 1

SWEPCO Texas Rate Case Information			
Area	Work Order	Description	Amount
T-Line - Response			
	TL0036348001	Knox Lee-Pirkey - Emergency Aerial Patrol	\$ 2,074.58
	TL00036356022	Jefferson North Marshall - Conductor down	\$ 5,328.75
			\$ 7,403.33
P&C - Mitigation			
	T10139501	SWEPCO CT Verification - Trans. OM	\$ 8,053.05
	T10139506	SWPCO (AR/LA) CT Verification - Distr. OM	\$ 1,763.77
	T10139730	SWEPCO TX CT Verification - Dist. OM	\$ 5,039.04
			\$ 14,855.86
Station/P&C - Response			
	4044033901	TS-T-194 (1252) P&C DIRECT LABOR	\$ 1,004.13
	4203016001	SWEPCO TRANS INCIDENTAL STATION MAINT LESS THAN 4 HRS	\$ 230.42
	4203060301	SWEPCO TRANSMISSION TRANSFORMER MAINTENANCE	\$ 1,208.55
	4203060401	SWEPCO TRANSMISSION BREAKER MAINTENANCE	\$ 162.04
	4203060601	SWEPCO TRANSMISSION STATION SWITCHING	\$ 7,180.02
	4203061401	SWEPCO DISTRIBUTION STATION SWITCHING	\$ 429.26
	4203964801	OPERATION ANALYSIS	\$ 1,508.59
	4203964805	RELAY	\$ 326.39
			\$ 12,049.40
		Grand Total	\$ 34,308.59

SOAH DOCKET NO. 473-21-0538
PUC DOCKET NO. 51415

SOUTHWESTERN ELECTRIC POWER COMPANY'S RESPONSE TO COMMISSION
STAFF'S TENTH REQUEST FOR INFORMATION

Question No. STAFF 10-7:

Please identify all vegetation management expenses that resulted from work identified during the August 18, 2019 outage event.

Response No. STAFF 10-7:

See Staff 10-7_Attachment_1.xlsx for the Transmission vegetation management expenses that directly resulted from work identified during the August 18, 2019 outage event. Distribution has no Vegetation expenses as a result of the outage event.

Prepared By: William M. Romine

Title: Regulatory Consultant Staff

Prepared By: Paul D. Flory

Title: Regulatory Consultant Sr

Sponsored By: Daniel R. Boezio

Title: VP Trans Field Services

Sponsored By: Drew W. Seidel

Title: VP Dist Region Operers

SWEPCo Transmission

Line Name	Work Order	ABMS Project	Account Number	Sum of Total Cost
DIANA - PLILER ROAD	G0000194	000012900	5710000	530,162.24
KNOX LEE - PIRKEY	G0000194	000012900	5710000	10,281.39
PERDUE - DIANA	G0000194	000012900	5710000	202,829.29
PIRKEY - WHITNEY	G0000194	000012900	5710000	351,831.31
Grand Total				1,095,104.23

**SOAH DOCKET NO. 473-21-0538
PUC DOCKET NO. 51415**

**SOUTHWESTERN ELECTRIC POWER COMPANY'S RESPONSE TO COMMISSION
STAFF'S TENTH REQUEST FOR INFORMATION**

Question No. STAFF 10-8:

Knox Lee Outage – Quantify which expenses occurred as a result of the substation fire and explain whether this event was:

- a. Separate from the August 18, 2019 outage event;
- b. During the August 18, 2019 outage event;
- c. As a result of the August 18, 2019 outage event; and/or
- d. Immediately after the August 18, 2019 outage event.

Response No. STAFF 10-8:

The August 18, 2019 Knox Lee Unit 5 forced outage, which lasted approximately 4 hours, was due to a vegetation related transmission outage in the area. Knox Lee Unit 5 was offline at the time of the event. No expenses were incurred.

Prepared By: Tara D. Beske

Title: Regulatory Consultant Staff

Sponsored By: Monte A. McMahon

Title: VP Generating Assets SWEPCO

SWEPco TRANSMISSION
Blanket/Program Projects

CPP_ID	CPP_DESC	PROJECT_ID	PROJ_DESC	WO_ID	WO_DESC	UTILITY_ACCOUNT	IN-SERVICE_DATE	ACTIVITY_COST
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006319	000006319 T/SEP-Tx/ ASSOC W/S1194ARRE	T0149602SWP	PAIRIE GROVE CB GREENLAND 3820 REPLACE FAILED CABLE	35300 - Station Equipment	08/01/2016	5,226
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006319	000006319 T/SEP-Tx/ ASSOC W/S1194ARRE	T01497733SWP	MENA TRF P145 2 REPLACE FAILED FANS	35300 - Station Equipment	11/01/2016	1,273
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006319	000006319 T/SEP-Tx/ ASSOC W/S1194ARRE	T01502405SWP	SOUTH FAYETTEVILLE REPLACE FAILED METERS ON TRANSFORMERS	35300 - Station Equipment	07/01/2016	2,338
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006319	000006319 T/SEP-Tx/ ASSOC W/S1194ARRE	T01527075SWP	NORTH MAGAZINE PT CSIT12035635 - REPLACE FAILED PT WITH CCVT	35300 - Station Equipment	11/01/2016	2,576
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006319	000006319 T/SEP-Tx/ ASSOC W/S1194ARRE	T01532305SWP	SOUTH FAYETTEVILLE TRF P161 31 REPLACE FAILED 69 KV PT	35300 - Station Equipment	11/01/2016	2,380
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006319	000006319 T/SEP-Tx/ ASSOC W/S1194ARRE	T01541215SWP	EUREKA SPRINGS 161KV - REPLACE FAILED CCVT	35300 - Station Equipment	11/01/2016	4,190
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006319	000006319 T/SEP-Tx/ ASSOC W/S1194ARRE	T0173843SWP	REA - ELM SPRINGS DYESS 10457 REPLACE FAILED SF6 INTERRUPTERS	35300 - Station Equipment	07/01/2019	16,844
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006319	000006319 T/SEP-Tx/ ASSOC W/S1194ARRE	T01778605SWP	EUREKA SPRINGS 161KV STA REPLACE FAILED INTERCONNECT METERS	35300 - Station Equipment	06/01/2017	14,366
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006321	000006321 T/SEP-Tx/ ASSOC W/S1194LARE	426834135SWP	STANLEY NTEC REPLACE FAILED METER	35300 - Station Equipment	04/01/2018	922
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006321	000006321 T/SEP-Tx/ ASSOC W/S1194LARE	T01531585SWP	SOUTH SHREVEPORT CB 7260 REPL FAILED SURGE ARRESTERS	35300 - Station Equipment	09/01/2017	2,499
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006321	000006321 T/SEP-Tx/ ASSOC W/S1194LARE	T01551385SWP	LIEBERMAN - REPLACE FAILED 138 KV SWITCH 3015	35300 - Station Equipment	09/01/2016	12,211
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006322	000006322 T/SEP-Tx/ ASSOC W/S1194TXRE	42393085SWP	PITTSBURG CB 6210 - REPLACE FAILED SWITCH 6213	35300 - Station Equipment	08/01/2016	9,310
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006322	000006322 T/SEP-Tx/ ASSOC W/S1194TXRE	423937805SWP	DE KALB 12 5KV REPLACE FAILED METER	35300 - Station Equipment	04/01/2018	127
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006322	000006322 T/SEP-Tx/ ASSOC W/S1194TXRE	424660465SWP	NTEC DETC CENTER STATION REPLACE FAILED METER	35300 - Station Equipment	04/01/2018	3,176
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006322	000006322 T/SEP-Tx/ ASSOC W/S1194TXRE	425268205SWP	PERDUE SUBSTATION CHANGE OUT FAILED METER	35300 - Station Equipment	04/01/2018	745
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006322	000006322 T/SEP-Tx/ ASSOC W/S1194TXRE	425387175SWP	F BURGESS SUBSTATION CHANGE OUT FAILED METER	35300 - Station Equipment	07/01/2017	813
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006322	000006322 T/SEP-Tx/ ASSOC W/S1194TXRE	425743445SWP	WELSH HVDC REPLACE FAILED VALVE MODULE REACTORS	35300 - Station Equipment	11/01/2017	24,032
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006322	000006322 T/SEP-Tx/ ASSOC W/S1194TXRE	T01415395SWP	CARTHAGE POD - REPLACE FAILED CARRIER TUNER IN CCVT	35300 - Station Equipment	05/01/2016	3
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006322	000006322 T/SEP-Tx/ ASSOC W/S1194TXRE	T01504795SWP	ROCK HILL CB 1P70 - REPLACE (2) FAILED BUSHINGS	35300 - Station Equipment	12/01/2016	12,711
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006322	000006322 T/SEP-Tx/ ASSOC W/S1194TXRE	T01520885SWP	HUGHES SPRINGS CB 1200 CAPITAL PROJ-REPL FAILED SWITCH 1203	35300 - Station Equipment	11/01/2016	5,793
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006322	000006322 T/SEP-Tx/ ASSOC W/S1194TXRE	T01525055SWP	MOUNT PLEASANT CB 1860 REPL FAILED SWITCH 1863 CAP	35300 - Station Equipment	11/01/2016	7,716
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006322	000006322 T/SEP-Tx/ ASSOC W/S1194TXRE	T01533345SWP	NORTHWEST TEXARKANA CB 10690 REP FAILED SW 10693	35300 - Station Equipment	12/01/2016	31,082
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006322	000006322 T/SEP-Tx/ ASSOC W/S1194TXRE	T01544185SWP	MOUNT PLEASANT CB 1860 - REPLACE FAILED LIGHTNING ARRESTERS	35300 - Station Equipment	09/01/2016	8,696
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006322	000006322 T/SEP-Tx/ ASSOC W/S1194TXRE	T01642355SWP	IPC-JEFFERSON - REPLACE FAILED DLP RELAY WITH SEL 421 RELAY	35300 - Station Equipment	10/01/2017	5,323
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006322	000006322 T/SEP-Tx/ ASSOC W/S1194TXRE	T01644535SWP	CHILDRESS WEST (SEP) - C/O FAILED 69KV PTS	35300 - Station Equipment	06/01/2017	15,302
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006322	000006322 T/SEP-Tx/ ASSOC W/S1194TXRE	T01717595SWP	LAKE PAULINE C/O FAILED DISC SWITCHES	35300 - Station Equipment	09/01/2016	2,216
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006322	000006322 T/SEP-Tx/ ASSOC W/S1194TXRE	T01758275SWP	SCOTTSVILLE - REPLACE FAILED CARRIER WITH A TC10B SET	35300 - Station Equipment	11/01/2017	4,189
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006322	000006322 T/SEP-Tx/ ASSOC W/S1194TXRE	T01762775SWP	DIANA CB PIRKEY/SW SHREVEPORT - REPLACE FAILED CB11910	35300 - Station Equipment	07/01/2016	69,770
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006322	000006322 T/SEP-Tx/ ASSOC W/S1194TXRE	T01773985SWP	WELSH - REPLACE FAILED LIGHT FIXTURES	35300 - Station Equipment	12/01/2016	20,912
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006322	000006322 T/SEP-Tx/ ASSOC W/S1194TXRE	T01774245SWP	WHITNEY P141 66 NORTH - REPLACE (2) FAILED 24" FANS	35300 - Station Equipment	07/01/2016	454
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006322	000006322 T/SEP-Tx/ ASSOC W/S1194TXRE	T01774945SWP	DIANA P345 29 CENTER - REPLACE (3) FAILED 24" FANS	35300 - Station Equipment	08/01/2016	230
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006322	000006322 T/SEP-Tx/ ASSOC W/S1194TXRE	T01774955SWP	DIANA P345 25 SOUTH - REPLACE (2) FAILED 24" FANS	35300 - Station Equipment	08/01/2016	447
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006322	000006322 T/SEP-Tx/ ASSOC W/S1194TXRE	T01777365SWP	MARSHALL 138KV P142 64 NORTH - REPLACE (1) FAILED 24" FAN	35300 - Station Equipment	08/01/2016	354
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006322	000006322 T/SEP-Tx/ ASSOC W/S1194TXRE	T01778615SWP	SHAMROCK C/O FAILED CAPACITORS	35300 - Station Equipment	08/01/2016	5,018
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	000006322	000006322 T/SEP-Tx/ ASSOC W/S1194TXRE	T01783105SWP	KNOX LEE P141 54 - REPLACE (2) FAILED 24" FANS	35300 - Station Equipment	08/01/2016	638
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111ARSRE	B111ARSRE SHADOW for B194ARSRE	T01853205SWP	HUNTINGTON STA - FAILED 12KV INSULATORS & MET CURRENT XFMRs	35300 - Station Equipment	06/01/2017	5,414
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111ARSRE	B111ARSRE SHADOW for B194ARSRE	T01863595SWP	BONANZA STA REPLACE FAILED 34KV SWITCHES	35300 - Station Equipment	06/01/2017	1,340
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111ARSRE	B111ARSRE SHADOW for B194ARSRE	T01867635SWP	EAST ROGERS STA - REPLACE FAILING BUS PT	35300 - Station Equipment	05/01/2018	4,725
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111ARSRE	B111ARSRE SHADOW for B194ARSRE	T01871355SWP	NORTH HUNTINGTON STA REPLACE FAILED 69KV ARRESTERS	35300 - Station Equipment	11/01/2017	917
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111ARSRE	B111ARSRE SHADOW for B194ARSRE	T01874865SWP	FLINT CREEK SUB REPLACE FAILED 345KV ARRESTERS	35300 - Station Equipment	05/01/2018	13,393
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111ARSRE	B111ARSRE SHADOW for B194ARSRE	T01876925SWP	S FAYETTEVILLE CAP BANK REPLACE FAILED CAPACITORS & LIMITER	35300 - Station Equipment	05/01/2018	75
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111ARSRE	B111ARSRE SHADOW for B194ARSRE	T01879025SWP	EAST ROGERS CAP BANK REPLACE FAILED CAPACITORS & LIMITERS	35300 - Station Equipment	06/01/2017	6,308
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111ARSRE	B111ARSRE SHADOW for B194ARSRE	T01893615SWP	SILGAM SPRINGS 161KV STA REPLACE FAILED AC IN CONTROL HOUSE	35300 - Structures and Improvements	08/01/2017	476
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111ARSRE	B111ARSRE SHADOW for B194ARSRE	T01893615SWP	SILGAM SPRINGS 161KV STA REPLACE FAILED AC IN CONTROL HOUSE	35300 - Station Equipment	08/01/2017	23
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111ARSRE	B111ARSRE SHADOW for B194ARSRE	T01901415SWP	FLINT CREEK SUB TRF P345 50 EAST BUSHING FAILURE	35300 - Station Equipment	10/01/2018	143,135
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111ARSRE	B111ARSRE SHADOW for B194ARSRE	T01942185SWP	WEST BOONEVILLE STA REPLACE FAILED TRANSFER SWITCH	35300 - Station Equipment	05/01/2018	2,351
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111ARSRE	B111ARSRE SHADOW for B194ARSRE	T01976925SWP	DEQUEEN TRF P141 48 RPP39571 CAPITAL PROJECT/FAILED FANS	35300 - Station Equipment	04/01/2018	1,546
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111ARSRE	B111ARSRE SHADOW for B194ARSRE	T01996335SWP	CHAMBERS SPRING REPLACE FAILED 345KV CCVT	35300 - Station Equipment	09/01/2018	4,457
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111ARSRE	B111ARSRE SHADOW for B194ARSRE	T01997555SWP	MENA TRF P145 02 70705A CAPITAL PROJECT/FAILED FANS	35300 - Station Equipment	08/01/2018	1,691
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111ARSRE	B111ARSRE SHADOW for B194ARSRE	T02005365SWP	NORTH HUNTINGTON REPLACE FAILED 69KV ARRESTERS	35300 - Station Equipment	08/01/2018	231
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111ARSRE	B111ARSRE SHADOW for B194ARSRE	T02008585SWP	EAST ROGERS REPLACE FAILED 69KV CT	35300 - Station Equipment	01/01/2019	3,742
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111ARSRE	B111ARSRE SHADOW for B194ARSRE	T02046435SWP	NORTH HUNTINGTON REPLACE FAILED 161KV CCVT	35300 - Station Equipment	08/01/2018	3,129
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111ARSRE	B111ARSRE SHADOW for B194ARSRE	T02158695SWP	NASHVILLE 69KV CB CB-3050 REPL FAILED CB AND REPL LINE PT	35300 - Station Equipment	12/01/2019	20,256
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111ARSRE	B111ARSRE SHADOW for B194ARSRE	T02022175SWP	NORTH MAGAZINE BATTERY BANK - REPLACE FAILING BANK	35300 - Station Equipment	12/01/2019	4,617
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111ARSRE	B111ARSRE SHADOW for B194ARSRE	T020226595SWP	SOUTH NASHVILLE CB-REPL FAILED AIR COMPRESSOR	35300 - Station Equipment	09/01/2020	2,390
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111LASRE	B111LASRE T/SW/Shadow for B194LASRE	T01799345SWP	SOUTHWEST SHREVEPORT REPL FAILED PAD MOUNT XFMR	35300 - Station Equipment	04/01/2017	4,315
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111LASRE	B111LASRE T/SW/Shadow for B194LASRE	T01898285SWP	ARSENAL HILL STA CAPITAL PROJECT/P7184&P7202 FAILED FANS	35300 - Station Equipment	09/01/2017	566
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111LASRE	B111LASRE T/SW/Shadow for B194LASRE	T01898415SWP	BROADMOOR STA CAPITAL PROJECT/FAILED RMC 30	35300 - Station Equipment	09/01/2017	412
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111LASRE	B111LASRE T/SW/Shadow for B194LASRE	T01898605SWP	LOGANSPOUR STA CAPITAL PROJECT/CHANGED OUT FAILED FANS	35300 - Station Equipment	12/01/2017	4,116
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111LASRE	B111LASRE T/SW/Shadow for B194LASRE	T01943095SWP	LUCAS CCVT ELLERBE MID 1646701007 CAPITAL PROJECT/FAILED69KV	35300 - Station Equipment	07/01/2018	3,049
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111LASRE	B111LASRE T/SW/Shadow for B194LASRE	T02002875SWP	LIEBERMAN STA CAPITAL PROJECT/FAILED 138KV SWITCHES	35300 - Station Equipment	04/01/2018	26,585
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111LASRE	B111LASRE T/SW/Shadow for B194LASRE	T02066195SWP	NORTH BENTON STA CAPITAL PROJECT/FAILED FANS	35300 - Station Equipment	07/01/2019	9,102
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111LASRE	B111LASRE T/SW/Shadow for B194LASRE	T02068275SWP	ARSENAL HILL CAPB CAP BANK 13730 CAPBANK13730/FAILED CANS	35300 - Station Equipment	11/01/2018	1,439
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111LASRE	B111LASRE T/SW/Shadow for B194LASRE	T02068635SWP	SUPERIOR (SW) CB CB-9060 9739/FAILED BREAKER 9060	35300 - Station Equipment	07/01/2019	50,897
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111TXLRE	B111TXLRE T/SW/Shadow for B194TXLRE	T010358065SWP	KNOX LEE - PIRKEY A-1 INSULATOR FAILURE	35600 - Overhead Conductors, Device	09/01/2019	13,187
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111TXSRE	B111TXSRE T/SW/Shadow for B194TXSRE	42921285SWP	WELSH HVDC STATION REPLACE FAILED AUTO TRANSFORMER TWO1 L3	35300 - Station Equipment	05/01/2019	43,799
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111TXSRE	B111TXSRE T/SW/Shadow for B194TXSRE	T01834305SWP	WELSH STA REPL FAILED SWITCH 11683	35300 - Station Equipment	04/01/2018	33,067
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111TXSRE	B111TXSRE T/SW/Shadow for B194TXSRE	T01872125SWP	OVERTON STA REPLACE FAILED CCVT & CARRIER TUNER PK	35300 - Station Equipment	10/01/2017	9,835
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111TXSRE	B111TXSRE T/SW/Shadow for B194TXSRE	T01880355SWP	WELSH HVDC CONVERTER CB FILTER CB BM03 REP FAILED CTVT	35300 - Station Equipment	06/01/2017	2,636
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111TXSRE	B111TXSRE T/SW/Shadow for B194TXSRE	T01880675SWP	PIRKEY STA PIRKEY - REPLACE FAILED 3 TON AC UNIT	35300 - Station Equipment	04/01/2017	2,736
TBLANKTWSW	TBLANKTWSW Trans Capital Blanket - SWEPco	B111TXSRE	B111TXSRE T/SW/Shadow for B194TXSRE	T01884435SWP	HEDLEY C/O FAILED MOS 1663 1662	35300 - Station Equipment	03/01/2018	7,584

SWEPCO TRANSMISSION
Blanket/Program Projects

CPP_ID	CPP_DESC	PROJECT_ID	PROJ_DESC	WO_ID	WO_DESC	UTILITY_ACCOUNT	IN-SERVICE_DATE	ACTIVITY_COST
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B111TXSRE	B111TXSRE T/S/Shadow for B194TXSRE	T018920SWP	BUFORD SURVEY DSC MOABS 7625 REPLACE FAILED SWITCH	35300 - Station Equipment	09/01/2018	61,786
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B111TXSRE	B111TXSRE T/S/Shadow for B194TXSRE	T0189284SWP	PERDUE CAPB 86 4 MVAR CAP BANK 138KV REPLACE FAILED CAPACITO	35300 - Station Equipment	06/01/2017	4,040
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B111TXSRE	B111TXSRE T/S/Shadow for B194TXSRE	T0190186SWP	DIANA STA CAPITAL REPL FAILED SWITCH 1309H	35300 - Station Equipment	01/01/2018	18,591
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B111TXSRE	B111TXSRE T/S/Shadow for B194TXSRE	T0193246SWP	DIANA STA REPL FAILED SWITCH 1310S	35300 - Station Equipment	11/01/2017	15,777
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B111TXSRE	B111TXSRE T/S/Shadow for B194TXSRE	T0195570SWP	DIANA STA DIANA REPLACE FAILED CVT'S	35300 - Station Equipment	01/01/2018	10,481
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B111TXSRE	B111TXSRE T/S/Shadow for B194TXSRE	T0195649SWP	SHAMROCK C/O FAILED CAP BANK CS 6730	35300 - Station Equipment	03/01/2018	56,875
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B111TXSRE	B111TXSRE T/S/Shadow for B194TXSRE	T0195885SWP	EASTON SUBSTATION- REPLACE FAILED ION METER	35300 - Station Equipment	01/01/2020	905
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B111TXSRE	B111TXSRE T/S/Shadow for B194TXSRE	T0198923SWP	JERICHO C/O FAILED A/C UNIT	35200 - Structures and Improvements	03/01/2018	290
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B111TXSRE	B111TXSRE T/S/Shadow for B194TXSRE	T0198923SWP	JERICHO C/O FAILED A/C UNIT	35300 - Station Equipment	03/01/2018	372
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B111TXSRE	B111TXSRE T/S/Shadow for B194TXSRE	T0198953SWP	LYDIA MET LYDIA 345 - VALLIANT 345 REPLACETWO FAILED METERS	35300 - Station Equipment	10/01/2018	1,517
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B111TXSRE	B111TXSRE T/S/Shadow for B194TXSRE	T0204172SWP	CAMP COUNTY POD CAPITAL PROJECT/REPLACE FAILED HVAC	35300 - Station Equipment	12/01/2019	1,862
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B111TXSRE	B111TXSRE T/S/Shadow for B194TXSRE	T0204310SWP	SHAMROCK C/O FAILED RELAY 38062R2	35300 - Station Equipment	10/01/2018	2,686
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B111TXSRE	B111TXSRE T/S/Shadow for B194TXSRE	T0204310SWP	SHAMROCK C/O FAILED RELAY 38062R2	35316 - Station Equipment-SmartGrid	10/01/2018	480
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B111TXSRE	B111TXSRE T/S/Shadow for B194TXSRE	T0204533SWP	LEBROCK MET STG 001 BACKUP 907A716_ REPLACE FAILED METER	35300 - Station Equipment	03/01/2020	1,288
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B111TXSRE	B111TXSRE T/S/Shadow for B194TXSRE	T0204635SWP	JERICHO C/O FAILED BATTERY ONLY	35300 - Station Equipment	09/01/2018	3,580
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B111TXSRE	B111TXSRE T/S/Shadow for B194TXSRE	T0206525SWP	WOODLAWN (SW) CB CB-2090 REPLACE FAILED COMPRESSOR AND MOTOR	35300 - Station Equipment	12/01/2019	629
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B111TXSRE	B111TXSRE T/S/Shadow for B194TXSRE	T0206888SWP	MARSHALL 69KV CB ROCKHILL 1340 REPLACE FAILED CB	35300 - Station Equipment	12/01/2018	30,636
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B111TXSRE	B111TXSRE T/S/Shadow for B194TXSRE	T0210070SWP	TRO80022772_PIRKEY STA REPL 3 FAILED LIGHTNING ARRESTERS	35300 - Station Equipment	01/01/2020	8,813
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B111TXSRE	B111TXSRE T/S/Shadow for B194TXSRE	T0215642SWP	ROCK HILL CB CB-10120 REPLACE FAILED COMPRESSOR	35300 - Station Equipment	11/01/2019	2,936
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B111TXSRE	B111TXSRE T/S/Shadow for B194TXSRE	TS0222402SWP	CHILDRESS WEST C/O FAILED CB 6480	35300 - Station Equipment	12/01/2019	26,962
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194ARSRE	B194ARSRE T/S/Non-Specific Work-Station	T0185320	HUNTINGTON STA - FAILED 12KV INSULATORS & MET CURRENT XFRMRS	35300 - Station Equipment	06/01/2017	10,870
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194ARSRE	B194ARSRE T/S/Non-Specific Work-Station	T0186359	BONANZA STA REPLACE FAILED 34KV SWITCHES	35300 - Station Equipment	06/01/2017	2,950
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194ARSRE	B194ARSRE T/S/Non-Specific Work-Station	T0186763	EAST ROGERS STA - REPLACE FAILING BUS PT	35300 - Station Equipment	06/01/2018	9,282
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194ARSRE	B194ARSRE T/S/Non-Specific Work-Station	T0187135	NORTH HUNTINGTON STA REPLACE FAILED 69KV ARRESTERS	35300 - Station Equipment	11/01/2017	1,784
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194ARSRE	B194ARSRE T/S/Non-Specific Work-Station	T0187486	FLINT CREEK SUB REPLACE FAILED 345KV ARRESTERS	35300 - Station Equipment	06/01/2018	26,365
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194ARSRE	B194ARSRE T/S/Non-Specific Work-Station	T0187692	5 FAYETTEVILLE CAP BANK REPLACE FAILED CAPACITORS & LIMITER	35300 - Station Equipment	06/01/2018	149
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194ARSRE	B194ARSRE T/S/Non-Specific Work-Station	T0187902	EAST ROGERS CAP BANK REPLACE FAILED CAPACITORS & LIMITERS	35300 - Station Equipment	06/01/2017	12,288
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194ARSRE	B194ARSRE T/S/Non-Specific Work-Station	T0189361	SLOAM SPRINGS 161KV STA REPLACE FAILED AC IN CONTROL HOUSE	35200 - Structures and Improvements	08/01/2017	949
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194ARSRE	B194ARSRE T/S/Non-Specific Work-Station	T0189361	SLOAM SPRINGS 161KV STA REPLACE FAILED AC IN CONTROL HOUSE	35300 - Station Equipment	08/01/2017	45
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194ARSRE	B194ARSRE T/S/Non-Specific Work-Station	T0190141	FLINT CREEK SUB TRF P345 50 EAST BUSHING FAILURE	35300 - Station Equipment	10/01/2018	284,512
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194ARSRE	B194ARSRE T/S/Non-Specific Work-Station	T0194218	WEST BOONEVILLE STA REPLACE FAILED TRANSFER SWITCH	35300 - Station Equipment	06/01/2018	4,625
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194ARSRE	B194ARSRE T/S/Non-Specific Work-Station	T0197692	DEQUEEN TRF P141 8R RPP39571 CAPITAL PROJECT/FAILED FANS	35300 - Station Equipment	04/01/2018	3,048
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194ARSRE	B194ARSRE T/S/Non-Specific Work-Station	T0199633	CHAMBERS SPRING REPLACE FAILED 345KV CCVT	35300 - Station Equipment	09/01/2018	8,783
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194ARSRE	B194ARSRE T/S/Non-Specific Work-Station	T0199755	MENA TRF P145 02 70705A CAPITAL PROJECT/FAILED FANS	35300 - Station Equipment	08/01/2018	3,350
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194ARSRE	B194ARSRE T/S/Non-Specific Work-Station	T0200536	NORTH HUNTINGTON REPLACE FAILED 69KV ARRESTERS	35300 - Station Equipment	08/01/2018	493
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194ARSRE	B194ARSRE T/S/Non-Specific Work-Station	T0200858	EAST ROGERS REPLACE FAILED 69KV CT	35300 - Station Equipment	01/01/2019	7,494
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194ARSRE	B194ARSRE T/S/Non-Specific Work-Station	T0204643	NORTH HUNTINGTON REPLACE FAILED 161KV CCVT	35300 - Station Equipment	08/01/2018	6,210
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194ARSRE	B194ARSRE T/S/Non-Specific Work-Station	T0215869	NASHVILLE 69KV CB CB-3050 REPL FAILED CB AND REPL LINE PT	35300 - Station Equipment	12/01/2019	41,247
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194ARSRE	B194ARSRE T/S/Non-Specific Work-Station	TS0222179	NORTH MAGAZINE BATTERY BANK - REPLACE FAILING BANK	35300 - Station Equipment	12/01/2019	9,199
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194ARSRE	B194ARSRE T/S/Non-Specific Work-Station	TS0222659	SOUTH NASHVILLE CB-REPL FAILED AIR COMPRESSOR	35300 - Station Equipment	03/01/2020	4,838
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194LASRE	B194LASRE T/S/NonSpecificWorkStation-LA	T0179934	SOUTHWEST SHREVEPORT REPL FAILED PAD MOUNT XFMR	35300 - Station Equipment	04/01/2017	8,929
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194LASRE	B194LASRE T/S/NonSpecificWorkStation-LA	T0189828	ARSENAL HILL STA CAPITAL PROJECT/P7184&P7202 FAILED FANS	35300 - Station Equipment	09/01/2017	1,174
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194LASRE	B194LASRE T/S/NonSpecificWorkStation-LA	T0189841	BROADMOOR STA CAPITAL PROJECT/FAILED RMC 30	35300 - Station Equipment	09/01/2017	812
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194LASRE	B194LASRE T/S/NonSpecificWorkStation-LA	T0189860	LOGANSPOUT STA CAPITAL PROJECT/CHANGED OUT FAILED FANS	35300 - Station Equipment	12/01/2017	8,205
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194LASRE	B194LASRE T/S/NonSpecificWorkStation-LA	T0194309	LUCAS CCVT ELLERBE MID 1646701007 CAPITAL PROJECT/FAILED69KV	35300 - Station Equipment	07/01/2018	6,029
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194LASRE	B194LASRE T/S/NonSpecificWorkStation-LA	T0200287	LIEBERMAN STA CAPITAL PROJECT/FAILED 138KV SWITCHES	35300 - Station Equipment	04/01/2019	52,994
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194LASRE	B194LASRE T/S/NonSpecificWorkStation-LA	T0206619	NORTH BENTON STA CAPITAL PROJECT/FAILED FANS	35300 - Station Equipment	07/01/2019	18,161
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194LASRE	B194LASRE T/S/NonSpecificWorkStation-LA	T0206827	ARSENAL HILL CAPB CAP BANK 13730 CAPBANK13730/FAILED CANS	35300 - Station Equipment	11/01/2018	2,869
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194LASRE	B194LASRE T/S/NonSpecificWorkStation-LA	T0206863	SUPERIOR (SW) CB CB-9060 9739/FAILED BREAKER 9060	35300 - Station Equipment	07/01/2019	101,965
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194TXLRE	B194TXLRE T/S/Non-Specific Work - Line	T1035806	KNOX LEE - PIRKEY A-1 INSULATOR FAILURE	35600 - Overhead Conductors, Device	09/01/2019	27,104
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194TXSRE	B194TXSRE T/S/Non-Specific Work Station	42921285	WELSH HVDC STATION REPLACE FAILED AUTO TRANSFORMER TWO1 L3	35300 - Station Equipment	05/01/2019	89,845
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194TXSRE	B194TXSRE T/S/Non-Specific Work Station	T0183430	WELSH STA REPL FAILED SWITCH 11683	35300 - Station Equipment	04/01/2018	65,749
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194TXSRE	B194TXSRE T/S/Non-Specific Work Station	T0187212	OVERTON STA REPLACE FAILED CCVT & CARRIER TUNER PK	35300 - Station Equipment	10/01/2017	19,322
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194TXSRE	B194TXSRE T/S/Non-Specific Work Station	T0188035	WELSH HVDC CONVERTER CB FILTER CB BM03 REP FAILED CVT	35300 - Station Equipment	06/01/2017	5,232
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194TXSRE	B194TXSRE T/S/Non-Specific Work Station	T0188067	PIRKEY STA PIRKEY - REPLACE FAILED 3 TON AC UNIT	35300 - Station Equipment	04/01/2017	5,325
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194TXSRE	B194TXSRE T/S/Non-Specific Work Station	T0188443	HEDLEY C/O FAILED MOS 1663 1662	35300 - Station Equipment	09/01/2018	15,451
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194TXSRE	B194TXSRE T/S/Non-Specific Work Station	T0188920	BUFORD SURVEY DSC MOABS 7625 REPLACE FAILED SWITCH	35300 - Station Equipment	09/01/2018	122,783
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194TXSRE	B194TXSRE T/S/Non-Specific Work Station	T0189284	PERDUE CAPB 86 4 MVAR CAP BANK 138KV REPLACE FAILED CAPACITO	35300 - Station Equipment	06/01/2017	7,990
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194TXSRE	B194TXSRE T/S/Non-Specific Work Station	T0190186	DIANA STA CAPITAL REPL FAILED SWITCH 1309H	35300 - Station Equipment	01/01/2018	37,059
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194TXSRE	B194TXSRE T/S/Non-Specific Work Station	T0193246	DIANA STA REPL FAILED SWITCH 1310S	35300 - Station Equipment	11/01/2017	31,115
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194TXSRE	B194TXSRE T/S/Non-Specific Work Station	T0195570	DIANA STA DIANA REPLACE FAILED CVT'S	35300 - Station Equipment	01/01/2018	20,730
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194TXSRE	B194TXSRE T/S/Non-Specific Work Station	T0195649	SHAMROCK C/O FAILED CAP BANK CS 6730	35300 - Station Equipment	03/01/2018	112,704
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194TXSRE	B194TXSRE T/S/Non-Specific Work Station	T0195885	EASTON SUBSTATION- REPLACE FAILED ION METER	35300 - Station Equipment	01/01/2020	1,810
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194TXSRE	B194TXSRE T/S/Non-Specific Work Station	T0198923	JERICHO C/O FAILED A/C UNIT	35200 - Structures and Improvements	03/01/2018	579
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194TXSRE	B194TXSRE T/S/Non-Specific Work Station	T0198923	JERICHO C/O FAILED A/C UNIT	35300 - Station Equipment	03/01/2018	744
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194TXSRE	B194TXSRE T/S/Non-Specific Work Station	T0198953	LYDIA MET LYDIA 345 - VALLIANT 345 REPLACETWO FAILED METERS	35300 - Station Equipment	10/01/2018	2,952
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194TXSRE	B194TXSRE T/S/Non-Specific Work Station	T0204172	CAMP COUNTY POD CAPITAL PROJECT/REPLACE FAILED HVAC	35300 - Station Equipment	12/01/2019	3,623
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194TXSRE	B194TXSRE T/S/Non-Specific Work Station	T0204310	SHAMROCK C/O FAILED RELAY 38062R2	35300 - Station Equipment	10/01/2018	5,306
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194TXSRE	B194TXSRE T/S/Non-Specific Work Station	T0204310	SHAMROCK C/O FAILED RELAY 38062R2	35316 - Station Equipment-SmartGrid	10/01/2018	949
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194TXSRE	B194TXSRE T/S/Non-Specific Work Station	T0204533	LEBROCK MET STG 001 BACKUP 907A716_ REPLACE FAILED METER	35300 - Station Equipment	03/01/2020	2,606
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWEPCo	B194TXSRE	B194TXSRE T/S/Non-Specific Work Station	T0204635	JERICHO C/O FAILED BATTERY ONLY	35300 - Station Equipment	09/01/2018	7,240

SWPECO TRANSMISSION
Blanket/Program Projects

CPP_ID	CPP_DESC	PROJECT_ID	PROJ_DESC	WO_ID	WO_DESC	UTILITY_ACCOUNT	IN-SERVICE_DATE	ACTIVITY_COST
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	B194TXSRE	B194TXSRE T/SW/Non-Specific Work Station	T0206525	WOODLAWN (SW) CB CB-2090 REPLACE FAILED COMPRESSOR AND MOTOR	35300 - Station Equipment	12/01/2019	1,283
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	B194TXSRE	B194TXSRE T/SW/Non-Specific Work Station	T0206888	MARSHALL 69KV CB ROCKHILL 1340 REPLACE FAILED CB	35300 - Station Equipment	12/01/2018	61,335
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	B194TXSRE	B194TXSRE T/SW/Non-Specific Work Station	T0210070	TROB0002772_PIRKEY STA REPL 3 FAILED LIGHTNING ARRESTERS	35300 - Station Equipment	01/01/2020	17,394
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	B194TXSRE	B194TXSRE T/SW/Non-Specific Work Station	T0215642	ROCK HILL CB CB-10120 REPLACE FAILED COMPRESSOR	35300 - Station Equipment	11/01/2019	5,901
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	B194TXSRE	B194TXSRE T/SW/Non-Specific Work Station	TS0222402	CHILDRESS WEST C/O FAILED CB 6480	35300 - Station Equipment	12/01/2019	54,300
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SETXA1501	SETXA1501 T/SEP/TX/Assoc w/SETXS 00/00/0	42664029SWP	NW HENDERSON REPLACE FAILED CB 10930	35300 - Station Equipment	06/01/2017	15,525
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SETXS1501	SETXS1501 T/SEP/TX/Maj Min Storm 00/00/0	42664029	NW HENDERSON REPLACE FAILED CB 10930	35300 - Station Equipment	06/01/2017	30,218
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI111ARLR	SI111ARLR TB/SEP-Tx ASSOC W/SI194ARLR	42579933SWP	DIERKS - MENA- REPLACE FAILED CROSS ARM	35500 - Poles and Fixtures	08/01/2016	1,419
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194ARLR	SI194ARLR TB/SI/SEP/AR - LINE REHAB	42579933	DIERKS - MENA- REPLACE FAILED CROSS ARM	35500 - Poles and Fixtures	08/01/2016	2,859
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194ARRE	SI194ARRE TB/SEP-NT ARK SYS REHAB	T0084007	WEST BOONEVILLE CB 9380 - REPLACE 3 FAILING 69KV SURGE ARRES	35300 - Station Equipment	11/01/2008	(127)
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194ARRE	SI194ARRE TB/SEP-NT ARK SYS REHAB	T0149602	PRAIRIE GROVE CB GREENLAND 3820 REPLACE FAILED CABLE	35300 - Station Equipment	08/01/2016	10,527
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194ARRE	SI194ARRE TB/SEP-NT ARK SYS REHAB	T0149773	MENA TRF P145 2 REPLACE FAILED FANS	35300 - Station Equipment	11/01/2016	2,652
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194ARRE	SI194ARRE TB/SEP-NT ARK SYS REHAB	T0150240	SOUTH FAYETTEVILLE REPLACE FAILED METERS ON TRANSFORMERS	35300 - Station Equipment	07/01/2016	4,657
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194ARRE	SI194ARRE TB/SEP-NT ARK SYS REHAB	T0152707	NORTH MAGAZINE PT CSIT12035635 - REPLACE FAILED PT WITH CCVT	35300 - Station Equipment	11/01/2016	5,149
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194ARRE	SI194ARRE TB/SEP-NT ARK SYS REHAB	T0153230	SOUTH FAYETTEVILLE TRF P161 31 REPLACE FAILED 69 KV PT	35300 - Station Equipment	11/01/2016	4,757
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194ARRE	SI194ARRE TB/SEP-NT ARK SYS REHAB	T0154121	EUREKA SPRINGS 161KV - REPLACE FAILED CCVT	35300 - Station Equipment	11/01/2016	8,458
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194ARRE	SI194ARRE TB/SEP-NT ARK SYS REHAB	T0177384	REA - ELM SPRINGS DYESS 10457 REPLACE FAILED SF6 INTERRUPTERS	35300 - Station Equipment	07/01/2019	33,232
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194ARRE	SI194ARRE TB/SEP-NT ARK SYS REHAB	T0177860	EUREKA SPRINGS 161KV STA REPLACE FAILED INTERCONNECT METERS	35300 - Station Equipment	06/01/2017	28,355
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194LARE	SI194LARE TB/SI/SEP-NT LA SYS REHAB	42683413	STANLEY NTEC. REPLACE FAILED METER	35300 - Station Equipment	04/01/2018	1,813
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194LARE	SI194LARE TB/SI/SEP-NT LA SYS REHAB	T0153158	SOUTH SHREVEPORT CB 7260 REPL FAILED SURGE ARRESTERS	35300 - Station Equipment	09/01/2017	4,976
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194LARE	SI194LARE TB/SI/SEP-NT LA SYS REHAB	T0155138	LIEBERMAN - REPLACE FAILED 138 KV SWITCH 3015	35300 - Station Equipment	09/01/2016	23,858
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194TXRE	SI194TXRE TB/SI/SEP-Tx TEXAS SYS REHAB	42383085	PITTSBURG CB 6210 - REPLACE FAILED SWITCH 6213	35300 - Station Equipment	08/01/2016	19,157
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194TXRE	SI194TXRE TB/SI/SEP-Tx TEXAS SYS REHAB	42393780	DE KALB 12 5KV REPLACE FAILED METER	35300 - Station Equipment	04/01/2018	2,419
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194TXRE	SI194TXRE TB/SI/SEP-Tx TEXAS SYS REHAB	42466046	NTEC DETC CENTER STATION REPLACE FAILED METER	35300 - Station Equipment	04/01/2018	6,247
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194TXRE	SI194TXRE TB/SI/SEP-Tx TEXAS SYS REHAB	42526820	PERDUE SUBSTATION CHANGE OUT FAILED METER	35300 - Station Equipment	04/01/2018	1,458
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194TXRE	SI194TXRE TB/SI/SEP-Tx TEXAS SYS REHAB	42538717	E BURGESS SUBSTATION: CHANGE OUT FAILED METER	35300 - Station Equipment	07/01/2017	1,631
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194TXRE	SI194TXRE TB/SI/SEP-Tx TEXAS SYS REHAB	42574344	WELSH HVDC REPLACE FAILED VALVE MODULE REACTORS	35300 - Station Equipment	11/01/2017	46,775
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194TXRE	SI194TXRE TB/SI/SEP-Tx TEXAS SYS REHAB	T0141539	CARTHAGE POD - REPLACE FAILED CARRIER TUNER IN CCVT	35300 - Station Equipment	05/01/2016	5
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194TXRE	SI194TXRE TB/SI/SEP-Tx TEXAS SYS REHAB	T0150479	ROCK HILL CB 1P70 - REPLACE (2) FAILED BUSHINGS	35300 - Station Equipment	12/01/2016	25,178
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194TXRE	SI194TXRE TB/SI/SEP-Tx TEXAS SYS REHAB	T0152088	HUGHES SPRINGS CB 1200 CAPITAL PROJ-REPL FAILED SWITCH 1203	35300 - Station Equipment	11/01/2016	12,180
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194TXRE	SI194TXRE TB/SI/SEP-Tx TEXAS SYS REHAB	T0152505	MOUNT PLEASANT CB 1860 REPL FAILED SWITCH 1863 CAP	35300 - Station Equipment	11/01/2016	17,559
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194TXRE	SI194TXRE TB/SI/SEP-Tx TEXAS SYS REHAB	T0153334	NORTHWEST TEXARKANA CB 10690 REP FAILED SW 10693	35300 - Station Equipment	12/01/2016	60,860
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194TXRE	SI194TXRE TB/SI/SEP-Tx TEXAS SYS REHAB	T0154418	MOUNT PLEASANT CB 1860 - REPLACE FAILED LIGHTNING ARRESTERS	35300 - Station Equipment	09/01/2016	17,566
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194TXRE	SI194TXRE TB/SI/SEP-Tx TEXAS SYS REHAB	T0164235	IPC-JEFFERSON - REPLACE FAILED DLP RELAY WITH SEL 421 RELAY	35300 - Station Equipment	10/01/2017	10,694
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194TXRE	SI194TXRE TB/SI/SEP-Tx TEXAS SYS REHAB	T0164453	CHILDRESS WEST (SEP) - C/O FAILED 69KV PTS	35300 - Station Equipment	06/01/2017	30,532
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194TXRE	SI194TXRE TB/SI/SEP-Tx TEXAS SYS REHAB	T0171759	LAKE PAULINE C/O FAILED DISC SWITCHES	35300 - Station Equipment	09/01/2016	4,627
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194TXRE	SI194TXRE TB/SI/SEP-Tx TEXAS SYS REHAB	T0175827	SCOTTSVILLE - REPLACE FAILED CARRIER WITH A TC108 SET	35300 - Station Equipment	11/01/2017	8,265
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194TXRE	SI194TXRE TB/SI/SEP-Tx TEXAS SYS REHAB	T0176277	DIANA CB PIRKEY/SW SHREVEPORT - REPLACE FAILED CB11910	35300 - Station Equipment	07/01/2016	140,018
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194TXRE	SI194TXRE TB/SI/SEP-Tx TEXAS SYS REHAB	T0177398	WELSH - REPLACE FAILED LIGHT FIXTURES	35300 - Station Equipment	12/01/2016	41,317
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194TXRE	SI194TXRE TB/SI/SEP-Tx TEXAS SYS REHAB	T0177424	WHITNEY P141 66 NORTH - REPLACE (2) FAILED 24" FANS	35300 - Station Equipment	07/01/2016	887
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194TXRE	SI194TXRE TB/SI/SEP-Tx TEXAS SYS REHAB	T0177494	DIANA P345 29 CENTER - REPLACE (3) FAILED 24" FANS	35300 - Station Equipment	08/01/2016	450
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194TXRE	SI194TXRE TB/SI/SEP-Tx TEXAS SYS REHAB	T0177495	DIANA P345 25 SOUTH - REPLACE (2) FAILED 24" FANS	35300 - Station Equipment	08/01/2016	874
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194TXRE	SI194TXRE TB/SI/SEP-Tx TEXAS SYS REHAB	T0177736	MARSHALL 138KV P142 64 NORTH - REPLACE (1) FAILED 24" FAN	35300 - Station Equipment	08/01/2016	701
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194TXRE	SI194TXRE TB/SI/SEP-Tx TEXAS SYS REHAB	T0177861	SHAMROCK C/O FAILED CAPACITORS	35300 - Station Equipment	08/01/2016	9,969
TBLANKTSW	TBLANKTSW Trans Capital Blanket - SWPECo	SI194TXRE	SI194TXRE TB/SI/SEP-Tx TEXAS SYS REHAB	T0178310	KNOX LEE P141 54 - REPLACE (2) FAILED 24" FANS	35300 - Station Equipment	08/01/2016	1,252
	Grand Total							2,982,924

SWEPCO Transmission

SOAH Docket No. 473-21-0538

PUC Docket No. 51415

Staff's 10th RFI, Q. # Staff 10-6

Attachment 1

Page 1 of 1

SWEPCO Texas Rate Case Information			
Area	Work Order	Description	Amount
T-Line - Response			
	TL0036348001	Knox Lee-Pirkey - Emergency Aerial Patrol	\$ 2,074.58
	TL00036356022	Jefferson North Marshall - Conductor down	\$ 5,328.75
			\$ 7,403.33
P&C - Mitigation			
	T10139501	SWEPCO CT Verification - Trans. OM	\$ 8,053.05
	T10139506	SWPCO (AR/LA) CT Verification - Distr. OM	\$ 1,763.77
	T10139730	SWEPCO TX CT Verification - Dist. OM	\$ 5,039.04
			\$ 14,855.86
Station/P&C - Response			
	4044033901	TS-T-194 (1252) P&C DIRECT LABOR	\$ 1,004.13
	4203016001	SWEPCO TRANS INCIDENTAL STATION MAINT LESS THAN 4 HRS	\$ 230.42
	4203060301	SWEPCO TRANSMISSION TRANSFORMER MAINTENANCE	\$ 1,208.55
	4203060401	SWEPCO TRANSMISSION BREAKER MAINTENANCE	\$ 162.04
	4203060601	SWEPCO TRANSMISSION STATION SWITCHING	\$ 7,180.02
	4203061401	SWEPCO DISTRIBUTION STATION SWITCHING	\$ 429.26
	4203964801	OPERATION ANALYSIS	\$ 1,508.59
	4203964805	RELAY	\$ 326.39
			\$ 12,049.40
		Grand Total	\$ 34,308.59

SWEPCo Transmission

Line Name	Work Order	ABMS Project	Account Number	Sum of Total Cost
DIANA - PLILER ROAD	G0000194	000012900	5710000	530,162.24
KNOX LEE - PIRKEY	G0000194	000012900	5710000	10,281.39
PERDUE - DIANA	G0000194	000012900	5710000	202,829.29
PIRKEY - WHITNEY	G0000194	000012900	5710000	351,831.31
Grand Total				1,095,104.23