


Control Number: 51856

Item Number: 18

Addendum StartPage: 0





TEXAS COMMISSION ON ENVIRONMENTAL QUALITY

Protecting Texas by Reducing and Preventing Pollution

April 17, 2012

Mr. James Maclin Mid America Communities 6584 Poplar Avenue Suite 300 Memphis, TX 38138

Re: Request for Approval to Change Billing Method for the following:

- 1. Venue at Stonebridge Ranch, Registration No. S5211: CN601549181, RN104965876
- 2. Cascade at Fall Creek, Registration No. S5685: CN601702715, RN105692768
- 3. Legacy Pines, Registration No. S4654; CN601702715, RN103997581
- 4. La Valencia at Starwood, Not Registered
- 5. Alamo Ranch, Not Registered

Dear Mr. Maclin & Mr. Whitmire:

The requests you have submitted on behalf of **Venue at Stonebridge Ranch**, **Cascade at Fall Creek**, **Legacy Pines**, **La Valencia at Starwood**, and **Alamo Ranch** apartments to change from submetered to allocated billing are approved. These approvals are based on the facts stated in your letters of **March 16**, **2012**. Thank you for completing the TCEQ-10363 and TCEQ-10400 forms. A copy of this approval letter will remain on file for each request you submitted for the above apartments. For a description and explanation of submetered and allocated utility billing, please visit the following website:

http://www.tceq.texas.gov/utilities/submeter.html

If you have any questions, please contact Debbie Reyes Tamayo at 512/239-4683. Via e-mail to debbie.reyes-tamayo@tceq.texas.qov.

Sincerely,

Tammy Benter, Manager Utilities & Districts Section Water Supply Division

anny Benter

TB/DRT/mmg



TCEQ Utilities & Districts Section, MC-153 PO Box 13087 Austin, TX 78711-3087

MAA 6584 Poplar Ave Memphis, TN 38138

RE: La Valencia at Starwood Apartments 6805 Lebanon Road, Frisco, TX 75034

Dear Sir or Madam,

The purpose of this letter is to request permission for a change in billing method for Alamo Ranch Apartments from sub-metered billing to RUBs allocation. Included with this letter are the following:

- TCEQ Core Data Form
- TCEQ Registration Form
- Repair proposal to repair the known meter issues at the property
- A meter repair report where some meter work has already been performed.
- A comparison between the average submetered charges and the estimated RUBs charges.

Brandon Whitmire 901-248-4162 brandon.whitmire@maac.com

Thanks you for your time and attention to this matter.

Respectfully,

SVP, Director of Corporate Services

MAA

March 16, 2012