

Control Number: 51856



Item Number: 361

5AF 0256 (D

Budov Garcia. Chairman Larry K Soward Commissioner Bryan W. Shaw, Ph.D., Commissioner Mark R. Vicken, P.G., Executive Director



TEXAS COMMISSION ON ENVIRONMENTAL

Protecting Texas by Reducing and Preventing Pollution no

March 24, 2009

Ms. Julie Carswell Director Portfolio Management ista North America icarswell@ista-na.com 3655 North Point Parkway, Suite 250 Alpharetta, Georgia 30005-2027

Re: Request for approval to change billing method

Limestone Ranch, Registration No. S0256

CN: 600676548 RN: 101238665

Dear Ms. Carswell:

The request you submitted on behalf of Limestone Ranch to change from submetered to allocated billing is approved. This approval is based on the facts stated in your request of March 27, 2009. Please complete the attached forms and return them along with a copy of this letter. You may do so via facsimile at: 512-239-6190.

If you have any questions, please contact me at 512-239-6403, via e-mail at mtaunton@tceq.state.tx.us, or by fax at 512-239-6190.

Sincerely,

Margot Taunton, Program Specialist

Margot Jaunton

Utilities & Districts Section

Water Supply Division

MT/as

Attachments (TCEQ-10363 and TCEQ-10400)

26

# Application to Change Billing Method

	RN number	CN number	S numbe	)°				
1	Name of Property	Limestone Ranch						
2	Street Address	28	11 LA FRONTERA BLVD					
3	City and state	Austin, TX		Zip code	78728			
4	Telephone number	5122181773	Fax number					
5	Email address	bnunez@camapts.com						
6	Number of Units	512	Number & percentage of non- functioning units	35% (11 out of 32 Buildings)				
7	Billing Method	Submetered - Tariff			<u> </u>			
8	Have any tenants con billing or submetering		Yes					
9		spent In repairs to date?	The meters can not be replaced due to the type of system. This is an Oiask system and has not been manufactured in 10 years. It would cost \$77,804.97 (best case pricing) to replace the entire system.					
-	Ista Contact Julie Carswell 3655 Northpolnt Parkway Suite 250 Alpharetta, GA 300 678-832-0932	Concierge Con Barbara Moffitt Regional Property Manager Concierge Americ Housing 2811 La Frontera, TX 78728 Cell 512.788.4131	y can					
(	Carsul	Fax 512.733.1777	ing Method Change					
	The meters can not be been manufactured in system.	replaced due to the type 10 years. It would cost \$7	of system. This is an 077,804.97 (best case p	Diask system ricing) to rep	n and has not lace the entire			

We will be billing the property as a RUBS. 50% based on occupany and 50% based on square footage. The property will have a 25% CAD.



March 17, 2009

Dear Limestone Ranch,

ista uses reliable, high quality precision products from the industry's leading manufacturers of utility metering and submetering hardware. From time to time your hardware requires service or calibration. We understand that quality assurance and control are key to your successful utility management program. Therefore ista assigns qualified and experienced technicians to service submetering systems.

During an audit of your community's submetering system, it was found that repairs are needed. Please find the attached proposal for hardware maintenance services, which includes a breakdown of the issues and a summary of your community's hardware system.

Please do not pay from this proposal. You will receive an invoice upon completion of work. Please sign and fax the proposal to 770-242-0431 so that we can get someone out to your property as quickly as possible.

Thank you for your business, and we look forward to working with you. If you have any questions, please do not hesitate to contact your Client Relations Manager.

Regards,

Cheryl Morgan

### Property Information:

Property Name Limestone Ranch Contact Address. 2811 La Fontera Blvd Address Emailbnunez@camapts.com Phone 512-218-1773 Fax n/a



_ity	Austin				
State:	TX	••			
Σŧρ·	72728				

## System Condition

Meter Type. Read Type.

Age of System·

Total # of meters


Meters Functioning 0 0% 100% Meters Not Functioning

Property Code 32962 Created By: Felicia Rivera Date Created 3/17/2009 5/1/2009

#### Limestone Ranch

■ Meters functioning L. Meters Not Functioning

0%



#### Units requiring repair:

Proposal Expiration Date.

#### **Entire Property Conversion**

Unit	Issue	Unit	Issue	Unit	Issue
<u> </u>					
		ĺ			
		!			
				3	

Osakı

n/a

512

Manual Read




PROPERTY NAME:

LIMESTONE RANCH (32962)

### Equipment & Labor Required

ltem	Part #	Quantity		Price	Total	Description
Inovonics DCC 5800	38000	1	\$	1,246.00	\$ 1,246.00	Data Collector and Concentrator
EchoStream Receiver	36005	1	\$	252.00	\$ 252 00	Receiver for DCC
EchoStream PMTransmitter	36000	512	\$	46 20	\$ 23,654 40	Transmits reads from water meter
AMCO V100 Positive Displacement Meter						
w/ Pulse Output	25640	512	\$	45.50	\$ 23,296.00	Water Meter
AMCO Connector Washer	25637	512	\$	. 049	\$ 250.88	Washers
	İ			}	\$ -	
Equipment Subtotal	1				\$ 48,699.28	
Labor Subtotal		512	\$	49.00	\$ 25,088 00	Labor
Sales Tax (Labor)					\$ -	
Sales Tax (Equipment)			:	8 25%	\$ 4,017.69	
Total					\$ 77,804 97	

## Acceptance





Maintenance Service Proposal

Contact: Cheryl Morgan Email. cmorgan@ista-na.com

> Tel: 678-832-0981 Fax: 770-242-0431

### Application to Change Billing Method

	RN number	CN number	S numbe	er			
1	Name of Property	Limestone Ranch					
2	Street Address	,2811 LA FRONTERA BLVD					
3	City and state	Austin, TX		Zip code	78728		
4	Telephone number	5122181773	Fax number				
5	Email address	bnunez@camapts com					
6	Number of Units	512	Number & percentage of non-functioning units	35% (11 d Buildings			
7	Billing Method	Submetered - Tariff			<del></del>		
8	Have any tenants combilling or submetering		Yes	- 100			
9	How much has been spent in repairs to date?		The meters can not be replaced due to the type of system. This is an Oiask system and has not been manufactured in 10 years. It would cost \$77,804.97 (best case pricing) to replace the entire system.				
		-					

Ista Contact
Julie Carswell
3655 Northpoint
Parkway
Suite 250
Alpharetta, GA 30005
678-832-0932

. . . >

Concierge Contact
Barbara Moffitt
Regional Property
Manager
Concierge American
Housing
2811 La Frontera, Austin,
TX 78728
Cell 512.788 4131
Fax 512.733.1777

Reason for Billing Method Change

The meters can not be replaced due to the type of system. This is an Oiask system and has not been manufactured in 10 years. It would cost \$77,804.97 (best case pricing) to replace the entire system.

We will be billing the property as a RUBS. 50% based on occupany and 50% based on square footage. The property will have a 25% CAD.