

Control Number: 32182




Item Number: 114

Addendum StartPage: 0



FIVE AREA TELEPHONE COOPERATIVE, INC. P.O. BOX 448

MULESHOE, TEXAS 79347-0448



September 18, 2006

Filing Clerk Public Utility Commission of Texas PO Box 13326 Austin, TX 78711

RE:

Project No. 32182

Investigation of Methods to Improve Electric and Telecom Infrastructure That Will Minimize Long Term Outages and Restoration Costs

This is to advise the Commission of Five Area's efforts regarding its vegetation management program and on-going ground-based inspection program for overhead facilities. Five Area Telephone Cooperative employees make routine inspections, as time allows, of all overhead facilities to make sure that vegetation is kept trimmed and away from all overhead cable, poles, and pole attachments. These inspections are monitored by a supervisor and result in the facilities being kept in well-maintained order and fully operational.

Please advise if any further information is needed at this time.

Sincerely,

Sandy Vandevender

Executive Vice President and General Manager

SV/jb