

Control Number: 45866



Item Number: 362

Addendum StartPage: 0

## ATTACHMENT 10 Request to Intervene in PUC Docket No. Date Page 40 of 41

The following information must be submitted by the person requesting if it is an in the information. This completed form will be provided to all parties in this docket. If you DO NOT want to be an intervenor, but still want to file comments, please complete the "Comments" pagePUBLIC UTILITY COMMISSIEN FILING CLERK

Mail this completed form and 10 copies to:

Public Utility Commission of Texas Central Records Attn: Filing Clerk 1701 N. Congress Ave. P.O. Box 13326 Austin, TX 78711-3326

First Name: Horace	Last Name:	Dicks
Phone Number: 512-297-7730	Fax Number:	NA
Address, City, State: 4073 Honey Bear	Loop Rou	nd Rock, Tx. 78681

# I am requesting to intervene in this proceeding. As an INTERVENOR, I understand the following:

- I am a party to the case;
- I am required to respond to all discovery requests from other parties in the case;
- If I file testimony, I may be cross-examined in the hearing;
- If I file any documents in the case, I will have to provide a copy of that document to every other party in the case: and
- I acknowledge that I am bound by the Procedural Rules of the Public Utility Commission of Texas (PUC) and the State Office of Administrative Hearings (SOAH).

#### Please check one of the following:

I own property with a habitable structure located near one or more of the utility's proposed routes for a transmission line.

One or more of the utility's proposed routes would cross my property.

Other. Please describe and provide comments. You may attach a separate page, if necessary. \_

se read the attached Comments - Headlines you Don't Want to Read

Signature of person requesting intervention:

erred SI

Effective: January 1, 2003

### Attachment to Horace Dicks Comments

#### Request to Intervene in PUC Docket No. 45866

#### Headlines You Don't Want to Read:

Approximately 16 years ago, as President of the Vista Oaks Neighborhood Association, my neighbors and I fought for many months to get a signal light installed at the entry of the subdivision(Vista Hills Dr. and 1431). Unfortunately we were met with much opposition, involving cost, until a fatality occurred. I only mention this incident as a way of reminding us of what we are preparing to do with the installation of 80ft. powerlines and what we may need to rethink:

- 1. <u>Safety for Vista Oaks kids</u> Powerlines hanging over Church nursery/Daycare Center, Vista Oaks Pool and recreation area can create a recipe for headlines you don't want to read.
- Safety for Vista Oaks residential drivers 80 ft. powerlines hanging over "other lower powerlines", + semi-trucks constantly traveling to and from the quarry + 65 mph traffic on 1431, can create a recipe for headlines you don't want to read.
- 3. <u>Safety for homes in Vista Oaks</u> Since 1431 (from 183 to I-35) is known as tornado alley, additional powerlines may increase electrical fires and headlines you don't want to read.