



Control Number: 50422



Item Number: 15

Addendum StartPage: 0

SP UTILITY COMPANY
PO BOX 690521
HOUSTON, TX 77269

MAY 11 PM 12:09

DOCKET NO. 50422

COMMISSION STAFF'S FIRST REQUEST FOR INFORMATION
TO JOHNSON WATER SERVICE AND SP UTILITY COMPANY, INC.
QUESTION NOS. STAFF 1-1 THROUGH STAFF 1-2

Staff 1-1

Please provide the costs and funding source(s) needed to correct each of the Violations listed in the compliance plan, page 19 provided on March 23rd, 2020.

Response: The estimated costs to correct all violations is \$2,245.05. The funding sources will come from revenues from SP utility company and its affiliated operating company Flow-Tech. Please see attachment filed confidentially.

Staff 1-2

Please provide proof of funding sources such as the current financial statements or bank statement

Response: The funding sources will come from revenues from SP utility company and its affiliated operating company Flow-Tech. Please see attachment filed confidentially.