

Control Number: 51415



Item Number: 93

Addendum StartPage: 0



APPLICATION OF SOUTHWESTERN \$
ELECTRIC POWER COMPANY FOR \$

BEFORE THE STATE OFFICE

RECEIVED

DEC 1 8 2020

§ §

AUTHORITY TO CHANGE RATES §

OF
ADMINISTRATIVE HEARINGS

SOUTHWESTERN ELECTRIC POWER COMPANY'S RESPONSE TO OFFICE OF PUBLIC UTILITY COUNSEL'S SECOND REQUEST FOR INFORMATION

DECEMBER 4, 2020

TABLE OF CONTENTS

<u>SECTION</u>	FILE NAME	PAGE
Response No. OPUC 2-1	51415 OPUC02 Pkg.pdf	3
Response No. OPUC 2-2	51415 OPUC02 Pkg.pdf	
Response No. OPUC 2-3	51415 OPUC02 Pkg.pdf	
Response No. OPUC 2-4	51415 OPUC02 Pkg.pdf	7
Response No. OPUC 2-5	51415 OPUC02 Pkg.pdf	
Attachment 1 to No. OPUC 2-5	OPUC 2-5 Attachment 1.xlsx	
Response No. OPUC 2-6	51415 OPUC02 Pkg.pdf	10
Attachment 1 to No. OPUC 2-6	OPUC 2-6 Attachment 1.xlsx	
Response No. OPUC 2-7	51415 OPUC02 Pkg.pdf	12
Attachment 1 to No. OPUC 2-7	OPUC 2-7 Attachment 1.xlsx	
Response No. OPUC 2-8	51415 OPUC02 Pkg.pdf	36
Attachment 1 to No. OPUC 2-8	OPUC 2-8 Attachment 1.xlsx	
Response No. OPUC 2-9	51415 OPUC02 Pkg.pdf	38
Response No. OPUC 2-10	51415 OPUC02 Pkg.pdf	
Response No. OPUC 2-11	51415 OPUC02 Pkg.pdf	
Attachment 2 to No. OPUC 2-11	OPUC_2-11_Attachment_2.xlsx	42
Response No. OPUC 2-12	51415 OPUC02 Pkg.pdf	
Attachment 1 to No. OPUC 2-12	51415 OPUC02 Pkg.pdf	
Response No. OPUC 2-13	51415 OPUC02 Pkg.pdf	47
Attachment 1 to No. OPUC 2-13	51415 OPUC02 Pkg.pdf	
Response No. OPUC 2-14	51415 OPUC02 Pkg.pdf	
Attachment 1 to No. OPUC 2-14	51415 OPUC02 Pkg.pdf	
Response No. OPUC 2-15	51415 OPUC02 Pkg.pdf	
Attachment 1 to No. OPUC 2-15	OPUC_2-15_Attachment_1.xlsx	

SOUTHWESTERN ELECTRIC POWER COMPANY'S RESPONSE TO OFFICE OF PUBLIC UTILITY COUNSEL'S SECOND REQUEST FOR INFORMATION

DECEMBER 4, 2020

TABLE OF CONTENTS (Continued)

Files provided electronically on the PUC Interchange

- P司 OPUC_2-1_Attachment_1.xlsx
- Page OPUC_2-1_Attachment_2.xlsx
- Page OPUC_2-5 Attachment 1.xlsx
- Pi OPUC_2-6_Attachment_1 xlsx
- Pa OPUC 2-7 Attachment 1.xlsx
- P OPUC_2-8_Attachment_1.xlsx
- OPUC_2-11 Attachment 1 (2018_2020_IBEW_Master_and_Local_SWEPCO_Contract).pdf
- P OPUC_2-11_Attachment_2.xlsx
- PI OPUC_2-15_Attachment_1.xlsx

SOUTHWESTERN ELECTRIC POWER COMPANY'S RESPONSE TO OFFICE OF PUBLIC UTILITY COUNSEL'S SECOND REQUEST FOR INFORMATION

Question No. OPUC 2-1:

Please refer to the Direct Testimony of Mr. Paul Pratt, Jr., pages 23 – 28. Please provide American Electric Power Service Company ("AEPSC") Customer Services budgeted and actual expenses for each of the years 2015, 2016 and 2017. Please include in your response the budgeted and actual expense for SWEPCO for the same period.

Response No. OPUC 2-1:

Please see OPUC 2-1 Attachments 1 and 2 provided electronically on the PUC Interchange for AEPSC Customer Services and SWEPCO budgeted and actual expenses for years 2015, 2016, and 2017.

Prepared By: Victoria A. Allinson Title: Regulatory Consultant Sr

Sponsored By: Paul E. Pratt Title: Dir Customer Svcs & Mktg

SOUTHWESTERN ELECTRIC POWER COMPANY'S RESPONSE TO OFFICE OF PUBLIC UTILITY COUNSEL'S SECOND REQUEST FOR INFORMATION

Question No. OPUC 2-2:

Please refer to the Direct Testimony of Mr. Paul Pratt, Jr., page 32. Please provide AEPSC's Customer Services budgeted and actual expenses as shown in Figure 6 with the short-term and long-term incentive compensation amounts included.

Response No. OPUC 2-2:

No short-term or long-term incentive compensation amounts were included or removed from AEPSC's Customer Services budgeted expenses shown in Figure 6 as incentive compensation is not budgeted at the department level. However, in order to create an apples to apples comparison of witness Pratt's performance-to-budget cost trends, short-term and long-term incentive compensation amounts were removed from AEPSC's Customer Services actual expenses in Figure 6 in the following amounts: 2018) \$855,499; 2019) \$1,786,147, and; Test Year) \$1,498,730.

Prepared By: Victoria A. Allinson Title: Regulatory Consultant Sr

Sponsored By: Paul E. Pratt Title: Dir Customer Svcs & Mktg

SOUTHWESTERN ELECTRIC POWER COMPANY'S RESPONSE TO OFFICE OF PUBLIC UTILITY COUNSEL'S SECOND REQUEST FOR INFORMATION

Question No. OPUC 2-3:

Please refer to the Direct Testimony of Mr. Paul Pratt, Jr., page 32. Please provide a detailed description of the services provided with the implementation of "customer relationship management, engagement and survey tools" that were not provided in the years prior to 2018. Please include in your response the budgeted and actual expenses for these services in each of the years 2018, 2019 and the test year in total for AEPSC as well as the amount allocated to SWEPCO.

Response No. OPUC 2-3:

The Company has two tools, Medallia and the Customer Relationship Management (CRM), that were implemented after 2018. A breakdown of these tools with a detailed description of the services and budgeted and actual expenses in years 2018, 2019, and the test year in total for AEPSC Customer Services (CCO Organization) as well as the amount allocated to SWEPCO has been provided below. The operation and maintenance (O&M) expenses for neither of these tools was directly budgeted to their specific projects until after implementation, but rather were budgeted within the CCO Organization to be paid out of general O&M dollars. Medallia O&M is for licensing fees and managed account dollars. CRM O&M is related mainly to cloud-based subscription charges and licensing fees. The O&M for both tools also include some internal labor.

Medallia

<u>Description:</u> Medallia allows the Company to listen to and act on customer feedback in near-real time. The Medallia platform provides quick access to key performance metrics and customer comments, insightful graphics, and trend data for identifying improvement opportunities. In addition, the platform supports a "closed loop process" to allow us the ability to track and follow-up with customers who express dissatisfaction. The following surveys are currently in production:

- Digital surveys are "pop ups" that appear when customers are using the website or the mobile app. Questions are focused on satisfaction and ease of the channel;
- Contact Center surveys are sent the day after the customer contacts us. They identify satisfaction with call and agent, reason for call, and issue resolution; and
- Reputation surveys help us understand brand satisfaction and factors that influence satisfaction (billing, payment, reliability, restoration, etc.).

Link to additional information - http://aepnow.aepnow.com/news/47946.

Funding: O&M

Page 2 of 2

	2018	2018	2019	2019	Test Year	Test Year
	Budget	Actuals	Budget	Actuals	Budget	Actuals
Total Amount	\$0	\$0	\$400,000	\$398,99	\$400,000	\$398,990
Allocated to						
SWEPCO-TX	\$0	\$0	\$0	\$13,638	\$0	\$13,638
BU 161						

Customer Relationship Management (CRM)

<u>Description</u>: The CRM project lays a foundation for providing an end-to-end, 360 degree view of customer data across sales, marketing, and customer service. The project is part of AEP's Customer Experience (CX) program, which aims to create a world-class customer experience and position AEP as the energy provider of choice. CRM helps improve our customer and experience by:

- Providing a more efficient way to track and share customer interactions with AEP;
- Knowing our customer better and providing more personalized experiences for our customers;
- Deploying a mobile application for customer service reps to have access to customer information while in the field;
- Allowing customers to have easier interactions with AEP through interactive email campaigns;
- Providing employees easier access to updated AEP policies and answers to customer's Frequently Asked Questions for faster answers;
- Providing employees easier access to customer billing and usage information to answer customers questions quickly and accurately;
- Providing employees better reporting capabilities to help analyze customer needs and offer solutions for customers; and
- Providing employees better visibility into Customer complaints and reporting capabilities to understand trends and how to proactively solve customer issues.

Link to additional information - http://crm.aepsc.com/overview/.

Funding: O&M

	2018	2018	2019	2019	Test Year	Test Year
	Budget	Actuals	Budget	Actuals	Budget	Actuals
Total Amount	\$1,500,000	\$900,700	\$1,500,000	\$1,980,515	\$1,500,000	\$1,875,271
Allocated to SWEPCO-TX BU 161	\$0	\$30,887	\$0	\$66,899	\$0	\$63,315

Prepared By: Victoria A. Allinson Title: Regulatory Consultant Sr

Sponsored By: Paul E. Pratt Title: Dir Customer Svcs & Mktg

SOUTHWESTERN ELECTRIC POWER COMPANY'S RESPONSE TO OFFICE OF PUBLIC UTILITY COUNSEL'S SECOND REQUEST FOR INFORMATION

Question No. OPUC 2-4:

Please refer to the Direct Testimony of Mr. Paul Pratt, Jr., page 30. Please provide the amount of outside services costs included in each of the amounts shown in Figure 5. Please include a detailed description of the services provided by each vendor by year and the associated amounts paid to each vendor.

Response No. OPUC 2-4:

Please see OPUC 2-4 Confidential Attachment 1 for a detailed description of the services provided by each vendor by year and the associated amounts paid to each vendor. Additionally, Figure 5 has been updated below to provide the amount of outside services included in CCO Affiliate O&M costs for 2017-2019 and the Test Year.

Figure 5 – CCO Affiliate O&M Costs

Year	Total Amount	Outside Services Costs
2017	\$9,168,426	\$1,496,376
2018	\$10,605,592	\$1,941,376
2019	\$11,235,436	\$2,212,336
Current Test Year	\$11,392,833	\$2,319,889

The attachment responsive to this request is CONFIDENTIAL under the terms of the Protective Order. Due to current restrictions associated with COVID-19, this information is being provided electronically and a secure login to access the information will be provided upon request to individuals who have signed the Protective Order Certification.

Prepared By: Victoria A. Allinson Title: Regulatory Consultant Sr

Sponsored By: Paul E. Pratt Title: Dir Customer Svcs & Mktg

Sponsored By: Brian J. Frantz Title: Dir Accounting

SOUTHWESTERN ELECTRIC POWER COMPANY'S RESPONSE TO OFFICE OF PUBLIC UTILITY COUNSEL'S SECOND REQUEST FOR INFORMATION

Question No. OPUC 2-5:

Please refer to the Direct Testimony of Mr. Brian Bond, Table 2. Please provide a detailed explanation of the significant increase in Environmental Services expense from 2018 to 2019 and the test year. Please identify specific categories of cost increases and the associated actual expenses in 2019 and the test year for each category.

Response No. OPUC 2-5:

The Environmental Services expenses increased from 2018 to 2019 and in the test year as the result of severance costs incurred due to a departmental reorganization referenced in Brian Bond's testimony. The specific cost category is defined as severance costs and severance fringe costs. In 2019, overall Department expenses associated with severance related costs was \$622,281. During the test year, overall Department expenses associated with severance related costs was \$591,949. OPUC 2-5 Attachment 1 provides the details of costs by category.

Prepared By: Brian Bond Title: VP External Affairs

Sponsored By: Brian Bond Title: VP External Affairs

SOAH Docket No. 473-21-0538 PUC Docket No. 51415 OPUC 2nd, Q. # OPUC 2-5, Attachment 1

		Cost Category	Cost Subcategory	2018	2019	Test Year
10773R	Environmental Services	Fringes	Labor Fringes	628,536	641,451	636,841
			Other Labor Fringes	7	1,698	1,717
			Severance Fringes		3,324	22,164
		Fringes Total		628,543	646,472	660,721
		Internal Labor	Overtime Labor	5,209	7,006	6,446
			Straight Time Labor	2,050,166	2,114,028	2,085,924
		Internal Labor Total		2,055,376	2,121,033	2,092,370
		Material & Supplies	Matls And Supplies L3	218,211	197,495	214,928
		Material & Supplies Total		218,211	197,495	214,928
		Other Clearings/Billings	Clearings/Billings	8,856	9,931	13,629
		Other Clearings/Billings Total		8,856	9,931	13,629
		Other Cost Category	Employee Lump Sum Payments	62	15,027	15,192
			Leases	87,092	92,411	96,460
			Memberships	266	845	450
			Miscellaneous & Other	2,540	1,206	1,470
			Postage Phone & Pager	10,883	12,516	12,967
			Reimbursement Credits	-719		-385
		Other Cost Category Total		100,125	122,005	126,154
		Outside Services	Outside Services L3	260,713	310,009	252,187
		Outside Services Total		260,713	310,009	252,187
		Severance	Severance L3		618,957	569,785
		Severance Total			618,957	569,785
		Travel & Entertainment	Travel & Entertainment L3	72,222	78,041	73,588
		Travel & Entertainment Total		72,222	78,041	73,588
10773R	Environmental Services Total			3,344,046	4,103,944	4,003,363

SOUTHWESTERN ELECTRIC POWER COMPANY'S RESPONSE TO OFFICE OF PUBLIC UTILITY COUNSEL'S SECOND REQUEST FOR INFORMATION

Question No. OPUC 2-6:

Please refer to the Direct Testimony of Mr. Brian J. Frantz, executive summary, page 4. Please provide a chart that includes the same breakout of cost categories included on page 4 of Mr. Frantz's executive summary for each of the last four calendar years.

Response No. OPUC 2-6:

Please refer to OPUC 2-6 Attachment 1 for requested information.

Prepared By: Brian J. Frantz Title: Dir Accounting

Sponsored By: Brian J. Frantz Title: Dir Accounting

SOAH Docket No 473-21-0538 PUC Docket No 51415 OPUC 2nd, Q 6 OPUC 2-6 Attachment 1 Page 1 of 1

SOUTHWESTERN ELECTRIC POWER COMPANY Frantz Executive Summary AEPSC Charges Billed to SWEPCO For The Last Four Calendar Years

Class of Service	2016	2017	2018	2019
Chief Financial Officer	6,297,418	5,304,331	6,670,800	1,306,455
Chief Executive Officer/Internal Audit	1,332,036	1,387,440	969,737	1,144,226
Supply Chain, Procurement and Fleet Operations	274,573	267,640	319,634	369,965
Internal Support	1,262,806	1,077,752	1,867,380	2,711,648
AEPSC Incentives	14,494,673	10,894,290	12,104,096	14,190,068
Grand Total	23,661,506	18,931,453	21,931,647	19,722,362

SOUTHWESTERN ELECTRIC POWER COMPANY'S RESPONSE TO OFFICE OF PUBLIC UTILITY COUNSEL'S SECOND REQUEST FOR INFORMATION

Question No. OPUC 2-7:

Please refer to the Direct Testimony of Mr. Brian J. Frantz, Table 5. Please provide a breakdown by AEPSC department of the \$21.4 million that was directly assigned to SWEPCO during the test year. Please provide a detailed description of the projects according to the AEPSC department to which these directly assigned costs relate to the project.

Response No. OPUC 2-7:

Please refer to OPUC 2-7 Attachment 1 for requested information.

Prepared By: Brian J. Frantz Title: Dir Accounting

Sponsored By: Brian J. Frantz Title: Dir Accounting

AEPSC Department	Project ID/Description	Amount
Chief Administrative Officer	000005502 CSC - All Call Types	272,736
	OPBLDG Gs Operating Co Building Expen	206,476
	X00116782 Power Plant Operation Technica	56,160
	FANANDA Activity NOT assoc with a PROJ	46,826
	X00116795 Day-to-Day Permit and Regulato	40,083
	BAOCOREBL BAO Core Billing	37,387
	SSITNANDA Accumulate Gen _ Admin IT Exp	30,932
	ETNANDA Transmission Anda	24,396
	SSSANANDA Accumulate Gen & Admin Securit	21,060
	000005442 CSC Call Center Support	20,548
	EDNANDA Distribution Anda Project	19,910
	LGNANDA Legal/Policy/Cc Anda	14,705
	EON018181 Rate Case Support	12,812
	ETN001007 Abd Proposal Estimate Preprtn	11,771
	X00116805 Environmental Analyses	9,055
	CHNANDA Chairman Anda	8,941
	SSGSNANDA Shared Services-Accumulate Gen	8,926
	TDOANDA T And D Other Anda	8,563
	ETN000159 Sep Distribution Station Overh	8,290
	EDN103181 Ds Sep Ark-Anda	7,071
	SSN100013 Ss Ed Distribution Nanda Proj	6,846
	FHGENNERC FHG Gen NERC Compliance	6,685
	LGN101704 Litigation - General	6,674
	X00116794 Permitting and Regulatory Supp	6,576
	SSN100012 Ss Ed Trans Nanda Proj	6,005
	BAONONCOR BAO Non-Core Billing	5,947
	X00116949 Rata Services (O&M)	5,902
	000001072 Regulated Fuel Supply	5,736
	EON100347 Collections Support	5,593
	WSX110939 Environmental Serv -Distribut	5,496
	TRKBENVIR TRK BASE ENVIRON EXPENDITURES	5,220
	X00116760 Chemical Engineering Services	5,218
	SOCIALMED Social Media Organization	5,206
	X00116764 Environmental Optimization Ser	5,065
	000011894 Energy Delivery Oil Analysis	5,023
	X00116816 Administrative Services Suppor	4,902
	WSX109104 WILKES -BASE COST OF OPERATION	4,871
	000005554 CSC Corpus - All Call Types	4,271
	X00116803 Plant O&M Related Analyses	4,215
	WSX114371 SWEPCO REO O M Staff Budget	4,087
	ECNMLWN01 TCOM-Lan/Wan Program	3,944
	X00116777 Infrastructure Inspection & As	3,729
	WSHMU0071 WSH U0 CCR RULE-0&M	3,581
	000002524 PRK - BCO	3,300
	WSHM1G001 WSH U1 GBIR	3,067
	X00116759 CEMS Support Services (O&M)	2,838
	FLC054100 FLC BCO Non-Payroll	2,605
	WSHM3G001 WSH U3 GBIR	2,506
	LGN101901 Environmental General	2,325
	TRKOMISCM TRK OMRO MISC MAINTENANCE	2,214
	PRK19GBIR O&M GBIR	1,867
	ARS6SMAJR 6S TURB/GEN MAJOR	1,817
	000012310 SEP LA Attach Serv Rentals	1,662
	CCRGWMONP Plant CCR GW Monitoring	1,646
	000001073 Regulated Fuels Admin	1,487
	000020779 Customer Web Inquiry	1,486
	000002786 Simulator Learning Center O M	1,480
	TRKBCHEMS TRK BASE CHEMICALS	1,398
	TRABUTEINO TRABASE UTENITUALO	

AEPSC Department	Project ID/Description	Amount
	ACTCARADM Activated Carbon	1,267
	EON102461 Value Creation Non-Sever Reloc	1,249
	NGCCSTUDY Natural Gas Siting Study - CC	1,231
	000001585 O&M / Fuel Staff Project	1,207
	ETN100257 TR/BATT Battery Insp Detailed	1,109
	000012311 SEP TX Attach Serv Rentals	1,089
	LGN101639 Labor Law & Relations	1,022
	000005325 Core Load Research Activity	1,012
	X00116802 Emissions Testing	969
	000005708 Ds SEP La-Anda	941
	X00116804 Industrial Hygiene Analyses	926
	LGN101699 General Regulatory Services	903
	KXL5MM009 KXL U5 Generator Inspection	889
	LIMEADMIN Procure Lime for AEP Plants	886
	ETN000194 T Sep T Anda	835
	LBM0MLRSO RSO LABOR	784
	EDN103182 Ds Sep Tx Anda	777
	GENOPEREX Gen Operational Excellence	733
	HWARRANTY Home Warranty Program	685
	TRKOVALVE TRK TURBINE MAIN & STOP VALVES	683
	SSN100004 Ss Wholesale Other	679
	TURKRAIL2 New Turk Rail Access	658
	BUSREV012 Business Process Review	654
	ETN100223 Tr/Trns Tran-Cm Not Assoc/Pm	650
	ETN100220 Tr/Pagm Prop & Grnds Maint	650
	000001859 Greg/Rusk 8898 & 8899 non cap	645
	TRKFBCO00 TRK COAL YARD MISC	590
	EDN102170 Ds/All/Dist ABD	576
	ECNMSCA01 TCOM-SCADA Program	568
	PRKMSTR01 SAFETY TEAM RECOMMENDATIONS	551
	DCRESERCH CSC Direct Collections - Recon	546
	PLANTREG4 Plant Eng Region 4 Support	516
	ARSHU6BCO ARS Hill Unit 6 BCO	508
	PRK19M001 O&M OUTAGE < \$100K	507
	ETN100221 Tr/Cbns Cb-Cm Not Assoc W/Pm	494
	ECNMTPT01 TCOM-Transport Program	484
	WSHMU3062 WSH U3 Boiler Tubes Drum WW	483
	KXL5MM005 KXL U5 Corrosion Fatigue	474
	TONNPMA01 TON NP Maintenance	457
	000007488 SWEP/Tx/Dist Undg Locates	413
	000007486 SWEP/Ark/Dist Undg Locates	413
	000007487 SWEP/La/Dist Undg locates	413
	X00116800 Spill Remediation Support and	412
	ETN100213 Tr/Trip Relay Trip Check	406
	000022452 Engineering Structural Inspect	406
		405
	<u> </u>	
	000003460 CSC Training-New Hire Classes	391
	OUTBNDCOM Outbound Communication	384
	ASHADMINS Ash Sales Administration	370
	WSX109160 Arsenal Hill - Base Cost Of Op	368
	TRKNSAFTY TRK NOMI SAFETY	364
	WSX109127 Lieberman -Base Cost Of Operat	363
	WSHMU3063 WSH U3 PSH and SH Repairs	363
	LBM4FOROT U4 Forced Outage	362
	LGN101636 Corporate Financing	359
	ANHYAMMON Procure Anhydrous Ammonia	353
		0.40
	CULTURETR Culture Train Power up & Lead	349
	CULTURETR Culture Train Power up & Lead CALBRMADM Procure Calcium Bromide	349 326

TRKNWWATER TRK WASTE WATER TREATMENT PLT ARSIGEMENT 319 ARSIGEMENT 319 ARSIGEMENT 318 W.K.M. 100170 U. CONTROL VALVES 315 LON101644 Property Sales 313 ITPPP1421 Maximo Implementation 312 K.K.L. 15 Forced Outages 300 K.K.L. 15 K.K.L. U.S Forced Outages 300 K.K.L. U.S F	AEPSC Department	Project ID/Description	Amount
ARSCHEMCL ARSUS CHEMICAL CLEAN W.KMY0019 UI CONTROL VALVES LON101644 Property Sales 313 ITFPF1421 Maxmo Implementation 312 KXL5FK001 KXL US Frored Outges 300 KXL5MB017 KXL US Man Steam Attemperator 291 ETN000161 Sep-Tx Distribution Station Ov 285 ETN100249 Tr/Tgorn Undefined O&M Projects 285 LGN101645 Rght Town Undefined O&M Projects 285 KXL5MB001 KXL US GBIR Overhaul 278 KXL5MM010 KXL US Heal Trace & Insulation 284 LBM0MDOOR Boiler Doors 285 ETN100203 Tr/Timm Transformer Minor Reg 285 LMSTADMIN Procure Limestone 280 X00116768 Regulatory Development 281 LBM0MECON Economizer Hair Pin Replace 282 LBMSTADMIN TRK NOMI CY MISC MAINT 287 FLC041000 FLC BCO - Non-payroll 285 WSHMU1083 WSH UI PSH and SH Repars 280 USHMU1083 WSH UI PSH and SH Repars 280 USHMU1083 WSH UI PSH and SH Repars 281 USSOLUTN Tulsa Business Solutions 282 USSOLUTN Tulsa Business Solutions 283 X00116973 Title 316 (b) Propect 281 W.KMM1083 UI BREAKER REBUILD 283 HSHATKSRE T/SWWINO-Specific Wink Station 284 UKLMM1083 UI BREAKER REBUILD 285 HSHATKSRE T/SWWINO-Specific Wink Station 286 ARSBOUTCL ARSB OUTAGE CONTRACT LABOR 285 USSOLUTO ARSB OUTAGE CONTRACT LABOR 286 USS 116578 TIK NOMI BCD REPAIRS 389 USSOLUTO ARSB OUTAGE CONTRACT LABOR 380 KSH UI BB BREAKER REBUILD 380 LB BHATKSRE T/SWWINO-Specific Wink Station 381 LGN100970 General Hill UI int GO Operations 380 LGN100970 SPEC MAINS SHAT ARROWS 381 USBAD LB BREAKER REBUILD 381 USSOLUTA ARSB OUTAGE CONTRACT LABOR 380 US		TRKNWWATR TRK WASTE WATER TREATMENT PLT	322
W.KM10019		ARSU6ORMR ARS STALL UNIT ORM REQUIREMENT	319
LGN101644 Property Sales 313 ITPFF1421 Maxmo Implementation 312 KXL5FK001 KXL US Forced Outages 300 KXL5M8017 KXL US Main Steam Attemperator 291 ETN000161 Sep+7 bilishibution Station Ov 285 ETN100249 TrTgom Undefined O&M Projects 285 LGN101645 Right Of Way/Easements 278 KXL5M8001 KXL US GBIR Overhaul 278 LGN102653 Video Web Design 276 KXL5MM010 KXL US GBIR Overhaul 278 LGN102653 Video Web Design 276 KXL5MM010 KXL US GBIR Overhaul 284 LBM0MD000R Boiler Doors 262 ETN100203 TrTmm Transformer Minor Reg 258 LMSTADMIN Procure Limestone 250 X00116796 Regulatory Development 248 LBM0MECON Economizer Hair Pin Replace 241 TRKNCYMIS TRK NOMI CY MISC MAINT 237 FLC041000 FLC BCO - Non-payroll 235 WSHMU1083 UJ MAIN STEAM STOP VALVE 241 TRKNCYMIS TRK NOMI CY MISC MAINT 237 FLC041000 FLC BCO - Non-payroll 235 WSHMU1083 WSH UJ PSH and SH Repairs 230 TRKLEANI5 TRK LEAN 2015 WORK 229 BUSSOLUTIN Tuisa Business Solutions 223 X00116973 Title 316 (b) Project 218 WLKM10033 UJ BREAKER REBUILD 213 B194TKSRE TSWINon-Specific Work Station 210 TRKBGRDST TRK NOMI GCY MISC Station 210 ARSSOUTCL		ARSCHEMCL ARSU5 CHEMICAL CLEAN	318
ITFFP1421 Maximo Implementation 312 KXL5FK001 KXL US Forced Outages 300 KXL5MB017 KXL US Main Steam Attemperator 291 ETN000161 Sep-TX Distribution Station Ov 285 ETN100249 TT/Egrou Interfience Oath Projects 285 LON101645 Right Of Way/Easements 278 KXL5MB001 KXL US GBIR Overhaul 278 LGN102563 Video Web Design 276 KXL5MM010 KXL US GBIR Overhaul 278 LGN102603 Video Web Design 276 KXL5MM010 KXL US Heal Trace & Insulation 264 LBMOMDOOR Boiler Doors 282 ETN10203 T/Timmr Transformer Minor Reg 285 LMSTADMIN Procure Limestone 250 X00116796 Regulatory Development 248 LBMOMECON Economizer Hair Pin Replace 241 WLKM10018 U1 MAIN STEAM STOP VALVE 241 TEKKCYMIS TRK NOMI CY MISC MAINT 237 FLC041000 FLC BCO - Non-payroll 235 WSHMU1083 WSH U1 PSH and SH Repairs 230 WSHMU1083 WSH U1 PSH and SH Repairs 230 TRKLEAN15 TRK LEAN 2015 WORK 229 BUSSOLUTN Tulsa Business Solutions 223 X00116730 Tills 136 (b) Project 218 TRKBMISCR TRK MISC REPAIRS 218 WLKM10033 UI BREAKER REBUILD 213 B141XSRE T/SWNon-Specific Work Station 210 TRKBGRIST TRK NOMI GROUNDS MAINT LABOR 206 ARSUGUTCL ARSA OUTAGE CONTRACT LABOR 206 ARSUGUTCL ARSA OUTAGE CONTRACT LABOR 206 ARSUGUTCL ARSA OUTAGE CONTRACT LABOR 206 ARSOUTCL ARSA OUTAGE CONTRACT LABOR		WLKM10019 U1 CONTROL VALVES	315
XXL5FK001 XXL US Foirced Outages 300 XXL5MB017 XXL US Main Steam Attemperator 291 ETN000161 Sep-Tx Distribution Station Ov 285 ETN100249 Tr/Tgom Undefined D&M Projects 285 LGN101645 Right Of Way/Easements 278 XXL5MB010 XXL US GBIR Overhaul 278 XXL5MB010 XXL US Healt Trace & Insulation 264 LBM0MDOOR Boiler Doors 282 ETN100203 Tr/Immr Transformer Minor Reg 258 LMSTADMIN Procure Limestone 250 X00116796 Regulatory Development 248 LBM0MECON Economizer Hair Pin Replace 241 TRKNCYMIS TRK NOMI CY MISC MAINT 237 FLC041000 FLC BCO - Non-payroli 235 XVSHM01083 WSH UJ PSH and SH Repairs 230 TRKLEAN15 TRK LEAN 2015 WORK 229 SUSSOLUTIN Tulas Business Solutions 223 X00116973 Title 316 (b) Project 218 WAM101033 U1 BEBEAKER REBUILD 213 B194TXSRE T/SW/Non-Specific Work Station 210 TRKBGROST TRK NOMI GROUNDS MAINT LAD 243 ARSSOUTCL ARSSOU		LGN101644 Property Sales	313
ETN000161 Sep-TX Distribution Station Ov 285		ITPFP1421 Maximo Implementation	312
ETN00161 Sep-Tx Distribution Station Ov 285 ETN100249 T/T/5gorn Windefined O&M Projects 285 LGN101645 Right Of Way/Easements 278 KXL5M8001 KXL US GBIR Overhaul 278 KXL5M8010 KXL US GBIR Overhaul 278 LGN102653 Video Web Design 276 KXL5M8010 KXL US Heal Trace & Insulation 264 LBM0MDOOR Boiler Doors 262 ETN100203 T/T/Immr Transformer Minor Reg 258 LMSTADMIN Procure Limestone 250 X00116796 Regulatory Development 248 LBM0MECON Economizer Hair Pin Replace 241 WLKM10018 U1 MAIN STEAM STOP VALVE 241 TRKNCYMIS TRK NOMI CY MISC MAINT 237 FLC041000 FLC BCO - Non-payroll 235 WSHMU1063 WSH U1 PSH and SH Repairs 230 TRKLEAN15 TRK LEAN 2015 WORK 229 BUSSOLUTIN Tutas Business Solutions 223 X00116973 Title 316 (3) Project 218 TRKBMISCS TRK MISC REPAIRS 218 WLKM10033 U1 BERAKER REBUILD 213 B141TXSRE T/SWNNon-Specific Work Station 210 TRKBGROST TRK NOMI GRUNDS MAINT LABOR 266 ARSUGOUTG Arsenal Hill Unit 6 Outage 206 ARSCOUTC ARSO OUTAGE CONTRACT LABOR 206 WSX100080 WSH U0 Base Cost Of Operations 200 X00116750 Coal Pile Inventory Services (197 TRKNBLDGR TRK NOMI BCR DEPAIRS 196 ECN103052 DI Abd Telecom Projects 189 FLC156574 PSH and SH Repairs 160 CON 20116750 Coal Pile Inventory Services (197 TRKNBLDGR TRK NOMI BCR DEPAIRS 196 ECN103052 DI Abd Telecom Projects 189 FLC1565764 PSH and SH Repairs 160 ARSGOUTG ARSEN DI BREAKER REBUILD 166 ECN103052 DI Abd Telecom Projects 189 FLC1565764 PSH and SH Repairs 160 ARSGOUTG ARSEN DI BREAKER REPAIRS 196 ECN103052 DI Abd Telecom Projects 189 FLC1676764 PSH and SH Repair 163 LGN 100970 General Contracts/Agreements 163 ETN100255 T/Tipa Line Inspection 162 X00116760 Metallurgical Failure Analysis 162 ETN100277 Tr/Teem Electrical Equip Maint 152 LBM0MOUTX Outage Combined 162 DMS19LAOS SWL-LAVAILEY/STStorm 4-13-19 143 ETN102054 TRKNBCPL TRK NOW INDER EXPLISE 198 FLT 10000001445 PK.Marshall South-Land 7700 166 ARSGBHINS 6 BI RISG INSPECTIONS 136 WSHMUIO74 WSH U1 TURBINE VALVE INSP RPR 133 TRKRBSOUT. TRK NSO PLANT LABOR 132 TRKNBSERVO TKK NOM IMISC SERVICES 126 TRKNSAFPF TRK NOM INGLO SERVICES 12		KXL5FK001 KXL U5 Forced Outages	300
ETN100249		KXL5MB017 KXL U5 Main Steam Attemperator	291
LGM1014-5		ETN000161 Sep-Tx Distribution Station Ov	285
KXLSMB001 KXL U5 GBÍR Overhaul 278 LGN102653 Video Web Design 276 KXLSMM010 KXL U5 Heat Trace & Insulation 264 LBM0MDOOR Boiler Doors 262 ETN100203 Tri7mmr Transformer Minor Reg 258 LMSTADMIN Procure Limestone 250 X00116796 Regulatory Development 248 LBM0MECON Economizer Hair Pin Replace 241 WLKM10018 U1 MAIN STEAM STOP VALVE 241 TRKNCYMIS TRK NOMIC YMISC MAINT 237 FLC941000 FLC BCO - Non-payroll 235 WSHMU1063 WSH U1 PSH and SH Repairs 230 TRKLEAN15 TRK LEAN 2015 WORK 229 BUSSOLUTIN Tulsa Business Solutions 223 X00116973 Title 316 (b) Project 218 TRKEMISCR TRK ISK REPAIRS 218 TRKMINGOR TRK MISC REPAIRS 218 WLKM10033 U1 BREAKER REBUILD 213 B194TXSRE TISWNon-Specific Work Station 210 <t< td=""><td></td><td>ETN100249 Tr/Tgom Undefined O&M Projects</td><td>285</td></t<>		ETN100249 Tr/Tgom Undefined O&M Projects	285
LGN102653		LGN101645 Right Of Way/Easements	278
KXL 5MM010 KXL US Heat Trace & Insulation 264 LBM0MDOOR Boiler Doors 262 ETN100203 T/Tmmr Transformer Minor Reg 258 LMSTADMIN Procure Limestone 250 X00116796 Regulatory Development 248 LBM0MECON Economizer Hair Pin Replace 241 WLKM10018 U1 MAIN STEAM STOP VALVE 241 TRKNCYMIS TRK NCYMIS 178 FLC 960 - Non-payroll 235 WSHMU1063 WSH U1 PSH and SH Repairs 230 TRKLEAN15 TRK LEAN 2015 WORK 229 BUSSOLUTN Tulsa Business Solutions 223 X00116973 Tille 316 (b) Project 218 TRKBMISCR TRK MISC REPAIRS 218 WLKM10033 U1 BREAKER REBUILD 213 B1941XSRE TISK NOMI GROUNDS MAINT LABOR 206 ARSUBOUTG Arseal Hui Inti & Outage 206 ARSUBOUTG Arseal Hui Inti & Outage 20 WSX109080 WSH LU Base Cost Of Operations 20 WSY109080		KXL5MB001 KXL U5 GBIR Overhaul	278
LBMOMDOOR Boiler Doors 252 ETN100203 Tr/Tmmr Transformer Minor Reg 258 LMSTADMIM Procure Limestone 250 X00116796 Regulatory Development 248 LBMOMECON Economizer Hair Pin Replace 241 WLKM10018 U MAIN STEAM STOP VALVE 241 TRKNCYMIS TRK NOMI CY MISC MAINT 237 FLC041000 FLC BCO - Non-payroll 235 WSHMU1063 WSH U1 PSH and SH Repairs 230 TRKLEAN 15 TRK LEAN 2015 WORK 229 BUSSOLUTN Tulea Business Solutions 223 X00116973 Title 316 (b) Project 218 TRKBMISCR TRK MISC REPAIRS 218 WLKM10033 U 1 BREAKER REBUILD 213 B194TXSRE TJKNWOn-Specific Work Station 210 TRKBGRDS1 TRK NGROUNDS MAINT LABOR 206 ARS6OUTCL ARS6 OUTAGE CONTRACT LABOR 206 ARS6OUTCL ARS6 OUTAGE CONTRACT LABOR 206 ARS6OUTCL ARS6 OUTAGE CONTRACT LABOR 206		LGN102653 Video Web Design	276
ETN100203		KXL5MM010 KXL U5 Heat Trace & Insulation	264
LMSTADMIN Procure Limestone 250 X00116796 Regulatory Development 248 LBMOMECON Economizer Hair Pin Replace 241 WLKM10018 U1 MAIN STEAM STOP VALVE 241 TRKNCYMIS TRK NOMI CY MISC MAINT 237 FLC041000 FLC BCO - Non-payroll 235 WSHMU1063 WSH U1 PSH and SH Repairs 230 TRKLEAN15 TRK LEAN 216 WORK 229 BUSSOLUTN Tulsa Business Solutions 223 X00116973 Title 316 (b) Project 218 WLKM10033 U1 BREAKER REBUILD 213 B194TXSRE TKM MISC REPAIRS 218 WLKM10033 U1 BREAKER REBUILD 213 B194TXSRE TKM MISC ROVINDS MAINT LABOR 206 ARSUGOUTG Arsenal Hill Unit 6 Outage 206 ARSUGOUTG ARSO OUTAGE CONTRACT LABOR 206 WSX109080 WSH U0 Base Cost of Operations 200 X00116750 Coal Pile Inventory Services (197 TRKNBLOGN TKK NOS DIOPRINS 189 ECN103052 DI Abd Telecom Projects 189 FLC165784 PSH and SH Repairs 189 WSX112283 Non-Billable Organizational PI 186 000012309 SEP AK Attach Serv Rentals 170 ARSUGORMR ARS ORM REQUIREMENTS 167 000001465 PK-Marshall South-Land 7700 166 ARSGORRRO Stall Steam Turbine Val Repair 163 LGN100970 General Contracts/Agreements 163 ETN100235 Tr/Tlap Line Inspection 162 X00116780 Metallurgical Failure Analysis 162 ETN100237 Tr/Tlap Line Inspection 162 X00116780 Metallurgical Failure Analysis 162 ETN100237 Tr/Tlap Line Inspection 162 X00116780 Metallurgical Failure Analysis 162 ETN100237 Tr/Tlap Line Inspection 163 ARSGEMING SHALL Steam Turbine Val Repair 163 LGN100970 General Contracts/Agreements 163 ETN100235 Tr/Tlap Line Inspection 162 X00116780 Metallurgical Failure Analysis 162 ETN100237 Tr/Tlap Line Inspection 163 ARSGEMING 6B HRSG INSPECTIONS 133 TRKBRSOPL TRK SOP LANT LABOR 132 TRKDSAFP TRK SAFETY PLATFORMS 126 TRKNSERVO TRK NOM MISC SERVICES 1		LBM0MDOOR Boiler Doors	262
X00116796 Regulatory Development 248 LBMOMECON Economizer Hair Pin Replace 241 WILMI 10018 U1 MAIN STEAM STOP VALVE 241 TRKNCYMIS TRK NOMI CY MISC MAINT 237 FLC041000 FLC BCO - Non-payroll 235 XSHMU1063 WSHU1 195H and SH Repairs 230 TRKLEAN15 TRK LEAN 2015 WORK 229 BUSSOLUTN Tulsa Business Solutions 223 X00116973 Title 316 (b) Project 218 TRKBMISCR TRK MISC REPAIRS 218 WLKM10033 U1 BREAKER REBUILD 213 TRKBMISCR TRK MISC REPAIRS 218 WLKM10033 U1 BREAKER REBUILD 213 TRKBGRDS1 TRK NOMI GROUNDS MAINT LABOR 206 ARSGOUTGL ARSGOUTG		ETN100203 Tr/Tmmr Transformer Minor Reg	258
LBMOMECON Economizer Hair Pin Replace 241		LMSTADMIN Procure Limestone	250
WLKM10018		X00116796 Regulatory Development	248
TRKNCYMIS		LBM0MECON Economizer Hair Pin Replace	241
FLC041000 FLC BCO - Non-payroll 235 WSHMU1063 WSH U1 PSH and SH Repairs 230 TRKLEAN15 TRK LEAN 2015 WORK 229 BUSSOLUTN Tulsa Business Solutions 223 X00116973 Title 316 (b) Project 218 TRKBMISCR TRK MISC REPAIRS 218 WLKM10033 U1 BREAKER REBUILD 213 B194TXSRE T\SWNon-Specific Work Station 210 TRKBGRDS1 TRK NOMI GROUNDS MAINT LABOR 206 ARS06OUTG Arsenal Hill Unit 6 Outage 206 ARS06OUTG ARS06 OUTAGE CONTRACT LABOR 206 WSX109080 WSH U0 Base Cost Of Operations 200 X00116750 Coal Pile Inventory Services 197 TRKNBLDGR TRK NOMI BLDG REPAIRS 196 ECN103052 DI Abd Telecom Projects 189 FLC165784 PSH and SH Repairs 188 WSX112283 Non-Billable Organizational Pi 186 000012309 SEP AK Attach Serv Rentals 170 ARSUSORMR ARS ORM REQUIREMENTS 167 000001465 PK-Marshall South-Land 7700 166 ARS6GNRRO Stall Steam Turbine Val Repair 163 LGN100970 General Contracts/Agreements 163 LGN100970 General Contracts/Agreements 162 ETN100235 Tr/Tap Line Inspection 162 ARS0BHINS 6B HRSG INSPECTIONS 136 WSHIU1074 WSH U1 TURBINE VALVE INSP RPR 133 TKRBSOPL TRK RSO PLANT LABOR 132 TRKRSCOPL TRK RSO PLANT LABOR 132 TRKNSERVO TRK R		WLKM10018 U1 MAIN STEAM STOP VALVE	241
FLC041000 FLC BCO - Non-payroll 235 WSHMU1063 WSH U1 PSH and SH Repairs 230 TRKLEAN15 TRK LEAN 2015 WORK 229 BUSSOLUTN Tulsa Business Solutions 223 X00116973 Title 316 (b) Project 218 TRKBMISCR TRK MISC REPAIRS 218 WLKM10033 U1 BREAKER REBUILD 213 B194TXSRE T\SWNon-Specific Work Station 210 TRKBGRDS1 TRK NOMI GROUNDS MAINT LABOR 206 ARS06OUTG Arsenal Hill Unit 6 Outage 206 ARS06OUTG ARS06 OUTAGE CONTRACT LABOR 206 WSX109080 WSH U0 Base Cost Of Operations 200 X00116750 Coal Pile Inventory Services 197 TRKNBLDGR TRK NOMI BLDG REPAIRS 196 ECN103052 DI Abd Telecom Projects 189 FLC165784 PSH and SH Repairs 188 WSX112283 Non-Billable Organizational Pi 186 000012309 SEP AK Attach Serv Rentals 170 ARSUSORMR ARS ORM REQUIREMENTS 167 000001465 PK-Marshall South-Land 7700 166 ARS6GNRRO Stall Steam Turbine Val Repair 163 LGN100970 General Contracts/Agreements 163 LGN100970 General Contracts/Agreements 162 ETN100235 Tr/Tap Line Inspection 162 ARS0BHINS 6B HRSG INSPECTIONS 136 WSHIU1074 WSH U1 TURBINE VALVE INSP RPR 133 TKRBSOPL TRK RSO PLANT LABOR 132 TRKRSCOPL TRK RSO PLANT LABOR 132 TRKNSERVO TRK R		TRKNCYMIS TRK NOMI CY MISC MAINT	237
WSHMU1063 WSH U1 PSH and SH Repairs 230 TRKLEAN15 TRK LEAN 2015 WORK 229 BUSSOLUTN Tusta Business Solutions 223 X00116973 Title 316 (b) Project 218 TRKMBISCR TRK MISC REPAIRS 218 WLKM1003 U1 BREAKER REBUILD 213 B194TXSRE T/SW/Non-Specific Work Station 210 TRKBGRDS1 TRK NOMI GROUNDS MAINT LABOR 206 ARS60UTCL ARS6 OUTAGE CONTRACT LABOR 206 ARS60UTCL ARS6 OUTAGE CONTRACT LABOR 206 WSX109080 WSH U0 Base Cost Of Operations 200 X00116750 Coal Pile Inventory Services (197 TRKNBLDCR TRK NOMI BLDG REPAIRS 196 ECN 103052 Dt Abd Telecom Projects 189 FLC165784 PSH and SH Repairs 189 WSX112283 Non-Billable Organizational PI 186 00001485 PK-Marshall South-Land 7700 166 ARS6GNRO Stall Steam Turbine Val Repair 163 LGN100970 General Contracts/Agreement			
TRKLEAN15 TRK LEAN 2015 WORK 229			
X00116973 Title 316 (b) Project 218 TRKBMISCR TRK MISC REPAIRS 218 WLKM10033 U1 BREAKER REBUILD 213 B194TXSRE TISWINOn-Spectific Work Station 210 TRKBGRDS1 TRK NOMI GROUNDS MAINT LABOR 206 ARS60UTCL ARS6 OUTAGE CONTRACT LABOR 206 WSX109080 WSH U0 Base Cost Of Operations 200 X00116750 Coal Pile Inventory Services (197 TRKNBLDGR TRK NOMI BLDG REPAIRS 196 ECN103052 Dt Abd Telecom Projects 189 FLC165784 PSH and SH Repairs 189 WSX112283 Non-Billable Organizational PI 186 00012309 SEP AK Attach Serv Rentals 170 ARSUSORMR ARS ORM REQUIREMENTS 167 00001465 PK-Marshall South-Land 7700 166 ARS6GNRO Stall Steam Turbine Val Repair 163 LGN109970 General Contracts/Agreements 163 ETN100225 Tr/Teem Electrical Equip Maint 152 DMS19LA05 SW-LAV/alley/TSt		· ·	229
X00116973 Title 316 (b) Project 218 TRKBMISCR TRK MISC REPAIRS 218 WLKM10033 U1 BREAKER REBUILD 213 B194TXSRE TISWINOn-Spectific Work Station 210 TRKBGRDS1 TRK NOMI GROUNDS MAINT LABOR 206 ARS60UTCL ARS6 OUTAGE CONTRACT LABOR 206 WSX109080 WSH U0 Base Cost Of Operations 200 X00116750 Coal Pile Inventory Services (197 TRKNBLDGR TRK NOMI BLDG REPAIRS 196 ECN103052 Dt Abd Telecom Projects 189 FLC165784 PSH and SH Repairs 189 WSX112283 Non-Billable Organizational PI 186 00012309 SEP AK Attach Serv Rentals 170 ARSUSORMR ARS ORM REQUIREMENTS 167 00001465 PK-Marshall South-Land 7700 166 ARS6GNRO Stall Steam Turbine Val Repair 163 LGN109970 General Contracts/Agreements 163 ETN100225 Tr/Teem Electrical Equip Maint 152 DMS19LA05 SW-LAV/alley/TSt			
TRKBMISCR			
WILKM10033		• • • • • • • • • • • • • • • • • • • •	
B194TXSRE			
TRKBGRDS1 TRK NOMI GROUNDS MAINT LABOR 206 ARSU6OUTCL Arsenal Hill Unit 6 Outage 206 ARS6OUTCL ARS6 OUTAGE CONTRACT LABOR 206 WSX109080 WSH U0 Base Cost Of Operations 200 X00116750 Coal Pile Inventory Services (197 TRKNBLDGR TRK NOMI BLDG REPAIRS 196 ECN103052 Dt Abd Telecom Projects 189 FLC1G5784 PSH and SH Repairs 189 WSX112283 Non-Billable Organizational PI 186 000012309 SEP AK Attach Serv Rentals 170 ARSU5ORMR ARS ORM REQUIREMENTS 167 00001465 PK-Marshall South-Land 7700 166 ARS6GNRRO Stall Steam Turbine Val Repair 163 LGN100970 General Contracts/Agreements 163 ETN100225 Tr/Tlap Line Inspection 162 X00116780 Metallurgical Failure Analysis 162 ETN100225 Tr/Fee Electrical Equip Maint 152 DMS19LA05 SW-LAValley/TStorm 4-13-19 143 ETN100253			
ARS06OUTGL Arsenal Hill Unit 6 Outage 206 ARS6OUTGL ARS6 OUTAGE CONTRACT LABOR 206 WSX109080 WSH U0 Base Cost Of Operations 200 X00116750 Coal Pile Inventory Services (197 TRKNBLDGR TRK NOMI BLDG REPAIRS 196 ECN103052 Dt Abd Telecom Projects 189 FLC1056784 PSH and SH Repairs 188 WSX112283 Non-Billable Organizational PI 186 000012309 SEP AK Attach Serv Rentals 170 ARSU5ORMR ARS ORM REQUIREMENTS 167 000001465 PK-Marshall South-Land 7700 166 ARS6GNRRO Stall Steam Turbine Val Repair 163 LGN100970 General Contracts/Agreements 163 ETN100235 Tr/Tlap Line Inspection 162 X00116780 Metallurgical Failure Analysis 162 ETN100227 Tr/Teem Electrical Equip Maint 152 LBM0MOUTX Outage Combined 152 DMS19LA05 SW-LAVAlley/TStorm 4-13-19 143 ETN100253 Tr/Pice Power Line Carrier 142 000020544 SPP RE Compliance 136 ARS6BHINS 6B HRSG INSPECTIONS 136 WSHMU1074 WSH U1 TURBINE VALVE INSP RPR 133 TRKBRSOPL TRK RSO PLANT LABOR 132 PRK13M011 O M Forced Outage 125 TRK NSAFPF TRK SAFETY PLATFORMS 126 WLKNO1006 NOMI Combine 125 UNLNO1006 TR/TPDM Pred Diag Maint Proj 122		·	
ARS6OUTCL ARS6 OUTAGE CONTRACT LABOR WSX109080 WSH U0 Base Cost Of Operations 200 X00116750 Coal Pile Inventory Services (197 TRKNBLDGR TRK NOMI BLDG REPAIRS 196 ECN103052 Dt Abd Telecom Projects 188 FLC1G5784 PSH and SH Repairs 189 WSX112283 Non-Billable Organizational Pl 186 000012309 SEP AK Attach Serv Rentals 170 ARSU5ORMR ARS ORM REQUIREMENTS 167 00001465 PK-Marshall South-Land 7700 166 ARS6GNRRO Stall Steam Turbine Val Repair 163 LGN100970 General Contracts/Agreements 163 ETN100235 Tr/Tap Line Inspection 162 X00116780 Metallurgical Failure Analysis 162 ETN100227 Tr/Teem Electrical Equip Maint 152 LBM0MOUTX Outage Combined 152 DMS19LA05 SW-LA/Valley/T'Storm 4-13-19 143 ETN100253 Tr/Ploe Power Line Carrier 142 000020544 SPP RE Compliance 136 ARS6BHINS 6B HRSG INSPECTIONS 136 WSHMU1074 WSH U1 TURBINE VALVE INSP RPR 133 TRKBRSOPL TRK RSO PLANT LABOR 132 PRK13M011 OM Forced Outage 129 TRKNSERVO TRK NOMI MISC SERVICES 126 WLKN01006 NOMI Combine 125 ETN100256 TR/TPDM Pred Diag Maint Proj 122			
WSX109080 WSH U0 Base Cost Of Operations 200 X00116750 Coal Pile Inventory Services (197 TRKNBLDGR TRK NOMI BLDG REPAIRS 196 ECN103052 Dt Abd Telecom Projects 189 FLC165784 PSH and SH Repairs 189 WSX112283 Non-Billable Organizational PI 186 000012309 SEP AK Attach Serv Rentals 170 ARSU5ORMR ARS ORM REQUIREMENTS 167 00001465 PK-Marshall South-Land 7700 166 ARS6GNRRO Stall Steam Turbine Val Repair 163 LGN100970 General Contracts/Agreements 163 ETN100235 Tr/Tlap Line Inspection 162 X00116780 Metallurgical Failure Analysis 162 ETN100227 Tr/Teem Electrical Equip Maint 152 LBM0MOUTX Outage Combined 152 DMS19LA05 SW-LAValley/TStorm 4-13-19 143 ETN100253 Tr/Pice Power Line Carrier 142 000020544 SPP RE Compliance 136 ARS6BHINS 6B HRSG INSPECTIO		· ·	
X00116750 Coal Pile Inventory Services (197 TRKNBLDGR TRK NOMI BLDG REPAIRS 196 ECN103052 Dt Abd Telecom Projects 189 FLC165784 PSH and SH Repairs 189 WSX112283 Non-Billable Organizational PI 186 000012309 SEP AK Attach Serv Rentals 170 ARSU50RMR ARS ORM REQUIREMENTS 167 00001465 PK-Marshall South-Land 7700 166 ARS6GNRRO Stall Steam Turbine Val Repair 163 LGN100970 General Contracts/Agreements 163 ETN100235 Tr/Tap Line Inspection 162 X00116780 Metallurgical Failure Analysis 162 ETN100225 Tr/Teem Electrical Equip Maint 152 LBM0MOUTX Outage Combined 152 DMS19LA05 SW-LA/Valley/T'Storm 4-13-19 143 ETN100253 Tr/Plce Power Line Carrier 143 ETN86BHINS 6B HRSG INSPECTIONS 136 WSHMU1074 WSH U1 TURBINE VALVE INSP RPR 133 TRK RSO PLANT LABOR 132<			
TRKNBLDGR TRK NOMI BLDG REPAIRS 196 ECN103052 Dt Abd Telecom Projects 189 FLC1G5784 PSH and SH Repairs 189 WSX112283 Non-Billable Organizational PI 196 000012309 SEP AK Attach Serv Rentals 170 ARSU50RMR ARS ORM REQUIREMENTS 167 00001465 PK-Marshall South-Land 7700 166 ARS6GNRRO Stall Steam Turbine Val Repair 163 LGN100970 General Contracts/Agreements 163 ETN100235 Tr/Tiap Line Inspection 162 X00116780 Metallurgical Failure Analysis 162 ETN100227 Tr/Teem Electrical Equip Maint 152 LBM0MOUTX Outage Combined 152 DMS19LA05 SW-LAV/alley/T'Storm 4-13-19 143 ETN100253 Tr/Plce Power Line Carrier 142 000020544 SPP RE Compliance 136 ARS6BHINS 6B HRSG INSPECTIONS 136 WSHMU1074 WSH U1 TURBINE VALVE INSP RPR 133 TRKRSOPL TRK RSO PLANT LABOR		•	
ECN103052 Dt Abd Telecom Projects 189 FLC1G5784 PSH and SH Repairs 189 WSX112283 Non-Billable Organizational PI 186 000012309 SEP AK Attach Serv Rentals 170 ARSU50RMR ARS ORM REQUIREMENTS 167 000001465 PK-Marshall South-Land 7700 166 ARS6GNRRO Stall Steam Turbine Val Repair 163 LGN100970 General Contracts/Agreements 163 ETN100235 Tr/Tlap Line Inspection 162 X00116780 Metallurgical Failure Analysis 162 ETN100227 Tr/Teem Electrical Equip Maint 152 DMS19LA05 SW-LA/Valley/T'Storm 4-13-19 143 ETN100253 Tr/Ploe Power Line Carrier 142 000020544 SPP RE Compliance 136 ARS6BHINS 6B HRSG INSPECTIONS 136 WSHMU1074 WSH U1 TURBINE VALVE INSP RPR 133 TRK RSOPL TRK RSO PLANT LABOR 132 PRK13M011 OM Forced Outage 129 TRKNSERVO TRK NOMI MISC SERVICES		• • • • • • • • • • • • • • • • • • • •	
FLC1G5784 PSH and SH Repairs 189 WSX112283 Non-Billable Organizational Pi 186 000012309 SEP AK Attach Serv Rentals 170 ARSU50RMR ARS ORM REQUIREMENTS 167 000001465 PK-Marshall South-Land 7700 166 ARS6GNRRO Stall Steam Turbine Val Repair 163 LGN100970 General Contracts/Agreements 163 ETN100235 Tr/Tap Line Inspection 162 X00116780 Metallurgical Failure Analysis 162 ETN100227 Tr/Teem Electrical Equip Maint 152 LBM0MOUTX Outage Combined 152 DMS19LA05 SW-LAValley/T'Storm 4-13-19 143 ETN100253 Tr/Pice Power Line Carrier 142 000020544 SPP RE Compliance 136 ARS6BHINS 6B HRSG INSPECTIONS 136 WSHMU1074 WSH U1 TURBINE VALVE INSP RPR 133 TRKRSOPL TRK RSO PLANT LABOR 132 PRK13M011 O M Forced Outage 129 TRKNSAFPF TRK SAFETY PLATFORMS <td< td=""><td></td><td></td><td></td></td<>			
WSX112283 Non-Billable Organizational PI 186 000012309 SEP AK Attach Serv Rentals 170 ARSU50RMR ARS ORM REQUIREMENTS 167 000001465 PK-Marshall South-Land 7700 166 ARS6GNRRO Stall Steam Turbine Val Repair 163 LGN100970 General Contracts/Agreements 163 ETN100235 Tr/Tlap Line Inspection 162 X00116780 Metallurgical Failure Analysis 162 ETN100227 Tr/Teem Electrical Equip Maint 152 LBM0MOUTX Outage Combined 152 DMS19LA05 SW-LAValley/T'Storm 4-13-19 143 ETN100253 Tr/Plce Power Line Carrier 142 000020544 SPP RE Compliance 136 ARS6BHINS 6B HRSG INSPECTIONS 136 WSHMU1074 WSH U1 TURBINE VALVE INSP RPR 133 TRK RSO PL ANT LABOR 132 PRK13M011 O M Forced Outage 129 TRKNSERVO TRK NOMI MISC SERVICES 126 TRKNSAFPF TRK SAFETY PLATFORMS 126		·	
000012309 SEP AK Attach Serv Rentals 170 ARSU50RMR ARS ORM REQUIREMENTS 167 000001465 PK-Marshall South-Land 7700 166 ARS6GNRRO Stall Steam Turbine Val Repair 163 LGN100970 General Contracts/Agreements 163 ETN100235 Tr/Tlap Line Inspection 162 X00116780 Metallurgical Failure Analysis 162 ETN100227 Tr/Teem Electrical Equip Maint 152 LBM0MOUTX Outage Combined 152 DMS19LA05 SW-LAValley/T'Storm 4-13-19 143 ETN100253 Tr/Plce Power Line Carrier 142 000020544 SPP RE Compliance 136 ARS6BHINS 6B HRSG INSPECTIONS 136 WSHMU1074 WSH U1 TURBINE VALVE INSP RPR 133 TRKBRSOPL TRK RSO PLANT LABOR 132 PRK13M011 O M Forced Outage 129 TRKNSERV0 TRK NOMI MISC SERVICES 126 TRKNSAFETY PLATFORMS 126 WLKN01006 NOMI Combine 125 <t< td=""><td></td><td>•</td><td></td></t<>		•	
ARSU5ORMR ARS ORM REQUIREMENTS 167 000001465 PK-Marshall South-Land 7700 166 ARS6GNRRO Stall Steam Turbine Val Repair 163 LGN100970 General Contracts/Agreements 163 ETN100235 Tr/Tlap Line Inspection 162 X00116780 Metallurgical Failure Analysis 162 ETN100227 Tr/Teem Electrical Equip Maint 152 LBM0MOUTX Outage Combined 152 DMS19LA05 SW-LA/Valley/T'Storm 4-13-19 143 ETN100253 Tr/Plce Power Line Carrier 142 000020544 SPP RE Compliance 136 ARS6BHINS 6B HRSG INSPECTIONS 136 WSHMU1074 WSH U1 TURBINE VALVE INSP RPR 133 TRKBRSOPL TRK RSO PLANT LABOR 132 PRK13M011 O M Forced Outage 129 TRKNSERV0 TRK NOMI MISC SERVICES 126 TRKNSAFPF TRK SAFETY PLATFORMS 126 WLKN01006 NOMI Combine 125 ETN100256 TR/TPDM Pred Diag Maint Proj 122		•	
000001465 PK-Marshall South-Land 7700 166 ARS6GNRRO Stall Steam Turbine Val Repair 163 LGN100970 General Contracts/Agreements 163 ETN100235 Tr/Tlap Line Inspection 162 X00116780 Metallurgical Failure Analysis 162 ETN100227 Tr/Teem Electrical Equip Maint 152 LBM0MOUTX Outage Combined 152 DMS19LA05 SW-LA/Valley/T'Storm 4-13-19 143 ETN100253 Tr/Plce Power Line Carrier 142 000020544 SPP RE Compliance 136 ARS6BHINS 6B HRSG INSPECTIONS 136 WSHMU1074 WSH U1 TURBINE VALVE INSP RPR 133 TRKBRSOPL TRK RSO PLANT LABOR 132 PRK13M011 O M Forced Outage 129 TRKNSERVO TRK NOMI MISC SERVICES 126 TRKNSAFPF TRK SAFETY PLATFORMS 126 WLKN01006 NOMI Combine 125 ETN100256 TR/TPDM Pred Diag Maint Proj 122			
ARS6GNRRO Stall Steam Turbine Val Repair 163 LGN100970 General Contracts/Agreements 163 ETN100235 Tr/Tlap Line Inspection 162 X00116780 Metallurgical Failure Analysis 162 ETN100227 Tr/Teem Electrical Equip Maint 152 LBM0MOUTX Outage Combined 152 DMS19LA05 SW-LA/Valley/T'Storm 4-13-19 143 ETN100253 Tr/Plce Power Line Carrier 142 000020544 SPP RE Compliance 136 ARS6BHINS 6B HRSG INSPECTIONS 136 WSHMU1074 WSH U1 TURBINE VALVE INSP RPR 133 TRKBRSOPL TRK RSO PLANT LABOR 132 PRK13M011 O M Forced Outage 129 TRKNSERVO TRK NOMI MISC SERVICES 126 TRKNSAFPF TRK SAFETY PLATFORMS 126 WLKN01006 NOMI Combine 125 ETN100256 TR/TPDM Pred Diag Maint Proj 122			
LGN100970 General Contracts/Agreements 163 ETN100235 Tr/Tlap Line Inspection 162 X00116780 Metallurgical Failure Analysis 162 ETN100227 Tr/Teem Electrical Equip Maint 152 LBM0MOUTX Outage Combined 152 DMS19LA05 SW-LA/Valley/T'Storm 4-13-19 143 ETN100253 Tr/Plce Power Line Carrier 142 000020544 SPP RE Compliance 136 ARS6BHINS 6B HRSG INSPECTIONS 136 WSHMU1074 WSH U1 TURBINE VALVE INSP RPR 133 TRKBRSOPL TRK RSO PLANT LABOR 132 PRK13M011 O M Forced Outage 129 TRKNSERV0 TRK NOMI MISC SERVICES 126 TRKNSAFPF TRK SAFETY PLATFORMS 126 WLKN01006 NOMI Combine 125 ETN100256 TR/TPDM Pred Diag Maint Proj 122			
ETN100235 Tr/Tlap Line Inspection 162 X00116780 Metallurgical Failure Analysis 162 ETN100227 Tr/Teem Electrical Equip Maint 152 LBM0MOUTX Outage Combined 152 DMS19LA05 SW-LA/Valley/T'Storm 4-13-19 143 ETN100253 Tr/Plce Power Line Carrier 142 000020544 SPP RE Compliance 136 ARS6BHINS 6B HRSG INSPECTIONS 136 WSHMU1074 WSH U1 TURBINE VALVE INSP RPR 133 TRKBRSOPL TRK RSO PLANT LABOR 132 PRK13M011 O M Forced Outage 129 TRKNSERV0 TRK NOMI MISC SERVICES 126 TRKNSAFPF TRK SAFETY PLATFORMS 126 WLKN01006 NOMI Combine 125 ETN100256 TR/TPDM Pred Diag Maint Proj 122		•	
X00116780 Metallurgical Failure Analysis 162 ETN100227 Tr/Teem Electrical Equip Maint 152 LBM0MOUTX Outage Combined 152 DMS19LA05 SW-LA/Valley/T'Storm 4-13-19 143 ETN100253 Tr/Plce Power Line Carrier 142 000020544 SPP RE Compliance 136 ARS6BHINS 6B HRSG INSPECTIONS 136 WSHMU1074 WSH U1 TURBINE VALVE INSP RPR 133 TRKBRSOPL TRK RSO PLANT LABOR 132 PRK13M011 O M Forced Outage 129 TRKNSERV0 TRK NOMI MISC SERVICES 126 TRKNSAFPF TRK SAFETY PLATFORMS 126 WLKN01006 NOMI Combine 125 ETN100256 TR/TPDM Pred Diag Maint Proj 122			
ETN100227 Tr/Teem Electrical Equip Maint 152 LBM0MOUTX Outage Combined 152 DMS19LA05 SW-LA/Valley/T'Storm 4-13-19 143 ETN100253 Tr/Plce Power Line Carrier 142 000020544 SPP RE Compliance 136 ARS6BHINS 6B HRSG INSPECTIONS 136 WSHMU1074 WSH U1 TURBINE VALVE INSP RPR 133 TRKBRSOPL TRK RSO PLANT LABOR 132 PRK13M011 O M Forced Outage 129 TRKNSERV0 TRK NOMI MISC SERVICES 126 TRKNSAFPF TRK SAFETY PLATFORMS 126 WLKN01006 NOMI Combine 125 ETN100256 TR/TPDM Pred Diag Maint Proj 122		·	
LBM0MOUTX Outage Combined 152 DMS19LA05 SW-LA/Valley/T'Storm 4-13-19 143 ETN100253 Tr/Plce Power Line Carrier 142 000020544 SPP RE Compliance 136 ARS6BHINS 6B HRSG INSPECTIONS 136 WSHMU1074 WSH U1 TURBINE VALVE INSP RPR 133 TRKBRSOPL TRK RSO PLANT LABOR 132 PRK13M011 O M Forced Outage 129 TRKNSERV0 TRK NOMI MISC SERVICES 126 TRKNSAFPF TRK SAFETY PLATFORMS 126 WLKN01006 NOMI Combine 125 ETN100256 TR/TPDM Pred Diag Maint Proj 122			
DMS19LA05 SW-LA/Valley/T'Storm 4-13-19 143 ETN100253 Tr/Plce Power Line Carrier 142 000020544 SPP RE Compliance 136 ARS6BHINS 6B HRSG INSPECTIONS 136 WSHMU1074 WSH U1 TURBINE VALVE INSP RPR 133 TRKBRSOPL TRK RSO PLANT LABOR 132 PRK13M011 O M Forced Outage 129 TRKNSERV0 TRK NOMI MISC SERVICES 126 TRKNSAFPF TRK SAFETY PLATFORMS 126 WLKN01006 NOMI Combine 125 ETN100256 TR/TPDM Pred Diag Maint Proj 122		, ,	
ETN100253 Tr/PIce Power Line Carrier 142 000020544 SPP RE Compliance 136 ARS6BHINS 6B HRSG INSPECTIONS 136 WSHMU1074 WSH U1 TURBINE VALVE INSP RPR 133 TRKBRSOPL TRK RSO PLANT LABOR 132 PRK13M011 O M Forced Outage 129 TRKNSERV0 TRK NOMI MISC SERVICES 126 TRKNSAFPF TRK SAFETY PLATFORMS 126 WLKN01006 NOMI Combine 125 ETN100256 TR/TPDM Pred Diag Maint Proj 122		•	
000020544 SPP RE Compliance 136 ARS6BHINS 6B HRSG INSPECTIONS 136 WSHMU1074 WSH U1 TURBINE VALVE INSP RPR 133 TRKBRSOPL TRK RSO PLANT LABOR 132 PRK13M011 O M Forced Outage 129 TRKNSERV0 TRK NOMI MISC SERVICES 126 TRKNSAFPF TRK SAFETY PLATFORMS 126 WLKN01006 NOMI Combine 125 ETN100256 TR/TPDM Pred Diag Maint Proj 122		•	
ARS6BHINS 6B HRSG INSPECTIONS 136 WSHMU1074 WSH U1 TURBINE VALVE INSP RPR 133 TRKBRSOPL TRK RSO PLANT LABOR 132 PRK13M011 O M Forced Outage 129 TRKNSERV0 TRK NOMI MISC SERVICES 126 TRKNSAFPF TRK SAFETY PLATFORMS 126 WLKN01006 NOMI Combine 125 ETN100256 TR/TPDM Pred Diag Maint Proj 122			
WSHMU1074 WSH U1 TURBINE VALVE INSP RPR 133 TRKBRSOPL TRK RSO PLANT LABOR 132 PRK13M011 O M Forced Outage 129 TRKNSERV0 TRK NOMI MISC SERVICES 126 TRKNSAFPF TRK SAFETY PLATFORMS 126 WLKN01006 NOMI Combine 125 ETN100256 TR/TPDM Pred Diag Maint Proj 122		•	
TRKBRSOPL TRK RSO PLANT LABOR 132 PRK13M011 O M Forced Outage 129 TRKNSERV0 TRK NOMI MISC SERVICES 126 TRKNSAFPF TRK SAFETY PLATFORMS 126 WLKN01006 NOMI Combine 125 ETN100256 TR/TPDM Pred Diag Maint Proj 122			
PRK13M011 O M Forced Outage 129 TRKNSERV0 TRK NOMI MISC SERVICES 126 TRKNSAFPF TRK SAFETY PLATFORMS 126 WLKN01006 NOMI Combine 125 ETN100256 TR/TPDM Pred Diag Maint Proj 122			
TRKNSERV0 TRK NOMI MISC SERVICES 126 TRKNSAFPF TRK SAFETY PLATFORMS 126 WLKN01006 NOMI Combine 125 ETN100256 TR/TPDM Pred Diag Maint Proj 122			
TRKNSAFPF TRK SAFETY PLATFORMS 126 WLKN01006 NOMI Combine 125 ETN100256 TR/TPDM Pred Diag Maint Proj 122		-	
WLKN01006 NOMI Combine 125 ETN100256 TR/TPDM Pred Diag Maint Proj 122			
ETN100256 TR/TPDM Pred Diag Maint Proj 122			
· · ·			
ETN100214 Tr/Call Relay Calibration 120		•	
		ETNTUUZ14 Tr/Call Relay Calibration	120

AEPSC Department	Project ID/Description	Amount
	DMS19LA18 SW-LA/SHV/Thunderstorm 6-19-19	119
	ARS6AHINS 6A HRSG INSPECTIONS/INSULATION	118
	ETN100210 Tr/Rt01 Station Inspection	118
	DMS19LA19 SW-LA/SHV/Thunderstorm 6-23-19	117
	LBM0DRAIN Drain System	110
	ETN201102 NERC Relay Calibration	107
	TRKBPRMIT TRK BASE PERMITS & ENVIRONMENT	107
	EON102240 Supply Chain Value Creation	106
	TONNPOP01 TON NP Operations	104
	000014094 O M Forced Outage	104
	X00116758 Boiler Reliability Optimizatio	103
	2019NCOV1 2019-nCoV Planning & Response	103
	WSHMU3081 WSH U3 FW HEATER AND FW SYSTEM	103
	ECNMPHV01 TCOM-Telephone/Video Program	95
	LBM2FOROT U2 Forced Outage	94
	WSHMU1075 WSH U1 CIRC WATER SYSTEM	93
	TRKNMISCM TRK NOMI MISC MAINT	92
	TRKOBRSAM TRK OUTAGE BOILER TUBE SAMPLES	91
	DMS19LA09 SW-LA/Valley/T'storm 5-8-19	90
	TRKNRPLOW TRK ROTARY PLOWS 1 & 2	88
	DMS19AR03 SW-ARFAYThunderstorm 5-1-19	87
	TRKBMECH3 TRK BCO MECH 3 LABOR	87
	B159LASRE D/SW/Non-SpeicificWork Station	83
	DMS20LA02 SW-LA/SHV/T'storm 1-11-2020	77
	LSTONESVY Limestone Pile Surveys	76
	FLC1G5563 SH RH Repairs	74
	TRKNGENAX TRK N GENERATOR AND AUX SYSTEM	68
	FLCFGD814 Misc Routine Maintenance	65
	WLKM20043 U2 BREAKER REBUILD	63
	WSHMU3085 WSH U3 TURB STM, CTRLS, AUX	62
	B194ARSRE T/SW/Non-Specific Work-Station	61
	DMS19LA24 SW-LA/SHV/T'storm 10-20-19	57
	000022545 Turk Procurement Activities	56
	ECNMMUL01 TCOM-MULTI Program	53
	WSX109112 Knox Lee -Base Cost Of Operati	51
	WLKM30033 U3 BREAKER REBUILD	51
	ETN201301 Relay CT/PT Verification	51
	ARSU5GBIR U5 BOILER MAINTENANCE/INSPECTI	51
	FLC1G1742 Routine Boiler Maintenance	50
	DMS19LA16 SW-LA/SHV/Thunderstorm 5-8-19	50
	FLC1G1732 Economizer Repairs	50
	ARS10U6GO ARS Unit 6 Routine Outage	49
	000013139 FLC Boiler Riser Tubes	49
	KXL5MB013 KXL U5 Hot Spot Repairs	47
	DMS19LA12 SW-LASHVThunderstorm 4-18-19	42
	ETN100199 Trans - P C Direct Time	40
	DMS19LA14 SW-LASHVThunderstorm 4-25-19	38
	KXL2FK001 KXL U2 Forced Outages	37
	ARS56ETAX ARS/Stall 5&6 Electric Usage	36
	WSHFORC16 Welsh Forced Outage	34
	ETN100236 Tr/Tlci Comprehensive Inspect	34
	PRK11M940 ENVIRO DIKES & BERMS	33
	DIVINGOPS FHG Diving at the plants	32
	ARS6BLTSA STALL 6B LTSA CT	31
	TRKBICE03 TRK BCO ICE 3 LABOR	31
	ETN100204 Tr/Tmmn Transformer Minor Non	28
	DMS19TX21 SW-TX/LGV/Thunderstorm 7-10-19	27
	ETN201101 NERC Relay Trip Check	26
	TRKBCOMIS TRK MISC EXPENSE	25
		_

AEPSC Department	Project ID/Description	Amount
	FLCU10063 FLC Misc Valve Repair	24
	000004743 SWEP-TSectionalizing Program	24
	DMS20LA01 SW-LA/Valley/T'storm 1-11-2020	20
	DMS19AR14 SW-ARTDWind 7-10-19	20
	DMS19LA22 SW-LASHVThunderstorm 10-3-19	20
	WLKM10003 U1 ORM REQUIREMENT	20
	A15706018 Lone Star Power Plant sub	19 19
	DMS19LA21 SW-LAValleyTstorm 10-20-19	19
	DMS19AR13 SW-AR/FAY/Wind 10-20-19 ETN100202 Tr/Cbci Cb Complete Inspection	19
	WLKM20008 U2 ORM REQUIREMENT	18
	WLKM30001 U3 ORM REQUIREMENT	18
	EON103045 Customer Handbooks	17
	B194TXLRE T/SW/Non-Specific Work - Line	17
	ETN100246 Tr/Tisa T-Line Structure Maint	17
	DMS19LA08 SW-LASHVThunderstorm 4-7-19	17
	A17031001 Tontitown Spare Prchse	14
	ETN100201 Tr/Cbei Cb External Inspection	14
	DMS19AR05 SW-ARFAYThunderstorm 5-18-19	10
	PRK20GBIR O M GBIR	1:
	KXL0MM023 KXL Business Travel/Expenses	1:
	X00116801 Special Studies	10
	TRKOROUTG TRK OMRO ROUTINE OUTAGE	,,
	B161TXSRE D/SW/Non-Specific Work Station	,
	TRKBICE01 TRK BCO ICE 1 LABOR	,
	ARSCTDUES LTSA Annual Dues	,
	TRKORENEQ TRK OUTAGE RENTAL EQUIPMENT	
	DMS20LA03 SW-LA/Valley/T'storm 3-4-2020	·
	A18806031 Welsh breaker 11670 failure	•
	ETN100225 Tr/Pcns P&C Non-Sched Repairs	-
	DMS19LA01 SW-LAValleyTstorm 4-7-19	
	SWEHPITRN SWEPCO HPI Training	
	X00116770 GBIR Outage and Support Servic	4
	WLKFOU111 U 1 Forced Outage	;
	WSN100526 Comm Operations Staff Project	
	CULTUREGR General Culture Initiative	
	DR18S01A5 Overhead Renewal Project - TX	,
	DR18S01A8 DA Distribution Line - Texas	((
	DMS19LA06 SW-LASHVThunderstorm3-14-19	(0
hief Administrative Officer Total		1,074,911
hief Executive Officer	000005502 CSC - All Call Types	882,85
	SSSANANDA Accumulate Gen & Admin Securit	236,544
	CHNANDA Chairman Anda	230,217
	SSITNANDA Accumulate Gen _ Admin IT Exp	209,12
	LGNANDA Legal/Policy/Cc Anda	194,65
	BAOCOREBL BAO Core Billing	121,214
	LGN101704 Litigation - General	96,350
	X00116782 Power Plant Operation Technica	84,529
	FANANDA Activity NOT assoc with a PROJ	77,418
	X00116795 Day-to-Day Permit and Regulato	69,38
	000005442 CSC Call Center Support	67,21
	ETNANDA Transmission Anda	56,44
		54,36
	ECNMLWN01 TCOM-Lan/Wan Program	04,00
	ECNMLWN01 TCOM-Lan/Wan Program EDNANDA Distribution Anda Project	
		46,650
	EDNANDA Distribution Anda Project	46,650 41,186
	EDNANDA Distribution Anda Project OPBLDG Gs Operating Co Building Expen	46,650 41,186 32,768
	EDNANDA Distribution Anda Project OPBLDG Gs Operating Co Building Expen WSX109104 WILKES -BASE COST OF OPERATION	46,650 41,186 32,768 31,127 24,307

AEPSC Department	Project ID/Description	Amount
	000001072 Regulated Fuel Supply	21,413
	EON018181 Rate Case Support	19,511
	BAONONCOR BAO Non-Core Billing	19,246
	X00116816 Administrative Services Suppor	19,075
	LGN101639 Labor Law & Relations	18,440
	EON100347 Collections Support	17,999
	000002524 PRK - BCO	16,579
	X00116805 Environmental Analyses	16,514
	WSHM1G001 WSH U1 GBIR	16,439
	FLC054100 FLC BCO Non-Payroll	14,245
	TRKOMISCM TRK OMRO MISC MAINTENANCE	13,952
	000005554 CSC Corpus - All Call Types	13,863
	LGN101699 General Regulatory Services	12,482
	WSHM3G001 WSH U3 GBIR	12,211
	X00116794 Permitting and Regulatory Supp	11,801
	SOCIALMED Social Media Organization	11,773
	EDN103181 Ds Sep Ark-Anda	10,722
	PRK19GBIR O&M GBIR	9,568
	FHGENNERC FHG Gen NERC Compliance	9,459
	WSX110939 Environmental Serv -Distribut	9,319
	000001859 Greg/Rusk 8898 & 8899 non cap	9,154
	TRKBENVIR TRK BASE ENVIRON EXPENDITURES	9,034
	000011894 Energy Delivery Oil Analysis	8,246
	ECNMSCA01 TCOM-SCADA Program	8,212
	000002786 Simulator Learning Center O M	8,127
	ARS6SMAJR 6S TURB/GEN MAJOR	7,991
	X00116760 Chemical Engineering Services	7,985 7,715
	X00116764 Environmental Optimization Ser	7,713 7,104
	X00116803 Plant O&M Related Analyses ECNMTPT01 TCOM-Transport Program	6,587
	WSHMU0071 WSH U0 CCR RULE-O&M	6,197
	000001073 Regulated Fuels Admin	6,084
	ETN001007 Abd Proposal Estimate Preprtn	5,928
	X00116777 Infrastructure Inspection & As	5,650
	WSX114371 SWEPCO REO O M Staff Budget	5,309
	LGN101636 Corporate Financing	5,233
	LGN101645 Right Of Way/Easements	4,945
	000020779 Customer Web Inquiry	4,824
	ACTCARADM Activated Carbon	4,745
	000005325 Core Load Research Activity	4,531
	X00116759 CEMS Support Services (O&M)	4,526
	KXL5MM009 KXL U5 Generator Inspection	4,495
	GENOPEREX Gen Operational Excellence	4,063
	LGN101644 Property Sales	4,036
	ETN000159 Sep Distribution Station Overh	3,879
	LBM0MLRSO RSO LABOR	3,742
	LIMEADMIN Procure Lime for AEP Plants	3,326
	000012310 SEP LA Attach Serv Rentals	3,026
	ARSHU6BCO ARS Hill Unit 6 BCO	2,845
	TRKOVALVE TRK TURBINE MAIN & STOP VALVES	2,721
	ETN100257 TR/BATT Battery Insp Detailed	2,646
	CCRGWMONP Plant CCR GW Monitoring	2,594
	PRKMSTR01 SAFETY TEAM RECOMMENDATIONS	2,528
	LGN100970 General Contracts/Agreements	2,513
	KXL5MM005 KXL U5 Corrosion Fatigue	2,430
	ITPFP1421 Maximo Implementation	2,423
	TRKBCHEMS TRK BASE CHEMICALS	2,392
	PRK19M001 O&M OUTAGE < \$100K	2,350
	000001465 PK-Marshall South-Land 7700	2,289

AEPSC Department	Project ID/Description	Amount
	WSHMU3062 WSH U3 Boiler Tubes Drum WW	2,254
	X00116754 Landfill, Reservior Management	2,249
	LBM4FOROT U4 Forced Outage	2,204
	WSX109160 Arsenal Hill - Base Cost Of Op	2,073
	LBM0MECON Economizer Hair Pin Replace	1,969
	TURKRAIL2 New Turk Rail Access	1,939
	ECN103052 Dt Abd Telecom Projects	1,907
	TRKNWWATR TRK WASTE WATER TREATMENT PLT	1,871
	WSHMU1063 WSH U1 PSH and SH Repairs	1,861
	PRKOMPULV PULVERIZER MAINTENANCE	1,851
	000012311 SEP TX Attach Serv Rentals	1,834
	KXL5FK001 KXL U5 Forced Outages	1,782
	DCRESERCH CSC Direct Collections - Recon	1,777
	KXL5MM010 KXL U5 Heat Trace & Insulation	1,762
	WSHMU3063 WSH U3 PSH and SH Repairs	1,746
	000001585 O&M / Fuel Staff Project	1,737
	X00116802 Emissions Testing	1,650
	ARSU6ORMR ARS STALL UNIT ORM REQUIREMENT	1,589
	ETN000194 T Sep T Anda	1,556
	LGN101900 Tax - General	1,511
	ASHADMINS Ash Sales Administration	1,506
	KXL5MB017 KXL U5 Main Steam Attemperator	1,470
	ETN100220 Tr/Pagm Prop & Grnds Maint	1,459
	ARSCHEMCL ARSU5 CHEMICAL CLEAN	1,445
	ETN100223 Tr/Trns Tran-Cm Not Assoc/Pm	1,441
	ECNMPHV01 TCOM-Telephone/Video Program	1,405
		•
	KXL5MB001 KXL U5 GBIR Overhaul WLKM10019 U1 CONTROL VALVES	1,388
		1,379
	X00116804 Industrial Hygiene Analyses	1,367
	ANHYAMMON Procure Anhydrous Ammonia	1,361
	SSN100013 Ss Ed Distribution Nanda Proj	1,343
	LBM0MDOOR Boiler Doors	1,315
	FLC1G5784 PSH and SH Repairs	1,285
	TRKFBC000 TRK COAL YARD MISC	1,284
	EDN103182 Ds Sep Tx Anda	1,237
	OUTBNDCOM Outbound Communication	1,235
	ARSU6OUTG Arsenal Hill Unit 6 Outage	1,234
	CALBRMADM Procure Calcium Bromide	1,208
	BUSREV012 Business Process Review	1,196
	SSN100012 Ss Ed Trans Nanda Proj	1,187
	ETN100221 Tr/Cbns Cb-Cm Not Assoc W/Pm	1,132
	WSX109080 WSH U0 Base Cost Of Operations	1,117
	TRKNCYMIS TRK NOMI CY MISC MAINT	1,097
	TONNPMA01 TON NP Maintenance	1,094
	WSHMU1074 WSH U1 TURBINE VALVE INSP RPR	1,085
	WLKM10018 U1 MAIN STEAM STOP VALVE	1,074
	EDN102170 Ds/All/Dist ABD	1,071
	EON102461 Value Creation Non-Sever Reloc	994
	TRKBGRDS1 TRK NOMI GROUNDS MAINT LABOR	987
	LMSTADMIN Procure Limestone	969
	000003460 CSC Training-New Hire Classes	967
	ARS6OUTCL ARS6 OUTAGE CONTRACT LABOR	955
	WLKM10033 U1 BREAKER REBUILD	951
	ARSU5ORMR ARS ORM REQUIREMENTS	855
	ETN100213 Tr/Trip Relay Trip Check	846
	TRKNBLDGR TRK NOMI BLDG REPAIRS	808
	LBM0MOUTX Outage Combined	805
	BUSSOLUTN Tulsa Business Solutions	774
	WSX109127 Lieberman -Base Cost Of Operat	773
	WON 108 127 Lieueiman -base Cost Of Operat	113

AEPSC Department	Project ID/Description	Amount
	LGN102653 Video Web Design	773
	X00116790 Training	749
	TRKLEAN15 TRK LEAN 2015 WORK	746
	000022452 Engineering Structural Inspect	735
	LBM0DRAIN Drain System	735
	PRK13M011 O M Forced Outage	731
	TRKBMISCR TRK MISC REPAIRS	718
	ARS6GNRRO Stall Steam Turbine Val Repair	710
	PLANTREG4 Plant Eng Region 4 Support	709
	ETN100249 Tr/Tgom Undefined O&M Projects	689
	ARS6BHINS 6B HRSG INSPECTIONS	684
	TRKBRSOPL TRK RSO PLANT LABOR	657
	000005708 Ds SEP La-Anda	650
	TRKNSERV0 TRK NOMI MISC SERVICES	649
	TRKNSAFPF TRK SAFETY PLATFORMS	642
	000007487 SWEP/La/Dist Undg locates	637
	000007488 SWEP/Tx/Dist Undg Locates	637
	000007486 SWEP/Ark/Dist Undg Locates	637
	ETN000161 Sep-Tx Distribution Station Ov	631
	•	
	X00116800 Spill Remediation Support and	600
	LBM2FOROT U2 Forced Outage	596
	WLKN01006 NOMI Combine	594
	ARS6AHINS 6A HRSG INSPECTIONS/INSULATION	589
	WSHMU3081 WSH U3 FW HEATER AND FW SYSTEM	583
	TRKOBRSAM TRK OUTAGE BOILER TUBE SAMPLES	575
	TRKBMECH3 TRK BCO MECH 3 LABOR	547
	ETN100203 Tr/Tmmr Transformer Minor Reg	545
	TRKNSAFTY TRK NOMI SAFETY	543
	FLC1G5563 SH RH Repairs	525
	000014094 O M Forced Outage	518
	CULTURETR Culture Train Power up & Lead	505
	NGCCSTUDY Natural Gas Siting Study - CC	492
	X00116973 Title 316 (b) Project	479
	ARS56ETAX ARS/Stall 5&6 Electric Usage	478
	SSGSNANDA Shared Services-Accumulate Gen	473
	HWARRANTY Home Warranty Program	470
	TRKNRPLOW TRK ROTARY PLOWS 1 & 2	428
	WSX112283 Non-Billable Organizational Pi	415
	X00116796 Regulatory Development	408
	FLC041000 FLC BCO - Non-payroll	405
	ETN100235 Tr/Tlap Line Inspection	398
	ECNMMUL01 TCOM-MULTI Program	397
	•	388
	B194TXSRE T/SW/Non-Specific Work Station	
	ETN100227 Tr/Teem Electrical Equip Maint	386
	TRKNGENAX TRK N GENERATOR AND AUX SYSTEM	385
	000020544 SPP RE Compliance	357
	X00116750 Coal Pile Inventory Services (350
	TRKNMISCM TRK NOMI MISC MAINT	343
	ETN100253 Tr/Plce Power Line Carrier	334
	000004743 SWEP-TSectionalizing Program	330
	WLKM20043 U2 BREAKER REBUILD	311
	ETN100214 Tr/Calı Relay Calıbration	298
	WSHMU3085 WSH U3 TURB STM, CTRLS, AUX	298
	DMS19LA05 SW-LA/Valley/T'Storm 4-13-19	296
	000012309 SEP AK Attach Serv Rentals	282
	ARSU5GBIR U5 BOILER MAINTENANCE/INSPECTI	270
	2019NCOV1 2019-nCoV Planning & Response	266
	FLC1G1732 Economizer Repairs	264
	FLC1G1742 Routine Boiler Maintenance	260
	1 20 10 17 72 Noutine Doner Maintenance	200

AEPSC Department	Project ID/Description	Amount_
	000013139 FLC Boiler Riser Tubes	259
	ARS10U6GO ARS Unit 6 Routine Outage	253
	KXL5MB013 KXL U5 Hot Spot Repairs	249
	ETN100256 TR/TPDM Pred Diag Maint Proj	242
	KXL2FK001 KXL U2 Forced Outages	241
	ETN100210 Tr/Rt01 Station Inspection	240
	DMS19LA18 SW-LA/SHV/Thunderstorm 6-19-19	234
	ETN201102 NERC Relay Calibration	233
	DMS19LA19 SW-LA/SHV/Thunderstorm 6-23-19	229
	TONNPOP01 TON NP Operations	225
	X00116780 Metallurgical Failure Analysis	224
	PRK11M940 ENVIRO DIKES & BERMS	215
	EON102240 Supply Chain Value Creation	213
	000022545 Turk Procurement Activities	202
	WSX109112 Knox Lee -Base Cost Of Operati	200
	WSHFORC16 Welsh Forced Outage	194
	X00116758 Boiler Reliability Optimizatio	193
	WLKM30033 U3 BREAKER REBUILD	190
	B159LASRE D/SW/Non-SpeicificWork Station	188
	TRKBICE03 TRK BCO ICE 3 LABOR	184
	DMS20LA02 SW-LA/SHV/T'storm 1-11-2020	172
	TRKBPRMIT TRK BASE PERMITS & ENVIRONMENT	171
	ARS6BLTSA STALL 6B LTSA CT	163
	B194ARSRE T/SW/Non-Specific Work-Station	162
	FLCFGD814 Misc Routine Maintenance	159
	TRKBCOMIS TRK MISC EXPENSE	156
	DMS19LA09 SW-LA/Valley/T'storm 5-8-19	153
	WSHMU1075 WSH U1 CIRC WATER SYSTEM	149
	DMS19AR03 SW-ARFAYThunderstorm 5-1-19	148
	SSN100004 Ss Wholesale Other	143
	DMS19LA14 SW-LASHVThunderstorm 4-25-19	142
	DMS19LA24 SW-LA/SHV/T'storm 10-20-19	127
	ETN201301 Relay CT/PT Verification	125
	FLCU10063 FLC Misc Valve Repair	121
	LSTONESVY Limestone Pile Surveys	120
	DMS19LA16 SW-LA/SHV/Thunderstorm 5-8-19	84
	ETN100199 Trans - P C Direct Time	83
	DMS19LA12 SW-LASHVThunderstorm 4-18-19	72
	ETN100236 Tr/Tlci Comprehensive Inspect	70
	ETN201101 NERC Relay Trip Check	67
	ETN100204 Tr/Tmmn Transformer Minor Non	66
	TRKORENEQ TRK OUTAGE RENTAL EQUIPMENT	63
	TRKOROUTG TRK OMRO ROUTINE OUTAGE	60
	DMS20LA01 SW-LA/Valley/T'storm 1-11-2020	59
	PRK20GBIR O M GBIR	59 53
	TRKBICE01 TRK BCO ICE 1 LABOR	53
	WLKM10003 U1 ORM REQUIREMENT	51
	B194TXLRE T/SW/Non-Specific Work - Line A15706018 Lone Star Power Plant sub	49 47
	WLKM20008 U2 ORM REQUIREMENT	46
	WLKM30001 U3 ORM REQUIREMENT	46
	DIVINGOPS FHG Diving at the plants	45
	DMS19LA21 SW-LAValleyTstorm 10-20-19	43
	DMS19AR13 SW-AR/FAY/Wind 10-20-19	42
	DMS19AR13 SW-AR/PA1/Willd 10-20-19 DMS19LA22 SW-LASHVThunderstorm 10-3-19	42 41
	KXL0MM023 KXL Business Travel/Expenses	40
	ETN100202 Tr/Cbci Cb Complete Inspection	40
	ETN100202 Tricbic Cb Complete Inspection ETN100246 Tr/Tisa T-Line Structure Maint	35
	DMS19LA08 SW-LASHVThunderstorm 4-7-19	34
		U-7

AEPSC Department	Project ID/Description	Amoun
	A17031001 Tontitown Spare Prchse	:
	DMS19TX21 SW-TX/LGV/Thunderstorm 7-10-19	
	ETN100201 Tr/Cbei Cb External Inspection	;
	DMS19AR14 SW-ARTDWind 7-10-19	;
	DMS19AR05 SW-ARFAYThunderstorm 5-18-19	;
	B161TXSRE D/SW/Non-Specific Work Station	
	A18806031 Welsh breaker 11670 failure WLKFOU111 U 1 Forced Outage	
	Ç	
	DMS20LA03 SW-LA/Valley/T'storm 3-4-2020	
	DR18S01A5 Overhead Renewal Project - TX	
	ETN100225 Tr/Pcns P&C Non-Sched Repairs WSN100526 Comm Operations Staff Project	
	X00116801 Special Studies	
	ARSCTDUES LTSA Annual Dues	
	DMS19LA01 SW-LAValleyTstorm 4-7-19	
	CULTUREGR General Culture Initiative	
	X00116770 GBIR Outage and Support Servic	
	SWEHPITRN SWEPCO HPI Training	
	DR18S01A8 DA Distribution Line - Texas	
ief Executive Officer Total	DMS19LA06 SW-LASHVThunderstorm3-14-19	3,185,9
nief Financial Officer	FANANDA Activity NOT assoc with a PROJ	727,1
	BUSREV012 Business Process Review	30,0
	LGNANDA Legal/Policy/Cc Anda	18,3
	TRKOMISCM TRK OMRO MISC MAINTENANCE	11,1
	ETNANDA Transmission Anda	11,0
	000002524 PRK - BCO	10,3
	X00116816 Administrative Services Suppor	10,2
	X00116949 Rata Services (O&M)	9,3
	WSHM1G001 WSH U1 GBIR	8,7
	EON018181 Rate Case Support	8,0
	FLC054100 FLC BCO Non-Payroll	7,7
	000001072 Regulated Fuel Supply	7,3
	WSHM3G001 WSH U3 GBIR	5,4
	GLNANDA General Ledger Expense	5,1
	PRK19GBIR O&M GBIR	4,7
	X00116795 Day-to-Day Permit and Regulato	3,9
	LIMEADMIN Procure Lime for AEP Plants	3,7
	WSX110939 Environmental Serv -Distribut	3,1
	X00116794 Permitting and Regulatory Supp	2,7
	ARS6SMAJR 6S TURB/GEN MAJOR	2,6
	WSHMU0071 WSH U0 CCR RULE-0&M	2,0
	EDNANDA Distribution Anda Project	1,9
	SSSANANDA Accumulate Gen & Admin Securit	1,9
	LBM4FOROT U4 Forced Outage	1,7
	ARSHU6BCO ARS Hill Unit 6 BCO	1,7
	X00116782 Power Plant Operation Technica	1,6
	KXL5MM009 KXL U5 Generator Inspection	1,5
	WSHMU1063 WSH U1 PSH and SH Repairs	1,5
	KXL5MM010 KXL U5 Heat Trace & Insulation	1,5
	LBMOMLRSO RSO LABOR	1,5
	LBM0MECON Economizer Hair Pin Replace	1,3
	000001585 O&M / Fuel Staff Project	
	000001585 O&M / Fuel Staff Project	
	ITPFP1421 Maximo Implementation	1,2
	ITPFP1421 Maximo Implementation TRKOVALVE TRK TURBINE MAIN & STOP VALVES	1,2 1,2
	ITPFP1421 Maximo Implementation TRKOVALVE TRK TURBINE MAIN & STOP VALVES ACTCARADM Activated Carbon	1,3 1,2 1,2 1,2
	ITPFP1421 Maximo Implementation TRKOVALVE TRK TURBINE MAIN & STOP VALVES	1,2 1,2

AEPSC Department	Project ID/Description	Amount
	PRKMSTR01 SAFETY TEAM RECOMMENDATIONS	881
	WSHMU3062 WSH U3 Boiler Tubes Drum WW	868
	WSX109160 Arsenal Hill - Base Cost Of Op	838
	PRK19M001 O&M OUTAGE < \$100K	804
	WSX109104 WILKES -BASE COST OF OPERATION	791
	ARSU6OUTG Arsenal Hill Unit 6 Outage	786
	X00116750 Coal Pile Inventory Services (784
	WSHMU1074 WSH U1 TURBINE VALVE INSP RPR	718
	CCRGWMONP Plant CCR GW Monitoring	665
	WLKM10019 U1 CONTROL VALVES	652
	KXL5FK001 KXL U5 Forced Outages	642
	WSHMU3063 WSH U3 PSH and SH Repairs	617
	X00116754 Landfill, Reservior Management	607
	ETN100257 TR/BATT Battery Insp Detailed	569
	TRKNCYMIS TRK NOMI CY MISC MAINT	500
	ARSCHEMCL ARSU5 CHEMICAL CLEAN	462
	LBM0DRAIN Drain System	436
	TRKNBLDGR TRK NOMI BLDG REPAIRS	433
	ARS6OUTCL ARS6 OUTAGE CONTRACT LABOR	405
	KXL5MB017 KXL U5 Main Steam Attemperator	392
	LBM0MDOOR Boiler Doors	384
	WLKM10018 U1 MAIN STEAM STOP VALVE	372
	SSN100013 Ss Ed Distribution Nanda Proj	357
	WSX109127 Lieberman -Base Cost Of Operat	346
	FLC1G5784 PSH and SH Repairs	341
	TRKNWWATR TRK WASTE WATER TREATMENT PLT	340
	ETN100220 Tr/Pagm Prop & Grnds Maint	338
	ARS6AHINS 6A HRSG INSPECTIONS/INSULATION	337
	CHNANDA Chairman Anda	332
	KXL5MB001 KXL U5 GBIR Overhaul	332
	TRKBGRDS1 TRK NOMI GROUNDS MAINT LABOR	331
	ARSU6ORMR ARS STALL UNIT ORM REQUIREMENT	330
	ARS6GNRRO Stall Steam Turbine Val Repair	329
	ETN100223 Tr/Trns Tran-Cm Not Assoc/Pm	306
	TRKOBRSAM TRK OUTAGE BOILER TUBE SAMPLES	300
	SSN100012 Ss Ed Trans Nanda Proj	298
	000014094 O M Forced Outage	272
	PRK11M940 ENVIRO DIKES & BERMS	271
	TRKBMISCR TRK MISC REPAIRS	265
	LSTONESVY Limestone Pile Surveys	257
	TRKBRSOPL TRK RSO PLANT LABOR	251
	TRKLEAN15 TRK LEAN 2015 WORK	251
	000001073 Regulated Fuels Admin	250
	ETN100221 Tr/Cbns Cb-Cm Not Assoc W/Pm	248
	TRKNSAFPF TRK SAFETY PLATFORMS	246
	X00116800 Spill Remediation Support and	233
	ETN100253 Tr/Plce Power Line Carrier	221
	ETN100213 Tr/Trip Relay Trip Check	210
	TRKNRPLOW TRK ROTARY PLOWS 1 & 2	209
	ARSU5ORMR ARS ORM REQUIREMENTS	206
	WSHMU3081 WSH U3 FW HEATER AND FW SYSTEM	204
	ETN000159 Sep Distribution Station Overh	203
	TRKNMISCM TRK NOMI MISC MAINT	200
	ETN000161 Sep-Tx Distribution Station Ov	197
	X00116764 Environmental Optimization Ser	190
	TONNPMA01 TON NP Maintenance	185
		184 183

ETN100249 Tr/Tgom Undefined O&M Projects 164 000022545 Turk Procurement Activities 161 WLKM10033 U1 BREAKER REBUILD 159 WLKN01006 NOMI Combine 159 WSHMUJ3085 WSH U3 TURB STM, CTRLS, AUX 141 PRK13M011 O M Forced Outage 141 ETN100203 Tr/Tmm Transformer Minor Reg 132 CALBRMADM Procure Calcium Bromide 128 TRKBICE03 TRK BCO ICE 3 LABOR 127 X00116796 Regulatory Development 126 LBM0MOUTX Outage Combined 122 TRKNSERV0 TRK NOMI MISC SERVICES 116 PLANTREG4 Plant Eng Region 4 Support 111 WSX109112 Knox Lee - Base Cost Of Operati 108 ARS10U6GO ARS Unit 6 Routine Outage 102 FLC1G5563 Sh Rh Repairs 102 SGSNANDA Shared Services-Accumulate Gen 94 X00116759 CEMS Support Services (O&M) 94 TRKNGENAX TRK N GENERATOR AND AUX SYSTEM 90 LBM2FOROT U2 Forced Outage 89 TRKBMECH3 TRK BOO MECH 3 LABOR 85 TRKBPRMIT TRK BO MECH 3 LABOR 85 TRKBCOMIS TRK BOS MECH 3 LABOR 85 TRKBPRMIT TRK BOS MECH 3 LABOR 85 TRKBPRMIT TRK BO MECH 3 LABOR 85 TRKBPRMIT TRK BO MECH 3 LABOR 85 TRKBPCMIS STALL 6B LTSA CT 68 WLKM20043 U2 BREAKER REBUILD 58 TRKOROUTG TRK OUTAGE 57 TRKOROUTG TRK OUTAGE	AEPSC Department	Project ID/Description	Amount
000022545 Turk Procurement Activities 161		ARS6BHINS 6B HRSG INSPECTIONS	165
W.KM10036 NOM Combine		ETN100249 Tr/Tgom Undefined O&M Projects	164
W.K.NO1006 NOMI Combine WSHMU3085 WSH U3 TURB STM, CTRLS, AUX 141 PRK13M011 OM Forced Outage 141 ETN100203 Tr/Timm Transformer Minor Reg 132 CALERMADM Procure Calcium Bromde 122 TRKBIGE03 TRK BCO ICE 3 LABOR 127 X00116796 Regulatory Development 126 LBM0MOUTX Outage Combined 122 TRKNSERV0 TRK NOMI MISC SERVICES 116 PLANTREG4 Plant Eng Region 4 Support 111 WSX109112 Knox Lee -Base Cost Ol Operath 108 ARS104G0 ARS Unit 8 Routine Outage 102 FLC1G5503 SH RN Repairs 102 SSGSNANDA Shared Services-Accumulate Gen 34 X00116759 CEMS Support Services (OSM) 44 TRKNGENAX TRK N GENERATOR AND AUX SYSTEM 18ME/FORT 12 FORT OUT 12 FORT OUT 12 FORT OUT 12 FORT OUT 14 FORT OUT 1		000022545 Turk Procurement Activities	161
WSHMU3085		WLKM10033 U1 BREAKER REBUILD	159
PRK13M011		WLKN01006 NOMI Combine	159
ETN100203 Tr/Tmmr Transformer Minor Reg CALBRMADM Procure Calcium Bromide 122 TRKBICE03 TRK BCO ICE 3 LABOR 127 X00116796 Regulatory Development 126 LBM0MOUTX Outage Combiner 122 TRKNSERVO TRK NOMI MISC SERVICES 116 PLANTREGA PINE TRE REGULATE 4 Support 1111 WSX109112 Knox Lee - Base Cost Of Operati 108 ARS10U6CO ARS Unit Routine Outage 102 FLC165563 SH RIN Repairs 122 SSGSNANIDA Shared Services-Accumulate Gen 34 X00116759 CEM Support Services (O&M) 34 TRKNGENAX TRK N GENERATOR AND AUX SYSTEM 90 LBM2FOROT 122 Forced Outage 189 TRKBECHS TRK BCO MECH 3 LABOR 88 TRKBPRMIT TRK BASE PERMITS & ENVIRONMENT 92 WSHMU1075 WSH 11 CIRC WATER SYSTEM 71 TRKBCOMIS TRK MISC EXPENSE 98 ARSSBLTSA STALL 6B LTSA CT 98 WLKM2043 12 BREAKER REBUILD 58 TRKOROUTG TRK OMFO ROUTINE OUTAGE 57 TRKORENEO TRK Called Self Permits 6 Self Permits 7 Self Permits		WSHMU3085 WSH U3 TURB STM, CTRLS, AUX	141
CALBRMADM		PRK13M011 O M Forced Outage	141
TRKBICEO3		ETN100203 Tr/Tmmr Transformer Minor Reg	132
X00146796 Regulatory Development 126		CALBRMADM Procure Calcium Bromide	128
LBMMMOUTX		TRKBICE03 TRK BCO ICE 3 LABOR	127
TRKNSERVO		X00116796 Regulatory Development	126
PLANTREG4		LBM0MOUTX Outage Combined	122
WSX109112 Knox Lee - Base Cost Of Operati 108 ARS Unt6 GO ARS Unt 6 Routine Outage 102 FLC105559 SH RH Repairs 102 SCSSNANDA Shared Services-Accumulate Gen 94 X00116759 CEMS Support Services (O&M) 94 TRKNGENAX TRK N GENERATOR AND AUX SYSTEM 90 LBM2FOROT U2 Forced Outage 89 TRKBECHS TRK BOC MECH 3 LABOR 85 TRKBECHS TRK MISC SEXPENSE 69 ARSBELTSA STALL 6B LTSA CT 68 ARSBELTSA STALL 6B LTSA CT 68<		TRKNSERVO TRK NOMI MISC SERVICES	116
ARS10U6GO		PLANTREG4 Plant Eng Region 4 Support	111
FLC1G5563		WSX109112 Knox Lee -Base Cost Of Operati	108
SSGSNANDA Shared Services-Accumulate Gen X00116759 CEMS Support Services (O&M) 94 TRKNGENAX TRK N GEMERATOR AND AUX SYSTEM 90 TRKBPGONT U2 Forced Outage 89 TRKBPGMIT TRK BCO MECH 3 LABOR 85 TRKBPRMIT TRK BCO MECH 3 LABOR 85 TRKBPRMIT TRK BCO MECH 3 LABOR 86 TRKBPSMIT TRK BCO MECH 3 LABOR 86 TRKBPSMIT TRK BCO MECH 3 LABOR 87 WSH U1 CIRC WATER SYSTEM 71 TRK OCON TRK MISC EXPENSE 69 ARSBELTSA STALL 68 LTSA CT 68 WLKM20043 U2 BREAKER REBUILD 58 TRKOROUTG TRK OMRO ROUTINE OUTAGE 57 TRKORENED TRK OUTAGE RENTAL EQUIPMENT 54 WSX199080 WSH U0 Base Cost Of Operations 54 ETN201102 NERC Relay Calibration 54 TRXORLIVE NERC Relay Calibration 54 MSY AND AND AND AND AND AND AND AND AND AND AND		ARS10U6GO ARS Unit 6 Routine Outage	102
X00116759 CEMS Support Services (O&M) 94 TRKNGENAX TRK N GENERATOR AND AUX SYSTEM 90 LBM2FOROT U2 Forced Outage 89 TRKBMECH3 TRK BOO MECH 3 LABOR 85 TRKBPRMIT TRK BASE PERMITS & ENVIRONMENT 82 WSHMU1075 WSH U1 (CRC WATER SYSTEM 71 TRKBCOMIS TRK MISC EXPENSE 69 ARS6BLTSA STALL 6B LTSA CT 68 ARS6BLTSA STALL 6B LTSA CT 68 WLKM20043 U2 BREAKER REBUILD 58 TRKORENED TRK OMRO ROUTINE OUTAGE 57 TRKORENED TRK OUTAGE RENTAL EQUIPMENT 54 WSX109080 WSH U0 Base Cost Of Operations 54 ETN201102 NERC Relay Calibration 54 000005442 CSC Call Center Support 53 ANHYAMMON Procure Anhydrous Ammonia 47 NGCCSTUDY Natural Gas Sting Study - CC 43 X00116760 Chemical Engineering Services 43 SSN100004 Ss Wholesale Other 41 KXL2FK001 KXL U2 Forced Outages 41 LMSTADMIN Procure Limestone 41 B159LASE D/SW/Mon-SpecificWork Station 40 ETN100210 Tr/Rt01 Station Inspection 40 ASHADMINS Ash Sales Administration 39 KXL MSH DAMS KXL U5 Hot Spot Repairs 37 000013139 KLU U5 Hot Spot Repairs 38 ARSU5GBIR U5 BOILER MAINTENANCE/INSPECTI 38 FLC1G1732 Cenomizer Repairs 37 000013139 FLC Boiler Riser Tubes 36 FLC1G1742 Routine Boiler Maintenance 36 B194ARSRE T/SW/Non-Specific Work-Station 39 CLC Glier Riser Tubes 36 CLC Glier Riser Tubes 37 CNO116777 Trift Call Relay Calibration 28 ETN100215 Tr/Tap Line Inspection 28 ETN100217 Tr/Cell Relay Calibration 28 ETN100227 Tr/Teem Electrical Equip Maint 23 KXL USH DOUT Tr/Cell Relay Calibration 28 ETN100227 Tr/Teem Electrical Equip Maint 23 ENN103182 DS Sep TX Anda 23		FLC1G5563 SH RH Repairs	102
TRKNGENAX		SSGSNANDA Shared Services-Accumulate Gen	94
TRKNGENAX			94
LBM2FOROT U2 Forced Outage 89 TRKBMECH3 TRK BCO MECH3 LABOR 85 TRKBPMECH3 TRK BCO MECH3 LABOR 85 TRKBPMIT TRK BSE PERMITS & ENVIRONMENT 82 WSHMU1075 WSH U1 CIRC WATER SYSTEM 71 TRKBCOMIS TRK MISC EXPENSE 69 ARSBEITSA STALL 6B LTSA CT 68 WLKM20043 U2 BREAKER REBUILD 58 TRKOROUTG TRK OMRO ROUTINE OUTAGE 57 TRKOROUTG TRK OMRO ROUTINE OUTAGE 57 TRKORENEG TRK OUTAGE RENTAL EQUIPMENT 54 WSX109080 WSH U0 Base Cost Of Operations 54 ETN201102 NERC Relay Calibration 54 O00005442 CSC Call Center Support 53 ANHYAMMON Procure Anhydrous Ammonia 47 NGCCSTUDY Natural Cas Sting Study - CC 43 X00116760 Chemical Engineering Services 43 SSN100004 Ss Wholesale Other 41 KXL2FK001 KXL U2 Forced Outages 41 LMSTADMIN Procure Limestone 41 KXL2FK001 Tr/K01 Station Inspection 40 ASHADMINS AS Sales Administration 40 ASHADMINS AS Sales Administration 40 ASHADMINS KXL U5 Hot Spot Repairs 38 ARSUGGBIR U5 BOILER MAINTENANCE/INSPECTI 38 FLC161732 Economizer Repairs 36 FLC161742 Routine Boiler Maintenance 36 B194ARSRE T/SW/Non-Specific Work-Station 28 FLC161742 Routine Boiler Maintenance 36 B194ARSRE T/SW/Non-Specific Work-Station 28 ETN100214 Tr/Cali Relay Calibration 28 ETN100215 Tr/Gal Relay Calibration 28 ETN100215 Tr/Gal Relay Calibration 28 ETN100225 Tr/Tap Line Inspection 27 DIVINGOPS FHG Diving at the plants 27 X00116778 Boiler Reliability Optimizatio 25 Infrastructure Inspection 28 ETN100227 Tr/Teem Electrical Equip Maint 23 KXL LOMMOSS KXL Business Travel/Expenses 23 EDN103182 ES PTX Anda 23		* * * *	90
TRKBMECH3 TRK BO MECH 3 LABOR 85 TRKBPRMIT TRK BASE PERMITS & ENVIRONMENT 82 WSHMU1075 WH LO CIRC WATER SYSTEM 71 TRKBCOMIS TRK MISC EXPENSE 69 ARS6BLTSA STALL 6B LTSA CT 68 WLKM20043 U2 BREAKER REBUILD 58 TRKORCOUTG TRK OMRO ROUTINE OUTAGE 57 TRKORENEQ TRK OUTAGE RENTAL EQUIPMENT 54 WSX109080 WSH U0 Base Cost Of Operations 54 ETN201102 NERC Relay Calibration 54 000005442 CSC Call Center Support 53 ANHYAMMON Procure Anhydrous Ammonia 47 NGCCSTUDY Natural Gas Sting Study - CC 43 X00116760 Chemical Engineering Services 43 SSN100004 Ss Wholesale Other 41 KXLZFKO01 KXL U2 Forced Outages 41 LMSTADMIN Procure Limestone 41 B1594ASRE D/SWINOn-SpecificWork Station 40 ETN100210 Tr/Rt01 Station Inspection 40 <tr< td=""><td></td><td></td><td>89</td></tr<>			89
TRKBPRMIT		<u> </u>	85
WSHMU1075 WSH U1 CIRC WATER SYSTEM 71 TRKBCOMIS TRK MISC EXPENSE 69 ARS6BLTSA STALL 6B LTSA CT 68 WLKM20043 U2 BREAKER REBUILD 58 TRKOROUTG TRK OMRO ROUTINE OUTAGE 57 TRKORENEQ TRK OUTAGE RENTAL EQUIPMENT 54 WSX190908 WSH U0 Base Cost Of Operations 54 ETN201102 NERC Relay Calibration 54 000005442 CSC Call Center Support 53 ANHYMMON Procure Anhydrous Ammonia 47 NGCCSTUDY Natural Gas Siting Study - CC 43 X00116760 Chemical Engineering Services 43 SSN100004 Ss Wholesale Other 41 KXL 102 Forced Outages 41 LMSTADMIN Procure Limestone 41 B159LASRE D/SW/Non-SpecificWork Station 40 ETN100210 Tr/Rt01 Station Inspection 40 ASHADMINS Ash Sales Administration 39 KXL55BGIR U5 BOILER MAINTENANCE/INSPECTI 38 FLC Glo			82
ARS6BLTSA STALL 6B LTSA CT WLKM20043 U2 BREAKER REBUILD 58 TRKORENED TRK OMRO ROUTINE OUTAGE 57 TRKORENED TRK OMRO ROUTINE OUTAGE 57 TRKORENED TRK OUTAGE RENTAL EQUIPMENT 54 WSX19080 WSH U0 Base Cost Of Operations 54 ETN201102 NERC Relay Calibration 54 O00005442 CSC Call Center Support 53 ANHYAMMON Procure Anhydrous Ammonia 47 NGCCSTUDY Natural Gas Sting Study - CC 43 X00116760 Chemical Engineering Services 43 SSN100004 Ss Wholesale Other 41 KXL2FK001 KXL U2 Forced Outages 41 LMSTADMIN Procure Limestone 41 B159LASRE D/SW/Non-Specific/Work Station 40 ETN100210 Tr/Rt01 Station Inspection 40 ASHADMINS Ash Sales Administration 39 KXL5MB013 KXL U5 Hot Spot Repairs 38 ARSU5GBIR U5 BOILER MAINTENANCE/INSPECTI 38 FLC 161732 Economizer Repairs 37 000013139 FLC Boiler Riser Tubes 36 FLC1G1742 Rottine Boiler Maintenance 36 B194ARSRE T/SW/Non-Specific Work-Station 35 WLKM30033 U3 BREAKER REBUILD 31 ETN201301 Relay C1/PT Verification 28 ETN100215 Tr/Clar Relay Calibration 28 ETN100275 Tr/Clar Relay Calibration 28 Tr/Tlap Line Inspection 4A SUDINGOPS FHG Diving at the plants 27 X00116776 TRK OMN SAFETY 18K NOMI SAFETY 25 ETN100277 Tr/Teem Electrical Equip Maint 23 XXL Business Trave/Expenses 23 EDN103182 DS Sep Tx Anda 23			71
ARS6BLTSA STALL 6B LTSA CT WLKM20043 U2 BREAKER REBUILD 58 TRKORENED TRK OMRO ROUTINE OUTAGE 57 TRKORENED TRK OMRO ROUTINE OUTAGE 57 TRKORENED TRK OUTAGE RENTAL EQUIPMENT 54 WSX19080 WSH U0 Base Cost Of Operations 54 ETN201102 NERC Relay Calibration 54 O00005442 CSC Call Center Support 53 ANHYAMMON Procure Anhydrous Ammonia 47 NGCCSTUDY Natural Gas Sting Study - CC 43 X00116760 Chemical Engineering Services 43 SSN100004 Ss Wholesale Other 41 KXL2FK001 KXL U2 Forced Outages 41 LMSTADMIN Procure Limestone 41 B159LASRE D/SW/Non-Specific/Work Station 40 ETN100210 Tr/Rt01 Station Inspection 40 ASHADMINS Ash Sales Administration 39 KXL5MB013 KXL U5 Hot Spot Repairs 38 ARSU5GBIR U5 BOILER MAINTENANCE/INSPECTI 38 FLC 161732 Economizer Repairs 37 000013139 FLC Boiler Riser Tubes 36 FLC1G1742 Rottine Boiler Maintenance 36 B194ARSRE T/SW/Non-Specific Work-Station 35 WLKM30033 U3 BREAKER REBUILD 31 ETN201301 Relay C1/PT Verification 28 ETN100215 Tr/Clar Relay Calibration 28 ETN100275 Tr/Clar Relay Calibration 28 Tr/Tlap Line Inspection 4A SUDINGOPS FHG Diving at the plants 27 X00116776 TRK OMN SAFETY 18K NOMI SAFETY 25 ETN100277 Tr/Teem Electrical Equip Maint 23 XXL Business Trave/Expenses 23 EDN103182 DS Sep Tx Anda 23		TRKBCOMIS TRK MISC EXPENSE	69
WLKM20043 U2 BREAKER REBUILD 58		ARS6BLTSA STALL 6B LTSA CT	68
TRKOROUTG TRK OMRO ROUTINE OUTAGE 57 TRKORENEQ TRK OUTAGE RENTAL EQUIPMENT 54 WSX109080 WSH U0 Base Cost Of Operations 54 ETN201102 NERC Relay Calibration 54 000005442 CSC Call Center Support 53 ANHYAMMON Procure Anhydrous Ammonia 47 NGCCSTUDY Natural Gas Siting Study - CC 43 X00116760 Chemical Engineering Services 43 SSN100004 Ss Wholesale Other 41 KXL2FK001 KXL U2 Forced Outages 41 LMSTADMIN Procure Limestone 41 B159LASRE D/SW/Non-SpecificWork Station 40 ASHADMINS Ash Sales Administration 39 KXL5MB013 KXL U5 Hot Spot Repairs 38 ARSU5GBIR U5 BOILER MAINTENANCE/INSPECTI 38 FLC1G1732 Economizer Repairs 37 000013139 FLC Boiler Riser Tubes 36 FLC1G1742 Routine Boiler Maintenance 36 B194ARSSE T/SW/Non-Specific Work-Station			58
TRKORENEQ TRK OUTAGE RENTAL EQUIPMENT 54 WSX109080 WSH U0 Base Cost Of Operations 54 ETN201102 NERC Relay Calibration 54 000005442 CSC Call Center Support 53 ANHYAMMON Procure Anhydrous Ammonia 47 NGCCSTUDY Natural Gas Siting Study - CC 43 X00116760 Chemical Engineering Services 43 SSN100004 Ss Wholesale Other 41 KXL2FK001 KXL U2 Forced Outages 41 LMSTADMIN Procure Limestone 41 ETN100210 Tri/Rt01 Station Inspection 40 ASHADMINS Ash Sales Administration 39 KXL5MB013 KXL U5 Hot Spot Repairs 38 ARSU5GBIR U5 BOILER MAINTENANCE/INSPECTI 38 ARSU5GBIR EConomizer Repairs 37 000013139 FLC Boiler Riser Tubes 36 FLC1G1742 Routine Boiler Maintenance 36 B194ARSRE T/SW/Non-Specific Work-Station 35 WLKM30033 U3 BREAKER REBUILD 31			57
WSX109080 WSH U0 Base Cost Of Operations 54 ETN201102 NERC Relay Calibration 54 000005442 CSC Call Center Support 53 ANHYAMMON Procure Anhydrous Ammonia 47 NGCCSTUDY Natural Gas Siting Study - CC 43 X00116760 Chemical Engineering Services 43 SSN100004 Ss Wholesale Other 41 KXL2FK001 KXL U2 Forced Outages 41 LMSTADMIN Procure Limestone 41 B159LASRE D/SW/Non-SpecificWork Station 40 ETM100210 Tr/Rik10 Station Inspection 40 ASHADMINS Ash Sales Administration 39 KXL5MB013 KXL U5 Hot Spot Repairs 38 ARSU5GBIR U5 BOILER MAINTENANCE/INSPECTI 38 FLC1G1732 Economizer Repairs 37 000013139 FLC Boiler Riser Tubes 36 FLC1G1742 Routine Boiler Maintenance 36 FLC1G1742 Routine Boiler Maintenance 36 WLKM30033 U3 BREAKER REBUILD 31			54
ETN201102 NERC Relay Calibration 54 000005442 CSC Call Center Support 53 ANHYAMMON Procure Anhydrous Ammonia 47 NGCCSTUDY Natural Gas Siting Study - CC 43 X00116760 Chemical Engineering Services 43 SSN100004 Ss Wholesale Other 41 KXL2FK001 KXL U2 Forced Outages 41 LMSTADMIN Procure Limestone 41 B159LASRE D/SW/Non-SpeicificWork Station 40 ETN100210 Tir/Rt01 Station Inspection 40 ASHADMINS Ash Sales Administration 39 KXL5MB013 KXL U5 Hot Spot Repairs 38 ARSU5GBIR U5 BOILER MAINTENANCE/INSPECTI 38 FLC1G1732 Rounnier Repairs 37 000013139 FLC Boiler Riser Tubes 36 FLC161742 Routine Boiler Maintenance 36 B194ARSRE T/SW/Non-Specific Work-Station 35 WLKM30033 U3 BREAKER REBUILD 31 ETN100214 Tr/Cali Relay Calibration 28			54
000005442 CSC Call Center Support 53 ANHYAMMON Procure Anhydrous Ammonia 47 NGCCSTUDY Natural Gas Siting Study - CC 43 X00116760 Chemical Engineering Services 43 SSN100004 Ss Wholesale Other 41 KXL2FK001 KXL U2 Forced Outages 41 LMSTADMIN Procure Limestone 41 B159LASRE D/SW/Non-SpecificWork Station 40 ASHADMINS Ash Sales Administration 39 KXL5MB013 KXL U5 Hot Spot Repairs 38 ARSU5GBIR U5 BOILER MAINTENANCE/INSPECTI 38 FLC1G1742 Routine Boiler Riser Tubes 36 FLC1G1742 Routine Boiler Maintenance 36 B194ARSRE T/SW/Non-Specific Work-Station 35 WLKM30033 U3 BREAKER REBUILD 31 ETN100214 Tr/Cali Relay Calibration 28 ETN100225 Tr/Cali Relay Calibration 28 ETN100275 FHG Diving at the plants 27 X00116758 Boiler Reliability Optimizatio		•	54
ANHYAMMON Procure Anhydrous Ammonia 47 NGCCSTUDY Natural Gas Siting Study - CC 43 X00116760 Chemical Engineering Services 43 SSN100004 Sw Wholesale Other 41 KXL2FK001 KXL U2 Forced Outages 41 LMSTADMIN Procure Limestone 41 B159LASRE D/SW/Non-SpecificWork Station 40 ETN100210 Tr/Rt01 Station Inspection 40 ASHADMINS Ash Sales Administration 39 KXL5MB013 KXL U5 Hot Spot Repairs 38 ARSU5GBIR U5 BOILER MAINTENANCE/INSPECTI 38 FLC 161732 Economizer Repairs 37 000013139 FLC Boiler Riser Tubes 36 FLC1G1742 Routine Boiler Maintenance 36 B194ARSRE T/SW/Non-Specific Work-Station 35 WLKM3003 U3 BREAKER REBUILD 31 ETN201301 Relay CT/PT Verification 28 ETN100214 Tr/Call Relay Calibration 28 ETN100215 Tr/Tlap Line Inspection 27 DIVINGOPS FHG Diving at the plants 27 X00116758 Boiler Reliability Optimizatio 25 X00116777 TRKNSAFTY TRK NOMI SAFETY 25 ETN100227 Tr/Tem Electrical Equip Maint 23 KXL Business Travel/Expenses 23 EDN103182 Ds Sep Tx Anda 23		·	
NGCCSTUDY Natural Gas Siting Study - CC 43 X00116760 Chemical Engineering Services 43 SSN100004 Ss Wholesale Other 41 KXL2FK001 KXL U2 Forced Outages 41 LMSTADMIN Procure Limestone 41 B159LASRE D/SW/Non-Speicific/Work Station 40 ETN100210 Tr/Rt01 Station Inspection 40 ASHADMINS Ash Sales Administration 39 KXLSMB013 KXL U5 Hot Spot Repairs 38 ARSU5GBIR U5 BOILER MAINTENANCE/INSPECTI 38 FLC1G1732 Economizer Repairs 37 000013139 FLC Boiler Riser Tubes 36 FLC1G1742 Routine Boiler Maintenance 36 FLC1G1742 Routine Boiler Maintenance 36 WLKM30033 U3 BREAKER REBUILD 31 ETN201301 Relay CT/PT Verification 28 ETN100214 Tr/Call Relay Calibration 28 ETN100225 Tr/Tlap Line Inspection 27 X00116758 Boiler Reliability Optimizatio 25 <td></td> <td>••</td> <td></td>		••	
X00116760 Chemical Engineering Services 43		•	
SSN100004 Ss Wholesale Other 41 KXL2FK001 KXL U2 Forced Outages 41 LMSTADMIN Procure Limestone 41 B159LASRE D/SW/Non-SpeicificWork Station 40 ETN100210 Tr/Rt01 Station Inspection 40 ASHADMINS Ash Sales Administration 39 KXL5MB013 KXL U5 Hot Spot Repairs 38 ARSU5GBIR U5 BOILER MAINTENANCE/INSPECTI 38 FLC1G1732 Economizer Repairs 37 000013139 FLC Boiler Riser Tubes 36 FLC1G1742 Routine Boiler Maintenance 36 B194ARSRE T/SW/Non-Specific Work-Station 35 WLKM30033 U3 BREAKER REBUILD 31 ETN201301 Relay CT/PT Verification 28 ETN100214 Tr/Cali Relay Calibration 28 ETN100235 Tr/Tlap Line Inspection 27 NO0116775 Infrastructure Inspection & As 25 TRKNSAFTY TRK NOMI SAFETY 25 ETN100227 Tr/Teem Electrical Equip Maint 23 KXL DMM023 KXL Business Travel/Expenses 23 <		* *	
KXL2FK001 KXL U2 Forced Outages 41 LMSTADMIN Procure Limestone 41 B159LASRE D/SW/Non-SpecificWork Station 40 TT/Rt01 Station Inspection 40 ASHADMINS Ash Sales Administration 39 KXL5MB013 KXL U5 Hot Spot Repairs 38 ARSU5GBIR U5 BOILER MAINTENANCE/INSPECTI 38 FLC1G1732 Economizer Repairs 37 000013139 FLC Boiler Riser Tubes 36 FLC1G1742 Routine Boiler Maintenance 36 B194ARSRE T/SW/Non-Specific Work-Station 35 WLKM30033 U3 BREAKER REBUILD 31 ETN201301 Relay CT/PT Verification 28 ETN100214 Tr/Cali Relay Calibration 28 ETN100235 Tr/Tlap Line Inspection 27 X00116758 Boiler Reliability Optimizatio 25 X00116777 Infrastructure Inspection & As 25 TRKNSAFTY TRK NOMI SAFETY 25 ETN100227 Tr/Teem Electrical Equip Maint 23 KXL Business Travel/Expenses 23 DS Sep Tx Anda </td <td></td> <td></td> <td></td>			
LMSTADMIN B159LASRE D/SW/Non-SpeicficWork Station 40 ETN100210 Tr/Rt01 Station Inspection 40 ASHADMINS Ash Sales Administration 39 KXL5MB013 KXL U5 Hot Spot Repairs 38 ARSU5GBIR LC1G1732 U5 BOILER MAINTENANCE/INSPECTI 38 FLC1G1732 Economizer Repairs 37 000013139 FLC Boiler Riser Tubes 36 FLC1G1742 Routine Boiler Maintenance 36 B194ARSRE T/SW/Non-Specific Work-Station 35 WLKM30033 U3 BREAKER REBUILD 31 ETN201301 Relay CT/PT Verification 28 ETN100214 Tr/Cali Relay Calibration 28 ETN100235 Tr/Tlap Line Inspection 27 DIVINGOPS FHG Diving at the plants 27 X00116779 Infrastructure Inspection & As 25 TRKNSAFTY TRK NOMI SAFETY 25 ETN100227 Tr/Teem Electrical Equip Maint 23 KXL Business Travel/Expenses 23 DS Sep Tx Anda 23			
B159LASRE D/SW/Non-SpeicificWork Station 40		•	
ETN100210 Tr/Rt01 Station Inspection 40 ASHADMINS Ash Sales Administration 39 KXL5MB013 KXL U5 Hot Spot Repairs 38 ARSU5GBIR U5 BOILER MAINTENANCE/INSPECTI 38 FLC1G1732 Economizer Repairs 37 000013139 FLC Boiler Riser Tubes 36 FLC1G1742 Routine Boiler Maintenance 36 FLC1G1742 Routine Boiler Maintenance 36 B194ARSRE T/SW/Non-Specific Work-Station 35 WLKM30033 U3 BREAKER REBUILD 31 ETN201301 Relay CT/PT Verification 28 ETN100214 Tr/Cali Relay Calibration 28 ETN100235 FHG Diving at the plants 27 X00116758 Boiler Reliability Optimizatio 25 X00116777 Infrastructure Inspection & As 25 TRKNSAFTY TRK NOMI SAFETY 25 ETN100227 Tr/Teem Electrical Equip Maint 23 KXL Business Travel/Expenses 23 DN Sep Tx Anda 23			
ASHADMINS Ash Sales Administration 39 KXL5MB013 KXL U5 Hot Spot Repairs 38 ARSU5GBIR U5 BOILER MAINTENANCE/INSPECTI 38 FLC1G1732 Economizer Repairs 37 000013139 FLC Boiler Riser Tubes 36 FLC1G1742 Routine Boiler Maintenance 36 B194ARSRE T/SW/Non-Specific Work-Station 35 WLKM30033 U3 BREAKER REBUILD 31 ETN201301 Relay CT/PT Verification 28 ETN100214 Tr/Cali Relay Calibration 28 ETN100235 Tr/Tlap Line Inspection 27 DIVINGOPS FHG Diving at the plants 27 X00116758 Boiler Reliability Optimizatio 25 X00116777 Infrastructure Inspection & As 25 TRKNSAFTY TRK NOMI SAFETY 25 ETN100227 Tr/Teem Electrical Equip Maint 23 KXL0MM023 KXL Business Travel/Expenses 23 EDN103182 Ds Sep Tx Anda 23			
KXL5MB013 KXL U5 Hot Spot Repairs 38 ARSU5GBIR U5 BOILER MAINTENANCE/INSPECTI 38 FLC1G1732 Economizer Repairs 37 000013139 FLC Boiler Riser Tubes 36 FLC1G1742 Routine Boiler Maintenance 36 B194ARSRE T/SW/Non-Specific Work-Station 35 WLKM30033 U3 BREAKER REBUILD 31 ETN201301 Relay CT/PT Verification 28 ETN100214 Tr/Cali Relay Calibration 28 ETN100235 Tr/Tlap Line Inspection 27 DIVINGOPS FHG Diving at the plants 27 X00116758 Boiler Reliability Optimizatio 25 X00116777 Infrastructure Inspection & As 25 TRKNSAFTY TRK NOMI SAFETY 25 ETN100227 Tr/Teem Electrical Equip Maint 23 KXL0MM023 KXL Business Travel/Expenses 23 EDN103182 Ds Sep Tx Anda 23		·	
ARSU5GBIR U5 BOILER MAINTENANCE/INSPECTI 38 FLC1G1732 Economizer Repairs 37 000013139 FLC Boiler Riser Tubes 36 FLC1G1742 Routine Boiler Maintenance 36 B194ARSRE T/SW/Non-Specific Work-Station 35 WLKM30033 U3 BREAKER REBUILD 31 ETN201301 Relay CT/PT Verification 28 ETN100214 Tr/Cali Relay Calibration 28 ETN100235 Tr/Tlap Line Inspection 27 DIVINGOPS FHG Diving at the plants 27 X00116758 Boiler Reliability Optimizatio 25 X00116777 Infrastructure Inspection & As 25 TRKNSAFTY TRK NOMI SAFETY 25 ETN100227 Tr/Teem Electrical Equip Maint 23 KXL0MM023 KXL Business Travel/Expenses 23 DN103182 Ds Sep Tx Anda 23			
FLC1G1732 Economizer Repairs 37 000013139 FLC Boiler Riser Tubes 36 FLC1G1742 Routine Boiler Maintenance 36 B194ARSRE T/SW/Non-Specific Work-Station 35 WLKM30033 U3 BREAKER REBUILD 31 ETN201301 Relay CT/PT Verification 28 ETN100214 Tr/Cali Relay Calibration 28 ETN100235 Tr/Tlap Line Inspection 27 DIVINGOPS FHG Diving at the plants 27 X00116758 Boiler Reliability Optimizatio 25 X00116777 Infrastructure Inspection & As 25 TRKNSAFTY TRK NOMI SAFETY 25 ETN100227 Tr/Teem Electrical Equip Maint 23 KXL0MM023 KXL Business Travel/Expenses 23 EDN103182 Ds Sep Tx Anda 23			
000013139 FLC Boiler Riser Tubes 36 FLC1G1742 Routine Boiler Maintenance 36 B194ARSRE T/SW/Non-Specific Work-Station 35 WLKM30033 U3 BREAKER REBUILD 31 ETN201301 Relay CT/PT Verification 28 ETN100214 Tr/Cali Relay Calibration 28 ETN100235 Tr/Tlap Line Inspection 27 DIVINGOPS FHG Diving at the plants 27 X00116758 Boiler Reliability Optimizatio 25 X00116777 Infrastructure Inspection & As 25 TRKNSAFTY TRK NOMI SAFETY 25 ETN100227 Tr/Teem Electrical Equip Maint 23 KXL0MM023 KXL Business Travel/Expenses 23 DN103182 Ds Sep Tx Anda 23			
FLC1G1742 Routine Boiler Maintenance 36 B194ARSRE T/SW/Non-Specific Work-Station 35 WLKM30033 U3 BREAKER REBUILD 31 ETN201301 Relay CT/PT Verification 28 ETN100214 Tr/Cali Relay Calibration 28 ETN100235 Tr/Tlap Line Inspection 27 DIVINGOPS FHG Diving at the plants 27 X00116758 Boiler Reliability Optimizatio 25 X00116777 Infrastructure Inspection & As 25 TRKNSAFTY TRK NOMI SAFETY 25 ETN100227 Tr/Teem Electrical Equip Maint 23 KXL0MM023 KXL Business Travel/Expenses 23 DN Sep Tx Anda 23		•	
B194ARSRE T/SW/Non-Specific Work-Station 35 WLKM30033 U3 BREAKER REBUILD 31 ETN201301 Relay CT/PT Verification 28 ETN100214 Tr/Call Relay Calibration 28 ETN100235 Tr/Tlap Line Inspection 27 DIVINGOPS FHG Diving at the plants 27 X00116758 Boiler Reliability Optimizatio 25 X00116777 Infrastructure Inspection & As 25 TRKNSAFTY TRK NOMI SAFETY 25 ETN100227 Tr/Teem Electrical Equip Maint 23 KXL0MM023 KXL Business Travel/Expenses 23 DN Sep Tx Anda 23			
WLKM30033 U3 BREAKER REBUILD 31 ETN201301 Relay CT/PT Verification 28 ETN100214 Tr/Call Relay Calibration 28 ETN100235 Tr/Tlap Line Inspection 27 DIVINGOPS FHG Diving at the plants 27 X00116758 Boiler Reliability Optimizatio 25 X00116777 Infrastructure Inspection & As 25 TRKNSAFTY TRK NOMI SAFETY 25 ETN100227 Tr/Teem Electrical Equip Maint 23 KXL0MM023 KXL Business Travel/Expenses 23 DS Sep Tx Anda 23			
ETN201301 Relay CT/PT Verification 28 ETN100214 Tr/Call Relay Calibration 28 ETN100235 Tr/Tlap Line Inspection 27 DIVINGOPS FHG Diving at the plants 27 X00116758 Boiler Reliability Optimizatio 25 X00116777 Infrastructure Inspection & As 25 TRKNSAFTY TRK NOMI SAFETY 25 ETN100227 Tr/Teem Electrical Equip Maint 23 KXL0MM023 KXL Business Travel/Expenses 23 EDN103182 Ds Sep Tx Anda 23		,	
ETN100214 Tr/Call Relay Calibration 28 ETN100235 Tr/Tlap Line Inspection 27 DIVINGOPS FHG Diving at the plants 27 X00116758 Boiler Reliability Optimizatio 25 X00116777 Infrastructure Inspection & As 25 TRKNSAFTY TRK NOMI SAFETY 25 ETN100227 Tr/Teem Electrical Equip Maint 23 KXL0MM023 KXL Business Travel/Expenses 23 EDN103182 Ds Sep Tx Anda 23			
ETN100235 Tr/Tlap Line Inspection 27 DIVINGOPS FHG Diving at the plants 27 X00116758 Boiler Reliability Optimizatio 25 X00116777 Infrastructure Inspection & As 25 TRKNSAFTY TRK NOMI SAFETY 25 ETN100227 Tr/Teem Electrical Equip Maint 23 KXL0MM023 KXL Business Travel/Expenses 23 EDN103182 Ds Sep Tx Anda 23		•	
DIVINGOPS FHG Diving at the plants 27 X00116758 Boiler Reliability Optimizatio 25 X00116777 Infrastructure Inspection & As 25 TRKNSAFTY TRK NOMI SAFETY 25 ETN100227 Tr/Teem Electrical Equip Maint 23 KXL0MM023 KXL Business Travel/Expenses 23 EDN103182 Ds Sep Tx Anda 23		•	
X00116758 Boiler Reliability Optimizatio 25 X00116777 Infrastructure Inspection & As 25 TRKNSAFTY TRK NOMI SAFETY 25 ETN100227 Tr/Teem Electrical Equip Maint 23 KXL0MM023 KXL Business Travel/Expenses 23 EDN103182 Ds Sep Tx Anda 23		, ,	
X00116777 Infrastructure Inspection & As 25 TRKNSAFTY TRK NOMI SAFETY 25 ETN100227 Tr/Teem Electrical Equip Maint 23 KXL0MM023 KXL Business Travel/Expenses 23 EDN103182 Ds Sep Tx Anda 23			
TRKNSAFTY TRK NOMI SAFETY 25 ETN100227 Tr/Teem Electrical Equip Maint 23 KXL0MM023 KXL Business Travel/Expenses 23 EDN103182 Ds Sep Tx Anda 23		, ,	
ETN100227 Tr/Teem Electrical Equip Maint 23 KXL0MM023 KXL Business Travel/Expenses 23 EDN103182 Ds Sep Tx Anda 23		•	
KXL0MM023 KXL Business Travel/Expenses 23 EDN103182 Ds Sep Tx Anda 23			
EDN103182 Ds Sep Tx Anda 23		• •	
,		•	
AUUTTOOUZ EINISSIONS FESTING 23		•	
		AUUT 10002 ETHISSIONS TESTING	23

AEPSC Department	Project ID/Description	Amount
	TRKBENVIR TRK BASE ENVIRON EXPENDITURES	20
	WSHFORC16 Welsh Forced Outage	20
	X00116973 Title 316 (b) Project	19
	DMS20LA02 SW-LA/SHV/T'storm 1-11-2020	18
	WSX114371 SWEPCO REO O M Staff Budget	16
	X00116803 Plant O&M Related Analyses	13
	ECNMMUL01 TCOM-MULTI Program	13
	TRKBICE01 TRK BCO ICE 1 LABOR	12
	X00116780 Metallurgical Failure Analysis	10
	ETN100204 Tr/Tmmn Transformer Minor Non	10
	A17031001 Tontitown Spare Prchse	9
	PRK20GBIR O M GBIR	9
	ETN100201 Tr/Cbei Cb External Inspection	8
	WLKFOU111 U 1 Forced Outage	8
	ETN100202 Tr/Cbci Cb Complete Inspection	8
	000011894 Energy Delivery Oil Analysis	7
	TONNPOP01 TON NP Operations	6
	B161TXSRE D/SW/Non-Specific Work Station	6
	FLCU10063 FLC Misc Valve Repair	6
	X00116790 Training	4
	FLCFGD814 Misc Routine Maintenance	4
	TRKBCHEMS TRK BASE CHEMICALS	4
	OUTBNDCOM Outbound Communication	3
	X00116804 Industrial Hygiene Analyses	3
		3
	ETN100236 Tr/Tlci Comprehensive Inspect	2
	EDN103181 Ds Sep Ark-Anda	
	B194TXLRE T/SW/Non-Specific Work - Line	2
	X00116805 Environmental Analyses	1
	ETN100246 Tr/Tlsa T-Line Structure Maint	1
	WSX112283 Non-Billable Organizational Pl	1
	LGN102653 Video Web Design	1
	000020779 Customer Web Inquiry	C
	TDOANDA T And D Other Anda	0
hief Financial Officer Total		945,791
xternal Affairs	000005502 CSC - All Call Types	3,922,531
	BAOCOREBL BAO Core Billing	416,984
	CUSOVRFLW Call Center Overflow	371,882
	PAYOPTION Payment Option	360,354
	EDNANDA Distribution Anda Project	282,110
	EON018181 Rate Case Support	250,551
	000005442 CSC Call Center Support	243,962
	TDOANDA T And D Other Anda	177,625
	OUTCOLAGT Outside Collection Agent	106,205
	EON100347 Collections Support	97,920
	SOCIALMED Social Media Organization	95,117
	BAONONCOR BAO Non-Core Billing	66,432
	000005554 CSC Corpus - All Call Types	47,202
	EON102461 Value Creation Non-Sever Reloc	25,010
	000005325 Core Load Research Activity	18,956
	•	
	, ,	16,522
	OTGOVRFLW Call Center Outage Overflow	16,177
	EDN102170 Ds/All/Dist ABD	15,644
	ETN001007 Abd Proposal Estimate Preprtn	11,977
	000003460 CSC Training-New Hire Classes	9,545
	HWARRANTY Home Warranty Program	7,536
	, and the second se	
	000012311 SEP TX Attach Serv Rentals	7,479
	, and the second se	
	000012311 SEP TX Attach Serv Rentals	7,479 6,072 5,545

AEPSC Department	Project ID/Description	Amount
	LGN102653 Video Web Design	4,678
	OUTBNDCOM Outbound Communication	4,345
	EDN103181 Ds Sep Ark-Anda	4,161
	ETNANDA Transmission Anda	4,092
	BUSSOLUTN Tulsa Business Solutions	2,728
	EON102240 Supply Chain Value Creation	2,649
	LGNANDA Legal/Policy/Cc Anda	1,965
	ECN103052 Dt Abd Telecom Projects	1,573
	2019NCOV1 2019-nCoV Planning & Response	1,565
	ECODEVPOW Economic Develop Program Work	1,083
	LGN101699 General Regulatory Services	919
	EON103045 Customer Handbooks	846
	DMS19LA14 SW-LASHVThunderstorm 4-25-19	807
	000009896 CSC Safety Initiatives	494
	SSGSNANDA Shared Services-Accumulate Gen	377
	000012310 SEP LA Attach Serv Rentals	189
	DMS19LA06 SW-LASHVThunderstorm3-14-19	168
	000013576 Customer Reimbursements	144
	000012309 SEP AK Attach Serv Rentals	142
Parallel Control	DMS19LA02 SW-LA/SHV/Thunderstorm 1-19-19	1 ((47.248
External Affairs Total		6,617,218
Generation	X00116782 Power Plant Operation Technica X00116795 Day-to-Day Permit and Regulato	932,686
	X00116795 Day-to-Day Permit and Regulato 000001072 Regulated Fuel Supply	485,217 329,512
	X00116816 Administrative Services Suppor	302,882
	X00116949 Rata Services (O&M)	238,497
	000002524 PRK - BCO	193,259
	WSHM1G001 WSH U1 GBIR	191,142
	FLC054100 FLC BCO Non-Payroll	175,628
	WSHM3G001 WSH U3 GBIR	159,102
	TRKOMISCM TRK OMRO MISC MAINTENANCE	157,516
	PRK19GBIR O&M GBIR	116,851
	FHGENNERC FHG Gen NERC Compliance	114,931
	ARS6SMAJR 6S TURB/GEN MAJOR	110,284
	X00116805 Environmental Analyses	106,079
	000002786 Simulator Learning Center O M	97,999
	X00116760 Chemical Engineering Services	93,140
	X00116764 Environmental Optimization Ser	87,914
	WSX109104 WILKES -BASE COST OF OPERATION	85,098
	X00116794 Permitting and Regulatory Supp	73,958
	X00116777 Infrastructure Inspection & As	64,431
	FANANDA Activity NOT assoc with a PROJ	64,240
	WSX110939 Environmental Serv -Distribut	61,651
	TRKBENVIR TRK BASE ENVIRON EXPENDITURES	57,400
	WSX114371 SWEPCO REO O M Staff Budget	56,432
	000001073 Regulated Fuels Admin	55,846
	KXL5MM009 KXL U5 Generator Inspection	53,159
	000011894 Energy Delivery Oil Analysis	52,772
	LBM0MLRSO RSO LABOR	51,404
	GENOPEREX Gen Operational Excellence	48,336
	X00116759 CEMS Support Services (O&M)	47,131
	X00116803 Plant O&M Related Analyses	46,438
	ACTCARADM Activated Carbon	42,968
	WSHMU0071 WSH U0 CCR RULE-O&M	40,646
	PRKMSTR01 SAFETY TEAM RECOMMENDATIONS	36,320
	ARSHU6BCO ARS Hill Unit 6 BCO	35,319
	TRKOVALVE TRK TURBINE MAIN & STOP VALVES	34,658
	PRK19M001 O&M OUTAGE < \$100K	32,292
	WSHMU3062 WSH U3 Boiler Tubes Drum WW	28,956
	TO THE PROPERTY OF SOME PURPLE AND STATE AND S	20,000

AEPSC Department	Project ID/Description	Amount
	LIMEADMIN Procure Lime for AEP Plants	28,107
	X00116754 Landfill, Reservior Management	27,592
	KXL5MM005 KXL U5 Corrosion Fatigue	25,342
	TRKNWWATR TRK WASTE WATER TREATMENT PLT	24,390
	LBM4FOROT U4 Forced Outage	23,673
	PRKOMPULV PULVERIZER MAINTENANCE	23,378
	000001585 O&M / Fuel Staff Project	23,324
	WSX109160 Arsenal Hill - Base Cost Of Op	22,932
	LBM0MECON Economizer Hair Pin Replace	22,444
	WSHMU3063 WSH U3 PSH and SH Repairs	21,350
	KXL5FK001 KXL U5 Forced Outages	21,174
	ARSCHEMCL ARSU5 CHEMICAL CLEAN	20,682
	KXL5MM010 KXL U5 Heat Trace & Insulation	20,313
	WLKM10019 U1 CONTROL VALVES	20,191
	WSHMU1063 WSH U1 PSH and SH Repairs	18,858
	KXL5MB017 KXL U5 Main Steam Attemperator	18,163
	ARS6OUTCL ARS6 OUTAGE CONTRACT LABOR	17,705
	CCRGWMONP Plant CCR GW Monitoring	17,484
	FLC1G5784 PSH and SH Repairs	16,823
	ARSU6ORMR ARS STALL UNIT ORM REQUIREMENT	16,763
	WLKM10018 U1 MAIN STEAM STOP VALVE	16,309
	LBM0MDOOR Boiler Doors	16,279
	TRKBCHEMS TRK BASE CHEMICALS	15,589
	ARSU6OUTG Arsenal Hill Unit 6 Outage	15,572
	TURKRAIL2 New Turk Rail Access	14,851
	TRKNCYMIS TRK NOMI CY MISC MAINT	14,426
	FAN102853 Labor Accrual Project	14,036
	TRKBGRDS1 TRK NOMI GROUNDS MAINT LABOR	13,483
	ASHADMINS Ash Sales Administration	13,325
	X00116790 Training	13,311
	WLKM10033 U1 BREAKER REBUILD	13,239
	TRKFBCO00 TRK COAL YARD MISC	12,790
	ANHYAMMON Procure Anhydrous Ammonia	12,484
	KXL5MB001 KXL U5 GBIR Overhaul	12,224
	WSHMU1074 WSH U1 TURBINE VALVE INSP RPR	11,374
	TONNPMA01 TON NP Maintenance	11,330
	000022452 Engineering Structural Inspect	11,204
	TRKBMISCR TRK MISC REPAIRS	11,184
	CALBRMADM Procure Calcium Bromide	10,969
	TRKNBLDGR TRK NOMI BLDG REPAIRS	10,546
	LBM0MOUTX Outage Combined	10,340
	•	
	X00116802 Emissions Testing	10,017
	ITPFP1421 Maximo Implementation	9,749
	ARSU5ORMR ARS ORM REQUIREMENTS	9,670
	EDN103261 Ds-Sep-Ark-Hazardous Waste	9,606
	PRK13M011 O M Forced Outage	9,325
	WLKN01006 NOMI Combine	9,222
	LBM0DRAIN Drain System	9,030
	WSHMU3081 WSH U3 FW HEATER AND FW SYSTEM	8,984
	X00116804 Industrial Hygiene Analyses	8,925
	TRKNSERV0 TRK NOMI MISC SERVICES	8,923
	LMSTADMIN Procure Limestone	8,801
	TRKLEAN15 TRK LEAN 2015 WORK	8,377
	ARS6AHINS 6A HRSG INSPECTIONS/INSULATION	7,976
	ARS6GNRRO Stall Steam Turbine Val Repair	7,882
	TRKNSAFTY TRK NOMI SAFETY	7,605
	FLC1G5563 SH RH Repairs	7,561
	TRKNSAFPF TRK SAFETY PLATFORMS	7,499
	PLANTREG4 Plant Eng Region 4 Support	7,312
	LANTINEOT FIGHT ENGINEET Support	1,312

AEPSC Department	Project ID/Description	Amount
	TRKBMECH3 TRK BCO MECH 3 LABOR	6,871
	TRKBRSOPL TRK RSO PLANT LABOR	6,754
	WSX109080 WSH U0 Base Cost Of Operations	6,719
	WSN100526 Comm Operations Staff Project	6,621
	ARS6BHINS 6B HRSG INSPECTIONS	6,546
	TRKOBRSAM TRK OUTAGE BOILER TUBE SAMPLES	6,105
	LBM2FOROT U2 Forced Outage	5,759
	X00116824 NPDES Permit Renewals (O & M	5,605
	TRKNRPLOW TRK ROTARY PLOWS 1 & 2	5,581
	TRKNMISCM TRK NOMI MISC MAINT	5,503
	TRKNGENAX TRK N GENERATOR AND AUX SYSTEM	5,351
	X00116750 Coal Pile Inventory Services (4,432
	FLC1G1742 Routine Boiler Maintenance	4,170
	000014094 O M Forced Outage	4,166
	WLKM20043 U2 BREAKER REBUILD	4,156
	X00116800 Spill Remediation Support and	3,926
	FLC041000 FLC BCO - Non-payroll	3,901
	WSHMU3085 WSH U3 TURB STM, CTRLS, AUX	3,859
	WSX112283 Non-Billable Organizational PI	3,763
	WSX109127 Lieberman -Base Cost Of Operat	3,636
	ARSU5GBIR U5 BOILER MAINTENANCE/INSPECTI	3,543
	000013139 FLC Boiler Riser Tubes	3,490
	FLC1G1732 Economizer Repairs	3,435
	ARS10U6GO ARS Unit 6 Routine Outage	3,408
	KXL5MB013 KXL U5 Hot Spot Repairs	3,380
	NGCCSTUDY Natural Gas Siting Study - CC	3,359
	EON018181 Rate Case Support	3,216
	WSX109112 Knox Lee -Base Cost Of Operati	3,167
	WLKM30033 U3 BREAKER REBUILD	2,974
	X00116973 Title 316 (b) Project	2,882
	WSHFORC16 Welsh Forced Outage 000001859 Greg/Rusk 8898 & 8899 non cap	2,686
	FLCU10258 Small Tools and Equipment	2,663 2,635
	X00116796 Regulatory Development	2,588
	TRKBPRMIT TRK BASE PERMITS & ENVIRONMENT	2,588
	KXL2FK001 KXL U2 Forced Outages	2,457
	WSHMU1075 WSH U1 CIRC WATER SYSTEM	2,437
	ARS6BLTSA STALL 6B LTSA CT	2,224
	X00116780 Metallurgical Failure Analysis	2,142
	X00116758 Boiler Reliability Optimizatio	2,118
	TRKBICE03 TRK BCO ICE 3 LABOR	2,097
	PRK11M940 ENVIRO DIKES & BERMS	2,062
	TRKBCOMIS TRK MISC EXPENSE	2,022
	PROWEST01 West Plant Pro Reliability	1,713
	LSTONESVY Limestone Pile Surveys	1,679
	000022545 Turk Procurement Activities	1,601
	TONNPOP01 TON NP Operations	1,494
	KXL5MB006 KXL U5 Boiler Corrosn Fatigue	1,271
	FLCU10063 FLC Misc Valve Repair	1,176
	FLCFGD814 Misc Routine Maintenance	1,101
	TRKOROUTG TRK OMRO ROUTINE OUTAGE	890
	TRKBICE01 TRK BCO ICE 1 LABOR	729
	KXL0MM023 KXL Business Travel/Expenses	715
	TRKORENEQ TRK OUTAGE RENTAL EQUIPMENT	698
	PRK20GBIR O M GBIR	589
	TRKBEMPLO TRK BASE EMPLOYEE EXPENSE	474
	DIVINGOPS FHG Diving at the plants	468
	X00116770 GBIR Outage and Support Servic	354
	DMS20LA02 SW-LA/SHV/T'storm 1-11-2020	349
		•

AEPSC Department	Project ID/Description	Amount
	WLKFOU111 U 1 Forced Outage	242
	ECNMMUL01 TCOM-MULTI Program	236
	ARSCTDUES LTSA Annual Dues	139
	WSX110910 Air Quality West O&M Staff Bud	115
	PRK17RCAP 2017 RAIN CAP	110
	X00116801 Special Studies	97
	WSX115884 Cmf Support	91
	000018530 SEP/TD/Distr Line Tools	79
	000014419 SEP/DS/Distr Line Tools	79
	PRKMBLR64 CONDITION ASSESSMENTS	54
	SWEHPITRN SWEPCO HPI Training	50
	DR18S01A8 DA Distribution Line - Texas	(3)
Generation Total	, , , , , , , , , , , , , , , , , , ,	6,007,442
INCENTIVES	000005502 CSC - All Call Types	477,097
	FANANDA Activity NOT assoc with a PROJ	220,533
	X00116782 Power Plant Operation Technica	180,609
	X00116795 Day-to-Day Permit and Regulato	101,246
	CHNANDA Chairman Anda	78,943
	LGNANDA Legal/Policy/Cc Anda	75,503
	EON018181 Rate Case Support	73,935
	ETNANDA Transmission Anda	72,434
	BAOCOREBL BAO Core Billing	64,621
	EDNANDA Distribution Anda Project	58,619
	SSSANANDA Accumulate Gen & Admin Securit	52,145
	TDOANDA T And D Other Anda	50,703
	X00116949 Rata Services (O&M)	46,448
	WSHM3G001 WSH U3 GBIR	44,874
	000001072 Regulated Fuel Supply	44,853
	X00116816 Administrative Services Suppor	42,059
	LGN101704 Litigation - General	39,375
	000002524 PRK - BCO	38,724
	FLC054100 FLC BCO Non-Payroll	38,456
	PRK19GBIR O&M GBIR	38,220
	OPBLDG Gs Operating Co Building Expen	35,979
	000005442 CSC Call Center Support	35,443
	WSHM1G001 WSH U1 GBIR	34,985
	SSITNANDA Accumulate Gen _ Admin IT Exp	25,609
	FHGENNERC FHG Gen NERC Compliance	25,057
	KXL5MM009 KXL U5 Generator Inspection	24,103
	ARS6SMAJR 6S TURB/GEN MAJOR	22,988
	X00116764 Environmental Optimization Ser	22,285
	TRKOMISCM TRK OMRO MISC MAINTENANCE	22,078
	X00116805 Environmental Analyses	20,695
	X00116760 Chemical Engineering Services	19,755
	000002786 Simulator Learning Center O M	18,238
	WSX114371 SWEPCO REO O M Staff Budget	16,850
	X00116794 Permitting and Regulatory Supp	16,422
	WSHMU3062 WSH U3 Boiler Tubes Drum WW	16,396
	EDN103181 Ds Sep Ark-Anda	15,583
	WSX110939 Environmental Serv -Distribut	15,433
	WSX109104 WILKES -BASE COST OF OPERATION	14,400
	KXL5MM005 KXL U5 Corrosion Fatigue	14,400
	•	13,586
		•
	LGN101901 Environmental General	13,379
	TRKBENVIR TRK BASE ENVIRON EXPENDITURES	13,342
	V00440777 Infontering Ic	
	X00116777 Infrastructure Inspection & As	13,020
	SOCIALMED Social Media Organization	12,589

AEPSC Department	Project ID/Description	Amount
	GENOPEREX Gen Operational Excellence	11,689
	BAONONCOR BAO Non-Core Billing	10,138
	ACTCARADM Activated Carbon	10,125
	EON100347 Collections Support	9,525
	X00116803 Plant O&M Related Analyses	9,088
	BUSREV012 Business Process Review	8,768
	X00116759 CEMS Support Services (O&M)	8,713
	LBM0MLRSO RSO LABOR	8,651
	ECNMLWN01 TCOM-Lan/Wan Program	8,593
	WSHMU0071 WSH U0 CCR RULE-O&M	8,220
	ETN001007 Abd Proposal Estimate Preprtn	8,212
	KXL5MB017 KXL U5 Main Steam Attemperator	7,896
	WSX109160 Arsenal Hill - Base Cost Of Op	7,629
	000005554 CSC Corpus - All Call Types	7,333
	WLKM10018 U1 MAIN STEAM STOP VALVE	6,528
	WLKM10019 U1 CONTROL VALVES	6,400
	LIMEADMIN Procure Lime for AEP Plants	6,209
	TRKBGRDS1 TRK NOMI GROUNDS MAINT LABOR	6,074
	ARSHU6BCO ARS Hill Unit 6 BCO	5,884
	LBM0MDOOR Boiler Doors	5,726
	WSHMU3063 WSH U3 PSH and SH Repairs	5,721
	000014094 O M Forced Outage	5,236
	ARSU6ORMR ARS STALL UNIT ORM REQUIREMENT	5,177
	ETN000159 Sep Distribution Station Overh	5,032
	ARS6BHINS 6B HRSG INSPECTIONS	5,014
	PRKMSTR01 SAFETY TEAM RECOMMENDATIONS	4,959
	LGN101699 General Regulatory Services	4,928
	TRKOVALVE TRK TURBINE MAIN & STOP VALVES	4,793
	TURKRAIL2 New Turk Rail Access	4,774
	PRKOMPULV PULVERIZER MAINTENANCE	4,518
	X00116754 Landfill, Reservior Management	4,144
	KXL5MB001 KXL U5 GBIR Overhaul	3,954
	KXL5FK001 KXL U5 Forced Outages	3,754
	ETN100257 TR/BATT Battery Insp Detailed	3,705
	ARSU6OUTG Arsenal Hill Unit 6 Outage	3,666
	LGN101639 Labor Law & Relations	3,608
	ARS6OUTCL ARS6 OUTAGE CONTRACT LABOR	3,416
	TRKLEAN15 TRK LEAN 2015 WORK	3,390
	TRKBCHEMS TRK BASE CHEMICALS	3,309
	WSHMU1063 WSH U1 PSH and SH Repairs	3,123
	LBM0MECON Economizer Hair Pin Replace	3,086
	ANHYAMMON Procure Anhydrous Ammonia	2,972
	ARSCHEMCL ARSU5 CHEMICAL CLEAN	2,968
	LBM4FOROT U4 Forced Outage	2,933
	TRKNWWATR TRK WASTE WATER TREATMENT PLT	2,750
	KXL5MM010 KXL U5 Heat Trace & Insulation	2,742
	000001585 O&M / Fuel Staff Project	2,715
	000012310 SEP LA Attach Serv Rentals	2,687
	000001859 Greg/Rusk 8898 & 8899 non cap	2,682
	ASHADMINS Ash Sales Administration	2,547
	CALBRMADM Procure Calcium Bromide	2,538
	ARSU5ORMR ARS ORM REQUIREMENTS	2,534
	000020779 Customer Web Inquiry	2,529
	X00116802 Emissions Testing	2,452
	CCRGWMONP Plant CCR GW Monitoring	2,343
	EON102461 Value Creation Non-Sever Reloc	2,317
	FLC1G5784 PSH and SH Repairs	2,212
	EDN103182 Ds Sep Tx Anda	2,172
	000005325 Core Load Research Activity	2,129

AEPSC Department	Project ID/Description	Amount
	EDN102170 Ds/All/Dist ABD	2,097
	WSX109080 WSH U0 Base Cost Of Operations	2,067
	LMSTADMIN Procure Limestone	2,047
	ETN000194 T Sep T Anda	2,043
	ITPFP1421 Maximo Implementation	2,024
	PLANTREG4 Plant Eng Region 4 Support	1,982
	TRKNSAFPF TRK SAFETY PLATFORMS	1,965
	TONNPMA01 TON NP Maintenance	1,956
	TRKFBCO00 TRK COAL YARD MISC	1,937
	TRKNCYMIS TRK NOMI CY MISC MAINT	1,924
	ARS6GNRRO Stall Steam Turbine Val Repair	1,897
	ETN100223 Tr/Trns Tran-Cm Not Assoc/Pm	1,845
	ETN100221 Tr/Cbns Cb-Cm Not Assoc W/Pm	1,842
	WSHMU1074 WSH U1 TURBINE VALVE INSP RPR	1,803
	ETN100220 Tr/Pagm Prop & Grnds Maint	1,773
	X00116804 Industrial Hygiene Analyses	1,695
	000012311 SEP TX Attach Serv Rentals	1,654
	TRKBRSOPL TRK RSO PLANT LABOR	1,545
	LGN101644 Property Sales	1,529
	LGN101636 Corporate Financing	1,527
	ETN100213 Tr/Trip Relay Trip Check	1,445
	LBM0MOUTX Outage Combined	1,357
	000001465 PK-Marshall South-Land 7700	1,300
	WSX109127 Lieberman -Base Cost Of Operat	1,296
	LBM0DRAIN Drain System	1,268
	TRKBMISCR TRK MISC REPAIRS	1,230
	WLKM10033 U1 BREAKER REBUILD	1,220
	ETN000161 Sep-Tx Distribution Station Ov	1,219
	TRKNSERV0 TRK NOMI MISC SERVICES	1,199
	WLKN01006 NOMI Combine	1,173
	ECNMSCA01 TCOM-SCADA Program	1,155
	TRKNSAFTY TRK NOMI SAFETY	1,133
	X00116800 Spill Remediation Support and	1,131
	TRKOBRSAM TRK OUTAGE BOILER TUBE SAMPLES	1,106
	000022452 Engineering Structural Inspect	1,103
	SSN100013 Ss Ed Distribution Nanda Proj	1,076
	X00116790 Training	1,057
	ARS10U6GO ARS Unit 6 Routine Outage	991
	FLC1G5563 SH RH Repairs	984
	WSHMU3085 WSH U3 TURB STM, CTRLS, AUX	982
	LGN102653 Video Web Design	979
	DCRESERCH CSC Direct Collections - Recon	958
	TRKNBLDGR TRK NOMI BLDG REPAIRS	948
	LGN101645 Right Of Way/Easements	941
	ETN100249 Tr/Tgom Undefined O&M Projects	917
	SSN100012 Ss Ed Trans Nanda Proj	905
	PRK13M011 O M Forced Outage	904
	TRKBMECH3 TRK BCO MECH 3 LABOR	902
	ETN100235 Tr/Tlap Line Inspection	894
	TRKNMISCM TRK NOMI MISC MAINT	893
	000020544 SPP RE Compliance	860
	LGN100970 General Contracts/Agreements	825
	FLC1G1742 Routine Boiler Maintenance	819
	ARS6AHINS 6A HRSG INSPECTIONS/INSULATION	819
	LBM2FOROT U2 Forced Outage	810
	000007486 SWEP/Ark/Dist Undg Locates	779
	000007487 SWEP/La/Dist Undg locates	779
	000007488 SWEP/Tx/Dist Undg Locates	779
	X00116750 Coal Pile Inventory Services (746
	, ,	

AEPSC Department	Project ID/Description	Amount
	HWARRANTY Home Warranty Program	742
	WSHMU3081 WSH U3 FW HEATER AND FW SYSTEM	720
	WSX109112 Knox Lee -Base Cost Of Operati	705
	X00116780 Metallurgical Failure Analysis	658
	X00116796 Regulatory Development	657
	ECNMTPT01 TCOM-Transport Program	656
	FLC041000 FLC BCO - Non-payroll	594
	NGCCSTUDY Natural Gas Siting Study - CC	579
	ETN100214 Tr/Calı Relay Calıbration	571
	OUTBNDCOM Outbound Communication	543
	WSX112283 Non-Billable Organizational Pl	541
	CULTURETR Culture Train Power up & Lead	531
	ARS6BLTSA STALL 6B LTSA CT	528
	TRKNGENAX TRK N GENERATOR AND AUX SYSTEM	514
	WLKM30033 U3 BREAKER REBUILD	485
	000005708 Ds SEP La-Anda	485
	SSGSNANDA Shared Services-Accumulate Gen	462
	KXL5MB013 KXL U5 Hot Spot Repairs	450
	B194ARSRE T/SW/Non-Specific Work-Station	450
	FLC1G1732 Economizer Repairs	444
	ARSU5GBIR U5 BOILER MAINTENANCE/INSPECTI	443
	X00116973 Title 316 (b) Project	442
	ETN201102 NERC Relay Calibration	438
	000022545 Turk Procurement Activities	437
	000013139 FLC Boiler Riser Tubes	437
	B194TXSRE T/SW/Non-Specific Work Station	419
	ETN100203 Tr/Tmmr Transformer Minor Reg	417
	TRKBICE03 TRK BCO ICE 3 LABOR	415
	FLCFGD814 Misc Routine Maintenance	415
	ETN100227 Tr/Teem Electrical Equip Maint	405
	000003460 CSC Training-New Hire Classes	403
	ECN103052 Dt Abd Telecom Projects	395
	TRKNRPLOW TRK ROTARY PLOWS 1 & 2	385
	BUSSOLUTN Tulsa Business Solutions	367
	ETN100210 Tr/Rt01 Station Inspection	359
	FLCU10063 FLC Misc Valve Repair	344
	KXL2FK001 KXL U2 Forced Outages	338
	WLKM20043 U2 BREAKER REBUILD	330
	PRK11M940 ENVIRO DIKES & BERMS	301
	EON102240 Supply Chain Value Creation	293
	WSHMU1075 WSH U1 CIRC WATER SYSTEM	279
	TRKBPRMIT TRK BASE PERMITS & ENVIRONMENT	271
	X00116758 Boiler Reliability Optimizatio	266
	WSHFORC16 Weish Forced Outage	265
	ETN100256 TR/TPDM Pred Diag Maint Proj	257
	000012309 SEP AK Attach Serv Rentals	255
	TRKBCOMIS TRK MISC EXPENSE	240
	LSTONESVY Limestone Pile Surveys	216
	B159LASRE D/SW/Non-SpeicificWork Station	199
	DMS19LA05 SW-LA/Valley/T'Storm 4-13-19	199
	ECNMPHV01 TCOM-Telephone/Video Program	194
	TONNPOP01 TON NP Operations	174
	DMS19LA09 SW-LA/Valley/T'storm 5-8-19	155
	DMS19AR03 SW-ARFAYThunderstorm 5-1-19	154
	ETN201101 NERC Relay Trip Check	146
	DMS19LA19 SW-LA/SHV/Thunderstorm 6-23-19	145
	DMS19LA18 SW-LA/SHV/Thunderstorm 6-19-19	143
	2019NCOV1 2019-nCoV Planning & Response	142
	ETN100253 Tr/Pice Power Line Carrier	133
	out of one the outer	, 55

AEPSC Department	Project ID/Description	Amount
	DMS19LA24 SW-LA/SHV/T'storm 10-20-19	129
	SSN100004 Ss Wholesale Other	125
	A15706018 Lone Star Power Plant sub	121
	KXL0MM023 KXL Business Travel/Expenses	104
	PRK20GBIR O M GBIR	99
	TRKOROUTG TRK OMRO ROUTINE OUTAGE	98
	ETN201301 Relay CT/PT Verification	93
	TRKORENEQ TRK OUTAGE RENTAL EQUIPMENT	90
	DIVINGOPS FHG Diving at the plants	85
	ARSCTDUES LTSA Annual Dues	82
	ETN100199 Trans - P C Direct Time	79
	ARS56ETAX ARS/Stall 5&6 Electric Usage	77
	ECNMMUL01 TCOM-MULTI Program	73
	TRKBICE01 TRK BCO ICE 1 LABOR	72
	ETN100236 Tr/Tlci Comprehensive Inspect	69
	DMS19LA16 SW-LA/SHV/Thunderstorm 5-8-19	66
	000004743 SWEP-TSectionalizing Program	60
	DMS19LA12 SW-LASHVThunderstorm 4-18-19	59
	DMS19LA14 SW-LASHVThunderstorm 4-25-19	55
	WLKFOU111 U 1 Forced Outage	53
	DMS19LA22 SW-LASHVThunderstorm 10-3-19	43
	DMS19AR13 SW-AR/FAY/Wind 10-20-19	43
	DMS19LA21 SW-LAValleyTstorm 10-20-19	43
	B194TXLRE T/SW/Non-Specific Work - Line	40
	WLKM10003 U1 ORM REQUIREMENT	36
	ETN100246 Tr/Tlsa T-Line Structure Maint	33
	WLKM30001 U3 ORM REQUIREMENT	33
	WLKM20008 U2 ORM REQUIREMENT	33
	ETN100202 Tr/Cbci Cb Complete Inspection	28
	ETN100201 Tr/Cbei Cb External Inspection	27
	A18806031 Welsh breaker 11670 failure	25
	B161TXSRE D/SW/Non-Specific Work Station	18
	DMS19TX21 SW-TX/LGV/Thunderstorm 7-10-19	17
	ETN100204 Tr/Tmmn Transformer Minor Non	17
	DMS19AR05 SW-ARFAYThunderstorm 5-18-19 DMS19LA08 SW-LASHVThunderstorm 4-7-19	16 15
	ETN100225 Tr/Pcns P&C Non-Sched Repairs	14
	DMS20LA03 SW-LA/Valley/T'storm 3-4-2020	13
	DMS19AR14 SW-ARTDWind 7-10-19	13
	WSN100526 Comm Operations Staff Project	12
	SWEHPITRN SWEPCO HPI Training	11
	X00116801 Special Studies	9
	CULTUREGR General Culture Initiative	6
	DMS19LA01 SW-LAValleyTstorm 4-7-19	5
	X00116770 GBIR Outage and Support Servic	4
	DR18S01A5 Overhead Renewal Project - TX	4
	A17031001 Tontitown Spare Prchse	2
	DMS19LA06 SW-LASHVThunderstorm3-14-19	(0)
	DR18S01A8 DA Distribution Line - Texas	(2)
	DMS20LA02 SW-LA/SHV/T'storm 1-11-2020	(12)
	DMS20LA01 SW-LA/Valley/T'storm 1-11-2020	(41)
INCENTIVES Total		2,745,438
Transmission	ETNANDA Transmission Anda	380,242
	ETN000159 Sep Distribution Station Overh	42,323
	ETN001007 Abd Proposal Estimate Preprtn	37,363
	ETN100257 TR/BATT Battery Insp Detailed	20,793
	CHNANDA Chairman Anda	19,504
	ETN100223 Tr/Trns Tran-Cm Not Assoc/Pm	18,000
	ETN100220 Tr/Pagm Prop & Grnds Maint	11,517

AEPSC Department	Project ID/Description	Amount
	ETN000194 T Sep T Anda	11,379
	ETN100221 Tr/Cbns Cb-Cm Not Assoc W/Pm	9,649
	X00116782 Power Plant Operation Technica	7,541
	ETN100249 Tr/Tgom Undefined O&M Projects	6,457
	WSX109127 Lieberman -Base Cost Of Operat	6,019
	ETN100213 Tr/Trip Relay Trip Check	5,934
	EDNANDA Distribution Anda Project	5,595
	ETN000161 Sep-Tx Distribution Station Ov	4,911
	ETN100203 Tr/Tmmr Transformer Minor Reg	4,182
	CULTURETR Culture Train Power up & Lead	3,601
	B194TXSRE T/SW/Non-Specific Work Station	3,368
	ITPFP1421 Maximo Implementation	2,523
	ETN100235 Tr/Tlap Line Inspection	2,470
	ETN100253 Tr/Plce Power Line Carrier	2,445
	000020544 SPP RE Compliance	2,303
	ETN100227 Tr/Teem Electrical Equip Maint	2,218
	ETN100202 Tr/Cbci Cb Complete Inspection	2,185
	ETN100256 TR/TPDM Pred Diag Maint Proj	2,054
	ETN100214 Tr/Calı Relay Calibration	1,879
	ETN201102 NERC Relay Calibration	1,839
	ETN100210 Tr/Rt01 Station Inspection	1,792
	B159LASRE D/SW/Non-SpeicificWork Station	1,356
	A15706018 Lone Star Power Plant sub	1,335
	B194ARSRE T/SW/Non-Specific Work-Station	948
	ETN201301 Relay CT/PT Verification	915
	FLCFGD814 Misc Routine Maintenance	668
	ETN100236 Tr/Tlci Comprehensive Inspect	667
	000002524 PRK - BCO	640
	ETN100199 Trans - P C Direct Time	633
	WSX109080 WSH U0 Base Cost Of Operations	573
	ETN100204 Tr/Tmmn Transformer Minor Non	502
	ETN201101 NERC Relay Trip Check	442
	WLKM10003 U1 ORM REQUIREMENT	337
	WLKM30001 U3 ORM REQUIREMENT	303
	WLKM20008 U2 ORM REQUIREMENT	303
	ETN100246 Tr/Tlsa T-Line Structure Maint	269
	B194TXLRE T/SW/Non-Specific Work - Line	257
	ETN100201 Tr/Cbei Cb External Inspection	239
	B161TXSRE D/SW/Non-Specific Work Station	173
	ETN100225 Tr/Pcns P&C Non-Sched Repairs	121
	A18806031 Welsh breaker 11670 failure	96
	CULTUREGR General Culture Initiative	49
	A17031001 Tontitown Spare Prchse	7
	FANANDA Activity NOT assoc with a PROJ	0
	EON018181 Rate Case Support	0
Transmission Total		630,921
Utilities	EDNANDA Distribution Anda Project	68,364
	EDN103181 Ds Sep Ark-Anda	51,297
	000012310 SEP LA Attach Serv Rentals	16,460
	EDN103182 Ds Sep Tx Anda	7,903
	000005708 Ds SEP La-Anda	5,057
	000007486 SWEP/Ark/Dist Undg Locates	3,064
	000007488 SWEP/Tx/Dist Undg Locates	3,064
	000007487 SWEP/La/Dist Undg locates	3,064
		2 105
	CHNANDA Chairman Anda	
	CHNANDA Chairman Anda 000012309 SEP AK Attach Serv Rentals	2,195 1,239
	000012309 SEP AK Attach Serv Rentals	1,239

AEPSC Department	Project ID/Description	Amount
	DMS19LA18 SW-LA/SHV/Thunderstorm 6-19	9-19 859
	DMS19LA09 SW-LA/Valley/T'storm 5-8-19	698
	DMS19AR03 SW-ARFAYThunderstorm 5-1-1	19 692
	DMS20LA02 SW-LA/SHV/T'storm 1-11-2020	585
	DMS19LA24 SW-LA/SHV/T'storm 10-20-19	536
	DMS19LA16 SW-LA/SHV/Thunderstorm 5-8-	19 388
	DMS19LA12 SW-LASHVThunderstorm 4-18-	19 355
	DMS20LA01 SW-LA/Valley/T'storm 1-11-202	0 276
	DMS19LA22 SW-LASHVThunderstorm 10-3-	19 186
	DMS19AR13 SW-AR/FAY/Wind 10-20-19	174
	DMS19LA21 SW-LAValleyTstorm 10-20-19	167
	DMS19LA08 SW-LASHVThunderstorm 4-7-1	19 133
	DMS19TX21 SW-TX/LGV/Thunderstorm 7-10	0-19 133
	EDN103262 Ds/Sep-T/Ast Imp Hazard Waste	e 129
	DMS19AR14 SW-ARTDWind 7-10-19	101
	DMS20LA03 SW-LA/Valley/T'storm 3-4-2020	91
	DMS19AR05 SW-ARFAYThunderstorm 5-18	-19 89
	DMS19LA01 SW-LAValleyTstorm 4-7-19	44
	SSNANDA Shared Services Anda	0
	EON018181 Rate Case Support	0
Utilities Total	The state of the s	170,403
Grand Total		21,378,104

}

SOUTHWESTERN ELECTRIC POWER COMPANY'S RESPONSE TO OFFICE OF PUBLIC UTILITY COUNSEL'S SECOND REQUEST FOR INFORMATION

Question No. OPUC 2-8:

Please refer to the Direct Testimony of Mr. Brian J. Frantz, Exhibit BJF-8. Please provide the same information contained in this exhibit on page 4 as it relates to the charges to SWEPCO from Dolet Hills Lignite Co. LLC ("Dolet Hills") for each of the last four calendar years. Please provide the information by FERC account.

Response No. OPUC 2-8:

Please refer to OPUC 2-8 Attachment 1 for the same information contained in Exhibit BJF-8 on page 4 as it relates to the charges SWEPCO billed to Dolet Hills Lignite Co. for the calendar years 2016-2019 by FERC Account.

Prepared By: Brian J. Frantz Title: Dir Accounting

Sponsored By: Brian J. Frantz Title: Dir Accounting

SOAH Docket No 473-21-0538 PUC Docket No 51415 OPUC 2nd, Q 8 OPUC 2-8 Attachment 1 Page 1 of 1

SOUTHWESTERN ELECTRIC POWER COMPANY Exhibit BJF-8 SWEPCO billings to Dolet Hills in Cost of Service by FERC Account For The Last Four Calendar Years

FERC Account	2016	2017	2018	2019
5000 - Oper Supervision & Engineering	2		5,061	118
5060 - Misc Steam Power Expenses		64		
5880 - Miscellaneous Distribution Exp		179		
5930 - Maintenance of Overhead Lines		30		
9200 - Administrative & Gen Salaries	1,209,722	616,519	610,803	566,727
9210 - Office Supplies and Expenses	51,916	57,389	35,980	18,274
9230 - Outside Services Employed				2,944
9350 - Maintenance of General Plant				21,460
Grand Total	1,261,640	674,181	651,845	609,523

SOUTHWESTERN ELECTRIC POWER COMPANY'S RESPONSE TO OFFICE OF PUBLIC UTILITY COUNSEL'S SECOND REQUEST FOR INFORMATION

Question No. OPUC 2-9:

Please refer to the Direct Testimony of Mr. Brian J. Frantz, Exhibit BJF-18. Please provide a detailed description of the Pro Forma adjustment to FERC Account 9230 on page 11 of 19.

Response No. OPUC 2-9:

Per page 12 of Company Witness Frantz' Direct testimony, the Company "adjusts the test year benefit plan costs for pension and other post-employment benefits to a 2020 level, per current actuarial estimates". In March 2017, the Financial Accounting Standards Board issued Accounting Standards Update (ASU) 2017-07 which required that only the service cost component of pension and postretirement benefits is eligible for capitalization as applicable following labor. Company management adopted ASU 2017-07 effective January 1, 2018. Therefore, starting in 2018, AEPSC recorded the non-service cost component of pension and postretirement benefits to a separate account (as it was no longer eligible to follow labor) and AEPSC billed the AEP affiliates for these non-service costs to FERC account 9230 on the AEP affiliates' books. Therefore, the pro-forma adjustment in FERC Account 9230 on page 11 of 19 of Exhibit BJF-18 primarily reflects the adjustment of test year benefit plan costs related to this non-service cost component of pension and postretirement benefits.

Prepared By: Brian J. Frantz Title: Dir Accounting

Sponsored By: Brian J. Frantz Title: Dir Accounting

į.

SOUTHWESTERN ELECTRIC POWER COMPANY'S RESPONSE TO OFFICE OF PUBLIC UTILITY COUNSEL'S SECOND REQUEST FOR INFORMATION

Question No. OPUC 2-10:

Please refer to the Direct Testimony of Mr. Patrick L. Baryenbruch, Exhibit 15. Please provide the underlying reasons for the Management Consultant outside services costs and the Professional Engineering outside services costs for Environmental & Safety services provided by AEPSC to SWEPCO. Please include the identification of any particular project or current asset. Please also include the amount that is related to the Texas jurisdiction for each category of cost.

Response No. OPUC 2-10:

Exhibit 15 of Mr. Baryenbruch's Direct Testimony is meant to show which category of outside service provider would be assigned work of AEPSC departments if it were outsourced. The dollar amounts in this exhibit represent fully allocated costs (e.g., labor, fringes, overheads) associated with the AEPSC departments that provide services to SWEPCO. This RFI has been interpreted to ask for .information about the services AEPSC's Environmental Services departments provided to SWEPCO during Test Year 2020.

AEPSC supports SWEPCO by managing its environmental programs, which include permitting and compliance, laboratory services, and strategy and planning. The following AEPSC Environmental Services departments performed the described work for SWEPCO during the test year ending March 31, 2020 ("Test Year 2020").

•	
Environmental Services Departments	Description of Services Provided to SWEPCO
10773 Environmental Services	Oversee AEP's Environmental Services program (this department
	includes the VP of Environmental Services)
10200 Air Quality Services	Provide environmental permitting, licensing, and compliance support,
	participate in environmental rulemaking at the federal and state levels,
	and coordinate research and development in the areas of air emissions
	permits and regulations
10502 Water & Ecolog Resource Svcs	Provide environmental permitting, licensing, and compliance support,
	participate in environmental rulemaking at the federal and state levels,
	and coordinate research and development in the areas of water
	pollution and ecological and endangered species protection
11134 Air & Water Qlty Svcs - Dallas	Provide regional support for the programs described for departments
·	10200 and 10502
10676 Land Env & Remediation Svcs	Provide environmental permitting, licensing, and compliance support,
	participate in environmental rulemaking at the federal and state levels,
	and coordinate research and development in the areas of waste
	management, groundwater monitoring and data evaluation, hazardous
	chemical reporting, hazardous material/waste transportation, spill
	response and remediation, and real property transactions
10140 Land Envrnmnt & T&D Compliance	Provide regional support for the programs described for department
10328 Env Training & T&D Compliance	10676
10769 Dolan Chemical Laboratory	Provide analytical laboratory services and consultation including testing
10782 GET Eng Coal Lab	of water, wastewater, waste, flue gas, and other miscellaneous
10874 Shreveport Chemical Laboratory	materials in support of environmental compliance and facility design,
-	operation and maintenance
12813 ENV Management Systems	Develop, implement, and maintain the Environmental Management
,	System for AEP which includes processes and apps to support
	environmental compliance and internal business activities.
	environmental task management and data collection, continuous
	improvement initiatives, document control, electronic data collection,
	mobile-based solutions and development of environmental training
13742 Env Risk Management	Evaluate, develop, and direct programs for environmental risk
	identification and mitigation in order to prevent environmental
	noncompliance, catastrophic failure and/or company reputational
	noncompliance, catastrophic failure and/or company reputational damage

SOAH DOCKET NO. 473-21-0538 PUC DOCKET NO. 51415 OPUC's 2nd RFI, Q. # OPUC 2-10 Page 2 of 2

During Test Year 2020, substantially all of Environmental Services' support for SWEPCO was of an ongoing nature (O&M) and related to the services described in the table above. However, one charge allocated to SWEPCO was for a 3-year license fee for Enviance, a cloud-based environmental, health and safety application used to maintain critical information (e.g., compliance responsibilities) and manage associated tasks. The license fee (approximately \$273,000) was recorded as a capital asset. Environmental Services also supported a number of capital projects during Test Year 2020. However, the charges associated with this work were not significant, with no capital project requiring more than \$10,000 in support from Environmental Services.

Mr. Baryenbruch's Exhibit 15 of his direct testimony shows which outside provider the work of Environmental Services would be assigned to if it were outsourced. The amounts shown in Exhibit 15 are charges to SWEPCO's Texas jurisdiction during Test Year 2020.

The table below shows an analysis of Environmental Services' charges by cost category for the amounts shown in Mr. Baryenbruch's Exhibit 15. It should be noted that these amounts are total charges from Environmental Services departments. The purpose of Exhibit 15 is to develop cost pools by which total hours are divided to arrive at an hourly rate for AEPSC services. As shown in Exhibit 14, certain charges (e.g., travel expenses, outside services, enterprise-wide IT costs, non-service expenses) are not included in the cost pools because these costs are not recovered by outside providers in their billing rates. Thus, the amounts in Exhibit 15 are equivalent to the costs of outside service providers.

Test Year 2020 Cost Pool for Environmental and Safety Services

	 00.11000
Internal Labor	\$ 2,297,437
Fringes	\$ 787,062
Incentives	\$ 781,043
Severance	\$ 569,785
Shrd Svces/Ovrhead	\$ 755,433
Other Cost Category	\$ 130,317
Total	\$ 5,321,078

Prepared By: Alan R. Wood Title: Dir Water Quality

Prepared By: Patrick L. Baryenbruch Title: Baryenbruch & Company

Sponsored By: Patrick L. Baryenbruch Title: Baryenbruch & Company

SOUTHWESTERN ELECTRIC POWER COMPANY'S RESPONSE TO OFFICE OF PUBLIC UTILITY COUNSEL'S SECOND REQUEST FOR INFORMATION

Question No. OPUC 2-11:

Please refer to the Direct Testimony of Mr. Andrew R. Carlin, page 14. Please provide a copy of the agreement between SWEPCO and International Brotherhood of Electrical Workers ("IBEW") Locals 329 as it relates to the short-term incentive ("STI") compensation requested in this Application. Please include in your response the total amount of STI compensation for union represented employees for SWEPCO and the total included in the cost of service for the Texas jurisdiction, broken down between the expense and capitalized amounts.

Response No. OPUC 2-11:

Please see Article X, Section 2 of OPUC 2-11 Attachment 1 for the relevant agreement between SWEPCO and IBEW. Attachment 1 is voluminous and is provided electronically with the native files on the PUC Interchange. Please see OPUC 2-11 Attachment 2 for the total amount of STI compensation for union represented employees for SWEPCO in the test year (including amounts related to financial and non-financial measures), and variances from target amounts along with the total included in the cost of service for the Texas jurisdiction, broken down between the expense and capitalized amounts.

Prepared By: Andrew R. Carlin Title: Dir Comp & Executive Benefits

Prepared By: Frances K. Bourland Title: Regulatory Acctng Case Mgr.

Sponsored By: Andrew R. Carlin Title: Dir Comp & Executive Benefits

Sponsored By: Michael A. Baird Title: Mng Dir Acctng Policy & Research

SOUTHWESTERN ELECTRIC POWER COMPANY Annual Incentive Compensation Information For SWEPCO Union Represented Employees For the Test Year Ended 3/31/20

1070 1 1080 1 1080 1 1510 1 1520 1 1850 1 1860 1 1880 4010 4 264 4265 5000 5010 5020 5050 5050 5050 5100 5110 5120 5130 5140 5420 5440 5480 5520 5660 5660 5660 5680 5690 5710 5820 5830 5840 5850 5860 5870 5880 5990 5910 5920 5930 5940	tonical ,474,583 202,905 19,506 205,630 10,243 42,921 (30) 303 9,866 3,506 219,585 3,527 414,430 355,798 (100,951) 179,430 40,002 415,099 106,937 78,995 5 151 9,848 21,536 75,911 37 16,635 539 (42,308)	Target Amount 131,114 1,963 243,090 205,454 455,016 101,910 23,454 238,361 60,511 46,730 4 80 5,608 12 8,542 45,299 21 10,071 277 73,468 57	36.92910% 36.96190% 36.96190% 36.92820% 36.92820% 36.95440% 36.95400% 36.96190% 36.92820% 36.92820% 36.92820% 36.92820% 43.75490% 43.75490% 43.82520% 43.75490%	48,419 27 725 39 89,768 91 75,870 57 168,029 12 37,660 20 8,661 20 88,102 74 22,365 91 17,256 43 152 29 55 2,070.90 4 51 3,154 59 19,814 28 9 04 4,393 85 121 35 32,145 91
1080 1510 1520 1850 1850 1880 4010 4264 4265 5000 5010 5020 5050 5060 5110 5120 5130 5140 5420 5440 55480 5520 5530 5600 5612 5620 5630 5660 5680 5690 5710 5800 5810 5820 5830 5840 5820 5830 5840 5820 5830 5840 5820 5830 5840 5850 5850 5850 5850 5850 5850 585	202,905 19,506 205,630 10,243 42,921 (30) 303 9,866 3,506 219,585 3,527 414,430 355,798 (100,951) 179,430 40,002 415,099 106,937 78,995 5 151 9,848 23 14,536 75,911 37 16,635 539 (42,308)	1,963 243,090 205,454 455,016 101,910 23,454 238,361 60,511 46,730 4 80 5,608 12 8,542 45,299 21 10,071 277 73,468	36.96190% 36.92820% 36.92820% 36.92820% 36.92820% 36.96190% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 43.75490% 43.75490% 43.75490%	725 39 89,768 91 75,870 57 168,029 12 37,660 20 8,661 20 88,102 74 22,365 91 17,256 43 1 52 29 55 2,070.90 4 51 3,154 59 19,814 28 9 04 4,393 85 121 35 32,145 91
1510 1520 1850 1860 1880 4010 4264 4265 5000 5010 5020 5050 5060 5110 5110 5120 5130 5140 5420 5480 5520 5530 5600 5612 5660 5680 5690 5710 5800 5820 5830 5860 5890 5710 5800 5820 5830 5840 5850 5850 5850 5850 5850 5850 585	19,506 205,630 10,243 42,921 (30) 303 9,866 3,506 219,585 3,527 414,430 355,798 (100,951) 179,430 40,002 415,099 106,937 78,995 5 151 9,848 23 14,536 75,911 37 16,635 539 (42,308)	1,963 243,090 205,454 455,016 101,910 23,454 238,361 60,511 46,730 4 80 5,608 12 8,542 45,299 21 10,071 277 73,468	36.96190% 36.92820% 36.92820% 36.92820% 36.92820% 36.96190% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 43.75490% 43.75490% 43.75490%	725 39 89,768 91 75,870 57 168,029 12 37,660 20 8,661 20 88,102 74 22,365 91 17,256 43 1 52 29 55 2,070.90 4 51 3,154 59 19,814 28 9 04 4,393 85 121 35 32,145 91
1520 1850 1860 1880 4010 4264 4265 5000 5010 5020 5050 5060 5110 5110 5110 5120 5130 5140 5420 5440 5440 5540 5540 5530 5600 5612 5660 5630 5660 5680 5690 5710 5800 5820 5830 5840 5840 5850 5850 5850 5850 5850 585	205,630 10,243 42,921 (30) 303 9,866 3,506 219,585 3,527 414,430 40,002 415,099 106,937 78,995 5 151 9,848 23 14,536 75,911 37 16,635 539 (42,308)	1,963 243,090 205,454 455,016 101,910 23,454 238,361 60,511 46,730 4 80 5,608 12 8,542 45,299 21 10,071 277 73,468	36.96190% 36.92820% 36.92820% 36.92820% 36.92820% 36.96190% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 43.75490% 43.75490% 43.75490%	725 39 89,768 91 75,870 57 168,029 12 37,660 20 8,661 20 88,102 74 22,365 91 17,256 43 1 52 29 55 2,070.90 4 51 3,154 59 19,814 28 9 04 4,393 85 121 35 32,145 91
1850 1850 1860 1880 4010 44264 4265 5000 5010 5020 5050 5060 5110 5110 5120 5130 5140 5420 5440 5480 5520 5530 5600 5612 5620 5630 5660 5680 5690 5710 5800 5820 5830 5840 5880 5890 5870 5880 5890 5870 5880 5900 5910 5920 5930 5940	10,243 42,921 (30) 303 9,866 3,506 219,585 3,527 414,430 355,798 (100,951) 179,430 40,002 415,099 106,937 78,995 5151 9,848 23 14,536 75,911 37 16,635 539 (42,308)	1,963 243,090 205,454 455,016 101,910 23,454 238,361 60,511 46,730 4 80 5,608 12 8,542 45,299 21 10,071 277 73,468	36.96190% 36.92820% 36.92820% 36.92820% 36.92820% 36.96190% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 43.75490% 43.75490% 43.75490%	725 39 89,768 91 75,870 57 168,029 12 37,660 20 8,661 20 88,102 74 22,365 91 17,256 43 1 52 29 55 2,070.90 4 51 3,154 59 19,814 28 9 04 4,393 85 121 35 32,145 91
1860 1880 4010 4264 4265 5000 5010 5020 5050 5050 5100 5110 5120 5130 5140 5420 5440 5480 5520 5530 5660 5612 5620 5630 5660 5660 5680 5690 5710 5810 5810 5810 5810 5810 5810 5810 58	42,921 (30) 303 9,866 3,506 219,585 3,527 414,430 355,798 (100,951) 179,430 40,002 415,099 106,937 78,995 5151 9,848 23 14,536 75,911 37 16,635 539 (42,308)	1,963 243,090 205,454 455,016 101,910 23,454 238,361 60,511 46,730 4 80 5,608 12 8,542 45,299 21 10,071 277 73,468	36.96190% 36.92820% 36.92820% 36.92820% 36.92820% 36.96190% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 43.75490% 43.75490% 43.75490%	725 39 89,768 91 75,870 57 168,029 12 37,660 20 8,661 20 88,102 74 22,365 91 17,256 43 1 52 29 55 2,070.90 4 51 3,154 59 19,814 28 9 04 4,393 85 121 35 32,145 91
1880 4010 4264 4265 5000 5010 5020 5050 5060 5110 5120 5130 5140 5420 5440 5480 5520 5530 5600 5612 5620 5630 5660 5680 5690 5710 5800 5710 5800 5820 5830 5840 5820 5830 5840 5850 5850 5850 5870 5850 5860 5870 5880 5900 5910 5920 5930 5940	(30) 303 9,866 3,506 219,585 3,527 414,430 355,798 (100,951) 179,430 40,002 415,099 106,937 78,995 5 151 9,848 23 14,536 75,911 37 16,635 539 (42,308)	1,963 243,090 205,454 455,016 101,910 23,454 238,361 60,511 46,730 4 80 5,608 12 8,542 45,299 21 10,071 277 73,468	36.96190% 36.92820% 36.92820% 36.92820% 36.92820% 36.96190% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 43.75490% 43.75490% 43.75490%	725 39 89,768 91 75,870 57 168,029 12 37,660 20 8,661 20 88,102 74 22,365 91 17,256 43 1 52 29 55 2,070.90 4 51 3,154 59 19,814 28 9 04 4,393 85 121 35 32,145 91
4010 4264 4265 5000 5010 5020 5050 5060 5100 5110 5120 5130 5140 5420 5440 5440 55480 5520 5530 5600 5612 5620 5630 5660 5680 5690 5710 5800 5810 5820 5830 5800 5810 5820 5830 5800 5810 5820 5830 5800 5810 5820 5830 5840 5850 5850 5850 5850 5850 5850 585	303 9,866 3,506 219,585 3,527 414,430 355,798 (100,951) 179,430 40,002 415,099 106,937 78,995 5 151 9,848 23 14,536 75,911 37 16,635 539 (42,308)	1,963 243,090 205,454 455,016 101,910 23,454 238,361 60,511 46,730 4 80 5,608 12 8,542 45,299 21 10,071 277 73,468	36.96190% 36.92820% 36.92820% 36.92820% 36.92820% 36.96190% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 43.75490% 43.75490% 43.75490%	725 39 89,768 91 75,870 57 168,029 12 37,660 20 8,661 20 88,102 74 22,365 91 17,256 43 1 52 29 55 2,070.90 4 51 3,154 59 19,814 28 9 04 4,393 85 121 35 32,145 91
4264 4265 5000 5010 5020 5050 5060 5100 5110 5120 5130 5140 5420 5440 5440 55480 5520 5530 5600 5612 5660 5680 5690 5700 5710 5800 5820 5830 5840 5850 5850 5850 5870 5880 5900 5910 5920 5930 5940	9,866 3,506 219,585 3,527 414,430 355,798 (100,951) 179,430 40,002 415,099 106,937 78,995 5 151 9,848 23 14,536 75,911 37 16,635 539 (42,308)	1,963 243,090 205,454 455,016 101,910 23,454 238,361 60,511 46,730 4 80 5,608 12 8,542 45,299 21 10,071 277 73,468	36.96190% 36.92820% 36.92820% 36.92820% 36.92820% 36.96190% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 43.75490% 43.75490% 43.75490%	725 39 89,768 91 75,870 57 168,029 12 37,660 20 8,661 20 88,102 74 22,365 91 17,256 43 1 52 29 55 2,070.90 4 51 3,154 59 19,814 28 9 04 4,393 85 121 35 32,145 91
4265 5000 5010 5010 5020 5050 5060 5100 5110 5110 5110 5110 5120 5130 5140 5420 5440 5480 5520 5530 5600 5612 5620 5630 5660 5680 5690 5710 5800 5820 5830 5840 5880 5890 5870 5850 5860 5870 5880 5900 5910 5920 5930 5940	3,506 219,585 3,527 414,430 355,798 (100,951) 179,430 40,002 415,099 106,937 78,995 5 151 9,848 23 14,536 75,911 37 16,635 539 (42,308)	1,963 243,090 205,454 455,016 101,910 23,454 238,361 60,511 46,730 4 80 5,608 12 8,542 45,299 21 10,071 277 73,468	36.96190% 36.92820% 36.92820% 36.92820% 36.92820% 36.96190% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 43.75490% 43.75490% 43.75490%	725 39 89,768 91 75,870 57 168,029 12 37,660 20 8,661 20 88,102 74 22,365 91 17,256 43 1 52 29 55 2,070.90 4 51 3,154 59 19,814 28 9 04 4,393 85 121 35 32,145 91
5000 5010 5020 5020 5050 5050 5060 5110 5120 5130 5140 5420 5440 5480 5520 5530 5600 5612 5620 5630 5660 5680 5690 5700 5710 5800 5820 5830 5840 5850 5840 5850 5850 5850 5850 585	219,585 3,527 414,430 355,798 (100,951) 179,430 40,002 415,099 106,937 78,995 5 151 9,848 23 14,536 75,911 37 16,635 539 (42,308)	1,963 243,090 205,454 455,016 101,910 23,454 238,361 60,511 46,730 4 80 5,608 12 8,542 45,299 21 10,071 277 73,468	36.96190% 36.92820% 36.92820% 36.92820% 36.92820% 36.96190% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 43.75490% 43.75490% 43.75490%	725 39 89,768 91 75,870 57 168,029 12 37,660 20 8,661 20 88,102 74 22,365 91 17,256 43 1 52 29 55 2,070.90 4 51 3,154 59 19,814 28 9 04 4,393 85 121 35 32,145 91
5010 5020 5020 5050 5060 5110 5110 5120 5130 5140 5440 5480 5520 5530 5600 5612 5622 5630 5660 5680 5690 5710 5800 5710 5800 5820 5830 5840 5820 5830 5840 5850 585	3,527 414,430 355,798 (100,951) 179,430 40,002 415,099 106,937 78,995 5 151 9,848 23 14,536 75,911 37 16,635 539 (42,308)	1,963 243,090 205,454 455,016 101,910 23,454 238,361 60,511 46,730 4 80 5,608 12 8,542 45,299 21 10,071 277 73,468	36.96190% 36.92820% 36.92820% 36.92820% 36.92820% 36.96190% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 43.75490% 43.75490% 43.75490%	725 39 89,768 91 75,870 57 168,029 12 37,660 20 8,661 20 88,102 74 22,365 91 17,256 43 1 52 29 55 2,070.90 4 51 3,154 59 19,814 28 9 04 4,393 85 121 35 32,145 91
5020 5050 5050 5060 5100 5110 5120 5130 5140 5420 5440 5480 5520 5530 5600 5612 5620 5630 5660 5680 5690 5710 5800 5710 5800 5820 5830 5840 5850 5850 5870 5850 5870 5880 5900 5910 5920 5930 5940	3,527 414,430 355,798 (100,951) 179,430 40,002 415,099 106,937 78,995 5 151 9,848 23 14,536 75,911 37 16,635 539 (42,308)	243,090 205,454 455,016 101,910 23,454 238,361 60,511 46,730 4 80 5,608 12 8,542 45,299 21 10,071 277 73,468	36 92820% 36 92820% 36 92820% 36 95440% 36 95490% 36.96190% 36.92820% 36.92820% 36.92820% 36.92820% 43.75490% 43.75490% 43.82520% 43.75490%	89,768 91 75,870 57 168,029 12 37,660 20 8,661 20 88,102 74 22,365 91 17,256 43 1 52 29 55 2,070.90 4 51 3,154 59 19,814 28 9 04 4,393 85 121 35 32,145 91
5050 5060 5060 5100 5110 5110 5120 5130 5140 5420 5440 55480 5550 5560 5661 5660 5660 5680 5690 5770 5800 5820 5830 5840 5850 5850 5850 5850 5850 5850 585	414,430 355,798 (100,951) 179,430 40,002 415,099 106,937 78,995 5 151 9,848 23 14,536 75,911 37 16,635 539 (42,308)	243,090 205,454 455,016 101,910 23,454 238,361 60,511 46,730 4 80 5,608 12 8,542 45,299 21 10,071 277 73,468	36 92820% 36 92820% 36 95440% 36 96190% 36.96190% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 43.74080% 43.75490% 43.82520% 43.75490%	75,870 57 168,029 12 37,660 20 8,661 20 88,102 74 22,365 91 17,256 43 1 52 29 55 2,070,90 4 51 3,154 59 19,814 28 9 04 4,393 85 121 35 32,145 91
5060 5100 5110 5110 5110 5120 5130 5140 5420 5440 5480 5580 5600 5612 5620 5630 5660 5680 5690 5700 5710 5820 5830 5840 5850 5850 5850 5850 5850 5850 585	355,798 (100,951) 179,430 40,002 415,099 106,937 78,995 5 151 9,848 23 14,536 75,911 37 16,635 539 (42,308)	205,454 455,016 101,910 23,454 238,361 60,511 46,730 4 80 5,608 12 8,542 45,299 21 10,071 277 73,468	36 92820% 36 95440% 36 92820% 36 96190% 36.96190% 36 92820% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 43.74080% 43.75490% 43.82520% 43.75490%	75,870 57 168,029 12 37,660 20 8,661 20 88,102 74 22,365 91 17,256 43 1 52 29 55 2,070,90 4 51 3,154 59 19,814 28 9 04 4,393 85 121 35 32,145 91
5060 5100 5110 5110 5110 5120 5130 5140 5420 5440 5480 5580 5600 5612 5620 5630 5660 5680 5690 5700 5710 5820 5830 5840 5850 5850 5850 5850 5850 5850 585	(100,951) 179,430 40,002 415,099 106,937 78,995 5 151 9,848 23 14,536 75,911 37 16,635 539 (42,308)	455,016 101,910 23,454 238,361 60,511 46,730 4 80 5,608 12 8,542 45,299 21 10,071 277 73,468	36 95440% 36 92820% 36 96190% 36.96190% 36 92820% 36.92820% 36.92820% 36.92820% 36.92820% 43.75490% 43.75490% 43.75490% 43.75490%	168,029 12 37,660 20 8,661 20 88,102 74 22,365 91 17,256 43 152 29 55 2,070.90 4 51 3,154 59 19,814 28 9 04 4,393 85 121 35 32,145 91
5100 5110 5120 5130 5140 5420 5440 5480 5520 5530 5600 5612 5620 5630 5660 5680 5690 5770 57710 5800 5820 5830 5840 5840 58570 5870 5870 5870 5910 5920 5930 5940	179,430 40,002 415,099 106,937 78,995 5 151 9,848 23 14,536 75,911 37 16,635 539 (42,308)	101,910 23,454 238,361 60,511 46,730 4 80 5,608 12 8,542 45,299 21 10,071 277 73,468	36 95440% 36 92820% 36 96190% 36.96190% 36 92820% 36.92820% 36.92820% 36.92820% 36.92820% 43.75490% 43.75490% 43.75490% 43.75490%	37,660 20 8,661 20 88,102 74 22,365 91 17,256 43 152 29 55 2,070.90 4 51 3,154 59 19,814 28 9 04 4,393 85 121 35 32,145 91
5110 5120 5130 5140 5420 5440 5440 5540 5540 5550 5530 5660 5660 5660 5680 5700 5710 5800 5820 5830 5840 5850 585	40,002 415,099 106,937 78,995 5 151 9,848 23 14,536 75,911 37 16,635 539 (42,308)	23,454 238,361 60,511 46,730 4 80 5,608 12 8,542 45,299 21 10,071 277 73,468	36 92820% 36 96190% 36.96190% 36 92820% 36.92820% 36.92820% 36.92820% 36.92820% 43.74080% 43.75490% 43.82520% 43.75490%	8,661 20 88,102 74 22,365 91 17,256 43 152 29 55 2,070.90 4 51 3,154 59 19,814 28 9 04 4,393 85 121 35
5120 5130 5140 5420 5440 5480 5520 5530 5600 5612 5620 5630 5660 5680 5690 5710 5800 5820 5830 5840 5850 5840 5850 5840 5850 5870 5840 5850 5870 5880 5900 5910 5920 5930	415,099 106,937 78,995 5 151 9,848 23 14,536 75,911 37 16,635 539 (42,308)	238,361 60,511 46,730 4 80 5,608 12 8,542 45,299 21 10,071 277 73,468	36 96190% 36.96190% 36 92820% 36 92820% 36 92820% 36 92820% 36.92820% 43 74080% 43 75490% 43 82520% 43 75490%	88,102 74 22,365 91 17,256 43 1 52 29 55 2,070.90 4 51 3,154 59 19,814 28 9 04 4,393 85 121 35 32,145 91
5130 5140 5420 5440 5480 5540 5540 5550 5530 5600 5612 5660 5680 5690 57700 5710 5800 5820 5830 5840 5840 5850 5870 5850 5870 5870 5910 5920 5930 5940	106,937 78,995 5 151 9,848 23 14,536 75,911 37 16,635 539 (42,308)	60,511 46,730 4 80 5,608 12 8,542 45,299 21 10,071 277 73,468	36.96190% 36.92820% 36.92820% 36.92820% 36.92820% 36.92820% 43.74080% 43.75490% 43.82520% 43.75490%	22,365 91 17,256 43 1 52 2 9 55 2,070.90 4 51 3,154 59 19,814 28 9 04 4,393 85 121 35 32,145 91
5140 5420 5440 5440 55480 55520 55530 5600 5612 56620 56630 5660 5690 5770 5800 5820 5830 5840 5880 5840 5850 5850 5850 5850 585	78,995 5 151 9,848 23 14,536 75,911 37 16,635 539 (42,308)	46,730 4 80 5,608 12 8,542 45,299 21 10,071 277 73,468	36 92820% 36 92820% 36.92820% 36 92820% 36 92820% 43 74080% 43 75490% 43 62730% 43 82520% 43 75490%	17,256 43 1 52 29 55 2,070.90 4 51 3,154 59 19,814 28 9 04 4,393 85 121 35 32,145 91
5420 5440 5480 55480 55520 5530 5600 5612 5620 5660 5660 5660 5680 5690 5770 58710 5880 5820 58810 58840 58850 58860 58870 55850 58870 59910 59910 59920 5930 59940	5 151 9,848 23 14,536 75,911 37 16,635 539 (42,308)	4 80 5,608 12 8,542 45,299 21 10,071 277 73,468	36 92820% 36.92820% 36 92820% 36 92820% 36.92820% 43 74080% 43 75490% 43 62730% 43 82520% 43 75490%	1 52 29 55 2,070.90 4 51 3,154 59 19,814 28 9 04 4,393 85 121 35 32,145 91
5440 5480 5520 5530 55600 5612 5620 5630 5660 5680 5700 5710 5800 5820 5830 5840 5850 5840 5850 5860 5870 5980 5990 5910 5910 5920 5930 5940	151 9,848 23 14,536 75,911 37 16,635 539 (42,308)	80 5,608 12 8,542 45,299 21 10,071 277 73,468	36.92820% 36 92820% 36 92820% 36.92820% 43 74080% 43 75490% 43 62730% 43 82520% 43 75490%	29 55 2,070.90 4 51 3,154 59 19,814 28 9 04 4,393 85 121 35 32,145 91
5480 5520 5530 5600 5612 5620 5630 5660 5680 5660 5710 5800 5710 5820 5830 5840 5850 5840 5850 5860 5900 5910 5920 5930 5940	9,848 23 14,536 75,911 37 16,635 539 (42,308)	5,608 12 8,542 45,299 21 10,071 277 73,468	36 92820% 36 92820% 36.92820% 43 74080% 43 75490% 43 62730% 43 82520% 43 75490%	2,070.90 4 51 3,154 59 19,814 28 9 04 4,393 85 121 35 32,145 91
5520 5530 5600 5612 5620 5630 5660 5680 5690 5710 5820 5820 5830 5840 5850 5850 5860 5870 5880 5900 5910 5920 5930 5940	23 14,536 75,911 37 16,635 539 (42,308)	12 8,542 45,299 21 10,071 277 73,468	36 92820% 36.92820% 43 74080% 43 75490% 43 62730% 43 82520% 43 75490%	4 51 3,154 59 19,814 28 9 04 4,393 85 121 35 32,145 91
5530 5600 5612 5620 5630 5660 5680 5690 5700 5710 5800 5820 5830 5840 5850 5860 5870 5900 5910 5920 5930 5940	14,536 75,911 37 16,635 539 (42,308)	8,542 45,299 21 10,071 277 73,468	36.92820% 43 74080% 43 75490% 43 62730% 43 82520% 43 75490%	3,154 59 19,814 28 9 04 4,393 85 121 35 32,145 91
5600 5612 5620 5630 5660 5680 5690 5700 5710 5800 5820 5830 5840 5840 5840 5850 5860 5870 5910 5910 5920 5930 5940	75,911 37 16,635 539 (42,308)	45,299 21 10,071 277 73,468	43 74080% 43 75490% 43 62730% 43 82520% 43 75490%	19,814 28 9 04 4,393 85 121 35 32,145 91
5612 5620 5630 5660 5660 55680 5700 5710 5880 5820 5880 5880 5880 5880 5980 5990 5990 599	37 16,635 539 (42,308)	21 10,071 277 73,468	43 75490% 43 62730% 43 82520% 43 75490%	9 04 4,393 85 121 35 32,145 91
5620 5630 5660 5680 5700 5710 5800 5820 5830 5840 5840 5850 5860 5870 5880 5990 5910 5920 5930 5940	16,635 539 (42,308)	10,071 277 73,468	43 62730% 43 82520% 43 75490%	4,393 85 121 35 32,145 91
5630 5660 5680 5690 5700 5710 5800 5820 5830 5840 5850 5860 5870 5880 5900 5910 5920 5930 5940	539 (42,308)	277 73,468	43 82520% 43 75490%	121 35 32,145 91
5660 5680 5690 5700 5710 5800 5820 5830 5840 5840 5850 5860 5870 5880 5900 5910 5920 5930 5940	(42,308)	73,468	43 75490%	32,145 91
5680 5690 5700 5710 5800 5820 5830 5840 5850 5860 5870 5880 5900 5910 5920 5930 5940		•		
5690 5700 5710 5800 5820 5830 5840 5850 5860 5870 5880 5990 59910 5920 5930 5940	103	5/	10.570000/	
5700 5710 5800 5820 5830 5840 5850 5860 5870 5880 5900 5910 5920 5930 5940		400	43 67390%	24 83
5710 5800 5820 5830 5840 5850 5860 5870 5880 5900 5910 5920 5930 5940	213	138	43 62730%	60 39
5800 5820 5830 5840 5850 5860 5870 5880 5900 5910 5920 5930 5940	50,903	30,887	43.62730%	13,474 98
5820 5830 5840 5850 5860 5870 5880 5900 5910 5920 5930 5940	19,557	11,656	43.82520%	5,108 33
5830 5840 5850 5860 5870 5880 5900 5910 5920 5930 5940	35,914	9,782	32 89900%	3,218 24
5840 5850 5860 5870 5880 5900 5910 5920 5930 5940	14,964	9,133	36 84290%	3,365 03
5850 5860 5870 5880 5900 5910 5920 5930 5940	73,468	16,118	37.24740%	6,003 44
5860 5870 5880 5900 5910 5920 5930 5940	25,574	5,284	28 41730%	1,501 68
5870 5880 5900 5910 5920 5930 5940	1,596	83	25 44640%	21 15
5880 5900 5910 5920 5930 5940	142,342	28,477	26 69180%	7,600 89
5900 5910 5920 5930 5940	11,359	2,652	37 01120%	981.56
5910 5920 5930 5940	124,319	905,746	35 23500%	319,139 65
5920 5930 5940	6,534	1,598	36 01670%	575 43
5930 5940	228	150	32 46290%	48 68
5940	28,839	17,752	36.84290%	6,540 43
	516,394	133,946	36.93260%	49,469 56
F0F0	8,220	1,435	28 41730%	407 68
5950	3,415	212	36.22150%	76 74
5960	8,122	768	25 44640%	195.49
5970	14,963	3,215	26 69180%	858.11
5980	8,309	1,497	37 01120%	554.03
9010	25,747	4,321	35 42940%	1,530.90
9020	75,735	15,730	34 95720%	5,498 61
9030	119,511	30,781	35 53580%	10,938.38
9070	46,816	9,539	42.91820%	4,093 79
9080	95,882	16,646	42 96780%	7,152.39
9200	227,653	54,500	37 08620%	20,211 81
9220		34,300	37 08620%	0.42
9250 9250		8,516	37 08620%	3,158 31
	(2)	0,510		
9280	(2) 18,351	//21	37 08620%	(15 43) 1,830 47
9302 9350	(2) 18,351 52	(42)	27 006200/	
9350 Total 5	(2) 18,351	(42) 4,936 55,800	37 08620% 37 08620%	20,694 27

SOUTHWESTERN ELECTRIC POWER COMPANY'S RESPONSE TO OFFICE OF PUBLIC UTILITY COUNSEL'S SECOND REQUEST FOR INFORMATION

Question No. OPUC 2-12:

Please refer to the Direct Testimony of Mr. Andrew R. Carlin, page 31. Please provide copies of any communications with SWEPCO employees regarding the STI compensation awarded during the test year.

Response No. OPUC 2-12:

In addition to the communications to all AEP employees provided in OPUC 2-13 Attachment 1 and both verbal and bulletin board communications of STI goals and year-to-date results, SWEPCO communicated the information in OPUC 2-12 Attachment 1 to its employees.

Prepared By: Andrew R. Carlin Title: Dir Comp & Executive Benefits

Sponsored By: Andrew R. Carlin Title: Dir Comp & Executive Benefits

SOAH Docket No. 473-21-0538 PUC Docket No. 51415 OPUC 2nd RFI, Q. # OPUC 2-12 Attachment 1 Page 1 of 3

SWEPCO Now Page 1 of 6

SWEPCO Now

Posted 3/6/2020 11 50 AM ET I By Peter Main I Category ICP Results

An ICP Message from Malcolm Smoak

Hello SWEPCO Team,

You accomplished a great deal during 2019. SWEPCO had a fantastic year due to your hard work.

Our SWEPCO Incentive Compensation Plan score of 1.60 reflects those results. As you know, our ICP target is 1.0 and our stretch goal is 2.0, so your performance really pushed us forward.

Please take a look at the accompanying 2019 ICP update graphic. A few examples:

We hit our SAIDI target, which demonstrates your emphasis on reliable service for customers.

We exceeded our targets in JD Power corporate citizenship and ease of doing business, which shows our focus on community and taking care of the customers.

We met our financial targets for net income and return on equity.

However, we fell short of our safety targets, specifically our DART rate and total recordable incident rate. As we move forward in 2020, I ask you to focus on Zero Harm. Maintain that commitment. Make 2020 a banner year for safety.

ICP provides a solid measure of our success – for our customers, our company and ourselves as the SWEPCO team.

We – SWEPCO – are a strong team with an even stronger focus on Zero Harm, improving our culture, and growing our business.

SOAH Docket No. 473-21-0538 PUC Docket No. 51415 OPUC 2nd RFI, Q. # OPUC 2-12 Attachment 1 Page 2 of 3


SWEPCO Now Page 2 of 6

As you enjoy "ICP Friday," please know that I appreciate everything you have done. and continue to do – to make SWEPCO a success.
Maleolin
Malcolm
Reactions
No one has yet reacted publicly
Subscribe to this blog and receive an email alert whenever a new post is published.
SUBSCRIBE TO THIS BLOG
Blog Home
About This Blog
About his blog
Blog Post Archive
Search This Blog
Recent Posts
SWEPCO ranked highest in segment for customer satisfaction by J.D. Power
Formular and the second department of Washing House for Washing and
Employees deliver boxes of donations to Woody's Home for Veterans
Preventing COVID-19 in close quarters
PHOTOS: More Hurricane Zeta Mutual Aid
Three dates added for SWEPCO Safe Space Discussions

SOAH Docket No. 473-21-0538 PUC Docket No. 51415 OPUC 2nd RFI, Q. # OPUC 2-12 Attachment 1 Page 3 of 3

ICPUpdate







Financial

Net Income 1.36 Return on Equity 1.07

Customer

JD Power Corporate Citizenship Score 2.0 Ease of Doing Business 2.0

Workforce Development

DART rate, employee/contracor 0
Total recordable incident rate 0

Proactive safety measures **2.0**Advanced Distribution Line Training **2.0**Culture Action Plans **2.0**

Operational Excellence

SAIDI 1.01 SAIDI Workplan 2.0 Sustainable efficiency gains 2.0

Strategic Operational Goals 2.0

SOUTHWESTERN ELECTRIC POWER COMPANY'S RESPONSE TO OFFICE OF PUBLIC UTILITY COUNSEL'S SECOND REQUEST FOR INFORMATION

Question No. OPUC 2-13:

Please refer to the Direct Testimony of Mr. Andrew R. Carlin, page 31. Please provide copies of any communications with AEPSC employees with respect to the STI compensation awarded during the test year, both before and after the STI compensation awards were made to the employees.

Response No. OPUC 2-13:

Because AEP maintains a large number of STI plans, each operating company and business unit with a separate plan is largely responsible for communicating STI goals and results to their employees. Please see OPUC 2-13 Attachment 1 for the AEP and SWEPCO communication of 2019 STI results. Each group also generally posts their STI goals and year-to-date results on bulletin boards and in other locations where employees will notice them but such postings are not stored. AEP and SWEPCO management often also speak to STI goals and results when addressing groups of employees.

Prepared By: Andrew R. Carlin Title: Dir Comp & Executive Benefits

Sponsored By: Andrew R. Carlin Title: Dir Comp & Executive Benefits

AEP Now: Incentive Compensation Plan Funding Score 172.3 Percent for 2019

News & Events



ENVIRONMENTAL

FINANCIAL PERFORMANCE

Incentive Compensation Plan Funding Score 172.3 Percent for 2019

Monday, March 2, 2020 at 6:00 AM ET • Comments: 18 • View Comments

Akıns thanks employees for their hard work and commitment to AEP's strategy

Continued focus on safety and Zero Harm emphasized

To All AEP Employees:

I want to sincerely thank you for your contributions to AEP's success in 2019. Your hard work and commitment to our strategy was the foundation for our strong performance last year, and I am thrilled that we were able to achieve an overall Incentive Compensation Plan (ICP) funding score of 172.3 percent.



NIck Akins speaks at a leadership meeting in 2019

Our 2019 ICP score reflects our performance on key initiatives designed to benefit our employees, customers and shareholders:

Operating Earnings Performance (70 percent weight) – 195.5 percent score

Your commitment to managing costs and growing the business helped deliver \$4.24 operating earnings per share (EPS) in 2019 and a 195.5 percent score. Strong regulatory results, favorable weather, your commitment to cost savings initiatives,

AEP Now: Incentive Compensation Plan Funding Score 172.3 Percent for 2019

favorable Transmission results, lower interest rates and our investment in renewables supported our earnings performance last year.

Safety & Compliance (10 percent weight) – 25.0 percent score

Safety is the most important part of our job. Our goal is Zero Harm. Every employee should go home every day in the same or better condition than they came to work. In 2019, we lost an employee and two contractors -- this is a reminder why it is so important that all of us continue our efforts towards Zero Harm. The DART rate improved slightly above threshold the Severity Rate and North American Electric Reliability Corporation (NERC) compliance results were below threshold, while environmental stewardship achieved above target results with zero applicable enforcements.

Cost Control (4 percent weight) - 200.0 percent score

Your commitment to sustainable efficiency gains exceeded expectations and helped AEP achieve our O&M budget.

Infrastructure Investment (9 percent weight) – 157.8 percent score

We were able to achieve nearly all of our infrastructure investment goals for 2019. We achieved above-target results for putting new Transmission assets into service and very strong regulated and competitive renewables investment results. We achieved target results for customer-targeted regulated renewables and Transmission capital investments. Our competitive business supported earnings growth with the acquisition of wind farms while the regulated side was able to advance the North Central Wind Project.

Customer Experience(4 percent weight) – 140.0 percent score

Our wires reliability came in slightly below target and customer satisfaction results were at target. Strong performance in achieving our reliability work plans and new service connection initiative helped attain an above target score. Wires reliability was impacted by severe weather and extended outages, which also negatively impacted customer satisfaction.

Culture and Employee Engagement (3 percent weight) – 170.0 percent score

AEP's culture score continues to improve, coming in at the 87th percentile. We also exceeded our work plan for the Future of Work initiative. Employee diversity continued to improve during 2019; however, we did not quite hit all of our targets. Continuing to strengthen diversity and inclusion at AEP is essential for our future success.

Page 3 of 5

AEP Now: Incentive Compensation Plan Funding Score 172.3 Percent for 2019

ICP funding allocations are based on business unit and operating company performance against their specific ICP goals. In 2019, business unit and operating company scores ranged from 160 percent to 200 percent of target. ICP awards for most employees also are adjusted based on individual employee performance.

Thank you again for your outstanding work last year and your ongoing commitment to AEP.

Sincerely,

With

Nick Akins, AEP chairman, president and chief executive officer

Reactions

18 individuals have reacted publicly; 0 highlighted



Rhonda L Eagon Canton, OH, on 03/02/20 10 58 AM I appreciate it . . . Thank you.



Anthony Gulley Tulsa, OK, on 03/02/20 11 27 AM This is much appreciated beyond category. Thank you to all who make this a viable and successful employee benefit. I have been employed here since 1985, and there hasn't always been a reward or sharing benefit like this. Thank you.



Dodie A Saunders Columbus. OH, on 03/02/20 11 39 AM Thank you. Most appreciated. I love working with wonderful people and an awesome company!



Stephen Broderson St. Clairsville, OH, on 03/02/20 12:57 PM Thank you, to the AEP family. It is a pleasure working with all of you.

Page 4 of 5

AEP Now: Incentive Compensation Plan Funding Score 172.3 Percent for 2019



Nedra A Edwards Groveport, OH, on 03/02/20 3·02 PM
Thank you AEP, it is a pleasure working for the company.



Kimberly L Myles Fort Wayne, IN, on 03/03/20 8 33 AM I appreciate it.



Carmen M Ortega Columbus, OH, on 03/03/20 10:16 AM Thank you!!!



Brian A Wieczorek Bridgman, MI, on 03/03/20 3·12 PM
So Blessed to work for AEP... Although this ICP is hard earned, there are too many folks in this country that are underappreciated... But not here... THANK YOU AEP Board of Directors, THANK YOU NICK !!!

My family, church, and community will reap the rewards of an unanticipated boost in economy...



Denzil L Welsh Jr. Columbus, OH, on 03/04/20 8.43 AM This is a good week. In celebration, I bought a few Baconators for some team members. It's a solid sandwich, Bacon/Sausage/Egg/Bacon.



Deborah Morgan Tulsa, OK, on 03/04/20 9 07 AM Thank You!



Aaron J Austin Columbus, OH, on 03/04/20 2 23 PM Thank you for a great 2019.

AEP Now: Incentive Compensation Plan Funding Score 172.3 Percent for 2019

Page 5 of 5



Jon M Kline Fort Wayne. IN. on 03/05/20 11 04 AM Thank you AEP. Very much appreciated.



Danielle M Satkoski Buchanan, MI. on 03/05/20 2·58 PM Thank you!



Gary A McGee Bridgman, Ml. on 03/06/20 5:16 AM Employment is a privilege, and a bonus is greatly appreciated. Thank you AEP!



 $\label{lossym} {\it Joseph~A~Lopez~Corpus~Christi,~TX,~on~03/06/20~8:37~AM} \\ {\it Thanks~for~all~the~great~things~this~company~does~for~its~employees~,i~will~always~be~grateful~for~all~AEP~has~done~for~me~and~my~family~}$



Carolyn J Martin Columbus. OH, on 03/06/20 9.20 AM Thanks AEP for a great 2019. This ICP is much appreciated!



Phillip Gonzalez Victoria, TX, on 03/09/20 9·56 AM The ICP is very much appreciated, thanks to everyone that worked to make it possible.



Rosie Underwood Pharr, TX, on 03/09/20 11 21 AM Thanks to all who made this possible; very blessed to work for this amazing company. Thank you Mr. Atkins.

SOAH Docket No. 473-21-0538
PUC Docket No. 51415
OPUC 2nd RFI, Q. # OPUC 2-13
Attachment 1
Page 6 of 8
Page 1 of 6

SWEPCO Now

SWEPCO Now

Posted: 3/6/2020 11 50 AM ET | By Peter Main | Category ICP Results

An ICP Message from Malcolm Smoak

Hello SWEPCO Team.

You accomplished a great deal during 2019. SWEPCO had a fantastic year due to your hard work.

Our SWEPCO Incentive Compensation Plan score of 1.60 reflects those results. As you know, our ICP target is 1.0 and our stretch goal is 2.0, so your performance really pushed us forward.

Please take a look at the accompanying 2019 ICP update graphic. A few examples:

We hit our SAIDI target, which demonstrates your emphasis on reliable service for customers.

We exceeded our targets in JD Power corporate citizenship and ease of doing business, which shows our focus on community and taking care of the customers.

We met our financial targets for net income and return on equity.

However, we fell short of our safety targets, specifically our DART rate and total recordable incident rate. As we move forward in 2020, I ask you to focus on Zero Harm. Maintain that commitment. Make 2020 a banner year for safety.

ICP provides a solid measure of our success – for our customers, our company and ourselves as the SWEPCO team.

We – SWEPCO – are a strong team with an even stronger focus on Zero Harm, improving our culture, and growing our business.

SOAH Docket No. 473-21-0538 PUC Docket No. 51415 OPUC 2nd RFI, Q. # OPUC 2-13 Attachment 1 Page 7 of 8 Page 2 of 6

SWEPCO Now


As you enjoy "ICP Friday," please know that I appreciate everything you have done. and continue to do – to make SWEPCO a success.

Maleolm
Malcolm
Reactions No one has yet reacted publicly
Subscribe to this blog and receive an email alert whenever a new post is published. SUBSCRIBE TO THIS BLOG
Blog Home About This Blog
Blog Post Archive Search This Blog
Recent Posts
SWEPCO ranked highest in segment for customer satisfaction by J.D. Power
Employees deliver boxes of donations to Woody's Home for Veterans
Preventing COVID-19 in close quarters
PHOTOS: More Hurricane Zeta Mutuai Aid
Three dates added for SWEPCO Safe Space Discussions

SOAH Docket No. 473-21-0538 PUC Docket No. 51415 OPUC 2nd RFI, Q. # OPUC 2-13 Attachment 1

ICP Update







Financial

Net Income 1.36 Return on Equity 1.07

Customer

JD Power Corporate Citizenship Score 2.0 Ease of Doing Business 2.0

Workforce Development

DART rate, employee/contracor 0
Total recordable incident rate 0

Proactive safety measures 2.0 Advanced Distribution Line Training 2.0 Culture Action Plans 2.0

Operational Excellence

SAIDI 1.01 SAIDI Workplan 2.0 Sustainable efficiency gains 2.0

Strategic Operational Goals 2.0

SOUTHWESTERN ELECTRIC POWER COMPANY'S RESPONSE TO OFFICE OF PUBLIC UTILITY COUNSEL'S SECOND REQUEST FOR INFORMATION

Question No. OPUC 2-14:

Please refer to the Direct Testimony of Mr. Andrew R. Carlin, page 31. Please provide copies of any communications, presentations or meeting notes concerning the change in the funding measure for the Annual Incentive Plan being based on a "balanced scorecard of performance measures" to being based entirely on AEP's Operating Earnings per Share.

Response No. OPUC 2-14:

Please OPUC 2-14 Attachment 1.

Prepared By: Andrew R. Carlin Title: Dir Comp & Executive Benefits

Sponsored By: Andrew R. Carlin Title: Dir Comp & Executive Benefits

SOAH Docket No. 473-21-0538 PUC Docket No. 51415 OPUC 2nd RFI, Q. # OPUC 2-14 Attachment 1 Page 1 of 8

From:

Andy Carlin

To:

Sarah R Smithhisler; Thomas G Berkemeyer

Subject:

FW: HRC Resolution and Revised Short Term Incentive Plan

Date: Attachments: Friday, May 1, 2020 5:58:03 PM

Revised STI Draft May 2020.pptx unanimous writen consent of HRC for 2020 ICP.doc

Tom and Sarah,

Are either of you available to make this change?

From: Lana L Hillebrand < Ihillebrand@aep.com>

Sent: Friday, May 1, 2020 5:55 PM

To: Andy Carlin <arcarlin@aep.com>; Julius Cox <jcox2@aep.com>; Thomas G Berkemeyer

<tgberkemeyer@aep com>

Cc: Nick Akıns <nkakins@aep.com>; Davıd M Feinberg <dmfeinberg@aep.com>

Subject: FW: HRC Resolution and Revised Short Term Incentive Plan

Talked to Ralph – He is good with the revised plan design and the slides. He would like one addition to the unanimous written consent. "Whereas the HRC retains the right to exercise discretion on these awards in the plan" – add to the resolution

Tom – The thought process behind the addition was instead of using the strategic objectives/operational goals as a modifier – the HRC potentially could use those goals as an objective way to apply positive or negative discretion.

Please revise and send to Andy and I We are going to post later this evening or first thing in the morning. We are awaiting a cover note from Ralph.

Thanks to all,

Lana

From: Lana L Hillebrand

Sent: Friday, May 1, 2020 2:53 PM

To: Ralph Crosby (crosbyrdjr@gmail.com>

 $\textbf{Cc:} \ \ \text{Nick Akıns} \ (\underline{nkakıns@aep.com}) < \underline{nkakıns@aep.com} >; \ \text{Julius Cox} < \underline{Jcox2@aep.com} >; \ \text{Andy Carlin}$

<arcarlin@aep.com>

Subject: HRC Resolution and Revised Short Term Incentive Plan

Ralph – Thank you for your thoughts last evening. As we discussed this morning, Management is recommending due to the COVID19 pandemic that we revise the 2020 short term incentive plan to be solely EPS based during this crisis year. See 1st attachment – depicting new slope of the incentive line as well as the mechanics of the plan. We will ensure that the strategic and operational goals stay in front of management and employees and will continue to report the progress to the HRC even though their measures are not part of the plan.

SOAH Docket No. 473-21-0538 PUC Docket No. 51415 OPUC 2nd RFI, Q. # OPUC 2-14 Attachment 1 Page 2 of 8

The 2nd attachment is the resolution for the HRC to approve.

Please review and I will give you a call to discuss and we can get posted on Boardvantage after any edits.

Talk with you soon,

Lana

AEP CONFIDENTIAL

SOAH Docket No. 473-21-0538 PUC Docket No. 51415 OPUC 2nd RFI, Q. # OPUC 2-14 Attachment 1 Page 3 of 8

Annual Incentive Compensation

BOUNDLESS ENERGY"

Company-wide Funding Measure (Action Item) 2020 Executive Council Scorecard and

Action Item



Proposed Revision 2020 STI Funding


Performance Category	Proposed 2020	Original 2020	2019	2018	2017
Funding Measures		•			
Operating Earnings Per Shares	100%	60%	70%	70%	70%
Safety & Compliance	-	10%	10%	10%	12%
Strategic Initiatives		30%	20%	20%	18%
Safety DART Rate*	-	-	-	-	-
Zero Harm*	-	-	_	-	_
*Included in Safety & Compliance	performance	category		•	

SOAH Docket No. 473-21-0538
PUC Docket No. 51415
OPUC 2nd RFI, Q. # OPUC 2-14
Attachment 1
Page 4 of 8

Action Item



Proposed Revision 2020 Operating EPS Measure (100% weight)



SOAH Docket No. 473-21-0538 PUC Docket No. 51415 OPUC 2nd RFI, Q. # OPUC 2-14 Attachment 1 Page 6 of 8

AMERICAN ELECTRIC POWER COMPANY, INC. HUMAN RESOURCES COMMITTEE

UNANIMOUS WRITTEN CONSENT BY DIRECTORS WITHOUT A MEETING

The undersigned, being all of the directors of the Human Resources Committee (the "Committee") of the Board of Directors of American Electric Power Company, Inc. (the "Company"), a New York corporation, do hereby adopt in writing without a meeting the following actions:

WHEREAS, the Human Resources Committee (the "<u>Committee</u>") of the Board of Directors of American Electric Power Company, Inc., a New York corporation (the "<u>Company</u>"), oversees the Company's Annual Incentive Plan; and

WHEREAS, the Committee has previously approved the 2020 Annual Incentive Plan that was based on financial performance, safety and strategic objectives; and

WHEREAS, the Company is responding to the global outbreak of the novel coronavirus (COVID-19) by taking steps to mitigate the potential risks posed by its spread; and

WHEREAS, many businesses have been forced to limit or reduce their operations in response to the COVID-19 outbreak, which have had a significant impact on the Company's commercial and industrial sales; and

WHEREAS, the Committee has determined because of those economic uncertainties that it should amend the Company's 2020 Annual Incentive Plan to focus on Operating Earnings Per Share;

NOW, THEREFORE, BE IT

RESOLVED, that upon review and consideration, the Committee hereby approves amending the 2020 Annual Incentive Plan to eliminate the safety and strategic objectives **as performance metrics** and hereby makes 2020 Operating Earnings Per Share the sole performance metric, upon which 100% of the 2020 annual cash incentive payout will be based: and further

RESOLVED, that the Committee approves the 2020 Operating Earnings Per Share required for threshold, target and maximum payouts as set forth in Attachment A; and further

RESOLVED, that the officers of the Company be, and each of them hereby is, authorized and empowered to execute and deliver such documents and instruments, and to do such other acts and things as such officer may deem necessary or appropriate to implement the foregoing resolutions.

SOAH Docket No. 473-21-0538 PUC Docket No. 51415 OPUC 2nd RFI, Q. # OPUC 2-14 Attachment 1 Page 7 of 8

EFFECTIVE AS OF May 1, 2020.


J. Barnie Beasley, Jr.	Stephen S. Rasmussen
Ralph D. Crosby, Jr.	Oliver G. Richard, III
Richard C. Notebaert	Sara M. Tucker



Action Item



Proposed Revision 2020 Operating EPS Measure (100% weight)



SOAH Docket No. 473-21-0538
PUC Docket No. 51415
OPUC 2nd RFI, Q. # OPUC 2-14
Attachment 1

SOUTHWESTERN ELECTRIC POWER COMPANY'S RESPONSE TO OFFICE OF PUBLIC UTILITY COUNSEL'S SECOND REQUEST FOR INFORMATION

Question No. OPUC 2-15:

Please refer to Schedule H-5.3b, sponsored by Mr. Michael A. Baird, page 4. Please provide a detailed description of the capital additions and associated costs at Dolet Hills for each of the years 2016, 2017, 2018 and 2019 that are included in the amounts shown on the line item WSX111023.

Response No. OPUC 2-15:

Please see OPUC 2-15 Attachment 1.xlsx for a description of the capital additions and associated costs at Dolet Hills for each of the years 2016, 2017, 2018 and 2019 that are included in the amounts shown on the line item WSX111023.

Prepared By: Jason A. Cash Title: Accounting Sr Mgr

Sponsored By: Michael A. Baird Title: Mng Dir Acctng Policy & Rsrch

Sponsored By: Monte A. McMahon Title: VP Generating Assets SWEPCO

					FERC Act		Page 1 of
Company	Budget ID	Work Order	Work Order Descr	Utility Account	Code	Month Number	Activity Cost
Southwestern Electric Pwr - Gen	WSX111023	W0025736	DHPS 1 - REPLACE THICKNER RAKE	31100 - Structures, Improvemnt-Coal	Addition	201601	(\$479 32)
Southwestern Electric Pwr - Gen	WSX111023	W0026177	DPNO - Pl Upgrade & Redundancy	39100 - Office Furniture, Equipment	Addition	201601	\$321 71
Southwestern Electric Pwr - Gen	WSX111023	W0023209	DHPS 1 - Replace/Upgrade Burne	31200 - Boiler Plant Equip-Coal	Addition	201601	(\$1.68)
Southwestern Electric Pwr - Gen	W5X111023		DHPS 1 - SO2 AREA GRATING	31200 - Boiler Plant Equip-Coal	Addition	201601	\$516 86
Southwestern Electric Pwr - Gen	WSX111023		DHPS-Rpice Gen Fix Connectors	31400 - Turbogenerator Units-Coal	Addition	201601	(\$1,448.42)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL SLUD CONV BLTS	31200 - Boiler Plant Equip-Coal	Addition	201602	(\$13,619 72)
Southwestern Electric Pwr - Gen	WSX111023		DPNO - PI Upgrade & Redundancy	39100 - Office Furniture, Equipment	Addition	201602	\$2 72
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - Rbld "A" PA Fan Rotor	31100 - Structures, Improvemnt-Coal	Addition	201602	\$16,126 25
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - Replace/Upgrade Burner	31200 - Boiler Plant Equip-Coal	Addition	201602	(\$28,255.54)
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - Rbld "A" PA Fan Rotor DHPS 1 - REP LIG CONV BELT	31200 - Boiler Plant Equip-Coal	Addition	201602	(\$16,126.25)
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - SO2 AREA GRATING	31100 - Structures, Improvemnt-Coal 31200 - Boiler Plant Equip-Coal	Addition Addition	201602 201602	\$13,319 72 \$17 31
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS-Rpice Gen Fix Connectors	31400 - Turbogenerator Units-Coal	Addition	201602	(\$49.02)
Southwestern Electric Pwr - Gen	WSX111023		DHPS-RPLCE UPPER LOOP TNK LNR	31200 - Boiler Plant Equip-Coal	Addition	201602	(\$43,218.23)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL COMB AIR CRS DMP	31400 - Turbogenerator Units-Coal	Addition	201603	\$63,859 25
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPR PARK LOT	39000 - Structures and Improvements	Addition	201603	\$97,734 39
Southwestern Electric Pwr - Gen	WSX111023	W0025379	DHPS 1 - REP LIG CONV BELT	31100 - Structures, Improvemnt-Coal	Addition	201603	(\$1,743.15)
Southwestern Electric Pwr - Gen	WSX111023	W0025610	DHPS 1 - REPAIR/RPL LIG REC CON	31100 - Structures, Improvemnt-Coal	Addition	201603	\$10,260 51
Southwestern Electric Pwr - Gen	WSX111023	W0026726	DHPS 1 - RPL MISC HVAC UNITS	31200 - Boiler Plant Equip-Coal	Addition	201603	\$31,113 26
Southwestern Electric Pwr - Gen	WSX111023	W0026510	DHPS 1 - PI System Upgrades	39100 - Office Furniture, Equipment	Addition	201603	\$18,259 71
Southwestern Electric Pwr - Gen	W5X111023	W0025664	DHPS - RPL FGD DUC LNRS, EXP JTS	31200 - Boiler Plant Equip-Coal	Addition	201603	\$245,922 98
Southwestern Electric Pwr - Gen	WSX111023	W0026175	DHPS 1 - Repl LIG Conv Belt	31100 - Structures, Improvemnt-Coal	Addition	201603	(\$7,371 46)
Southwestern Electric Pwr - Gen	WSX111023	W0026252	DHPS 1 - RPL MCB ANNUNCIATOR	31200 - Boiler Plant Equip-Coal	Addition	201603	\$317 38
Southwestern Electric Pwr - Gen	WSX111023	W0026831	DHPS 1 - UPG COOL TWR MTR FDS	31400 - Turbogenerator Units-Coal	Addition	201603	\$24,948 50
Southwestern Electric Pwr - Gen	W\$X111023		DHPS 1 - RPL FGD EXP JOINTS	31200 - Boiler Plant Équip-Coal	Addition	201603	\$5,782 47
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL BOIL WTR STBLWR	31200 - Boiler Plant Equip-Coal	Addition	201603	\$128,038 84
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL LWR LP SPR HDRS	31200 - Boiler Plant Equip-Coal	Addition	201603	\$184,536 33
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - PUR/INS PLT SFT UPG	31100 - Structures, Improvemnt-Coal	Addition	201603	\$51,716 64
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - UPG SO2 AREA LGT-2015	31200 - Boiler Plant Equip-Coal	Addition	201603	\$31,698 42
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - INST TRUCK SCALES	31100 - Structures, Improvemnt-Coal	Addition	201603	\$114,038 47
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - INSTALL BOILR WTR SYS	31200 - Boiler Plant Equip-Coal	Addition	201603	(\$2,743.70)
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO-Rpl Voltage Regulator DHPS 1 - RPL CONTR SIGN IN BLD	31500 - Accessory Elect Equip-Coal 31100 - Structures, Improvemnt-Coal	Addition Addition	201603 201603	\$108,059 89 \$97,950 19
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO - Pur Golf Cart for PDM use	31600 - Misc Pwr Plant Equip-Coal	Addition	201603	(\$46 23)
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - RPL FGD PIPING	31200 - Boiler Plant Equip-Coal	Addition	201603	\$80,486 23
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL RING GRAN	31200 - Boiler Plant Equip-Coal	Addition	201603	\$41,536 52
Southwestern Electric Pwr - Gen	WSX111023		Additional Radio Channels at D	39700 - Communication Equipment	Addition	201603	\$4,854 69
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL MISC VALVES	31600 - Misc Pwr Plant Equip-Coal	Addition	201603	\$70,259 46
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL SLUD CONV BLTS	31200 - Boiler Plant Equip-Coal	Addition	201603	\$1,795 07
Southwestern Electric Pwr - Gen	WSX111023	W0026257	DHPS 1 - RP BLR FURN COUT	31200 - Boiler Plant Equip-Coal	Addition	201603	\$127,323 23
Southwestern Electric Pwr - Gen	WSX111023	W0026344	DHPS 1 - PURCH TOOLS - 2015	31600 - Misc Pwr Plant Equip-Coal	Addition	201603	\$31,255 39
Southwestern Electric Pwr - Gen	WSX111023	W0027030	DHPS 1 - RPL FGD CONV FRWK	31200 - Boiler Plant Equip-Coal	Addition	201603	\$15,471 99
Southwestern Electric Pwr - Gen	WSX111023		DPNO - Rpl Cooling Twr Demisters	31400 - Turbogenerator Units-Coal	Addition	201603	\$51,260 53
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - REP/RPL LIG CON 2015	31100 - Structures, Improvemnt-Coal	Addition	201603	(\$35,971 86)
Southwestern Electric Pwr - Gen	WSX111023		DHPS - RPL THICKNER RAKE	31100 - Structures, Improvemnt-Coal	Addition	201603	\$140,401 55
Southwestern Electric Pwr - Gen	W5X111023		Modernization of DHPS	31100 - Structures, Improvemnt-Coal	Addition	201603	\$232 99
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - REF/UPG CIRC WTR PMPS	31600 - Misc Pwr Plant Equip-Coal	Addition	201603	\$45,457 54
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - UPG 1F1 AND 1F2 MCC	31200 - Boiler Plant Equip-Coal	Addition	201603	\$38,172 36
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - INS BOIL ELV RLS & BFS	31200 - Boiler Plant Equip-Coal	Addition	201603	\$20,217 61
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO Upg DCS Equip DHPS 1 - Replace CO2 Tank-2014	31200 - Boiler Plant Equip-Coal 31200 - Boiler Plant Equip-Coal	Addition Addition	201603 201603	\$244,747 27 \$93,865 42
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - RPL FGD DCT LNRS	31200 - Boiler Plant Equip-Coal	Addition	201603	\$257,592 14
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - UPG PLT LGT TEMP 2015	31200 - Boiler Plant Equip-Coal	Addition	201603	\$45,890 69
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL BOIL EXP JTS	31200 - Boiler Plant Equip-Coal	Addition	201603	\$69,876 07
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL FGD PUMP BASES	31200 - Boiler Plant Equip-Coal	Addition	201603	\$15,628 90
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL MCB ANNUN SYS	31200 - Boiler Plant Equip-Coal	Addition	201603	\$125,469 58
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RENE SURG TANK	31200 - Boiler Plant Equip-Coal	Addition	201603	\$18,167 74
Southwestern Electric Pwr - Gen	WSX111023	W0026508	DHPS 1 - RPL MAIN VAC PUMP	31200 - Boiler Plant Equip-Coal	Addition	201603	\$28,093 01
Southwestern Electric Pwr - Gen	WSX111023	W0026584	DHPS 1 - RPL AUX VACUUM PUMP	31200 - Boiler Plant Equip-Coal	Addition	201603	\$15,268 18
Southwestern Electric Pwr - Gen	WSX111023	W0026508	DHPS 1 - RPL MAIN VAC PUMP	31200 - Boiler Plant Equip-Coal	Addition	201604	\$2 56
Southwestern Electric Pwr - Gen	W\$X111023	W0026174	DPNO Upg DCS Equip	31200 - Boiler Plant Equip-Coal	Addition	201604	\$19,844 21
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL FGD PUMP BASES	31200 - Boiler Plant Equip-Coal	Addition	201604	(\$0.10)
Southwestern Electric Pwr - Gen	WSX111023	W0026258	DPNO - Rpl Cooling Twr Demisters	31400 - Turbogenerator Units-Coal	Addition	201604	\$491 01
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL AUX VACUUM PUMP	31200 - Boiler Plant Equip-Coal	Addition	201604	(\$3.31)
Southwestern Electric Pwr - Gen	W\$X111023		DHPS 1 - Replace Air Heater Th	31200 - Boiler Plant Equip-Coal	Addition	201604	(\$2,916 18)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - INSTALL BOILR WTR SYS	31200 - Boiler Plant Equip-Coal	Addition	201604	(\$13.86)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL SLUD CONV BLTS	31200 - Boiler Plant Equip-Coal	Addition	201604	(\$7,495.81)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - PURCH TOOLS - 2015	31600 - Misc Pwr Plant Equip-Coal	Addition	201604	(\$0.17)
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - RPL MISC VALVES	31600 - Misc Pwr Plant Equip-Coal	Addition Addition	201604	\$135 03
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - RPL BOIL WTR STBLWR DHPS 1 - RPL RING GRAN	31200 - Boiler Plant Equip-Coal 31200 - Boiler Plant Equip-Coal	Addition	201604 201604	\$24 99
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - RPL AIR HTR CLR SEALS	31200 - Boiler Plant Equip-Coal	Addition	201604	(\$0 66) (\$4,535 48)
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - Repl LIG Conv Belt	31100 - Structures, Improvemnt-Coal	Addition	201604	(\$4,535.46) \$295.38
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - REPLICONTR SIGN IN BLD	31100 - Structures, Improvemnt-Coal 31100 - Structures, Improvemnt-Coal	Addition	201604	\$295.38 (\$1,762.11)
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - RPL LWR LP SPR HDRS	31200 - Structures, Improvemint-coal	Addition	201604	\$110,513 39
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - Replace CO2 Tank-2014	31200 - Boiler Plant Equip-Coal	Addition	201604	(\$31.78)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL COMB AIR CRS DMP	31400 - Turbogenerator Units-Coal	Addition	201604	(\$63.06)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - PUR/INS PLT SFT UPG	31100 - Structures, Improvemnt-Coal	Addition	201604	\$11 24
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - UPG SO2 AREA LGT-2015	31200 - Boiler Plant Equip-Coal	Addition	201604	\$0 80
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL SLUD CONV FRWK	31200 - Boiler Plant Equip-Coal	Addition	201604	(\$3,525.00)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - INST TRUCK SCALES	31100 - Structures, Improvemnt-Coal	Addition	201604	\$6,959 61
Southwestern Electric Pwr - Gen	WSX111023	W0027029	DHPS 1 - RPR PARK LOT	39000 - Structures and Improvements	Addition	201604	\$0 74

							Page 2 of
Company	Budget ID	Work Order	Work Order Descr	Utility Account	FERC Act Code	Month Number	Activity Cost
Southwestern Electric Pwr - Gen	WSX111023	W0026725	DHPS 1 - RPL CONTR SIGN IN BLD	31100 - Structures, Improvemnt-Coal	Addition	201605	\$274 49
Southwestern Electric Pwr - Gen	WSX111023	W0023442	DHPS 1 - Replace Air Heater Th	31200 - Boiler Plant Equip-Coal	Addition	201605	\$457 41
Southwestern Electric Pwr - Gen	WSX111023	W0025320	DHPS 1 - RPL AIR HTR CLR SEALS	31200 - Boiler Plant Equip-Coal	Addition	201605	\$711 40
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL SLUD CONV BLTS	31200 - Boiler Plant Equip-Coal	Addition	201605	\$1,175 73
Southwestern Electric Pwr - Gen	WSX111023		DPNO Upg DCS Equip	31200 - Boiler Plant Equip-Coal	Addition	201605	(\$2,935 61)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL LWR LP SPR HDRS	31200 - Boiler Plant Equip-Coal	Addition	201605	(\$16,345 51)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - INST TRUCK SCALES	31100 - Structures, Improvemnt-Coal	Addition	201605	(\$1 022 52)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL SLUD CONV FRWK	31200 - Boiler Plant Equip-Coal	Addition	201605	\$552 90
Southwestern Electric Pwr - Gen	WSX111023		Modernization of DHPS	31100 - Structures, Improvemnt-Coal	Addition	201606	\$4,663 28
Southwestern Electric Pwr - Gen	WSX111023		DPNO Upg DCS Equip	31200 - Boiler Plant Equip-Coal	Addition	201606	\$1,320 53
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - REF/UPG CIRC WTR PMPS DHPS 1 - RPR PARK LOT	31600 - Misc Pwr Plant Equip-Coal 39000 - Structures and Improvements	Addition	201606 201606	\$24,121 19 \$1,141 29
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - RLNE SURG TANK	31200 - Structures and improvements	Addition Addition	201607	\$10,024 65
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - RPR PARK LOT	39000 - Structures and Improvements	Addition	201607	\$62 79
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL FGD DCT LNRS	31200 - Boiler Plant Equip-Coal	Addition	201607	(\$20,345 41)
Southwestern Electric Pwr - Gen	WSX111023	W0026174	DPNO Upg DCS Equip	31200 - Boiler Plant Equip-Coal	Addition	201607	\$72 65
Southwestern Electric Pwr - Gen	WSX111023	W0026340	DHPS 1 - RPL FGD PIPING	31200 - Boiler Plant Equip-Coal	Addition	201608	\$222 47
Southwestern Electric Pwr - Gen	WSX111023	W0026341	DHPS 1 - UPG PWR FEED RDL STCK	31100 - Structures, Improvemnt-Coal	Addition	201608	\$13,313 70
Southwestern Electric Pwr - Gen	WSX111023	W0023449	DHSP 1 - Replace Misc Valves	31200 - Boiler Plant Equip-Coal	Addition	201608	(\$6 546 88)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - PURC COMPUTERS-2015	39111 - Office Equip - Computers	Addition	201608	\$7,828 82
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - Replace Pulverizer Yo	31200 - Boiler Plant Equip-Coal	Addition	201608	(\$4,926 50)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - UPG PLT LGT TEMP 2015	31200 - Boiler Plant Equip-Coal	Addition	201608	(\$2,225 50)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - UPG COOL TWR MTR FDS	31400 - Turbogenerator Units-Coal	Addition	201608	(\$2,696 91)
Southwestern Electric Pwr - Gen	WSX111023		DPNO - UPG TURB CRANE CNTRL	31200 - Boiler Plant Equip-Coal	Addition	201608	\$50,564 18
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - Replace TDBFP Rotatin DHPS1-REPLACE LIGNITE CONVEYOR	31200 - Boiler Plant Equip-Coal 31200 - Boiler Plant Equip-Coal	Addition	201608 201608	(\$142 61) \$60 00
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS - RPL THICKNER RAKE	31100 - Structures, Improvemnt-Coal	Addition Addition	201608	\$535 46
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL SLD TRMT BLD ROOF	31100 - Structures, Improvemnt-Coal	Addition	201608	\$33,455 34
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL WATER TRUCK	31200 - Boiler Plant Equip-Coal	Addition	201608	\$57,944 49
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - Refurbish FGD, Boiler	31100 - Structures, Improvemnt-Coal	Addition	201608	(\$3,271 61)
Southwestern Electric Pwr - Gen	WSX111023	W0023450	DHPS 1 - Replace Transmitters	31200 - Boiler Plant Equip-Coal	Addition	201608	(\$1,125 93)
Southwestern Electric Pwr - Gen	WSX111023	W0024680	DHPS 1- RPLCE SLUDGE CONV FRAME	31200 - Boiler Plant Equip-Coal	Addition	201608	(\$3 144 29)
Southwestern Electric Pwr - Gen	WSX111023	W0024107	DHPS1-Repice Powerblock Piping	31200 - Boiler Plant Equip-Coal	Addition	201608	(\$896 17)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - INST ELEV CRSHR HSE	31100 - Structures, Improvemnt-Coal	Addition	201608	\$144,517 41
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - Replace LHCB Annun Sys	31500 - Accessory Elect Equip-Coal	Addition	201608	(\$298 79)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1= Replace RO Membrane	31200 - Boiler Plant Equip-Coal	Addition	201608	(\$486 25)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL FGD PUMP BASES	31200 - Boiler Plant Equip-Coal	Addition	201608	(\$1,644 90)
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS1-Rpl Boil Wtr STBLWR DHPS 1 - RPL AIR HTR THERM ADJ	31200 - Boiler Plant Equip-Coal 31200 - Boiler Plant Equip-Coal	Addition Addition	201608 201608	\$7,118 73
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - Repl PAH Gas Outlet D	31200 - Boiler Plant Equip-Coal	Addition	201608	\$217,242 50 (\$637 72)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL CONV GEAR RDC 2015	31200 - Boiler Plant Equip-Coal	Addition	201608	\$129,691 94
Southwestern Electric Pwr - Gen	WSX111023		DHPS - RPL THICKNER RAKE	31100 - Structures, Improvemnt-Coal	Addition	201609	(\$71 43)
Southwestern Electric Pwr - Gen	WSX111023	W0026340	DHPS 1 - RPL FGD PIPING	31200 - Boiler Plant Equip-Coal	Addition	201609	(\$29 68)
Southwestern Electric Pwr - Gen	WSX111023	W0026336	DHPS 1 - RPL AIR HTR THERM ADJ	31200 - Boiler Plant Equip-Coal	Addition	201609	\$5,182 47
Southwestern Electric Pwr - Gen	WSX111023	W0024479	DHPS 1 - Expand Maint Office Buil	31100 - Structures, Improvemnt-Coal	Addition	201609	(521 40)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - UPG COOL TWR MTR FDS	31400 - Turbogenerator Units-Coal	Addition	201609	(\$202.78)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - UPG PLT LGT TEMP 2015	31200 - Boiler Plant Equip-Coal	Addition	201609	\$300 04
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL CONV GEAR RDC 2015	31200 - Boiler Plant Equip-Coal	Addition	201609	\$13,168 44
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL FGD PUMP BASES	31200 - Boiler Plant Equip-Coal	Addition	201609	(\$123.68)
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - RPL CONV GEAR RDC 2015 DHPS1 - Repl Sludge Conv Belts	31200 - Boiler Plant Equip-Coal 31200 - Boiler Plant Equip-Coal	Addition Addition	201610 201610	(\$1,353 56) (\$807 90)
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS - MODIFY SLUDGE LANDFILL	31100 - Structures, Improvemnt-Coal	Addition	201610	\$451,042.05
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL AIR HTR THERM ADJ	31200 - Boiler Plant Equip-Coal	Addition	201610	(\$582.70)
Southwestern Electric Pwr - Gen	WSX111023		DHPS1-Rpl Boil Wtr STBLWR	31200 - Boiler Plant Equip-Coal	Addition	201611	(\$2.40)
Southwestern Electric Pwr - Gen	WSX111023	W0026253	DHPS 1 - RPL FGD DCT LNRS	31200 - Boiler Plant Equip-Coal	Addition	201611	(\$1,941 02)
Southwestern Electric Pwr - Gen	W\$X111023	W0027160	DHPS 1 - RPL SLD TRMT BLD ROOF	31100 - Structures, Improvemnt-Coal	Addition	201611	(\$5,748 89)
Southwestern Electric Pwr - Gen	WSX111023	W0026507	DHPS 1 - RLNE SURG TANK	31200 - Boiler Plant Equip-Coal	Addition	201611	(\$1,174.79)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - INST ELEV CRSHR HSE	31100 - Structures, Improvemnt-Coal	Addition	201611	(\$2,815 54)
Southwestern Electric Pwr - Gen	WSX111023		Modernization of DHPS	31100 - Structures, Improvemnt-Coal	Addition	201611	\$256 56
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL WATER TRUCK	31200 - Boiler Plant Equip-Coal	Addition	201611	(\$1,100 58)
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023		DPNO - UPG TURB CRANE CNTRL	31200 - Boiler Plant Equip-Coal	Addition	201611	(\$693.49)
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - REF/UPG CIRC WTR PMPS DHPS 1 - PURC COMPUTERS-2015	31600 - Misc Pwr Plant Equip-Coal 39111 - Office Equip - Computers	Addition Addition	201611 201611	\$1,327 10 {\$106 171
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL CONV GEAR RDC 2015	31200 - Boiler Plant Equip-Coal	Addition	201611	(\$23.48)
Southwestern Electric Pwr - Gen	WSX111023		DHPS1-Rpl Boil Wtr STBLWR	31200 - Boiler Plant Equip-Coal	Addition	201612	(\$8,067 19)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL AIR HTR THERM ADJ	31200 - Boiler Plant Equip-Coal	Addition	201612	(\$6,490 37)
Southwestern Electric Pwr - Gen	WSX111023	W0026907	DHPS 1 - RPL CONV GEAR RDC 2015	31200 - Boiler Plant Equip-Coal	Addition	201612	\$11 09
Southwestern Electric Pwr - Gen	WSX111023	W0026419	DHPS 1 - RPL MISC VALVES	31600 - Misc Pwr Plant Equip-Coal	Addition	201612	\$5,331 34
Southwestern Electric Pwr - Gen	W\$X111023		DHPS 1 - RPR PARK LOT	39000 - Structures and Improvements	Addition	201612	(\$12,025 00)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - PUR/INS PLT SFT UPG	31100 - Structures, Improvemnt-Coal	Addition	201612	(\$1,320.00)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL MISC VALVES	31600 - Misc Pwr Plant Equip-Coal	Addition	201701	(\$357.83)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL AIR HTR THERM ADJ	31200 - Boiler Plant Equip-Coal	Addition	201701	\$621 72
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - PUR/INS PLT SFT UPG	31100 - Structures, Improvemnt-Coal	Addition	201701	\$126 44
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPR PARK LOT	39000 - Structures and Improvements	Addition	201701	\$1,151 89
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - RPL FGD CONV FRWK DOLET HILLS 345KV BREAKER REPL	31200 - Boiler Plant Equip-Coal 35300 - Station Equipment	Addition Addition	201702	(\$1,644.86)
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - RPL MISC VALVES	31600 - Misc Pwr Plant Equip-Coal	Addition	201702 201702	(\$43,101 17) \$0 06
Southwestern Electric Pwr - Gen	WSX111023		DPNO - UPG TURB CRANE CNTRL	31200 - Mise FWI Flant Equip-Coal	Addition	201702	(\$8,536 16)
Southwestern Electric Pwr - Gen	WSX111023		DPNO - UPG TURB CRANE CNTRL	31200 - Boiler Plant Equip-Coal	Addition	201703	(\$1,519.59)
Southwestern Electric Pwr - Gen	W\$X111023		DHPS 1 - RPL FGD CONV FRWK	31200 - Boiler Plant Equip-Coal	Addition	201703	(\$292.81)
Southwestern Electric Pwr - Gen	WSX111023	W0027850	DHPS 1 - UP CLG TOW MTR - 2016	31200 - Boiler Plant Equip-Coal	Addition	201705	\$23,513 56
Southwestern Electric Pwr - Gen	WSX111023	W0028853	DHPS 1 - RPL FUEL HND NUC CHUT	31200 - Boiler Plant Equip-Coal	Addition	201705	\$14,128 09

					FFD0.4.		Page 3 of 8
Company	Budget ID	Work Order	Work Order Descr	Utility Account	FERC Act Code	Month Number	Activity Cost
Southwestern Electric Pwr - Gen	WSX111023	W0026907	DHPS 1 - RPL CONV GEAR RDC 2015	31200 - Boiler Plant Equip-Coal	Addition	201705	\$5,529 35
Southwestern Electric Pwr - Gen	WSX111023	W0027846	DHPS 1 - PUR/INS SFTY UPG-201	31100 - Structures, Improvemnt-Coal	Addition	201705	\$43,693 22
Southwestern Electric Pwr - Gen	WSX111023	W0028575	DHPS 1 - UPG SLUD DST SYS	31200 - Boiler Plant Equip-Coal	Addition	201705	\$158,982 51
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - INST FIRE MONITORS	31600 - Misc Pwr Plant Equip-Coal	Addition	201705	\$25,145 13
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rpl A&C Absor Twr Elbows	31200 - Boiler Plant Equip-Coal	Addition	201705	\$261,314 26
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rpl A&C Absor Twr Elbows	31200 - Boiler Plant Equip-Coal	Addition	201706	\$37,143 06
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL CONV GEAR RDC 2015	31200 - Boiler Plant Equip-Coal	Addition	201706	\$17,567 99
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - RPL FUEL HND NUC CHUT 2015 WO Reclass	31200 - Boiler Plant Equip-Coal	Addition	201706 201706	\$925 48
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - UPG SLUD DST SYS	31200 - Boiler Plant Equip-Coal 31200 - Boiler Plant Equip-Coal	Addition Addition	201706	(\$1,117 96) \$457 89
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO-Rpl A&C Absor Twr Elbows	31200 - Boiler Plant Equip-Coal	Addition	201707	\$930 75
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL FUEL HND NUC CHUT	31200 - Boiler Plant Equip-Coal	Addition	201707	\$59 12
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL CONV GEAR RDC 2015	31200 - Boiler Plant Equip-Coal	Addition	201707	(\$297.51)
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rpl A&C Absor Twr Elbows	31200 - Boiler Plant Equip-Coal	Addition	201708	\$128,013 31
Southwestern Electric Pwr - Gen	WSX111023	W0027553	DHPS AUTO BUSHING REPL	31500 - Accessory Elect Equip-Coal	Addition	201708	\$12,107 91
Southwestern Electric Pwr - Gen	WSX111023	W0026022	DHPS 1 - RPL SLUD CONV BLTS	31200 - Boiler Plant Equip-Coal	Addition	201708	(\$485.75)
Southwestern Electric Pwr - Gen	WSX111023	W0027846	DHPS 1 - PUR/INS SFTY UPG-201	31100 - Structures, Improvemnt-Coal	Addition	201708	\$3 54
Southwestern Electric Pwr - Gen	WSX111023	W0024358	DHPS1-Repice Conveyor Belt	31200 - Boiler Plant Equip-Coal	Addition	201708	\$485 75
Southwestern Electric Pwr - Gen	WSX111023	W0026907	DHPS 1 - RPL CONV GEAR RDC 2015	31200 - Boiler Plant Equip-Coal	Addition	201708	(\$10,400 32)
Southwestern Electric Pwr - Gen	WSX111023	W0027850	DHPS 1 - UP CLG TOW MTR - 2016	31200 - Boiler Plant Equip-Coal	Addition	201708	\$2 22
Southwestern Electric Pwr - Gen	WSX111023	W0028853	DHPS 1 - RPL FUEL HND NUC CHUT	31200 - Boiler Plant Equip-Coal	Addition	201708	\$69 74
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - UPG SLUD DST SYS	31200 - Boiler Plant Equip-Coal	Addition	201708	\$244 83
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rpl Cool Twr Fan Shrouds	31400 - Turbogenerator Units-Coal	Addition	201708	(\$315.04)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - UPG PWR FEED RDL STCK	31100 - Structures, Improvemnt-Coal	Addition	201708	(\$15,691.58)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL UNDGRD PIP	31200 - Boiler Plant Equip-Coal	Addition	201709	\$383,920 41
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - UPG 1F1 & 1F2 MCC	31200 - Boiler Plant Equip-Coal	Addition	201709	\$37,960 17
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - Purchase Tools 2016	31600 - Misc Pwr Plant Equip-Coal	Addition Addition	201709 201709	\$39,830 13
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - RFB COOL TOW GEARBXS DPNO-Rpl Water Plt Controls	31400 - Turbogenerator Units-Coal 31500 - Accessory Elect Equip-Coal	Addition	201709	\$56,341 49 \$180,000 30
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS1-Replice Conveyor Belt	31200 - Accessory Elect Equip-Coal	Addition	201709	(\$49 14)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - UPG PWR FEED RDL STCK	31100 - Structures, Improvemnt-Coal	Addition	201709	\$1,691 56
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL FUEL HND NUC CHUT	31200 - Boiler Plant Equip-Coal	Addition	201709	\$8 17
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - UPG PWR FD RDL - 2016	31200 - Boiler Plant Equip-Coal	Addition	201709	\$47,775 02
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL FGD EXP JOINTS	31200 - Boiler Plant Equip-Coal	Addition	201709	\$29,822 24
Southwestern Electric Pwr - Gen	WSX111023	W0028574	DHPS 1 - UPG FUEL HAND FIRE PR	31200 - Boiler Plant Equip-Coal	Addition	201709	\$15,441 60
Southwestern Electric Pwr - Gen	WSX111023	W0029090	DPNO-Rpl Lignite Conv Belts	31100 - Structures, Improvemnt-Coal	Addition	201709	\$72,852 77
Southwestern Electric Pwr - Gen	WSX111023	W0029091	DPNO-Rpl Rtr Plow Spider Wheel	31200 - Boiler Plant Equip-Coal	Addition	201709	\$18,689 05
Southwestern Electric Pwr - Gen	WSX111023	W0026022	DHPS 1 - RPL SLUD CONV BLTS	31200 - Boiler Plant Equip-Coal	Addrtion	201709	\$52 37
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL STATION BAT	31100 - Structures, Improvemnt-Coal	Addition	201709	\$52,598 41
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - UP CLG TOW MTR - 2016	31200 - Boiler Plant Equip-Coal	Addition	201709	\$0 26
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - UPG SLUD DST SYS	31200 - Boiler Plant Equip-Coal	Addition	201709	\$28 66
Southwestern Electric Pwr - Gen	WSX111023		DHPS AUTO BUSHING REPL	31500 - Accessory Elect Equip-Coal	Addition	201709	(\$86.96)
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Upg Prim Airhtr Seal Sys	31200 - Boiler Plant Equip-Coal	Addition	201709	\$241,873 72
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO-Rpl Cool Twr Fan Shrouds DHPS 1 - Instl Flr Tile & DRS	31400 - Turbogenerator Units-Coal	Addition	201709 201709	\$285,551 01
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - RPL BOX CULVERTS	31100 - Structures, Improvemnt-Coal 31100 - Structures, Improvemnt-Coal	Addition Addition	201709	\$35,204 80 \$37,492 52
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - UPG PLT LGT TEMP 2016	31200 - Structures, Improvemint-coar 31200 - Boiler Plant Equip-Coal	Addition	201709	\$45,849 26
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - Rpl "B" MCVP	31200 - Boiler Plant Equip-Coal	Addition	201709	\$38,000 79
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL FGD CON FRWK-2016	31200 - Boiler Plant Equip-Coal	Addition	201709	\$15,078 61
Southwestern Electric Pwr - Gen	W\$X111023	W0028975	DPNO-REFURB CT GEARBOXES	31100 - Structures, Improvemnt-Coal	Addition	201709	\$73,646 69
Southwestern Electric Pwr - Gen	WSX111023	W0029097	DPNO - Upgrd Stm Turbine VIvs	31200 - Boiler Plant Equip-Coal	Addition	201709	\$457,849 77
Southwestern Electric Pwr - Gen	WSX111023	W0029176	DPNO-ACI Silo Coating	31200 - Boiler Plant Equip-Coal	Addition	201709	\$29,990 92
Southwestern Electric Pwr - Gen	WSX111023	W0028577	DPNO-Rpl Blr Fur Tubing	31200 - Boiler Plant Equip-Coal	Addition	201709	\$222,866 34
Southwestern Electric Pwr - Gen	WSX111023	W0028578	DPNO-Rpl Cooling Twr Demisters	31400 - Turbogenerator Units-Coal	Addition	201709	\$307,841 71
Southwestern Electric Pwr - Gen	WSX111023	W0028856	DHPS 1-Replace Conveyor Gear	31200 - Boiler Plant Equip-Coal	Addition	201709	\$40,108 71
Southwestern Electric Pwr - Gen	WSX111023		DPNO-RPL FGD EXP JOINTS	31200 - Boiler Plant Equip-Coal	Addition	201709	\$23,982 20
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rpl Water Plant Controls	31100 - Structures, Improvemnt-Coal	Addition	201709	\$28,811 98
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - PUR/INS SFTY UPG-201	31100 - Structures, Improvemnt-Coal	Addition	201709	\$0 41
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL CONV GEAR RDC 2015	31200 - Boiler Plant Equip-Coal	Addition	201709	(\$1,131.18)
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - REPL ELECTRI CARTS - 2016	31600 - Misc Pwr Plant Equip-Coal	Addition	201709	\$10,180 76
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS1-Rpice FGD Convey Frame DHPS 1 - RPL LIG DIVERT GATE	31600 - Misc Pwr Plant Equip-Coal 31100 - Structures, Improvemnt-Coal	Addition Addition	201709 201709	\$15,621.05
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		SHPS 1 - REP SO2 MONITOR RD	31100 - Structures, Improvemnt-Coal	Addition	201709	\$29,616 99 \$8 05
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - UPG FGD AREA LIGHT	31100 - Structures, Improvemnt-Coal	Addition	201709	\$46,300 22
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO-Rpl A&C Absor Twr Elbows	31200 - Boiler Plant Equip-Coal	Addition	201709	\$14,845 10
Southwestern Electric Pwr - Gen	WSX111023		DPNO ERL Tesla 4000	31200 - Boiler Plant Equip-Coal	Addition	201709	\$32,416 40
Southwestern Electric Pwr - Gen	W\$X111023		DHPS 1 - SO2 AREA GRATING 2016	31200 - Boiler Plant Equip-Coal	Addition	201709	\$24,646 98
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - Rpl Misc Valves	31600 - Misc Pwr Plant Equip-Coal	Addition	201709	\$89,142 49
Southwestern Electric Pwr - Gen	WSX111023	W0027667	DHPS 1 - RPL FGD CONV BELTS	31200 - Boiler Plant Equip-Coal	Addition	201709	\$16,316 94
Southwestern Electric Pwr - Gen	WSX111023	W0027669	DHPS 1 - RPL CL RADIOS - 2016	39700 - Communication Equipment	Addition	201709	\$6,174 51
Southwestern Electric Pwr - Gen	WSX111023	W0029089	DPNO-Replace Fuel Handl Chutes	31100 - Structures, Improvemnt-Coal	Addition	201709	\$27,389 76
Southwestern Electric Pwr - Gen	WSX111023	W0028573	DHPS 1- RPL STACK ELEV BLTS	31100 - Structures, Improvemnt-Coal	Addition	201709	\$25,599 77
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL FGD PMP CAS IMPLS	31200 - Boiler Plant Equip-Coal	Addition	201709	\$26,108 07
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - REP CIRC WTR PMP MTR	31200 - Boiler Plant Equip-Coal	Addition	201709	\$172,137 43
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1-Pur Com Washer Dryer	31200 - Boiler Plant Equip-Coal	Addition	201709	\$3,924 64
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - Inst Condenser Tube	31400 - Turbogenerator Units-Coal	Addition	201710	(\$3,248 64)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - UPG PWR FD RDL - 2016	31200 - Boiler Plant Equip-Coal	Addition	201710	(\$1,497.07)
	W/CV111000	W0027367	DHPS 1 - UPG 1F1 & 1F2 MCC	31200 - Boiler Plant Equip-Coal	Addition	201710	(\$5,667.33)
					4 6 1 1		1000
Southwestern Electric Pwr - Gen	WSX111023	W0028000	DHPS 1 - UPG FGD AREA LIGHT	31100 - Structures, Improvemnt-Coal	Addition	201710	(\$794-24)
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023	W0028000 W0027707	DHPS 1 - UPG FGD AREA LIGHT DPNO-RpI A&C Absor Twr Elbows	31100 - Structures, Improvemnt-Coal 31200 - Boiler Plant Equip-Coal	Addition	201710	\$6,267 02
Southwestern Electric Pwr - Gen	WSX111023	W0028000 W0027707 W0027239	DHPS 1 - UPG FGD AREA LIGHT	31100 - Structures, Improvemnt-Coal			

Membrane						FERC Act		Page 4 of
Addression Extent Per - 6	Company	Budget ID	Work Order	Work Order Descr	Utility Account		Month Number	Activity Cost
### And Providence	Southwestern Electric Pwr - Gen	WSX111023	W0027769	DHPS 1 - RPL FGD CON FRWK-2016	31200 - Boiler Plant Equip-Coal	Addition	201710	(\$544.73)
Additional pattern for Gen Will 1987 Will 1997	Southwestern Electric Pwr - Gen	WSX111023	W0027704	DPNO-Rpl Water Plt Controls	31500 - Accessory Elect Equip-Coal	Addition	201710	\$5,950 03
	Southwestern Electric Pwr - Gen							
Comparison Com					• •			
Limbestein belter Fer - Ges Wilstall 2007 1990 (1991) - 1991 (1992) 13109 - Journ Plant Equip-Cool Julian State But - Ges 2017 1991 (1992) 13109 - Journ Plant Equip-Cool Julian State But - Ges 2017 1991 (1992) 13109 - Journ Plant Equip-Cool Julian State But - Ges 2017 1991 (1992) 13109 - Journ Plant Equip-Cool Julian State But - Ges 2017 1991 (1992) 13109 - Journ Plant Equip-Cool Julian State But - Ges 2017 1991 (1992) 13109 - Journ Plant Equip-Cool Julian State But - Ges 2017 1991 (1992) 13109 - Journ Plant Equip-Cool Julian State But - Ges 2017 1991 (1992) 13109 - Journ Plant Equip-Cool Julian State But - Ges 2017 1991 (1992) 13109 - Journ Plant Equip-Cool Julian State But - Ges 2017 1991 (1992) 13109 - Journ Plant Equip-Cool Julian State But - Ges 2017 1991 (1992) 13109 - Journ Plant Equip-Cool Julian State But - Ges 2017 1991 (1992) 13109 - Journ Plant Equip-Cool Julian State But - Ges 2017 1991 (1992) 13109 - Journ Plant Equip-Cool Julian State But - Ges 2017 1991 (1992) 13109 - Journ Plant Equip-Cool Julian State But - Ges 2017 1991 (1992) 13109 - Journ Plant Equip-Cool Julian State But - Ges 2017 1991 (1992) 13109 - Journ Plant Equip-Cool Julian State But - Ges 2017 1991 (1992) 13109 - Journ Plant Equip-Cool Julian State But - Ges 2017 1991 (1992) 13109 - Journ Plant Equip-Cool Julian State But - Ges 2017 1991 (1992) 13109 - Journ Plant Equip-Cool Julian State But - Ges 2017 1991 (1992) 13109 - Journ Plant Equip-Cool Julian State But - Ges 2017 1991 (1992) 13109 - Journ Plant Equip-Cool Julian State But - Ges 2017 1991 (1992) 13109 - Journ Plant Equip-Cool Julian State But - Ges 2017 1991 (1992) 13109 - Journ Plant Equip-Cool Julian State But - Ges 2017 1991 (1992) 13109 - Journ Plant Equip-Cool Julian State But - Ges 2017 1991 (1992) 13109 - Journ Plant Equip-Cool Julian State But - Ges 2017 1991 (1992) 13109 - Journ Plant Equip-Cool Julian State But - Ges 2017 1991 (1992) 13109 - Journ Plant Equip-Cool Julian State But - Ges 2017 1991 (1992) 13109 - Journ Plant Equip-Cool J								
Labouston Bittern Fer - Gen Universitien Bittern Fer - Gen U	Southwestern Electric Pwr - Gen							
	Southwestern Electric Pwr - Gen			-				
ollwestend Better, Perr - Gen 53111122 wild wild begregate fletch perr - Gen 5311122 wild begregat	Southwestern Electric Pwr - Gen	WSX111023	W0028975	DPNO-REFURB CT GEARBOXES	31100 - Structures, Improvemnt-Coal	Addition	201710	\$21,972 48
Coloration Col	Southwestern Electric Pwr - Gen	WSX111023	W0027705			Addition	201710	\$699 89
ollwestern Bettern Per- Gen W3111022 W0027952 M193 1 VRRY LECTURE CASTS - 2005 3100 0 More Per Fixed Equip-Coal Addition 201710 5331 1 33 uthwestern Bettern Per- Gen W3111023 W0027955 M193 1 VRRY LECTURE CONVENTION 31300 - Solet Per Ref Aqui-Coal Addition 201710 5532 200 uthwestern Bettern Per- Gen W3111023 W0027955 M193 1 VRRY ARK WILL WILL WILL WILL WILL WILL WILL WIL	Southwestern Electric Pwr - Gen			1 11				
ubswetzen Betrick Part - Gen W3311020 W007260 DIRS 3 - RPL FOOD CONV RESTS 32100 - Bolter Plant Fapup-Coal Addison 20710 1,5535-505 ubswetzen Betrick Pert - Gen W3311020 W007260 DIRS 3 - RPL FOOD CONV RESTS 32110 - Bolter Plant Fapup-Coal Addison 20710 5,258-50 ubswetzen Betrick Pert - Gen W3311020 W007260 DIRS 3 - RPL FOOD COARD 3210 - Bolter Plant Fapup-Coal Addison 20710 5,238-28 ubswetzen Betrick Pert - Gen W3311020 W007260 DIRS 3 - RPL FACK ELEV RUS 32100 - Bolter Plant Fapup-Coal Addison 20710 5,238-20 ubswetzen Betrick Pert - Gen W3311020 W007260 DIRS 3 - RPL FACK ELEV RUS 32100 - Bolter Flant Fapup-Coal Addison 20710 (5,379-00) ubswetzen Betrick Pert - Gen W3311020 W007260 DIRS 3 - RPL FLOR CARRON 32100 - Bolter Flant Fapup-Coal Addison 20710 (5,379-00) ubswetzen Betrick Pert - Gen W3311020 W007270 DIRS 3 - RPL FLOR CARRON 32100 - Bolter Flant Fapup-Coal Addison 20710 (5,379-00) 15,379-00 32100 - Bolter Flant Fapup-Coa	i i							
unbeweign Reither (Per - Gen Will 1922 WO07295 DIRPS 1 - PURE COMPUTES 2016 3911 - Office Equip. Computers Addition 2017 53,284 54,000 1								
uilwestern Richter Per Gen WXXXII 1020 WXXXII 1020 WXXXII 1020 WXXII 1020 WXXII 1020 XXXII 1020								
uithwesten Besche Perr - Gen WXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX								
uthwesten Better Per - Gen withwesten Better Per - Gen wit								
uthwestern Electors Per - Gen Will 1023 W0002459 DHFS 1-RH STACK ELV BLIS allowed real Electors Per - Gen Will 1023 W0002459 DHFS 1-RH STACK ELV BLIS allowed real Electors Per - Gen Will 1023 W0002459 DHFS 1-RH STACK ELV BLIS allowed real Electors Per - Gen Will 1023 W0002459 DHFS 1-RH STACK ELV BLIS allowed real Electors Per - Gen Will 1023 W0002459 DHFS 1-RH STACK ELV BLIS allowed real Electors Per - Gen Will 1023 W0002459 DHFS 1-RH STACK ELV BLIS allowed real Electors Per - Gen Will 1023 W0002459 DHFS 1-RH STACK ELV BLIS allowed real Electors Per - Gen Will 1023 W0002459 DHFS 1-RH STACK ELV BLIS allowed real Electors Per - Gen Will 1023 W0002459 DHFS 1-RH STACK ELV BLIS allowed real Electors Per - Gen Will 1023 W0002459 DHFS 1-RH STACK ELV BLIS allowed real Electors Per - Gen Will 1023 W0002459 DHFS 1-RH STACK ELV BLIS allowed real Electors Per - Gen Will 1023 W0002459 DHFS 1-RH STACK ELV BLIS allowed real Electors Per - Gen Will 1023 W0002459 DHFS 1-RH STACK ELV BLIS allowed real Electors Per - Gen Will 1023 W0002459 DHFS 1-RH STACK ELV BLIS allowed real Electors Per - Gen Will 1023 W0002459 DHFS 1-RH STACK ELV BLIS allowed real Electors Per - Gen Will 1023 W0002459 DHFS 1-RH STACK ELV BLIS allowed real Electors Per - Gen Will 1023 W0002459 DHFS 1-RH STACK ELV BLIS allowed real Electors Per - Gen Will 1023 W0002459 DHFS 1-RH STACK ELV BLIS allowed real Electors Per - Gen Will 1023 W0002459 DHFS 1-RH STACK ELV BLIS allowed real Electors Per - Gen Will 1023 W0002459 DHFS 1-RH STACK ELV BLIS allowed real Electors Per - Gen Will 1023 W0002459 DHFS 1-RH STACK ELV BLIS allowed real Electors Per - Gen Will 1024 W0002459 DHFS 1-RH STACK ELV BLIS allowed real Electors Per - Gen Will 1024 W0002459 DHFS 1-RH STACK ELV BLIS allowed real Electors Per - Gen Will 1024 W0002459 DHFS 1-RH STACK ELV BLIS allowed real Electors Per - Gen Will 1024 W0002459 DHFS 1-RH STACK ELV BLIS allowed real Electors Per - Gen Will 1024 W0002459 DHFS 1-RH STACK ELV BLIS allowed real Elector	Southwestern Electric Pwr - Gen				=			
ultwesters Elector Per - Gen withwesters Elector Per - Gen withwes	Southwestern Electric Pwr - Gen	WSX111023	W0028573	DHPS 1- RPL STACK ELEV BLTS	the state of the s			
withwestern Electric Per - Gen	Southwestern Electric Pwr - Gen	WSX111023	W0026343	DPNO ERL Tesla 4000	31200 - Boiler Plant Equip-Coal	Addition	201710	(\$1,239 40)
unthwestern Electric PwrGen withwestern Electric PwrGen	Southwestern Electric Pwr - Gen			DHPS 1 - RFB COOL TOW GEARBXS	31400 - Turbogenerator Units-Coal	Addition	201710	(\$1,075 03)
withwestern Electric Pwr - Gen	Southwestern Electric Pwr - Gen							
unthwestern Electric Pwr Gen withwestern Electric Pwr Gen	Southwestern Electric Pwr - Gen							
withwestern Electric Pwr - Gen								
uthwestern Fletcher Nur- Gen withwestern Electric Nur- Gen w								
uithwestern flectric Pwr - Gen								
uitwestern Electric Pwr - Gen W3311023 W0027550 DWPS 1 = MFL/IPG RICH & RDS 31200 - Boler Plant Equip-Coal Addeon 20170 \$5825 7 1 uitwestern Electric Pwr - Gen W3311023 W0027550 DWPS 1 = MFL First Park & RDS 31200 - Boler Plant Equip-Coal Addeon 20170 \$5850 64) uitwestern Electric Pwr - Gen W3311023 W0027550 DWPS 1 = MFL FIRST PMPR 2018 31200 - Boler Plant Equip-Coal Addeon 20171 \$585 64) uitwestern Electric Pwr - Gen W3311023 W0027550 DWPS 1 = MFL FIRST PMPR 2018 31200 - Boler Plant Equip-Coal Addeon 20171 \$588 68 uitwestern Electric Pwr - Gen W3311023 W0022550 DWPS 1 = MFL FIRST DEBER ERPAR 10 31200 - Boler Plant Equip-Coal Addeon 20171 \$588 68 uitwestern Electric Pwr - Gen W3311023 W0022557 DWPS 1 = MFL FIRST PMP AND BRITE PMP AND								
uithwestern fector Pwr - Gen W3311023 W0027570 DiPRS 1 PR 1560 PWR CAS MPLS 2 3100 - Structures, Improvement-Coal Addition Addition 20170 (5639 19) uithwestern fector Pwr - Gen W3311023 W0027570 DiPRS 1 PR 1560 PWR CAS MPLS 3 31200 - Boler P Flant Equip-Coal Addition Addition 201710 (5648 8) uithwestern fector Pwr - Gen W3311023 W0027500 DiPRS 1 PR 1560 PWR CAS MPLS 3 31200 - Boler P Flant Equip-Coal Addition 201711 (5145 8) 31300 - Boler P Flant Equip-Coal Addition 201711 (5145 8) 31300 - Boler P Flant Equip-Coal Addition 201711 (5145 8) 31300 - Boler P Flant Equip-Coal Addition 201711 (5145 8) 31300 - Boler P Flant Equip-Coal Addition 201711 (5145 8) 31300 - Boler P Flant Equip-Coal Addition 201711 (5145 8) 31300 - Boler P Flant Equip-Coal Addition 201711 (5145 8) 31300 - Boler P Flant Equip-Coal Addition 201711 (5145 8) 31300 - Boler P Flant Equip-Coal Addition 201711 (5145 8) 31300 - Boler P Flant Equip-Coal Addition 201711 (5145 8) 31300 - Boler P Flant Equip-Coal Addition 201711 (5145 8) 31300 - Boler P Flant Equip-Coal Addition 201711 (5145 8) 31300 - Boler P Flant Equip-Coal Addition 201711 (5145 8) 31300 - Boler P Flant Equip-Coal Addition 201711 (5145 8) 31300 - Boler P Flant Equip-Coal Addition 201711 (5145	Southwestern Electric Pwr - Gen							
uthwestern Flectric Pwr - Gen withwestern Flectric Pwr - Gen	Southwestern Electric Pwr - Gen	WSX111023	W0027670	· ·				
uthwestern Flectric Pwr - Gen WSX111023 W0027850 DMF31-Flect FloC Convey Frame 31000 - Note Pwr Flant Equip-Coal Addition 201711 \$48 Bt uthwestern Flectric Pwr - Gen WSX111023 W0027850 DMF31-Right FloC Convey Frame 31000 - Mack Pwr Plant Equip-Coal Addition 201711 \$381 Bt uthwestern Flectric Pwr - Gen WSX111023 W0027850 DMF31-Right FloR Coll Convey Frame 31200 - Booler Plant Equip-Coal Addition 201711 \$381 Bt uthwestern Flectric Pwr - Gen WSX111023 W0027876 DMF91-Right Flora Boole Set Plant Equip-Coal Addition 201711 \$3,165 St uthwestern Flectric Pwr - Gen WSX111023 W0027876 PMF91-Right Flora Bornous 31400 - Turbogenerator Units-Coal Addition 201711 \$3,600 12 uthwestern Flectric Pwr - Gen WSX111023 W0027876 PMF91-Right Flora Bornous 31200 - Booler Plant Equip-Coal Addition 201711 \$3,600 12 uthwestern Flectric Pwr - Gen WSX111023 W0027869 PMF91-Flera Flera Equip-Coal 31200 - Booler Plant Equip-Coal Addition 201711 \$5,600 21 uthwestern Flectric Pwr - Gen WSX111023 W0027869 WSX111023 W0027869 PMF91-Flera Flera	Southwestern Electric Pwr - Gen	WSX111023	W0027159					
withwestern Electric Pur- Gen W\$111023 W0022995 DHP51-Riple FGD Convey Frame withwestern Electric Pur- Gen W\$111023 W002295 DHP51-Riple FGD Convey Frame withwestern Electric Pur- Gen W\$111023 W002295 DHP51-Riple FGD Convey Frame withwestern Electric Pur- Gen W\$111023 W002295 DHP51-Riple FGD Convey Frame withwestern Electric Pur- Gen W\$111023 W002295 DHP51-Riple FGD Convey Frame withwestern Electric Pur- Gen W\$111023 W002295 DHP51-Riple FGD Convey Frame withwestern Electric Pur- Gen W\$111023 W002295 DHP51-Riple FGD Convey Frame withwestern Electric Pur- Gen W\$111023 W002295 DPNO-Riple Conveyors 2016 31000 - Bottler Plant Equip-Coal Addition 201711 \$33,869 12 \$3,869 12 \$3,869 12 \$3,410 01 \$3,421 13	Southwestern Electric Pwr - Gen			DHPS 1 - RPL FGD PIPING 2016	31200 - Boiler Plant Equip-Coal	Addition	201710	\$107,766 43
uthwestern Electric Pwr - Gen withwestern Electric Pwr - Gen	Southwestern Electric Pwr - Gen					Addition		
uthwestern [lectric Pwr - Gen withwestern [lectric Pwr - Gen	Southwestern Electric Pwr - Gen							
uthwestern Electric Pwr - Gen WSX11023 WO027444 DIFS 1 - REF CIRC WTR PM M MTR 31200 - Booler Plant Equip-Coal Addition 201711 (53,165.87) uthwestern Electric Pwr - Gen WSX11023 WO02878 DPNO-Ref Cooling Twn Demoters 31400 - Turbogenerator Units-Coal Addition 201711 (53,869.12 uthwestern Electric Pwr - Gen WSX11023 WO02875 DPNO-Ref Cooling Twn Demoters 31400 - Turbogenerator Units-Coal Addition 201711 (53,869.12 uthwestern Electric Pwr - Gen WSX11023 WO027370 DIPS 1 - REF CDE W DINTS 31200 - Booler Plant Equip-Coal Addition 201711 (59,806.51) uthwestern Electric Pwr - Gen WSX111023 WO027688 DIPS 1 - REF CORL TWO GEARBSS 31400 - Turbogenerator Units-Coal Addition 201711 (59,806.51) uthwestern Electric Pwr - Gen WSX111023 WO027868 DIPS 1 - REF CORL TWO GEARBSS 31400 - Turbogenerator Units-Coal Addition 201711 515.56 uthwestern Electric Pwr - Gen WSX111023 WO02787 DPNO-Replace Full Hand Chiutes 31100 - Structures, Improvement-Coal Addition 201711 5415.50								
uthwester lectric Pwr - Gen WSX11023 W0028576 PDNO-Rej Cool Twr Fan Shrouds 31400 Turbogenerator Units-Coal Addition 20171 534 847 13 uthwester lectric Pwr - Gen WSX11023 W002857 PDNO-Rej Cooling Twr Demarkers 31400 Turbogenerator Units-Coal Addition 20171 \$34 80 uthwestern Electric Pwr - Gen WSX111023 W002857 PDNO-Rej Cooling Twr Demarkers 31400 Turbogenerator Units-Coal Addition 20171 \$34 80 uthwestern Electric Pwr - Gen WSX111023 W0027371 DIPPS 1- Rej Boil Exp TS 2016 31200 Boiler Plant Equip-Coal Addition 201711 \$3160 Turbogenerator Units-Coal Addition 201711 \$3160 Turbogenerator Units								
uthwestern Electric Pwr - Gen WSX111023 W0028378 PPNO-RRI Cooling Two Demosters 31400 - Turbogenerator Units-Coal Addition 20111 \$3,060 12 uthwestern Electric Pwr - Gen WSX111023 W0027370 HPR5 1-Rep/Rploc Conveyors 2016 31200 - Boler Plant Equip-Coal Addition 20111 (\$6,002.61) uthwestern Electric Pwr - Gen WSX111023 W0027370 HPR5 1-Rep/Rploc Conveyors 2016 31200 - Boler Plant Equip-Coal Addition 20111 (\$1,677.65) uthwestern Electric Pwr - Gen WSX111023 W0027873 HPR5 1- In FB COD. I TOW GEARBAS 31400 - Turbogenerator Units-Coal Addition 201711 \$155.07 uthwestern Electric Pwr - Gen WSX111023 W0028878 PMPO-Replace Fuel Hand Chutes 31100 - Structures, Improvemit-Coal Addition 201711 \$434.94 uthwestern Electric Pwr - Gen WSX111023 W0028990 PPMO-Replace Fuel Hand Chutes 31100 - Structures, Improvemit-Coal Addition 201711 \$435.33 uthwestern Electric Pwr - Gen WSX111023 W002890 PPMO-Replace Fuel Hand Chutes 31200 - Soler Plant Equip-Coal Addition 201711 \$15.56								
uthwestern Electric Pwr - Gen WSX111023 W0028969 PPNO-RIF FGD EXP POINTS 31200 - Boller Plant Equip-Coal Addition 201711 \$5,48 (9)(8) (8) (8) (8) (8) (9) (8) (1) (1) (1) (1) (5) (7) (6) (8) (1) (1) (1) (1) (1) (1) (1) (1) (1) (1					-			
uthwestern Electric Pwr - Gen withwestern Electric Pwr - Gen	Southwestern Electric Pwr - Gen							
uthwestern Electric Pwr - Gen WXX111023 W0027668 DHPS 1. RER COLO TOW GARRISS 31400 - Turbogenerator Units-Coal Addition 201711 \$156 Or uthwestern Electric Pwr - Gen WXX111023 W0028978 DHPS 1. RER COLO TOW GARRISS 31200 - Boller Plant Equip-Coal Addition 201711 \$43 28 uthwestern Electric Pwr - Gen WXX111023 W0028978 DPNO-Replace Fuel Hand Chutes 31100 - Structures, Improvement-Coal Addition 201711 \$415 50 uthwestern Electric Pwr - Gen WXX111023 W0028978 DPNO-Replace Fuel Hand Chutes 31100 - Structures, Improvement-Coal Addition 201711 \$415 50 uthwestern Electric Pwr - Gen WXX111023 W0027729 DPNO-Replicar Fuel Hand Chutes 31100 - Structures, Improvement-Coal Addition 201711 \$52,582 28 uthwestern Electric Pwr - Gen WXX11023 W0027729 DIPS 1. REP (AFS) URLICE PUMP 3100 - Boler Plant Equip-Coal Addition 201711 \$52,882 29 uthwestern Electric Pwr - Gen WXX11023 W0028950 PDN-REPLICACE Conveyor Gear 3100 - Boler Plant Equip-Coal Addition 201711 \$51,692 20 <td>Southwestern Electric Pwr - Gen</td> <td>WSX111023</td> <td>W0027370</td> <td></td> <td></td> <td></td> <td></td> <td></td>	Southwestern Electric Pwr - Gen	WSX111023	W0027370					
uthwestern Electric Pwr - Gen WSX111023 W0028974 DPNO-Repl Water Plant Controls 31100 - Structures, Improvemnt-Coal Addition 201711 \$43 4 uthwestern Electric Pwr - Gen WSX111023 W0028989 DPNO-Repl Water Plant Controls 31100 - Structures, Improvemnt-Coal Addition 201711 \$415 90 uthwestern Electric Pwr - Gen WSX111023 W0029989 DPNO-Repleace Fuel Handl Chutes 31100 - Structures, Improvemnt-Coal Addition 201711 \$523 28 uthwestern Electric Pwr - Gen WSX111023 W0027995 DPNO-Repliante Conv Belts 31100 - Structures, Improvemnt-Coal Addition 201711 \$523 28 uthwestern Electric Pwr - Gen WSX111023 W0027845 DHPS 1 - RPL GAPINER 31200 - Boller Plant Equip-Coal Addition 201711 \$52,811 231 uthwestern Electric Pwr - Gen WSX111023 W0028969 DHPS 1 - RPL CORW GEAR RDC 2015 31200 - Boller Plant Equip-Coal Addition 201711 \$51,812 21 uthwestern Electric Pwr - Gen WSX111023 W0028951 DPNO-REFURS CT GEARBOXES 31200 - Boller Plant Equip-Coal Addition 201711 \$51,636 00	Southwestern Electric Pwr - Gen	WSX111023	W0027371	DHPS 1 - Rpl Boil Exp JTS 2016	31200 - Boiler Plant Equip-Coal	Addition	201711	(\$1,677.46)
uthwestern Electric Pwr - Gen WSX111023 W0028978 DPNO-Replace Fuel Handl Chutes 31100 - Structures, Improvemnt-Coal Addition 201711 \$232 8 uthwestern Electric Pwr - Gen WSX111023 W0029089 DPNO-Replace Fuel Handl Chutes 31100 - Structures, Improvemnt-Coal Addition 201711 \$573 18 uthwestern Electric Pwr - Gen WSX111023 W0027972 DHPS 1- RPL FEGD PIPNIG 2016 31200 - Boller Plant Equip-Coal Addition 201711 \$52,62 52) uthwestern Electric Pwr - Gen WSX111023 W0027845 DHPS 1- RPL FEGD PIPNIG 2016 31200 - Boller Plant Equip-Coal Addition 201711 \$52,62 52) uthwestern Electric Pwr - Gen WSX111023 W0025696 DHPS 1- RIP CANW GEAR RDC 2015 31200 - Boller Plant Equip-Coal Addition 201711 \$532 67 uthwestern Electric Pwr - Gen WSX111023 W0028975 DHPS 1- Replace Conveyor Gear 31200 - Boller Plant Equip-Coal Addition 20171 \$532 67 uthwestern Electric Pwr - Gen WSX111023 W0028975 DPNO-REPURB CT GEARBOXES 31100 - Structures, Improvement-Coal Addition 20171 \$535 68	Southwestern Electric Pwr - Gen	WSX111023	W0027668	DHPS 1 - RFB COOL TOW GEARBXS	31400 - Turbogenerator Units-Coal	Addition	201711	\$156 07
uthwestern Electric Pwr - Gen WSX111023 W0029990 DPNO-Replace Fuel Hand Chutes 31100 - Structures, Improvement-Coal Addition 20171 \$415 90 uthwestern Electric Pwr - Gen WSX111023 W0027972 DPNO-Replace Fuel Hand Chutes 31200 - Structures, Improvement-Coal Addition 201711 \$573 18 uthwestern Electric Pwr - Gen WSX111023 W0027972 DHPS 1 - RPL FGD PIPING 2016 31200 - Stoleer Plant Equip-Coal Addition 201711 \$52,662 52 uthwestern Electric Pwr - Gen WSX111023 W0027967 DHPS 1 - RPL FGD PIPING 2016 31200 - Boleer Plant Equip-Coal Addition 201711 \$52,662 52 uthwestern Electric Pwr - Gen WSX111023 W0025650 DHPS 1 - RPL CONV GEAR RDC 2015 31200 - Boleer Plant Equip-Coal Addition 201711 \$(31,036 19) uthwestern Electric Pwr - Gen WSX111023 W0029921 DHPS 1 - RPL CONV GEAR RDC 2015 31200 - Boleer Plant Equip-Coal Addition 201711 \$(31,036 19) uthwestern Electric Pwr - Gen WSX111023 W0029923 WDO-REFURS CT GEARBOXES 31200 - Boleer Plant Equip-Coal Addition 201711 \$(35,680 24) <td>Southwestern Electric Pwr - Gen</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	Southwestern Electric Pwr - Gen							
uthwestern Electric Pwr - Gen WSX111023 W0029950 PMPO-Rpl Lagnate Conv Belts 31100 - Structures, Improvement-Coal Addition 201711 \$573 18 uthwestern Electric Pwr - Gen WSX111023 W0027372 DHPS 1 - RPL RFG PIPING 2016 31200 - Boller Plant Equip-Coal Addition 201711 \$52,811 231 uthwestern Electric Pwr - Gen WSX111023 W0027875 DHPS 1 - RPL RFG PIPING 2016 31400 - Tunts-Coal Addition 201711 \$52,811 231 uthwestern Electric Pwr - Gen WSX111023 W0028975 DHPS 1 - RPL CONT CARR RDC 2015 31400 - Tunts-Coal Addition 201711 \$(52,811 231) uthwestern Electric Pwr - Gen WSX111023 W0028975 DHPS 1 - RPL CONT CARR RDC 2015 31200 - Boller Plant Equip-Coal Addition 201711 \$(51,036 19) uthwestern Electric Pwr - Gen WSX111023 W0029991 DPNO-RPL RIF Plow Spider Wheel 31200 - Boller Plant Equip-Coal Addition 201711 \$(51,66 0) uthwestern Electric Pwr - Gen WSX111023 W0027529 DPNO-RPL RIF CREABEOXES 31200 - Boller Plant Equip-Coal Addition 201711 \$(52,681 23)								
withwestern Electric Pwr - Gen WSXI11023 W0027847 DHPS 1- RPL FGD PINNG 2016 31200 - Boiler Plant Equip-Coal Addition 201711 (\$2,662.52) uthwestern Electric Pwr - Gen WSXI11023 W0027845 DHPS 1 - RPL ASH SILUCE PUMP 31200 - Boiler Plant Equip-Coal Addition 201711 (\$2,662.52) uthwestern Electric Pwr - Gen WSXI11023 W0025863 DHPS 1 - RPL CONV GEAR RDC 2015 31200 - Boiler Plant Equip-Coal Addition 201711 (\$10,306.19) uthwestern Electric Pwr - Gen WSXI11023 W0028975 DPNO-REFURB CT GEARBOXES 31100 - Structures, Improvement-Coal Addition 201711 (\$11,636.00) uthwestern Electric Pwr - Gen WSXI11023 W00289975 DPNO-REFURB CT GEARBOXES 31100 - Structures, Improvement-Coal Addition 201711 (\$11,636.00) uthwestern Electric Pwr - Gen WSXI11023 W0029393 DPNO-REFURB CT GEARBOXES 31100 - Structures, Improvement-Coal Addition 201711 (\$82.87) uthwestern Electric Pwr - Gen WSXI11023 W0027959 DPND-REPURS CORDITIES EVENANCION 31200 - Booler Plant Equip-Coal Addition 201711 (\$82.88.7)								
uthwestern Electric Pwr - Gen WXII11023 W0027845 DHPS 1 - RPL ASH SLUICE PUMP 31200 - Booler Plant Equip-Coal Addition 201711 (52,827) uthwestern Electric Pwr - Gen WXXII11023 W0026693 DHPS 1 - RPL CONV GEAR RDC 2015 31200 - Booler Plant Equip-Coal Addition 201711 (5382 07) uthwestern Electric Pwr - Gen WXXII11023 W0028955 DHPS 1 - RPL CONV GEAR RDC 2015 31200 - Booler Plant Equip-Coal Addition 201711 (510,306 19) uthwestern Electric Pwr - Gen WXXII1023 W0028955 DPPO-REFURBE CT GEARBOXES 31100 - Structures, improvement-Coal Addition 201711 (511,636 00) uthwestern Electric Pwr - Gen WXXII1023 W0029933 DPPO-REFURBE CT GEARBOXES 31200 - Booler Plant Equip-Coal Addition 201711 525 68 uthwestern Electric Pwr - Gen WXXII1023 W0027953 DPPS 1 - RPL CON TEPT COW Synder Wheel 31200 - Booler Plant Equip-Coal Addition 201711 (5878 87) uthwestern Electric Pwr - Gen WXXII1023 W0027907 DPN F1 - RPL CON Washer Dryer 31200 - Booler Plant Equip-Coal Addition 201711 (5888 82) <td></td> <td></td> <td></td> <td>_</td> <td>the state of the s</td> <td></td> <td></td> <td></td>				_	the state of the s			
withwestern Electric Pwr - Gen WSX111023 W0022663 DHPS 1 - Inst Condenser Tube 31400 - Turbogenerator Units-Coal Addition 201711 (\$382.07) uthwestern Electric Pwr - Gen WSX111023 W0028950 DHPS 1 - RPIL CONV GEAR RIOC 2015 31200 - Boiler Plant Equip-Coal Addition 201711 (\$10,306.19) uthwestern Electric Pwr - Gen WSX111023 W0028975 WSX111023 W0029975 WSX111023 W0029975 Addition 201711 (\$10,306.19) uthwestern Electric Pwr - Gen WSX111023 W002933 W								
uthwestern Electric Pwr - Gen WSX111023 W0025897 DHPS 1 - RPL CONV GEAR RDC 2015 31200 - Boiler Plant Equip-Coal Addition 201711 (\$10,366 19) uthwestern Electric Pwr - Gen WSX111023 W00228956 DHPS 1 - RPL CONV GEAR RDC 2015 31200 - Boiler Plant Equip-Coal Addition 201711 (\$10,749 04) uthwestern Electric Pwr - Gen WSX111023 W0022993 DPNO-REFURB CT GEARBOXES 31100 - Boiler Plant Equip-Coal Addition 201711 (\$10,749 04) uthwestern Electric Pwr - Gen WSX111023 W00229349 DPNO-REFURB CT GEARBOXES 31200 - Boiler Plant Equip-Coal Addition 201711 \$58.91 uthwestern Electric Pwr - Gen WSX111023 W00227549 DHPS 1 - Pur Corw Washer Dryer 31200 - Boiler Plant Equip-Coal Addition 201711 \$58.91 uthwestern Electric Pwr - Gen WSX111023 W00227549 DHPS 1 - Pur Corw Washer Dryer 31200 - Boiler Plant Equip-Coal Addition 201711 \$518.98 22 uthwestern Electric Pwr - Gen WSX111023 W00227565 DHPS 1 - PUR C COMPUTERS-2016 39111 - Office Equip - Computers Addition 201711 \$53,026 94	Southwestern Electric Pwr - Gen							
uthwestern Electric Pwr - Gen WSX111023 W0028855 DHPS 1-Replace Conveyor Gear 31200 - Boiler Plant Equip-Coal Addition 201711 \$10,749 04 uthwestern Electric Pwr - Gen WSX111023 W0028975 DPNO-REFURB CT GEARBOXES 31100 - Structures, Improvement-Coal Addition 201711 \$526 08 uthwestern Electric Pwr - Gen WSX111023 W00292938 DHPS 1-RUCOM Washer Dryer 31200 - Boiler Plant Equip-Coal Addition 201711 \$526 08 uthwestern Electric Pwr - Gen WSX111023 W0022759 DHPS 1-RPLACE BOILER EXPANSION 31200 - Boiler Plant Equip-Coal Addition 201711 \$526 08 uthwestern Electric Pwr - Gen WSX111023 W0022750 DHPS 1-RPLACE BOILER EXPANSION 31200 - Boiler Plant Equip-Coal Addition 201711 \$35,425 05 uthwestern Electric Pwr - Gen WSX111023 W00227552 DHPS 1- PURC COMPUTERS-2016 39111 - Office Equip - Computers Addition 20171 \$35,425 05 uthwestern Electric Pwr - Gen WSX111023 W00227552 DHPS 1 - PURC COMPUTERS-2016 39111 - Office Equip - Coal Addition 20171 \$534,225 05	Southwestern Electric Pwr - Gen				=			
uthwestern Electric Pwr - Gen WSX111023 W002991 DPNO-Rpl Rtr Plow Spider Wheel 31200 - Boiler Plant Equip-Coal Addition 201711 \$85 91 uthwestern Electric Pwr - Gen WSX111023 W0029238 DHPS 1-Pur Com Washer Dryer 31200 - Boiler Plant Equip-Coal Addition 201711 \$25 68 uthwestern Electric Pwr - Gen WSX111023 W0020750 DHPS 1-RPL ROT PLOW SW 31200 - Boiler Plant Equip-Coal Addition 201711 (\$88 87) uthwestern Electric Pwr - Gen WSX111023 W0027707 DPNO-Rpl A&C Absor Twr Elbows 31200 - Boiler Plant Equip-Coal Addition 201711 (\$189 82) uthwestern Electric Pwr - Gen WSX111023 W0027707 DPNO-Rpl A&C Absor Twr Elbows 31200 - Boiler Plant Equip-Coal Addition 201711 (\$189 82) uthwestern Electric Pwr - Gen WSX111023 W0027552 DHPS 1 - PURC COMPUTERS-2016 31200 - Boiler Plant Equip-Coal Addition 201711 (\$145 54) uthwestern Electric Pwr - Gen WSX111023 W0028000 DHPS 1 - PURC COMPUTERS-2016 31200 - Boiler Plant Equip-Coal Addition 201711 \$543 28 <td< td=""><td>Southwestern Electric Pwr - Gen</td><td>WSX111023</td><td>W0028856</td><td>DHPS 1-Replace Conveyor Gear</td><td></td><td></td><td></td><td></td></td<>	Southwestern Electric Pwr - Gen	WSX111023	W0028856	DHPS 1-Replace Conveyor Gear				
uthwestern Electric Pwr - Gen WSX111023 W0029238 DHPS 1-Pur Com Washer Dryer 31200 - Boiler Plant Equip-Coal Addition 201711 \$25 68 uthwestern Electric Pwr - Gen WSX111023 W0027549 DHPS 1 - RPL ROT PLOW SW 31200 - Boiler Plant Equip-Coal Addition 201711 \$25 68 uthwestern Electric Pwr - Gen WSX111023 W0027579 DHPS 1 - RPL ROT PLOW SW 31200 - Boiler Plant Equip-Coal Addition 201711 \$35,425 05 uthwestern Electric Pwr - Gen WSX111023 W0027652 DHPS 1 - RPL ROT PLOW SW 31200 - Boiler Plant Equip-Coal Addition 201711 \$35,425 05 uthwestern Electric Pwr - Gen WSX111023 W0027652 DHPS 1 - PLP GCOMPUTERS-2016 39111 - Office Equip - Coal man Equip-Coal Addition 201711 \$54,525 69 uthwestern Electric Pwr - Gen WSX111023 W0027552 DHPS 1 - PL GRZ RAFA LIGHT 31100 - Structures, Improvement-Coal Addition 201711 \$544 28 uthwestern Electric Pwr - Gen WSX111023 W0029097 DPNO - Upgrd Stm Turbine Vivs 31200 - Boiler Plant Equip-Coal Addition 201711 \$533,626	Southwestern Electric Pwr - Gen	WSX111023	W0028975	DPNO-REFURB CT GEARBOXES	31100 - Structures, Improvemnt-Coal	Addition	201711	(\$11,636 00)
uthwestern Electric Pwr - Gen WSX111023 W0027549 DHPS 1 - RPL ROT PLOW SW 31200 - Boiler Plant Equip-Coal Addition 201711 (5878 87) uthwestern Electric Pwr - Gen WSX111023 W0020750 DHPS 1 - RPL ROT PLOW SW 31200 - Boiler Plant Equip-Coal Addition 201711 (5189 82) uthwestern Electric Pwr - Gen WSX111023 W0027655 DHPS 1 - PURC COMPUTERS-2016 39111 - Office Equip - Computers Addition 201711 \$35,425 05 uthwestern Electric Pwr - Gen WSX111023 W0027552 DHPS 1 - PURC COMPUTERS-2016 39111 - Office Equip - Computers Addition 201711 \$63,026 94 uthwestern Electric Pwr - Gen WSX111023 W0027552 DHPS 1 - PURC COMPUTERS-2016 39110 - Office Equip - Coal Addition 201711 \$63,026 94 uthwestern Electric Pwr - Gen WSX111023 W0028575 DHPS 1 - PUR GRZLY BARS 31200 - Boiler Plant Equip-Coal Addition 201711 \$44 28 uthwestern Electric Pwr - Gen WSX111023 W0027857 DHPS 1 - UPG SLUD DST SYS 31200 - Boiler Plant Equip-Coal Addition 201711 \$18,518 87 uth	Southwestern Electric Pwr - Gen			DPNO-Rpl Rtr Plow Spider Wheel		Addition	201711	\$85 91
uthwestern Electric Pwr - Gen WSX111023 W0020750 DHPS1-REPLACE BOILER EXPANSION 31200 - Boiler Plant Equip-Coal Addition 201711 \$35,425 05 uthwestern Electric Pwr - Gen WSX111023 W0027707 DPNO-Rpl A&C Absor Twr Elbows 31200 - Boiler Plant Equip-Coal Addition 201711 \$35,425 05 uthwestern Electric Pwr - Gen WSX111023 W0027655 DHPS 1 - PURC COMPUTERS-2016 39111 - Office Equip - Coal Addition 201711 \$63,026 94 uthwestern Electric Pwr - Gen WSX111023 W0022052 DHPS 1 - PURC GCMPUTERS-2016 39110 - Office Equip - Coal Addition 201711 \$63,026 94 uthwestern Electric Pwr - Gen WSX111023 W0022000 DHPS 1 - UPG FGD AREA LIGHT 31100 - Structures, Improvemnt-Coal Addition 201711 \$534 26 uthwestern Electric Pwr - Gen WSX111023 W0022097 DPNO - Upgrd Strn Turbine Wiss 31200 - Boiler Plant Equip-Coal Addition 201711 \$18,518 87 uthwestern Electric Pwr - Gen WSX111023 W0022705 2015 TelComm Purchases-DHPS 39700 - Communication Equipment Addition 201711 \$18,518 87	Southwestern Electric Pwr - Gen							
outhwestern Electric Pwr - Gen WSX111023 W0027707 DPNO-Rpl A&C Absor Twr Elbows 31200 - Boiler Plant Equip-Coal Addition 201711 \$35,425 05 uthwestern Electric Pwr - Gen WSX111023 W0027565 DHPS 1 - PURC COMPUTERS-2016 39111 - Office Equip - Computers Addition 201711 (5145 54) uthwestern Electric Pwr - Gen WSX111023 W0027505 DHPS 1 - PURC COMPUTERS-2016 39111 - Office Equip - Coal Addition 201711 \$63,026 94 uthwestern Electric Pwr - Gen WSX111023 W0028000 DHPS 1 - UPG SLUD DST SYS 31200 - Boiler Plant Equip-Coal Addition 201711 \$534 26 uthwestern Electric Pwr - Gen WSX111023 W0029997 DPNO - Upgrd Stm Turbine Vivs 31200 - Boiler Plant Equip-Coal Addition 201711 \$18,518 87 uthwestern Electric Pwr - Gen WSX111023 W0027749 DHPS 1 - RPI Bif Furn Cout - 2016 31200 - Boiler Plant Equip-Coal Addition 201711 \$18,518 87 uthwestern Electric Pwr - Gen WSX111023 W0027449 DHPS 1 - RPI Bif Furn Cout - 2016 31200 - Boiler Plant Equip-Coal Addition 201711 \$158,185 73 </td <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>								
uthwestern Electric Pwr - Gen WSX111023 W0027655 DHPS 1 - PURC COMPUTERS-2016 39111 - Office Equip - Computers Addition 201711 (\$145 54) uthwestern Electric Pwr - Gen WSX111023 W0027552 DHPS 1 - PUR GRZIV BARS 31200 - Boiler Plant Equip-Coal Addition 201711 \$63,026 94 uthwestern Electric Pwr - Gen WSX111023 W0028000 DHPS 1 - UPG FGD AREA LIGHT 31100 - Structures, Improvemnt-Coal Addition 201711 \$542 28 uthwestern Electric Pwr - Gen WSX111023 W0028057 DHPS 1 - UPG SUUD DST SYS 31200 - Boiler Plant Equip-Coal Addition 201711 \$534 26 uthwestern Electric Pwr - Gen WSX111023 W0027907 DPNO - Upgrd Stm Turbine Vlvs 31200 - Boiler Plant Equip-Coal Addition 201711 \$18,518 87 uthwestern Electric Pwr - Gen WSX111023 W0027705 2015 TelComm Purchases-DHPS 39700 - Communication Equipment Addition 201711 \$18,518 87 uthwestern Electric Pwr - Gen WSX111023 W0027349 DHPS 1 - Inst Condins Tube Coat 31400 - Turbogenerator Units-Coal Addition 201711 \$425 48								
uthwestern Electric Pwr - Gen WSX111023 W0027552 DHPS 1 - RPL GRZLY BARS 31200 - Boiler Plant Equip-Coal Addition 201711 \$63,026 94 uthwestern Electric Pwr - Gen WSX111023 W0028000 DHPS 1 - UPG FGD AREA LIGHT 31100 - Structures, Improvement-Coal Addition 201711 \$44 28 uthwestern Electric Pwr - Gen WSX111023 W0028907 DHPS 1 - UPG SLUD DST SYS 31200 - Boiler Plant Equip-Coal Addition 201711 \$534 26 uthwestern Electric Pwr - Gen WSX111023 W0027907 DHPS 1 - UPG SLUD DST SYS 31200 - Boiler Plant Equip-Coal Addition 201711 \$534 26 uthwestern Electric Pwr - Gen WSX111023 W0027905 2015 TelComm Purchases-DHPS 39700 - Communication Equipment Addition 201711 \$18,518 87 uthwestern Electric Pwr - Gen WSX111023 W0027349 DHPS 1 - Inst Condons Tube Coal 31200 - Boiler Plant Equip-Coal Addition 201711 \$18,518 87 uthwestern Electric Pwr - Gen WSX111023 W0027846 DHPS 1 - PUR/INS SFTY UPG-201 31100 - Structures, Improvemnt-Coal Addition 201711 \$77 71				'	• •			
uthwestern Electric Pwr - Gen WSX111023 W0028000 DHPS 1 - UPG FGD AREA LIGHT 31100 - Structures, Improvemnt-Coal Addition 201711 \$44 28 uthwestern Electric Pwr - Gen WSX111023 W0028575 DHPS 1 - UPG SLUD DST SYS 31200 - Boiler Plant Equip-Coal Addition 201711 \$534 26 uthwestern Electric Pwr - Gen WSX111023 W0029097 DPNO - Upgrd Stm Turbine Vlvs 31200 - Boiler Plant Equip-Coal Addition 201711 \$534 26 uthwestern Electric Pwr - Gen WSX111023 W0027705 2015 TelComm Purchases-DHPS 39700 - Communication Equipment Addition 201711 \$158,518 87 uthwestern Electric Pwr - Gen WSX111023 W0027449 DHPS 1 - Rpl Blr Furn Cout - 2016 31200 - Boiler Plant Equip-Coal Addition 201711 \$158,188 73 uthwestern Electric Pwr - Gen WSX111023 W0027846 DHPS 1 - Rpl Blr Furn Cout - 2016 31200 - Boiler Plant Equip-Coal Addition 201711 \$425 48 uthwestern Electric Pwr - Gen WSX111023 W0027846 DHPS 1 - PUR/INS SFTY UPG-201 31100 - Structures, Improvemnt-Coal Addition 201711 \$30,555 26 </td <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>								
uthwestern Electric Pwr - Gen WSX111023 W0028575 DHPS 1 - UPG SLUD DST SYS 31200 - Boiler Plant Equip-Coal Addition 201711 \$534 26 uthwestern Electric Pwr - Gen WSX111023 W0029097 DPNO - Upgrd Stm Turbine Vivs 31200 - Boiler Plant Equip-Coal Addition 201711 \$18,518 87 uthwestern Electric Pwr - Gen WSX111023 W0027749 DHPS 1 - Rpl Bir Furn Cout - 2016 31200 - Boiler Plant Equip-Coal Addition 201711 \$22 85) uthwestern Electric Pwr - Gen WSX111023 W0027349 DHPS 1 - Rpl Bir Furn Cout - 2016 31200 - Boiler Plant Equip-Coal Addition 201711 \$425 48 uthwestern Electric Pwr - Gen WSX111023 W0027382 DHPS 1 - Inst Condustry Tube Coat 31400 - Turbogenerator Units-Coal Addition 201711 \$425 48 uthwestern Electric Pwr - Gen WSX111023 W0027764 DPNO-Rpl Water Pit Controls 31500 - Structures, Improvement-Coal Addition 201711 \$30,555 26 uthwestern Electric Pwr - Gen WSX111023 W0027867 DPNO-Rpl Water Pit Controls 31100 - Structures, Improvement-Coal Addition 201711 \$32,555 26								
uthwestern Electric Pwr - Gen WSX111023 W0029097 DPNO - Upgrd Stm Turbine VIvs 31200 - Boiler Plant Equip-Coal Addition 201711 \$18,518 87 uthwestern Electric Pwr - Gen WSX111023 W0027705 2015 TelComm Purchases-DHPS 39700 - Communication Equipment Addition 201711 \$128,518 87 uthwestern Electric Pwr - Gen WSX111023 W0027449 DHPS 1 - Inst Conders Tube Coat 31200 - Boiler Plant Equip-Coal Addition 201711 \$158,188 73 uthwestern Electric Pwr - Gen WSX111023 W0027849 DHPS 1 - Inst Conders Tube Coat 31400 - Turbogenerator Units-Coal Addition 201711 \$425 48 uthwestern Electric Pwr - Gen WSX111023 W0027846 DHPS 1 - PUR/INS SFTY UPG-201 31100 - Structures, Improvemnt-Coal Addition 201711 \$7 71 uthwestern Electric Pwr - Gen WSX111023 W0027670 DHPS 1 - Inst Flir Tile & DRS 31100 - Structures, Improvemnt-Coal Addition 201711 \$30,555 26 uthwestern Electric Pwr - Gen WSX111023 W0027670 DHPS 1 - Inst Flir Tile & DRS 31100 - Structures, Improvemnt-Coal Addition 201711 \$32,555 2								
uthwestern Electric Pwr - Gen WSX111023 W0027705 2015 TelComm Purchases-DHPS 39700 - Communication Equipment Addition 201711 (\$22 85) uthwestern Electric Pwr - Gen WSX111023 W00277449 DHPS 1 - RIP BIF Furn Cout - 2016 31200 - Boiler Plant Equip-Coal Addition 201711 \$158,185 73 uthwestern Electric Pwr - Gen WSX111023 W0027846 DHPS 1 - Inst Condons Tube Coal 31400 - Turbogenerator Units-Coal Addition 201711 \$425 48 uthwestern Electric Pwr - Gen WSX111023 W0027846 DHPS 1 - PUR/INS SFTY UPG-201 31100 - Structures, Improvement-Coal Addition 201711 \$30,555 26 uthwestern Electric Pwr - Gen WSX111023 W0027704 DPNO-Rpl Water PIt Controls 31500 - Accessory Elect Equip-Coal Addition 201711 \$30,555 26 uthwestern Electric Pwr - Gen WSX111023 W0027870 DHPS 1 - RPL FUEL HND NUC CHUT 31200 - Boiler Plant Equip-Coal Addition 201711 \$532,552 29 uthwestern Electric Pwr - Gen WSX111023 W0027867 DHPS 1 - RPL FUEL HND NUC CHUT 31200 - Boiler Plant Equip-Coal Addition 201711 \$452 49	Southwestern Electric Pwr - Gen							
uthwestern Electric Pwr - Gen WSX111023 W0027449 DHPS 1 - Rpl Blr Furn Cout - 2016 31200 - Boiler Plant Equip-Coal Addition 201711 \$158,185 73 uthwestern Electric Pwr - Gen WSX111023 W0027846 DHPS 1 - Inst Condinst Tube Coat 31400 - Turbogenerator Units-Coal Addition 201711 \$425 48 uthwestern Electric Pwr - Gen WSX111023 W0027846 DHPS 1 - PUR/INS STTY UPG-201 31100 - Structures, Improvemnt-Coal Addition 201711 \$57 71 uthwestern Electric Pwr - Gen WSX111023 W0027767 DPNO-Rpl Water Pit Controls 31500 - Accessory Elect Equip-Coal Addition 201711 \$30,555 26 uthwestern Electric Pwr - Gen WSX111023 W0027670 DHPS 1 - Insti Pir Tile & DRS 31100 - Structures, Improvemnt-Coal Addition 201711 \$30,555 26 uthwestern Electric Pwr - Gen WSX111023 W0027867 DHPS 1 - RPI FUEL HND NUC CHUT 31200 - Boiler Plant Equip-Coal Addition 201711 \$425 44 uthwestern Electric Pwr - Gen WSX111023 W0028853 DHPS 1 - RPI FUEL HND NUC CHUT 31200 - Boiler Plant Equip-Coal Addition 201711 \$432 49<	Southwestern Electric Pwr - Gen	WSX111023	W0027705		39700 - Communication Equipment			
uthwestern Electric Pwr - Gen WSX111023 W0027846 DHPS 1 - PUR/INS SFTY UPG-201 31100 - Structures, Improvemnt-Coal Addition 201711 \$7 71 uthwestern Electric Pwr - Gen WSX111023 W0027704 DPNO-Rpl Water PIt Controls 31500 - Accessory Elect Equip-Coal Addition 201711 \$30,555 26 uthwestern Electric Pwr - Gen WSX111023 W0027670 DHPS 1 - Inst I Fir Tile & DRS 31100 - Structures, Improvemnt-Coal Addition 201711 \$30,555 26 uthwestern Electric Pwr - Gen WSX111023 W0027833 DHPS 1 - RPL FUEL HND NUC CHUT 31200 - Boiler Plant Equip-Coal Addition 201711 \$452 19 uthwestern Electric Pwr - Gen WSX111023 W0027677 DHPS 1 - UPG IF1 & 1F2 MCC 31200 - Boiler Plant Equip-Coal Addition 201711 \$452 44 uthwestern Electric Pwr - Gen WSX111023 W0027671 DHPS 1 - RPL FUEL HND NUC CHUT 31200 - Boiler Plant Equip-Coal Addition 201711 \$132 93 uthwestern Electric Pwr - Gen WSX111023 W0027671 DHPS 1 - RPL FUEL HND TUR-2015 39100 - Office Furniture, Equipment Addition 201711 \$136 44 </td <td>Southwestern Electric Pwr - Gen</td> <td>WSX111023</td> <td>W0027449</td> <td>DHPS 1 - Rpl Blr Furn Cout - 2016</td> <td>31200 - Boiler Plant Equip-Coal</td> <td>Addition</td> <td>201711</td> <td></td>	Southwestern Electric Pwr - Gen	WSX111023	W0027449	DHPS 1 - Rpl Blr Furn Cout - 2016	31200 - Boiler Plant Equip-Coal	Addition	201711	
uthwestern Electric Pwr - Gen WSX111023 W0027704 DPNO-Rpl Water Plt Controls 31500 - Accessory Elect Equip-Coal Addition 201711 \$30,555 26 uthwestern Electric Pwr - Gen WSX111023 W0027670 DHPS 1 - Instl Flr Tile & DRS 31100 - Structures, Improvemnt-Coal Addition 201711 (\$842 13) uthwestern Electric Pwr - Gen WSX111023 W00227870 DHPS 1 - RPL FUEL HND NUC CHUT 31200 - Boiler Plant Equip-Coal Addition 201711 (\$495 44) uthwestern Electric Pwr - Gen WSX111023 W00227867 DHPS 1 - RPL FUEL HND NUC CHUT 31200 - Boiler Plant Equip-Coal Addition 201711 (\$495 44) uthwestern Electric Pwr - Gen WSX111023 W0022767 DHPS 1 - RPL OFF FURNITUR-2015 39100 - Office Furniture, Equipment Addition 201711 (\$363 14) uthwestern Electric Pwr - Gen WSX111023 W0027672 DHPS 1 - RPL OFF FURNITUR-2016 39100 - Office Furniture, Equipment Addition 201711 (\$363 14) uthwestern Electric Pwr - Gen WSX111023 W0027672 DHPS 1 - RPL OFF FURNITUR-2016 39100 - Office Furniture, Equipment Addition 201711	Southwestern Electric Pwr - Gen					Addition	201711	\$425 48
uthwestern Electric Pwr - Gen WSX111023 W0027670 DHPS 1 - InstI Flr Tile & DRS 31100 - Structures, Improvemnt-Coal Addition 201711 (\$842 13) uthwestern Electric Pwr - Gen WSX111023 W0028853 DHPS 1 - RPI FUEL HND NUC CHUT 31200 - Boiler Plant Equip-Coal Addition 201711 \$152 19 uthwestern Electric Pwr - Gen WSX111023 W0029176 DHPS 1 - RPI FUEL HND NUC CHUT 31200 - Boiler Plant Equip-Coal Addition 201711 \$152 19 uthwestern Electric Pwr - Gen WSX111023 W0029176 DHPS 1 - RPI FUEL HND NUC CHUT 31200 - Boiler Plant Equip-Coal Addition 201711 \$132 93 uthwestern Electric Pwr - Gen WSX111023 W0029771 DHPS 1 - RPI OFF FURNITUR-2015 39100 - Office Furniture, Equipment Addition 201711 \$1363 14) uthwestern Electric Pwr - Gen WSX111023 W0027672 DHPS 1 - RPI OFF FURNITUR-2016 39100 - Office Furniture, Equipment Addition 201711 \$156 02 uthwestern Electric Pwr - Gen WSX111023 W0028605 Replace Ash Hopper Wall - DHPS 31200 - Boiler Plant Equip-Coal Addition 201711 \$16 30	Southwestern Electric Pwr - Gen				· ·			
uthwestern Electric Pwr - Gen WSX111023 W0028853 DHPS 1 - RPL FUEL HND NUC CHUT 31200 - Boiler Plant Equip-Coal Addition 201711 \$152 19 uthwestern Electric Pwr - Gen WSX111023 W0027367 DHPS 1 - VPG IF1. & IF2 MCC 31200 - Boiler Plant Equip-Coal Addition 201711 \$455 44 uthwestern Electric Pwr - Gen WSX111023 W0027671 DPNO-ACI Silo Coating 31200 - Boiler Plant Equip-Coal Addition 201711 \$132 93 uthwestern Electric Pwr - Gen WSX111023 W0027671 DPNO-ACI Silo Coating 31200 - Boiler Plant Equip-Coal Addition 201711 \$132 93 uthwestern Electric Pwr - Gen WSX111023 W0027672 DHPS 1 - RPL OFF FURNITUR-2015 39100 - Office Furniture, Equipment Addition 201711 \$156 02 uthwestern Electric Pwr - Gen WSX111023 W0027672 DHPS 1 - RPL OFF FURNITUR-2016 39100 - Office Furniture, Equipment Addition 201711 \$156 02 uthwestern Electric Pwr - Gen WSX111023 W0028605 Replace Ash Hopper Wall - DHPS 31200 - Boiler Plant Equip-Coal Addition 201711 \$18 42	Southwestern Electric Pwr - Gen							
uthwestern Electric Pwr - Gen WSX111023 W0027367 DHPS 1 - UPG IF1 & 1F2 MCC 31200 - Boiler Plant Equip-Coal Addition 20711 (\$495 44) uthwestern Electric Pwr - Gen WSX111023 W0029176 DPNO-ACI Silo Coating 31200 - Boiler Plant Equip-Coal Addition 201711 \$132 93 uthwestern Electric Pwr - Gen WSX111023 W0027671 DHPS 1 - RPL OFF FURNITUR-2015 39100 - Office Furniture, Equipment Addition 201711 (\$166 02) uthwestern Electric Pwr - Gen WSX111023 W0027672 DHPS 1 - RPL OFF FURNITUR-2016 39100 - Office Furniture, Equipment Addition 201711 (\$166 02) uthwestern Electric Pwr - Gen WSX111023 W0028605 Replace Ash Hopper Wall - DHPS 31200 - Boiler Plant Equip-Coal Addition 201711 (\$31 63) uthwestern Electric Pwr - Gen WSX111023 W0028853 DHPS 1 - RPL FUEL HND NUC CHUT 31200 - Boiler Plant Equip-Coal Addition 201712 \$18 42 uthwestern Electric Pwr - Gen WSX111023 W0029176 DPNO-ACI Silo Coating 31200 - Boiler Plant Equip-Coal Addition 201712 \$16 69								
uthwestern Electric Pwr - Gen WSX111023 W0029176 DPNO-ACI Silo Coating 31200 - Boiler Plant Equip-Coal Addition 201711 \$132 93 uthwestern Electric Pwr - Gen WSX111023 W0027671 DHPS 1 - RPL OFF FURNITUR-2015 39100 - Office Furniture, Equipment Addition 201711 (\$163 14) uthwestern Electric Pwr - Gen WSX111023 W0027672 DHPS 1 - RPL OFF FURNITUR-2016 39100 - Office Furniture, Equipment Addition 201711 (\$156 02) uthwestern Electric Pwr - Gen WSX111023 W0028605 Replace Ash Hopper Wall - DHPS 31200 - Boiler Plant Equip-Coal Addition 201712 (\$316 63) uthwestern Electric Pwr - Gen WSX111023 W0028853 DHPS 1 - RPL FUEL HND NUC CHUT 31200 - Boiler Plant Equip-Coal Addition 201712 \$18 42 uthwestern Electric Pwr - Gen WSX111023 W0029176 DPNO-ACI Silo Coating 31200 - Boiler Plant Equip-Coal Addition 201712 \$16 09 uthwestern Electric Pwr - Gen WSX111023 W0027449 DHPS 1 - RPL Full Full Cout - 2016 31200 - Boiler Plant Equip-Coal Addition 201712 \$16 09								
uthwestern Electric Pwr - Gen WSX111023 W0027671 DHPS 1 - RPL OFF FURNITUR-2015 39100 - Office Furniture, Equipment Addition 201711 (\$163 14) uthwestern Electric Pwr - Gen WSX111023 W0027672 DHPS 1 - RPL OFF FURNITUR-2016 39100 - Office Furniture, Equipment Addition 201711 (\$156 02) uthwestern Electric Pwr - Gen WSX111023 W002865 Replace Ash Hopper Wall - DHPS 31200 - Boiler Plant Equip-Coal Addition 201711 (\$31 63) uthwestern Electric Pwr - Gen WSX111023 W0028853 DHPS 1 - RPL FUEL HND NUC CHUT 31200 - Boiler Plant Equip-Coal Addition 201712 \$18 42 uthwestern Electric Pwr - Gen WSX111023 W0029176 DPNO-ACI Silo Coating 31200 - Boiler Plant Equip-Coal Addition 201712 \$16 69 uthwestern Electric Pwr - Gen WSX111023 W0027449 DHPS 1 - Rpl Bir Furn Cout - 2016 31200 - Boiler Plant Equip-Coal Addition 201712 \$17,149 41								
uthwestern Electric Pwr - Gen WSX111023 W0027672 DHPS 1 - RPL OFF FURNITUR-2016 39100 - Office Furniture, Equipment Addition 201711 (\$156 02) uthwestern Electric Pwr - Gen WSX111023 W0028605 Replace Ash Hopper Wall - DHPS 31200 - Boiler Plant Equip-Coal Addition 201711 (\$31 63) uthwestern Electric Pwr - Gen WSX111023 W0028853 DHPS 1 - RPL FUEL HND NUC CHUT 31200 - Boiler Plant Equip-Coal Addition 201712 \$18 42 uthwestern Electric Pwr - Gen WSX111023 W0029176 DPNO-ACI Silo Coating 31200 - Boiler Plant Equip-Coal Addition 201712 \$16 69 uthwestern Electric Pwr - Gen WSX111023 W0027449 DHPS 1 - Rpl Bir Furn Cout - 2016 31200 - Boiler Plant Equip-Coal Addition 201712 \$16 09								
uthwestern Electric Pwr - Gen WSX111023 W0028605 Replace Ash Hopper Wall - DHPS 31200 - Boiler Plant Equip-Coal Addition 201711 (\$31 63) uthwestern Electric Pwr - Gen WSX111023 W0028853 DHPS 1 - RPL FUEL HND NUC CHUT 31200 - Boiler Plant Equip-Coal Addition 201712 \$18 42 uthwestern Electric Pwr - Gen WSX111023 W0029176 DPNO-ACI Silo Coating 31200 - Boiler Plant Equip-Coal Addition 201712 \$16 09 uthwestern Electric Pwr - Gen WSX111023 W0027449 DHPS 1 - Rpl Blr Furn Cout - 2016 31200 - Boiler Plant Equip-Coal Addition 201712 (\$7,149 41)								
uthwestern Electric Pwr - Gen WSX111023 W0028853 DHPS 1 - RPL FUEL HND NUC CHUT 31200 - Boiler Plant Equip-Coal Addition 201712 \$18 42 uthwestern Electric Pwr - Gen WSX111023 W0029176 DPNO-ACI Silo Coating 31200 - Boiler Plant Equip-Coal Addition 201712 \$16 09 uthwestern Electric Pwr - Gen WSX111023 W0027449 DHPS 1 - Rpl Blr Furn Cout - 2016 31200 - Boiler Plant Equip-Coal Addition 201712 (\$7,149 41)								
uthwestern Electric Pwr - Gen WSX111023 W0029176 DPNO-ACI Silo Coating 31200 - Boiler Plant Equip-Coal Addition 201712 \$16.09 uthwestern Electric Pwr - Gen WSX111023 W0027449 DHPS 1 - Rpl Blr Furn Cout - 2016 31200 - Boiler Plant Equip-Coal Addition 201712 (\$7,149.41)	Southwestern Electric Pwr - Gen							
uthwestern Electric Pwr - Gen WSX111023 W0027449 DHPS 1 - Rpl Blr Furn Cout - 2016 31200 - Boiler Plant Equip-Coal Addition 201712 (57,149 41)	Southwestern Electric Pwr - Gen							
	Southwestern Electric Pwr - Gen			-				
uthwestern Electric Pwr - Gen WSX111023 W0023457 DHPS 1- REPLACE BOILER EXPAN J 31200 - Boiler Plant Equip-Coal Addition 201712 (518 59)	Southwestern Electric Pwr - Gen	WSX111023	W0023457	DHPS 1- REPLACE BOILER EXPAN J	31200 - Boiler Plant Equip-Coal	Addition	201712	(\$18 59)
uthwestern Electric Pwr - Gen WSX111023 W0029097 DPNO - Upgrd Stm Turbine Vlvs 31200 - Boiler Plant Equip-Coal Addition 201712 \$155 12	Southwestern Electric Pwr - Gen	WSX111023	W0029097	DPNO - Upgrd Stm Turbine Vivs	31200 - Boiler Plant Equip-Coal	Addition	201712	\$155 12

							Page 5 o
Company	Budget ID	Work Order	Work Order Descr	Utility Account	FERC Act Code	Month Number	Activity Cost
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1-Pur Com Washer Dryer	31200 - Boiler Plant Equip-Coal	Addition	201712	\$3 11
Southwestern Electric Pwr - Gen	WSX111023		DHPS1-RPL TDBFP ELEMENT	31200 - Boiler Plant Equip-Coal	Addition	201712	\$303,809 99
Southwestern Electric Pwr - Gen	WSX111023		DHPS1-REPLACE BOILER EXPANSION	31200 - Boiler Plant Equip-Coal	Addition	201712	\$19 06
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rpl Cool Twr Fan Shrouds	31400 - Turbogenerator Units-Coal	Addition	201712	\$4,118 19
Southwestern Electric Pwr - Gen	WSX111023	W0028975	DPNO-REFURB CT GEARBOXES	31100 - Structures, Improvemnt-Coal	Addition	201712	\$3,566 65
Southwestern Electric Pwr - Gen	WSX111023	W0029090	DPNO-Rpl Lignite Conv Belts	31100 - Structures, Improvemnt-Coal	Addition	201712	\$69 40
Southwestern Electric Pwr - Gen	WSX111023	W0028969	DPNO-RPL FGD EXP JOINTS	31200 - Boiler Plant Equip-Coal	Addition	201712	\$29 22
Southwestern Electric Pwr - Gen	WSX111023		DHPS1-Rpice FGD Convey Frame	31600 - Misc Pwr Plant Equip-Coal	Addition	201712	\$ 19 1 5
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - Instl Flr Tile & DRS	31100 - Structures, Improvemnt-Coal	Addition	201712	(\$99 34)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL CONV GEAR RDC 2015	31200 - Boiler Plant Equip-Coal	Addition	201712	(\$1,215 79)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - UP CLG TOW MTR - 2016	31200 - Boiler Plant Equip-Coal	Addition	201712	\$0 58
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rpl Water Plt Controls	31500 - Accessory Elect Equip-Coal	Addition	201712	(\$2,544 55)
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO-Rpl Water Plant Controls	31100 - Structures, Improvemnt-Coal	Addition	201712	\$30 67
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - RPL ROT PLOW SW DHPS 1 - RPL/UPG HGH PR DR PMP	31200 - Boiler Plant Equip-Coal	Addition	201712 201712	\$234 50
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - UPG FGD AREA LIGHT	31200 - Boiler Plant Equip-Coal 31100 - Structures, Improvemnt-Coal	Addition Addition	201712	(\$1,455.49) \$5.36
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rpl Cooling Twr Demisters	31400 - Turbogenerator Units-Coal	Addition	201712	\$370 48
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - UPG FUEL HAND FIRE PR	31200 - Boiler Plant Equip-Coal	Addition	201712	\$5 37
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rpl A&C Absor Twr Elbows	31200 - Boiler Plant Equip-Coal	Addition	201712	\$22,941 27
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RFB COOL TOW GEARBXS	31400 - Turbogenerator Units-Coal	Addition	201712	\$18 89
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1-Replace Conveyor Gear	31200 - Boiler Plant Equip-Coal	Addition	201712	\$1,301 36
Southwestern Electric Pwr - Gen	WSX111023	W0027846	DHPS 1 - PUR/INS SFTY UPG-201	31100 - Structures, Improvemnt-Coal	Addition	201712	\$0.93
Southwestern Electric Pwr - Gen	WSX111023	W0028575	DHPS 1 - UPG SLUD DST SYS	31200 - Boiler Plant Equip-Coal	Addition	201712	\$64 68
Southwestern Electric Pwr - Gen	WSX111023	W0029089	DPNO-Replace Fuel Handl Chutes	31100 - Structures, Improvemnt-Coal	Addition	201712	\$50 35
Southwestern Electric Pwr - Gen	WSX111023	W0029091	DPNO-Rpl Rtr Plow Spider Wheel	31200 - Boiler Plant Equip-Coal	Addition	201712	\$10 40
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL GRZLY BARS	31200 - Boiler Plant Equip-Coal	Addition	201712	(52,714 82)
Southwestern Electric Pwr - Gen	WSX111023		DHPS1-RPL TDBFP ELEMENT	31200 - Boiler Plant Equip-Coal	Addition	201801	(\$1,395 20)
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rpl A&C Absor Twr Elbows	31200 - Boiler Plant Equip-Coal	Addition	201801	(\$3,078 13)
Southwestern Electric Pwr - Gen	WSX111023		DPNO-REFURB CT GEARBOXES	31100 - Structures, Improvemnt-Coal	Addition	201801	\$16,813 75
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1-Pur Com Washer Dryer	31200 - Boiler Plant Equip-Coal	Addition	201801	\$1,270 16
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1-Pur Com Washer Dryer	31200 - Boiler Plant Equip-Coal 31200 - Boiler Plant Equip-Coal	Addition	201802 201802	(\$154.30)
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO-Rpl A&C Absor Twr Elbows DPNO-REFURB CT GEARBOXES	31100 - Structures, Improvemnt-Coal	Addition Addition	201802	(\$149 50) (\$2,042 64)
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS1-RPL TOBFP ELEMENT	31200 - Soiler Plant Equip-Coal	Addition	201802	\$0 11
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Inst BFPT Control Oil Filt	31200 - Boiler Plant Equip-Coal	Addition	201803	\$16,351 57
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Upgrade FGD Area Lighting	31200 - Boiler Plant Equip-Coal	Addition	201803	\$20,034 10
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rpl 4160V Switchgear - 2017	31200 - Boiler Plant Equip-Coal	Addition	201803	\$26,725 51
Southwestern Electric Pwr - Gen	WSX111023	W0030538	DHPS Rpl Blr Fur Cout Tube	31200 - Boiler Plant Equip-Coal	Addition	201803	(\$17.30)
Southwestern Electric Pwr - Gen	WSX111023	W0029454	Dolet Hills Power Station	31200 - Boiler Plant Equip-Coal	Addition	201803	\$10,373 24
Southwestern Electric Pwr - Gen	WSX111023	W0028576	DPNO-Rpl Cool Twr Fan Shrouds	31400 - Turbogenerator Units-Coal	Addition	201803	\$859 75
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1-Replace Conveyor Gear	31200 - Boiler Plant Equip-Coal	Addition	201803	\$5,149 10
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rpl Rcyc Pmp Impeliers	31200 - Boiler Plant Equip-Coal	Addition	201803	\$37,498 12
Southwestern Electric Pwr - Gen	W5X111023		DPNO - REPL/REFB TDBFP EL	31200 - Boiler Plant Equip-Coal	Addition	201803	(\$6,429 91)
Southwestern Electric Pwr - Gen	W5X111023		DPNO-Rpl Transmitters	31200 - Boiler Plant Equip-Coal	Addition	201803	\$12,611 11
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO-Refurbish Crit Equip Heat DHPS1 Line work for Dolet	31200 - Boiler Plant Equip-Coal 31600 - Misc Pwr Plant Equip-Coal	Addition Addition	201803 201803	\$12,302 37 \$234,234 67
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - RPL BRN NOZ TIPS-2016	31200 - Nilse Fwi Flant Equip-Coal	Addition	201803	\$207,307 40
Southwestern Electric Pwr - Gen	WSX111023		DPNO - REPAVE SRV BLDG PK LOT	31100 - Structures, Improvemnt-Coal	Addition	201803	\$7,044 79
Southwestern Electric Pwr - Gen	W\$X111023		DPNO-Rpice Fuel Handi Gar Door	31100 - Structures, Improvemnt-Coal	Addition	201803	\$12,944 54
Southwestern Electric Pwr - Gen	WSX111023	W0029239	DHPS 1-Rpl FGD Convey Belt	31500 - Accessory Elect Equip-Coal	Addition	201803	\$13,878 31
Southwestern Electric Pwr - Gen	W5X111023	W0029238	DHPS 1-Pur Com Washer Dryer	31200 - Boiler Plant Equip-Coal	Addition	201803	\$791 13
Southwestern Electric Pwr - Gen	WSX111023	W0028716	DHPS 1 - RPL COOL TWR FAN MTRS	31400 - Turbogenerator Units-Coal	Addition	201803	\$25,253 81
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Replace Misc Valves	31600 - Misc Pwr Plant Equip-Coal	Addition	201803	\$89,023 78
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rpl Misc Cable Tray	31100 - Structures, Improvemnt-Coal	Addition	201803	\$10,361 61
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - INSTL AMB AIR SO2 MON	31200 - Boiler Plant Equip-Coal	Addition	201803	\$217,049 98
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rpl Boiler Exp Joints	31200 - Boiler Plant Equip-Coal	Addition	201803 201803	\$23,529 95
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO Rpic Boiler Waterwall Soo DPNO - RPLC D9 DOZER ENG	31200 - Boiler Plant Equip-Coal 31600 - Misc Pwr Plant Equip-Coal	Addition	201803	\$320,115 76 \$28,205 80
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO-Rpl Fuel Hnd Gran Rtr	31200 - Misc FWI Flant Equip-Coal	Addition Addition	201803	\$55,929 72
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO-Inst Wireless Vib Equip	31200 - Boiler Plant Equip-Coal	Addition	201803	\$15,564 20
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Replic Electric Carts	31200 - Boiler Plant Equip-Coal	Addition	201803	\$12,785 00
Southwestern Electric Pwr - Gen	WSX111023		DPNO - Upgd Fuel Fire Sys Ctrl	31200 - Boiler Plant Equip-Coal	Addition	201803	\$25,895 26
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL UNDGRD PIP	31200 - Boiler Plant Equip-Coal	Addition	201803	\$48,221 25
Southwestern Electric Pwr - Gen	WSX111023	W0029237	DHPS 1 - RPL ASH SLUICE PUMP	31200 - Boiler Plant Equip-Coal	Addition	201803	\$19,570 78
Southwestern Electric Pwr - Gen	WSX111023	W0029452	DPNO-Rpl Pulverizer Ring	31200 - Boiler Plant Equip-Coal	Addition	201803	\$129,084 44
Southwestern Electric Pwr - Gen	WSX111023	W0029856	DPNO-RPLC SH/RH DMPR DRVS	31200 - Boiler Plant Equip-Coal	Addition	201803	\$56,536 33
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL COOL TWR FAN MTRS	31400 - Turbogenerator Units-Coal	Addition	201804	(\$/92 23)
Southwestern Electric Pwr - Gen	WSX111023		DPNO Rplc Boiler Waterwall Soo	31200 - Boiler Plant Equip-Coal	Addition	201804	(\$5 246 54)
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rpl 4160V Switchgear - 2017	31200 - Borler Plant Equip-Coal	Addition	201804	(\$796.74)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL UNDGRD PIP	31200 - Boiler Plant Equip-Coal	Addition	201804	\$8,684 10
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL BRN NOZ TIPS-2016	31200 - Boiler Plant Equip-Coal	Addition	201804	(\$6 515 27)
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO-Rpl Misc Cable Tray DPNO-Rpl Rcyc Pmp Impellers	31100 - Structures, Improvemnt-Coal 31200 - Boiler Plant Equip-Coal	Addition	201804 201804	(\$216.15)
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO-RPLC SH/RH DMPR DRVS	31200 - Boiler Plant Equip-Coal 31200 - Boiler Plant Equip-Coal	Addition Addition	201804	(\$894 17) (\$774 02)
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO-Inst BFPT Control Oil Filt	31200 - Boiler Plant Equip-Coal	Addition	201804	(\$260.02)
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Refurbish Crit Equip Heat	31200 - Boiler Plant Equip-Coal	Addition	201804	(\$250 20)
Southwestern Electric Pwr - Gen	WSX111023		Dolet Hills Power Station	31200 - Boiler Plant Equip-Coal	Addition	201804	\$182 27
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rpl Fuel Hnd Gran Rtr	31200 - Boiler Plant Equip-Coal	Addition	201804	(\$1,112 57)
Southwestern Electric Pwr - Gen	WSX111023	W0029452	DPNO-Rpl Pulverizer Ring	31200 - Boiler Plant Equip-Coal	Addition	201804	(\$2,548.12)
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Repic Electric Carts	31200 - Boiler Plant Equip-Coal	Addition	201804	(\$351 10)
Southwestern Electric Pwr - Gen	WSX111023		DPNO - RPLC D9 DOZER ENG	31600 - Misc Pwr Plant Equip-Coal	Addition	201804	(\$483 84)
Southwestern Electric Pwr - Gen	WSX111023	W0029978	DPNO-Rpice Fuel Handl Gar Door	31100 - Structures, Improvemnt-Coal	Addition	201804	(\$223 62)

Attachment 1
Page 6 of 8

Company Budget ID Work Order Work Order Descr Utility Account Code Month Number Activity Cost

Pern Electric Pwr - Gen WSX111023 W0029239 DHPS 1-Rpl FGD Convey Belt 31500 - Accessory Elect Equip-Coal Addition 201804 (\$381 17)

Pern Electric Pwr - Gen WSX111023 W0029856 DHPS 1-Replace Conveyor Gear 31200 - Boller Plant Equip-Coal Addition 201804 \$7,944 61

Page 6 of 8

FERC Act

Code Month Number Activity Cost

15381 17)

DHPS 1-Replace Conveyor Gear 31200 - Boller Plant Equip-Coal Addition 201804 \$7,944 61

Page 6 of 8

Company	Budget ID	Work Order	Work Order Descr	Utility Account	Code	Month Number	Activity Cost
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1-Rpl FGD Convey Belt	31500 - Accessory Elect Equip-Coal	Addition	201804	(\$381 17)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1-Replace Conveyor Gear	31200 - Boiler Plant Equip-Coal	Addition	201804	\$7,944 61
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Replace Misc Valves	31600 - Misc Pwr Plant Equip-Coal	Addition	201804	(\$1,827.50)
Southwestern Electric Pwr - Gen	WSX111023		DHPS Rpl Blr Fur Cout Tube	31200 - Boiler Plant Equip-Coal	Addition	201804	\$20 11
Southwestern Electric Pwr - Gen	WSX111023		DHPS1 Line work for Dolet	31600 - Misc Pwr Plant Equip-Coal	Addition	201804	\$42 26
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1-Pur Com Washer Dryer	31200 - Boiler Plant Equip-Coal	Addition	201804	\$137 11
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rpl Transmitters	31200 - Boiler Plant Equip-Coal	Addition	201804	(\$338 18)
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Inst Wireless Vib Equip	31200 - Boiler Plant Equip-Coal	Addition	201804	(\$248 27)
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Upgrade FGD Area Lighting	31200 - Boiler Plant Equip-Coal	Addition	201804	(\$479 39)
Southwestern Electric Pwr - Gen	WSX111023		DPNO - REPAVE SRV BLDG PK LOT	31100 - Structures, Improvemnt-Coal	Addition	201804	(\$173 63)
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - RPL ASH SLUICE PUMP DPNO - RPLC SIDING PLT BLDGS	31200 - Boiler Plant Equip-Coal	Addition	201804 201805	(\$382.80)
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO - PURC COMPUTERS-2017	31100 - Structures, Improvemnt-Coal 39111 - Office Equip - Computers	Addition Addition	201805	\$21,541 37 \$12,324 11
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1-Replace Conveyor Gear	31200 - Boiler Plant Equip-Coal	Addition	201805	(\$1,551.74)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL UNDGRD PIP	31200 - Boiler Plant Equip-Coal	Addition	201805	(\$44.62)
Southwestern Electric Pwr - Gen	WSX111023		Dolet Hills Power Station	31200 - Boiler Plant Equip-Coal	Addition	201805	(\$24.86)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL MDBFP	31200 - Boiler Plant Equip-Coal	Addition	201805	\$253,689 13
Southwestern Electric Pwr - Gen	WSX111023		DPNO-REFURB CT GEARBOXES	31100 - Structures, Improvemnt-Coal	Addition	201805	(\$22,928.05)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL BRN NOZ TIPS-2016	31200 - Boiler Plant Equip-Coal	Addition	201805	\$19,525 30
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rpl Fuel Hndl NcIr Cht	31200 - Boiler Plant Equip-Coal	Addition	201805	\$13,352 76
Southwestern Electric Pwr - Gen	WSX111023		DPNO-RPLC PLNT BLDG ROOFs	31100 - Structures, Improvemnt-Coal	Addition	201805	\$84,195 35
Southwestern Electric Pwr - Gen	WSX111023		DPNO - INST PLNT SEC CMRS	31100 - Structures, Improvemnt-Coal	Addition	201805	\$3,182 65
Southwestern Electric Pwr - Gen	WSX111023		DHPS1-Rpl Boil Wtr STBLWR	31200 - Boiler Plant Equip-Coal	Addition	201805	\$772 77
Southwestern Electric Pwr - Gen	WSX111023	W0028715	DHPS 1 - RPL MISC HVAC UNITS	31200 - Boiler Plant Equip-Coal	Addition	201805	\$68,399 35
Southwestern Electric Pwr - Gen	WSX111023	W0028576	DPNO-Rpl Cool Twr Fan Shrouds	31400 - Turbogenerator Units-Coal	Addition	201805	(\$194.20)
Southwestern Electric Pwr - Gen	WSX111023	W0028976	DPNO-2017 Purchase Tools	31600 - Misc Pwr Plant Equip-Coal	Addition	201805	\$32,852 67
Southwestern Electric Pwr - Gen	WSX111023	W0028714	DPNO - Upgrade stack lighting	31100 - Structures, Improvemnt-Coal	Addition	201805	\$42,986 68
Southwestern Electric Pwr - Gen	WSX111023	W0030749	Project Management Fin-1-11-18	31200 - Boiler Plant Equip-Coal	Addition	201806	\$28,945 13
Southwestern Electric Pwr - Gen	WSX111023	W0027369	DHPS 1 - RPL BRN NOZ TIPS-2016	31200 - Boiler Plant Equip-Coal	Addition	201806	\$19,575 37
Southwestern Electric Pwr - Gen	WSX111023	W0029855	DPNO-Repice FGD PMP Bases	31200 - Boiler Plant Equip-Coal	Addition	201806	\$38,890 68
Southwestern Electric Pwr - Gen	WSX111023	W0028990	DPNO - Replace Underground Pip	31600 - Misc Pwr Plant Equip-Coal	Addition	201806	\$65,618 21
Southwestern Electric Pwr - Gen	WSX111023		DHPS Rpl Blr Fur Cout Tube	31200 - Boiler Plant Equip-Coal	Addition	201806	\$59 36
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL MISC HVAC UNITS	31200 - Boiler Plant Equip-Coal	Addition	201806	(\$3,163.56)
Southwestern Electric Pwr - Gen	WSX111023		GE MS PMT 1 PO	31200 - Boiler Plant Equip-Coal	Addition	201806	\$81,187 77
Southwestern Electric Pwr - Gen	WSX111023		Boilr Furnace Ctnt Tube-1/24/1	31200 - Boiler Plant Equip-Coal	Addition	201806	\$874,983 42
Southwestern Electric Pwr - Gen	WSX111023		DPNO - Upgrade stack lighting	31100 - Structures, Improvemnt-Coal	Addition	201806	(\$1,615 00)
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rpl Fuel Hndl Nclr Cht	31200 - Boiler Plant Equip-Coal	Addition	201806	(\$280 24)
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Replce FGD Piping	31200 - Boiler Plant Equip-Coal	Addition	201806	\$113,196 17
Southwestern Electric Pwr - Gen	WSX111023		DPNO - Ins Boiler Wtr Cl Alz	31200 - Boiler Plant Equip-Coal	Addition	201806	\$12,525 45
Southwestern Electric Pwr - Gen	WSX111023		TFA Boiler Tubing Design	31200 - Boiler Plant Equip-Coal	Addition	201806	\$4,001 34
Southwestern Electric Pwr - Gen	WSX111023		Plant Stores	31200 - Boiler Plant Equip-Coal	Addition	201806	\$19,122 10
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO-Rpl Cool Twr Fan Shrouds DPNO - INST PLNT SEC CMRS	31400 - Turbogenerator Units-Coal 31100 - Structures, Improvemnt-Coal	Addition	201806 201806	\$8,477 84
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - RPL MDBFP	31200 - Structures, Improvenint-Coal	Addition Addition	201806	(\$18 86) (\$8,342 40)
Southwestern Electric Pwr - Gen	WSX111023		DPNO-REFURB CT GEARBOXES	31100 - Structures, Improvemnt-Coal	Addition	201806	(\$19,831 24)
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO - MDFY PRHT COILS DRN SYS	31200 - Structures, Improvemme-coal	Addition	201806	(\$237.99)
Southwestern Electric Pwr - Gen	WSX111023		Construction Mgmt Fin-2-23-18	31200 - Boiler Plant Equip-Coal	Addition	201806	\$16,511 86
Southwestern Electric Pwr - Gen	WSX111023		DPNO-2017 Purchase Tools	31600 - Misc Pwr Plant Equip-Coal	Addition	201806	(\$1,111 77)
Southwestern Electric Pwr - Gen	WSX111023		DPNO - RPLC SIDING PLT BLDGS	31100 - Structures, Improvemnt-Coal	Addition	201806	(5138 26)
Southwestern Electric Pwr - Gen	WSX111023		Scaffolding & Insulation Cont	31200 - Boiler Plant Equip-Coal	Addition	201806	\$288,165 67
Southwestern Electric Pwr - Gen	WSX111023		DHPS Boiler Count Tubing Labor	31200 - Boiler Plant Equip-Coal	Addition	201806	\$563,214 37
Southwestern Electric Pwr - Gen	WSX111023	W0027666	DHPS 1 - RPL UNIT SILO DUST	31200 - Boiler Plant Equip-Coal	Addition	201806	\$526,482 04
Southwestern Electric Pwr - Gen	WSX111023	W0029446	DPNO - Ins Boiler Wtr Cl Alz	31200 - Boiler Plant Equip-Coal	Addition	201807	(\$338.56)
Southwestern Electric Pwr - Gen	WSX111023	W0030749	Project Management Fin-1-11-18	31200 - Boiler Plant Equip-Coal	Addition	201807	\$3,089 91
Southwestern Electric Pwr - Gen	WSX111023	W0030538	DHPS Rpl Bir Fur Cout Tube	31200 - Boiler Plant Equip-Coal	Addition	201807	(\$64.11)
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Repice FGD Piping	31200 - Boiler Plant Equip-Coal	Addition	201807	(\$2,638 91)
Southwestern Electric Pwr - Gen	W\$X111023		Plant Stores	31200 - Boiler Plant Equip-Coal	Addition	201807	\$42,822 02
Southwestern Electric Pwr - Gen	WSX111023		DPNO - Replace Underground Pip	31600 - Misc Pwr Plant Equip-Coal	Addition	201807	(\$1,430.53)
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Repice FGD PMP Bases	31200 - Boiler Plant Equip-Coal	Addition	201807	(\$1,084 21)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL UNIT SILO DUST	31200 - Boiler Plant Equip-Coal	Addition	201807	(\$12,507 37)
Southwestern Electric Pwr - Gen	WSX111023		DHPS Boiler Count Tubing Labor	31200 - Boiler Plant Equip-Coal	Addition	201807	\$45,565 82
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL LIG DIVERT GATE	31100 - Structures, Improvemnt-Coal	Addition	201807	(\$250.00)
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rpi Cool Twr Fan Shrouds	31400 - Turbogenerator Units-Coal	Addition	201807	(\$10,023.06)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - Rpi "B" MCVP	31200 - Boiler Plant Equip-Coal	Addition	201807	(\$55C OC)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL BRN NOZ TIPS-2016	31200 - Boiler Plant Equip-Coal	Addition	201807	(\$1,946 41)
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023		DPNO-REFURB CT GEARBOXES	31100 - Structures, Improvemnt-Coal	Addition Addition	201807	\$2,076 42
	WSX111023 WSX111023		Scaffolding & Insulation Cont	31200 - Boiler Plant Equip-Coal		201807	\$33,147 09
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		Construction Mgmt Fin-2-23-18 Boilr Furnace Ctnt Tube-1/24/1	31200 - Boiler Plant Equip-Coal 31200 - Boiler Plant Equip-Coal	Addition Addition	201807 201807	(\$239 16) (\$185 27)
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO - MDFY PRHT COILS DRN SYS	31200 - Boiler Plant Equip-Coal 31200 - Boiler Plant Equip-Coal	Addition	201807	\$170 23
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO-Rpl Cool Twr Fan Shrouds	31400 - Boller Plant Equip-Coal 31400 - Turbogenerator Units-Coal	Addition	201808	\$1,635 72
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		Plant Stores	31200 - Boiler Plant Equip-Coal	Addition	201808	\$983 01
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO-Inst Elevator Trsfr House	31200 - Boiler Plant Equip-Coal	Addition	201808	\$140,768 26
Southwestern Electric Pwr - Gen	WSX111023		DPNO - Ugrd Plt Lgt & Tmp Fd	31100 - Structures, Improvemnt-Coal	Addition	201808	\$53,724 59
Southwestern Electric Pwr - Gen	WSX111023		DPNO - RPLC FGD AREA GRATING	31500 - Stractures, Improvemint-coal	Addition	201808	\$42,908 49
Southwestern Electric Pwr - Gen	WSX111023		DHPS Rpi Bir Fur Cout Tube	31200 - Roller Plant Equip-Coal	Addition	201808	(\$0.89)
Southwestern Electric Pwr - Gen	WSX111023		Project Management Fin-1-11-18	31200 - Boiler Plant Equip-Coal	Addition	201808	\$99 36
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Repice Chmny Air BLower	31200 - Boiler Plant Equip-Coal	Addition	201808	\$22,279 17
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL LIG DIVERT GATE	31100 - Structures, Improvemnt-Coal	Addition	201808	(\$3.76)
Southwestern Electric Pwr - Gen	WSX111023		Construction Mgmt Fin-2-23-18	31200 - Boiler Plant Equip-Coal	Addition	201808	\$19 59
Southwestern Electric Pwr - Gen	WSX111023	W0029707	DPNO-Refurb Cathodic Prot Syst	31200 - Boiler Plant Equip-Coal	Addition	201808	\$11,843 26
Southwestern Electric Pwr - Gen	WSX111023	W0027445	DHPS 1 - Rpl "B" MCVP	31200 - Boiler Plant Equip-Coal	Addition	201808	(\$8.28)

					FFD6 4		Page 7 of
Company	Budget ID	Work Order	Work Order Descr	Utility Account	FERC Act Code	Month Number	Activity Cost
Southwestern Electric Pwr - Gen	WSX111023	W0030243	Scaffolding & Insulation Cont	31200 - Boiler Plant Equip-Coal	Addition	201808	\$1,047 64
Southwestern Electric Pwr - Gen	WSX111023	W0030753	DHPS Boiler Count Tubing Labor	31200 - Boiler Plant Equip-Coal	Addition	201808	\$2,060 25
Southwestern Electric Pwr - Gen	WSX111023		DPNO - RPLC FGD AREA GRATING	31500 - Accessory Elect Equip-Coal	Addition	201809	(\$1 332 21)
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Inst Elevator Trsfr House	31200 - Boiler Plant Equip-Coal	Addition	201809	(\$4,078 57)
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO - OVHL "C" CNDSTE PMP DPNO - RPL FGD EXP JNTS	31200 - Boiler Plant Equip-Coal 31200 - Boiler Plant Equip-Coal	Addition	201809	\$66,390 42 \$36,939 07
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - Rpl Boil Wtr SBR-2016	31200 - Boiler Plant Equip-Coal 31200 - Boiler Plant Equip-Coal	Addition Addition	201809 201809	\$200,148 42
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO-Rpl Cool Twr Fan Mtrs	31600 - Misc Pwr Plant Equip-Coal	Addition	201809	\$104,113 02
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Prch Inst Plt Sfty Upgrad	31100 - Structures, Improvemnt-Coal	Addition	201809	\$49,117 17
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Replce Chmny Air BLower	31200 - Boiler Plant Equip-Coal	Addition	201809	(\$674.10)
Southwestern Electric Pwr - Gen	WSX111023	W0030810	DPNO - INST FIRE MONITORS	31100 - Structures, Improvemnt-Coal	Addition	201809	\$896 98
Southwestern Electric Pwr - Gen	W\$X111023		DPNO-Replce Sm Roll Equip	31100 - Structures, Improvemnt-Coal	Addition	201809	\$32,844 47
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Refurb Cathodic Prot Syst	31200 - Boiler Plant Equip-Coal	Addition	201809	(\$291 03)
Southwestern Electric Pwr - Gen	WSX111023		DPNO - RPL LIG CONVYR BELTS	31600 - Misc Pwr Plant Equip-Coal	Addition	201809	\$15,253 10
Southwestern Electric Pwr - Gen	WSX111023		DPNO - Ugrd Plt Lgt & Tmp Fd	31100 - Structures, Improvemnt-Coal	Addition	201809	(\$1,362 45)
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO - RPL FGD CONVYR BELT	31600 - Misc Pwr Plant Equip-Coal	Addition	201809	\$11,782 60
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO - PRC/INS VFD WW PMP MTR DPNO-RPLCE 790 Trackhoe	31200 - Boiler Plant Equip-Coal 31200 - Boiler Plant Equip-Coal	Addition Addition	201809 201809	\$27,722 25 \$84,127 42
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO - RPL FUEL HNDL CHTE	31200 - Boiler Plant Equip-Coal	Addition	201809	\$54,490 25
Southwestern Electric Pwr - Gen	WSX111023		DPNO - RPL COOLING TWR FAN MTR	31400 - Turbogenerator Units-Coal	Addition	201809	\$105,865 40
Southwestern Electric Pwr - Gen	WSX111023		DPNO - REFB COOLING TWR GRBX	31100 - Structures, Improvemnt-Coal	Addition	201809	\$24,068 91
Southwestern Electric Pwr - Gen	WSX111023	W0030108	DPNO-RPLC MISC HVAC UNITS	31100 - Structures, Improvemnt-Coal	Addition	201809	\$26,203 67
Southwestern Electric Pwr - Gen	WSX111023	W0028717	DHPS 1 - RPL B FD FAN MTR	31200 - Boiler Plant Equip-Coal	Addition	201809	\$103,751 18
Southwestern Electric Pwr - Gen	WSX111023	W0029981	DHPS-1Rpl Conv Gear Reducer	31200 - Boiler Plant Equip-Coal	Addition	201809	\$81,521 07
Southwestern Electric Pwr - Gen	WSX111023		DPNO - RPL INS HIGH ENGY PIP	31200 - Boiler Plant Equip-Coal	Addition	201809	\$98,812 91
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Prch Inst Plt Sfty Upgrad	31100 - Structures, Improvemnt-Coal	Addition	201810	(\$1,608 65)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - Rpl Boil Wtr SBR-2016	31200 - Boiler Plant Equip-Coal	Addition	201810	(\$15,391.71)
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO - OVHL "C" CNDSTE PMP DPNO - RPL COOLING TWR FAN MTR	31200 - Boiler Plant Equip-Coal 31400 - Turbogenerator Units-Coal	Addition Addition	201810 201810	(\$1,994 43) (\$1,161 23)
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO-Install Fire Monitors	31100 - Structures, Improvemnt-Coal	Addition	201810	\$20,112 91
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Replice Sm Roll Equip	31100 - Structures, Improvemnt-Coal	Addition	201810	(\$976.03)
Southwestern Electric Pwr - Gen	WSX111023		DPNO - PRC/INS VFD WW PMP MTR	31200 - Boiler Plant Equip-Coal	Addition	201810	(\$294 32)
Southwestern Electric Pwr - Gen	WSX111023		DPNO - RPL FGD CONVYR BELT	31600 - Misc Pwr Plant Equip-Coal	Addition	201810	(\$104.54)
Southwestern Electric Pwr - Gen	WSX111023	W0028977	DPNO-Rpl Cool Twr Fan Mtrs	31600 - Misc Pwr Plant Equip-Coal	Addition	201810	(\$3,055.00)
Southwestern Electric Pwr - Gen	WSX111023	W0030663	DPNO - REFB COOLING TWR GRBX	31100 - Structures, Improvemnt-Coal	Addition	201810	(\$162 43)
Southwestern Electric Pwr - Gen	WSX111023	W0030807	DPNO - RPL PLVR DMPR DRV	31200 - Boiler Plant Equip-Coal	Addition	201810	\$43,626 51
Southwestern Electric Pwr - Gen	W5X111023		DHPS-1Rpl Conv Gear Reducer	31200 - Boiler Plant Equip-Coal	Addition	201810	(\$2,237.91)
Southwestern Electric Pwr - Gen	WSX111023		DPNO - RPLC MISC HVAC UNITS	31100 - Structures, Improvemnt-Coal	Addition	201810	\$2,687 15
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		Coal Combustion Residuals Stdy	31200 - Boiler Plant Equip-Coal	Addition	201810	(\$76.46)
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO - RPL FGD EXP JNTS DPNO-RPL SH/RH DMP DRV	31200 - Boiler Plant Equip-Coal 31200 - Boiler Plant Equip-Coal	Addition Addition	201810 201810	(\$250 30) \$51,733 73
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO-RPLC MISC HVAC UNITS	31100 - Structures, Improvemnt-Coal	Addition	201810	(\$769 62)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL B FD FAN MTR	31200 - Boiler Plant Equip-Coal	Addition	201810	(\$1,114 97)
Southwestern Electric Pwr - Gen	WSX111023		DPNO-RPLCE 790 Trackhoe	31200 - Boiler Plant Equip-Coal	Addition	201810	(\$1,224 72)
Southwestern Electric Pwr - Gen	WSX111023	W0030672	DPNO - Rpl Boil Wtr SBR	31200 - Boiler Plant Equip-Coal	Addition	201810	\$232,241 15
Southwestern Electric Pwr - Gen	WSX111023	W0030803	DPNO - RPL LIG CONVYR BELTS	31600 - Misc Pwr Plant Equip-Coal	Addition	201810	(\$128 84)
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Inst Orifices in Reheater	31200 - Boiler Plant Equip-Coal	Addition	201810	\$129,648 29
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL FGD CON FRWK-2016	31200 - Boiler Plant Equip-Coal	Addition	201811	(\$467.65)
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - RPL BRN NOZ TIPS-2016	31200 - Boiler Plant Equip-Coal	Addition	201811	(\$40 677 37)
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS Rpl Bir Fur Cout Tube DPNO - PURC COMPUTERS-2017	31200 - Boiler Plant Equip-Coal	Addition Addition	201811	(\$3.43) \$124.22
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO-PORC COMPOTERS-2017 DPNO-Install Fire Monitors	39111 - Office Equip - Computers 31100 - Structures, Improvemnt-Coal	Addition	201811 201811	\$134 23 (\$446 73)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL ASH SLUICE PUMP	31200 - Boiler Plant Equip-Coal	Addition	201811	(\$1,000 00)
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Inst Orifices in Reheater	31200 - Boiler Plant Equip-Coal	Addition	201811	(\$147,032.03)
Southwestern Electric Pwr - Gen	W\$X111023	W0030749	Project Management Fin-1-11-18	31200 - Boiler Plant Equip-Coal	Addition	201811	\$12,416 98
Southwestern Electric Pwr - Gen	WSX111023	W0030999	DPNO - RPLC MISC HVAC UNITS	31100 - Structures, Improvemnt-Coal	Addition	201811	(\$25.23)
Southwestern Electric Pwr - Gen	WSX111023	W0030807	DPNO - RPL PLVR DMPR DRV	31200 - Boiler Plant Equip-Coal	Addition	201811	\$7,974 58
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RFB COOL TOW GEARBXS	31400 - Turbogenerator Units-Coal	Addition	201811	(\$9 000 00)
Southwestern Electric Pwr - Gen	WSX111023		DPNO-RPL SH/RH DMP DRV	31200 - Boiler Plant Equip-Coal	Addition	201811	(\$644.53)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL BOX CULVERTS	31100 - Structures, Improvemnt-Coal	Addition	201811	(\$500 00)
Southwestern Electric Pwr - Gen	WSX111023		DHPS Boiler Count Tubing Labor	31200 - Boiler Plant Equip-Coal	Addition	201811	\$14,337 97
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO - RPL INS HIGH ENGY PIP DHPS 1 - RPL FGD PMP CAS IMPLS	31200 - Boiler Plant Equip-Coal	Addition	201811	\$32,153 88
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - INSTL AMB AIR SO2 MON	31200 - Boiler Plant Equip-Coal 31200 - Boiler Plant Equip-Coal	Addition Addition	201811 201811	(\$63 43) \$492 44
Southwestern Electric Pwr - Gen	WSX111023		TFA Boiler Tubing Design	31200 - Boiler Plant Equip-Coal	Addition	201811	\$107 19
Southwestern Electric Pwr - Gen	WSX111023		Plant Stores	31200 - Boiler Plant Equip-Coal	Addition	201811	\$32,243 90
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - UPG FGD AREA LIGHT	31100 - Structures, Improvemnt-Coal	Addition	201811	(\$3,867.50)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1- RPL STACK ELEV BLTS	31100 - Structures, Improvemnt-Coal	Addition	201811	(\$1,665.47)
Southwestern Electric Pwr - Gen	WSX111023	W0026853	DHPS 1 - RPL UNDGRD PIP	31200 - Boiler Plant Equip-Coal	Addition	201811	\$1,606 01
Southwestern Electric Pwr - Gen	WSX111023	W0027374	DHPS 1 - Purchase Tools 2016	31600 - Misc Pwr Plant Equip-Coal	Addition	201811	(\$1,541 32)
Southwestern Electric Pwr - Gen	WSX111023	W0030572	DPNO - RPL FUEL HNDL CHTE	31200 - Boiler Plant Equip-Coal	Addition	201811	\$32 72
Southwestern Electric Pwr - Gen	WSX111023		DHPS1 Line work for Dolet	31600 - Misc Pwr Plant Equip-Coal	Addition	201811	(\$1,643 14)
Southwestern Electric Pwr - Gen	WSX111023		Scaffolding & Insulation Cont	31200 - Boiler Plant Equip-Coal	Addition	201811	\$19,382 20
Southwestern Electric Pwr - Gen	WSX111023		DPNO - Rpl Boil Wtr SBR	31200 - Boiler Plant Equip-Coal	Addition	201811	\$46,478 43
Southwestern Electric Pwr - Gen	WSX111023		Coal Combustion Residuals Stdy	31200 - Boiler Plant Equip-Coal	Addition	201812	(\$0.48)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1- RPL STACK ELEV BLTS	31100 - Structures, Improvemnt-Coal	Addition	201812	(\$61.37)
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - Purchase Tools 2016 DHPS 1 - RFB COOL TOW GEARBXS	31600 - Misc Pwr Plant Equip-Coal 31400 - Turbogenerator Units-Coal	Addition Addition	201812 201812	(\$56 80) (\$331 64)
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - RPL ASH SLUICE PUMP	31200 - Boiler Plant Equip-Coal	Addition	201812	(\$351.64) (\$36.85)
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - RPL BRN NOZ TIPS-2016	31200 - Boiler Plant Equip-Coal	Addition	201812	(\$1,498 91)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL B FD FAN MTR	31200 - Boiler Plant Equip-Coal	Addition	201812	\$871 03
Southwestern Electric Pwr - Gen	WSX111023		DHPS Rpl Bir Fur Cout Tube	31200 - Boiler Plant Equip-Coal	Addition	201812	(\$0.13)
			,	- march			(*/

					FERC Act		
Company	Budget !D	Work Order	Work Order Descr	Utility Account	Code	Month Number	Activity Cost
Southwestern Electric Pwr - Gen	WSX111023	W0027159	DHPS 1 - RPL FGD PMP CAS IMPLS	31200 - Boiler Plant Equip-Coal	Addition	201812	(\$2 34)
Southwestern Electric Pwr - Gen	WSX111023	W0028000	DHPS 1 - UPG FGD AREA LIGHT	31100 - Structures, Improvemnt-Coal	Addition	201812	(\$142.51)
Southwestern Electric Pwr - Gen	WSX111023	W0026853	DHPS 1 - RPL UNDGRD PIP	31200 - Boiler Plant Equip-Coal	Addition	201812	\$60 37
Southwestern Electric Pwr - Gen	WSX111023	W0027849	DHPS 1 - RPL BOX CULVERTS	31100 - Structures, Improvemnt-Coal	Addition	201812	(\$18.42)
Southwestern Electric Pwr - Gen	WSX111023	W0027769	DHPS 1 - RPL FGD CON FRWK-2016	31200 - Boiler Plant Equip-Coal	Addition	201812	(\$17.23)
Southwestern Electric Pwr - Gen	WSX111023	W0030749	Project Management Fin-1-11-18	31200 - Boiler Plant Equip-Coal	Addition	201901	\$1,590 05
Southwestern Electric Pwr - Gen	WSX111023		DPNO - PURC COMPUTERS-2017	39111 - Office Equip - Computers	Addition	201901	\$1,055 07
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL UNDGRD PIP	31200 - Boiler Plant Equip-Coal	Addition	201901	\$326 06
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL UNDGRD PIP	31200 - Boiler Plant Equip-Coal	Addition	201902	\$74 81
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - UPG SLUD DST SYS	31200 - Boiler Plant Equip-Coal	Addition	201902	(\$952 66)
Southwestern Electric Pwr - Gen	WSX111023		Dolet Hills Power Station	31200 - Boiler Plant Equip-Coal	Addition	201902	\$624 16
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - RPL B FD FAN MTR DPNO - RPL FUEL HNDL CHTE	31200 - Boiler Plant Equip-Coal 31200 - Boiler Plant Equip-Coal	Addition	201903	(\$163.97)
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		Scaffolding & Insulation Cont	31200 - Boiler Plant Equip-Coal	Addition Addition	201903 201903	(\$6 15) (\$3,648 59)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL FGD PMP CAS IMPLS	31200 - Boiler Plant Equip-Coal	Addition	201903	\$12 39
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RFB COOL TOW GEARBXS	31400 - Turbogenerator Units-Coal	Addition	201903	\$1,757 88
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Inst Orifices in Reheater	31200 - Boiler Plant Equip-Coal	Addition	201903	\$27,697 68
Southwestern Electric Pwr - Gen	WSX111023		DHPS1 Line work for Dolet	31600 - Misc Pwr Plant Equip-Coal	Addition	201903	\$309 53
Southwestern Electric Pwr - Gen	WSX111023	W0030809	DPNO - RPL INS HIGH ENGY PIP	31200 - Boiler Plant Equip-Coal	Addition	201903	(\$6,052.76)
Southwestern Electric Pwr - Gen	WSX111023	W0026853	DHPS 1 - RPL UNDGRD PIP	31200 - Boiler Plant Equip-Coal	Addition	201903	(\$377 36)
Southwestern Electric Pwr - Gen	WSX111023	W0027845	DHPS 1 - RPL ASH SLUICE PUMP	31200 - Boiler Plant Equip-Coal	Addition	201903	\$195 32
Southwestern Electric Pwr - Gen	WSX111023	W0030807	DPNO - RPL PLVR DMPR DRV	31200 - Boiler Plant Equip-Coal	Addition	201903	(\$1,501 16)
Southwestern Electric Pwr - Gen	WSX111023	W0030242	TFA Boiler Tubing Design	31200 - Boiler Plant Equip-Coal	Addition	201903	(\$20.18)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL BOX CULVERTS	31100 - Structures, Improvemnt-Coal	Addition	201903	\$97 66
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL BRN NOZ TIPS-2016	31200 - Boiler Plant Equip-Coal	Addition	201903	\$7,945 10
Southwestern Electric Pwr - Gen	WSX111023		DHPS Rpl Blr Fur Cout Tube	31200 - Boiler Plant Equip-Coal	Addition	201903	\$0 67
Southwestern Electric Pwr - Gen	WSX111023		DPNO - PURC COMPUTERS-2017	39111 - Office Equip - Computers	Addition	201903	(\$192.89)
Southwestern Electric Pwr - Gen	WSX111023		Project Management Fin-1-11-18	31200 - Boiler Plant Equip-Coal	Addition	201903	(\$2,590 01)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1- RPL STACK ELEV BLTS	31100 - Structures, Improvemnt-Coal	Addition	201903	\$325 30
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - UPG FGD AREA LIGHT DHPS 1 - Purchase Tools 2016	31100 - Structures, Improvemnt-Coal 31600 - Misc Pwr Plant Equip-Coal	Addition	201903	\$755 40
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1 - INSTL AMB AIR SO2 MON	31200 - Misc Pwr Plant Equip-Coal	Addition Addition	20 1903 20 19 03	\$301 05 (\$92 70)
Southwestern Electric Pwr - Gen	W\$X111023		Coal Combustion Residuals Stdy	31200 - Boiler Plant Equip-Coal	Addition	201903	\$0.09
Southwestern Electric Pwr - Gen	W5X111023		DHPS Boiler Count Tubing Labor	31200 - Boiler Plant Equip-Coal	Addition	201903	(\$2,699 04)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL FGD CON FRWK-2016	31200 - Boiler Plant Equip-Coal	Addition	201903	\$91 34
Southwestern Electric Pwr - Gen	WSX111023	W0030672	DPNO - Rpl Boil Wtr SBR	31200 - Boiler Plant Equip-Coal	Addition	201903	(\$8,749 27)
Southwestern Electric Pwr - Gen	WSX111023		Plant Stores	31200 - Boiler Plant Equip-Coal	Addition	201903	(\$6,069 72)
Southwestern Electric Pwr - Gen	WSX111023		DPNO - INST PLV SWG VALVES	31200 - Boiler Plant Equip-Coal	Addition	201904	\$142,789 52
Southwestern Electric Pwr - Gen	WSX111023	W0028575	DHPS 1 - UPG SLUD DST SYS	31200 - Boiler Plant Equip-Coal	Addition	201904	\$143 56
Southwestern Electric Pwr - Gen	WSX111023	W0031450	DHPS1-COMPUTERPURCHASE	39100 - Office Furniture, Equipment	Addition	201904	(\$369 44)
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rplc LVBush MPT	31500 - Accessory Elect Equip-Coal	Addition	201904	\$110,377 23
Southwestern Electric Pwr - Gen	WSX111023		Plant Stores	31200 - Boiler Plant Equip-Coal	Addition	201904	\$12,639 52
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Reline FGD Concrete Tank	31200 - Boiler Plant Equip-Coal	Addition	201904	\$153,194 31
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - UPG FUEL HAND FIRE PR	31200 - Boiler Plant Equip-Coal	Addition	201904	(\$2,696.25)
Southwestern Electric Pwr - Gen	WSX111023		DHPS 1 - RPL FUEL HND NUC CHUT	31200 - Boiler Plant Equip-Coal	Addition	201904	(\$687.34)
Southwestern Electric Pwr - Gen	WSX111023		Dolet Hills Power Station	31200 - Boiler Plant Equip-Coal	Addition	201904	(\$94.04)
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS1-COMPUTERPURCHASE DHPS 1 - UP CLG TOW MTR - 2016	39111 - Office Equip - Computers	Addition	201904 201904	\$1,577 13 (\$3,790 95)
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO-Rpl Cool Twr Fan Shrouds	31200 - Boiler Plant Equip-Coal 31100 - Structures, Improvemnt-Coal	Addition Addition	201904	\$23,892 17
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO - Ugrd Plt Lgt & Tmp Fd	31100 - Structures, Improvemnt-Coal	Addition	201904	\$24,203 14
Southwestern Electric Pwr - Gen	WSX111023		DPNO - Rpl Boiler Exp Joints	31200 - Boiler Plant Equip-Coal	Addition	201904	\$75,598 36
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rpl Cool Twr Fan Shrouds	31400 - Turbogenerator Units-Coal	Addition	201905	\$7,814 63
Southwestern Electric Pwr - Gen	WSX111023		DPNO Sales Tax Refund	39100 - Office Furniture, Equipment	Addition	201905	(\$257,456 17)
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rpl Water Plt Controls	31500 - Accessory Elect Equip-Coal	Addition	201905	(\$45.41)
Southwestern Electric Pwr - Gen	WSX111023	W0030675	DPNO - Ugrd Plt Lgt & Tmp Fd	31100 - Structures, Improvemnt-Coal	Addition	201905	(\$829.48)
Southwestern Electric Pwr - Gen	WSX111023	W0030814	DPNO - Rpl Boiler Exp Joints	31200 - Boiler Plant Equip-Coal	Addition	201905	(\$3,299 41)
Southwestern Electric Pwr - Gen	WSX111023	W0031417	DHPS1-COMPUTERPURCHASE	39111 - Office Equip - Computers	Addition	201905	(\$43.31)
Southwestern Electric Pwr - Gen	WSX111023	W0028574	DHPS 1 - UPG FUEL HAND FIRE PR	31200 - Boiler Plant Equip-Coal	Addition	201905	\$140 91
Southwestern Electric Pwr - Gen	WSX111023	W0030671	DPNO-Rpl Cool Twr Fan Shrouds	31100 - Structures, Improvemnt-Coal	Addition	201905	(\$1,025 45)
Southwestern Electric Pwr - Gen	WSX111023	W0030669	Plant Stores	31200 - Boiler Plant Equip-Coal	Addition	201905	(\$389 14)
Southwestern Electric Pwr - Gen	WSX111023		DPNO - INST PLV SWG VALVES	31200 - Boiler Plant Equip-Coal	Addition	201905	(\$6,476 68)
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rpl 4160V Switchgear - 2017	31200 - Boiler Plant Equip-Coal	Addition	201908	\$24,500 00
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rpl Cool Twr Fan Shrouds	31400 - Turbogenerator Units-Coal	Addition	201908	\$26,439 70
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rpl 4160V Switchgear - 2017	31200 - Boiler Plant Equip-Coal	Addition	201909	(\$4,785.34)
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rpl Cool Twr Fan Shrouds	31400 - Turbogenerator Units-Coal	Addition	201910	\$5,349 49
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rpi 4160V Switchgear - 2017	31200 - Boiler Plant Equip-Coal	Addition	201910	(\$19,714 66)
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO - Pur Golf Cart for PDM use	31600 - Misc Pwr Plant Equip-Coal	Addition	201910	\$1,701 72
Southwestern Electric Pwr - Gen Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS 1-Replace Conveyor Gear DPNO-Pur/Ins SF1 Feeder	31200 - Boiler Plant Equip-Coal 31200 - Boiler Plant Equip-Coal	Addition Addition	201910 201910	\$2,424 18 \$737,103 12
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DHPS1-COMPUTERPURCHASE	39111 - Office Equip - Computers	Addition	201910	\$22 19
Southwestern Electric Pwr - Gen	WSX111023 WSX111023		DPNO-Pur/ins SF1 Feeder	31200 - Boiler Plant Equip-Coal	Addition	201911	(\$15,206.88)
Southwestern Electric Pwr - Gen	WSX111023		DPNO-Rpl Cool Twr Fan Shrouds	31400 - Turbogenerator Units-Coal	Addition	201912	\$93 40
				• • • • • • • • •			

\$16,933,947 83