

STAFF 1-95 Please provide a list of any hurricane response staging area you established in the lead up to and in the aftermath of Hurricane Beryl. Please include the date the center(s) was established, the location of the center(s), the day-to-day staffing levels at the center, and types of equipment and personnel staged at the center(s).

RESPONSE:

Hurricane Beryl was not projected to have an effect on BEC’s system. Therefore, no hurricane response staging areas were established.

SPONSOR: Daniel Sanders

STAFF 1-96 How did the rollout and deployment of mutual assistance during the events of Hurricane Beryl compare to previous hurricane events during which you requested assistance from mutual assistance programs? In your response, please specifically compare the types and quantities of resources requested, the percentage of request aid provided, the efficacy of coordination between your company and the mutual assistance provider, and the efficiency of staging, deployment, and release of those assistance resources.

RESPONSE:

Bartlett Electric Cooperative did not request mutual assistance to respond to Hurricane Beryl.

SPONSOR: Daniel Sanders

STAFF 1-97 Please describe what specific actions you took to begin staging internal staff and any responsive mutual assistance crews or resources.

RESPONSE:

Bartlett Electric Cooperative did not request mutual assistance to respond to Hurricane Beryl.

SPONSOR: Daniel Sanders

STAFF 1-98 Did you have to train or on-board any personnel that was provided in response to your request(s) for mutual assistance during the events of Hurricane Beryl? If yes, please describe what kind of training or on-boarding you provided.

RESPONSE:

Bartlett Electric Cooperative did not request mutual assistance to respond to Hurricane Beryl.

SPONSOR: Daniel Sanders

Mobile Generation

STAFF 1-99 Please provide details regarding the lease or procurement of each mobile generation facility in the Transmission and Distribution Utility’s (TDU) control, including:

- a. Details regarding the competitive bidding process used or the justification for not using a competitive bidding process;
- b. The size of each mobile generation facility in megawatts (MW);
- c. The initial lease or procurement date of each facility;
- d. The lease term, in months, of each mobile generation facility;
- e. The expiration date of each facility’s lease;
- f. The to-date costs associated with each mobile generation facility, including operating, leasing costs, or other capital expense;
- g. The expected costs associated with each lease, including operation and leasing costs; and
- h. The expected return on investment associated with each lease or procurement.

RESPONSE:

BEC has not procured any mobile generation facilities.

SPONSOR: Daniel Sanders

STAFF 1-100 Please provide details regarding mobile generation or temporary emergency electric energy facilities (TEEEF):

- a. The control number of the TDU’s most recently approved mobile generation or TEEEF cost recovery;
- b. Details regarding whether the mobile generation or TEEEF cost recovery was processed as part of a larger Distribution Cost Recovery Factor proceeding or in a separate contested case;
- c. The revenue requirement associated with the TDU’s mobile generation or TEEEF expenses, broken out by rate class; and
- d. The in-force tariffs associated with the TDU’s mobile generation or TEEEF rider, broken out by rate class.

RESPONSE:

BEC has not procured any mobile generation facilities.

BEC did not procure temporary emergency electric energy facilities.

SPONSOR: Daniel Sanders

STAFF 1-101 Provide the following information concerning your customer base:

- a. Total number of customers served by rate class;
- b. Average demand by rate class;
- c. Peak demand by rate class; and
- d. Net peak demand by rate class.

RESPONSE:

- a) 101-10841, 105-683, 402-3409, 403-240, 403C-2, 404-41, 406-2, 602-1, 701-1, 702-45, 703-24, 704-2
- b) 101- AVG-26KW PEAK-47KW
- c) 105-AVG-1.4KW PEAK-2.4KW
402-AVG-2.5KW PEAK-3.8KW
403-AVG-4.3KW PEAK-6.0KW
404-AVG-.66KW PEAK-1.7KW
(406,602,701,702,703,704,403C) all less than 1KW peak
- d) 105 NET AVG .51KW NET PEAK-2.39KW

SPONSOR: Daniel Sanders

STAFF 1-102 Please provide information on the average customer density by circuit mile for the feeders in the Impacted Area.

RESPONSE:

8.5 meters per circuit mile

SPONSOR: Daniel Sanders

STAFF 1-103 Please provide an explanation of any alternatives to mobile generation facilities considered by the TDU before entering a lease for or procuring mobile generation facilities.

RESPONSE:

BEC has not procured any mobile generation facilities.

SPONSOR: Daniel Sanders

STAFF 1-104 Please describe the specific use cases contemplated by the TDU before executing a contract for the lease or procurement of mobile generation facilities.

RESPONSE:

BEC has not procured any mobile generation facilities.

SPONSOR: Daniel Sanders

STAFF 1-105 Please provide the following information concerning mobile generation facilities in your possession:

- a. The total capacity, in MWs, of mobile generation facilities leased or procured before July 8, 2024;
- b. The rationale for leasing or procuring that capacity; and
- c. And how mobility and capacity were prioritized when leasing or procuring mobile generation facilities.

RESPONSE:

BEC has not procured any mobile generation facilities.

SPONSOR: Daniel Sanders

STAFF 1-106 Provide the following information for mobile generation facilities already under lease or procured before July 8, 2024:

- a. The size, in MWs, of each deployed mobile generation facility;
- b. The length of time needed to move each deployed mobile generation facility from storage to its designated staging area;
- c. the length of time needed to move each mobile generation facility from staging to its deployment location;
- d. An explanation for how and where the mobile generation facility was used; and
- e. If a mobile generation facility was not used, an explanation as to why.

RESPONSE:

BEC has not procured any mobile generation facilities.

SPONSOR: Daniel Sanders

STAFF 1-107 Please describe all situations in which the TDU’s leased or procured mobile generation facilities were deployed before Hurricane Beryl. If applicable, please describe how those previous deployment situations differed from the use cases initially contemplated by the TDU.

RESPONSE:

BEC has not procured any mobile generation facilities.

SPONSOR: Daniel Sanders

STAFF 1-108 Please provide the following information on power restoration plans or procedures regarding critical infrastructure facilities.

- a. Did the TDU develop a list of critical infrastructure facilities within the TDU’s service territory?
- b. Did the TDU develop emergency preparedness plans in collaboration with critical infrastructure facilities in its service territory?
- c. Did the TDU develop a list of routes for use in reaching critical infrastructure facilities during an emergency or significant power outage?
- d. Did the TDU identify the specific steps it would take to energize critical infrastructure facilities in its service territory with mobile generation facilities?
- e. Did the TDU pre-position mobile generation facilities at critical infrastructure facilities in its service territory to respond to significant power outages in a timely manner?

RESPONSE:

- a) Yes
- b) Yes
- c) Yes
- d) BEC does not utilize mobile generation facilities.
- e) BEC does not utilize mobile generation facilities.

SPONSOR: Daniel Sanders

STAFF 1-109 Please provide the following information regarding drills, procedures, and plans to use mobile generation facilities.

- a. Did the TDU develop operating plans or procedures for the deployment of mobile generation? If so, please describe the TDUs strategy for deploying its mobile generation.
- b. Did the TDU assign specific personnel to manage, either directly or indirectly, the operation and deployment of its mobile generation facilities?
- c. Did the TDU conduct personnel trainings or preparedness drills for the operation of its mobile generation facilities?
- d. Please describe any plans or procedures developed in coordination with other TDUs or mutual assistance groups for the operation or deployment of mobile generation.

RESPONSE:

BEC does not utilize mobile generation facilities.

SPONSOR: Daniel Sanders

STAFF 1-110 Please provide the following information regarding each mobile generation facility borrowed during Hurricane Beryl as part of a mutual assistance program or agreement.

- a. How the original request for mobile generation facilities through mutual assistance was made;
- b. The size, in MW, of each borrowed mobile generation facility;
- c. The date the mutual assistance program or agreement was entered;
- d. The date the borrowed mobile generation facility was deployed;
- e. The duration, in hours, of the borrowing agreement. Describe whether this duration was for a fixed number of hours or a specific number of operating hours;
- f. The identity of the original owner or lessor of the mobile generation facility subject to the mutual assistance program or agreement; and
- g. Whether obtained mobile generation facilities were used during, or in power restoration efforts following, Hurricane Beryl.
 - i. If the mobile generation facility was not deployed, provide an explanation as to why the mobile generation facility was not deployed; and
 - ii. If the mobile generation facility was deployed, provide an explanation of how it was used.

RESPONSE:

BEC did not borrow generation facilities during Hurricane Beryl.

SPONSOR: Daniel Sanders

STAFF 1-111 When mobile generation facilities are offered to other TDUs during significant power outages, what information does the loaning TDU require from the borrowing TDU related to the probable operation of the mobile generation?

RESPONSE:

BEC does not utilize mobile generation facilities.

SPONSOR: Daniel Sanders

STAFF 1-112 Please describe if any mobile generation facilities in the TDU’s control were deployed in the service territories of municipally owned utilities or electric cooperatives during Hurricane Beryl.

RESPONSE:

BEC did not control or deploy any mobile generation facilities during Hurricane Beryl.

SPONSOR: Daniel Sanders

STAFF 1-113 Please describe how the determination was made regarding when and where to deploy or redeploy each mobile generation facility during, or in response to, Hurricane Beryl.

RESPONSE:

BEC did not control or deploy any mobile generation facilities during Hurricane Beryl.

SPONSOR: Daniel Sanders

STAFF 1-114 Please describe the number of distribution customers that had power restored by each mobile generation facility leased or procured by the TDU during, or in response to, Hurricane Beryl.

RESPONSE:

BEC did not deploy any mobile generation facilities during or in response to Hurricane Beryl.

SPONSOR: Daniel Sanders

STAFF 1-115 Please describe the number of distribution customers that had power restored by each mobile generation facility obtained through mutual assistance during, or in response to, Hurricane Beryl.

RESPONSE:

BEC did not deploy any mobile generation facilities during or in response to Hurricane Beryl.

SPONSOR: Daniel Sanders

STAFF 1-116 Please describe the number of transmission customers that had power restored by a mobile generation facility leased or procured by the TDU during, or in response to, Hurricane Beryl.

RESPONSE:

BEC did not deploy any mobile generation facilities during or in response to Hurricane Beryl.

SPONSOR: Daniel Sanders

STAFF 1-117 Please describe the number of transmission customers that had power restored by a mobile generation facility obtained through mutual assistance during, or in response to, Hurricane Beryl.

RESPONSE:

BEC did not deploy any mobile generation facilities during or in response to Hurricane Beryl.

SPONSOR: Daniel Sanders

STAFF 1-118 If applicable, please note if any fueling problems arose with deployed mobile generation facilities during, or in response to, Hurricane Beryl. If so, please describe the fueling problems in detail and any action that the TDU took in response.

RESPONSE:

Not applicable.

SPONSOR: Daniel Sanders

STAFF 1-119 Please describe all costs incurred by the TDU that were associated with the deployment of mobile generation facilities during, or in response to, Hurricane Beryl.

RESPONSE:

BEC did not deploy any mobile generation facilities during or in response to Hurricane Beryl.

SPONSOR: Daniel Sanders

STAFF 1-120 Please describe any obstacles that limited the deployment of mobile generation facilities during, or in response to, Hurricane Beryl.

RESPONSE:

Not applicable.

SPONSOR: Daniel Sanders

STAFF 1-121 Please describe any procedural improvements that the TDU intends to make prior to the next deployment of mobile generation facilities. If available, please reference specific sections of any after action report or lessons learned document the TDU has created.

RESPONSE:

BEC does not intend to deploy mobile generation facilities in the future.

SPONSOR: Daniel Sanders

Attachment 1



EMERGENCY DECLARATION AND TRACKING

EDDM

Date / Time

February 1, 2023/ 0700

(Initial Declaration)

Declared By

Daniel Sanders

(Name and Position)

Chief Operations Officer

Type of Emergency

Winter weather event with significant icing.

(Describe)

Declared Emergency Level (Check one)

(P) Pre-Emergency Preparation

- BEC conducts normal business while individuals responsible for emergency preparation tasks initiate these preparatory tasks.
- Typically lasts up to 24 hours and may escalate if forecasts or actual events unfold or if corrective measures are not timely and effective.
- An Incident Commander may be designated depending on the potential impact of the storm or forecasted event.

(E-1) Significant Event(s)

- The emergency event is significant in a limited area. The loss or curtailment of service affects a limited area of the system and should be corrected within 24 hours.
- An Incident Commander may be designated. If designated, the Incident Commander will typically be the Director of Engineering and Operations or a District Operations Supervisor. The Incident Commander shall determine if other ICS roles are required.

(E-2) Major Event

- A segment of the organization has experienced a power interruption or other significant business disruption in excess of 24 hours, or where the need for power restoration requires the suspension of normal field work.
- Major events are severe but not yet catastrophic. This type of emergency needs to be monitored closely to determine if, in fact, it will escalate to a catastrophic condition.
- An Incident Commander shall be designated. This will typically be the Director of Engineering and Operations. The Incident Commander shall identify the BEC management and/or staff personnel to fill the ICS roles.

(E-3) Catastrophic Event

- A Catastrophic Event can occur when a significant portion of the electric system is lost due to a natural or man-made disaster; or the computer center is lost due to system failure for an extended period.



EMERGENCY DECLARATION AND TRACKING

EOPM

Signature Daniel Sanders

**Person Responsible for
Emergency Declaration**
(CEO or CEO Designee)

Incident Commander February 1, 2023
(Include Date and Time
of Designation) 0700

Notes Operations should complete restoration efforts by the end of shift tomorrow. Tailboards are at 0630, work is assigned, and material is loaded. Operational leadership conducts telephone conference at 1600 for status updates. All stop occurs at 10:30pm. No accidents or incidents to report at this time.

Date	Time	Event Log / Notes of Significant Response Events
2/1/2023	0700	1,169 meters out of power at time of EOP declaration.



EMERGENCY DECLARATION AND TRACKING

EDDM

- 2/1/2023** 1830 The accumulation on conductors and trees has made it very difficult to restore power permanently across our system. 3,833 meters are affected at this time. BEC, S&H, & Brazos Electric crews will work 16 hour shifts during daylight hours until power has been restored to all meters. Material stocks are adequate for restoration efforts, fleet vehicles are in good operating condition, and there are no safety issues to report.
- 2/2/2023** 1900 Social media updates informing members to be prepared to be without power through Saturday, February 4th have been released. Conditions are improving. Evaluation is near completion.
- Schwertner-01 4 broke poles left to replace ETR -noon Feb. 3rd
- Bartlett-01 8 broke poles, 15 cross arms, 20 spans on the ground ETR- Saturday, Feb. 4th evening
- Other circuits are affected by failed conductor. The majority of these locations will be restored by the end of the day Feb. 3rd.
- Tree trimming crews continue to clear trees around Salty and Talbertridge.
- Bulldozers will continue to be utilized to place equipment in a position to complete work off the road.
- Assistance has been requested from other cooperatives and partnering contractors. More mutual aid may become available tomorrow. Comanche EC will send 6 crews and 4 trucks to assist with restoration efforts tomorrow.
- 2/3/2023** 2300 2,418 meters without power at the time of this report. Estimation for restoration to all members on the following circuits by Saturday night, February 4th:
- Bartlett- 1201, 1203
- Buckholts 1204
- Schwertner 2402, 2401,2404
- Salty 1203
- Restoration efforts to continue on Talbert 1204, 1202, 1201 Sunday, February 5th.
- This timeline could change if additional resources become available.
- We currently have all BEC operations personnel working in addition to 6 contract crews from two different contract companies, and mutual aide response from Comanche EC & Brazos electric.
- Scope of work involves cutting trees, pole replacement and splicing/replacing downed conductor. We are utilizing bulldozers, tractors and are climbing poles to complete the work in a safe and effective manner.



EMERGENCY DECLARATION AND TRACKING

EDDM

2/4/2023	2230	1,835 meters without power at the time of this report. We have 265 individual outages. 210 of those events affect 10 or fewer meters. Scope of work has not changed. The work is time consuming. No accidents or incidents to report at this time.
2/5/2023	2230	1,018 meters without power. The largest outage is behind the Thorndale metering point. It affects 47 members. Poles were set there today. Wire will be strung there first thing in the morning. Brazos EC and contractors continue to assist with restoration efforts. Total restoration timeline could be affected by high winds tomorrow and thunderstorms on Tuesday. There are 239 individual events, 200 of those affect 10 meters or fewer.
2/6/2023	2200	559 meters without power. There are 125 individual events. Weather will impact outage count and restoration time tomorrow. Many trees compromised during the ice accumulation last week will fall creating additional outages. Mutual aid and contract crews are still on our system and are committed to working along with BEC until restoration is complete.
2/7/2023	2200	97 Meters without power. There are 39 individual events. Tree trimming crews and bulldozers have been scheduled for tomorrow morning.
Date	Time	Event Log / Notes of Significant Response Events
2/8/2023	2200	Power restored to all meters.



EMERGENCY DECLARATION AND TRACKING

EDDM

Attachment 2

Daniel Sanders

From: asctxwx-request@utlists.utexas.edu on behalf of Troy Kimmel
<asctxwx@utlists.utexas.edu>
Sent: Wednesday, July 3, 2024 6:20 PM
Subject: [asctx-weather] ALL / Weather Update 1 - Increasing our Weather Awareness as We Continue to Closely Monitor Tropical Cyclone Beryl

Bartlett Electric Cooperative Inc.

Warning: The sender asctxwx@utlists.utexas.edu might be a spam sender.

[Block as Spam Not a Spam Sender](#)

powered by Graphus®

**ALL / Austin, Travis County and South Central Texas Weather Update 1
Prepared by UT University/Incident Response Meteorologist Troy Kimmel
620pm CT - Wednesday / 03 July 2024**

**... Increasing our Weather Awareness as We Continue to Closely Monitor
Tropical Cyclone Beryl...**

As we approach our Fourth of July holiday, I wanted to touch bases with everyone to let you know that I continue to closely monitor tropical cyclone Beryl, currently a category 4 hurricane just south southwest of Jamaica. As you'll notice in the NWS National Hurricane Center graphic below, this system is forecast to continue slightly northwest of due west before moving ashore of the eastern coast of the Yucatan Peninsula before sunrise Friday morning. While the system may fluctuate in intensity a bit, it is still expected to arrive on the Yucatan Peninsula coast as a strong category 2 hurricane.

The trip across the Yucatan Peninsula will, of course, cause the system to weaken but will likely remain a tropical storm. It is this track across Yucatan Peninsula and beyond into the west/southwestern Gulf of Mexico where we see forecast uncertainty, both in exact position and directional movement as well as forecast intensity greatly increase. Notice, as well, that most of south Texas including the central and lower Texas coast are now officially in the NWS National Hurricane Center's cone of uncertainty.

As a result, you're getting this email late on this Wednesday afternoon. Given the projected movement, given that tomorrow is a holiday, I just wanted everyone to increase

their awareness of this system and know that given the current projected path and earliest expected arrival times of tropical storm force winds (second graphic below), tropical cyclone watches for the western Gulf of Mexico coastal areas, including parts of the Texas coast, could be forthcoming by Friday.

As my third graphic, I'm including the latest NWS Weather Prediction Center 7 day rainfall guidance, courtesy Pivotal Weather, from this afternoon to give you an idea of what NWS forecasters are thinking about rainfall amounts between now and 7pm next Wednesday (10 July). Please understand that these forecast rainfall amounts over Texas will change - totals could go up, totals could go down at any given location - over the next few days as we get a better look at Beryl and exactly where it tracks and any forecast intensification after crossing the Yucatan Peninsula.

As far as the IH35 corridor/Austin metro area is concerned, it still entirely too early to know the effects we could see for late in the weekend into early next week. There is simply too much uncertainty.. we will get a better handle on this over the next few days.

A couple of important reminders..

(1) Although I like to use the NWS/National Hurricane Center center point forecast track/line below (when using these forecast point/line positions, remember the storm has a counter clockwise rotation around that point with the right forward side of this center point often experiencing the most significant conditions), a tropical cyclone itself is NOT a point, it's a relatively large system with inclement conditions experienced over a fairly wide area.

(2) Now is the time for all of us to increase our weather awareness - and to have our plans handy - in regards to tropical cyclone Beryl.

(3) Remember, be a good critical thinker and utilize have your trusted weather sources (folks you

KNOW and TRUST) including your colleagues at our local Austin-San Antonio NWS office (weather.gov/ewx) as well as the NWS National Hurricane Center (nhc.noaa.gov). Your local media folks, that you know, are good and reliable sources as well. On the other hand, stay away from unknown social media folks that are more interested in passing along extreme/"gloom and doom" model solutions and getting social media clicks.

I will continue to monitor... tk

... Authority / NWS National Hurricane Center ...





... Authority / NWS Weather Prediction Center ...



(Courtesy: Pivotal Weather)

Reminders...

I encourage everyone to be weather aware. Know, in advance, the difference between a NWS issued WATCH, ADVISORY and WARNING.



INCLEMENT WEATHER TERMS

! WATCH

Conditions are favorable for specified weather. Simply keep a "watch" on the weather.

!! ADVISORY

Specified weather is happening or is imminent and is a public inconvenience. Use caution.

!!! WARNING

Specified weather is happening or is imminent and is LIFE THREATENING. Seek shelter immediately.



Always have at least two methods of getting current weather information..

.. follow me AND activate notifications on Twitter .. @troykimmelwx ..
.. have your NWS All Hazards Weather Radio properly set AT ALL TIMES so it can receive
and activate/alarm when NWS watches and warnings are issued ..
.. register to receive emergency updates at <https://warncentraltexas.org/>
.. make sure the WEA alerts are activated in your settings on your smart phone ..
.. go to the NWS Austin-San Antonio website at weather.gov/ewx ..
.. go to <http://mesonet.agron.iastate.edu/cgi-bin/afos/retrieve.py?pil=warewx&limit=20&fmt=html>
for a chronological text listing (most current at the top but note the page doesn't auto-refresh, you
must refresh page manually) of NWS Austin-San Antonio watches, advisories and warnings..

--

Troy Kimmel, AMS CBM #25
Owner / Meteorologist, KimCo Meteorological Services
Senior Lecturer, Department of Geography and the Environment, University of Texas at Austin
University/Incident Response Meteorologist, Office of Emergency Management, Campus Operations

6512 Sans Souci Cove
Austin, TX 78759-5163

Email / troy@troykimmelweather.com
Desk (512) 335-6472
Cell/Text (512) 917-7172

Fellow and Member, American Meteorological Society (Member #012403 / CBM #25)
Member, National Weather Association (Seals: TV #8301133 / Radio #0906952R)
Member, Association of American Geographers
Member, International Association of Emergency Managers
Member, Emergency Management Association of Texas

Web / troykimmelweather.com
Facebook / www.facebook.com/troymkimmeljr
Twitter / @troykimmelwx

--

"During my eighty-seven years I have witnessed a whole succession of technological revolutions. But none of them have done away with the need for character in the individual or the ability to think."
- Bernard M. Baruch (US businessman & politician, 1870-1965)

"Lord, we ain't what we oughta be. We ain't what we want to be. We ain't what we gonna be. But, thank God, we ain't what we was."
- Dr. Martin Luther King (1929-1968), at the end of a 1962 speech, quoted a slave preacher who he said "didn't quite have his grammar right but uttered words of great symbolic profundity."

Attachment 3

(A) Weather Emergency Annex

A.1 Purpose and Applicability

To provide the procedures for BEC personnel to respond to cold or hot weather emergency situations by developing a checklist for BEC personnel to use during cold or hot weather emergency response to ensure necessary supplies and personnel are available through the weather emergency.

A.2 Administration / Initial Tasks

Develop / Implement a Hot and Cold Weather Emergency EOP Annex (Weather Emergency Plan): BEC shall develop and maintain a Weather Emergency Plan that provides the procedures for BEC personnel to implement to prepare for an imminent cold or hot weather event that has a probability of resulting in a system emergency event.

A.3 Annual Review / Ongoing Maintenance

The Chief Operations Officer shall conduct a review of the Weather Emergency Plan each year. The Weather Emergency Plan shall be maintained by the Chief Operations Officer.

A.4 Weather Emergency Procedures

A.4.1 Cold Weather Event Preparation Procedures

Starting 72-hours prior to the forecasted arrival of severe cold weather conditions (freezing rain, snow, ice, winds, and extreme cold temperatures); BEC Operation personnel shall:

- Ice Storms typically are predicted with several days' notice as weather conditions develop. Weather will be monitored at the BEC main office by television, weather radio, and internet as necessary.
- If an ice storm is predicted, material stock will be checked, and additional material ordered for major pole and line replacement. BEC and In-house Contractor vehicles will be made ice storm ready with truck and tool inspections, fueling and de-icing materials, housekeeping including cleaning windshields and lighting, and additional stock of wire, splices, connectors, and fuses. Additional windshield fluid will be maintained for use as needed. The Backup generator will be checked for fuel and operation for extended loss of power. Rock salt will be placed at strategic locations for application to sidewalks and parking areas at the main office and service center as required.
- All BEC employees and In-house Contract crews will be placed on notice to be available as needed during and after business hours. All crews will make up duffel bags with clothing required for working in extended cold weather work. *Dependent on predicted severity*, The County Emergency Management Coordinator(s), The Texas Division of Emergency Management (TDEM) Coordinators, Texas Electric Cooperatives Inc. and additional contractors may be contacted prior to damages. Work order numbers and labor codes should be set up for each county prior to reconstruction.
- During icy conditions normal line construction will cease and vehicles will be arranged so that crews and equipment will have a short response time to all areas of the system. Travel will be restricted to "as required". Digger trucks will have additional poles loaded according to predicted severity.
- Contract crews must check in with the Supervisor as required if wishing to leave because of rain out. The Supervisor will contact the Dispatcher and determine if contractors may leave

or must make preparations for damage repairs. Contractors will inform the Supervisor of contact and equipment location information in case assistance is needed for restoration & repairs.

- If damage occurs from an ice storm, Supervisors, or Chief Operations Officer will serve as Coordinator(s) to direct crews and dispatcher.
- Crews will be dispatched to assess damage as soon as deemed safe. The Dispatcher and Coordinator(s) will assess, group, coordinate, and relay the outage information to the dispatched employees. At least two vehicles with repair employees will be dispatched and coordinated when available. Contractors may be dispatched as necessary to limit outage duration. GPS tracking may be used to monitor truck locations. Supporting equipment (bucket trucks, digger trucks, poles, and other material) may be dispatched as anticipated before actual need to limit outage duration.
- If area is declared a disaster area, The County Emergency Management Coordinator(s), The Texas Division of Emergency Management (TDEM) Coordinators, Texas Electric Cooperatives Inc. and the RUS GFR should be contacted as soon as possible. The Public Utility Commission must be contacted to report Significant Interruption if over 20% of membership is affected. Work order numbers and labor codes should be set up for each county prior to reconstruction.
- Field Crew Preparation – ensure all crews / trucks are supplied; including:
 - Fuses
 - Long Sticks
 - Handlines
 - Check heaters in warehouse
 - Chainsaw’s gas, bar oil, and chains
 - De-icer for trucks
 - Contractors on standby
 - Overhead
 - Underground
 - Communication
 - Internal
 - External
 - Material
 - Fuel delivery
 - List of personnel to conduct field assessments
 - Realtime account notification
 - Critical Load Account notification
 - Check servers and computers
 - Push latest map update
 - ROW Contractor
 - Number of Crews
 - Point of contact for crews

A.4.1 Hot Weather Event Preparation Procedures

- Starting 72-hours prior to the forecasted arrival of extreme hot weather conditions (temperatures significantly above seasonal norms); BEC Operation personnel shall:
- Review engineer load study on the system (if needed)
- Field Crew Preparation – ensure all crews / trucks are supplied; including:
 - Fuses
 - Long Sticks
 - Handlines
 - Chainsaw’s gas, bar oil, and chains
 - Check ice machines
- Contractors on standby
 - Overhead
 - Underground
- Communication
 - Internal
 - External
- Material
- Fuel delivery
- List of personnel to conduct field assessments
- Realtime account notification
- Critical Load Account notification
- Check servers and computers
- Push latest map update
- ROW Contractor
 - Number of Crews
 - Point of contact for crews
- Activate staffing plan to ensure Operations personnel are prepared and available for service during the anticipated timeframe of the hot weather event.

Attachment 4

height	class	material	owner	sub	feeder number	manufactured	usage	gps latitude	gps longitude
20'	9	WOOD	Bartlett	Thorndale	1	UNK	SEC	30.608698	-97.239593
20'	7	WOOD	Bartlett	Thorndale	1	UNK	SEC	30.639527	-97.264647
20'	9	WOOD	Bartlett	Thorndale	1	UNK	SEC	30.609227	-97.249282
20'	9	WOOD	Bartlett	Thorndale	1	UNK	SEC	30.639585	-97.264947
20'	9	WOOD	Bartlett	Talbertridge	4	UNK	SEC	30.686895	-96.918662
20'	6	WOOD	Bartlett	Bartlett	1	UNK	GUY	30.849897	-97.338361
20'	5	WOOD	Bartlett	Cedar Valley	11	UNK	GUY	31.009831	-97.616322
20'	5	WOOD	Bartlett	Cedar Valley	11	UNK	SEC	30.976533	-97.588534
20'	6	WOOD	Bartlett	Ding Dong	1	UNK	SEC	30.944717	-97.784
20'	4	WOOD	Bartlett	Ding Dong	2	UNK	SEC	30.979404	-97.787079
20'	6	WOOD	Bartlett	Ding Dong	2	UNK	SEC	31.021937	-97.87349
20'	5	WOOD	Bartlett	Trimmier	3	UNK	SEC	31.036292	-97.732573
20'	6	WOOD	Bartlett	Trimmier	3	UNK	SEC	31.036408	-97.73269
25'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.712535	-97.157941
25'	7	WOOD	Bartlett	Talbertridge	4	UNK	SEC	30.607829	-96.874871
25'	7	WOOD	Bartlett	Buckholts	1	UNK	SEC	30.83061	-97.287891
25'	7	WOOD	Bartlett	Buckholts	4	UNK	SEC	30.708921	-97.230256
25'	7	WOOD	Bartlett	Buckholts	4	UNK	GUY	30.745021	-97.219596
25'	6	WOOD	Bartlett	Buckholts	4	UNK	SEC	30.772268	-97.263956
25'	7	WOOD	Bartlett	Buckholts	1	UNK	GUY	30.921888	-97.264379
25'	6	WOOD	Bartlett	Bartlett	3	UNK	SEC	30.744549	-97.421512
25'	7	WOOD	Bartlett	Bartlett	3	UNK	GUY	30.76404	-97.377864
25'	6	WOOD	Bartlett	Bartlett	3	UNK	SEC	30.748514	-97.364097
25'	7	WOOD	Bartlett	Bartlett	3	UNK	SEC	30.735243	-97.357007
25'	5	WOOD	Bartlett	Bartlett	1	UNK	SEC	30.850507	-97.33761
25'	7	WOOD	Bartlett	Schwertner	3	UNK	SEC	30.807026	-97.530554
25'	7	WOOD	Bartlett	Sonterra	13	UNK	SEC	30.855302	-97.625165
25'	6	WOOD	Bartlett	Cedar Valley	11	UNK	SEC	31.005101	-97.626203
25'	7	WOOD	Bartlett	Cedar Valley	13	UNK	GUY	30.925389	-97.752437
25'	7	WOOD	Bartlett	Ding Dong	1	UNK	GUY	30.937739	-97.818115
25'	6	WOOD	Bartlett	Trimmier	1	UNK	SEC	31.022091	-97.638124
25'	5	WOOD	Bartlett	Trimmier	1	UNK	SEC	31.007552	-97.680315

25'	6	WOOD	Bartlett	Trimmer	1	UNK	SEC	31.026831	-97.634745
30'	6	WOOD	Bartlett	Salty	3	1986	PRI	30.651439	-97.172077
30'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.67022	-97.079374
30'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.672962	-97.069119
30'	6	WOOD	Bartlett	Salty	3	UNK	GUY	30.702686	-97.142007
30'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.649612	-97.176882
30'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.627832	-97.080498
30'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.63224	-97.135506
30'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.615652	-97.108261
30'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.633845	-97.040238
30'	5	WOOD	Bartlett	Salty	3	UNK	GUY	30.637266	-97.045528
30'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.639348	-97.051782
30'	5	WOOD	Bartlett	Salty	3	UNK	SEC	30.634382	-97.141147
30'	6	WOOD	Bartlett	Salty	3	UNK	GUY	30.629986	-97.046845
30'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.622131	-97.089367
30'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.638517	-97.140684
30'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.643448	-97.130153
30'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.625511	-97.101554
30'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.645408	-97.101736
30'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.62282	-97.085317
30'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.645475	-97.056611
30'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.689287	-97.06646
30'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.648313	-97.070632
30'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.671938	-97.046857
30'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.645266	-97.132095
30'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.617085	-97.102914
30'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.643347	-97.128781
30'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.646641	-97.128829
30'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.641717	-97.101315
30'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.645736	-97.178814
30'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.631257	-97.091969
30'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.649697	-97.092536
30'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.608614	-97.092454

30'	6	WOOD	Bartlett	Salty	3	UNK	GUY	30.675614	-97.155942
30'	6	WOOD	Bartlett	Salty	3	1974	SEC	30.632956	-97.096316
30'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.625112	-97.102273
30'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.623396	-97.087784
30'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.516527	-97.165242
30'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.50067	-97.15067
30'	6	WOOD	Bartlett	Salty	1	UNK	SEC	30.498665	-97.157364
30'	6	WOOD	Bartlett	Thorndale	1	UNK	SEC	30.610379	-97.238442
30'	6	WOOD	Bartlett	Salty	1	UNK	SEC	30.59397	-97.132465
30'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.602672	-97.136325
30'	6	WOOD	Bartlett	Salty	1	UNK	SEC	30.589112	-97.126161
30'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.516327	-97.164449
30'	6	WOOD	Bartlett	Salty	1	UNK	SEC	30.595223	-97.145128
30'	6	WOOD	Bartlett	Salty	1	UNK	SEC	30.53617	-97.178242
30'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.482439	-97.137934
30'	6	WOOD	Bartlett	Talbertridge	2	UNK	GUY	30.622993	-96.926905
30'	7	WOOD	Bartlett	Talbertridge	4	UNK	PRI	30.725123	-96.931989
30'	9	WOOD	Bartlett	Talbertridge	4	UNK	SEC	30.683174	-96.934722
30'	6	WOOD	Bartlett	Talbertridge	2	UNK	SEC	30.606833	-96.949458
30'	6	WOOD	Bartlett	Talbertridge	4	UNK	SEC	30.711685	-96.845173
30'	6	WOOD	Bartlett	Talbertridge	1	UNK	SEC	30.735704	-96.983004
30'	6	WOOD	Bartlett	Talbertridge	4	UNK	PRI	30.696767	-96.83582
30'	7	WOOD	Bartlett	Talbertridge	4	UNK	PRI	30.687914	-96.856162
30'	6	WOOD	Bartlett	Talbertridge	1	1977	SEC	30.705611	-97.017443
30'	6	WOOD	Bartlett	Talbertridge	1	UNK	SEC	30.702671	-96.999151
30'	6	WOOD	Bartlett	Talbertridge	1	UNK	SEC	30.732306	-97.036263
30'	7	WOOD	Bartlett	Talbertridge	4	UNK	GUY	30.672651	-96.910638
30'	7	WOOD	Bartlett	Talbertridge	2	UNK	PRI	30.598554	-96.920879
30'	6	WOOD	Bartlett	Talbertridge	4	1969	SEC	30.734274	-96.915633
30'	7	WOOD	Bartlett	Talbertridge	4	UNK	PRI	30.692862	-96.868042
30'	6	WOOD	Bartlett	Talbertridge	2	UNK	PRI	30.671599	-96.970506
30'	9	WOOD	Bartlett	Talbertridge	4	UNK	SEC	30.690651	-96.935907
30'	6	WOOD	Bartlett	Talbertridge	2	UNK	SEC	30.606137	-96.965443

30'	6	WOOD	Bartlett	Talbertrige	2	UNK	SEC	30.589649	-96.909985
30'	7	WOOD	Bartlett	Talbertrige	4	UNK	SEC	30.736103	-96.924076
30'	6	WOOD	Bartlett	Talbertrige	4	1970	PRI	30.674451	-96.90172
30'	7	WOOD	Bartlett	Talbertrige	4	UNK	PRI	30.712196	-96.89351
30'	6	WOOD	Bartlett	Talbertrige	2	UNK	SEC	30.671035	-96.970748
30'	6	WOOD	Bartlett	Talbertrige	1	UNK	SEC	30.731203	-96.973043
30'	6	WOOD	Bartlett	Talbertrige	1	UNK	SEC	30.681259	-97.050506
30'	6	WOOD	Bartlett	Talbertrige	1	UNK	SEC	30.73022	-97.035634
30'	6	WOOD	Bartlett	Talbertrige	4	UNK	PRI	30.709921	-96.841301
30'	6	WOOD	Bartlett	Talbertrige	4	UNK	SEC	30.683586	-96.872659
30'	7	WOOD	Bartlett	Talbertrige	4	UNK	PRI	30.710096	-96.842253
30'	6	WOOD	Bartlett	Talbertrige	2	UNK	SEC	30.586368	-96.961215
30'	6	WOOD	Bartlett	Talbertrige	4	UNK	PRI	30.673022	-96.901132
30'	6	WOOD	Bartlett	Talbertrige	4	UNK	SEC	30.672239	-96.911273
30'	7	WOOD	Bartlett	Talbertrige	4	UNK	SEC	30.695748	-96.838748
30'	6	WOOD	Bartlett	Talbertrige	4	UNK	SEC	30.703166	-96.843887
30'	6	WOOD	Bartlett	Talbertrige	1	UNK	SEC	30.759454	-97.064395
30'	6	WOOD	Bartlett	Talbertrige	4	UNK	SEC	30.697061	-96.839323
30'	6	WOOD	Bartlett	Talbertrige	4	UNK	SEC	30.684896	-96.830629
30'	6	WOOD	Bartlett	Talbertrige	2	UNK	SEC	30.634	-96.988196
30'	6	WOOD	Bartlett	Talbertrige	2	UNK	PRI	30.595993	-96.968592
30'	7	WOOD	Bartlett	Talbertrige	4	UNK	SEC	30.674063	-96.871568
30'	6	WOOD	Bartlett	Talbertrige	4	UNK	PRI	30.672333	-96.900845
30'	7	WOOD	Bartlett	Talbertrige	4	UNK	PRI	30.693171	-96.866952
30'	6	WOOD	Bartlett	Talbertrige	4	UNK	GUY	30.62999	-96.856839
30'	6	WOOD	Bartlett	Talbertrige	4	UNK	SEC	30.697353	-96.839316
30'	6	WOOD	Bartlett	Talbertrige	4	UNK	SEC	30.733824	-96.922706
30'	7	WOOD	Bartlett	Talbertrige	4	UNK	PRI	30.673645	-96.90759
30'	6	WOOD	Bartlett	Talbertrige	3	UNK	SEC	30.670454	-96.967247
30'	6	WOOD	Bartlett	Talbertrige	1	UNK	SEC	30.730339	-97.035166
30'	6	WOOD	Bartlett	Talbertrige	1	UNK	SEC	30.70661	-97.00037
30'	7	WOOD	Bartlett	Talbertrige	4	UNK	PRI	30.733782	-96.915633
30'	5	WOOD	Bartlett	Talbertrige	2	UNK	PRI	30.615755	-96.926613

30'	7	WOOD	Bartlett	Talbertridge	4	UNK	SEC	30.680611	-96.943873
30'	7	WOOD	Bartlett	Talbertridge	4	1974	SEC	30.671558	-96.900089
30'	6	WOOD	Bartlett	Talbertridge	1	UNK	SEC	30.716808	-97.069606
30'	6	WOOD	Bartlett	Talbertridge	4	UNK	SEC	30.692528	-96.847755
30'	6	WOOD	Bartlett	Talbertridge	1	UNK	SEC	30.720652	-97.039558
30'	6	WOOD	Bartlett	Talbertridge	2	UNK	SEC	30.616228	-96.950902
30'	6	WOOD	Bartlett	Talbertridge	4	UNK	SEC	30.685934	-96.855174
30'	6	WOOD	Bartlett	Talbertridge	2	UNK	PRI	30.569983	-96.948464
30'	6	WOOD	Bartlett	Talbertridge	4	UNK	GUY	30.67299	-96.90121
30'	5	WOOD	Bartlett	Buckholts	4	UNK	SEC	30.807735	-97.188431
30'	6	WOOD	Bartlett	Buckholts	4	UNK	GUY	30.775691	-97.277588
30'	7	WOOD	Bartlett	Buckholts	4	UNK	SEC	30.793263	-97.285276
30'	6	WOOD	Bartlett	Buckholts	4	UNK	SEC	30.756718	-97.184337
30'	6	WOOD	Bartlett	Buckholts	1	UNK	SEC	30.932263	-97.200686
30'	6	WOOD	Bartlett	Buckholts	1	UNK	SEC	30.932539	-97.201051
30'	6	WOOD	Bartlett	Buckholts	1	UNK	SEC	30.92184	-97.276106
30'	6	WOOD	Bartlett	Buckholts	4	UNK	GUY	30.753593	-97.182175
30'	6	WOOD	Bartlett	Buckholts	1	UNK	SEC	30.912114	-97.189778
30'	6	WOOD	Bartlett	Buckholts	4	UNK	GUY	30.734854	-97.214321
30'	7	WOOD	Bartlett	Salty	3	UNK	PRI	30.713889	-97.174871
30'	6	WOOD	Bartlett	Buckholts	4	UNK	GUY	30.758634	-97.264778
30'	6	WOOD	Bartlett	Buckholts	1	UNK	PRI	30.910257	-97.296908
30'	7	WOOD	Bartlett	Buckholts	1	UNK	SEC	30.909345	-97.280775
30'	6	WOOD	Bartlett	Buckholts	4	UNK	SEC	30.78442	-97.281141
30'	6	WOOD	Bartlett	Bartlett	1	UNK	SEC	30.804299	-97.291893
30'	7	WOOD	Bartlett	Bartlett	1	UNK	SEC	30.801248	-97.426649
30'	5	WOOD	Bartlett	Bartlett	3	UNK	GUY	30.748783	-97.474088
30'	6	WOOD	Bartlett	Bartlett	3	UNK	SEC	30.727984	-97.419356
30'	6	WOOD	Bartlett	Bartlett	1	1947	SEC	30.792365	-97.368042
30'	6	WOOD	Bartlett	Bartlett	3	UNK	SEC	30.783218	-97.440426
30'	6	WOOD	Bartlett	Bartlett	3	UNK	SEC	30.754892	-97.445167
30'	6	WOOD	Bartlett	Bartlett	1	UNK	SEC	30.863942	-97.361088
30'	6	WOOD	Bartlett	Bartlett	1	UNK	SEC	30.859768	-97.358835

30'	7	WOOD	Bartlett	Bartlett	1	UNK	SEC	30.826243	-97.361553
30'	6	WOOD	Bartlett	Bartlett	1	UNK	SEC	30.826968	-97.427034
30'	5	WOOD	Bartlett	Bartlett	3	UNK	GUY	30.762928	-97.399965
30'	6	WOOD	Bartlett	Bartlett	3	UNK	GUY	30.698465	-97.252687
30'	6	WOOD	Bartlett	Bartlett	3	UNK	SEC	30.704247	-97.282426
30'	7	WOOD	Bartlett	Bartlett	1	UNK	SEC	30.808731	-97.315226
30'	5	WOOD	Bartlett	Bartlett	1	UNK	GUY	30.822211	-97.424413
30'	7	WOOD	Bartlett	Bartlett	3	1974	GUY	30.735746	-97.351177
30'	4	WOOD	Bartlett	Bartlett	1	UNK	PRI	30.842101	-97.418715
30'	7	WOOD	Bartlett	Bartlett	1	UNK	SEC	30.800719	-97.334643
30'	7	WOOD	Bartlett	Bartlett	1	UNK	SEC	30.824325	-97.397556
30'	7	WOOD	Bartlett	Bartlett	1	1974	SEC	30.826564	-97.361764
30'	5	WOOD	Bartlett	Bartlett	1	2003	PRI	30.864877	-97.467786
30'	7	WOOD	Bartlett	Bartlett	1	UNK	GUY	30.80832	-97.350353
30'	7	WOOD	Bartlett	Bartlett	1	UNK	GUY	30.82615	-97.405502
30'	7	WOOD	Bartlett	Bartlett	1	UNK	GUY	30.841069	-97.471204
30'	7	WOOD	Bartlett	Bartlett	1	2002	PRI	30.845279	-97.356136
30'	6	WOOD	Bartlett	Bartlett	1	UNK	GUY	30.823889	-97.386118
30'	7	WOOD	Bartlett	Bartlett	3	UNK	SEC	30.697035	-97.247728
30'	6	WOOD	Bartlett	Schwertner	1	UNK	SEC	30.713765	-97.553389
30'	5	WOOD	Bartlett	Schwertner	3	1970	SEC	30.821254	-97.529283
30'	6	WOOD	Bartlett	Schwertner	1	UNK	SEC	30.706134	-97.55786
30'	6	WOOD	Bartlett	Sonterra	12	UNK	GUY	30.861171	-97.574645
30'	6	WOOD	Bartlett	Schwertner	1	UNK	SEC	30.726155	-97.50313
30'	6	WOOD	Bartlett	Schwertner	1	UNK	SEC	30.690156	-97.57778
30'	6	WOOD	Bartlett	Schwertner	2	UNK	SEC	30.794746	-97.600055
30'	6	WOOD	Bartlett	Schwertner	2	UNK	SEC	30.781815	-97.599453
30'	6	WOOD	Bartlett	Schwertner	1	UNK	SEC	30.727855	-97.583336
30'	6	WOOD	Bartlett	Sonterra	13	UNK	SEC	30.834747	-97.628162
30'	6	WOOD	Bartlett	Schwertner	2	UNK	SEC	30.787591	-97.56626
30'	6	WOOD	Bartlett	Schwertner	1	UNK	GUY	30.720698	-97.547347
30'	6	WOOD	Bartlett	Schwertner	1	UNK	GUY	30.699876	-97.547353
30'	7	WOOD	Bartlett	Schwertner	2	UNK	SEC	30.7766	-97.584778

30'	6	WOOD	Bartlett	Schwertner	1	UNK	SEC	30.756008	-97.540877
30'	6	WOOD	Bartlett	Sonterra	12	UNK	SEC	30.863542	-97.538399
30'	6	WOOD	Bartlett	Schwertner	2	UNK	SEC	30.800043	-97.590832
30'	6	WOOD	Bartlett	Schwertner	1	UNK	SEC	30.70471	-97.510476
30'	6	WOOD	Bartlett	Schwertner	1	UNK	SEC	30.700916	-97.516732
30'	6	WOOD	Bartlett	Schwertner	1	UNK	GUY	30.684312	-97.574691
30'	6	WOOD	Bartlett	Schwertner	3	UNK	PRI	30.86601	-97.487009
30'	6	WOOD	Bartlett	Schwertner	3	UNK	GUY	30.824277	-97.482016
30'	6	WOOD	Bartlett	Sonterra	12	UNK	SEC	30.884814	-97.545359
30'	6	WOOD	Bartlett	Sonterra	13	UNK	SEC	30.834965	-97.628301
30'	6	WOOD	Bartlett	Schwertner	1	UNK	SEC	30.764588	-97.575195
30'	6	WOOD	Bartlett	Schwertner	1	UNK	SEC	30.770794	-97.550232
30'	6	WOOD	Bartlett	Schwertner	3	UNK	SEC	30.821715	-97.529959
30'	6	WOOD	Bartlett	Schwertner	1	UNK	SEC	30.746202	-97.565973
30'	6	WOOD	Bartlett	Schwertner	1	UNK	SEC	30.702378	-97.524049
30'	6	WOOD	Bartlett	Schwertner	1	UNK	SEC	30.728012	-97.58327
30'	6	WOOD	Bartlett	Sonterra	12	UNK	SEC	30.887425	-97.53073
30'	7	WOOD	Bartlett	Schwertner	3	UNK	SEC	30.803863	-97.516366
30'	6	WOOD	Bartlett	Schwertner	3	UNK	SEC	30.800771	-97.559027
30'	6	WOOD	Bartlett	Schwertner	1	UNK	SEC	30.746579	-97.54912
30'	6	WOOD	Bartlett	Sonterra	12	UNK	SEC	30.846948	-97.569893
30'	6	WOOD	Bartlett	Schwertner	1	UNK	SEC	30.743441	-97.565967
30'	6	WOOD	Bartlett	Schwertner	3	UNK	SEC	30.80357	-97.516117
30'	6	WOOD	Bartlett	Schwertner	2	UNK	SEC	30.777726	-97.6024
30'	6	WOOD	Bartlett	Schwertner	1	UNK	SEC	30.74963	-97.556772
30'	5	WOOD	Bartlett	Cedar Valley	13	UNK	SEC	30.909722	-97.785169
30'	6	WOOD	Bartlett	Cedar Valley	13	1964	SEC	30.947713	-97.705768
30'	6	WOOD	Bartlett	Cedar Valley	11	UNK	SEC	30.91522	-97.601329
30'	6	WOOD	Bartlett	Cedar Valley	11	UNK	SEC	30.979924	-97.588244
30'	6	WOOD	Bartlett	Cedar Valley	11	UNK	SEC	30.918303	-97.587149
30'	5	WOOD	Bartlett	Cedar Valley	13	UNK	SEC	30.965205	-97.723705
30'	5	WOOD	Bartlett	Cedar Valley	13	UNK	SEC	30.942761	-97.731198
30'	6	WOOD	Bartlett	Cedar Valley	11	1974	SEC	30.982639	-97.584595

30'	6	WOOD	Bartlett	Ding Dong	1	UNK	SEC	30.969437	-97.768699
30'	6	WOOD	Bartlett	Ding Dong	1	UNK	SEC	30.971289	-97.768888
30'	6	WOOD	Bartlett	Ding Dong	1	UNK	SEC	30.980533	-97.770133
30'	6	WOOD	Bartlett	Ding Dong	1	UNK	LIGHT	30.928846	-97.799763
30'	6	WOOD	Bartlett	Ding Dong	1	UNK	SEC	30.980713	-97.767759
30'	6	WOOD	Bartlett	Ding Dong	1	UNK	SEC	30.980354	-97.757315
30'	6	WOOD	Bartlett	Ding Dong	1	UNK	SEC	30.933374	-97.796785
30'	5	WOOD	CenturyLink	Ding Dong	3	1999	SEC	31.005317	-97.752164
30'	6	WOOD	Bartlett	Ding Dong	2	UNK	SEC	30.997877	-97.854888
30'	5	WOOD	Bartlett	Ding Dong	3	2001	SEC	31.007281	-97.754481
30'	6	WOOD	Bartlett	Ding Dong	4	UNK	SEC	30.986699	-97.74915
30'	6	WOOD	Bartlett	Ding Dong	1	UNK	LIGHT	30.945522	-97.785619
30'	6	WOOD	Bartlett	Ding Dong	1	UNK	SEC	30.977288	-97.764593
30'	6	WOOD	Bartlett	Ding Dong	1	UNK	SEC	30.981886	-97.759131
30'	7	WOOD	Bartlett	Ding Dong	3	UNK	SEC	31.009734	-97.753892
30'	6	WOOD	Bartlett	Ding Dong	1	UNK	SEC	30.976688	-97.76909
30'	6	WOOD	Bartlett	Ding Dong	1	UNK	SEC	30.982162	-97.749723
30'	6	WOOD	Bartlett	Ding Dong	1	UNK	SEC	30.977609	-97.769212
30'	5	WOOD	Bartlett	Ding Dong	2	UNK	SEC	30.99363	-97.827422
30'	6	WOOD	Bartlett	Ding Dong	1	UNK	LIGHT	30.968843	-97.760985
30'	6	WOOD	Bartlett	Ding Dong	3	UNK	SEC	31.012796	-97.751258
30'	6	WOOD	Bartlett	Ding Dong	1	UNK	SEC	30.92709	-97.800902
30'	6	WOOD	Bartlett	Ding Dong	1	1972	SEC	30.97903	-97.756928
30'	6	WOOD	Bartlett	Ding Dong	4	1952	SEC	30.984465	-97.758103
30'	6	WOOD	Bartlett	Ding Dong	1	UNK	SEC	30.962003	-97.778311
30'	6	WOOD	Bartlett	Ding Dong	1	UNK	SEC	30.927104	-97.798592
30'	6	WOOD	Bartlett	Ding Dong	1	UNK	SEC	30.976781	-97.76203
30'	6	WOOD	Bartlett	Ding Dong	2	1962	GUY	30.982192	-97.803966
30'	6	WOOD	Bartlett	Ding Dong	1	UNK	SEC	30.963688	-97.765949
30'	6	WOOD	Bartlett	Ding Dong	1	UNK	LIGHT	30.945167	-97.825994
30'	6	WOOD	Bartlett	Ding Dong	3	UNK	SEC	31.003226	-97.743514
30'	6	WOOD	Bartlett	Ding Dong	1	UNK	SEC	30.967552	-97.755594
30'	7	WOOD	Bartlett	Ding Dong	3	UNK	SEC	31.00904	-97.753538

30'	6	WOOD	Bartlett	Ding Dong	1	UNK	SEC	30.928404	-97.789535
30'	6	WOOD	Bartlett	Ding Dong	1	UNK	SEC	30.934769	-97.827962
30'	6	WOOD	Bartlett	Trimmier	4	UNK	LIGHT	31.035159	-97.639488
30'	6	WOOD	Bartlett	Trimmier	3	UNK	SEC	31.027957	-97.736163
30'	6	WOOD	Bartlett	Trimmier	4	UNK	LIGHT	31.039697	-97.658852
30'	6	WOOD	Bartlett	Trimmier	3	UNK	SEC	31.027756	-97.736246
30'	6	WOOD	Bartlett	Trimmier	4	UNK	LIGHT	31.03671	-97.638586
30'	6	WOOD	Bartlett	Trimmier	4	UNK	SEC	31.021797	-97.698207
30'	6	WOOD	Bartlett	Trimmier	3	UNK	SEC	31.041846	-97.740646
30'	7	WOOD	Bartlett	Trimmier	1	UNK	SEC	31.029436	-97.648708
30'	6	WOOD	Bartlett	Trimmier	4	UNK	SEC	31.021715	-97.689348
30'	7	WOOD	Bartlett	Trimmier	3	UNK	SEC	31.012397	-97.722457
30'	6	WOOD	Bartlett	Trimmier	4	UNK	SEC	31.034533	-97.638687
30'	5	WOOD	Bartlett	Trimmier	2	UNK	SEC	31.001202	-97.672093
30'	6	WOOD	Bartlett	Trimmier	2	1965	SEC	30.996557	-97.671836
30'	6	WOOD	Bartlett	Trimmier	4	UNK	LIGHT	31.04307	-97.654999
30'	6	WOOD	Bartlett	Trimmier	4	UNK	LIGHT	31.037079	-97.635051
30'	6	WOOD	Bartlett	Trimmier	4	UNK	LIGHT	31.034162	-97.636975
30'	6	WOOD	Bartlett	Trimmier	4	UNK	LIGHT	31.04377	-97.65443
30'	6	WOOD	Bartlett	Trimmier	1	UNK	SEC	31.033175	-97.640948
30'	6	WOOD	Bartlett	Trimmier	1	UNK	SEC	31.02997	-97.633774
30'	7	WOOD	Bartlett	Trimmier	4	UNK	SEC	31.016555	-97.687128
30'	6	WOOD	Bartlett	Trimmier	1	UNK	SEC	31.029387	-97.63669
30'	6	WOOD	Bartlett	Trimmier	4	UNK	SEC	31.025912	-97.699758
30'	6	WOOD	Bartlett	Trimmier	4	UNK	SEC	31.027262	-97.679204
30'	6	WOOD	Bartlett	Trimmier	4	UNK	LIGHT	31.010149	-97.683922
30'	7	WOOD	Bartlett	Trimmier	1	UNK	SEC	31.022052	-97.639415
30'	6	WOOD	Bartlett	Trimmier	4	UNK	LIGHT	31.03659	-97.633811
30'	6	WOOD	Bartlett	Trimmier	4	UNK	LIGHT	31.035337	-97.634703
30'	6	WOOD	Bartlett	Trimmier	1	UNK	SEC	31.019166	-97.645187
30'	6	WOOD	Bartlett	Trimmier	4	UNK	SEC	31.027144	-97.696347
30'	6	WOOD	Bartlett	Trimmier	4	UNK	LIGHT	31.037513	-97.635616
30'	7	WOOD	Bartlett	Trimmier	2	UNK	SEC	31.00198	-97.67985

30'	6	WOOD	Bartlett	Trimmier	1	UNK	SEC	31.028082	-97.635967
30'	6	WOOD	Bartlett	Trimmier	3	UNK	PRI	31.040037	-97.722314
30'	6	WOOD	Bartlett	Trimmier	1	UNK	SEC	31.028449	-97.636084
30'	6	WOOD	Bartlett	Trimmier	1	UNK	SEC	31.027059	-97.634758
30'	6	WOOD	Bartlett	Trimmier	1	UNK	SEC	31.027017	-97.63109
30'	6	WOOD	Bartlett	Trimmier	1	UNK	SEC	31.020755	-97.636434
30'	6	WOOD	Bartlett	Trimmier	1	1970	SEC	31.019066	-97.637808
30'	5	WOOD	Bartlett	Cedar Valley	11	UNK	SEC	30.9187	-97.588853
30'	4	WOOD	Bartlett	Buckholts	1	2011	SEC	30.854436	-97.310149
30'	6	WOOD	Bartlett	Thorndale	1		LIGHT	30.609475	-97.222156
30'	5	WOOD	Bartlett	Trimmier	4		SEC	31.038954	-97.639479
30'	5	WOOD	Bartlett	Trimmier	1		LIGHT	31.019281	-97.637762
30'	4	WOOD	Bartlett	Ding Dong	2	1976	LIGHT	30.983431	-97.827193
30'			Bartlett					30.996284	-97.839035
35'	6	WOOD	Bartlett	Salty	3	1995	PRI	30.606387	-97.084624
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.615509	-97.083666
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.602793	-97.128467
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.704174	-97.15633
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.604042	-97.086073
35'	5	WOOD	Bartlett	Salty	3	1998	PRI	30.621032	-97.112042
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.706259	-97.131675
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.633036	-97.103529
35'	6	WOOD	Bartlett	Salty	3	1996	PRI	30.646117	-97.095497
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.643693	-97.1263
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.603538	-97.117211
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.633988	-97.049573
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.640678	-97.126202
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.650652	-97.05463
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.624548	-97.08652
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.663009	-97.0565
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.652979	-97.068183
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.687468	-97.119527
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.622313	-97.113755

35'	6	WOOD	Bartlett	Salty	3	2003	PRI	30.637158	-97.033787
35'	6	WOOD	Bartlett	Salty	3	2003	PRI	30.660738	-97.060285
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.696336	-97.17817
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.667314	-97.187565
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.649981	-97.16729
35'	5	WOOD	Bartlett	Salty	3	2006	SEC	30.669478	-97.148947
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.649039	-97.07424
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.689492	-97.125253
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.651632	-97.065655
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.663263	-97.058644
35'	6	WOOD	Bartlett	Salty	3	1991	PRI	30.612081	-97.105903
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.637546	-97.046047
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.646187	-97.129296
35'	6	WOOD	Bartlett	Salty	3	1985	SEC	30.633222	-97.039259
35'	6	WOOD	Bartlett	Salty	3	1984	SEC	30.635199	-97.040258
35'	4	WOOD	Bartlett	Salty	3	2003	PRI	30.639984	-97.140689
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.642516	-97.12888
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.66671	-97.059083
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.625504	-97.100487
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.629208	-97.082707
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.702472	-97.11115
35'	5	WOOD	Bartlett	Salty	3	1994	PRI	30.645108	-97.047628
35'	7	WOOD	Bartlett	Salty	3	UNK	PRI	30.608937	-97.092002
35'	6	WOOD	Bartlett	Salty	3	2001	SEC	30.701297	-97.179693
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.650516	-97.167672
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.687526	-97.091022
35'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.650571	-97.055216
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.649768	-97.0928
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.663974	-97.05924
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.649024	-97.106088
35'	6	WOOD	Bartlett	Salty	3	1995	PRI	30.604759	-97.085434
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.650074	-97.067685
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.649775	-97.063688

35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.638052	-97.062522
35'	6	WOOD	Bartlett	Salty	3	1978	GUY	30.640421	-97.048621
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.626942	-97.087277
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.6419	-97.141212
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.64342	-97.129349
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.643298	-97.142892
35'	6	WOOD	Bartlett	Salty	3	2003	PRI	30.66223	-97.058666
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.620816	-97.111519
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.635466	-97.084861
35'	6	WOOD	Bartlett	Salty	3	1997	PRI	30.635711	-97.087191
35'	5	WOOD	Bartlett	Salty	3	2006	PRI	30.668733	-97.188522
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.666448	-97.158346
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.62841	-97.112501
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.697247	-97.113309
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.666798	-97.157284
35'	5	WOOD	Bartlett	Salty	3	1997	PRI	30.668055	-97.145789
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.635266	-97.0335
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.63091	-97.045036
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.638916	-97.032568
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.70147	-97.115969
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.652951	-97.075669
35'	5	WOOD	Bartlett	Salty	3	2007	PRI	30.706844	-97.126777
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.636596	-97.038416
35'	5	WOOD	Bartlett	Salty	3	1994	PRI	30.643136	-97.127212
35'	6	WOOD	Bartlett	Salty	3	1998	SEC	30.610372	-97.11185
35'	5	WOOD	Bartlett	Salty	3	2003	PRI	30.628733	-97.046613
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.62772	-97.088476
35'	6	WOOD	Bartlett	Salty	3	1977	SEC	30.639236	-97.05079
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.648544	-97.070363
35'	6	WOOD	Bartlett	Salty	3	1996	PRI	30.609269	-97.084142
35'	6	WOOD	Bartlett	Salty	3	1999	PRI	30.657876	-97.080316
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.663657	-97.171536
35'	6	WOOD	Bartlett	Salty	3	1983	PRI	30.661955	-97.082703

35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.673528	-97.124469
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.634543	-97.03583
35'	4	WOOD	Bartlett	Salty	3	2008	PRI	30.630118	-97.03926
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.639698	-97.125805
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.637005	-97.101845
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.637771	-97.104212
35'	5	WOOD	Bartlett	Salty	3	2003	PRI	30.707493	-97.135603
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.622162	-97.104554
35'	6	WOOD	Bartlett	Salty	3	1999	PRI	30.657639	-97.081056
35'	6	WOOD	Bartlett	Salty	3	1987	PRI	30.650084	-97.078602
35'	5	WOOD	Bartlett	Salty	3	1980	PRI	30.689484	-97.089849
35'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.621194	-97.106691
35'	5	WOOD	Bartlett	Salty	3	2005	PRI	30.648163	-97.168043
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.662549	-97.058045
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.691997	-97.115138
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.612773	-97.109192
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.672619	-97.105674
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.648866	-97.070592
35'	6	WOOD	Bartlett	Salty	3	1995	PRI	30.604381	-97.089448
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.6328	-97.097807
35'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.635849	-97.081781
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.651198	-97.169101
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.651036	-97.064435
35'	6	WOOD	Bartlett	Salty	3	1995	PRI	30.609437	-97.082086
35'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.639097	-97.051071
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.638113	-97.050078
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.630195	-97.105501
35'	5	WOOD	Bartlett	Salty	3	1994	PRI	30.668285	-97.049557
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.632393	-97.103804
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.696184	-97.102371
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.651109	-97.121496
35'	5	WOOD	Bartlett	Salty	3	1994	PRI	30.667039	-97.050368
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.639063	-97.0345

35'	6	WOOD	Bartlett	Salty	3	1995	PRI	30.604851	-97.088655
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.633499	-97.043131
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.621118	-97.089646
35'	5	WOOD	Bartlett	Salty	3	2003	PRI	30.66133	-97.059501
35'	5	WOOD	Bartlett	Salty	3	1994	PRI	30.61472	-97.100231
35'	5	WOOD	Bartlett	Salty	3	2006	PRI	30.698977	-97.154233
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.633735	-97.050288
35'	6	WOOD	Bartlett	Salty	3	1997	PRI	30.627992	-97.087716
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.638164	-97.098067
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.670955	-97.06645
35'	5	WOOD	Bartlett	Salty	3	2005	PRI	30.617351	-97.106775
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.671272	-97.042554
35'	6	WOOD	Bartlett	Salty	3	1983	PRI	30.636356	-97.041412
35'	6	WOOD	Bartlett	Salty	3	1995	PRI	30.603452	-97.09135
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.635904	-97.060415
35'	6	WOOD	Bartlett	Salty	3	1994	SEC	30.639	-97.035241
35'	6	WOOD	Bartlett	Salty	3	1999	PRI	30.664729	-97.072649
35'	6	WOOD	Bartlett	Salty	3	1999	PRI	30.658477	-97.082095
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.705707	-97.109304
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.699335	-97.178533
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.707947	-97.140147
35'	6	WOOD	Bartlett	Salty	3	2000	PRI	30.631023	-97.046529
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.638462	-97.034246
35'	5	WOOD	Bartlett	Salty	3	2006	PRI	30.700711	-97.154934
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.639995	-97.049803
35'	5	WOOD	Bartlett	Salty	3	1979	PRI	30.642257	-97.132346
35'	6	WOOD	Bartlett	Salty	3	1983	PRI	30.648609	-97.072297
35'	6	WOOD	Bartlett	Salty	3	1984	PRI	30.635086	-97.037404
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.644658	-97.054987
35'	5	WOOD	Bartlett	Salty	3	1978	PRI	30.643825	-97.126339
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.628616	-97.110493
35'	5	WOOD	Bartlett	Salty	3	1990	PRI	30.633947	-97.039934
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.70226	-97.146116

35'	5	WOOD	Bartlett	Salty	3	1994	PRI	30.615175	-97.099751
35'	6	WOOD	Bartlett	Salty	3	2003	PRI	30.637287	-97.033381
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.622939	-97.114593
35'	6	WOOD	Bartlett	Salty	3	2000	PRI	30.631066	-97.046934
35'	5	WOOD	Bartlett	Salty	3	2003	PRI	30.670946	-97.112167
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.662753	-97.056696
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.637554	-97.036836
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.646619	-97.081078
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.624204	-97.087063
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.652037	-97.172507
35'	6	WOOD	Bartlett	Salty	3	1999	PRI	30.664381	-97.075818
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.65128	-97.063747
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.677171	-97.043513
35'	6	WOOD	Bartlett	Salty	3	1999	PRI	30.607472	-97.087909
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.708569	-97.158227
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.673364	-97.046268
35'	5	WOOD	Bartlett	Salty	3	2001	PRI	30.637163	-97.082154
35'	5	WOOD	Bartlett	Salty	3	2003	PRI	30.620892	-97.107782
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.698791	-97.17855
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.640303	-97.037453
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.638206	-97.032835
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.637702	-97.095164
35'	6	WOOD	Bartlett	Salty	3	1995	PRI	30.642092	-97.115295
35'	6	WOOD	Bartlett	Salty	3	1995	PRI	30.603148	-97.092114
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.696733	-97.106786
35'	6	WOOD	Bartlett	Salty	3	2003	PRI	30.636917	-97.061302
35'	5	WOOD	Bartlett	Salty	3	1947	PRI	30.632345	-97.043731
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.650678	-97.068018
35'	5	WOOD	Bartlett	Salty	3	2006	PRI	30.699844	-97.154583
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.641718	-97.140239
35'	5	WOOD	Bartlett	Salty	3	2001	PRI	30.619709	-97.087477
35'	5	WOOD	Bartlett	Salty	3	2006	PRI	30.685277	-97.064503
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.676327	-97.044329

35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.634382	-97.102954
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.682259	-97.066498
35'	5	WOOD	Bartlett	Salty	3	2004	PRI	30.666929	-97.058929
35'	5	WOOD	Bartlett	Salty	3	2009	PRI	30.706382	-97.16135
35'	6	WOOD	Bartlett	Salty	3	1965	SEC	30.637089	-97.061383
35'	5	WOOD	Bartlett	Salty	3	1978	PRI	30.635985	-97.031235
35'	6	WOOD	Bartlett	Salty	3	2002	PRI	30.639679	-97.050767
35'	5	WOOD	Bartlett	Salty	3	2008	PRI	30.675298	-97.129376
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.670613	-97.187031
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.688988	-97.090824
35'	4	WOOD	Bartlett	Salty	3	2010	PRI	30.623561	-97.099227
35'	6	WOOD	Bartlett	Salty	3	2003	PRI	30.626492	-97.047584
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.638081	-97.037087
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.668107	-97.157948
35'	5	WOOD	Bartlett	Salty	3	1980	PRI	30.689656	-97.090444
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.670096	-97.129491
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.667125	-97.188176
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.670202	-97.188364
35'	5	WOOD	Bartlett	Salty	3	2003	PRI	30.629056	-97.099174
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.650105	-97.074976
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.647591	-97.108012
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.630378	-97.038967
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.603281	-97.116346
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.631823	-97.104055
35'	6	WOOD	Bartlett	Salty	3	1982	PRI	30.638316	-97.06864
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.675874	-97.041125
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.630302	-97.0441
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.640086	-97.036607
35'	6	WOOD	Bartlett	Salty	3	1996	PRI	30.611668	-97.080695
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.609251	-97.113013
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.68911	-97.127334
35'	6	WOOD	Bartlett	Salty	3	2001	SEC	30.633061	-97.039843
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.647468	-97.183462

35'	5	WOOD	Bartlett	Salty	3	2001	SEC	30.636987	-97.081993
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.670365	-97.187839
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.700127	-97.149097
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.651256	-97.11912
35'	6	WOOD	Bartlett	Salty	3	1999	SEC	30.637034	-97.040315
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.694319	-97.091775
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.634825	-97.034938
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.688102	-97.065109
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.676075	-97.150456
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.706259	-97.138844
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.705554	-97.141291
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.630414	-97.045685
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.64322	-97.129254
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.648971	-97.070351
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.636889	-97.092497
35'	6	WOOD	Bartlett	Salty	3	1970	PRI	30.663922	-97.161916
35'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.632307	-97.03681
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.667196	-97.189589
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.641591	-97.076234
35'	6	WOOD	Bartlett	Salty	3	1971	PRI	30.649891	-97.167164
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.647783	-97.126451
35'	6	WOOD	Bartlett	Salty	3	1996	PRI	30.640017	-97.077802
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.690825	-97.118006
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.631024	-97.13118
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.709561	-97.140792
35'	6	WOOD	Bartlett	Salty	3	1996	PRI	30.660965	-97.096225
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.64127	-97.041392
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.636213	-97.03825
35'	5	WOOD	Bartlett	Salty	3	1978	PRI	30.614418	-97.083279
35'	6	WOOD	Bartlett	Salty	3	1979	PRI	30.691157	-97.115858
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.638288	-97.098838
35'	6	WOOD	Bartlett	Salty	3	1993	SEC	30.638145	-97.037712
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.69405	-97.114299

35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.675357	-97.039684
35'	6	WOOD	Bartlett	Salty	3	1996	PRI	30.64089	-97.078027
35'	5	WOOD	Bartlett	Salty	3	UNK	SEC	30.606638	-97.08895
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.650662	-97.074858
35'	5	WOOD	Bartlett	Salty	3	2001	PRI	30.675768	-97.065363
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.698675	-97.114699
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.644437	-97.173353
35'	6	WOOD	Bartlett	Salty	3	1997	PRI	30.631962	-97.087463
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.701627	-97.111083
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.631686	-97.035852
35'	5	WOOD	Bartlett	Salty	3	2007	PRI	30.697911	-97.178891
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.675279	-97.044332
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.616812	-97.110271
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.706158	-97.163017
35'	5	WOOD	Bartlett	Salty	3	2006	PRI	30.696427	-97.154012
35'	6	WOOD	Bartlett	Salty	3	1993	PRI	30.667122	-97.157158
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.639024	-97.075836
35'	6	WOOD	Bartlett	Salty	3	2003	PRI	30.636305	-97.060951
35'	6	WOOD	Bartlett	Salty	3	1970	PRI	30.65145	-97.067142
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.644701	-97.05543
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.630729	-97.130456
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.624526	-97.086067
35'	6	WOOD	Bartlett	Salty	3	1997	PRI	30.705725	-97.169109
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.653361	-97.054374
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.672029	-97.067106
35'	5	WOOD	Bartlett	Salty	3	2005	SEC	30.616448	-97.103948
35'	6	WOOD	Bartlett	Salty	3	1974	PRI	30.601905	-97.127858
35'	5	WOOD	Bartlett	Salty	3	2005	PRI	30.685992	-97.141673
35'	7	WOOD	Bartlett	Salty	3	UNK	PRI	30.669933	-97.074428
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.62262	-97.10608
35'	5	WOOD	Bartlett	Salty	3	2004	PRI	30.69258	-97.141317
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.630058	-97.104533
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.708945	-97.144874

35'	5	WOOD	Bartlett	Salty	3	2008	PRI	30.660881	-97.090187
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.647218	-97.127417
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.641481	-97.042188
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.634467	-97.078787
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.634217	-97.048913
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.678037	-97.045485
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.661508	-97.082595
35'	6	WOOD	Bartlett	Salty	3	2003	PRI	30.660221	-97.060967
35'	7	WOOD	Bartlett	Salty	3	1950	PRI	30.609335	-97.092909
35'	5	WOOD	Bartlett	Salty		UNK	PRI	30.703407	-97.157168
35'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.70232	-97.175087
35'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.70258	-97.175032
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.648744	-97.094323
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.666297	-97.171705
35'	6	WOOD	Bartlett	Salty	3	2003	PRI	30.625915	-97.047878
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.648261	-97.063561
35'	6	WOOD	Bartlett	Salty	3	1977	PRI	30.637587	-97.04897
35'	5	WOOD	Bartlett	Salty	3	2005	PRI	30.670789	-97.067176
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.626463	-97.077952
35'	5	WOOD	Bartlett	Salty	1	UNK	PRI	30.694309	-97.056257
35'	5	WOOD	Bartlett	Salty	3	UNK	GUY	30.63897	-97.047912
35'	6	WOOD	Bartlett	Salty	3	2001	SEC	30.63633	-97.082955
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.649115	-97.054437
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.63377	-97.039862
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.647843	-97.127631
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.673058	-97.047318
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.629523	-97.107271
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.623881	-97.08585
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.661659	-97.056516
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.670024	-97.039871
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.677557	-97.044548
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.63679	-97.040329
35'	5	WOOD	Bartlett	Salty	3	2006	GUY	30.661441	-97.160782

35'	5	WOOD	Bartlett	Salty	3	2008	PRI	30.689759	-97.124261
35'	6	WOOD	Bartlett	Salty	3	1987	PRI	30.64086	-97.08692
35'	6	WOOD	Bartlett	Salty	3	1993	PRI	30.640917	-97.040021
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.654009	-97.057702
35'	7	WOOD	Bartlett	Salty	3	UNK	PRI	30.616088	-97.103635
35'	5	WOOD	Bartlett	Salty	3	2003	PRI	30.627179	-97.04723
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.64373	-97.127788
35'	6	WOOD	Bartlett	Salty	3	2003	PRI	30.624721	-97.048471
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.629095	-97.108392
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.62466	-97.100867
35'	5	WOOD	Bartlett	Salty	3	2006	PRI	30.671744	-97.06614
35'	5	WOOD	Bartlett	Salty	3	1985	PRI	30.643035	-97.127737
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.642401	-97.13155
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.64287	-97.170369
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.66372	-97.078774
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.63289	-97.135153
35'	7	WOOD	Bartlett	Salty	3	UNK	PRI	30.611958	-97.094597
35'	5	WOOD	Bartlett	Salty	3	2008	PRI	30.693217	-97.125624
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.67061	-97.066586
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.677954	-97.102914
35'	5	WOOD	Bartlett	Salty	3	2005	SEC	30.688215	-97.141494
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.632233	-97.039186
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.678381	-97.045422
35'	6	WOOD	Bartlett	Salty	3	1964	PRI	30.645178	-97.131878
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.666233	-97.063405
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.630134	-97.130801
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.652271	-97.173267
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.63507	-97.03415
35'	5	WOOD	Bartlett	Salty	3	2008	PRI	30.661525	-97.090552
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.635222	-97.040815
35'	6	WOOD	Bartlett	Salty	3	1999	PRI	30.645425	-97.09747
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.628691	-97.133721
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.643222	-97.130095

35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.666411	-97.05142
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.613903	-97.112519
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.700232	-97.114212
35'	6	WOOD	Bartlett	Salty	3	2003	PRI	30.645747	-97.130104
35'	6	WOOD	Bartlett	Salty	3	1996	PRI	30.607189	-97.083979
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.654061	-97.077833
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.601849	-97.126761
35'	5	WOOD	Bartlett	Salty	3	2005	PRI	30.705897	-97.109273
35'	6	WOOD	Bartlett	Salty	3	1987	PRI	30.637846	-97.096035
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.701502	-97.179759
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.64259	-97.126987
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.634248	-97.036785
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.62564	-97.102508
35'	6	WOOD	Bartlett	Salty	3	1946	PRI	30.643396	-97.081073
35'	5	WOOD	Bartlett	Salty	3	2001	PRI	30.636868	-97.082864
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.651291	-97.093759
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.626826	-97.078977
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.678918	-97.045324
35'	6	WOOD	Bartlett	Salty	3	1990	PRI	30.631299	-97.082987
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.649943	-97.094052
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.670416	-97.127602
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.689681	-97.128149
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.625473	-97.103589
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.691011	-97.116929
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.612444	-97.108133
35'	5	WOOD	Bartlett	Salty	3	2004	PRI	30.705415	-97.166975
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.670445	-97.11416
35'	6	WOOD	Bartlett	Salty	3	1995	PRI	30.610638	-97.080461
35'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.633423	-97.03636
35'	6	WOOD	Bartlett	Salty	3	1990	PRI	30.631291	-97.088093
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.639239	-97.050567
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.650304	-97.167759
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.660605	-97.094762

35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.649893	-97.07397
35'	6	WOOD	Bartlett	Salty	3	1996	SEC	30.635742	-97.048259
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.694773	-97.09215
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.612791	-97.111248
35'	6	WOOD	Bartlett	Salty	3	1995	PRI	30.603842	-97.085798
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.635742	-97.050301
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.670968	-97.069719
35'	6	WOOD	Bartlett	Salty	3	2003	PRI	30.637113	-97.061994
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.703194	-97.142387
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.653392	-97.077207
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.652237	-97.075417
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.625302	-97.102884
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.632367	-97.036155
35'	6	WOOD	Bartlett	Salty	3	1975	PRI	30.632015	-97.043026
35'	6	WOOD	Bartlett	Salty	3	2001	SEC	30.669651	-97.076017
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.636178	-97.045382
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.639669	-97.048991
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.664824	-97.061618
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.653667	-97.075928
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.661968	-97.170962
35'	6	WOOD	Bartlett	Salty	3	1959	PRI	30.664806	-97.062613
35'	6	WOOD	Bartlett	Salty	3	1988	PRI	30.622519	-97.105287
35'	4	WOOD	Bartlett	Salty	3	2003	PRI	30.622588	-97.113346
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.641689	-97.101516
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.633276	-97.035914
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.643298	-97.025045
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.66936	-97.188359
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.688989	-97.128398
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.695855	-97.114639
35'	6	WOOD	Bartlett	Salty	3	2000	PRI	30.636257	-97.049719
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.624192	-97.101689
35'	5	WOOD	Bartlett	Salty	3	2007	PRI	30.706062	-97.12947
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.653507	-97.067775

35'	6	WOOD	Bartlett	Salty	3	1978	PRI	30.617031	-97.08789
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.638183	-97.036814
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.667506	-97.186952
35'	6	WOOD	Bartlett	Salty	3	1986	PRI	30.697262	-97.178598
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.631295	-97.104275
35'	7	WOOD	Bartlett	Salty	3	UNK	SEC	30.634118	-97.037199
35'	5	WOOD	Bartlett	Salty	3	2006	PRI	30.65801	-97.169838
35'	5	WOOD	Bartlett	Salty	3	2008	PRI	30.69947	-97.11445
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.67234	-97.12567
35'	6	WOOD	Bartlett	Salty	3	1999	PRI	30.665362	-97.071889
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.65279	-97.058442
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.622338	-97.112778
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.63704	-97.036586
35'	5	WOOD	Bartlett	Salty	3	2004	PRI	30.641615	-97.061086
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.650975	-97.071173
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.652062	-97.155166
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.641627	-97.126596
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.689681	-97.124233
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.666744	-97.18939
35'	6	WOOD	Bartlett	Salty	3	2003	PRI	30.673855	-97.125661
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.642652	-97.08394
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.688922	-97.128392
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.68784	-97.143959
35'	5	WOOD	Bartlett	Salty	3	UNK	SEC	30.631929	-97.039617
35'	6	WOOD	Bartlett	Salty	3	1996	PRI	30.641862	-97.078229
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.677432	-97.048881
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.685138	-97.140804
35'	5	WOOD	Bartlett	Salty	3	2008	PRI	30.692504	-97.125235
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.640231	-97.04913
35'	6	WOOD	Bartlett	Salty	3	1999	PRI	30.609807	-97.086856
35'	6	WOOD	Bartlett	Salty	3	2000	PRI	30.645991	-97.082736
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.636934	-97.047383
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.695073	-97.096864

35'	6	WOOD	Bartlett	Salty	3	2003	PRI	30.625353	-97.048158
35'	6	WOOD	Bartlett	Salty	3	1998	SEC	30.634192	-97.040376
35'	6	WOOD	Bartlett	Salty	3	1998	SEC	30.643908	-97.12716
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.614031	-97.098542
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.633661	-97.036689
35'	5	WOOD	Bartlett	Salty	3	2005	PRI	30.707673	-97.11128
35'	5	WOOD	Bartlett	Salty	3	2005	PRI	30.64818	-97.07666
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.640797	-97.049825
35'	5	WOOD	Bartlett	Salty	3	2006	PRI	30.658066	-97.169328
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.605327	-97.087856
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.628048	-97.087643
35'	5	WOOD	Bartlett	Salty	3	1994	PRI	30.641096	-97.040691
35'	5	WOOD	Bartlett	Salty	3	2004	PRI	30.667371	-97.059155
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.666997	-97.171998
35'	5	WOOD	Bartlett	Salty	3	2005	PRI	30.648325	-97.075553
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.677248	-97.125913
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.63672	-97.05997
35'	6	WOOD	Bartlett	Salty	3	1996	PRI	30.670918	-97.177933
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.650876	-97.071987
35'	5	WOOD	Bartlett	Salty	3	2006	PRI	30.686837	-97.139127
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.704158	-97.110426
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.66485	-97.060634
35'	5	WOOD	Bartlett	Salty	3	2003	PRI	30.669593	-97.187635
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.629682	-97.045639
35'	5	WOOD	Bartlett	Salty	3	2004	PRI	30.673591	-97.069208
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.673758	-97.046006
35'	6	WOOD	Bartlett	Salty	3	1996	PRI	30.640605	-97.112578
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.670025	-97.041091
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.631112	-97.037648
35'	6	WOOD	Bartlett	Salty	3	1982	PRI	30.63349	-97.037277
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.650807	-97.055053
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.603689	-97.115043
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.696104	-97.114052

35'	5	WOOD	Bartlett	Salty	3	2006	PRI	30.686977	-97.139197
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.629399	-97.130721
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.632932	-97.036985
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.69026	-97.121095
35'	6	WOOD	Bartlett	Salty	3	1998	SEC	30.623082	-97.114681
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.617301	-97.106648
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.652859	-97.120157
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.637493	-97.046168
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.685369	-97.145334
35'	6	WOOD	Bartlett	Salty	3	1999	PRI	30.610325	-97.086662
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.63107	-97.039339
35'	5	WOOD	Bartlett	Salty	3	2004	PRI	30.67305	-97.06968
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.668845	-97.185422
35'	5	WOOD	Bartlett	Salty	3	2003	PRI	30.69538	-97.176953
35'	6	WOOD	Bartlett	Salty	3	2000	SEC	30.649981	-97.05224
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.652357	-97.093539
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.636152	-97.049218
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.644758	-97.05588
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.635775	-97.102357
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.649296	-97.073196
35'	6	WOOD	Bartlett	Salty	3	1979	PRI	30.654482	-97.058681
35'	6	WOOD	Bartlett	Salty	3	1983	PRI	30.646701	-97.12836
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.669409	-97.048829
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.640495	-97.038285
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.634205	-97.036912
35'	6	WOOD	Bartlett	Salty		1990	PRI	30.688505	-97.064323
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.605388	-97.119833
35'	5	WOOD	Bartlett	Salty	3	2006	PRI	30.697325	-97.154481
35'	6	WOOD	Bartlett	Salty	3	1996	PRI	30.634771	-97.039973
35'	4	WOOD	Bartlett	Salty	3	2016	PRI	30.697483	-97.110754
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.696728	-97.114805
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.667785	-97.18606
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.62659	-97.075691

35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.641827	-97.114206
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.687781	-97.11855
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.676934	-97.150114
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.637687	-97.083123
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.670396	-97.043462
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.634005	-97.039157
35'	6	WOOD	Bartlett	Salty	3	1995	PRI	30.605622	-97.085077
35'	6	WOOD	Bartlett	Salty	3	2001	SEC	30.649985	-97.075131
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.6661	-97.159425
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.706096	-97.13941
35'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.630539	-97.045445
35'	6	WOOD	Bartlett	Salty	3	1983	PRI	30.635321	-97.040527
35'	6	WOOD	Bartlett	Salty	3	1996	PRI	30.647	-97.095979
35'	6	WOOD	Bartlett	Salty	3	2002	PRI	30.643647	-97.082908
35'	6	WOOD	Bartlett	Salty	3	1983	PRI	30.628414	-97.131095
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.67528	-97.045016
35'	6	WOOD	Bartlett	Salty	3	1998	GUY	30.710235	-97.145244
35'	5	WOOD	Bartlett	Salty	3	2006	PRI	30.701582	-97.155284
35'	5	WOOD	Bartlett	Salty	3	2001	SEC	30.637634	-97.049229
35'	5	WOOD	Bartlett	Salty	3	2006	PRI	30.702444	-97.155636
35'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.635412	-97.047987
35'	5	WOOD	Bartlett	Salty	3	2005	PRI	30.706712	-97.10988
35'	6	WOOD	Bartlett	Salty	3	2003	PRI	30.62941	-97.046347
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.690068	-97.122133
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.66791	-97.156855
35'	5	WOOD	Bartlett	Salty	3	1974	PRI	30.639263	-97.030654
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.700798	-97.111016
35'	6	WOOD	Bartlett	Salty	3	2000	PRI	30.607175	-97.091016
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.668094	-97.185137
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.637552	-97.101607
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.642338	-97.116331
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.688736	-97.090156
35'	6	WOOD	Bartlett	Salty	3	1992	PRI	30.631024	-97.046993

35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.635627	-97.032377
35'	6	WOOD	Bartlett	Salty	3	2002	PRI	30.643991	-97.08289
35'	6	WOOD	Bartlett	Salty	3	1983	PRI	30.635968	-97.040795
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.689633	-97.128436
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.669611	-97.185732
35'	5	WOOD	Bartlett	Salty	3	2005	PRI	30.708626	-97.164061
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.650073	-97.166176
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.62211	-97.085747
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.607563	-97.090984
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.639456	-97.088507
35'	6	WOOD	Bartlett	Salty	3	1995	PRI	30.64293	-97.117623
35'	6	WOOD	Bartlett	Salty	3	1999	PRI	30.657439	-97.081689
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.631841	-97.047343
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.628525	-97.111121
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.666835	-97.086246
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.648886	-97.070858
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.700147	-97.178502
35'	5	WOOD	Bartlett	Salty	3	1995	PRI	30.608525	-97.083818
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.638089	-97.050309
35'	5	WOOD	Bartlett	Salty	3	2008	PRI	30.660192	-97.089799
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.65258	-97.172736
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.643793	-97.083586
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.670854	-97.186266
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.702922	-97.143621
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.606603	-97.088832
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.689879	-97.123163
35'	5	WOOD	Bartlett	Salty	3	2004	PRI	30.66997	-97.186446
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.649887	-97.065727
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.638106	-97.035218
35'	6	WOOD	Bartlett	Salty	3	1997	SEC	30.621156	-97.106398
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.641843	-97.085803
35'	6	WOOD	Bartlett	Salty	3	1999	PRI	30.645856	-97.098047
35'	6	WOOD	Bartlett	Salty	3	1993	PRI	30.649849	-97.165419

35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.650322	-97.053716
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.679363	-97.120581
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.641762	-97.077486
35'	6	WOOD	Bartlett	Salty	3	1999	SEC	30.635152	-97.041059
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.629477	-97.103204
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.637992	-97.090166
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.633104	-97.036459
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.687567	-97.06465
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.675353	-97.040502
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.676942	-97.0424
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.630997	-97.038294
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.628976	-97.132671
35'	5	WOOD	Bartlett	Salty	3	1978	PRI	30.64278	-97.131785
35'	5	WOOD	Bartlett	Salty	3	2005	SEC	30.670637	-97.06725
35'	5	WOOD	Bartlett	Salty	3	2008	PRI	30.661875	-97.091461
35'	5	WOOD	Bartlett	Salty	3	1980	PRI	30.631117	-97.044664
35'	5	WOOD	Bartlett	Salty	3	2006	PRI	30.69801	-97.153842
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.629113	-97.081538
35'	5	WOOD	Bartlett	Salty	3	2003	PRI	30.646351	-97.098723
35'	6	WOOD	Bartlett	Salty	3	1993	PRI	30.640696	-97.039094
35'	5	WOOD	Bartlett	Salty	3	2008	PRI	30.678991	-97.044988
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.694958	-97.114471
35'	6	WOOD	Bartlett	Salty	3	1988	PRI	30.651448	-97.075134
35'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.649684	-97.065893
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.648332	-97.167936
35'	6	WOOD	Bartlett	Salty	3	1997	PRI	30.6117	-97.081501
35'	5	WOOD	Bartlett	Salty	3	1978	PRI	30.614947	-97.083468
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.689849	-97.116018
35'	5	WOOD	Bartlett	Salty	3	1995	PRI	30.603858	-97.090336
35'	5	WOOD	Bartlett	Salty	3	1980	PRI	30.636908	-97.033709
35'	5	WOOD	Bartlett	Salty	3	2008	PRI	30.691692	-97.124775
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.689529	-97.066227
35'	5	WOOD	Bartlett	Salty	3	UNK	SEC	30.617762	-97.084227

35'	6	WOOD	Bartlett	Salty	3	1999	PRI	30.608363	-97.087499
35'	5	WOOD	Bartlett	Salty	3	2006	PRI	30.703309	-97.155983
35'	5	WOOD	Bartlett	Salty	3	2005	PRI	30.707791	-97.163709
35'	5	WOOD	Bartlett	Salty	3	2005	PRI	30.70751	-97.110473
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.609503	-97.113718
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.628815	-97.109531
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.669463	-97.188058
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.647885	-97.05517
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.638701	-97.035337
35'	5	WOOD	Bartlett	Salty	3	2004	SEC	30.623494	-97.099468
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.69997	-97.110951
35'	6	WOOD	Bartlett	Salty	3	1996	PRI	30.658992	-97.169719
35'	5	WOOD	Bartlett	Salty	3	1982	PRI	30.650389	-97.064749
35'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.636974	-97.033872
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.634846	-97.049934
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.626262	-97.086328
35'	6	WOOD	Bartlett	Salty	3	1987	PRI	30.638499	-97.089599
35'	5	WOOD	Bartlett	Salty	3	1994	PRI	30.644583	-97.046889
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.641311	-97.114503
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.66099	-97.170556
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.630075	-97.099433
35'	6	WOOD	Bartlett	Salty	3	1997	PRI	30.686838	-97.090924
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.641683	-97.082022
35'	5	WOOD	Bartlett	Salty	3	1994	PRI	30.667661	-97.049959
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.643542	-97.127376
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.612071	-97.111155
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.696877	-97.107941
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.649014	-97.063626
35'	6	WOOD	Bartlett	Salty	3	1995	PRI	30.689604	-97.117029
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.647654	-97.128327
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.667793	-97.173127
35'	6	WOOD	Bartlett	Salty	3	1999	PRI	30.605686	-97.088356
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.652606	-97.174313

35'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.641478	-97.081991
35'	6	WOOD	Bartlett	Salty	3	2003	PRI	30.675889	-97.040793
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.672466	-97.14689
35'	5	WOOD	Bartlett	Salty	3	1980	PRI	30.629662	-97.043882
35'	5	WOOD	Bartlett	Salty	3	1995	PRI	30.610105	-97.081367
35'	7	WOOD	Bartlett	Salty	3	UNK	PRI	30.602565	-97.127619
35'	6	WOOD	Bartlett	Salty	3	1983	PRI	30.632443	-97.037449
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.707008	-97.139775
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.675298	-97.122683
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.648818	-97.071171
35'	6	WOOD	Bartlett	Salty	3	1999	PRI	30.609264	-97.087044
35'	6	WOOD	Bartlett	Salty	3	1987	PRI	30.641324	-97.086392
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.67278	-97.125225
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.652928	-97.175325
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.652869	-97.076959
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.643149	-97.145284
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.641614	-97.115594
35'	5	WOOD	Bartlett	Salty	3	2006	PRI	30.690906	-97.089276
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.627944	-97.093257
35'	5	WOOD	Bartlett	Salty	3	2004	PRI	30.705951	-97.167121
35'	4	WOOD	Bartlett	Salty	3	2003	PRI	30.667795	-97.187783
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.670413	-97.06557
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.644513	-97.053157
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.660069	-97.056609
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.705752	-97.164586
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.673165	-97.124837
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.680949	-97.120016
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.636251	-97.048699
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.708785	-97.144804
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.705331	-97.167577
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.650149	-97.172593
35'	7	WOOD	Bartlett	Salty	3	UNK	PRI	30.616955	-97.105783
35'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.646829	-97.078535

35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.690637	-97.119012
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.666931	-97.188792
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.671706	-97.12631
35'	6	WOOD	Bartlett	Salty	3	1996	PRI	30.641773	-97.078255
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.633385	-97.036577
35'	6	WOOD	Bartlett	Salty	3	1996	PRI	30.660012	-97.170144
35'	5	WOOD	Bartlett	Salty	3	2006	PRI	30.669597	-97.148864
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.67221	-97.043096
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.643803	-97.133756
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.622701	-97.104696
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.664867	-97.059663
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.680352	-97.103794
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.621695	-97.11293
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.66943	-97.075924
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.674657	-97.045427
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.668555	-97.078518
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.633081	-97.039556
35'	5	WOOD	Bartlett	Salty	3	1998	PRI	30.629074	-97.116896
35'	6	WOOD	Bartlett	Salty	3	1998	SEC	30.638407	-97.049987
35'	5	WOOD	Bartlett	Salty	3	2005	PRI	30.686627	-97.142359
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.695415	-97.177743
35'	5	WOOD	Bartlett	Salty	3	2003	PRI	30.706978	-97.163364
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.6382	-97.036134
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.632279	-97.039043
35'	5	WOOD	Bartlett	Salty	3	2008	PRI	30.696954	-97.111923
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.634292	-97.040086
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.649634	-97.177576
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.670085	-97.188749
35'	6	WOOD	Bartlett	Salty	3	1992	PRI	30.603469	-97.128394
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.668851	-97.188141
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.632562	-97.036823
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.676405	-97.041754
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.671282	-97.068743

35'	6	WOOD	Bartlett	Salty	3	1993	PRI	30.637957	-97.037567
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.690433	-97.120118
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.646469	-97.128793
35'	6	WOOD	Bartlett	Salty	3	1995	PRI	30.627593	-97.091123
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.647845	-97.10874
35'	5	WOOD	Bartlett	Salty	3	2006	PRI	30.668923	-97.186298
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.631532	-97.037806
35'	6	WOOD	Bartlett	Salty	3	1995	PRI	30.671255	-97.06748
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.6906	-97.127834
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.637852	-97.033987
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.675344	-97.14894
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.642229	-97.085367
35'	6	WOOD	Bartlett	Salty	3	1974	PRI	30.647953	-97.095072
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.642346	-97.140236
35'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.703924	-97.142134
35'	5	WOOD	Bartlett	Salty	3	2008	PRI	30.675278	-97.129909
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.670128	-97.185944
35'	6	WOOD	Bartlett	Salty	3	1999	PRI	30.659067	-97.082096
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.636443	-97.082723
35'	6	WOOD	Bartlett	Salty	3	1996	PRI	30.667871	-97.173888
35'	4	WOOD	Bartlett	Salty	3	2003	PRI	30.623073	-97.112639
35'	6	WOOD	Bartlett	Salty	3	1993	PRI	30.642678	-97.116448
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.66565	-97.172349
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.648001	-97.081076
35'	6	WOOD	Bartlett	Salty	3	2000	PRI	30.652338	-97.12281
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.640906	-97.114716
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.650753	-97.076328
35'	6	WOOD	Bartlett	Salty	3	1997	PRI	30.631399	-97.087397
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.638404	-97.099564
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.638131	-97.047363
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.648163	-97.074512
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.706869	-97.157489
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.634647	-97.05058

35'	6	WOOD	Bartlett	Salty	3	1987	GUY	30.702343	-97.177514
35'	6	WOOD	Bartlett	Salty	3	1996	PRI	30.660779	-97.095487
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.657953	-97.057523
35'	5	WOOD	Bartlett	Salty	3	2005	PRI	30.648413	-97.074448
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.667493	-97.084911
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.685136	-97.062073
35'	5	WOOD	Bartlett	Salty	3	UNK	SEC	30.632275	-97.038278
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.670717	-97.068842
35'	6	WOOD	Bartlett	Salty	3	2001	PRI	30.647451	-97.12904
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.651009	-97.122307
35'	5	WOOD	Bartlett	Salty	3	UNK	SEC	30.703203	-97.143556
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.626449	-97.076792
35'	6	WOOD	Bartlett	Salty	3	1994	PRI	30.650518	-97.063757
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.650775	-97.072821
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.706751	-97.137104
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.618127	-97.088188
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.63386	-97.081799
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.601589	-97.127974
35'	6	WOOD	Bartlett	Salty	3	2001	SEC	30.678451	-97.04523
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.667704	-97.172291
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.63572	-97.048037
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.635726	-97.040698
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.637501	-97.035097
35'	5	WOOD	Bartlett	Salty	3	2003	PRI	30.620627	-97.107156
35'	6	WOOD	Bartlett	Salty	3	1985	PRI	30.694804	-97.17805
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.633896	-97.044823
35'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.701009	-97.177764
35'	6	WOOD	Bartlett	Salty	3	1995	PRI	30.608694	-97.082716
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.632945	-97.043418
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.63575	-97.089282
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.644162	-97.128499
35'	5	WOOD	Bartlett	Salty	3	UNK	PRI	30.649068	-97.173069
35'	6	WOOD	Bartlett	Salty	3	2003	PRI	30.628016	-97.046894

35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.660661	-97.05636
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.65201	-97.170891
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.628952	-97.045594
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.622962	-97.08554
35'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.625758	-97.102575
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.633801	-97.050347
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.645827	-97.101679
35'	6	WOOD	Bartlett	Salty	3	1993	PRI	30.639246	-97.033487
35'	5	WOOD	Bartlett	Salty	3	2004	PRI	30.706519	-97.16727
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.635814	-97.089655
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.652159	-97.059894
35'	6	WOOD	Bartlett	Salty	3	2002	PRI	30.630871	-97.103504
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.637132	-97.036249
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.653531	-97.076559
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.626729	-97.074599
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.638409	-97.0502
35'	6	WOOD	Bartlett	Salty	3	1974	PRI	30.631629	-97.102965
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.669242	-97.039257
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.670983	-97.071335
35'	6	WOOD	Bartlett	Salty	3	2003	PRI	30.624279	-97.048802
35'	6	WOOD	Bartlett	Salty	3	1995	PRI	30.689822	-97.115331
35'	6	WOOD	Bartlett	Salty	3	1998	SEC	30.650055	-97.172385
35'	6	WOOD	Bartlett	Salty	3	1993	PRI	30.650739	-97.168423
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.650899	-97.063527
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.64119	-97.275225
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.49406	-97.121665
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.47746	-97.137919
35'	6	WOOD	Bartlett	Salty	1	1998	PRI	30.492519	-97.090786
35'	5	WOOD	Bartlett	Salty	1	2001	PRI	30.541589	-97.048933
35'	5	WOOD	Bartlett	Thorndale	1	1998	SEC	30.605105	-97.259419
35'	6	WOOD	Bartlett	Salty	3	UNK	SEC	30.625266	-97.171248
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.484316	-97.140148
35'	6	WOOD	Bartlett	Salty	1	1996	PRI	30.504317	-97.171995

35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.554835	-97.095435
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.517107	-97.120895
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.585236	-97.127071
35'	6	WOOD	Bartlett	Salty	1	1946	PRI	30.566001	-97.097622
35'	6	WOOD	Bartlett	Salty	1	2003	PRI	30.589571	-97.150725
35'	6	WOOD	Bartlett	Salty	1	1997	PRI	30.5781	-97.104004
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.479283	-97.138465
35'	6	WOOD	Bartlett	Salty	1	2002	PRI	30.593039	-97.135478
35'	4	WOOD	Bartlett	Salty	1	UNK	SEC	30.553503	-97.090819
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.594699	-97.141481
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.573915	-97.126067
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.592958	-97.145974
35'	6	WOOD	Bartlett	Salty	1	1998	PRI	30.467346	-97.156194
35'	6	WOOD	Bartlett	Thorndale	1	1994	PRI	30.641754	-97.19063
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.623813	-97.173239
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.523396	-97.108514
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.489627	-97.121711
35'	6	WOOD	Bartlett	Thorndale	1	1995	PRI	30.621086	-97.226241
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.62324	-97.174581
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.520805	-97.171735
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.634024	-97.251862
35'	6	WOOD	Bartlett	Salty	1	2002	PRI	30.467567	-97.145789
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.528749	-97.045538
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.621679	-97.152209
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.52182	-97.112734
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.543478	-97.03882
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.522548	-97.110491
35'	6	WOOD	Bartlett	Salty	1	2003	PRI	30.503971	-97.173065
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.512499	-97.123266
35'	6	WOOD	Bartlett	Salty	1	1999	PRI	30.507369	-97.122116
35'	6	WOOD	Bartlett	Thorndale	1	2000	PRI	30.606315	-97.247903
35'	6	WOOD	Bartlett	Salty	1	1994	PRI	30.526339	-97.172963
35'	5	WOOD	Bartlett	Salty	1	2005	SEC	30.532325	-97.18039

35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.507226	-97.118883
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.50718	-97.114257
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.504717	-97.121817
35'	6	WOOD	Bartlett	Salty	1	1999	PRI	30.475239	-97.15534
35'	6	WOOD	Bartlett	Salty	1	2002	PRI	30.471259	-97.148378
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.509698	-97.113164
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.580173	-97.104325
35'	6	WOOD	Bartlett	Salty	1	2003	PRI	30.546057	-97.034883
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.531902	-97.080583
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.515201	-97.172999
35'	7	WOOD	Bartlett	Salty	3	UNK	PRI	30.624053	-97.16983
35'	6	WOOD	Bartlett	Salty	1	1985	PRI	30.526715	-97.173641
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.516348	-97.172654
35'	5	WOOD	Bartlett	Salty	1	2009	PRI	30.513175	-97.154806
35'	7	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.616401	-97.221007
35'	5	WOOD	Bartlett	Salty	1	2001	PRI	30.538885	-97.051863
35'	5	WOOD	Bartlett	Salty	1	1994	PRI	30.481403	-97.129647
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.498852	-97.119381
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.569849	-97.109456
35'	5	WOOD	Bartlett	Salty	1	2003	SEC	30.594785	-97.164397
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.645422	-97.195881
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.646513	-97.208643
35'	6	WOOD	Bartlett	Salty	1	1947	PRI	30.556185	-97.096198
35'	6	WOOD	Bartlett	Salty	1	1996	PRI	30.506923	-97.170665
35'	6	WOOD	Bartlett	Salty	1	1998	PRI	30.493602	-97.151242
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.597495	-97.117221
35'	6	WOOD	Bartlett	Salty	1	2001	PRI	30.511156	-97.173896
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.500428	-97.159277
35'	6	WOOD	Bartlett		1	UNK	PRI	30.619492	-97.21939
35'	6	WOOD	Bartlett	Thorndale	1	1998	PRI	30.625357	-97.251449
35'	6	WOOD	Bartlett	Salty	1	2003	PRI	30.546594	-97.034382
35'	7	WOOD	Bartlett	Salty	1	UNK	PRI	30.515337	-97.060077
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.532936	-97.083793

35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.625148	-97.169269
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.515534	-97.141393
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.611595	-97.236404
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.532252	-97.06236
35'	6	WOOD	Bartlett	Salty	1	2001	PRI	30.593748	-97.152123
35'	5	WOOD	Bartlett	Thorndale	1	2005	PRI	30.633563	-97.258811
35'	5	WOOD	Bartlett	Thorndale	1	2007	GUY	30.631616	-97.250245
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.540127	-97.044858
35'	6	WOOD	Bartlett	Salty	1	UNK	SEC	30.514921	-97.174143
35'	5	WOOD	Bartlett	Salty	1	2001	PRI	30.539553	-97.05113
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.499744	-97.161233
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.462287	-97.150722
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.524876	-97.105665
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.499917	-97.152882
35'	7	WOOD	Bartlett	Salty	1	UNK	PRI	30.515575	-97.06019
35'	6	WOOD	Bartlett	Salty	1	1946	PRI	30.582065	-97.127857
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.624117	-97.155299
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.579135	-97.104164
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.599848	-97.235849
35'	6	WOOD	Bartlett	Salty	1	UNK	SEC	30.594676	-97.141697
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.592447	-97.116473
35'	6	WOOD	Bartlett	Salty	1	UNK	SEC	30.521151	-97.170515
35'	6	WOOD	Bartlett	Salty	1	1996	SEC	30.518317	-97.172354
35'	6	WOOD	Bartlett	Thorndale	1	1999	PRI	30.646784	-97.201646
35'	7	WOOD	Bartlett	Salty	1	UNK	PRI	30.508466	-97.157935
35'	6	WOOD	Bartlett	Salty	1	1998	PRI	30.520648	-97.171075
35'	6	WOOD	Bartlett	Salty	1	1969	PRI	30.51321	-97.154701
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.610237	-97.231111
35'	6	WOOD	Bartlett	Thorndale	1	UNK	SEC	30.642142	-97.271115
35'	6	WOOD	Bartlett	Salty	3	1997	PRI	30.62656	-97.164514
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.5107	-97.122858
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.588588	-97.128475
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.513756	-97.164108

35'	6	WOOD	Bartlett	Thorndale	1	1998	PRI	30.638855	-97.272006
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.535727	-97.178753
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.518539	-97.12273
35'	5	WOOD	Bartlett	Thorndale	1	2005	PRI	30.633815	-97.25865
35'	6	WOOD	Bartlett	Salty	1	1997	PRI	30.603444	-97.159908
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.487342	-97.122576
35'	6	WOOD	Bartlett	Salty	1	2002	PRI	30.594754	-97.157154
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.571368	-97.102971
35'	6	WOOD	Bartlett	Salty	1	1998	PRI	30.466054	-97.152392
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.641	-97.213967
35'	6	WOOD	Bartlett	Salty	1	1998	PRI	30.508476	-97.124685
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.463158	-97.150625
35'	5	WOOD	Bartlett	Salty	1	2001	PRI	30.570301	-97.10411
35'	5	WOOD	Bartlett	Salty	1	2002	PRI	30.49304	-97.15312
35'	6	WOOD	Bartlett	Salty	1	2002	PRI	30.593549	-97.13551
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.472824	-97.145211
35'	6	WOOD	Bartlett	Salty	1	1997	PRI	30.51847	-97.173304
35'	6	WOOD	Bartlett	Salty	1	1999	PRI	30.567802	-97.103177
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.495688	-97.1213
35'	5	WOOD	Bartlett	Salty	1	2011	PRI	30.570276	-97.114353
35'	6	WOOD	Bartlett	Salty	1	1999	SEC	30.466893	-97.16007
35'	6	WOOD	Bartlett	Salty	1	2001	PRI	30.536878	-97.179943
35'	5	WOOD	Bartlett	Salty	1	1987	PRI	30.501503	-97.08092
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.520865	-97.115634
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.519352	-97.141434
35'	6	WOOD	Bartlett	Thorndale	1	1999	PRI	30.648332	-97.201028
35'	6	WOOD	Bartlett	Salty	1	1998	PRI	30.517411	-97.107083
35'	6	WOOD	Bartlett	Thorndale	1	2000	PRI	30.625947	-97.248177
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.55169	-97.103368
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.621613	-97.156823
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.507098	-97.120654
35'	6	WOOD	Bartlett	Thorndale	1	UNK	SEC	30.609726	-97.252714
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.48303	-97.125941

35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.471362	-97.150951
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.584299	-97.119945
35'	5	WOOD	Bartlett	Salty	1	2006	PRI	30.544103	-97.096847
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.547227	-97.173803
35'	6	WOOD	Bartlett	Salty	1	1998	SEC	30.513657	-97.129768
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.617071	-97.228875
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.645237	-97.212771
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.526963	-97.170843
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.522834	-97.070714
35'	6	WOOD	Bartlett	Salty	1	1998	PRI	30.466363	-97.15648
35'	6	WOOD	Bartlett	Salty	1	1994	PRI	30.593118	-97.151525
35'	6	WOOD	Bartlett	Salty	3	1998	PRI	30.623211	-97.153044
35'	5	WOOD	Bartlett	Salty	1	2006	PRI	30.542486	-97.038514
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.491403	-97.121694
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.581531	-97.104538
35'	6	WOOD	Bartlett	Salty	1	UNK	SEC	30.526669	-97.173969
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.539316	-97.183075
35'	6	WOOD	Bartlett	Salty	1	2001	PRI	30.491705	-97.148074
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.553327	-97.093403
35'	6	WOOD	Bartlett	Thorndale	1	2000	PRI	30.625474	-97.249067
35'	6	WOOD	Bartlett	Salty	3	2003	PRI	30.611219	-97.150658
35'	6	WOOD	Bartlett	Salty	1	1999	PRI	30.467829	-97.156047
35'	6	WOOD	Bartlett	Salty	1	1991	PRI	30.510628	-97.075833
35'	5	WOOD	Bartlett	Salty	1	2006	PRI	30.553628	-97.095325
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.490041	-97.142114
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.480149	-97.138727
35'	6	WOOD	Bartlett	Salty	1	2001	PRI	30.490074	-97.148961
35'	5	WOOD	Bartlett	Salty	1	UNK	PRI	30.485241	-97.139429
35'	6	WOOD	Bartlett	Thorndale	1	1999	PRI	30.627278	-97.249696
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.47431	-97.144281
35'	5	WOOD	Bartlett	Salty	1	UNK	PRI	30.600448	-97.116757
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.475053	-97.143818
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.633158	-97.255421

35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.584914	-97.12432
35'	6	WOOD	Bartlett	Salty	1	1996	PRI	30.511014	-97.165229
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.623187	-97.230138
35'	6	WOOD	Bartlett	Salty	1	UNK	SEC	30.570689	-97.110936
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.642406	-97.213831
35'	6	WOOD	Bartlett	Thorndale	1	1999	PRI	30.649173	-97.20171
35'	6	WOOD	Bartlett	Salty	1	1996	PRI	30.548091	-97.177545
35'	6	WOOD	Bartlett	Salty	1	1998	PRI	30.507832	-97.129062
35'	6	WOOD	Bartlett	Salty	1	2003	PRI	30.547785	-97.033276
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.625465	-97.15521
35'	6	WOOD	Bartlett	Salty	1	1997	PRI	30.603524	-97.158864
35'	5	WOOD	Bartlett	Salty	1	2006	PRI	30.593872	-97.135524
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.4814	-97.136695
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.516417	-97.069181
35'	5	WOOD	Bartlett	Salty	3	2008	SEC	30.623913	-97.1597
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.535206	-97.058195
35'	6	WOOD	Bartlett	Salty	1	UNK	SEC	30.512379	-97.173839
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.632238	-97.255772
35'	5	WOOD	Bartlett	Salty	1	UNK	PRI	30.560601	-97.100311
35'	5	WOOD	Bartlett	Salty	1	2006	PRI	30.592819	-97.148591
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.550134	-97.180339
35'	5	WOOD	Bartlett	Salty	1	1987	PRI	30.495393	-97.084114
35'	6	WOOD	Bartlett	Salty	1	1998	PRI	30.514699	-97.11225
35'	5	WOOD	Bartlett	Salty	1	2003	PRI	30.594694	-97.162768
35'	6	WOOD	Bartlett	Salty	1	1969	PRI	30.552755	-97.099412
35'	5	WOOD	Bartlett	Thorndale	1	2006	PRI	30.633181	-97.262548
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.483606	-97.138355
35'	6	WOOD	Bartlett	Salty	1	1987	PRI	30.59373	-97.145589
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.632531	-97.279073
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.6317	-97.279394
35'	5	WOOD	Bartlett	Salty	3	2006	PRI	30.628472	-97.162009
35'	6	WOOD	Bartlett	Salty	1	2002	PRI	30.467122	-97.144873
35'	5	WOOD	Bartlett	Salty	3	2007	PRI	30.623548	-97.167986

35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.518988	-97.142462
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.551003	-97.105397
35'	6	WOOD	Bartlett	Thorndale	1	1994	PRI	30.639976	-97.276278
35'	5	WOOD	Bartlett	Salty	1	1987	PRI	30.496162	-97.083413
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.492802	-97.153921
35'	6	WOOD	Bartlett	Thorndale	1	1999	PRI	30.626186	-97.246366
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.589278	-97.126086
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.51265	-97.174048
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.560285	-97.099293
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.481856	-97.133761
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.542197	-97.181493
35'	6	WOOD	Bartlett	Salty	1	1998	PRI	30.506781	-97.123699
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.519289	-97.173411
35'	6	WOOD	Bartlett	Salty	1	1999	PRI	30.46586	-97.158514
35'	6	WOOD	Bartlett	Thorndale	1	2001	PRI	30.639857	-97.274095
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.52747	-97.099035
35'	5	WOOD	Bartlett	Salty	3	1980	SEC	30.60424	-97.141272
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.481705	-97.134739
35'	6	WOOD	Bartlett	Salty	1	2001	PRI	30.566556	-97.100762
35'	5	WOOD	Bartlett	Salty	1	1987	PRI	30.505949	-97.079008
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.481542	-97.135751
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.475948	-97.142601
35'	6	WOOD	Bartlett	Salty	1	2001	PRI	30.520636	-97.122168
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.522716	-97.172465
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.518132	-97.156747
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.553474	-97.096726
35'	6	WOOD	Bartlett	Salty	1	1997	PRI	30.519207	-97.175302
35'	5	WOOD	Bartlett	Salty	1	2001	PRI	30.508244	-97.126123
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.495539	-97.15192
35'	7	WOOD	Bartlett	Salty	1	UNK	PRI	30.590558	-97.106305
35'	6	WOOD	Bartlett	Salty	1	1996	PRI	30.547837	-97.176441
35'	6	WOOD	Bartlett	Salty	1	1996	PRI	30.507796	-97.170233
35'	6	WOOD	Bartlett	Salty	1	1946	PRI	30.564514	-97.093009

35'	6	WOOD	Bartlett	Salty	1	1996	PRI	30.519511	-97.175213
35'	5	WOOD	Bartlett	Salty	1	2001	PRI	30.570824	-97.104075
35'	6	WOOD	Bartlett	Salty	1	1999	PRI	30.517302	-97.107978
35'	4	WOOD	Bartlett	Salty	3	UNK	PRI	30.616608	-97.159083
35'	7	WOOD	Bartlett	Thorndale	1	1940	PRI	30.610198	-97.23525
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.527779	-97.098144
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.490509	-97.121705
35'	5	WOOD	Bartlett	Thorndale	1	2007	GUY	30.624333	-97.234328
35'	6	WOOD	Bartlett	Thorndale	1	2000	PRI	30.607215	-97.248299
35'	5	WOOD	Bartlett	Salty	1	2001	PRI	30.579463	-97.12729
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.532561	-97.061354
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.511307	-97.124682
35'	6	WOOD	Bartlett	Salty	1	1998	PRI	30.536119	-97.183451
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.523806	-97.107742
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.529155	-97.070351
35'	6	WOOD	Bartlett	Salty	3	1996	PRI	30.629202	-97.149751
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.542531	-97.045896
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.487025	-97.121734
35'	5	WOOD	Bartlett	Salty	1	2005	SEC	30.513683	-97.142458
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.522682	-97.116365
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.537139	-97.092397
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.499528	-97.157447
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.623733	-97.217981
35'	6	WOOD	Bartlett	Salty	1	1999	PRI	30.465966	-97.158582
35'	5	WOOD	Bartlett	Salty	1	1987	PRI	30.502403	-97.080532
35'	6	WOOD	Bartlett	Thorndale	1	2000	PRI	30.625449	-97.248376
35'	6	WOOD	Bartlett	Salty	1	2002	PRI	30.594558	-97.156476
35'	6	WOOD	Bartlett	Salty	1	1991	PRI	30.511336	-97.075035
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.476872	-97.139768
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.488624	-97.121716
35'	6	WOOD	Bartlett	Salty	1	1998	PRI	30.517146	-97.169051
35'	6	WOOD	Bartlett	Salty	1	1998	PRI	30.464635	-97.156968
35'	6	WOOD	Bartlett	Salty	1	1989	PRI	30.540517	-97.180425

35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.510242	-97.126208
35'	6	WOOD	Bartlett	Thorndale	1	2001	PRI	30.620335	-97.234127
35'	5	WOOD	Bartlett	Salty	1	2001	PRI	30.536079	-97.054908
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.483923	-97.126178
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.516033	-97.167822
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.517456	-97.126057
35'	6	WOOD	Bartlett	Salty	1	1985	PRI	30.514579	-97.119856
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.485821	-97.139155
35'	6	WOOD	Bartlett	Salty	1	UNK	SEC	30.544196	-97.180666
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.532713	-97.082658
35'	4	WOOD	Bartlett	Salty	1	1980	PRI	30.593617	-97.143905
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.512037	-97.074217
35'	5	WOOD	Bartlett	Salty	1	UNK	PRI	30.544279	-97.043605
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.543657	-97.09544
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.524129	-97.066203
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.507317	-97.114691
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.546218	-97.174618
35'	6	WOOD	Bartlett	Salty	1	2003	PRI	30.513861	-97.124782
35'	6	WOOD	Bartlett	Salty	3	1997	PRI	30.604274	-97.13822
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.613939	-97.154628
35'	6	WOOD	Bartlett	Salty	1	1999	PRI	30.588526	-97.142362
35'	6	WOOD	Bartlett	Salty	1	1998	PRI	30.57347	-97.119727
35'	6	WOOD	Bartlett	Salty	1	1998	PRI	30.468257	-97.155958
35'	6	WOOD	Bartlett	Salty	1	1946	PRI	30.584569	-97.128409
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.548544	-97.095781
35'	6	WOOD	Bartlett	Salty	3	2003	PRI	30.609584	-97.152418
35'	6	WOOD	Bartlett	Salty	1	1982	PRI	30.514766	-97.173128
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.553428	-97.091183
35'	6	WOOD	Bartlett	Salty	1	1999	PRI	30.586416	-97.129547
35'	6	WOOD	Bartlett	Salty	1	2000	PRI	30.470581	-97.158988
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.522486	-97.116292
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.507409	-97.116302
35'	6	WOOD	Bartlett	Salty	1	1998	PRI	30.574893	-97.119155

35'	5	WOOD	Bartlett	Salty	1	2007	PRI	30.488685	-97.150544
35'	6	WOOD	Bartlett	Thorndale	1	1998	PRI	30.639387	-97.271796
35'	6	WOOD	Bartlett	Thorndale	1	UNK	SEC	30.642592	-97.279455
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.476566	-97.140714
35'	6	WOOD	Bartlett	Thorndale	1	1999	PRI	30.638229	-97.276838
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.609748	-97.222277
35'	6	WOOD	Bartlett	Salty	1	UNK	SEC	30.593584	-97.15407
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.517937	-97.121252
35'	6	WOOD	Bartlett	Thorndale	1	2000	PRI	30.605409	-97.247506
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.49317	-97.121677
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.498789	-97.119101
35'	6	WOOD	Bartlett	Salty	1	2001	PRI	30.515048	-97.163174
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.48202	-97.132703
35'	5	WOOD	Bartlett	Salty	1	2003	PRI	30.519109	-97.175679
35'	6	WOOD	Bartlett	Salty	1	1999	PRI	30.466609	-97.159328
35'	6	WOOD	Bartlett	Salty	1	1998	PRI	30.517327	-97.168987
35'	6	WOOD	Bartlett	Salty	1	2003	PRI	30.547198	-97.033819
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.514366	-97.143973
35'	6	WOOD	Bartlett	Salty	1	2001	PRI	30.492366	-97.147713
35'	6	WOOD	Bartlett	Thorndale	1	1999	PRI	30.637982	-97.276137
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.548409	-97.096616
35'	6	WOOD	Bartlett	Salty	1	2000	PRI	30.586989	-97.130091
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.499419	-97.15605
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.542438	-97.038596
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.482041	-97.128264
35'	6	WOOD	Bartlett	Salty	1	1995	PRI	30.556365	-97.088636
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.583218	-97.104311
35'	6	WOOD	Bartlett	Salty	3	2003	PRI	30.609089	-97.152479
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.494742	-97.121511
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.480012	-97.145566
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.623808	-97.160911
35'	7	WOOD	Bartlett	Salty	1	1973	PRI	30.514289	-97.052781
35'	6	WOOD	Bartlett	Salty	1	1995	PRI	30.516986	-97.171451

35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.535376	-97.088722
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.619955	-97.148782
35'	6	WOOD	Bartlett	Salty	1	2003	PRI	30.504258	-97.172399
35'	5	WOOD	Bartlett	Salty	1	1987	PRI	30.507593	-97.078298
35'	6	WOOD	Bartlett	Salty	1	1999	PRI	30.467047	-97.159885
35'	5	WOOD	Bartlett	Salty	1	1987	PRI	30.506837	-97.078624
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.519254	-97.120603
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.553959	-97.089899
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.519514	-97.069346
35'	5	WOOD	Bartlett	Salty	1	2006	PRI	30.543209	-97.096501
35'	5	WOOD	Bartlett	Salty	1	2006	PRI	30.544124	-97.097741
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.535604	-97.043809
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.515261	-97.17243
35'	5	WOOD	Bartlett	Salty	1	UNK	PRI	30.598519	-97.11774
35'	6	WOOD	Bartlett	Thorndale	1	2001	PRI	30.640569	-97.273824
35'	6	WOOD	Bartlett	Salty	1	2000	PRI	30.563329	-97.107055
35'	6	WOOD	Bartlett	Salty	1	1999	SEC	30.466596	-97.150976
35'	5	WOOD	Bartlett	Salty	1	2008	PRI	30.516715	-97.165996
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.520165	-97.06961
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.531444	-97.064995
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.52144	-97.113858
35'	6	WOOD	Bartlett	Salty	1	1947	PRI	30.555607	-97.095763
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.511938	-97.12496
35'	6	WOOD	Bartlett	Salty	1	2002	PRI	30.547362	-97.17189
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.521289	-97.121331
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.57289	-97.1032
35'	6	WOOD	Bartlett	Thorndale	1	1999	PRI	30.649242	-97.200745
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.521072	-97.115002
35'	7	WOOD	Bartlett	Salty	1	UNK	PRI	30.513073	-97.129677
35'	6	WOOD	Bartlett	Salty	1	1997	PRI	30.591327	-97.127091
35'	5	WOOD	Bartlett	Salty	1	1987	PRI	30.504148	-97.07978
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.544164	-97.044032
35'	6	WOOD	Bartlett	Salty	1	2002	PRI	30.467853	-97.14685

35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.580987	-97.104449
35'	5	WOOD	Bartlett	Salty	1	1969	PRI	30.498927	-97.088264
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.48409	-97.131505
35'	4	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.617475	-97.220753
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.503007	-97.12107
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.620278	-97.22239
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.51041	-97.125405
35'	4	WOOD	Bartlett	Salty	1	1979	PRI	30.523887	-97.10759
35'	5	WOOD	Bartlett	Salty	1	2006	PRI	30.532552	-97.180449
35'	6	WOOD	Bartlett	Salty	1	1987	PRI	30.516436	-97.17169
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.509983	-97.166938
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.56311	-97.088674
35'	7	WOOD	Bartlett	Salty	1	UNK	PRI	30.588927	-97.105652
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.613579	-97.148854
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.515289	-97.168106
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.500893	-97.120485
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.563613	-97.090235
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.544703	-97.095369
35'	5	WOOD	Bartlett	Salty	1	UNK	PRI	30.599807	-97.117091
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.519618	-97.119476
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.505551	-97.122187
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.478592	-97.138259
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.546018	-97.037931
35'	6	WOOD	Bartlett	Salty	1	1999	PRI	30.46665	-97.150832
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.642022	-97.27134
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.627884	-97.162206
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.506839	-97.118747
35'	7	WOOD	Bartlett	Salty	3	UNK	PRI	30.62369	-97.174915
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.585981	-97.128726
35'	5	WOOD	Bartlett	Salty	1	1987	PRI	30.497003	-97.082877
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.546453	-97.180148
35'	7	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.610029	-97.242191
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.512037	-97.17428

35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.502565	-97.154334
35'	6	WOOD	Bartlett	Thorndale	1	2001	SEC	30.63981	-97.273906
35'	5	WOOD	Bartlett	Salty	1	1987	PRI	30.497901	-97.082481
35'	6	WOOD	Bartlett	Salty	1	1978	PRI	30.517811	-97.124964
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.621539	-97.15754
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.480608	-97.141789
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.477172	-97.138838
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.483109	-97.131599
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.487537	-97.140617
35'	5	WOOD	Bartlett	Salty	1	2001	PRI	30.538207	-97.052602
35'	6	WOOD	Bartlett	Salty	1	1995	PRI	30.538734	-97.18162
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.482176	-97.131689
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.591566	-97.106711
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.48546	-97.139019
35'	6	WOOD	Bartlett	Salty	1	2000	PRI	30.504425	-97.1376
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.483221	-97.129015
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.618359	-97.220536
35'	5	WOOD	Bartlett	Salty	3	2005	PRI	30.625426	-97.157769
35'	6	WOOD	Bartlett	Salty	1	2003	PRI	30.484047	-97.128473
35'	6	WOOD	Bartlett	Salty	1	2002	PRI	30.466824	-97.145083
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.54855	-97.095055
35'	7	WOOD	Bartlett	Salty	1	UNK	PRI	30.589866	-97.106024
35'	6	WOOD	Bartlett	Thorndale	1	1996	PRI	30.62489	-97.234539
35'	6	WOOD	Bartlett	Salty	1	1997	SEC	30.519719	-97.175152
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.525926	-97.103587
35'	6	WOOD	Bartlett	Thorndale	1	1996	PRI	30.632017	-97.254791
35'	5	WOOD	Bartlett	Salty	1	UNK	PRI	30.590586	-97.12269
35'	6	WOOD	Bartlett	Salty	3	2002	PRI	30.604237	-97.138912
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.545967	-97.037802
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.500294	-97.151784
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.635078	-97.214206
35'	4	WOOD	Bartlett	Salty	1	1979	PRI	30.526685	-97.101342
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.551022	-97.094849

35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.51787	-97.142357
35'	6	WOOD	Bartlett	Salty	1	1998	PRI	30.474628	-97.154774
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.535395	-97.057524
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.472523	-97.152507
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.479377	-97.146224
35'	6	WOOD	Bartlett	Thorndale	1	1998	PRI	30.625123	-97.250583
35'	5	WOOD	Bartlett	Thorndale	1	2005	SEC	30.639602	-97.267093
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.4864	-97.127102
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.524509	-97.064917
35'	6	WOOD	Bartlett	Thorndale	1	2002	PRI	30.641994	-97.210943
35'	6	WOOD	Bartlett	Salty	1	1946	PRI	30.565901	-97.100797
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.498942	-97.119807
35'	7	WOOD	Bartlett	Salty	1	UNK	PRI	30.549972	-97.094941
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.559408	-97.098619
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.564125	-97.091819
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.58238	-97.104427
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.472074	-97.145675
35'	5	WOOD	Bartlett	Salty	1	2001	PRI	30.540916	-97.04966
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.496361	-97.152295
35'	5	WOOD	Bartlett	Salty	1	1994	PRI	30.481902	-97.129556
35'	6	WOOD	Bartlett	Salty	1	1999	PRI	30.473082	-97.153393
35'	5	WOOD	Bartlett	Thorndale	1	2006	SEC	30.634545	-97.256011
35'	6	WOOD	Bartlett	Salty	1	2001	PRI	30.575735	-97.126466
35'	6	WOOD	Bartlett	Salty	1	2001	PRI	30.489286	-97.149384
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.486775	-97.139498
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.51717	-97.054321
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.576326	-97.125913
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.510392	-97.122386
35'	7	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.611888	-97.223006
35'	5	WOOD	Bartlett	Salty	1	2005	GUY	30.516748	-97.172647
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.499884	-97.155156
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.57051	-97.117578
35'	7	WOOD	Bartlett	Salty	1	UNK	PRI	30.516305	-97.053621

35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.601897	-97.134081
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.584331	-97.124444
35'	7	WOOD	Bartlett	Salty	1	UNK	PRI	30.54259	-97.095504
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.534943	-97.05904
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.514337	-97.125236
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.642423	-97.210411
35'	6	WOOD	Bartlett	Salty	1	1992	PRI	30.512916	-97.073204
35'	6	WOOD	Bartlett	Salty	1	2000	PRI	30.508289	-97.130024
35'	5	WOOD	Bartlett	Salty	1	2007	PRI	30.483027	-97.135094
35'	6	WOOD	Bartlett	Thorndale	1	1999	PRI	30.626493	-97.247143
35'	6	WOOD	Bartlett	Salty	3	2002	PRI	30.615702	-97.157032
35'	6	WOOD	Bartlett	Salty	1	1998	PRI	30.5154	-97.112965
35'	5	WOOD	Bartlett	Salty	1	2003	PRI	30.592907	-97.146878
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.59335	-97.140512
35'	6	WOOD	Bartlett	Salty	1	1989	PRI	30.540333	-97.179796
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.526447	-97.171042
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.642385	-97.279293
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.634034	-97.25855
35'	6	WOOD	Bartlett	Salty	1	1997	PRI	30.518735	-97.174289
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.543206	-97.095466
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.587896	-97.143055
35'	5	WOOD	Bartlett	Salty	3	2005	PRI	30.625674	-97.158585
35'	6	WOOD	Bartlett	Salty	1	2001	PRI	30.492744	-97.148495
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.576765	-97.1267
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.485002	-97.128146
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.620578	-97.223127
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.581629	-97.113357
35'	6	WOOD	Bartlett	Salty	1	1998	PRI	30.507723	-97.128227
35'	6	WOOD	Bartlett	Salty	1	1987	PRI	30.591046	-97.116477
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.510565	-97.124664
35'	5	WOOD	Bartlett	Salty	1	UNK	PRI	30.590827	-97.123465
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.541591	-97.095613
35'	5	WOOD	Bartlett	Salty	1	1987	PRI	30.499703	-97.0817

35'	6	WOOD	Bartlett	Thorndale	1	1999	PRI	30.649114	-97.200717
35'	5	WOOD	Bartlett	Salty	1	2009	PRI	30.563939	-97.106542
35'	6	WOOD	Bartlett	Thorndale	1	UNK	SEC	30.640703	-97.273054
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.547687	-97.034383
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.630429	-97.241133
35'	6	WOOD	Bartlett	Salty	1	2003	PRI	30.545911	-97.035999
35'	6	WOOD	Bartlett	Thorndale	1	2001	PRI	30.640738	-97.273712
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.59366	-97.1449
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.519977	-97.11834
35'	5	WOOD	Bartlett	Salty	1	UNK	PRI	30.601065	-97.116436
35'	6	WOOD	Bartlett	Salty	3	2002	PRI	30.615858	-97.157551
35'	6	WOOD	Bartlett	Salty	1	1987	SEC	30.543472	-97.043982
35'	6	WOOD	Bartlett	Salty	1	2003	PRI	30.548368	-97.032733
35'	6	WOOD	Bartlett	Salty	1	1998	PRI	30.507618	-97.127388
35'	6	WOOD	Bartlett	Salty	3	2003	PRI	30.609859	-97.152384
35'	6	WOOD	Bartlett	Salty	1	2002	SEC	30.510141	-97.1219
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.49123	-97.154177
35'	5	WOOD	Bartlett	Salty	1	2006	PRI	30.542716	-97.038085
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.625502	-97.153879
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.499673	-97.163706
35'	5	WOOD	Bartlett	Salty	1	1987	PRI	30.500601	-97.081315
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.588453	-97.15137
35'	5	WOOD	Bartlett	Salty	1	2001	PRI	30.570906	-97.104049
35'	7	WOOD	Bartlett	Salty	1	UNK	PRI	30.543883	-97.044925
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.500158	-97.157836
35'	5	WOOD	Bartlett	Thorndale	1	2006	PRI	30.632454	-97.262888
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.585021	-97.12522
35'	5	WOOD	Bartlett	Salty	1	2003	SEC	30.519014	-97.175801
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.567631	-97.101328
35'	6	WOOD	Bartlett	Salty	1	1986	PRI	30.515462	-97.120234
35'	5	WOOD	Bartlett	Salty	1	2001	PRI	30.536801	-97.05412
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.51883	-97.069057
35'	6	WOOD	Bartlett	Salty	1	1989	PRI	30.540709	-97.181058

35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.546804	-97.095191
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.633468	-97.278721
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.484569	-97.1387
35'	6	WOOD	Bartlett	Salty	1	2005	PRI	30.538105	-97.181802
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.584468	-97.125483
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.612195	-97.221826
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.470557	-97.150358
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.543349	-97.046249
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.528429	-97.044415
35'	5	WOOD	Bartlett	Salty	1	2006	PRI	30.594473	-97.151455
35'	5	WOOD	Bartlett	Salty	1	UNK	PRI	30.503239	-97.080173
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.469801	-97.147095
35'	6	WOOD	Bartlett	Thorndale	1	2000	PRI	30.608828	-97.251287
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.522181	-97.111611
35'	6	WOOD	Bartlett	Salty	1	1999	PRI	30.465237	-97.15964
35'	6	WOOD	Bartlett	Thorndale	1	1999	PRI	30.62778	-97.251504
35'	7	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.613618	-97.221545
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.480745	-97.140878
35'	6	WOOD	Bartlett	Thorndale	1	2001	PRI	30.641012	-97.19542
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.585346	-97.128003
35'	6	WOOD	Bartlett	Salty	1	1987	PRI	30.501734	-97.154031
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.587177	-97.120987
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.470651	-97.146562
35'	6	WOOD	Bartlett	Salty	1	1985	PRI	30.512799	-97.129687
35'	6	WOOD	Bartlett	Salty	1	1946	PRI	30.565536	-97.096154
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.52571	-97.109586
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.469828	-97.149822
35'	6	WOOD	Bartlett	Salty	1	2001	PRI	30.493314	-97.146972
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.532293	-97.081619
35'	6	WOOD	Bartlett	Thorndale	1	1999	PRI	30.645991	-97.20196
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.61618	-97.223033
35'	5	WOOD	Bartlett	Thorndale	1	2001	PRI	30.641302	-97.275598
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.55676	-97.096639

35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.512619	-97.125129
35'	4	WOOD	Bartlett	Thorndale	1	UNK	SEC	30.647212	-97.19946
35'	5	WOOD	Bartlett	Salty	1	2001	PRI	30.537518	-97.053346
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.507165	-97.119704
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.586129	-97.119811
35'	5	WOOD	Bartlett	Salty	3	2007	PRI	30.627758	-97.154897
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.507484	-97.115232
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.537698	-97.181258
35'	6	WOOD	Bartlett	Salty	1	1985	PRI	30.548797	-97.179921
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.507064	-97.121148
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.600783	-97.233459
35'	5	WOOD	Bartlett	Salty	3	2003	PRI	30.626079	-97.160193
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.596872	-97.115766
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.478008	-97.138084
35'	6	WOOD	Bartlett	Salty	1	1998	PRI	30.57418	-97.11945
35'	6	WOOD	Bartlett	Salty	1	1987	PRI	30.543669	-97.044009
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.482286	-97.130964
35'	5	WOOD	Bartlett	Thorndale	1	2006	PRI	30.631728	-97.263231
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.502224	-97.12072
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.548523	-97.176314
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.591685	-97.116477
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.515158	-97.173091
35'	6	WOOD	Bartlett	Thorndale	1	1985	PRI	30.628768	-97.251495
35'	6	WOOD	Bartlett	Salty	1	1989	PRI	30.512441	-97.122339
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.481265	-97.137513
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.48189	-97.12773
35'	5	WOOD	Bartlett	Thorndale	1	2006	PRI	30.633915	-97.262205
35'	6	WOOD	Bartlett	Salty	1	2001	PRI	30.490901	-97.148512
35'	5	WOOD	Bartlett	Salty	1	UNK	PRI	30.484833	-97.139863
35'	6	WOOD	Bartlett	Salty	3	1996	PRI	30.629482	-97.150397
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.554589	-97.089068
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.565072	-97.100854
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.641027	-97.188069

35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.564124	-97.100734
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.633428	-97.256379
35'	4	WOOD	Bartlett	Thorndale	1	1985	PRI	30.645898	-97.208137
35'	6	WOOD	Bartlett	Thorndale	1	1994	PRI	30.64004	-97.277446
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.548179	-97.03494
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.553553	-97.09208
35'	6	WOOD	Bartlett	Salty	1	UNK	SEC	30.553754	-97.090884
35'	5	WOOD	Bartlett	Salty	1	2006	PRI	30.59517	-97.150831
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.516268	-97.120559
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.584976	-97.104071
35'	5	WOOD	Bartlett	Salty	1	2008	PRI	30.5485	-97.180869
35'	6	WOOD	Bartlett	Salty	1	2001	PRI	30.513874	-97.16329
35'	6	WOOD	Bartlett	Salty	1	2003	PRI	30.545751	-97.037151
35'	5	WOOD	Bartlett	Salty	1	UNK	PRI	30.508995	-97.077708
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.493674	-97.151178
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.603364	-97.160991
35'	6	WOOD	Bartlett	Salty	3	1996	PRI	30.612767	-97.148704
35'	5	WOOD	Bartlett	Salty	3	2007	PRI	30.627045	-97.155008
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.548917	-97.095026
35'	6	WOOD	Bartlett	Salty	3	2003	PRI	30.610685	-97.152275
35'	4	WOOD	Bartlett	Salty	1	UNK	GUY	30.517039	-97.127367
35'	6	WOOD	Bartlett	Salty	1	2002	PRI	30.594102	-97.157053
35'	6	WOOD	Bartlett	Salty	1	1969	PRI	30.552399	-97.100715
35'	6	WOOD	Bartlett	Salty	1	1969	PRI	30.514249	-97.155137
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.627162	-97.168421
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.568232	-97.101899
35'	6	WOOD	Bartlett	Thorndale	1	1994	PRI	30.633994	-97.250075
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.515526	-97.070194
35'	6	WOOD	Bartlett	Salty	1	2002	PRI	30.466455	-97.144386
35'	5	WOOD	Bartlett	Salty	1	2003	PRI	30.594777	-97.164209
35'	6	WOOD	Bartlett	Salty	1	1999	PRI	30.500591	-97.149683
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.53188	-97.063576
35'	6	WOOD	Bartlett	Salty	1	1993	PRI	30.500243	-97.119373

35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.503852	-97.12144
35'	6	WOOD	Bartlett	Salty	1	1969	PRI	30.55205	-97.102037
35'	6	WOOD	Bartlett	Salty	1	1994	SEC	30.515105	-97.172316
35'	6	WOOD	Bartlett	Salty	1	2001	PRI	30.514439	-97.163242
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.476259	-97.141647
35'	6	WOOD	Bartlett	Salty	1	1998	PRI	30.510065	-97.122068
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.571089	-97.102932
35'	5	WOOD	Bartlett	Salty	1	2001	PRI	30.571154	-97.103021
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.576789	-97.105208
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.526307	-97.102464
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.516297	-97.172571
35'	6	WOOD	Bartlett	Salty	1	1995	PRI	30.526706	-97.169958
35'	6	WOOD	Bartlett	Salty	1	2000	PRI	30.542263	-97.048199
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.628274	-97.151151
35'	5	WOOD	Bartlett	Thorndale	1	2007	GUY	30.64121	-97.189252
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.557629	-97.097292
35'	6	WOOD	Bartlett	Salty	1	1998	PRI	30.537046	-97.183438
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.51877	-97.121602
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.565057	-97.09471
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.585133	-97.126176
35'	6	WOOD	Bartlett	Salty	1	1995	PRI	30.547879	-97.095109
35'	5	WOOD	Bartlett	Salty	1	2004	PRI	30.484858	-97.127936
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.520341	-97.117205
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.570364	-97.113357
35'	6	WOOD	Bartlett	Salty	1	1999	PRI	30.567945	-97.103598
35'	5	WOOD	Bartlett	Salty	1	2005	PRI	30.479993	-97.145722
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.497167	-97.149805
35'	4	WOOD	Bartlett	Salty	1	UNK	PRI	30.517138	-97.068362
35'	6	WOOD	Bartlett	Salty	1	2001	PRI	30.548855	-97.180634
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.536826	-97.183685
35'	6	WOOD	Bartlett	Salty	3	UNK	PRI	30.626332	-97.155118
35'	6	WOOD	Bartlett	Thorndale	1	UNK	PRI	30.611573	-97.224221
35'	6	WOOD	Bartlett	Salty	1	UNK	PRI	30.508269	-97.114502