

Control Number: 50594



Item Number: 56

Addendum StartPage: 0



Public Utility Commission of Texas



Five-Year Report Required by 16 Texas Admin. Code § 25.97(e)

PROJECT NO. 50594

AFFECTED ENTITY: South Texas Electric Cooperative, Inc.

General Information

Pursuant to 16 Texas Admin. Code § 25.97(e)(1), not later than May 1 every five years, each affected entity that owns or operates overhead transmission facilities greater than 60 kilovolts must submit this report. The first report must be submitted not later than May 1, 2020.

Instructions

Answer all questions, fill-in all blanks, and have the report notarized in the Affidavit.

Affidavit

A representative of the affected entity must swear to and affirm the truthfulness, correctness, and completeness of the information provided by attaching a signed and notarized copy of the Affidavit provided with this form.

Filing Instructions

Submit four copies (an original and three copies) of the completed form and signed and notarized Affidavit to:

Central Records Filing Clerk Public Utility Commission of Texas 1701 N. Congress Avenue P.O. Box 13326 Austin, Texas 78711-3326 Telephone: (512) 936-7180

Five-Year Report Form Last Updated in Project No. 49827

510

1. Historical five-year reporting period: 2015 - 2019

What percentage of overhead transmission facilities greater than 60 kilovolts did you inspect for compliance with the National Electric Safety Code (NESC) relating to vertical clearance in the historical five-year reporting period?

All (100 percent) of STEC's transmission lines were inspected aerially utilizing airplanes or helicopters each year from 2015 through 2019 to detect transmission line and right-of-way issues that may have created situations that do not comply with NESC minimum vertical clearances.

Ground-based patrols were performed for vegetation management inspection, pole top inspection and rehabilitation, and pole ground line inspection and treatment. In addition, patrols were performed to find the causes of operations. Such ground-based inspections were performed to detect facility conditions that create situations that do not meet the NESC vertical clearance requirements. The per-year inspection percentages were as follows:

2015 86%

2016 85%

2017 70%

2018 89%

2019 97%

Five-Year Report Form Last Updated in Project No. 49827 Affected Entity: South Texas Electric Cooperative, Inc.

Five-Year Report Form Last Updated in Project No. 49827 PROJECT NO. 50594

AFFIDAVIT

I swear or affirm that I have personal knowledge of the facts stated in this report or am relying on people with personal knowledge, that I am competent to testify to them, and that I have the authority to submit this report on behalf of the affected entity. I further swear or affirm that all statements made in this report are true, correct, and complete.

Cory Allen

Printed Name

Assistant General Manager/Manager of Power Delivery Job Title

South Texas Electric Cooperative, Inc.

Name of Affected Entity

Sworn and subscribed before me this 30th day of April , 2020.

Month Year

BECKY A. LOREDO Notary Public, State of Texas Notary ID# 382204-6
My Commission Expires JUNE 24, 2021

Becky a. Lored

Notary Public in and For the State of Texas

My commission expires on 6-24-2021