

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Conbraco MODEL 40204T2 SIZE 3/4 SERIAL NO. 005400
SERVICE NUMBER: #120 LOCATION: Bldg 4415 w/Dock Part Washer
SERVICE NAME/ADDRESS: Bldg 441
OWNER NAME/ADDRESS: RRAD
AR: 6.8 RVOP: 3.2
CHECK VALVE #1 HT
CHECK VALVE #1 7.2

RP ☒
DC ☐
PVB ☐
SVB ☐
DCDA ☐
RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>7.2</u> PSID Leaked ☐	Held at _____ PSID Closed Tight ☒ Leaked ☐	Opened at <u>3.2</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____
FINAL TEST	_____ PSID	Closed Tight ☐ PSID	Opened at _____ PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-26-14</u> Time <u>11:00am</u> Certified Tester No. <u>15915</u> ☒ Passed ☐ Failed
REPAIR	Test By (Signature) <u>Robert W. Autrey</u> Print Name <u>ROBERT W. AUTREY</u>
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed
	Repaired by (Signature) _____ Print Name _____
	Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL 009-M3QT SIZE 3/4" SERIAL NO. 324276
 SERVICE NUMBER: #101 LOCATION: Bldg 4415 NW By Firewall
 SERVICE NAME/ADDRESS: Bldg 441 RRAD
 OWNER NAME/ADDRESS: RRAD
 AR: 7.7 RVOP: 3.8
 CHECK VALVE #2 HT
 CHECK VALVE #1 7.2

RP ☒
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>7.2</u> PSID	Held at _____ PSID	Opened at <u>3.8</u> PSID	AIR INLET Opened at _____ PSID
	Leaked ☐	Closed Tight ☒ Leaked ☐	Did Not Open ☐	Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced	☐ Cleaned ☐ Replaced	☐ Cleaned ☐ Replaced	CHECK VALVE Held at _____ PSID Leaked ☐
	_____	_____	_____	☐ Cleaned ☐ Replaced _____ _____ _____ _____
FINAL TEST	_____ PSID	Closed Tight ☐ PSID	Opened at _____ PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-26-14</u> Time <u>10:30am</u> Certified Tester No. <u>15915</u> ☒ Passed ☐ Failed
	Test By (Signature) <u>Robert W. Autrey</u> Print Name <u>ROBERT W. Autrey</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____
	Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed
	Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL 009M30T SIZE 3/4" SERIAL NO. 355318
 SERVICE NUMBER: #102 LOCATION: 421 high Bay Area East middle
 SERVICE NAME/ADDRESS: Bldg 421 RRAD Blue wash
 OWNER NAME/ADDRESS: RRAD
 AR: 8.6 RVOP: 2.6
 CHECK VALVE #2 H.T.
 CHECK VALVE #1 8.0

RP ☒
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>8.0</u> PSID Leaked ☐	Held at _____ PSID Closed Tight ☒ Leaked ☐	Opened at <u>2.6</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____
FINAL TEST	_____ PSID	Closed Tight ☐ PSID	Opened at _____ PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-25-14</u> Time <u>3:15</u> Certified Tester No. <u>15915</u> ☒ Passed ☐ Failed Test By (Signature) <u>Robert W Autrey</u> Print Name <u>Robert W Autrey</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____ Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL 009MAGT SIZE 1" SERIAL NO. 278775
SERVICE NUMBER: _____ LOCATION: West Rock Ctr of Bldg
SERVICE NAME/ADDRESS: Bldg 421 RRAD
OWNER NAME/ADDRESS: RRAD
AIR: 6.8 RVOP: 3.8
CHECK VALVE #2 HT
CHECK VALVE #1 6.8

RP ☒
DC ☐
PVB ☐
SVB ☐
DCDA ☐
RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>6.8</u> PSID Leaked ☐	Held at _____ PSID Closed Tight ☒ Leaked ☐	Opened at <u>3.8</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____
FINAL TEST	_____ PSID	Closed Tight ☐	Opened at _____ PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-26-14</u> Time <u>10:00am</u> Certified Tester No. <u>15915</u> ☒ Passed ☐ Failed
	Test By (Signature) <u>Robert W. Autrey</u> Print Name <u>ROBERT W. AUTREY</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____
	Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed
	Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE WILKINZ MODEL 975XL SIZE 1" SERIAL NO. 1258615
SERVICE NUMBER: 094 LOCATION: EAST SIDE CENTER IN PUMP AREA OUTSIDE
SERVICE NAME/ADDRESS: Bldg 421
OWNER NAME/ADDRESS: KRAD
AR: 9.0 RVOP: 3.0
CHECK VALVE #2 HT
CHECK VALVE #1 9.0

RP ☒
EC ☐
PVB ☐
SVB ☐
DCDA ☐
RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>9.0</u> PSID Leaked ☐	Held at _____ PSID Closed Tight ☒ Leaked ☐	Opened at <u>3.0</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____
FINAL TEST	_____ PSID	Closed Tight ☐ PSID	Opened at _____ PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-25-14</u> Time <u>3:45pm</u> Certified Tester No. <u>15915</u> ☒ Passed ☐ Failed Test By (Signature) <u>Robert W. Autrey</u> Print Name <u>Robert W. Autrey</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____ Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL 009M245 SIZE 2" SERIAL NO. 147172
 SERVICE NUMBER: #60 LOCATION: MAIN WTR Feed Nend Blvd 328
 SERVICE NAME/ADDRESS: BRAD 3169 328
 OWNER NAME/ADDRESS: BRAD
 AR 5.8 RVOH: 4.0
 CHECK VALVE #1 HT
 CHECK VALVE #1 6.0

RP ☒
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>6.0</u> PSID Leaked ☐	Held at _____ PSID Closed Tight ☒ Leaked ☐	Opened at <u>4.0</u> SID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____
FINAL TEST	_____ PSID	_____ PSID Closed Tight ☐	Opened at _____ PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-25-14</u> Time <u>12:30</u> Certified Tester No. <u>15915</u> ☒ Passed ☐ Failed
	Test By (Signature) <u>Robert W. Autrey</u> Print Name <u>ROBERT W. AUTREY</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____
	Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed
	Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE WATTS MODEL 009M2QT SIZE 2" SERIAL NO. 150228
 SERVICE NUMBER: 047 LOCATION: Bldg 286
 SERVICE NAME/ADDRESS: SECURITY CAGE AREA
 OWNER NAME/ADDRESS: RRAD
 AR: 9.5 psid RVOP: 2.2
 CHECK VALVE #1 H/T
 CHECK VALVE #1 9.8

RP ☒
 DC ☐
 PVB ☐
 SVII ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>9.8</u> PSID Leaked ☐	Held at _____ PSID Closed Tight ☒ Leaked ☐	Opened at <u>2.2</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____
FINAL TEST	<u>9.8</u> PSID	_____ PSID Closed Tight ☐	Opened at <u>2.2</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-19-14</u> Time <u>7:30</u> Certified Tester No. <u>16951</u> ☒ Passed ☐ Failed
REPAIR	Test By (Signature) <u>Robert W. Autrey</u> Print Name <u>Robert W. Autrey</u>
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed
	Repaired by (Signature) _____ Print Name _____
	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed
	Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL 009RP SIZE 2 1/2" SERIAL NO. 33300
 SERVICE NUMBER: 078 LOCATION: Bldg 582
 SERVICE NAME/ADDRESS: Bldg 582 ctr of Bldg west side (inside)
 OWNER NAME/ADDRESS: DLA / RRAD
 AR: 8.9 RVOP: 2.5 psid
 CHECK VALVE #2 H/T
 CHECK VALVE #1 8.9

RP ☒
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY
 DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>8.9</u> PSID Leaked ☐	Held at _____ PSID Closed Tight ☒ Leaked ☐	Opened at <u>2.5</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____
FINAL TEST	<u>8.9</u> PSID	_____ PSID Closed Tight ☐	Opened at <u>2.5</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-21-14</u> Time <u>3:30pm</u> Certified Tester No. <u>15915</u> ☒ Passed ☐ Failed Test By (Signature) <u>Robert W. Autrey</u> Print Name <u>Robert W. Autrey</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____ Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL 009M3QT SIZE 3/4" SERIAL NO. 372444
 SERVICE NUMBER: _____ LOCATION: 957 Equipment Room
 SERVICE NAME/ADDRESS: RRAD
 OWNER NAME/ADDRESS: RRAD
 AR: 8.9 RVOR: 4.2
 CHECK VALVE #2 9.2
 CHECK VALVE #1 9.2

RP ☒
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>9.2</u> PSID Leaked ☐	Held at <u>9.2</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>4.2</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____
FINAL TEST	_____ PSID	Closed Tight ☐ PSID	Opened at _____ PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>9-2-14</u> Time <u>3:10pm</u> Certified Tester No. <u>14467</u> ☒ Passed ☐ Failed
	Test By (Signature) <u>Stacey Sharp</u> Print Name <u>Stacey Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____
	Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed
	Test By (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL 009M3QT SIZE 3/4 SERIAL NO. 366059
 SERVICE NUMBER: 103 LOCATION: 1172 Southwest side
 SERVICE NAME/ADDRESS: PRAD Bldg 1172
 OWNER NAME/ADDRESS: PRAD
 AR: 9.4 RVOP: 2.0
 CHECK VALVE #2 H/T
 CHECK VALVE #1 9.4

RF ☐
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>9.4</u> PSID Leaked ☐	Held at _____ PSID Closed Tight ☒ Leaked ☐	Opened at <u>2.0</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced	☐ Cleaned ☐ Replaced	☐ Cleaned ☐ Replaced	CHECK VALVE Held at _____ PSID Leaked ☐
				☐ Cleaned ☐ Replaced
FINAL TEST	<u>9.4</u> PSID	Closed Tight ☐ PSID	Opened at <u>2.0</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-20-14</u> Time <u>2:00</u> Certified Tester No. <u>15915</u> ☒ Passed ☐ Failed
	Test By (Signature) <u>Robert W. Autrey</u> Print Name <u>Robert W. Autrey</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____
	Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed
	Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL 009M20T SIZE 1" SERIAL NO. 120801
 SERVICE NUMBER: 67 LOCATION: Boiler Rm.
 SERVICE NAME/ADDRESS: Bldg 1172
 OWNER NAME/ADDRESS: RRAD
 AR: 8.8 RVOP: 3.0
 CHECK VALVE #1 H-T
 CHECK VALVE #2 8.8

RF
DC
PVB
SVB
DCDA
RPDA

REDUCED PRESSURE PRINCIPLE ASSEMBLY
DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>8.8</u> PSID Leaked ☐	Held at _____ PSID Closed Tight ☒ Leaked ☐	Opened at <u>3.0</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____
FINAL TEST	_____ PSID	_____ PSID Closed Tight ☐	Opened at _____ PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: RELIEF valve has a minor drip

INITIAL TEST	Date <u>8-25-14</u> Time <u>8:00am</u> Certified Tester No. <u>15951</u> ☒ Passed ☐ Failed Test By (Signature) <u>Robert W. Autrey</u> Print Name <u>Robert W. Autrey</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____ Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL 009M20T SIZE 1" SERIAL NO. 116617
 SERVICE NUMBER: 66 LOCATION: Boiler Rm
 SERVICE NAME/ADDRESS: RRAD Bldg 1172
 OWNER NAME/ADDRESS: RRAD
 AR: 6.5 RVOP: 2.3
 CHECK VALVE #2 HT
 CHECK VALVE #1 6.8

RP ☒
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>6.8</u> PSID Leaked ☐	Held at <u>HT</u> PSID Closed Tight ☐ Leaked ☐	Opened at <u>2.3</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____
FINAL TEST	<u>6.8</u> PSID	Closed Tight ☐ PSID	Opened at <u>1.0</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-25-14</u> Time <u>7:30am</u> Certified Tester No. <u>15951</u> ☒ Passed ☐ Failed
	Test By (Signature) <u>Robert W. Autrey</u> Print Name <u>ROBERT W. Autrey</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____
	Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed
	Test By (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE WATTS MODEL 00923600T SIZE 3/4" SERIAL NO. 30222
 SERVICE NUMBER: 64 LOCATION: North Equipment Rm.
 SERVICE NAME/ADDRESS: RRAD Bldg 1174
 OWNER NAME/ADDRESS: RRAD
 AR: 9.0 RVOP: 2.0
 CHECK VALVE #2 H/T
 CHECK VALVE #1 9.2

RP ☒
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>9.2</u> PSID Leaked ☐	Held at _____ PSID Closed Tight ☒ Leaked ☐	Opened at <u>2.0</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____
FINAL TEST	<u>9.2</u> PSID	_____ PSID Closed Tight ☐	Opened at <u>2.0</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-20-14</u> Time <u>1:00</u> Certified Tester No. <u>15915</u> ☒ Passed ☐ Failed
	Test By (Signature) <u>Robert W. Autrey</u> Print Name <u>ROBERT W. Autrey</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____
	Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed
	Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL 009 M2 SIZE 2" SERIAL NO. 316559
 SERVICE NUMBER: #104 LOCATION: Bldg 406 Southeast
 SERVICE NAME/ADDRESS: Bldg 406 South
 OWNER NAME/ADDRESS: RRAD
 AR: 9.0 psid RVOR: 4.2 psid
 CHECK VALVE #2 H/T
 CHECK VALVE #1 9.2 psid

RF ☒
 DC ☐
 PVB ☐
 SVII ☐
 DCDA ☐
 RPDA ☐

		REDUCED PRESSURE PRINCIPLE ASSEMBLY		DOUBLE CHECK VALVE ASSEMBLY	
INITIAL -TEST	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB	
	Held at <u>9.2</u> PSID Leaked ☐	Held at _____ PSID Closed Tight ☒ Leaked ☐	Opened at <u>4.2</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐	
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced	☐ Cleaned ☐ Replaced	☐ Cleaned ☐ Replaced	CHECK VALVE Held at _____ PSID Leaked ☐	
	_____	_____	_____	☐ Cleaned ☐ Replaced _____	
FINAL TEST	<u>9.2</u> PSID	Closed Tight ☒	Opened at <u>4.2</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID	

Comments: _____

INITIAL TEST	Date <u>8-21-14</u> Time <u>11:00am</u> Certified Tester No. <u>15915</u> ☒ Passed ☐ Failed
	Test By (Signature) <u>Robert L. Autrey</u> Print Name <u>Robert L. Autrey</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____
	Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed
	Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL 009M2AT SIZE 1" SERIAL NO. 86587
 SERVICE NUMBER: Bldg 410A LOCATION: WESTSIDE OF WASH RACK
 SERVICE NAME/ADDRESS: Bldg 410A
 OWNER NAME/ADDRESS: PRAD
 AR: 8.2 psid RVOP: 2.6
 CHECK VALVE #2 HIT
 CHECK VALVE #1 8.0 psid

RF ☐
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>8.0</u> PSID Leaked ☐	Held at _____ PSID Closed Tight ☒ Leaked ☐	Opened at <u>2.6</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____
FINAL TEST	<u>8.0</u> PSID	_____ PSID Closed Tight ☐	Opened at <u>2.4</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-21-14</u> Time <u>1:00pm</u> Certified Tester No. _____ ☒ Passed ☐ Failed
	Test By (Signature) <u>Robert L. Autrey</u> Print Name <u>Robert L. Autrey</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____
	Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed
	Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Conbraco MODEL 40204T2 SIZE 3/4 SERIAL NO. 00541H
 SERVICE NUMBER: 061 LOCATION: Bldg 401 Westside ctr of Bldg
 SERVICE NAME/ADDRESS: Bldg 401
 OWNER NAME/ADDRESS: RRAD
 AR: 6.4 psid RVOP: 2.8
 CHECK VALVE #2 H/T
 CHECK VALVE #1 6.4 psid

RP ☒
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>6.4</u> PSID Leaked ☐	Held at _____ PSID Closed Tight ☒ Leaked ☐	Opened at <u>2.8</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____
FINAL TEST	<u>6.4</u> PSID	Closed Tight ☐ PSID	Opened at <u>2.8</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-21-14</u> Time <u>3:00</u> Certified Tester No. <u>15915</u> ☒ Passed ☐ Failed Test By (Signature) <u>Robert W. Autrey</u> Print Name <u>ROBERT W. Autrey</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____ Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed Test By (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Conbraco MODEL 4020412 SIZE 3/4" SERIAL NO. LT889
 SERVICE NUMBER: BPLBG038 LOCATION: Bldg 04
 SERVICE NAME/ADDRESS: BASEMENT Equip. Rm.
 OWNER NAME/ADDRESS: RRAD
 AR: 7.5 psid RVOP: 2.2 psid
 CHECK VALVE #2 HT
 CHECK VALVE #1 7.5

RF ☒
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>7.5</u> PSID Leaked ☐	Held at _____ PSID Closed Tight ☒ Leaked ☐	Opened at <u>2.2</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____
FINAL TEST	<u>7.5</u> PSID	Closed Tight ☐ PSID	Opened at <u>2.2</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-19-14</u> Time <u>10:30 AM</u> Certified Tester No. <u>15951</u> ☒ Passed ☐ Failed
	Test By (Signature) <u>Robert W. Autrey</u> Print Name <u>Robert W. Autrey</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____
	Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed
	Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000

BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL 907 SIZE 4" SERIAL NO. 181961
 SERVICE NUMBER: #085 LOCATION: 493 Main Water Feed E. Side Bld
 SERVICE NAME/ADDRESS: RRAD
 OWNER NAME/ADDRESS: RRAD
 AR: # 5.2 RVOP: 2.2
 CHECK VALVE #2 5.6
 CHECK VALVE #1 5.6

RP ☒
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>5.6</u> PSID Leaked ☐	Held at <u>5.6</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>2.2</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____
FINAL TEST	<u>5.6</u> PSID	Closed Tight ☒ PSID	Opened at <u>2.2</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-30-14</u> Time <u>10:10</u> Certified Tester No. <u>14467</u> ☒ Passed ☐ Failed
	Test By (Signature) <u>Stacy Sharp</u> Print Name <u>Stacy Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____
	Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed
	Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL 909M2QT SIZE 2" SERIAL NO. 147175
SERVICE NUMBER: #076 LOCATION: 493 Vat area W. Wall
SERVICE NAME/ADDRESS: RRAD
OWNER NAME/ADDRESS: RRAD
AR: 8.9 RVOR: 2.4
CHECK VALVE #2 9.5
CHECK VALVE #1 9.5

RP ☒
DC ☐
PVB ☐
SVB ☐
DCDA ☐
RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>9.5</u> PSID Leaked ☐	Held at <u>9.5</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>2.4</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____
FINAL TEST	<u>9.5</u> PSID	Closed Tight ☒ PSID	Opened at <u>2.4</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-30-14</u> Time <u>12:46pm</u> Certified Tester No. <u>14467</u> ☒ Passed ☐ Failed Test By (Signature) <u>Stacy Sharp</u> Print Name <u>Stacey Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____ Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL 909 SIZE 6" SERIAL NO. 255150
SERVICE NUMBER: _____ LOCATION: 336 Basement N.E. Corner Main Water Feed
SERVICE NAME/ADDRESS: RRAD
OWNER NAME/ADDRESS: RRAD
AR: 6.4 RVOP: 2.2
CHECK VALVE #2 6.4
CHECK VALVE #1 6.4

RP ☒
DC ☐
PVB ☐
SVB ☐
DCDA ☐
RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>6.4</u> PSID Leaked ☐	Held at <u>6.4</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>2.2</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____
FINAL TEST	<u>6.4</u> PSID	Closed Tight ☒ PSID	Opened at <u>2.2</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-30-14</u> Time <u>3:01</u> Certified Tester No. <u>14467</u> ☒ Passed ☐ Failed Test By (Signature) <u>Stacey Sharp</u> Print Name <u>Stacey Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____ Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed Test By (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL 709 SIZE 6" SERIAL NO. 255005
 SERVICE NUMBER: #57 LOCATION: 336 Basement N.E. Corner
 SERVICE NAME/ADDRESS: RRAD Main Water Bypass
 OWNER NAME/ADDRESS: RRAD
 AR: 8.6 RVOP: 3
 CHECK VALVE #2 7.2
 CHECK VALVE #1 7.2

RP ☒
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>7.2</u> PSID Leaked ☐	Held at <u>7.2</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>3</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____
FINAL TEST	<u>7.2</u> PSID	Closed Tight ☒ PSID	Opened at <u>3</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-30-14</u> Time <u>3:27</u> Certified Tester No. <u>14461</u> ☒ Passed ☐ Failed Test By (Signature) <u>Stacey Sharp</u> Print Name <u>Stacey Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____ Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed Test By (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL COMBAT SIZE 2" SERIAL NO. 218446
 SERVICE NUMBER: #103 LOCATION: 561 B Sprinkler house
 SERVICE NAME/ADDRESS: RRAO
 OWNER NAME /ADDRESS: RRAO
 AR: 10.4 RVOR: 4.6
 CHECK VALVE #2 7.6
 CHECK VALVE #1 10

RP ☒
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>10</u> PSID Leaked ☐	Held at <u>7.6</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>4.6</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____
FINAL TEST	<u>10</u> PSID	Closed Tight ☒ PSID	Opened at <u>4.6</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>9-25-14</u> Time <u>1504</u> Certified Tester No. <u>14467</u> ☒ Passed ☐ Failed
REPAIR	Test By (Signature) <u>Stacey Sharp</u> Print Name <u>Stacey Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____ Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Wilkins MODEL 975XL SIZE 2" SERIAL NO. 1342967
 SERVICE NUMBER: #109 LOCATION: 561 D Washneck
 SERVICE NAME/ADDRESS: RRAD
 OWNER NAME/ADDRESS: RRAD
 AR: 3.6 RVOP: 5.0
 CHECK VALVE #2 3.6
 CHECK VALVE #1 3.6

RP ☒
 DC ☐
 PVB ☐
 SVII ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>3.6</u> PSID Leaked ☐	Held at <u>3.6</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>5.0</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____
FINAL TEST	<u>3.6</u> PSID	Closed Tight ☒ PSID	Opened at <u>5.0</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>3-25-14</u> Time <u>15:24</u> Certified Tester No. <u>14461</u> ☒ Passed ☐ Failed
	Test By (Signature) <u>Stacey Sharp</u> Print Name <u>Stacey Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____
	Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed
	Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE DilkinsZurn MODEL 975XL SIZE 1" SERIAL NO. 39167457
 SERVICE NUMBER: #107 LOCATION: Elliot Lake Splashpad
 SERVICE NAME/ADDRESS: RRAD
 OWNER NAME/ADDRESS: RRAD
 AR: 7.1 RVOR: 3.2
 CHECK VALVE #2 7.4
 CHECK VALVE #1 7.4

RP ☒
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>7.4</u> PSID Leaked ☐	Held at <u>7.4</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>3.2</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____
FINAL TEST	<u>7.4</u> PSID	Closed Tight ☒ PSID	Opened at <u>3.2</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8.27.14</u> Time <u>7:54am</u> Certified Tester No. <u>14461</u> ☒ Passed ☐ Failed
REPAIR	Test By (Signature) <u>Stacey Sharp</u> Print Name <u>Stacey Sharp</u>
	Date _____ Time _____ Certified Tester No. _____
	Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed
	Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Apollo MODEL 40204T2 SIZE 3/4 SERIAL NO. 00539F
 SERVICE NUMBER: #080 LOCATION: Bldg 638 Boiler house
 SERVICE NAME/ADDRESS: RRAD
 OWNER NAME/ADDRESS: RRAD
 AR: 5.5 RVOR: 2.4
 CHECK VALVE #2 6.0
 CHECK VALVE #1 6.0

RF ☒
 DC ☐
 PVB ☐
 SVH ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>6.0</u> PSID	Held at <u>6.0</u> PSID	Opened at <u>2.4</u> PSID	AIR INLET
	Leaked ☐	Closed Tight ☒ Leaked ☐	Did Not Open ☐	Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced	☐ Cleaned ☐ Replaced	☐ Cleaned ☐ Replaced	CHECK VALVE
	_____	_____	_____	Held at _____ PSID Leaked ☐
FINAL TEST	<u>6.0</u> PSID	Closed Tight ☒ PSID	Opened at <u>2.4</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-27-14</u> Time <u>9:47 am</u> Certified Tester No. <u>14461</u> ☒ Passed ☐ Failed
	Test By (Signature) <u>Stacey Sharp</u> Print Name <u>Stacey Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____
	Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed
	Test By (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Flowmatic MODEL 6125 SIZE 3/4 SERIAL NO. 10527
 SERVICE NUMBER: _____ LOCATION: Bldg 15 Equip Room
 SERVICE NAME/ADDRESS: RRAD
 OWNER NAME/ADDRESS: RRAD
 AR: 6.8 RVOR: 2.6
 CHECK VALVE #1 6.5
 CHECK VALVE #1 6.5

RP ☒
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>6.5</u> PSID Leaked ☐	Held at <u>6.5</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>2.6</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____
FINAL TEST	<u>6.5</u> PSID	Closed Tight ☒ PSID	Opened at <u>2.6</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-27-14</u> Time <u>10:29 AM</u> Certified Tester No. <u>14467</u> ☒ Passed ☐ Failed Test By (Signature) <u>Stacy Sharp</u> Print Name <u>Stacy Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____ Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed Test By (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE 10a H5 MODEL CC91M307 SIZE 3/4" SERIAL NO. 10137425
 SERVICE NUMBER: # 019 LOCATION: Bldg 15 North Equip.
 SERVICE NAME/ADDRESS: RRAD
 OWNER NAME/ADDRESS: RRAD
 AR: 10.1 RVOP: 3.4
 CHECK VALVE #1 10.1
 CHECK VALVE #1 10.1

RP ☒
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>10.1</u> PSID Leaked ☐	Held at <u>10.1</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>3.4</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____
FINAL TEST	<u>10.1</u> PSID	Closed Tight ☒ PSID	Opened at <u>3.4</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-27-14</u> Time <u>10:49am</u> Certified Tester No. <u>14461</u> ☒ Passed ☐ Failed
REPAIR	Test By (Signature) <u>Stacey Sharp</u> Print Name <u>Stacey Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____
REPAIR	Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed
FINAL TEST	Test By (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL CD9M201 SIZE 2" SERIAL NO. A53174
 SERVICE NUMBER: #124 LOCATION: Bldg 364 Equip Room South Side
 SERVICE NAME/ADDRESS: RRAO
 OWNER NAME/ADDRESS: RRAO
 AR: 10 RVOP: 3.4
 CHECK VALVE #2 9.9
 CHECK VALVE #1 8.2

RP ☒
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>8.2</u> PSID Leaked ☐	Held at <u>9.9</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>3.4</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
	☐ Cleaned ☐ Replaced 	☐ Cleaned ☐ Replaced 	☐ Cleaned ☐ Replaced 	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced
Repairs: Give details of repairs made here.				
FINAL TEST	<u>8.2</u> PSID	Closed Tight ☒	Opened at <u>3.4</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-27-14</u> Time <u>2:52 pm</u> Certified Tester No. <u>14467</u> ☒ Passed ☐ Failed
	Test By (Signature) <u>Stacy Sharp</u> Print Name <u>Stacy Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____ Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed Test By (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Unit 15 MODEL COMM-DT SIZE 1 1/2" SERIAL NO. 53405
 SERVICE NUMBER: #122 LOCATION: Bldg 401-A Washback
 SERVICE NAME/ADDRESS: RRAD
 OWNER NAME/ADDRESS: RRAD
 AR: 7.2 RVOR: 3.3
 CHECK VALVE #2 7.2
 CHECK VALVE #1 8.1

RP ☒
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>8.1</u> PSID Leaked ☐	Held at <u>7.2</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>3.3</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____
FINAL TEST	<u>8.1</u> PSID	Closed Tight ☒ PSID	Opened at <u>3.3</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-28-14</u> Time <u>7:21 AM</u> Certified Tester No. <u>14467</u> ☒ Passed ☐ Failed Test By (Signature) <u>Stacey Sharp</u> Print Name <u>Stacey Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____ Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed Test By (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE 112115 MODEL 709 SIZE 3" SERIAL NO. 1103295
 SERVICE NUMBER: #045 LOCATION: Bldg 302 Outside
 SERVICE NAME/ADDRESS: RRAD
 OWNER NAME /ADDRESS: RRAD
 AR: 6.5 RVOP: 2.8
 CHECK VALVE #2 6.4
 CHECK VALVE #1 6.4

RP ☒
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>6.4</u> PSID Leaked ☐	Held at <u>6.4</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>2.8</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____
FINAL TEST	<u>6.4</u> PSID	_____ PSID Closed Tight ☒	Opened at <u>2.8</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-28-14</u> Time <u>12:42pm</u> Certified Tester No. <u>14467</u> ☒ Passed ☐ Failed Test By (Signature) <u>Stacey Sharp</u> Print Name <u>Stacey Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____ Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL 007M20T SIZE 1" SERIAL NO. 278784
 SERVICE NUMBER: #007 LOCATION: Bldg 3602 East Bay 1
 SERVICE NAME/ADDRESS: RRAD
 OWNER NAME/ADDRESS: RRAD
 AR: 7.8 RVOP: 3.6
 CHECK VALVE #2 7.0
 CHECK VALVE #1 7.0

RF ☒
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>7.0</u> PSID Leaked ☐	Held at <u>7.0</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>3.6</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____
FINAL TEST	<u>7.0</u> PSID	Closed Tight ☒ PSID	Opened at <u>3.6</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-28-14</u> Time <u>1:22pm</u> Certified Tester No. <u>1446</u> ☒ Passed ☐ Failed
	Test By (Signature) <u>Stacey Sh...</u> Print Name <u>Stacey Sh...</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____
	Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed
	Test By (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL CDM3QT SIZE 1/2 SERIAL NO. 19262
 SERVICE NUMBER: #008 LOCATION: Bldg 342 Bay 1 West
 SERVICE NAME/ADDRESS: RRAD
 OWNER NAME/ADDRESS: RRAD
 AR: 87 RVOP: 33
 CHECK VALVE #2 87
 CHECK VALVE #1 87

RP ☒
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>87</u> PSID Leaked ☐	Held at <u>87</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>33</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____
FINAL TEST	<u>87</u> PSID	Closed Tight ☒ PSID	Opened at <u>33</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-28-14</u> Time <u>1:34pm</u> Certified Tester No. <u>14467</u> ☒ Passed ☐ Failed Test By (Signature) <u>Stacey Sharp</u> Print Name <u>Stacey Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____ Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed Test By (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE UNHS MODEL 109CW/4 SIZE 3/4 SERIAL NO. 170145
SERVICE NUMBER: #055 LOCATION: Bldg 321/2nd Equip
SERVICE NAME/ADDRESS: RRAD
OWNER NAME /ADDRESS: RRAD
AR: 7.5 RVOP: 22
CHECK VALVE #2 7.7
CHECK VALVE #1 7.7

RP ☒
DC ☐
PVB ☐
SVB ☐
DCDA ☐
RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>7.7</u> PSID Leaked ☐	Held at <u>7.7</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>22</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____
FINAL TEST	<u>7.7</u> PSID	Closed Tight ☒ PSID	Opened at <u>22</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-28-14</u> Time <u>2:48pm</u> Certified Tester No. <u>14467</u> ☒ Passed ☐ Failed Test By (Signature) <u>Stacey Sharp</u> Print Name <u>Stacey Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____ Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed Test By (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL COM2GT SIZE 2" SERIAL NO. 208706
 SERVICE NUMBER: #021 LOCATION: 345 Pump House on Dock E. Side S. of Elevator
 SERVICE NAME/ADDRESS: RRAD
 OWNER NAME/ADDRESS: RRAD
 AR: 7.6 RVOR: 2.9
 CHECK VALVE #2 7.9
 CHECK VALVE #1 7.9

RP ☒
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>7.9</u> PSID Leaked ☐	Held at <u>7.9</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>2.9</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____
FINAL TEST	<u>7.9</u> PSID	Closed Tight ☒ PSID	Opened at <u>2.9</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-29-14</u> Time <u>3:32pm</u> Certified Tester No. <u>14467</u> ☒ Passed ☐ Failed Test By (Signature) <u>Stacey Sharp</u> Print Name <u>Stacey Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____ Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL 001M30T SIZE 3/4" SERIAL NO. 376942
 SERVICE NUMBER: _____ LOCATION: 345 E. side in Mech. Room next to Ch. Hl.
 SERVICE NAME/ADDRESS: BRAD
 OWNER NAME/ADDRESS: BRAD
 AR: 8.8 RVOP: 2.2
 CHECK VALVE #2 8.8
 CHECK VALVE #1 8.8

RP ☒
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY
DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>8.8</u> PSID Leaked ☐	Held at <u>8.8</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>2.2</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____
FINAL TEST	<u>8.8</u> PSID	<u>8.8</u> PSID Closed Tight ☒	Opened at <u>2.2</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-29-14</u> Time <u>3:08pm</u> Certified Tester No. <u>19461</u> ☒ Passed ☐ Failed
	Test By (Signature) <u>Stacey Sharp</u> Print Name <u>Stacey Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____
	Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed
	Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL 009m2QT SIZE 3/4" SERIAL NO. 376873
 SERVICE NUMBER: _____ LOCATION: 345 Inside Chain link Fence
 SERVICE NAME/ADDRESS: RRAD Hot Water Pump location
 OWNER NAME/ADDRESS: RRAD
 AR: 8.4 RVOP: 2
 CHECK VALVE #2 8.0
 CHECK VALVE #1 8.0

RP ☒
 DC ☐
 PVB ☐
 SVH ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY
DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>8.0</u> PSID Leaked ☐	Held at <u>8.0</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>2</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____
FINAL TEST	<u>8.0</u> PSID	Closed Tight ☒ PSID	Opened at <u>2</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-29-14</u> Time <u>12:51pm</u> Certified Tester No. <u>14467</u> ☒ Passed ☐ Failed
	Test By (Signature) <u>Stacey Sharp</u> Print Name <u>Stacey Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____
	Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed
	Test By (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL COM2QT SIZE 2" SERIAL NO. 208704
 SERVICE NUMBER: #096 LOCATION: 345 Line 16 E. End Between Columns 511 + 512
 SERVICE NAME/ADDRESS: RRAD
 OWNER NAME/ADDRESS: RRAD
 AR: 9.0 RVOR: 4.2
 CHECK VALVE #2 9.0
 CHECK VALVE #1 9.0

RP ☐
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>9.0</u> PSID	Held at <u>9.0</u> PSID	Opened at <u>4.2</u> PSID	AIR INLET
	Leaked ☐	Closed Tight ☒ Leaked ☐	Did Not Open ☐	Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced	☐ Cleaned ☐ Replaced	☐ Cleaned ☐ Replaced	CHECK VALVE
				Held at _____ PSID
				Leaked ☐
				☐ Cleaned ☐ Replaced
FINAL TEST	<u>9.0</u> PSID	Closed Tight ☒ PSID	Opened at <u>4.2</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-29-14</u> Time <u>2:43pm</u> Certified Tester No. <u>14467</u> ☒ Passed ☐ Failed
	Test By (Signature) <u>Stacey Sharp</u> Print Name <u>Stacey Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____
	Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed
	Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Wilkins Zurn MODEL TR990 SIZE 3/4" SERIAL NO. 125299
SERVICE NUMBER: #C.90 LOCATION: 345 S.E. Corner by Column Q 18
SERVICE NAME/ADDRESS: RRAD
OWNER NAME/ADDRESS: RRAD
AR: 9.0 RVOP: 3.0
CHECK VALVE #2 9.0
CHECK VALVE #1 9.0

RP ☒
DC ☐
PVB ☐
SVB ☐
DCDA ☐
RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>9.0</u> PSID Leaked ☐	Held at <u>9.0</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>3.0</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____
FINAL TEST	_____ PSID	Closed Tight ☐ PSID	Opened at _____ PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-29-14</u> Time <u>1:17pm</u> Certified Tester No. <u>14467</u> ☒ Passed ☐ Failed Test By (Signature) <u>Stacey Sharp</u> Print Name <u>Stacey Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____ Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed Test By (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

B-345

MANUFACTURE Watts MODEL 001MGT SIZE 1 1/2" SERIAL NO. 159742
 SERVICE NUMBER: #117 LOCATION: W. Side Community Center #1 on Washer
 SERVICE NAME/ADDRESS: RRAD
 OWNER NAME/ADDRESS: RRAD
 AR: 7.6 RYOP: 2.9
 CHECK VALVE #2 7.9
 CHECK VALVE #1 7.9

RP ☐
 DC ☐
 PVB ☐
 SVH ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>7.9</u> PSID Leaked ☐	Held at <u>7.9</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>2.9</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____
FINAL TEST	_____ PSID	Closed Tight ☒ PSID	Opened at _____ PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-29-14</u> Time <u>10:40 AM</u> Certified Tester No. <u>14467</u> ☒ Passed ☐ Failed Test By (Signature) <u>Stacey Sharp</u> Print Name <u>Stacey Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____ Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL CUM20T SIZE 1 1/2" SERIAL NO. 150782
 SERVICE NUMBER: _____ LOCATION: 345 Culoma R9 by washer
 SERVICE NAME/ADDRESS: PRAD
 OWNER NAME /ADDRESS: PRAD
 AR: 8.8 RVOP: 3.0
 CHECK VALVE #2 8.4
 CHECK VALVE #1 8.4

RP ☒
 DC ☐
 PVB ☐
 SVH ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>8.4</u> PSID Leaked ☐	Held at <u>8.4</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>3.0</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____
FINAL TEST	_____ PSID	Closed Tight ☒ PSID	Opened at _____ PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-29-14</u> Time <u>10:13 AM</u> Certified Tester No. <u>14467</u> ☒ Passed ☐ Failed Test By (Signature) <u>Stacey Sharp</u> Print Name <u>Stacey Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____ Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed Test By (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Lombroco MODEL 40204T2 SIZE 3/4" SERIAL NO. C0535A
 SERVICE NUMBER: #020 LOCATION: 345 E Line 9 by glove window Column K15
 SERVICE NAME/ADDRESS: BRAD
 OWNER NAME/ADDRESS: BRAD
 AR: 7.4 RVOR: 3.8
 CHECK VALVE #2 7.8
 CHECK VALVE #1 7.8

RP ☐
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>7.8</u> PSID Leaked ☐	Held at <u>7.8</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>3.8</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____
FINAL TEST	<u>7.8</u> PSID	Closed Tight ☒ PSID	Opened at <u>3.8</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-29-14</u> Time <u>9:24am</u> Certified Tester No. <u>14467</u> ☒ Passed ☐ Failed Test By (Signature) <u>Stacey Sharp</u> Print Name <u>Stacey Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____ Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL C09M2Q1 SIZE 2" SERIAL NO. 132070
 SERVICE NUMBER: #029 LOCATION: 345 Electroplating Middle Vats under Eyewash
 SERVICE NAME/ADDRESS: RRAD
 OWNER NAME/ADDRESS: RRAD
 AR: 8.8 RVOF: 3.8
 CHECK VALVE #2 9.0
 CHECK VALVE #1 9.0

RF ☐
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>9.0</u> PSID Leaked ☐	Held at <u>9.0</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>3.8</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____
FINAL TEST	<u>9.0</u> PSID	<u>9</u> PSID Closed Tight ☒	Opened at <u>3.8</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-29-14</u> Time <u>8:28 AM</u> Certified Tester No. <u>14467</u> ☒ Passed ☐ Failed Test By (Signature) <u>Stacey Sharp</u> Print Name <u>Stacey Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____ Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL CC9M2GT SIZE 2" SERIAL NO. 129385
 SERVICE NUMBER: #028 LOCATION: 345 Electric plating S.W. End
 SERVICE NAME/ADDRESS: RRAD
 OWNER NAME/ADDRESS: RRAD
 AR: 9.2 RVO: 3.8
 CHECK VALVE #2 9.4
 CHECK VALVE #1 9.4

RF ☒
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>9.4</u> PSID Leaked ☐	Held at <u>9.4</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>3.8</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____
FINAL TEST	<u>9.4</u> PSID	Closed Tight ☒ PSID	Opened at <u>3.8</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-27-14</u> Time <u>8:08am</u> Certified Tester No. <u>14467</u> ☒ Passed ☐ Failed
	Test By (Signature) <u>Stacey Sharp</u> Print Name <u>Stacey Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____
	Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed
	Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL C09-M20T SIZE 2" SERIAL NO. 146271
 SERVICE NUMBER: #005 LOCATION: 345 Electroplating N. End W. side of roll up door
 SERVICE NAME/ADDRESS: RRAD
 OWNER NAME/ADDRESS: RRAD
 AR: 9.4 RVOR: 3.0
 CHECK VALVE #2 9.4
 CHECK VALVE #1 9.4

RP ☒
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>9.4</u> PSID	Held at <u>9.4</u> PSID	Opened at <u>3.0</u> PSID	AIR INLET
	Leaked ☐	Closed Tight ☒ Leaked ☐	Did Not Open ☐	Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced	☐ Cleaned ☐ Replaced	☐ Cleaned ☐ Replaced	CHECK VALVE
				Held at _____ PSID
				Leaked ☐
				☐ Cleaned ☐ Replaced
FINAL TEST	<u>9.4</u> PSID	Closed Tight ☒ PSID	Opened at <u>3.0</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-29-14</u> Time <u>7:58am</u> Certified Tester No. <u>14467</u> ☒ Passed ☐ Failed
	Test By (Signature) <u>Stacy Sharp</u> Print Name <u>Stacy Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____
	Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed
	Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL DDM2GT SIZE 1" SERIAL NO. 113126
 SERVICE NUMBER: #006 LOCATION: 345 Electropolating N. End on E. side of fall up dew-
 SERVICE NAME/ADDRESS: BRAD
 OWNER NAME/ADDRESS: BRAD
 AR: 7.6 RVOP: 2.6
 CHECK VALVE #1 7.6
 CHECK VALVE #1 7.6

RF ☒
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>7.6</u> PSID Leaked ☐	Held at <u>7.6</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>2.6</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____
FINAL TEST	<u>7.6</u> PSID	Closed Tight ☒ PSID	Opened at <u>2.6</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-29-14</u> Time <u>7:50</u> Certified Tester No. <u>14467</u> ☒ Passed ☐ Failed Test By (Signature) <u>Stacey Sharp</u> Print Name <u>Stacey Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____ Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed Test By (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL 909QT SIZE 3/4 SERIAL NO. 518298
SERVICE NUMBER: #075 LOCATION: 345 N W. Corne. Line 5
SERVICE NAME/ADDRESS: BRAD
OWNER NAME/ADDRESS: BRAD
AR: 7.0 RVP: 2.2
CHECK VALVE #2 7.2
CHECK VALVE #1 7.2

RP ☒
DC ☐
PVB ☐
SVB ☐
DCDA ☐
RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>7.2</u> PSID Leaked ☐	Held at <u>7.2</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>2.2</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____
FINAL TEST	<u>7.2</u> PSID	Closed Tight ☒ PSID	Opened at <u>2.2</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-29-14</u> Time <u>7:13am</u> Certified Tester No. <u>14467</u> ☒ Passed ☐ Failed Test By (Signature) <u>Stacey Sharp</u> Print Name <u>Stacey Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____ Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Apollo MODEL RPLFYA SIZE 3/4" SERIAL NO 584894
 SERVICE NUMBER: _____ LOCATION: 345 Hydraulic Shop
 SERVICE NAME/ADDRESS: RRAD
 OWNER NAME/ADDRESS: RRAD
 AR: 5.9 RVOR: 2.6
 CHECK VALVE #2 5.9
 CHECK VALVE #1 5.9

RP ☐
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>5.9</u> PSID Leaked ☐	Held at <u>5.9</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>2.6</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____
FINAL TEST	<u>5.9</u> PSID	Closed Tight ☒ PSID	Opened at <u>2.6</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>9-2-14</u> Time <u>8:02am</u> Certified Tester No. <u>14467</u> ☒ Passed ☐ Failed
	Test By (Signature) <u>Stacey Sharp</u> Print Name <u>Stacey Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____
	Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed
	Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL 909M2GT SIZE 1 1/2" SERIAL NO. 51101
 SERVICE NUMBER: #030 LOCATION: 345 2nd Floor N.E. Side of Speed Control
 SERVICE NAME/ADDRESS: RRAD on N. Wall
 OWNER NAME/ADDRESS: RRAD
 AR: 8.2 RVOP: 2
 CHECK VALVE #2 7.6
 CHECK VALVE #1 7.6

RP ☒
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>7.6</u> PSID Leaked ☐	Held at <u>7.6</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>2</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____
FINAL TEST	<u>7.6</u> PSID	<u>7.6</u> PSID Closed Tight ☒	Opened at <u>2</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-30-14</u> Time <u>8:26am</u> Certified Tester No. <u>14467</u> ☒ Passed ☐ Failed
	Test By (Signature) <u>Stacey Sharp</u> Print Name <u>Stacey Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____
	Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed
	Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL WM2QT SIZE 1" SERIAL NO. 56551
 SERVICE NUMBER: #032 LOCATION: 345 2nd Floor N. of Column A13 on N. Wall
 SERVICE NAME/ADDRESS: RRAD
 OWNER NAME/ADDRESS: RRAD
 AR: 7.5 RVOP: 3.6
 CHECK VALVE #2 7.7
 CHECK VALVE #1 7.7

RP ☒
 DC ☐
 PVB ☐
 SVB ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>7.7</u> PSID Leaked ☐	Held at <u>7.7</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>3.6</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced _____ _____ _____ _____ _____ _____ _____
FINAL TEST	<u>7.7</u> PSID	Closed Tight ☒ PSID	Opened at <u>3.6</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-30-14</u> Time <u>8:02 AM</u> Certified Tester No. <u>14467</u> ☒ Passed ☐ Failed Test By (Signature) <u>Stacey Sharp</u> Print Name <u>Stacey Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____ Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed Test by (Signature) _____ Print Name _____

TEXARKANA, TX 75507-5000
BACKFLOW PREVENTION ASSEMBLY FIELD TEST REPORT

MANUFACTURE Watts MODEL 909 mod SIZE 3" SERIAL NO. 183354
 SERVICE NUMBER: #1026 LOCATION: 345 2nd Floor N.W. Corner vat area
 SERVICE NAME/ADDRESS: RRAD
 OWNER NAME/ADDRESS: RRAD
 AR: 7.2 RVOR: 2.6
 CHECK VALVE #2 7.2
 CHECK VALVE #1 7.2

RP ☒
 DC ☐
 PVB ☐
 SVII ☐
 DCDA ☐
 RPDA ☐

REDUCED PRESSURE PRINCIPLE ASSEMBLY

DOUBLE CHECK VALVE ASSEMBLY

	CHECK VALVE #1	CHECK VALVE #2	RELIEF VALVE	PVB/SVB
INITIAL TEST	Held at <u>7.2</u> PSID Leaked ☐	Held at <u>7.2</u> PSID Closed Tight ☒ Leaked ☐	Opened at <u>2.6</u> PSID Did Not Open ☐	AIR INLET Opened at _____ PSID Did Not Open ☐
Repairs: Give details of repairs made here.	☐ Cleaned ☐ Replaced 	☐ Cleaned ☐ Replaced 	☐ Cleaned ☐ Replaced 	CHECK VALVE Held at _____ PSID Leaked ☐ ☐ Cleaned ☐ Replaced
FINAL TEST	<u>7.2</u> PSID	Closed Tight ☒ PSID	Opened at <u>2.6</u> PSID	Air Inlet _____ PSID Check Valve _____ PSID

Comments: _____

INITIAL TEST	Date <u>8-30-14</u> Time <u>7:34am</u> Certified Tester No. <u>1446</u> ☒ Passed ☐ Failed Test By (Signature) <u>Steve Sharp</u> Print Name <u>Steve Sharp</u>
REPAIR	Date _____ Time _____ Certified Tester No. _____ Repaired by (Signature) _____ Print Name _____
FINAL TEST	Date _____ Time _____ Certified Tester No. _____ ☐ Passed ☐ Failed Test by (Signature) _____ Print Name _____