



Control Number: 45720



Item Number: 78

Addendum StartPage: 0

SOAH DOCKET NO. 473-16-3831.WS  
PUC DOCKET NO. 45720

RECEIVED

2016 SEP -1 PM 1:35

PUBLIC UTILITY COMMISSION  
FILING CLERK

APPLICATION OF RIO CONCHO  
AVIATION, INC. FOR A  
RATE/TARIFF CHANGE

§  
§  
§  
§

BEFORE THE STATE OFFICE  
OF  
ADMINISTRATIVE HEARINGS

**RIO CONCHO AVIATION, INC.'S AMENDED AND FIRST SUPPLEMENTAL  
RESPONSE TO COMMISSION STAFF'S THIRD REQUEST FOR INFORMATION  
QUESTION NO. STAFF 3-5**

COMES NOW, Rio Concho Aviation, Inc. ("Rio Concho") and files its Amended and First Supplemental Response to Commission Staff's Third Request for Information – Question No. Staff 3-5.

Respectfully submitted,

By: 

John J. Carlton  
The Carlton Law Firm P.L.L.C.  
2705 Bee Cave Road, Suite 200  
Austin, Texas 78746  
(512) 614-0901  
Fax (512) 900-2855  
State Bar No. 03817600

ATTORNEY FOR RIO CONCHO AVIATION,  
INC.

**CERTIFICATE OF SERVICE**

I hereby certify that I have served or will serve a true and correct copy of the foregoing document via hand delivery, facsimile, electronic mail, overnight mail, U.S. mail and/or Certified Mail Return Receipt Requested to all parties on this the 1<sup>st</sup> day of September, 2016.



John Carlton

78  
1

**REQUEST FOR INFORMATION  
QUESTION NO. STAFF 3-5**

**STAFF RFI 3-5.** Please provide all other maintenance records for the water system and facilities, applicable to the test year, and as required by TCEQ regulations at 30 TAC § 290.46(f)(3)(A)(vi).

**RESPONSE:** Responsive and non-privileged documents will be produced.

## **RESPONSIVE TO STAFF 3-5**

**MONTHLY OPERATING REPORT  
RIO CONCHO AVIATION INC PUBLIC WATER SYSTEM**

Report Date January 2015

Well output 26 Gallons per minute

**Weekly Checklist:**

| Date    | Bleach Used | Chl Pump/Lines | Pressure Pumps | Storage Tank | System Pressure | Dist. Lines | Master Meter | Gallons Pumped | Chl Reading |
|---------|-------------|----------------|----------------|--------------|-----------------|-------------|--------------|----------------|-------------|
| 1-3-15  | 7           | ✓              | ✓              | ✓            | ✓               | ✓           | 5732400      | 92,600         | 1.2         |
| 1-14-15 | 12          | ✓              | ✓              | ✓            | ✓               | ✓           | 5905100      | 172,700        | 1.5         |
| 1-20-15 | 9           | ✓              | ✓              | ✓            | ✓               | ✓           | 6016100      | 111,000        | 1.4         |
| 1-27-15 | 7           | ✓              | ✓              | ✓            | ✓               | ✓           | 6114200      | 98,100         | 1.4         |

System Flush ✓ Flush Location 1-25-15 NORM-dead end 659 South highway, No. 1000 459 + 262

Water Sample Analysis good Water Sample Report Date 1-9-15

Water System Operator/Supervisor Babbar

**MONTHLY OPERATING REPORT  
RIO CONCHO AVIATION INC PUBLIC WATER SYSTEM**

Report Date February 2015

Well output 26 Gallons per minute

**Weekly Checklist:**

| Date           | Bleach Used | Chl Pump/Lines | Pressure Pumps | Storage Tank | System Pressure | Dist. Lines | Master Meter   | Gallons Pumped | Chl Reading |
|----------------|-------------|----------------|----------------|--------------|-----------------|-------------|----------------|----------------|-------------|
| <u>2-21-15</u> | <u>7</u>    | <u>✓</u>       | <u>✓</u>       | <u>✓</u>     | <u>✓</u>        | <u>✓</u>    | <u>6199700</u> | <u>85,500</u>  | <u>1.4</u>  |
| <u>2-21-15</u> | <u>8</u>    | <u>✓</u>       | <u>✓</u>       | <u>✓</u>     | <u>✓</u>        | <u>✓</u>    | <u>6283500</u> | <u>83,600</u>  | <u>1.4</u>  |
| <u>2-14-15</u> | <u>7</u>    | <u>✓</u>       | <u>✓</u>       | <u>✓</u>     | <u>✓</u>        | <u>✓</u>    | <u>6365500</u> | <u>82,000</u>  | <u>1.5</u>  |
| <u>2-25-15</u> | <u>11</u>   | <u>✓</u>       | <u>✓</u>       | <u>✓</u>     | <u>✓</u>        | <u>✓</u>    | <u>6520700</u> | <u>154,800</u> | <u>1.4</u>  |

System Flush ✓ Flush Location 2-21-15 South dead end 703, near dead-end, 661,459, 262

Water Sample Analysis good Water Sample Report Date 2-9-15

Water System Operator/Supervisor Baker

**MONTHLY OPERATING REPORT  
RIO CONCHO AVIATION INC PUBLIC WATER SYSTEM**

Report Date MARCH 2015

Well output 216 Gallons per minute

**Weekly Checklist:**

| Date           | Bleach Used | Chl Pump/Lines | Pressure Storage Tank | System Pressure | Dist. Lines | Master Meter   | Gallons Pumped | Chl. Reading |
|----------------|-------------|----------------|-----------------------|-----------------|-------------|----------------|----------------|--------------|
| <u>3-3-15</u>  | <u>7</u>    | <u>✓</u>       | <u>✓</u>              | <u>✓</u>        | <u>✓</u>    | <u>6608800</u> | <u>88,100</u>  | <u>1.4</u>   |
| <u>3-9-15</u>  | <u>6</u>    | <u>✓</u>       | <u>✓</u>              | <u>✓</u>        | <u>✓</u>    | <u>6685700</u> | <u>71,900</u>  | <u>1.4</u>   |
| <u>3-17-15</u> | <u>9</u>    | <u>✓</u>       | <u>✓</u>              | <u>✓</u>        | <u>✓</u>    | <u>6797100</u> | <u>111,400</u> | <u>1.5</u>   |
| <u>3-23-15</u> | <u>8</u>    | <u>✓</u>       | <u>✓</u>              | <u>✓</u>        | <u>✓</u>    | <u>6888600</u> | <u>91,500</u>  | <u>1.5</u>   |

System Flush ✓ Flush Location 3-25-2015 NORM. dead end 262,459 + 661

Water Sample Analysis good Water Sample Report Date 3-18-15

Water System Operator/Supervisor B. B. B.

**MONTHLY OPERATING REPORT  
RIO CONCHO AVIATION INC PUBLIC WATER SYSTEM**

Report Date April 2015

Well output 26 Gallons per minute

**Weekly Checklist:**

| Date           | Bleach Used                                    | Chl Pump/Lines | Pressure Storage Tank | System Pressure | Dist. Lines | Master Meter | Gallons Pumped | Chl Reading |
|----------------|------------------------------------------------|----------------|-----------------------|-----------------|-------------|--------------|----------------|-------------|
| 4-1-15         | 9                                              | ✓              | ✓                     | ✓               | ✓           | 7021400      | 132,800        | 1.4         |
| 4-8-15         | 8                                              | ✓              | ✓                     | ✓               | ✓           | 7121400      | 100,000        | 1.5         |
| 4-11-15        | 7                                              | ✓              | ✓                     | ✓               | ✓           | 7209200      | 87,800         | 1.5         |
| 4-23-15        | 7                                              | ✓              | ✓                     | ✓               | ✓           | 7300500      | 91,300         | 1.4         |
| 4-27-15        | 4                                              | ✓              | ✓                     | ✓               | ✓           | 7352600      | 52,100         | 1.5         |
| System Flush   | ✓                                              |                |                       |                 |             |              |                |             |
| Flush Location | 4-25-15 Spun down into 703, 100m down and 66.1 |                |                       |                 |             |              |                |             |

Water Sample Analysis good Water Sample Report Date 4-15-15

Water System Operator/Supervisor Bambi 4-21-15 Suction line Repair in well house



**MONTHLY OPERATING REPORT  
RIO CONCHO AVIATION INC PUBLIC WATER SYSTEM**

Report Date May 2015

Well output 26 Gallons per minute

**Weekly Checklist:**

| Date           | Bleach Used | Chl Pump/Lines | Pressure Storage Tank | System Pressure | Dist. Lines | Master Meter   | Gallons Pumped | Chl Reading |
|----------------|-------------|----------------|-----------------------|-----------------|-------------|----------------|----------------|-------------|
| <u>5-4-15</u>  | <u>7</u>    | <u>✓</u>       | <u>✓</u>              | <u>✓</u>        | <u>✓</u>    | <u>7470900</u> | <u>88,300</u>  | <u>1.8</u>  |
| <u>5-11-15</u> | <u>8</u>    | <u>✓</u>       | <u>✓</u>              | <u>✓</u>        | <u>✓</u>    | <u>7532600</u> | <u>91,700</u>  | <u>1.6</u>  |
| <u>5-17-15</u> | <u>8</u>    | <u>✓</u>       | <u>✓</u>              | <u>✓</u>        | <u>✓</u>    | <u>7628800</u> | <u>94,200</u>  | <u>1.2</u>  |
| <u>5-25-15</u> | <u>10</u>   | <u>✓</u>       | <u>✓</u>              | <u>✓</u>        | <u>✓</u>    | <u>7788400</u> | <u>159,600</u> | <u>1.8</u>  |

System Flush ✓ Flush Location ND Met 659, South end 703

Water Sample Analysis Coliform per Water Sample Report Date 5-21-15, 5-26-15

Water System Operator/Supervisor Sample 5-20-15 5:00 PM  
Barby

**MONTHLY OPERATING REPORT  
RIO CONCHO AVIATION INC PUBLIC WATER SYSTEM**

Report Date June 2015

Well output 26 Gallons per minute

**Weekly Checklist:**

| Date           | Bleach Used | Chl Pump/Lines | Pressure Pumps | Storage Tank | System Pressure | Dist. Lines | Master Meter   | Gallons Pumped | Chl Reading |
|----------------|-------------|----------------|----------------|--------------|-----------------|-------------|----------------|----------------|-------------|
| <u>6-1-15</u>  | <u>7</u>    | <u>✓</u>       | <u>✓</u>       | <u>✓</u>     | <u>✓</u>        | <u>✓</u>    | <u>7884800</u> | <u>96400</u>   | <u>2.3</u>  |
| <u>6-8-15</u>  | <u>7</u>    | <u>✓</u>       | <u>✓</u>       | <u>✓</u>     | <u>✓</u>        | <u>✓</u>    | <u>7983100</u> | <u>98300</u>   | <u>2.4</u>  |
| <u>6-14-15</u> | <u>8</u>    | <u>✓</u>       | <u>✓</u>       | <u>✓</u>     | <u>✓</u>        | <u>✓</u>    | <u>8084300</u> | <u>101200</u>  | <u>2.0</u>  |
| <u>6-22-15</u> | <u>6</u>    | <u>✓</u>       | <u>✓</u>       | <u>✓</u>     | <u>✓</u>        | <u>✓</u>    | <u>8160700</u> | <u>76400</u>   | <u>1.7</u>  |

System Flush ✓ Flush Location Normand 654, south 703 dead end

Water Sample Analysis good Water Sample Report Date 6-22-15

Water System Operator/Supervisor Babie

6-27-15 repaired brass nipple on chl line at base of storage tank

**MONTHLY OPERATING REPORT  
RIO CONCHO AVIATION INC PUBLIC WATER SYSTEM**

Report Date July 2015

Well output 26 Gallons per minute.

**Weekly Checklist:**

| Date    | Bleach Used | Chl Pump/Lines | Pressure Storage Tank | System Pressure | Dist. Lines | Master Meter | Gallons Pumped | Chl Reading |
|---------|-------------|----------------|-----------------------|-----------------|-------------|--------------|----------------|-------------|
| 7-2-15  | 6           | ✓              | ✓                     | ✓               | ✓           | 8232300      | 74,600         | 1.9         |
| 7-9-15  | 8           | ✓              | ✓                     | ✓               | ✓           | 8337300      | 105,000        | 2.5         |
| 7-17-15 | 9           | ✓              | ✓                     | ✓               | ✓           | 8459200      | 121,900        | 2.5         |
| 7-25-15 | 7           | ✓              | ✓                     | ✓               | ✓           | 8548900      | 89,200         | 2.0         |

System Flush ✓ Flush Location South end 703, North end 459/262

Water Sample Analysis good Water Sample Report Date 7-2-15

Water System Operator/Supervisor B. Miller

**MONTHLY OPERATING REPORT  
RIO CONCHO AVIATION INC PUBLIC WATER SYSTEM**

Report Date August 2015

Well output 240 Gallons per minute

**Weekly Checklist:**

| Date    | Bleach Used | Chl Pump/Lines | Pressure Pumps | Storage Tank | System Pressure | Dist. Lines | Master Meter | Gallons Pumped | Chl Reading |
|---------|-------------|----------------|----------------|--------------|-----------------|-------------|--------------|----------------|-------------|
| 8-5-15  | 14          | ✓              | ✓              | ✓            | ✓               | ✓           | 8752400      | 207,000        | 1.3         |
| 8-13-15 | 11          | ✓              | ✓              | ✓            | ✓               | ✓           | 8924400      | 164,000        | 2.0         |
| 8-22-15 | 11          | ✓              | ✓              | ✓            | ✓               | ✓           | 9089700      | 168,300        | 1.0         |
| 8-28-15 | 9           | ✓              | ✓              | ✓            | ✓               | ✓           | 9211900      | 122,200        | 2.4         |

System Flush ☒ Flush Location 654 W. Main, south end 703 divided NW 459/262

Water Sample Analysis good Water Sample Report Date August 25, 2015

Water System Operator/Supervisor B. B. B.

**MONTHLY OPERATING REPORT  
RIO CONCHO AVIATION INC PUBLIC WATER SYSTEM**

Report Date Sept. 2005

Well output 261 Gallons per minute

**Weekly Checklist:**

| Date    | Bleach Used | Chl Pump/Lines | Pressure Storage Pumps | System Tank | Pressure Lines | Dist. | Master Meter | Gallons Pumped | Chl Reading |
|---------|-------------|----------------|------------------------|-------------|----------------|-------|--------------|----------------|-------------|
| 9-7-05  | 13          | ✓              | ✓                      | ✓           | ✓              | ✓     | 9399200      | 187,300        | 1.7         |
| 9-13-05 | 8           | ✓              | ✓                      | ✓           | ✓              | ✓     | 9500500      | 101,300        | 2.0         |
| 9-20-05 | 7           | ✓              | ✓                      | ✓           | ✓              | ✓     | 9588400      | 87,900         | 2.4         |
| 9-24-05 | 5           | ✓              | ✓                      | ✓           | ✓              | ✓     | 9640900      | 52,500         | 2.4         |

System Flush ✓ Flush Location Northern 654456/262 w/ submetered 703

Water Sample Analysis good Water Sample Report Date 9-21-05

Water System Operator/Supervisor Bartolo

**MONTHLY OPERATING REPORT  
RIO CONCHO AVIATION INC PUBLIC WATER SYSTEM**

Report Date October 2015

Well output 246 Gallons per minute

**Weekly Checklist:**

| Date     | Bleach Used | Chl Pump/Lines | Pressure Pumps | Storage Tank | System Pressure | Dist. Lines | Master Meter | Gallons Pumped | Chl Reading |
|----------|-------------|----------------|----------------|--------------|-----------------|-------------|--------------|----------------|-------------|
| 10-24-15 | 12          | ✓              | ✓              | ✓            | ✓               | ✓           | 981,7300     | 176,400        | 1.6         |
| 10-27-15 | 8           | ✓              | ✓              | ✓            | ✓               | ✓           | 992,2900     | 105,600        | 1.6         |
| 10-28-15 | 6           | ✓              | ✓              | ✓            | ✓               | ✓           | 1000,0900    | 78,000         | 1.7         |
| 10-29-15 | 11          | ✓              | ✓              | ✓            | ✓               | ✓           | 1017,2200    | 171,300        | 1.8         |

System Flush ✓ Flush Location Somerset 703, 454/2022 + 654 non dead end

Water Sample Analysis good Water Sample Report Date October 6, 2015

Water System Operator/Supervisor Bubbe

10-19-15 Line repairs in wellhouse = suction + pressure lines replaced due to rust and age  
New conduct set for electrode

10-23-15 replace breaker from lightning strike in wellhouse

**MONTHLY OPERATING REPORT  
RIO CONCHO AVIATION INC PUBLIC WATER SYSTEM**

Report Date November 2013

Well output 218 Gallons per minute

**Weekly Checklist:**

| Date            | Bleach Used | Chl Pump/Lines | Pressure Pumps | Storage Tank | System Pressure | Dist. Lines | Master Meter    | Gallons Pumped | Chl Reading |
|-----------------|-------------|----------------|----------------|--------------|-----------------|-------------|-----------------|----------------|-------------|
| <u>11-3-15</u>  | <u>10</u>   | <u>✓</u>       | <u>✓</u>       | <u>✓</u>     | <u>✓</u>        | <u>✓</u>    | <u>10304800</u> | <u>132,600</u> | <u>1.6</u>  |
| <u>11-9-15</u>  | <u>6</u>    | <u>✓</u>       | <u>✓</u>       | <u>✓</u>     | <u>✓</u>        | <u>✓</u>    | <u>10393400</u> | <u>88,600</u>  | <u>1.5</u>  |
| <u>11-16-15</u> | <u>7</u>    | <u>✓</u>       | <u>✓</u>       | <u>✓</u>     | <u>✓</u>        | <u>✓</u>    | <u>10493100</u> | <u>99,700</u>  | <u>1.6</u>  |
| <u>11-23-15</u> | <u>9</u>    | <u>✓</u>       | <u>✓</u>       | <u>✓</u>     | <u>✓</u>        | <u>✓</u>    | <u>10605800</u> | <u>112,700</u> | <u>1.6</u>  |

Flush Location: Nubend 654, 454, 262, Subend 703

System Flush ✓

Water Sample Analysis good Water Sample Report Date 11-19-15

Water System Operator/Supervisor Darbo

11-16-15 Inspection of storage tank/pipeline tank

**MONTHLY OPERATING REPORT  
RIO CONCHO AVIATION INC PUBLIC WATER SYSTEM**

Report Date December 2015

Well output 26 Gallons per minute

**Weekly Checklist:**

| Date            | Bleach Used | Chl Pump/Lines | Pressure Storage Tank Pumps | System Pressure | Dist. Lines | Master Meter    | Gallons Pumped | Chl. Reading |
|-----------------|-------------|----------------|-----------------------------|-----------------|-------------|-----------------|----------------|--------------|
| <u>12-2-15</u>  | <u>9</u>    | <u>✓</u>       | <u>✓</u>                    | <u>✓</u>        | <u>✓</u>    | <u>10739400</u> | <u>133,600</u> | <u>1.6</u>   |
| <u>12-14-15</u> | <u>12</u>   | <u>✓</u>       | <u>✓</u>                    | <u>✓</u>        | <u>✓</u>    | <u>10917600</u> | <u>178,200</u> | <u>1.9</u>   |
| <u>12-21-15</u> | <u>8</u>    | <u>✓</u>       | <u>✓</u>                    | <u>✓</u>        | <u>✓</u>    | <u>11014200</u> | <u>96,600</u>  | <u>1.8</u>   |
| <u>12-31-15</u> | <u>10</u>   | <u>✓</u>       | <u>✓</u>                    | <u>✓</u>        | <u>✓</u>    | <u>11159200</u> | <u>145,000</u> | <u>1.8</u>   |

System Flush ✓ Flush Location Subhead 703 Normal 262,459, 654

Water Sample Analysis good Water Sample Report Date 12-8-15

Water System Operator/Supervisor Buckie